

UNCLASSIFIED

|                                                                                                                                                                                                                                     |              |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|
| AD NUMBER                                                                                                                                                                                                                           |              |
| AD005343                                                                                                                                                                                                                            |              |
| CLASSIFICATION CHANGES                                                                                                                                                                                                              |              |
| TO:                                                                                                                                                                                                                                 | unclassified |
| FROM:                                                                                                                                                                                                                               | confidential |
| LIMITATION CHANGES                                                                                                                                                                                                                  |              |
| TO:<br>Approved for public release; distribution is unlimited.                                                                                                                                                                      |              |
| FROM:<br>Distribution authorized to DoD only; Test and Evaluation; 17 FEB 1953. Other requests shall be referred to Office of Naval Research, Arlington, VA 22203. Pre-dates formal DoD distribution statements. Treat as DoD only. |              |
| AUTHORITY                                                                                                                                                                                                                           |              |
| ONR ltr dtd 26 Oct 1977; ONR ltr dtd 26 Oct 1977                                                                                                                                                                                    |              |

THIS PAGE IS UNCLASSIFIED

UNCLASSIFIED

AD \_\_\_\_\_

DEFENSE DOCUMENTATION CENTER

FOR

SCIENTIFIC AND TECHNICAL INFORMATION

CAMERON STATION ALEXANDRIA, VIRGINIA

DOWNGRADED AT 3 YEAR INTERVALS:  
DECLASSIFIED AFTER 12 YEARS  
DCD DIR 5200.10



UNCLASSIFIED

5343  
ASTIA FILE COPY

DEPARTMENT OF THE NAVY  
OFFICE OF NAVAL RESEARCH  
WASHINGTON, D.C.

17 February 1953

Report No. 680

Final Report on Item 10

Copy No. 43

X- Tra

# IGNITION DELAY OF TRIETHYL TRITHIOPHOSPHITE WITH NITRIC ACID



Contract N7 onr-462  
Task Order III  
Item 10

SECURITY INFORMATION

**THIS REPORT HAS BEEN DECLASSIFIED  
AND CLEARED FOR PUBLIC RELEASE.**

**DISTRIBUTION A  
APPROVED FOR PUBLIC RELEASE;  
DISTRIBUTION UNLIMITED.**

17 February 1953

Report No. 680  
(Final)

A STUDY OF THE IGNITION DELAY OF  
TRIETHYL TRITHIOPHOSPHITE WITH NITRIC ACID IN AN  
IMPINGING-STREAM ROCKET STARTER MOTOR

Contract N7onr-462  
Task Order III  
Item 10

Written by:

E. M. Wilson

No. of Pages: 16

Approved by: *S. B. Kilner*  
S. B. Kilner  
Asst. Senior Chemist  
Solid Engine and  
Chemical Division

Period Covered:

11 November 1952 through 11 January 1953

Approved by: *D. L. Armstrong*  
D. L. Armstrong  
Principal Chemist  
Solid Engine and  
Chemical Division

This document contains information affecting the national defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Sections 793 and 794. The transmission or the revelation of its contents in any manner to an unauthorized person is prohibited by law.

AEROJET ENGINEERING CORPORATION

Azusa, California

SECURITY INFORMATION

CONTENTS

|                                                                      | <u>Page</u>   |
|----------------------------------------------------------------------|---------------|
| Contract Fulfillment Statement _____                                 | iii           |
| I. OBJECTIVE _____                                                   | 1             |
| II. RESUME _____                                                     | 1             |
| A. Problem _____                                                     | 1             |
| B. Test Results _____                                                | 1             |
| III. CONCLUSIONS AND RECOMMENDATIONS _____                           | 2             |
| IV. TESTING METHODS _____                                            | 2             |
| A. Propellants _____                                                 | 2             |
| B. Ignition-Delay Tester _____                                       | 3             |
| C. Testing _____                                                     | 4             |
| V. SUMMARY OF RESULTS _____                                          | 5             |
| References _____                                                     | 6             |
|                                                                      | <u>Table</u>  |
| Ignition-Delay Values _____                                          | I             |
| Ignition Tests with Other Fuels _____                                | II            |
|                                                                      | <u>Figure</u> |
| Assembly and Details of Impinging-Stream Ignition-Delay Tester _____ | 1             |
| General Views of Ignition-Delay Tester _____                         | 2             |
| Schematic of Ignition-Delay Tester and Associated System _____       | 3             |
| Typical Oscillograph Record of Ignition-Delay Test _____             | 4             |

CONTRACT FULFILLMENT STATEMENT

This final report completes the fulfillment of Item 10, Amendment 7 to Contract N7onr-462, Task Order III.

SECURITY INFORMATION

# CONFIDENTIAL

Report No. 680

## I. OBJECTIVE

The work described herein was authorized by Amendment 7, Item 10, to Contract N7onr-462, Task Order III, which required an investigation of the ignition delay of triethyl trithiophosphite with specially adjusted nitric acid. Delays were to be measured in a small rocket motor at temperatures of 70, 32, and -40°F, with fuel containing 0, 10, 20, 30, and 40 vol% n-heptane. The nitric acid used in the study was to be adjusted to 1.0% water, 0.5% nitrogen dioxide, and 98.5% nitric acid.

## II. RESUME

### A. PROBLEM

Several contractors have developed laboratory-scale testers for the determination of the delay of spontaneous ignition of rocket fuels with nitric acid (e.g., cf. References 1 and 2). In order to compare results obtained from such equipment with the delays that would actually occur in rocket motors, it is necessary to determine the delays in the various apparatus and in small rocket motors with identical propellants. A program was therefore organized by the Bureau of Aeronautics with this aim in mind. The propellants selected for this study, and furnished to each contractor, were triethyl trithiophosphite, n-heptane, and highly purified nitric acid, the latter to be adjusted to agreed-upon percentages of water and nitrogen dioxide. Each contractor was then to measure the delays in his own tester so that a comparison of the results could be made.

### B. TEST RESULTS

1. A small rocket motor using a single pair of impinging fuel and oxidizer streams, and equipped with a photocell and a pressure pickup, was used for the 55 tests performed during this program. Complete data are given in Section V of this report. Numerous hard starts were obtained with the diluted fuel mixtures, the combustion being so rapid after ignition that excessive pressures resulted. The high pressures caused damage to the photocell assembly or pressure pickup, although only in the last run (with 70% triethyl trithiophosphite and at ambient temperature) was the motor itself damaged.

2. It was possible to obtain reliable values of ignition delay for the 100% and 90% triethyl trithiophosphite. However, many of the tests with the 80% mixture, and all with the 70% mixture, gave hard starts and long, variable ignition delays. As a result, it was considered pointless to continue the tests into the lowest range of triethyl trithiophosphite concentration.

3. The ignition-delay values show no dependence upon concentration or temperature with 100% and 90% triethyl trithiophosphite. The values with more dilute fuel mixtures were so variable that it is not possible to establish any trend.

SECURITY INFORMATION

CONFIDENTIAL

# CONFIDENTIAL

II Resume, B (cont.)

Report No. 680

4. The use of both photocell and chamber-pressure pickup allowed comparison of the time of ignition indicated by these two methods. In all cases in which both were used, the time of ignition was the same by both methods, to within the precision of measurement (0.5 millisecc).

5. The reaction of personnel to exposure to vapors of triethyl trithiophosphite indicated that precautions similar to those prescribed for aniline or hydrazine are necessary in handling this material. However, because of the immediate nausea resulting from exposure to small amounts of the material, the dangers of systemic poisoning are thought to be less than with toxic agents having a more subtle effect.

## III. CONCLUSIONS AND RECOMMENDATIONS

A. It was the primary aim of this work to obtain test data on ignition delay in equipment that duplicated actual rocket motor conditions, for comparison with the results on identical propellants in laboratory testers. This aim has been achieved by determining the composition and temperature ranges over which satisfactory motor ignition could be obtained. The test motor was designed to duplicate as closely as possible the starter motors actually in use, which have been evolved in attempts to make the ignition of a rocket motor reliable under a wide variety of conditions. Thus it is seen that with 100% and 90% triethyl trithiophosphite, over the range of temperatures studied, the ignition delay was short and almost constant. On the other hand, the more dilute mixtures gave the long, variable ignition delays and hard starts that have caused trouble in the past in the design of starting mechanisms and in the selection of propellants for rocket motors.

B. This study indicates that triethyl trithiophosphite exhibits sufficiently short ignition delays at low temperatures to be considered for use as a rocket fuel in cases where hypergolicity is an important factor. The fuel is known, however, to be sensitive to air oxidation and gum formation, and it is thought that in the small-scale tests reported herein, some but not all of the variability was caused by small amounts of air oxidation, well below the level that results in gum formation. At least one other contractor (Reference 3) has recorded variable results with this fuel.

C. It is recommended that further work be done on the correlation of laboratory and test-engine ignition delays, with propellant combinations that are less sensitive to handling techniques.

## IV. TESTING METHODS

### A. PROPELLANTS

1. The nitric acid used in this program was manufactured by the General Chemical Division of the Allied Chemical & Dye Corporation, and was shipped as the frozen solid in as anhydrous a condition as possible. The acid was analyzed and adjusted as nearly as possible to the specifications given in

# CONFIDENTIAL

IV Testing Methods, A (cont.)

Report No. 680

Paragraph I. The adjusted acid was found to contain 98.31%  $\text{HNO}_3$ , 1.09%  $\text{H}_2\text{O}$  (by Karl Fischer titration), 0.56%  $\text{NO}_2$ , and 0.04% solids. The 4-lb lot of acid was divided among 10 bottles, which were stored at  $-80^\circ\text{C}$  until used.

2. The triethyl trithiophosphite was prepared by the California Research Corp., and was furnished in four sealed 0.5-lb glass ampoules. The material received at Aerojet was Serial No. 53070-R, Batch No. 1.

3. The ASTM n-heptane was supplied by the Phillips Petroleum Co.; it was taken from Lot No. 297.

## B. IGNITION-DELAY TESTER

1. The ignition delays were measured in a small motor assembled from standard rocket starter-motor parts, except that the motor chamber consisted of a 1-1/4-in. aluminum alloy elbow (AN833-20D). This arrangement permitted the use of a photocell to record the instant of ignition by the first production of flame. Except for the unusual shape of the chamber, the apparatus was as nearly as possible a duplicate of a standard starter motor. The assembly and details of the apparatus are shown in Figure 1, and three general views in Figure 2. A schematic diagram of the entire system is shown in Figure 3.

2. Six openings were present in the tester:

a. A removable sonic nozzle, 0.205 in. in diameter, was attached to one end of the elbow.

b. A Pyrex window was sealed onto the vertical portion of the elbow. A photocell was placed above this window for observing the time of first appearance of visible reaction.

c. A 1/4-in. fitting in the side of the elbow was connected by 2 in. of 1/4-in. tubing to a pressure pickup. Electronic Bourdon-type and diaphragm reluctance gages were used.

d. Another 1/4-in. fitting in the opposite side of the elbow was connected with a pressure switch. This switch was used to close the propellant valve if a preset chamber pressure was not reached before a preset interval after the start of the test.

e. A 1/8-in. fitting with an 0.039-in. opening was used for introducing the nitric acid into the chamber.

f. Another fitting, with an 0.024-in. hole, was used for directing the fuel against the oxidizer stream. The included angle of the streams was  $45^\circ$ . (Note that Figure 1 shows a different size; the orifice was changed to the above value before calibration.)

# CONFIDENTIAL

IV Testing Methods, B (cont.)

Report No. 680

3. The tester had a volume of 77 cc, giving it an  $L^*$  of 142 in. At the propellant flows used, a chamber pressure of approximately 250 psia was maintained after ignition.

4. The propellant tanks consisted of approximately 16 in. of 3/8-in. aluminum tubing, having a volume of approximately 30 cc each. Nitrogen pressurization was used for the displacement of the propellants, the mixture ratio being controlled by the pressures applied to the separate lines. The storage lines were connected to a standard Aerojet starter valve, in which oxidizer and fuel pintles are yoked together. This valve was actuated by nitrogen supplied by the opening of a solenoid-operated Saval valve. The propellant valve was equipped with a valve-motion indicator on the yoke, giving a record of valve position on the oscillograph. Approximately 4 in. of 1/8-in. stainless steel tubing led from each side of the propellant valve to the ends of the injectors. The valve was set to give a slight acid lead (about 0.1 millisec).

5. Nitric acid was added to the storage line by removing the cap on a cross in the line and filling it from a fresh bottle of acid. The propellant valve was briefly opened to bleed the acid down through the valve. Triethyl trithiophosphite was added through a cross in the fuel line. It was removed by means of a hypodermic syringe from bottles equipped with rubber serum stoppers in order to reduce the exposure to air to a minimum. The fuel was then bled through to the valve.

## C. TESTING

1. All tests were controlled by an electrical sequencing unit. This equipment was normally set to terminate the run if the chamber pressure had not reached 60 psig by 0.10 sec from the time of initiation of the test. At the risk of seriously damaging the equipment, the propellant valve was kept open for 0.25 sec in some cases where ignition appeared to be difficult.

2. Signals from the valve-motion indicator, photocell, and pressure pickup were recorded on a multichannel oscillograph. A typical record is shown as Figure 4. The vertical time traces are 10 millisec apart. "LSV," "Photocell," and " $P_{cs}$ " indicate, respectively, valve position, photocell response, and chamber pressure. Ignition delays were determined from these records by measuring the time interval from the first slow rise in chamber pressure to the point of the first very rapid increase. The photocell trace was used to verify the results obtained by the pressure-rise method. In no case in which both were used was there any perceptible difference between the ignition times by the two methods. Preliminary runs with an open-circuit probe at the impingement point and with commercial WFNA in the propellant lines showed that the time from initial valve motion to impingement averaged 5 millisec. During the testing with the pure propellants it was found that, although the average point of initial pressure rise approximated this calibration, there was a variation of several milliseconds from one test to the next. It was therefore decided that the time of impingement would be taken as the point of the first pressure rise, and not the predetermined factor obtained when the probe was in the motor.

CONFIDENTIAL

# CONFIDENTIAL

IV Testing Methods, C (cont.)

Report No. 680

3. The entire testing unit, including the sections of tubing which contained the fuel and oxidizer, was placed in a bath of circulating trichloroethylene. This bath was cooled with dry ice for the low-temperature tests.

## V. SUMMARY OF RESULTS

A. The ignition-delay values in millisecc are given in Table I. The firings with 100% trithiophosphite show no perceptible trend with temperature. It may well be that a preignition reaction of the fuel and oxidizer mixture in the motor chamber warms up a portion of the reactants enough to obscure the effects of changing temperature of motor walls and bulk propellants. When the trithiophosphite is diluted with n-heptane to 90%, no change in ignition delay either with concentration or temperature is noted. At 80% and below, difficulties with long delays and hard starts were encountered, and reproducibility was very poor. No firings were made at 60%, since the last run at 70% (No. 89) distorted the motor so that the propellant streams no longer impinged. It is apparent that no trend either with temperature or with fuel composition has been established, although it is certain that hard starts and variable performance result from dilution of the hypergolic fuel with a non-hypergolic diluent. This tendency was confirmed independently by the results obtained under a separate program in which a standard motor was employed in tests of mixed alkyl thiophosphite mixtures with JP-4, burned with AN specification WFNA.

B. After every three to four tests the motor was serviced by cleaning it with solvent and blowing it dry with nitrogen. No correlation between test results and servicing of the motor was noted. Just before the last test, the motor was cleaned in hot WFNA, rinsed with water, and blown dry.

C. During the checkout of the equipment, eleven firings were made with mixed alkyl thiophosphites, four with the hydrocarbon fuel HF-D, and one with 65% aniline and 35% furfuryl alcohol, all with AN specification WFNA as oxidizer. The results of these tests are given in Table II. Results with the HF-D are noteworthy, inasmuch as this material is under consideration primarily because of its hypergolic properties. The ignition delay for the one test with the aniline and furfuryl alcohol mixture and WFNA was approximately 1.5 times that obtained for the same mixture with RFNA (Reference 2, Figure 25) in the larger, vertical test engine used by the Jet Propulsion Laboratory.

CONFIDENTIAL

# CONFIDENTIAL

Report No. 680

## REFERENCES

1. Progress Reports No. 5 and 6, Contract NOrd 11338, Phillips Petroleum Co. (Confidential).
2. D. M. Griffin, Progress Report No. 9-30, Jet Propulsion Laboratory, California Institute of Technology, 17 May 1949 (Confidential).
3. Progress Report No. 8, Contract NOrd 11338, Phillips Petroleum Co., October 1952 (Confidential).

CONFIDENTIAL

# CONFIDENTIAL

Report No. 68C

TABLE I  
IGNITION-DELAY VALUES

| Test No. | Vol%<br>(C <sub>2</sub> H <sub>5</sub> S) <sub>3</sub> P | Vol%<br>n-Heptane | Temp<br>°F | Ignition<br>Delay<br>millisec | Remarks                                                         |
|----------|----------------------------------------------------------|-------------------|------------|-------------------------------|-----------------------------------------------------------------|
| 34       | 100                                                      | 0                 | 75         | 6                             |                                                                 |
| 35       | 100                                                      | 0                 | 75         | 7                             |                                                                 |
| 36       | 100                                                      | 0                 | 75         | 7                             |                                                                 |
| 37       | 100                                                      | 0                 | 60         | 46                            |                                                                 |
| 38       | 100                                                      | 0                 | 60         | 19                            | Flameout after ignition                                         |
| 39       | 100                                                      | 0                 | 60         | 11                            |                                                                 |
| 40       | 100                                                      | 0                 | 60         | 5                             |                                                                 |
|          |                                                          |                   |            |                               | Mean value, 6 millisec, neglecting<br>Tests No. 37, 38, and 39. |
| 41       | 100                                                      | 0                 | 28         | 5                             |                                                                 |
| 42       | 100                                                      | 0                 | 30         | 6                             |                                                                 |
| 43       | 100                                                      | 0                 | 28         | 6                             |                                                                 |
|          |                                                          |                   |            |                               | Mean value, 6 millisec                                          |
| 44       | 100                                                      | 0                 | -38        | 5                             |                                                                 |
| 45       | 100                                                      | 0                 | -39        | 6                             |                                                                 |
| 46       | 100                                                      | 0                 | -41        | 5                             |                                                                 |
|          |                                                          |                   |            |                               | Mean value, 5 millisec                                          |
| 51       | 90                                                       | 10                | 80         | 6                             | P <sub>c</sub> pickup damaged                                   |
| 62       | 90                                                       | 10                | 77         | 6                             |                                                                 |
| 63       | 90                                                       | 10                | 77         | 6                             |                                                                 |
| 64       | 90                                                       | 10                | 76         | 5                             |                                                                 |
| 52       | 90                                                       | 10                | 60         | 6                             | No photocell                                                    |
| 53       | 90                                                       | 10                | 60         | 5                             | No photocell                                                    |
| 54       | 90                                                       | 10                | 60         | 5                             | No photocell                                                    |
| 55       | 90                                                       | 10                | 60         | 6                             | No photocell                                                    |
|          |                                                          |                   |            |                               | Mean value, 6 millisec                                          |
| 56       | 90                                                       | 10                | 24         | 6                             |                                                                 |
| 57       | 90                                                       | 10                | 24         | 6                             |                                                                 |
| 58       | 90                                                       | 10                | 25         | 7                             |                                                                 |
|          |                                                          |                   |            |                               | Mean value, 6 millisec                                          |
| 59       | 90                                                       | 10                | -38        | 4                             |                                                                 |
| 60       | 90                                                       | 10                | -38        | 6                             |                                                                 |
| 61       | 90                                                       | 10                | -38        | 5                             |                                                                 |
|          |                                                          |                   |            |                               | Mean value, 5 millisec                                          |
| 48       | 80                                                       | 20                | 70         | 185                           | Photocell destroyed and 1500-psi<br>pickup damaged              |
| 49       | 80                                                       | 20                | 70         | 79                            | 1500-psi pickup damaged; no photocell                           |
| 50       | 80                                                       | 20                | 70         | 68                            | 3000-psi pickup damaged; no photocell                           |

Table I  
Sheet 1 of 2

# CONFIDENTIAL

# CONFIDENTIAL

Report No. 680

TABLE I (cont.)

| Test No. | Vol%<br>(C <sub>2</sub> H <sub>5</sub> S) <sub>3</sub> P | Vol%<br>n-Heptane | Temp<br>°F | Ignition<br>Delay<br>millisec | Remarks                                                                                                                                                                                                 |
|----------|----------------------------------------------------------|-------------------|------------|-------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 65       | 80                                                       | 20                | 60         | >160                          | Malfunction control terminated run before ignition                                                                                                                                                      |
| 66       | 80                                                       | 20                | 60         | 215                           | 3000-psi pickup damaged; no photocell                                                                                                                                                                   |
| 67       | 80                                                       | 20                | 64         | 8                             | Different fuel mixture from that used above because of possible exposure of other fuel to air; no photocell                                                                                             |
| 68       | 80                                                       | 20                | 64         | 8                             | No photocell                                                                                                                                                                                            |
| 69       | 80                                                       | 20                | 64         | 7                             | No photocell                                                                                                                                                                                            |
| 70       | 80                                                       | 20                | 65         | 14                            | No photocell                                                                                                                                                                                            |
| 74       | 80                                                       | 20                | 60         | 113                           | No photocell; new fuel mixture because of hard starts on Runs 72 and 73                                                                                                                                 |
| 75       | 80                                                       | 20                | 60         | 74                            | No photocell                                                                                                                                                                                            |
| 76       | 80                                                       | 20                | 60         | 47                            | No photocell                                                                                                                                                                                            |
| 77       | 80                                                       | 20                | 60         | 11                            | No photocell                                                                                                                                                                                            |
| 78       | 80                                                       | 20                | 30         | 19                            | No photocell                                                                                                                                                                                            |
| 79       | 80                                                       | 20                | 31         | 19                            | No photocell                                                                                                                                                                                            |
| 80       | 80                                                       | 20                | 32         | 18                            | No photocell                                                                                                                                                                                            |
| 71       | 80                                                       | 20                | -42        | 8                             | No photocell                                                                                                                                                                                            |
| 72       | 80                                                       | 20                | -40        | 52                            | Pickup damaged                                                                                                                                                                                          |
| 73       | 80                                                       | 20                | -40        | 94                            | Pickup damaged; photocell destroyed                                                                                                                                                                     |
| 85       | 70                                                       | 30                | 60         | 175                           | No photocell; pickup damaged                                                                                                                                                                            |
| 86       | 70                                                       | 30                | 60         | 219                           | No photocell; pickup damaged                                                                                                                                                                            |
| 87       | 70                                                       | 30                | 60         | 213                           | No photocell; pickup damaged                                                                                                                                                                            |
| 89       | 70                                                       | 30                | 70         | ca. 71                        | No pickup on; delay obtained by subtracting 5 millisec from time of valve opening to photocell trace rise before it was destroyed; motor had been cleaned in hot WFNA and impingment checked beforehand |
| 88       | 70                                                       | 30                | -38        | 99                            | No photocell; reluctance pickup seriously damaged and cap on vertical arm bulged                                                                                                                        |
|          | 60                                                       | 40                |            |                               | No tests made                                                                                                                                                                                           |

Table I  
Sheet 2 of 2

# CONFIDENTIAL

# CONFIDENTIAL

Report No. 680


TABLE II

## IGNITION TESTS WITH OTHER FUELS

| <u>Run No.</u> | <u>Fuel</u>                           | <u>Ignition Delay, millisec</u>        | <u>Temp, °F</u> |
|----------------|---------------------------------------|----------------------------------------|-----------------|
| 23             | Crude mixed alkyl<br>thiophosphites   | 12                                     | 70              |
| 24             | ↓                                     | 11                                     | 70              |
| 25             |                                       | 9                                      | 70              |
| 26             |                                       | No ignition                            | -40             |
| 27             |                                       | 18                                     | -40             |
| 28             |                                       | 62 (Poor run, low<br>chamber pressure) | -40             |
| 29             |                                       | No ignition                            | -40             |
| 30             |                                       | No ignition                            | 65              |
| 31             |                                       | No ignition                            | 65              |
| 32             |                                       | 11 (new fuel<br>and oxidizer)          | 60              |
| 33             |                                       | 12                                     | -40             |
| 22             | 65% aniline - 35%<br>furfuryl alcohol | 42                                     | 70              |
| 18             | HF-D                                  | No ignition                            | 70              |
| 19             | ↓                                     | ↓                                      | 70              |
| 20             |                                       |                                        | 70              |
| 21             |                                       |                                        | 70              |

Table II

# CONFIDENTIAL



⚠ OXIDIZER JET NOT SHOWN




SERIES D46LF  
PG. 2698  
W.O. 2817

Assembly and Details of Impinging-Stream Ignition-Delay Tester

Figure 1

R E S T R I C T E D


Report No. 680



General Views of Ignition-Delay Tester

Figure 2


R E S T R I C T E D



SERIES D46LF  
PG. 2698  
W.O. 2817

Schematic of Ignition-Delay Tester and Associated System

Report No. 633



### Typical Oscillograph Record of Ignition-Delay Test

SECURITY INFORMATION  
R E S T R I C T E D

Figure 1

UNCLASSIFIED

AD \_\_\_\_\_

DEFENSE DOCUMENTATION CENTER

FOR

SCIENTIFIC AND TECHNICAL INFORMATION

CAMERON STATION ALEXANDRIA, VIRGINIA

DOWNGRADED AT 3 YEAR INTERVALS:  
DECLASSIFIED AFTER 12 YEARS  
DCD DIR 5200.10



UNCLASSIFIED