

UNCLASSIFIED

AD NUMBER	
AD035575	
CLASSIFICATION CHANGES	
TO:	unclassified
FROM:	restricted
LIMITATION CHANGES	
TO:	Approved for public release, distribution unlimited
FROM:	Distribution authorized to U.S. Gov't. agencies and their contractors; Administrative/Operational Use; 03 DEC 1953. Other requests shall be referred to Naval Proving Ground, Dahlgren, VA.
AUTHORITY	
USNSWC ltr, 10 Jul 1975; USNSWC ltr, 10 Jul 1975	

THIS PAGE IS UNCLASSIFIED

Armed Services Technical Information Agency

Because of our limited supply, you are requested to return this copy WHEN IT HAS SERVED YOUR PURPOSE so that it may be made available to other requesters. Your cooperation will be appreciated.

AD

35575

NOTICE: WHEN GOVERNMENT OR OTHER DRAWINGS, SPECIFICATIONS OR OTHER DATA ARE USED FOR ANY PURPOSE OTHER THAN IN CONNECTION WITH A DEFINITELY RELATED GOVERNMENT PROCUREMENT OPERATION, THE U. S. GOVERNMENT THEREBY INCURS NO RESPONSIBILITY, NOR ANY OBLIGATION WHATSOEVER; AND THE FACT THAT THE GOVERNMENT MAY HAVE FORMULATED, FURNISHED, OR IN ANY WAY SUPPLIED THE SAID DRAWINGS, SPECIFICATIONS, OR OTHER DATA IS NOT TO BE REGARDED BY IMPLICATION OR OTHERWISE AS IN ANY MANNER LICENSING THE HOLDER OR ANY OTHER PERSON OR CORPORATION, OR CONVEYING ANY RIGHTS OR PERMISSION TO MANUFACTURE, USE OR SELL ANY PATENTED INVENTION THAT MAY IN ANY WAY BE RELATED THERETO.

Reproduced by
DOCUMENT SERVICE CENTER
KNOTT BUILDING, DAYTON, 2, OHIO

UNCLASSIFIED

U. S. NAVAL PROVING GROUND
DAHLGREN, VIRGINIA

REPORT NO. 1208

20MM AIRCRAFT GUNS, AN-M3 AND AN-M24
EXPERIMENTAL AND DEVELOPMENTAL TESTS

12th Partial Report

20MM AMMUNITION ASSIST FEEDER
DEVELOPED BY HARVEY MACHINE CO.

FINAL Report

Task
Assignment NPQ-Rese-102-20-52

Copy No. _____

Classification RESTRICTED
SECURITY INFORMATION

UNCLASSIFIED

UNCLASSIFIED

NPO REPORT NO. 1208

**20mm Ammunition Assist Feeder
Developed by Harvey Machine Company**

PART A

SYNOPSIS

1. This report covers the evaluation of a Harvey Assist Feeder in conjunction with 20mm aircraft gun Mk 16 as suggested by reference (b). The salient features that were to be designed into the mechanism are outlined as follows:

a. Supplies ammunition to gun feeder at essentially zero belt load regardless of belt pull between ammunition box and booster. This increases the reliability and possibly the average rate of fire.

b. Reduces "belt whip" by providing 1 1/2 rounds which can be withdrawn from the reservoir without any movement of the belt at the beginning of a burst. This reservoir action also cushions the stopping of the belt.

c. Prevents starving of gun during single shot or short burst operation (a condition which occurs in ammunition systems using ordinary booster).

d. Prevents overfeeding of gun through quick release action of single plate type magnetic clutch and "cushion" effect of reservoir.

e. Greatly reduces maximum current drain during starting under load, through unique idling system.

2. On basis of the results it is concluded that:

a. The Harvey Assist Feeder did not perform the task that it is designed to do, at least, not in conjunction with the 20mm aircraft gun Mk 16. Insufficient tests were conducted to definitely establish its performance in conjunction with the 20mm aircraft gun AN-M3.

b. No definite conclusions can be drawn concerning the location of defects in the design of booster since a completely satisfactory operation was never obtained. The tests were terminated after the anti-roll back ratchet wheel had failed.

RESTRICTED
SECURITY INFORMATION

UNCLASSIFIED

~~RESTRICTED~~

NPG REPORT NO. 1208

20mm Ammunition Assist Feeder
Developed by Harvey Machine Company

TABLE OF CONTENTS

	<u>Page</u>
SYNOPSIS.	1
TABLE OF CONTENTS	2
AUTHORITY	3
REFERENCES.	3
OBJECT OF TEST.	3
PERIOD OF TEST.	3
DESCRIPTION OF ITEM UNDER TEST.	4
DESCRIPTION OF TEST EQUIPMENT	5
PROCEDURE	5
RESULTS AND DISCUSSION.	6
CONCLUSIONS	7
APPENDIX A - TABULATED FIRING DATA.	1-7 (Incl)
APPENDIX B - NPG PHOTOGRAPHS.	FIGURES 1-7 (Incl)
APPENDIX C - DISTRIBUTION	1-2 (Incl)

~~RESTRICTED~~
~~SECURITY INFORMATION~~

20mm Ammunition Assist Feeder
Developed by Harvey Machine Company

PART C

DETAILS OF TEST

5. DESCRIPTION OF ITEM UNDER TEST:

The Harvey Assist Feeder or Booster, shown in Figures 2 and 3, is designed to assist the feeding of the ammunition to the gun on the demand of the gun feed mechanism. This feeding action is accomplished by a 24 volt D.C. motor geared to a sprocket wheel through planetary reduction gears. The booster incorporates a single plate-type magnetic clutch and an ammunition reservoir having one and one half rounds capacity. A quick release action in the magnetic clutch is designed to prevent overfeeding of the gun feed mechanism. The electric motor in the booster idles at half speed when the gun arming switch is closed and the ammunition reservoir is filled with ammunition. This reduces the electric current required at the beginning of a burst and permits quicker acceleration of the sprocket wheel. When the gun feed mechanism pulls on the ammunition belt the magnetic clutch switch is actuated and the clutch is engaged. The sprocket then assists in feeding ammunition to the gun as long as the clutch is engaged. The sprocket wheel free wheels at 135 rpm and has nine sprockets. When the firing switch is released, the booster continues to feed until the ammunition belt depresses the clutch switch which in turn disengages the sprocket wheel from the motor. The motor resumes half speed operation until either the gun is fired again or the arming switch is turned off. To remove the ammunition belt from the booster in a direction opposite to feed, it is necessary to release the anti-roll back device in the motor. This is done by rotating the depressed slotted pin located in one end of the motor.

20mm Ammunition Assist Feeder
Developed by Harvey Machine Company

6. DESCRIPTION OF TEST EQUIPMENT:

a. The following test equipment was used for the evaluation of the booster:

- (1) Batteries and a generator as a source for direct current electricity.
- (2) 20mm aircraft guns Mk 16 and AN-M3.
- (3) 20mm feed mechanisms Mk 8 Mod 0 and AN-M2.
- (4) Rigid box type gun mounts.
- (5) Two pieces of ammunition chuting each 3 feet long and a wooden ammunition box.
- (6) High speed movie camera, 35mm.
- (7) 20mm ammunition links MSEI made by L. A. Young and Company.
- (8) Heiland Recording Oscillograph.
- (9) 20mm Ammunition, M90 series - 3745 rounds.

b. A photograph of the test setup is shown in Figure (1).

7. PROCEDURE:

A standard 20mm aircraft gun Mk 16 was used in the major portion of the evaluation. Various length bursts, both continuous and interrupted, up to 270 rounds were fired at ambient temperatures. The booster, energized by 27 volts D.C. from either batteries or generated power, was located approximately midway between the ammunition box and the gun feed mechanism. About three feet of ammunition chuting was attached to each end of the booster. The chuting was fixed rigidly on a wooden platform. For portions of the tests the voltage to the booster was changed to as high as 31 volts since it was suspected that the motor speed during feeding was not high enough to keep the gun feed mechanism supplied with ammunition. Also, the action of belt motion in the booster was studied by high speed motion pictures. The action of the clutch switch as well as the current and voltage supplied to booster motor were recorded by a Heiland Recording Oscillograph.

20mm Ammunition Assist Feeder
Developed by Harvey Machine Company

8. RESULTS AND DISCUSSION:

Complete detailed results are included as Appendix (A). The results show that the booster does not supply ammunition at the rate required by a 20mm aircraft gun Mk 16 as is evidenced by failures to feed, link deformations on the outboard side of the gun feed mechanism belt retaining pawls, and belt separations between the gun feed mechanism and the booster. Only 19 of 64 attempts, exclusive of belt pull tests and stoppages from other causes, were successfully fired out. The tests were terminated because of the failure of the anti-roll back ratchet wheel in the booster before it was established whether this inability to maintain adequate ammunition supply was caused by the faster firing rate of 20mm aircraft gun Mk 16 (about 790 rpm as compared to 740 rpm using an AN-M3 gun) or by the more severe nature on belt motion of intermittent reciprocating feeding action of the Mk 8 feed mechanism as compared to more uniform flow of ammunition in the rotary action of the AN-M2 feed mechanism. Each of the three firing attempts made with a 20mm aircraft gun AN-M3 was a successful fireout. Even though the failures to feed cannot all be blamed on the booster, about one third of the failures to feed were accompanied by stretched links. This would indicate that a sizeable ratio of the failures to feed were directly chargeable to the booster. The motion pictures showed that there was considerable tension applied intermittently to the ammunition belt as it passes through the booster. A sequence of events taken from the motion pictures is included as Figure 6. The oscillograms showed that the clutch switch is open about 3/7 of the gun firing cycle, but that the clutch rarely disengages. It is seen from Figure 5 that the clutch pull-in is very rapid, about the order of 1 millisecond, but that the drop out is in excess of 50 milliseconds. The disturbances noted by both the voltage and current element in the motor circuit is apparently caused by surge of current drawn by the magnetic clutch slipping because of lubricants or other foreign materials on the faces of the plates. This was obviated by thoroughly cleaning them twice during the tests. While somewhat improved operation was obtained after the second cleaning, the belt separation and failures to feed were not entirely eliminated. The results appear anomalous, however, in that one form of gun feed malfunction which had been prevalent in previous firings of Mk 8 feed mechanisms using the same links was not noted in these tests. The double loops of the belt link deformed toward each other sufficiently permitting the link to ride off the stripper. The link would tend to follow the round into the feed throat causing a gun stoppage. Those links had a Rockwell C-38 hardness which is within the limits specified by

RESTRICTED

NPG REPORT NO. 1208

20mm Ammunition Assist Feeder
Developed by Harvey Machine Company

BUORD Dwg. 7238242. It was later found that links having Rockwell C-46 would function satisfactorily in the 20mm feed mechanism Mk 8. The motor load current and voltage was an average about 11 amperes and 23 volts D.C. The transient current at the beginning of a burst is approximately as high as 65 amperes under normal starting conditions without any extraneous load applied to the belt. The transient period is about 85 milliseconds under the same conditions.

PART D

CONCLUSIONS

9. On basis of the results it is concluded that:

a. The Harvey Assist Feeder did not perform the task that it is designed to do, at least, not in conjunction with the 20mm aircraft gun Mk 16. Insufficient tests were conducted to definitely establish its performance in conjunction with the 20mm aircraft gun AN-M3.

b. No definite conclusions can be drawn concerning the location of defects in the design of booster since completely satisfactory operation was never obtained. The tests were terminated after the anti-roll back ratchet wheel had failed.

UNCLASSIFIED

UNCLASSIFIED
RESTRICTED
SECURITY INFORMATION

RESTRICTED

NPG REPORT NO. 1208

20mm Ammunition Assist Feeder
Developed by Harvey Machine Company

The investigation upon which this report is based was conducted by:
J. V. BLANTON, Accessories and Ammunition Development Branch
Aircraft Armament Division
Aviation Ordnance Department

This report was prepared by:
JOHN PINKER, JR., Head Engineer,
Aircraft Armament Division
Aviation Ordnance Department

This report was reviewed by:
L. D. RUCKER, Lieutenant Commander, USNR
Aircraft Armament Officer
Aviation Ordnance Department
J. C. TALLEY, Director of Research
Aviation Ordnance Department
F. A. NUSOM, Captain, USN
Aviation Ordnance Officer
Aviation Ordnance Department
C. C. BRAMBLE, Director of Research, Ordnance Group

APPROVED: J. F. BYRNE
Captain, USN
Commander, Naval Proving Ground



E. A. RUCKNER
Captain, USN
Ordnance Officer
By direction

UNCLASSIFIED
RESTRICTED
SECURITY INFORMATION

UNCLASSIFIED

~~RESTRICTED~~

UNCLASSIFIED

NPO REPORT NO. 1208

U. S. NAVAL PROVING GROUND
DAHLGREN, VIRGINIA

Twelfth Partial Report

on

20mm Aircraft Guns, AN-M3 and AN-M24
Experimental and Developmental Tests

Final Report

on

20mm Ammunition Assist Feeder
Developed by Harvey Machine Company

Classification cancelled in accordance with
Executive Order 11652, dated August 14, 1953

J. D. Dill
8/4/54

Naval Proving Ground
Dahlgren, Virginia Agency

Project No.: NPG-RO8a-108-20-52
No. of Pages: 8

Date: DEC 3-1953

~~RESTRICTED~~
~~UNCLASSIFIED~~

UNCLASSIFIED

UNCLASSIFIED

20m Ammunition Aviator Powder Developed by Harvey Machine Company

STG REPORT NO. 2748

PARAMETER FIELD DATA

20m Aircraft Gun, M1 IS Serial Number 6100

Date	Rounds		Total Rounds on Gun	Capsule (RPM)	Total Rounds on Powder	Powder Air Pressure (PSI)	Harvey Ammunition Shooter Total Rounds	Killing Voltage V.D.C.	Killing Current AMP	Surge Voltage V.D.C.	Surge Current AMP	Operating Voltage V.D.C.	Operating Current AMP	Average This Class		
	In	Out												Class	Class	
2-1-52	APPROXIMATE NUMBER LOCATED IN FIELD															
2-1-52	230	20	9439	768	180	600	24	-	-	-	-	-	-	-	-	-
2-1-52	221	167	3508	767	447	600	148	-	-	-	-	-	-	-	-	-
2-1-52	52	58	3618	-	309	600	145	-	-	-	-	-	-	-	-	-
2-1-52	250	30	1656	765	437	600	203	-	-	-	-	-	-	-	-	-
2-1-52	212	16	5711	767	433	600	216	-	-	-	-	-	-	-	-	-
2-1-52	197	19	6730	760	471	600	217	-	-	-	-	-	-	-	-	-
2-2-52	GUN 8120 (8730 ROUNDS) REPLACED WITH 272 2248 (1948 ROUNDS). M1. 8-0 FEEDER M1-11 (471 ROUNDS) REPLACED WITH M1-10 (2115 ROUNDS) WHICH WAS CHECKED PER R.L. TO L.E.															
2-2-52	200	2	1548	-	2317	600	219	-	-	-	-	-	-	-	-	-
2-2-52	198	6	1561	719	2028	600	226	-	-	-	-	-	-	-	-	-
2-2-52	182	10	1561	720	2333	600	234	-	-	-	-	-	-	-	-	-
2-2-52	162	16	1576	-	2348	600	240	-	-	-	-	-	-	-	-	-
2-2-52	35	20	1586	763	2368	600	240	-	-	-	-	-	-	-	-	-
2-2-52	107	107	1703	772	2473	600	437	-	-	-	-	-	-	-	-	-
2-2-52	280	63	1786	764	2187	600	509	-	-	-	-	-	-	-	-	-
2-2-52	210	186	1953	770	2723	600	707	-	-	-	-	-	-	-	-	-
2-2-52	250	35	1980	770	2780	600	742	-	-	-	-	-	-	-	-	-
2-2-52	215	149	2137	770	2809	600	831	-	-	-	-	-	-	-	-	-
2-3-52	M1. 8 FEEDER M1-10 CLEARED AND RECALIBRATED. FEEDER FLOOR FROM M1-3 USED WITH FEEDER MOTOR M1-10.															

Rounds stacked high on feeder and plate. Run on last barrel. Fired and satisfactorily. Failures to feed. Round not down in time to be observed by both. Failures to feed. Single loop of link checked very badly. Run on last barrel.

Coiled round in feeder. Run on last barrel. Round failed to get down in time. Single loop of link from last round fired satisfactorily. Run on last barrel.

Ammunition binocular not used for this barrel only. Bolt runs under round. Fired and satisfactorily. Round fired and down very badly. Round failed to get down in time. Failures to feed. Round not down in time to be observed by both. Run on last barrel.

APPENDIX A

UNCLASSIFIED

RESTRICTED

Some Ammunition Loaded Powder Developed by Harvey Machine Company

HW REPORT NO. 1248

TABLED TESTS DATA (Continued)

Some Aircraft Gun, M 18 Serial Number 2248

Date	Rounds in Bin	Rounds Fired	Total Rounds on Gun	Cyclic Rate (RPM)	Total Rounds on Powder	Powder Air Pressure (PSI)	Harvey Ammunition Bin Total Rounds	Milling Voltage V.D.C.	Milling Current AMPS	Peak Surge Voltage V.D.C.	Surge Current AMPS	Operating Voltage V.D.C.	Operating Current AMPS	Average Bin Current (Milliamps)	Average Bin Voltage (Milliamps)	Average Bin Temp (F)	Remarks
2-6-52	250	22	228	775	3001	800	982	-	-	-	-	-	-	-	-	-	Bin voltage about 1/2 inch position sliding air to escape from gun barrel. Bin on last level.
2-5-52	150	61	210	775	3002	800	1044	-	-	-	-	-	-	-	-	-	Bin on last level. Powder water wetness not indicated with "3-4" (higher in com- parison than dry test green). Powder over aging replaced.
2-13-52	34	32	204	-	3412	800	1096	-	-	-	-	-	-	-	-	-	Filed with satisfactorily.
2-13-52	33	33	278	-	3465	800	1087	-	6	44	-	10	40	41	-	-	Filed with satisfactorily.
2-13-52	215	15	230	-	3460	800	1065	-	6	57	-	13	48	48	-	-	Filed with plate on Chamber floor observed off. In indication of what is each round. Powder M-7 (M8 rounds) installed. Ammunition found to show an entrance to ammunition bin (from ammunition box) containing both separation of powder. Failure to feed. Round failed to get down in this to be observed by bin. Bin on last level.
2-13-52	203	68	271	-	337	800	1085	-	6	43	-	10	46	46	-	-	Bin on last level. (from ammunition box) containing both separation of powder. Failure to feed. Round failed to get down in this to be observed by bin. Bin on last level.
2-13-52	120	34	254	-	343	800	1088	-	6	48	-	10	43	43	-	-	Bin on last level. (from ammunition box) containing both separation of powder. Failure to feed. Round failed to get down in this to be observed by bin. Bin on last level.
2-13-52	86	10	281	-	371	800	1049	-	6	43	-	11	43	43	-	-	Bin on last level. (from ammunition box) containing both separation of powder. Failure to feed. Round failed to get down in this to be observed by bin. Bin on last level.
2-13-52	76	9	282	-	380	800	1078	-	6	43	-	11	43	43	-	-	Bin on last level. (from ammunition box) containing both separation of powder. Failure to feed. Round failed to get down in this to be observed by bin. Bin on last level.
2-14-52	100	5	287	-	328	800	1088	-	6	43	-	10	43	43	-	-	Bin on last level. (from ammunition box) containing both separation of powder. Failure to feed. Round failed to get down in this to be observed by bin. Bin on last level.
2-10-52	138	9	230	750	318	800	1088	-	6	43	-	10	43	43	-	-	Bin on last level. (from ammunition box) containing both separation of powder. Failure to feed. Round failed to get down in this to be observed by bin. Bin on last level.
2-10-52	119	11	230	709	625	800	1085	-	6	43	-	9	43	43	-	-	Bin on last level. (from ammunition box) containing both separation of powder. Failure to feed. Round failed to get down in this to be observed by bin. Bin on last level.
2-10-52	118	28	238	704	640	800	1085	-	6	43	-	9	43	43	-	-	Bin on last level. (from ammunition box) containing both separation of powder. Failure to feed. Round failed to get down in this to be observed by bin. Bin on last level.
2-10-52	88	31	219	711	671	800	1089	7	6	18	23	10	43	43	-	-	Bin on last level. (from ammunition box) containing both separation of powder. Failure to feed. Round failed to get down in this to be observed by bin. Bin on last level.
2-10-52	107	34	241	711	686	800	1085	6	6	18	24	11	43	43	-	-	Bin on last level. (from ammunition box) containing both separation of powder. Failure to feed. Round failed to get down in this to be observed by bin. Bin on last level.
2-10-52	200	34	234	712	819	800	1177	6	5	16	23	13	43	43	-	-	Bin on last level. (from ammunition box) containing both separation of powder. Failure to feed. Round failed to get down in this to be observed by bin. Bin on last level.
2-10-52	180	29	209	-	548	800	1166	10	5	18	23	10	43	43	-	-	Bin on last level. (from ammunition box) containing both separation of powder. Failure to feed. Round failed to get down in this to be observed by bin. Bin on last level.
2-10-52	251	5	256	-	543	800	1161	-	-	-	-	-	-	-	-	-	Bin on last level. (from ammunition box) containing both separation of powder. Failure to feed. Round failed to get down in this to be observed by bin. Bin on last level.
2-10-52	218	13	230	714	688	800	1088	9	8	18	23	10	43	43	-	-	Bin on last level. (from ammunition box) containing both separation of powder. Failure to feed. Round failed to get down in this to be observed by bin. Bin on last level.

RESTRICTED SECURITY INFORMATION

APPENDIX A

UNCLASSIFIED

Continued

How Ammunition Loaded Powder Developed by Survey Machine Company

EPO REPORT NO. 1218

INCULCATED FIRING DATA (Continued)

How Aircraft's Gun, M2 16 Serial Number 2288

Date	Rounds In Bolt Fired		Total Rounds on Gun	Total Rounds on	Opalle Made (PBI)	Total Rounds	Powder Ammunition		Total Powder	Milling V.D.C. AMP	Milling Current	Surge V.D.C. AMP	Surge Current	Peak Surge V.D.C. AMP	Operating Voltage V.D.C.	Operating Current AMP	Average Time	
	Bolt	240					Aluminum	Aluminum									Classified	Classified
2-18-52	18	240	258	258	708	600	1800	000	000	-	-	-	-	-	-	-	29	80
2-18-52	4	240	244	244	708	600	1800	000	000	-	-	-	-	-	-	-	-	-
2-18-52	7	240	247	247	716	600	1801	000	000	-	-	-	-	-	-	-	-	-
2-18-52	18	229	247	247	708	600	1800	000	000	-	-	-	-	-	-	-	-	-
2-18-52	29	240	269	269	707	600	1800	000	000	-	-	-	-	-	-	-	-	-
2-18-52	18	240	258	258	708	600	1800	000	000	-	-	-	-	-	-	-	-	-
2-18-52	189	240	429	429	708	600	1800	000	000	-	-	-	-	-	-	-	-	-
2-18-52	159	240	399	399	708	600	1800	000	000	-	-	-	-	-	-	-	-	-
2-18-52	158	240	398	398	708	600	1800	000	000	-	-	-	-	-	-	-	-	-
2-28-52	200	240	400	400	186	600	1801	000	000	-	-	-	-	-	-	-	-	-
2-28-52	186	240	376	376	176	600	1876	000	000	-	-	-	-	-	-	-	-	-
2-28-52	181	240	361	361	186	600	1876	000	000	-	-	-	-	-	-	-	-	-
2-28-52	178	240	358	358	186	600	1888	000	000	-	-	-	-	-	-	-	-	-
2-28-52	17	240	257	257	186	600	1888	000	000	-	-	-	-	-	-	-	-	-
2-28-52	20	240	260	260	186	600	1898	000	000	-	-	-	-	-	-	-	-	-
2-28-52	108	240	348	348	186	600	1898	000	000	-	-	-	-	-	-	-	-	-
2-28-52	189	240	369	369	186	600	1909	000	000	-	-	-	-	-	-	-	-	-
2-28-52	168	240	336	336	186	600	1917	000	000	-	-	-	-	-	-	-	-	-

Summary

Bolt operation at booster belt holding position. Single loop of link on last round fired. Although on booster reduced to 18 v D.C. Gun stopped on above. Same as above. Station generator power. Same as above. Booster taken out of circuit. Fired out satisfactorily. 18 v D.C. input to ammunition booster. Bolt failed to get down in time to be taken home by belt. Same as above. 18 link in link - both ends cleared coming gun stoppage - breeching block crushed behind case (M28 rounds) replaced with standard M2 link. The Survey Booster was disassembled and aluminum plates cleaned.

On disassembly of booster M-7 for routine cleaning the following components broken: rubber buffer washers, shuttle crushed and shuttle stop plate badly battered. Powder M-2A substituted. 17 v D.C. from batteries applied to booster. Single loop of link on last round fired. Gun stopped very badly. 18 v D.C. applied to booster from batteries - gun stopped on above. 18 v D.C. applied to booster from batteries. Bolt home on empty chamber. Found on top of belt. Same as above. Survey booster not used this burst. Belt home empty. Found on top of belt. Same as above. Survey booster not used this burst. Although reduced to 18 v D.C. Gun revolved several times. Fired out satisfactorily. Single loop of link attached very badly. Bolt reds under round.

APPENDIX A

From Ammunition Assn. Powder Developed by Berney Machine Company

1270 REPORT NO. 1208

TABLED FIRING DATA (Continued)

From Alford's Gun, No. 18 Serial Number 2168

Date	Rounds In Belt Fired	Total Rounds on Gun	Total Spalls in the Powder (P.F.)	Powder Air Pressure (P.F.)	Total Ammunition Used	Landing		Peak		Average Time		
						Current V.D.C.	Voltage V.D.C.	Current V.D.C.	Voltage V.D.C.	Micro-Switch Closed	Click	Micro-Switch Open
2-21-52	8	3469	50	800	3180	-	-	-	-	-	-	
2-25-52	65	3244	47	600	2278	-	-	-	-	-	-	
2-25-52	150	3437	50	600	2318	-	-	-	-	-	-	
2-26-52 600 PSI APPLIED TO FEEDER. 27 V.D.C. (MATTERIES) APPLIED TO GUN BELLETRID AND BARRETT MOUNTS.												
2-26-52	20	2641	50	600	2135	2	7	8	20	10	20	
2-26-52	162	327	80	60	2436	-	-	-	-	-	-	
2-27-52 600 PSI APPLIED TO GUN FEEDER AND 27 V.D.C. APPLIED TO MOUNTS. NEW OSCILLOSCOPE, STANDARD BAY BELLETRID AS BEFORE. CURRENT ACROSS MICRO-SWITCH TO INDICATE OPERATION OF GUN. FIRST THREE TESTS WILL NOT HAVE POWER APPLIED TO FEEDER SO GUN FEEDER WILL NOT BE FULL RESPONSIVE THROUGH MOUNTS.												
2-27-52	24	3230	75	600	2302	-	-	-	-	-	-	
2-27-52	25	3233	70	600	2408	-	-	-	-	-	-	
2-27-52	32	3236	76	600	2408	-	-	-	-	-	-	
MOUNTS CLUTCH ASSEMBLY ENGAGED ON SUBSEQUENT TESTS SO THAT MICRO-SWITCH OPERATING DOES NOT GET CLUTCH IN AND OFF												
2-27-52	22	2870	600	750	2462	-	-	-	-	-	-	
2-27-52	188	3810	800	600	2482	-	-	18	97	12	24	
2-27-52	145	3841	796	600	2418	-	-	-	66	16	21	
MOUNTS REWIND TO FEEDER CLUTCH ACTION												
2-27-52	117	3340	-	874	2419	-	-	-	-	-	-	
2-27-52	118	3373	798	800	2648	-	-	-	-	-	-	

Micro-
Switch
Closed
Micro-
Switch
Open
(Milli-sec)

Belt runs under round.
Belt runs under round.
Belt runs under round.
Belt separation on booster side of feeder
Belt holding punch.
This test fired with clutch engaged through-
out test. Micro-switch completely out of
circuit. Intentional gun stoppage.

Single loop of link stretched very badly.
Belt separation at feeder belt holding punch.
Same as above.
Same as above.

Element jammed in booster micro-switch
to check for operation. Intentional gun
stoppage.
Same as above. Intentional gun stoppage.
Same conditions as above.

Belt separation on booster side of feeder
Belt holding punch.
One repeatable. Gun stoppage due to belt
operation.

Every booster although here down - Found
to have very small amount of grease on
clutch plates. Broken coil-spring
upper plate (S) which causes booster belt
to be held to be observed - Are changed and
all in booster to observe condition
to booster.

TABLE 1

REPRODUCED
FROM REPORT NO. 1208

RESTRICTED

20mm Ammunition Assult Powder Developed by Harvey Machine Company

EPO REPORT NO. 1208

TABLED FIRING DATA (Continued)

20mm Assault Gun, M2 16 Serial Number 22825

Date	Rounds in Bolt	Rounds Fired	Total Rounds on Gun	Total Cycles on Gun (M)	Total Rounds on Gun (M)	Powder Air Pressure (PSI)	Barrel Amplification		Milling Voltage V.D.C. MPS	Milling Current MPS	Serge Voltage V.D.C. MPS	Serge Current MPS	Peak Serge Current MPS	Operating Voltage V.D.C. MPS	Operating Current MPS	Average Time		Remarks
							Barrel Factor	Barrel Loss								Close Mills	Open Mills	
3-5-52	106	13	247	162	162	600	2433	7	4	17	88	31	31	11	68	23	Link stand in bolt of M21 linker. Both link and link observed off allowing round to drop down between strippers. On stoppage due to empty round in bolt. In addition to the 66 rounds in the feed tray, a 20 pound bolt load was applied to the ammunition belt. Substantial gas stoppage.	
3-5-52	153	63	480	791	1575	600	2458	-	-	-	-	-	-	-	-	-	-	Bolt not loose empty. Single loop of link on last round fired stretched very badly. 20 pound bolt load applied to ammunition belt. Failure to eject. Striker and extractor spring broken. Single loop of link on last round fired stretched very badly.
3-8-52	64	50	480	787	125	600	2423	6	7	17	87	28	31	16	62	61	20	Substantial gas stoppage. On replicated bolt times. Anti-rail hook device in Harvey brother broken. 20 pound bolt load applied to ammunition belt.
3-9-52	64	7	487	-	1622	600	2478	6	8	17	88	31	31	17	61	61	20	Bolt load increased to 75 pounds. On fail-ure due to failure of anti-rail hook device mentioned above.
3-9-52	67	6	481	-	1626	600	2483	-	-	-	-	-	-	-	-	-	-	75 pound bolt load. Badly stretched single loop of link on last round fired. Bolt extraction on boomer side of tender bolt holding pins.
3-9-52	64	26	488	781	1621	600	2486	7	6	16	86	21	31	17	61	61	20	Same as last burst.
3-8-52	64	4	480	-	1623	600	2482	8	6	16	88	21	31	18	60	60	20	Same as last burst.
3-11-52	64	6	486	-	1639	600	2488	8	6	16	88	21	31	17	-	-	-	Same as last burst.
3-11-52	60	3	487	-	1672	600	2489	6	6	16	86	22	31	19	-	-	-	Under electric valve stand in imminent position allowing air to escape. 75 pound bolt load.
3-11-52	64	8	503	-	1677	600	2474	10	6	16	88	22	31	18	-	-	-	
3-11-52	64	3	508	-	1630	600	2477	-	-	-	-	-	-	-	-	-	-	
3-11-52	64	4	498	-	1634	600	2481	10	6	16	87	22	31	18	63	63	20	
3-11-52	60	11	503	784	1628	600	2482	11	6	16	87	22	31	18	63	63	20	

RESTRICTED
SECURITY INFORMATION

20m Ammunition Aerial Powder Developed by Survey Station Company

TABLED FROM DATA (Continued)

20m Aircraft Gun, M 14 Serial Number 11200

Date	Rounds in Mils	Rounds Fired	Total Rounds on Gun	Total Oyale Mils (MI)	Total Rounds in Powder (MI)	Powder Air Pressure (PSI)	Survey Ammunition		Landing Mils (M.L.)	Landing Charge (G.M.)	Landing Charge (G.M.)	Pow Charge (G.M.)	Pow Charge (G.M.)	Operating Charge (G.M.)	Operating Charge (G.M.)	Average The Clock	
							Total Rounds	Total Mils								Micro-Section Clock (MILS)	Micro-Section Rate (MILS)
3-11-52	64	7	607	-	1708	600	6000	11	20	45	23	11	11	11	11	20	21
3-11-52	64	20	607	197	1702	600	6719	10	19	41	23	-	-	-	-	20	21
3-11-52	64	4	6081	-	1708	600	6725	-	-	-	-	-	-	-	-	-	-
3-11-52	60	1	6082	-	1719	600	6724	-	-	-	-	-	-	-	-	-	-
3-11-52	59	2	6084	-	1719	600	6723	-	-	-	-	-	-	-	-	-	-
3-11-52	64	4	6085	-	1728	600	6720	-	-	-	-	-	-	-	-	-	-
3-11-52	60	4	6086	-	1737	600	6718	-	-	-	-	-	-	-	-	-	-
3-11-52	56	11	6070	-	1768	600	6729	10	5	21	23	23	23	23	23	23	23

Remarks

10 pound ball load. Ball separation on
number six of powder ball holding gun.
Additional gun charge. No ball load
applied.
Ball load 20 pounds. Stalled round M14
in Chamber throat.
Heavy round in operation on ball.
Ball load 20 pounds. Ball separation on
number six of gun powder ball holding
gun.
Ball load 20 pounds.
Stalled round M14 in Chamber throat. Ball
load 20 pounds.
Additional gun charge. No ball load
applied.

RESTRICTED
EXCERPT

APPENDIX A

RESTRICTED
SECURITY INFORMATION
NP9 48727
Mk 16 20mm Gun, Mk 8/Mod 0 Gun Peel Mechanism, Harvey Assist Feeder, Ammunition
Box and Mitchell Movie Camera. Figure 1

APPENDIX B



UNCLASSIFIED



DIRECTION OF FEED




ANTI-BOLBACK
RELEASE

FIRST LOOP

20MM AMMO FEEDER

TOP VIEW


UNCLASSIFIED



REF ID: A6734
20mm Ammo Feeder

BOOSTER MOTOR







CLUTCH SWITCH



20 MM AMMO FEEDER

BOTTOM VIEW

UNCLASSIFIED




NPS 2016
APPROXIMATELY 2:00 PM, FEBRUARY 1968. PHOTOGRAPHIC RECORDING THROUGH KEYWAY ASSISTANT
Frame 1: Six 400-grain film frames showing the driver's view through the window and clutch
disengaged.
Frame 2-4: Slow accumulation of the Honey Assist Feeder to the MK-100
Car Foot V. (Note: In these frames the plan-view is of the road along the
road to originate traffic along the road.)
Frame 5: Six 400-grain film frames showing the driver's view through the window and
clutch disengaged. Direction of accumulation travel is to the right.
Figure 1
APPENDIX B

NP 9 487 29

Gear reduction and clutch plate assembly (anti-roll-back clutch assembly) (clutch plate).

Figure 7



U.S.N.P.G. DAHLGREN, VIRGINIA

3 INCHES



RESTRICTED

NIQ REPORT NO. 1208

20mm Ammunition Assist Feeder
Developed by Harvey Machine Company

DISTRIBUTION

Bureau of Ordnance:

Ad3	1
Re8	1
Re8a	1
Mn8	1
Re2	2

Armed Services Technical Information Agency
Document Service Center
Knott Building
Dayton 2, Ohio 5

Commanding General
Aberdeen Proving Ground
Aberdeen, Maryland
Attn: Technical Information Section
Development and Proof Services 1

Commander, Operational Development Force
U. S. Atlantic Fleet, U. S. Naval Base
Norfolk, Virginia 2

Bureau of Aeronautics
Attn: Armament Section 2

NATC, Patuxent River, Maryland
Attn: Armament Test 3

NAOTS, Chincoteague, Virginia 1

Air Materiel Command Liaison Officer
Wing 3 Headquarters
Aberdeen Proving Ground
Aberdeen, Maryland 2

Naval Liaison Officer
USAFPGC, Eglin Field, Florida 1

NADS, Johnsville, Pennsylvania 1

~~RESTRICTED~~

SECURITY INFORMATION

RESTRICTED

NPO REPORT NO. 1208

20mm Ammunition Assist Feeder
Developed by Harvey Machine Company

DISTRIBUTION (Continued)

U. S. Air Force AMC Engineering Field Office Room 1833, Main Navy Building Navy Department, Washington, D. C.	2
NOTS, Inyokern, California	1
NOTS, Inyokern, California Attn: Aviation Ordnance and Test Department	1
Watervliet Arsenal Watervliet, New York	1
Local:	
OV	1
OVG	1
OVE	1
File	1