

UNCLASSIFIED

AD NUMBER

AD344937

CLASSIFICATION CHANGES

TO: UNCLASSIFIED

FROM: CONFIDENTIAL

LIMITATION CHANGES

TO:

Approved for public release; distribution is unlimited. Document partially illegible.

FROM:

Distribution authorized to U.S. Gov't. agencies and their contractors;  
Administrative/Operational Use; 09 NOV 1959.  
Other requests shall be referred to Defence Atomic Support Agency, Washington, DC.

AUTHORITY

DNA notice, 5 Dec 1979; DNA notice, 5 Dec 1979

THIS PAGE IS UNCLASSIFIED

THIS REPORT HAS BEEN DELIMITED  
AND CLEARED FOR PUBLIC RELEASE  
UNDER DOD DIRECTIVE 5200.20 AND  
NO RESTRICTIONS ARE IMPOSED UPON  
ITS USE AND DISCLOSURE.

DISTRIBUTION STATEMENT A

APPROVED FOR PUBLIC RELEASE;  
DISTRIBUTION UNLIMITED.

UNCLASSIFIED

AD 344.937

CLASSIFICATION CHANGED-

TO: UNCLASSIFIED

FROM: CONFIDENTIAL

AUTHORITY:

DNA Notice

5 Dec 79



*Code  
23*

UNCLASSIFIED

# DISCLAIMER NOTICE



THIS DOCUMENT IS BEST QUALITY AVAILABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U. S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

NOTICE:

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 and 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

5) 104 500

AL

WT-1408

This document consists of 28 pages.  
No. 151 of 200 copies, Series A

DAHS-59-315L  
344937L

OPERATION

# PLUMBBOB



NEVADA TEST SITE  
MAY-OCTOBER 1957

## 3 4 4 9 3 7 L

Project 1.8b

EFFECTS of ROUGH TERRAIN on DRAG-SENSITIVE  
TARGETS (U)

5-2-1

Issuance Date: November 9, 1957

HEADQUARTERS FIELD COMMAND  
DEFENSE ATOMIC SUPPORT AGENCY  
SANDIA BASE, ALBUQUERQUE, NEW MEXICO



This material contains information affecting  
the national defense of the United States  
within the meaning of the espionage laws  
Title 18, U. S. C., Secs. 793 and 794, the  
transmission or revelation of which in any  
manner to an unauthorized person is pro-  
hibited by law.

EXCLUDED FROM AUTOMATIC  
DOWNGRADING: DOD-DIR 5200.10  
DOES NOT APPLY

NOV 14 1957

5-2-1

344937-219

**Inquiries relative to this report may be made to**

**Chief, Defense Atomic Support Agency  
Washington 25, D. C.**

**When no longer required, this document may be  
destroyed in accordance with applicable security  
regulations.**

**DO NOT RETURN THIS DOCUMENT**



## **ABSTRACT**

X The objective of Project 1.8b was to investigate the blast damage sustained by drag-sensitive targets when the blast wave passes over rough, hilly terrain to the target location. Of particular interest was the difference in the damage sustained by those targets which were positioned to take maximum advantage of terrain irregularities and the damage sustained by those targets placed over level terrain at corresponding distances.

For this study 51 jeeps were exposed on Shot Smoky. Vehicles were placed on three blast lines: a control line of essentially flat terrain, a line of rolling terrain, and a line of steeply sloping terrain with scattered gullies and washes. Earth revetments were constructed to examine the protection they would provide for vehicles. Project 1.8a made air-blast measurements at each station.

After the shot, the damage, orientation, and displacement of the vehicles were recorded. The results showed that the damage sustained by those vehicles on regular terrain agreed with the TM 23-200 damage chart. However, the damage sustained by those vehicles which utilized severe terrain irregularities was greatly reduced. Where any substantial obstacle, natural or artificial, having steep sloping rear walls was interposed between the detonation and the vehicle, damage was reduced from severe or moderate to light.

X

## **FOREWORD**

This report presents the final results of one of the 46 projects comprising the military-effect program of Operation Plumbbob, which included 24 test detonations at the Nevada Test Site in 1957.

For overall Plumbbob military-effects information, the reader is referred to the "Summary Report of the Director, DOD Test Group (Programs 1-9)," ITR-1445, which includes: (1) a description of each detonation, including yield, zero-point location and environment, type of device, ambient atmospheric conditions, etc.; (2) a discussion of project results; (3) a summary of the objectives and results of each project; and (4) a listing of project reports for the military-effect program.

## ***PREFACE***

To Harold B. Barton, 1st Lt., USA, the author is especially grateful. Lt. Barton's efforts in execution and evaluation of the project were invaluable.

Noel H. Ethridge was instrumental in the successful completion of this project. His suggestions and constructive criticisms were very useful.

Special appreciation is extended to the past Director of Program 1, Major H. T. Bingham, for his cooperation and helpful suggestions in planning the overall aspects of the project.

## CONTENTS

ABSTRACT	4
FOREWORD	5
PREFACE	6
OBJECTIVE	9
BACKGROUND AND THEORY	9
PROCEDURE	9
RESULTS AND DISCUSSIONS	15
CONCLUSIONS	24
RECOMMENDATIONS	24
REFERENCES	25
FIGURES	
1 Blast-line layout, Line 1	10
2 Line 1, looking toward ground zero	10
3 Artificial revetment	10
4 Blast-line layout, Line 2	12
5 Station 7.02(b), Line 2	13
6 Station 7.07, Line 5	13
7 Blast-line layout, Line 5	13
8 Vehicle stations on Line 1, postshot	14
9 Vehicle stations on Line 2, postshot	19
10 Vehicle stations on Line 5, postshot	20
11 Tank stations, postshot	21
12 Comparison of Smoky Line 1 with Teapot Shot 4 and the damage chart of TM 23-200 scaled to 1 kt	21
13 Layout of vehicle stations and resulting damage for Shot Smoky	22
14 Terrain profiles for vehicle stations	23
15 Station 7.08, in gully	23
TABLES	
1 Damage Evaluation of Trucks 1/4 ton, 4 x 4, Utility, Model MB, WW II	16

# CONFIDENTIAL

## *EFFECTS of ROUGH TERRAIN on DRAG-SENSITIVE TARGETS*

### OBJECTIVE

The objective of this project was to investigate the blast damage sustained by drag-sensitive targets (World War II jeeps) when the blast wave passes over rough, hilly terrain in traveling to the target location. Of particular interest was the difference in the damage sustained by those targets which were positioned to take maximum advantage of terrain irregularities and the damage sustained by those targets which were placed over level terrain at corresponding distances.

### BACKGROUND AND THEORY

Much work pertaining to vehicle damage sustained on level terrain was done on past operations. Damage prediction charts for such terrain were considered reliable. However, limited work was done toward the investigation of vehicle damage obtained on irregular terrain when maximum advantage was taken of defiladed positions. During Operation Teapot, vehicles were placed behind earth mounds and other artificial revetments (Reference 1). The results showed that such obstacles provided significant drag protection from the blast wave, implying that natural terrain features of a similar nature would provide significant protection for vehicles. Also of interest were the changes in the blast wave and target-response characteristics resulting from the passage of the blast wave over a series of hills and dales.


The basic theory of Reference 2 premises a change in character of a blast wave as it travels over a hill. This change presents itself as an overpressure build-up on the front face of a hill and an overpressure decrease as the wave breaks over the crest and travels down the back face of the hill.

### PROCEDURE

Project 1.8b participated on Shot Smoky. The terrain in Area T2-C presented ideal features for accomplishing the objective of the project.

Fifty-one jeeps (trucks,  $\frac{1}{4}$  ton, 4 x 4, utility, Model MB) were used. A preshot vehicle-condition inspection was performed. Numbers were painted on all major components of the vehicles and stakes were driven at each location to facilitate postshot evaluations. In each vehicle the transmission was put in reverse gear, the transfer case in low-range four-wheel drive, and the hand brake was engaged.

The postshot evaluation consisted of an inspection of damage sustained by each jeep and the recording of the vehicle displacement and orientation. Vehicles that could be rendered combat usable within 1 man-hour of maintenance time were considered to be lightly damaged. Other damage levels (moderate and severe) were selected on a basis of man-hours required for rendering the vehicle combat usable (Reference 3):



CONFIDENTIAL

Figure 1 East-line layout, Line 1.




Figure 2 Line 1, looking toward ground zero.




Figure 3 Artificial revetment.

<u>Damage Level</u>	<u>Man-hours</u>	<u>Type of Maintenance</u>	<u>Man-hours</u>
Light	0-1	Organizational	0-6
Moderate	1-32	Field	6-32
Severe	32	Depot or Salvage	32

The test was implemented as follows: (1) A control line over flat terrain was established in order to correlate input conditions with those obtained on previous NTS shots and to provide direct comparison with conditions over the rough terrain. (2) A hill-and-dale line was established over rolling terrain with vehicle stations at distances corresponding to those on the control line. Offset from the main lines were stations placed in defiladed positions, taking maximum advantage of terrain accidents. (3) A line consisting of widely scattered stations was used to take advantage of the rough terrain northwest of ground zero. (4) Earth revetments were constructed along both the control line and the hill-and-dale line to continue work done during Operation Teapot. (5) Free-field air blast measurements were taken at all stations by Project 1.8a (Reference 4).

The control line was designated as Line 1 (Figure 1). The terrain on Line 1 was essentially flat, although there was a slight downward slope away from ground zero. There were five vehicle stations along this line (Figure 2). Each station consisted of two vehicles, one oriented side-on (SO) toward ground zero and the other face-on (FO). At each of the second and fourth stations (6.02 and 6.04), a revetment was constructed. This was simply an earth mound approximately 7 feet high (Figure 3). One side-on vehicle was placed behind each of these revetments.

The area around Line 2 was of particular interest (Figure 4). Twenty-nine vehicles were employed on the tops of hills, down in the dales, and in various shielded positions. There were seven stations directly on Line 2 each having a side-on and face-on jeep. Stations 6.07 and 6.09 also had revetment stations. Two stations (7.03 and 7.04) were established on one side of Line 2 to provide a shielded station (7.03) for comparison with a hill station (6.09) at the same range and a hill station (7.04) for comparison with a dale station (6.10) at roughly the same range. On the other side of Line 2, Station 7.01 was a hill station at the same range as Station 6.06b, a dale station. Station 7.02a was directly behind a steep hill and was at the same approximate range as Station 6.08, which had much less protection.

At one location near Line 2 (Station 7.02b, c, and d) there was a steep bluff (the bank of a wash) behind which were placed three jeeps and an M48 tank, all side-on (Figure 5). This wash, or gully, was approximately 100 feet wide. One jeep and the tank were placed against the bluff, one jeep was placed midway in the wash, and the other jeep was placed against the far bank of the wash. This configuration was expected to ascertain the degree of protection which might be obtained at a given distance from a wall. The information would be of value in choosing a most advantageous position when the detonation point cannot be predicted.

One station (6.12) consisting of a side-on and face-on vehicle was placed on a hill at the end of Line 3 of Project 1.8a (Figure 4).

Line 5 was the term used to identify the general location of a group of five widely scattered vehicle stations to the northwest of ground zero (Figure 6 and 7). These stations were placed to investigate natural terrain features such as a gully (Stations 7.07 and 7.08), a ravine (6.13), a wash (7.05), and the back of a hill (7.06).

The data required consisted of a comprehensive evaluation of the damage sustained by each vehicle during the blast. In addition, basic air-blast data was obtained from Projects 1.8a and 1.8c.




Figure 4 Blast-line layout, Line 2.



Figure 5 Station 7.02(b), Line 2.




Figure 6 Station 7.07, Line 5.

o 7.07 (2975 ft)

o 7.06 (2341 ft)

o 6.13 (1836 ft)

o 7.05 (2425 ft)


o 7.08 (1728 ft)

Δ 8.00 (1231 ft)


o - FO AND SO  
 Δ - M 48 TANK




Figure 7 Blast-line layout, Line 5.



Station 6.02 (SO) 2,760 feet.



Station 6.02 (SO) 2,760 feet (behind artificial revetment).



Station 6.04 (SO) 3,406 feet.



Station 6.04 (SO) 3,406 feet (behind artificial revetment).

Figure 8 Vehicle stations on Line 1, postshot.

## RESULTS AND DISCUSSIONS

The damage evaluation of the vehicles is given in Table 1 for Lines 1, 2, and 5; all stations are listed. Off-line stations are grouped with the nearest line. The values for maximum side-on overpressure ( $P_g$ ) were obtained from Project 1.8a (Reference 3). These pressures were measured at ground level.

Figures 8, 9 and 10 contain postshot photographs of the jeeps and illustrate the damage sustained at typical stations. Postshot photographs of the tanks are included in Figure 11.

Figure 12 compares the damage sustained by the vehicle stations along the control line with that predicted by the TM 23-200 vehicle-damage chart. Data from another NTS shot of the same yield (Teapot, Shot 4, 43 kt at a height of burst of 500 feet is also plotted on this chart. The comparisons show that the control line results were typical for an NTS shot over level terrain both with respect to the TM 23-200 damage chart and the NTS shot of similar yield. (Note: The TM 23-200 chart was revised since this data was compiled; however, the revised material, at the height of interest, was only slightly altered.)

Figure 13 shows the damage sustained by all vehicle stations and designates the type of terrain at the station location. This information is shown on a polar plot in order that the various stations can be compared directly. The damage probability contours of TM 23-200 have been scaled to shot conditions and are shown in Figure 13 so that comparisons of actual and predicted damage can be made.

As shown in Figure 13, the damage experienced by the vehicles directly on Line 2 was identical at corresponding distances on the control line, with one exception. The side-on vehicle at Station 6.09 (a hill station) was severely damaged, while the vehicles in front of this station, as well as those equal distances on the control line, were only moderately damaged. Although severe damage is implied at this ground range, it is unusual to have those vehicles (surrounding and preceding the severely damaged vehicle) sustain only moderate damage.

An examination of the damage to the vehicles along Lines 2 and 5 for a study of the effect of terrain irregularities on damage showed that the degree of protection depended on the severity of the terrain profile between ground zero and the vehicle and the nearness of the vehicle to the profile, i. e., the steeper the slope and the nearer the vehicle to this slope, the greater the protection. While Line 2 itself was over gently rolling terrain with maximum slopes not exceeding 15 degrees, several stations on either side of Line 2 were protected by steep hills having downslopes of approximately 60 to 90 degrees. It was here that the objective of the experiment was answered.

The comparison of Stations 6.03, 6.08, and 7.02 in Figure 14 shows that, at about the same ground range, significant reduction in damage was obtained when proper advantage was taken of existing terrain accidents. The vehicle at Station 6.03 (2,943 feet) on the control line was displaced 115 feet, sustained moderate damage, and would have required about 12 hours of maintenance work to restore to combat usability. The corresponding vehicle at Station 6.08 (2,914 feet) on Line 2 was displaced 75 feet and sustained moderate damage requiring 4 hours maintenance time. Those vehicles at Stations 7.02a and 7.02b were not displaced and only lightly damaged, requiring no repair time.

Other significant examples of the protection afforded by sharp terrain features occurred at Stations 7.03 and 7.08. At Station 7.03 the vehicles survived the blast and were not damaged, while those vehicles at Station 6.09, which were at the same distance, were heavily damaged. This occurred because Station 6.09 was exposed on a hill and

TABLE 1 DAMAGE EVALUATION OF TRUCKS 1/4 TON, 4 x 4, UTILITY, MODEL MB (WW II)  
SO, Side-on; FO, Face-on; O, Organizational maintenance; F, Field maintenance.

Station	Range	Terrain	P <sub>s</sub>	Displacement	Description of Damage	Man-Hours Required		Maintenance
						Combat Usability	Complete Restoration	
	ft		psi	ft		hour	hour	
<b>Line 1</b>								
6.01	2,381 SO		10.2	630	Severe; vehicle demolished.	—	—	—
6.01	2,381 FO		10.2	430	Severe; vehicle upright, intact; body and frame ruined.	—	—	—
6.02	2,760 SO		8.8	150	Severe; vehicle upside down, body, frame, radiator, steering ruined	—	—	—
6.02	2,760 FO		8.8	150	Severe; vehicle upright, body badly damaged, frame bent, steering mechanism bent.	—	—	—
6.02*	2,760 SO		8.8	0	Light; vehicle upright, no damage	0	0	O
6.03	2,943 SO		10.4	115	Moderate; vehicle upside down, body, radiator destroyed, frame slightly bent.	11.5	80	F
6.03	2,943 FO		10.4	30	Moderate; vehicle upright, radiator destroyed, hood missing.	1.5	3.2	O
6.04	3,406 SO		6.4	110	Moderate; vehicle on right side, body severely damaged, right front wheel torn off, steering mechanism bent.	5.3	13.3	O
6.04	3,406 FO		6.4	25	Moderate; vehicle upright, radiator and body damaged.	2.0	6	O
6.04*	3,406 SO		6.4	0	Light; vehicle upright, no damage.	0	0	O
6.05	3,875 SO		7.2	20	Moderate; vehicle upside down, body badly bent, steering mechanism ruined.	3.5	9.5	O
6.05	3,875 FO		7.2	15	Moderate; vehicle upright, radiator and body damage, steering column bent.	3.5	13.5	O
<b>Line 2</b>								
6.06(a)	1,966 SO	Hill	20	700 to 1,000	Severe; vehicle demolished.	—	—	—
6.06(a)	1,966 FO	Hill	20	700	Severe; vehicle upside down, demolished.	—	—	—
6.06(b)	2,215 SO	Dale	23.5	30	Severe; vehicle upside down, still intact, but all components badly damaged.	—	—	—
6.06(b)	2,215 FO	Dale	23.5	20	Severe; vehicle upright, burned, body smashed, frame bent but intact.	—	—	—
7.01	2,215 SO	Hill	19.3	600	Severe; vehicle demolished.	—	—	—
7.01	2,215 FO	Hill	19.3	600	Severe; vehicle demolished.	—	—	—
6.07	2,548 SO	Hill	12.5	1,000	Severe; vehicle demolished.	—	—	—
6.07	2,548 FO	Hill	12.5	800	Severe; vehicle upside down, demolished.	—	—	—
6.07*	2,548 SO	Hill	12.5	0	Light; vehicle upright, hood missing, cowlings bent, windshield broken.	0	3	O

TABLE 1 CONTINUED

Station	Range	Terrain	P <sub>s</sub>	Displacement	Description of Damage	Man-Hours Required		Maintenance
						Combat Usability	Complete Restoration	
	ft		psi	ft		hour	hour	
7.02(a)	2,840 SO	Dale	12.6	0	Light; vehicle upright, bumper bent, grill bent, speedometer broken.	0	5	0
7.02(a)	2,840 FO	Dale	12.6	0	Light; vehicle upright, speedometer broken.	0	1	0
7.02(b)	2,840 SO	Dale	12.6	0	Light; vehicle upright, battery broken, hood blown off.	0.3	4	0
7.02(c)	2,890 SO	Wash	—	225	Severe; vehicle upside down, radiator destroyed, steering ruined, body destroyed, frame bent, transfer case and bell housing cracked.	—	—	—
7.02(d)	2,840 SO	Wash	—	110	Severe; vehicle upright, intact but components badly damaged.	—	—	—
6.08	2,914 SO	Dale	10.8	75	Moderate; vehicle upright, body badly bent, right rear wheel bent, ignition wiring missing.	4	15.4	0
6.08	2,914 FO	Dale	10.8	0	Moderate; vehicle upright, radiator ruined, hood bent, headlights broken.	1.5	4.8	0
6.09	3,218 SO	Hill	8.2	220	Severe; vehicle upside down, engine mounts sheared, body ruined, frame bent.	—	—	—
6.09	3,218 FO	Hill	8.2	55	Moderate; vehicle upright, radiator ruined, hood missing.	1.5	3.3	0
6.09*	3,218 SO	Hill	8.2	0	Light; vehicle upright, windshield bent.	0	0.3	0
7.03	3,218 SO	Dale	9.0	0	Light; vehicle upright, scorched, seats missing.	0	0.5	0
7.03	3,218 FO	Dale	9.0	0	Light; vehicle upright, scorched, hood missing.	0	0.5	0
7.04	3,568 SO	Hill	8.0	73	Moderate; vehicle upside down, right rear section of body crushed, steering mechanism bent.	4	8	0
7.04	3,568 FO	Hill	8.0	15	Moderate; vehicle upright, radiator ruined, hood missing, cowlings ripped.	2.5	9.8	0
6.10	3,739 SO	Dale	7.7	0	Moderate; vehicle upside down, steering mechanism destroyed, slight body damage.	2.5	9.8	0
6.10	3,739 FO	Dale	7.7	10	Moderate; vehicle upright, radiator damaged, hood missing.	1.5	3.3	0
6.12†	3,874 SO	Hill	7.1	110	Moderate; vehicle upside down, radiator ruined, body badly bent, steering mechanism bent.	5	13	0
6.12†	3,874 FO	Hill	7.1	20	Moderate; vehicle upside down, radiator damaged, body damaged, steering mechanism bent.	3	13.3	0
6.11	4,115 SO	Hill	7.0	120	Moderate; vehicle upright, front springs and U-bolt broken, body badly damaged.	3.5	10.5	0
6.11	4,115 FO	Hill	7.0	18	Moderate; vehicle upright, radiator and hood damaged.	1.5	3.3	0
M48	2,840 SO	Dale	12.6	0	None; vehicle upright, no damage.	0	0	0

TABLE 1 CONTINUED

Station	Range	Terrain	P <sub>s</sub>	Displacement	Description of Damage	Man-Hours Required		Maintenance
						Combat Usability	Complete Restoration	
	ft		psi	ft		hour	hour	
Line 5								
7.08	1,728 SO	Gully	54.0	0	Moderate; vehicle upright, front end of body badly damaged, radiator ruined, steering mechanism ruined.	8.5	14.5	F
7.08	1,728 FO	Gully	54.0	0	Moderate; vehicle upright, front portion of body crushed, radiator and steering ruined.	9.0	18	F
6.13	1,836 SO	Ravine	24.5	100 to 1,500	Severe; completely dismembered.	—	—	—
6.13	1,836 FO	Ravine	24.5	100	Severe; completely demolished.	—	—	—
7.06	2,341 SO	Back of Hill	15.7	100 to 600	Severe; vehicle upside down, engine and grill attached to frame, body stripped.	—	—	—
7.06	2,341 FO	Back of Hill	15.7	60	Moderate; vehicle upright, body badly bent, radiator and steering destroyed.	7.0	16.5	F
7.05	2,425 SO	Wash	20.0	800 to 1,000	Severe; frame only located.	—	—	—
7.05	2,425 FO	Wash	20.0	800 to 1,000	Severe; body located, badly mangled.	—	—	—
7.07	2,975 SO	Gully	11.6	15	Moderate; vehicle upside down, steering wheel and column destroyed, body bent.	3.5	12.5	O
7.07	2,975 FO	Gully	11.6	5	Moderate; vehicle upright, radiator destroyed, steering wheel and column bent.	4.0	7.8	O
9008 (M48)	1,231 SO	—	65	15	Severe; vehicle upside down, burned, engine melted.	—	—	—

\* Vehicle was placed behind artificial revetment.

† Line 3, Project 1.8a.



Station 7.01 (FO and SO) 2,215 feet.



Station 6.07 (SO) 2,548 feet (behind artificial revetment).



Station 6.09 (SO) 3,218 feet (hill).




Station 7.03 (SO and FO) 3,218 feet (dale).

Figure 9 Vehicle stations on Line 2, postshot.

7.03 was shielded by a bluff. An even greater contrast in damage was observed between Stations 6.13 and 7.08. Station 6.13 (1,836 feet) was completely demolished, while 7.08 (1,728 feet and well within the 90-percent-severe-probability radius) was only moderately damaged. The apparent reason for this was that Station 7.08 was located in a narrow gully which provided shielding as well as restriction of movement (Figure 15).

The artificial revetments provided excellent protection from the blast wave regard-



Station 7.08 (FO) 1,728 feet.




Station 6.13 (FO) 1,836 feet.


Figure 10 Vehicle station on Line 5, postshot.

less of their distance from ground zero (2,548, 2,760, 3,218, or 3,406 feet) or whether they were on level ground or hills. The vehicle behind these earth mounds received no damage, while those exposed unprotected at the same location received moderate-to-severe damage.

These revetments were in the same category as the natural terrain of Stations 7.02a and 7.02b with respect to steepness of the slope of the protecting hulls. The contrast



Station 7.02 (b).



Station 9008.

Figure 11 Tank stations, postshot.




Figure 12 Comparison of Smoky Line 1 with Teapot Shot 4 and the Damage Chart of TM 23-200 scaled to 1 kt.




Figure 13 Layout of vehicle stations and resulting damage for Shot Smoky.




Figure 14 Terrain profiles for vehicle stations.



Figure 15 Station 7.08, in gully.

between the light damage of Stations 7.02a and b, against the steep wall, with the severe damage at Station 7.03c, in the middle of the wash, and at Stations 7.02d against the far bank, emphasized the importance of locating the vehicle as close to the wall as possible.

#### CONCLUSIONS

The vehicle damage on the control line of Shot Smoky agreed with the TM 23-200 vehicle damage chart and another NTS shot of the same approximate yield.

Damage to the vehicles directly on Line 2, which were placed on hills and in dales without effort to utilize maximum protection of terrain, was essentially the same as that noted on the control line.

From the evaluation of the damage sustained by those vehicles which took maximum advantage of terrain features, it was concluded that damage was greatly influenced by the profile of the terrain between ground zero and the vehicle target, when the target was adjacent to the profile. For natural terrain or an artificial revetment providing a steep downslope immediately adjacent to the vehicle (placing a substantial obstacle between the vehicle and the direction of approach of the blast wave) the damage could be reduced from severe or moderate to light.

#### RECOMMENDATIONS

It is recommended that military field commanders be made cognizant of the significant protection afforded by terrain, whether natural or man-made. In paragraph 10.9, Section X of the current edition (November 1957) of TM 23-200, this protection is adequately discussed. If there are no severe terrain features available, then artificial revetments could be constructed. For cases where the intended ground zero is not known, a trench just wide enough and deep enough to hold the vehicle would offer both the most protection and the greatest simplicity of construction. The length would be determined by the number of vehicles requiring protection.

## **REFERENCES**

1. E. J. Bryant, N. H. Ethridge and M. R. Johnson, 2nd Lt., USA; "Response of Drag Type Equipment Targets in the Precursor Zone"; Project 3.1, Operation Teapot, ITR-1123; May 1955; Terminal Ballistics Laboratory, Ballistic Research Laboratories, Aberdeen Proving Ground, Maryland; Secret Restricted Data.
2. M. L. Merritt; "Air Shock Pressures as Affected by Hills and Dales"; Project 1.1c-2, Operation Upshot-Knothole, WT-713; September 1954; Sandia Corporation, Albuquerque, New Mexico; Secret Restricted Data.
3. E. J. Bryant, N. H. Ethridge and Joseph McCoy, 1st Lt., USA; "Statistical Estimation of Damage to Ordnance Equipment Exposed to Nuclear Blasts"; Project 3.21, Operation Upshot-Knothole, WT-733; February 1955; Terminal Ballistic Laboratory, Ballistic Research Laboratories, Aberdeen Proving Ground, Maryland; Secret Restricted Data.
4. E. J. Bryant and J. H. Keefer; "Effects of Rough and Sloping Terrain on Blast Wave"; Project 1.8a, Operation Plumbbob, ITR-1407; December 1957; Explosion Kinetics Branch, Terminal Ballistics Laboratory, Ballistic Research Laboratories, Aberdeen Proving Ground, Maryland; Confidential Formerly Restricted Data.

## DISTRIBUTION

### Military Distribution Category 72

- |                        |  |  |
|------------------------|--|--|
| <b>ARMY ACTIVITIES</b> |  |  |
| 1                      | Deputy Chief of Staff for Military Operations, D/A, Washington 25, D.C. ATTN: Dir. of SW&R   |  |
| 2                      | Chief of Research and Development, D/A, Washington 25, D.C. ATTN: Atomic Div.  |  |
| 3-                     | 4 Chief Chemical Officer, D/A, Washington 25, D.C.<br>5 Chief of Engineers, D/A, Washington 25, D.C. ATTN: ENGNB<br>6 Chief of Engineers, D/A, Washington 25, D.C. ATTN: ENGEB<br>7 Chief of Engineers, D/A, Washington 25, D.C. ATTN: ENGTE |  |
| 8-                     | 9 Office, Chief of Ordnance, D/A, Washington 25, D.C. ATTN: ORDTN  |  |
| 10                     | Chief Signal Officer, D/A, Comb. Dev. and Ops. Div., Washington 25, D.C. ATTN: SIGCO-4   |  |
| 11                     | Chief of Transportation, D/A, Office of Planning and Int., Washington 25, D.C.   |  |
| 12                     | The Surgeon General, D/A, Washington 25, D.C. ATTN: MEDNE  |  |
| 13-                    | 15 Commanding General, U.S. Continental Army Command, Ft. Monroe, Va.<br>16 Director of Special Weapons Development Office, Headquarters CONARC, Ft. Bliss, Tex. ATTN: Capt. Chester I. Peterson   |  |
| 17                     | President, U.S. Army Artillery Board, Ft. Sill, Okla.  |  |
| 18                     | President, U.S. Army Infantry Board, Ft. Benning, Ga.  |  |
| 19                     | President, U.S. Army Air Defense Board, Ft. Bliss, Tex.  |  |
| 20                     | Commandant, U.S. Army Command & General Staff College, Ft. Leavenworth, Kansas. ATTN: ARCHIVES   |  |
| 21                     | Commandant, U.S. Army Air Defense School, Ft. Bliss, Tex. ATTN: Command & Staff Dept.  |  |
| 22                     | Commandant, U.S. Army Armored School, Ft. Knox, Ky.  |  |
| 23                     | Commandant, U.S. Army Artillery and Missile School, Ft. Sill, Okla. ATTN: Combat Development Department  |  |
| 24                     | Commandant, U.S. Army Aviation School, Ft. Rucker, Ala.  |  |
| 25                     | Commandant, U.S. Army Infantry School, Ft. Benning, Ga. ATTN: C.D.S.   |  |
| 26                     | The Superintendent, U.S. Military Academy, West Point, N.Y. ATTN: Prof. of Ordnance  |  |
| 27                     | Commandant, The Quartermaster School, U.S. Army, Ft. Lee, Va. ATTN: Chief, QM Library  |  |
| 28                     | Commandant, U.S. Army Ordnance School, Aberdeen Proving Ground, Md.  |  |
| 29                     | Commandant, U.S. Army Ordnance and Guided Missile School, Redstone Arsenal, Ala.   |  |
| 30                     | Commanding General, Chemical Corps Training Comd., Ft. McClellan, Ala.   |  |
| 31                     | Commandant, USA Signal School, Ft. Monmouth, N.J.  |  |
| 32                     | Commandant, USA Transport School, Ft. Eustis, Va. ATTN: Security and Info. Off.  |  |
| 33                     | Security General, The Engineer Center, Ft. Belvoir, Va. ATTN: Asst. Cndt, Engr. School   |  |
| 34                     | Commanding General, Army Medical Service School, Brooke Army Medical Center, Ft. Sam Houston, Tex.   |  |
| 35                     | Director, Armed Forces Institute of Pathology, Walter Reed Army Med. Center, 625 16th St., NW, Washington 25, D.C.   |  |
| 36                     | Commanding Officer, Army Medical Research Lab., Ft. Knox, Ky.  |  |
| 37                     | Commandant, Walter Reed Army Inst. of Res., Walter Reed Army Medical Center, Washington 25, D.C.   |  |
| 38-                    | 39 Commanding General, QM R&D Comd., QM R&D Cntr., Natick, Mass. ATTN: CBR Liaison Officer   |  |
| 40-                    | 42 Commanding General, U.S. Army Chemical Corps, Research and Development Comd., Washington 25, D.C.   |  |
| 43-                    | 44 Commanding Officer, Chemical Warfare Lab., Army Chemical Center, Md. ATTN: Tech. Library  |  |
| 45                     | Commanding General, Engineer Research and Dev. Lab., Ft. Belvoir, Va. ATTN: Chief, Tech. Support Branch  |  |
| 46                     | Director, Waterways Experiment Station, P.O. Box 631, Vicksburg, Miss. ATTN: Library   |  |
| 47                     | Commanding Officer, Picatinny Arsenal, Dover, N.J. ATTN: ORDBB-TK  |  |
| 48                     | Commanding Officer, Diamond Ord. Fuze Labs., Washington 25, D.C. ATTN: Chief, Nuclear Vulnerability Br. (230)  |  |
| 49-                    | 50 Commanding General, Aberdeen Proving Grounds, Md. ATTN: Director, Ballistics Research Laboratory  |  |
| 51                     | Commanding General, Frankford Arsenal, Bridge and Tacony St., Philadelphia, Pa.  |  |
| 52                     | Commanding Officer, Watervliet Arsenal, Watervliet, New York. ATTN: ORDEF-RR   |  |
| 53-                    | 54 Commanding General, U.S. Army Ord. Missile Command, Redstone Arsenal, Ala.  |  |
| 55                     | Commanding General, Ordnance Tank Automotive Command, Detroit Arsenal, Centerline, Mich. ATTN: ORDMC-RO  |  |
| 56                     | Commanding General, Ordnance Ammunition Command, Joliet, Ill.  |  |
| 57                     | Commanding General, Ordnance Weapons Command, Rock Island, Ill.  |  |
| 58                     | Commanding Officer, USA Signal R&D Laboratory, Ft. Monmouth, N.J.  |  |
| 59                     | Commanding General, U.S. Army Electronic Proving Ground, Ft. Huachuca, Ariz. ATTN: Tech. Library   |  |
| 60                     | Commanding Officer, USA, Signal R&D Laboratory, Ft. Monmouth, N.J. ATTN: Tech. Doc. Ctr., Evans Area   |  |
| 61                     | Commanding Officer, USA Transportation R&E Comd., Ft. Eustis, Va. ATTN: Chief, Tech. Svcs. Div.  |  |
| 62                     | Commanding Officer, USA Transportation Combat Development Group, Ft. Eustis, Va.   |  |
| 63                     | Director, Operations Research Office, Johns Hopkins University, 6935 Arlington Rd., Bethesda 14, Md.   |  |
| 64                     | Commanding General, U. S. ORD Special Weapons-Ammunition Command, Dover, N.J.  |  |
| 65                     | Commander-in-Chief, U.S. Army Europe, APO 403, New York, N.Y. ATTN: Opot. Div., Weapons Br.  |  |
| 66                     | Commanding Officer, 9th Hospital Center, APO 180, New York, N.Y. ATTN: CO, US Army Nuclear Medicine Research Detachment, Europe  |  |
| <b>NAVY ACTIVITIES</b> |  |  |
| 67                     | Chief of Naval Operations, D/N, Washington 25, D.C. ATTN: OP-03BG  |  |
| 68                     | Chief of Naval Operations, D/N, Washington 25, D.C. ATTN: OP-31  |  |
| 69                     | Chief of Naval Operations, D/N, Washington 25, D.C. ATTN: OP-75  |  |
| 70                     | Chief of Naval Operations, D/N, Washington 25, D.C. ATTN: OP-91  |  |
| 71                     | Chief of Naval Operations, D/N, Washington 25, D.C. ATTN: OP-92G1  |  |
| 72-                    | 73 Chief of Naval Research, D/N, Washington 25, D.C. ATTN: Code 811  |  |
| 74-                    | 75 Chief, Bureau of Aeronautics, D/N, Washington 25, D.C.<br>76 Chief, Bureau of Medicine and Surgery, D/N, Washington 25, D.C. ATTN: Special Wpns. Def. Div.  |  |
| 77                     | Chief, Bureau of Ordnance, D/N, Washington 25, D.C.  |  |
| 78                     | Chief, Bureau of Ships, D/N, Washington 25, D.C. ATTN: Code 423  |  |
| 79                     | Chief, Bureau of Yards and Docks, D/N, Washington 25, D.C. ATTN: D-440   |  |
| 80                     | Director, U.S. Naval Research Laboratory, Washington 25, D.C. ATTN: Mrs. Katherine H. Cass   |  |
| 81-                    | 82 Commander, U.S. Naval Ordnance Laboratory, White Oak, Silver Spring 19, Md.   |  |
| 83                     | Commanding Officer and Director, Navy Electronics Laboratory, San Diego 92, Calif.   |  |
| 84                     | Commanding Officer, U.S. Naval Mine Defense Lab., Panama City, Fla.  |  |

~~CONFIDENTIAL~~

- 85-86 Commanding Officer, U.S. Naval Radiological Defense Laboratory, San Francisco, Calif. ATTN: Tech. Info. Div.
- 87-88 Commanding Officer and Director, U.S. Naval Civil Engineering Laboratory, Port Hueneme, Calif. ATTN: Code L31
- 89 Commanding Officer, U.S. Naval Schools Command, U.S. Naval Station, Treasure Island, San Francisco, Calif.
- 90 Superintendent, U.S. Naval Postgraduate School, Monterey, Calif.
- 91 Commanding Officer, Nuclear Weapons Training Center, Atlantic, U.S. Naval Base, Norfolk 11, Va. ATTN: Nuclear Warfare Dept.
- 92 Commanding Officer, Nuclear Weapons Training Center, Pacific, Naval Station, San Diego, Calif.
- 93 Commanding Officer, U.S. Naval Damage Control Tng. Center, Naval Base, Philadelphia 12, Pa. ATTN: ABC Defense Course
- 94 Commanding Officer, Air Development Squadron 5, VI-5, China Lake, Calif.
- 95 Director, Naval Air Experiment Station, Air Material Center, U.S. Naval Base, Philadelphia, Pa.
- 96 Commander, Officer U.S. Naval Air Development Center, Johnsville, Pa. ATTN: NAS, Librarian
- 97 Commanding Officer, U.S. Naval Medical Research Institute, National Naval Medical Center, Bethesda, Md.
- 98 Commanding Officer and Director, David W. Taylor Model Basin, Washington 7, D.C. ATTN: Library
- 99 Officer-in-Charge, U.S. Naval Supply Research and Development Facility, Naval Supply Depot, Bayonne, N.J.
- 100-103 Commandant, U.S. Marine Corps, Washington 25, D.C. ATTN: Code A03H
- 104 Commanding Officer, U.S. Naval CIC School, U.S. Naval Air Station, Glynnco, Brunswick, Ga.
- AIR FORCE ACTIVITIES
- 105 Assistant for Atomic Energy, HQ, USAF, Washington 25, D.C. ATTN: DCS/O
- 106 Deputy Chief of Staff, Operations HQ, USAF, Washington 25, D.C. ATTN: Operations Analysis
- 107 Director of Civil Engineering, HQ, USAF, Washington 25, D.C. ATTN: AFCE
- 108-109 Assistant Chief of Staff, Intelligence, HQ, USAF, Washington 25, D.C. ATTN: AFCIN-A2A
- 110 Director of Research and Development, DCS/D, HQ, USAF, Washington 25, D.C. ATTN: Guidance and Weapons Div.
- 111 The Surgeon General, HQ, USAF, Washington 25, D.C. ATTN: Bio.-Def. Pre. Med. Division
- 112 Commander, Tactical Air Command, Langley AFB, Va. ATTN: Doc. Security Branch
- 113 Commander, Air Defense Command, Ent AFB, Colorado. ATTN: Atomic Energy Div., ADLAN-A
- 114 Commander, HQ, Air Research and Development Command, Andrews AFB, Washington 25, D.C. ATTN: RDRWA
- 115 Commander, Air Force Ballistic Missile Div. HQ, ARDC, Air Force Unit Post Office, Los Angeles 45, Calif. ATTN: WDSOT
- 116-117 Commander, AF Cambridge Research Center, L. G. Hanscom Field, Bedford, Mass. ATTN: CRQST-2
- 118-122 Commander, Air Force Special Weapons Center, Kirtland AFB, Albuquerque, N. Mex. ATTN: Tech. Info. & Intel. Div.
- 123-124 Director, Air University Library, Maxwell AFB, Ala.
- 125 Commander, Lowry AFB, Denver, Colorado. ATTN: Dept. of Sp. Wpns. Tng.
- 126 Commandant, School of Aviation Medicine, USAF Randolph AFB, Tex. ATTN: Research Secretariat
- 127 Commander, 1009th Sp. Wpns. Squadron, HQ, USAF, Washington 25, D.C.
- 128-130 Commander, Wright Air Development Center, Wright-Patterson AFB, Dayton, Ohio. ATTN: WCOSI
- 131-132 Director, USAF Project RAND, VIA: USAF Liaison Office, The RAND Corp., 1700 Main St., Santa Monica, Calif.
- 133 Commander, Rome Air Development Center, ARDC, Griffiss AFB, N.Y. ATTN: The Documents Library, ROSSLD
- 134 Commander, Air Technical Intelligence Center, USAF, Wright-Patterson AFB, Ohio. ATTN: AFCIN-1BL, Library
- 135 Assistant Chief of Staff, Intelligence, HQ, USAF, APO 633, New York, N.Y. ATTN: Directorate of Air Targets
- 136 Commander-in-Chief, Pacific Air Forces, APO 9/3, San Francisco, Calif. ATTN: PFCIE-MB, Base Recovery
- OTHER DEPARTMENT OF DEFENSE ACTIVITIES
- 137 Director of Defense Research and Engineering, Washington 25, D.C. ATTN: Tech. Library
- 138 Chairman, Armed Services Explosives Safety Board, DOD, Building T-7, Gravelly Point, Washington 25, D.C.
- 139 Director, Weapons Systems Evaluation Group, Room 1E880, The Pentagon, Washington 25, D.C.
- 140-143 Chief, Defense Atomic Support Agency, Washington 25, D.C. ATTN: Document Library
- 144 Commander, Field Command, DASA, Sandia Base, Albuquerque, N. Mex.
- 145 Commander, Field Command, DASA, Sandia Base, Albuquerque, N. Mex. ATTN: FCIG
- 146-150 Commander, Field Command, DASA, Sandia Base, Albuquerque, N. Mex. ATTN: FCWF  
Mr. R. V. Rhode
- 151 Commander-in-Chief, Strategic Air Command, Offutt AFB, Neb. ATTN: OAWB
- 152 Commander-in-Chief, APO 128, New York, N.Y.
- ATOMIC ENERGY COMMISSION ACTIVITIES
- 153-155 U.S. Atomic Energy Commission, Technical Library, Washington 25, D.C. ATTN: For IMA
- 156-157 Los Alamos Scientific Laboratory, Report Library, P.O. Box 1663, Los Alamos, N. Mex. ATTN: Helen Redman
- 158-162 Sandia Corporation, Classified Document Division, Sandia Base, Albuquerque, N. Mex. ATTN: H. J. Smyth, Jr.
- 163-165 University of California Lawrence Radiation Laboratory, P.O. Box 808, Livermore, Calif. ATTN: Clovis G. Craig
- 166 Essential Operating Records, Division of Information Services for Storage at ERC-E, ATTN: John E. Hans Chief, Headquarters Records and Mail Service Branch, U.S. AEC, Washington 25, D.C.
- 167 Weapon Data Section, Technical Information Service Extension, Oak Ridge, Tenn.
- 168-200 Technical Information Service Extension, Oak Ridge, Tenn. (Surplus)

**SUPPLEMENTARY**

**INFORMATION**



SSTL

Defense Nuclear Agency  
6801 Telegraph Road  
Alexandria, Virginia 22310-3398

# ERRATA

14 September 1995

*AD-344937*

MEMORANDUM TO DEFENSE TECHNICAL INFORMATION CENTER  
ATTN: OCD/Mr Bill Bush

SUBJECT: Change of Distribution Statement

The following documents have been downgraded to Unclassified and the distribution statement changed to Statement A:

- |                     |                    |
|---------------------|--------------------|
| WT-1307, AD-311926  | WT-1305, AD-361774 |
| POR-2011, AD-352684 | WT-1303, AD-339277 |
| WT-1405, AD-611229  | WT-1408, AD-344937 |
| WT-1420, AD-B001855 | WT-1417, AD-360872 |
| WT-1423, AD-460283  | WT-1348, AD-362108 |
| WT-1422, AD-615737  | WT-1349, AD-361977 |
| WT-1225, AD-460282  | WT-1340, AD-357964 |
| WT-1437, AD-311158  |                    |
| WT-1404, AD-491310  |                    |
| WT-1421, AD-691406  |                    |
| WT-1304, AD-357971  |                    |

If you have any questions, please call MS Ardith Jarrett, at 325-1034.

FOR THE DIRECTOR:

*for* *Ardith Jarrett*  
JOSEPHINE WOOD  
Chief  
Technical Support

# ERRATA

15120/8