

UNCLASSIFIED

AD NUMBER

AD376822

CLASSIFICATION CHANGES

TO: unclassified

FROM: confidential

LIMITATION CHANGES

TO:

Approved for public release, distribution unlimited

FROM:

DISTRIBUTION: USGO: OTHERS TO DIRECTOR,
DEFENSE ATOMIC SUPPORT AGENCY, WASHINGTON,
D. C. 20301.

AUTHORITY

DSWA ltr., 9 Apr 1997; DSWA ltr., 9 Apr
1997

THIS PAGE IS UNCLASSIFIED

474

b ✓

XRD-56

AEC RESEARCH AND DEVELOPMENT REPORT


GROUP 1
Excluded from automatic downgrading
and declassification

CONFIDENTIAL

AD NO. 376822

DDG FILE COPY

TECHNICAL REPORT
1583/68
of 1968
29 NOV 1965
DEFENSE ATOMIC
SUPPORT AGENCY



A Facsimile Report

DDC


NOV 8 1965

Reproduced by
UNITED STATES

ATOMIC ENERGY COMMISSION

Division of Technical Information

P.O. Box 62 Oak Ridge, Tennessee 37831




This material contains information affecting the national defense of the United States within the meaning of the espionage laws, Title 18, U.S.C., Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

Incl 4 of 1

EXCLUDED FROM AUTOMATIC
DECLASSIFICATION
DATE 03-08-2000 BY
all J.P.
CONFIDENTIAL

SECTION NO.	<input type="checkbox"/>
DEST.	<input type="checkbox"/>
TOC	<input type="checkbox"/>
UNANNOUNCED	<input type="checkbox"/>
CLASSIFICATION	
BY	
DISTRIBUTION/AVAILABILITY CODES	
SIST.	AVAIL. AND/OR SPECIAL 3

IN ADDITION TO SECURITY REQUIREMENTS WHICH APPLY TO THIS DOCUMENT AND MUST BE MET, EACH TRANSMITTAL OUTSIDE THE AGENCIES OF THE U. S. GOVERNMENT MUST HAVE PRIOR APPROVAL OF THE DIRECTOR, DEFENSE ATOMIC SUPPORT AGENCY, WASHINGTON, D. C. 20301.



CONFIDENTIAL

XRD

65

(17) XRD-56

CONFIDENTIAL

BUREAU OF SHIPS GROUP
TECHNICAL INSPECTION REPORT

GROUP 3
Downgraded at 12 year intervals
Not Automatically Declassified



CONFIDENTIAL

Classification (Security) (Controlled) (Controlled) (Controlled) (Controlled)
By Authority of JCS SECRETARY OF DEFENSE
By Authority of JCS SECRETARY OF DEFENSE
BY JCS SECRETARY OF DEFENSE
MAY 16 1982

APPROVED:
F. K. Forest,
Captain, U.S.N.



Page 1 of 75 Pages

(17) 1946
(17) 41

CONFIDENTIAL
Security Information



ATOMIC ENERGY ACT 1946

CONFIDENTIAL

TABLE OF CONTENTS

	PAGE NO.
Ship Characteristics Sheet	3
Midship Section	4
Overall Summary of Damage	5
Hull Technical Inspection Report (Section I)	12
Machinery Technical Inspection Report (Section II)	18
Electrical Technical Inspection Report (Section III)	25
Photographic Section (Section IV)	34
Ship Measurement Data (Appendix)	54
Commanding Officers Report (Appendix)	55


CONFIDENTIAL

Classification (Security) (Controlled) (Controlled) (Controlled) (Controlled)
By Authority of JCS SECRETARY OF DEFENSE
By Authority of JCS SECRETARY OF DEFENSE
BY JCS SECRETARY OF DEFENSE
MAY 16 1982

USS BANNER (APA60)

Page 2 of 75 Pages

CONFIDENTIAL
Security Information



ATOMIC ENERGY ACT 1946

Handwritten signature or initials in the top right corner.

CONFIDENTIAL

U.S.S. BANNER (AFASO)

SHIP CHARACTERISTICS

Building Yard: Consolidated Steel Corp., Wilmington, California.

Commissioned: 18 September 1944.

HULL

Length Overall: 428 feet 0 inches.
Length on Waterline: 400 feet 0 inches.
Beam (extreme): 58 feet 0 inches.
Depth (molded to upper deck): 37 feet 0 inches.
Draft at time of test: 74 ft. 3 inches.
Draft at time of test: 74 ft. 3 inches.
Displacement at time of test: 7,150 tons.
Displacement at time of test: 6,588 tons.

MAIN PROPULSION PLANT

Main Engines: Two sets of Westinghouse steam turbines, directly connected to Westinghouse main generators. Two main shaft motors.
Main Condensers: Two are installed in ship.
Boilers: Two Babcock and Wilcox boilers are installed in ship. 460 psi range - 760° F.
Preheaters: Two are installed in ship.
Main Motors: Two are installed in ship.
Ship Service Generators: Five Turbo Gen's are installed. Two - 250 KW. - 460 V. - A.C., Cos - 140 KW. - 450 V. A.C. and two 100 KW. - 120V. - D.C. units.

CONFIDENTIAL

Classification: (changed to) CONFIDENTIAL (changed to) CONFIDENTIAL
By order of the SECRETARY OF THE NAVY
10/15/44
10/15/44
10/15/44


U.S.S. BANNER (AFASO)

Page 3 of 75

CONFIDENTIAL

Security Information

ATOMIC ENERGY ACT 1946



TRADE TO LOSING CITY

MIDSHIP SECTION

TEST A

U.S.S. BANNER (AFASO)

PAGE 4 OF 75

8050

TECHNICAL INSPECTION REPORT

OVERALL SUMMARY

1. Vessel Condition After Test

(A) Damage after test, list, amount of water in flooding, seawater.

1. No water was observed, water in bilge is 100 lbs. No list.

(B) Structural damage:

HULL

The vessel sustained no damage to the main hull. Superstructure on the starboard side has light superficial damage.

MACHINERY

The water passages of both stacks were moderately soaked on both sides, etc.

ELECTRICAL

Not observed.

(C) Other damage.

HULL

Not observed.

CHIMNEY

An electric drifting furnace in a passageway opening into the after cargo space was smashed by blast pressure entering via the cargo hatch opening.

SECRET

USS BANNER (APASO)

PROBABLE CAUSE

... were damaged by blast. A number of cables were broken by shock. A number of cables were broken by blast heat. The P.A.B. signal at the signal bridge was destroyed by fire.

... and ...

(a) Blast

NULL

Blast radiation came from approximately 150 degrees ... Blast caused and blistered paint on the entire starboard side ...

MACHINERY

... machinery spaces.

ELECTRICAL

Exposed paint work was scorched by the blast heat. A small amount of electrical cable had the insulation scorched by heat.

(b) Fires and explosions

NULL

A fire was started by heat radiation in the starboard engine room.

MACHINERY

Not evidenced.

SECRET

USS BANNER (AP-30)

Page 6 of 75 Pages

ELECTRICAL

A fire occurred in the main engine room on the signal bridge. There were no explosions.

(a) Blast

NULL

Shock came from approximately 150 degrees starboard. Arcular light bulbs in topside structure, starboard were broken. Bulbs in shock mounts were undamaged.

MACHINERY

Not evidenced.

ELECTRICAL

A number of lamps were broken by shock. Most of these were located above the main deck.

(b) Pressure

NULL

The apparent direction of the pressure blast was from approximately 150 degrees relative.

MACHINERY

Blast pressure moderately dented the outer coatings on both stacks, and smashed an electric drilling fountain exposed to the direct effect of the pressure.

ELECTRICAL

There were no effects of pressure noted in electrical equipment.

SECRET

USS BANNER (AP-30)

Page 7 of 75 Pages

(4) Effects resulting to the Atlantic Bomb

HULL

None.

MACHINERY

None.

ELECTRICAL

The above items by what was apparently radiant heat in the only affected noted as being peculiar to the atom bomb.

12. Results of Test on Target

(3) Effect on machinery, electrical, and ship control

HULL

None.

MACHINERY

The damage had no effect on the operation of the machinery installation. Ship control was not affected insofar as machinery was concerned.

ELECTRICAL

There was no effect on propulsion and ship control.

(4) Effect on gunnery and ship control

HULL

None.

SECRET

USS BANNER (APAGO)

Page 6 of 75 Pages

MACHINERY

No comment.

ELECTRICAL

There was no effect on gunnery and fire control.

(c) Effect on watertight integrity and stability.

HULL

The watertight integrity and stability of the vessel were not affected by the test.

MACHINERY

No comment.

ELECTRICAL

There was no effect on watertight integrity and stability.

(d) Effect on personnel and habitability.

HULL

Some injury to personnel would have probably resulted from the blast pressure or from the cargo hatch covers being blown into the holds. Habitability was negligibly affected.

MACHINERY

The test would have had no effect on personnel or habitability insofar as machinery is concerned.

ELECTRICAL

Electrical damage would have had no effect on the personnel nor on the habitability of the vessel.

SECRET

USS BANNER (APAGO)

Page 9 of 75 Pages

e) Effect on fighting capability.

NOTE

The blast pressure did not impair either the hull strength or its seaworthiness. The superficial damage done to the superstructure did not affect the operability of equipment.

MACHINERY

None, inside the machinery is concerned.

ELECTRICAL

Electrical damage would have had no effect on the operating capability of the vessel.

IV. Summary of Observers' Impressions and Conclusions.

Damage is superficial. While some casualties might have been sustained by personnel stationed topside, the vessel would have been able to proceed on its mission.

MACHINERY

The BANNER was outside the effective range of the explosion in test A.

ELECTRICAL

The vessel suffered moderate blast in the weather deck and moderate shock to the superstructure areas. There was sufficient heat to ignite inflammable material.

V. Preliminary Recommendations.

NOTE

None.

SECRET

Page 10 of 75 Pages
USS BANNER (APAG0)

MACHINERY

NOTE

ELECTRICAL

Light weight salient equipment should have the exposed area reduced as much as possible, or should be strengthened. Combustible material should not be exposed topside. High shock lamps should be used throughout the vessel.

SECRET

Page 11 of 75 Pages
USS BANNER (APAG0)

TECHNICAL INSPECTION REPORT

SECTION I - HULL

GENERAL SUMMARY OF HULL DAMAGE

I. Target Condition After Test.

(a) Drafts after test, list, general areas of flooding sources.

list. There was no flooding, hence no change in drafts or

(b) Structural Damage.

The vessel sustained no damage to the main hull Superstructure on the starboard side has light superficial damage.

(c) Other damage.

Not observed.

II. Forces Evidenced and Effects Noted.

(a) Heat.

Heat radiation came from approximately 150 degrees relative. Heat charred and blistered paint on the entire starboard side and caused a fire on the signal bridge. Signal halyards were burned. Exposed cordage was scorched.

(b) Fires and Explosions.

A fire was started by heat radiation in the starboard flagbag and damaged adjacent equipment.

There were no explosions.

SECRET

USS BANNER (APAGO)

Page 12 of 75 Pages

IV. Summary of Observations

Damage to structure of ship might have been sustained by... would have been able to proceed...

No comment.

VI. Instructions for loading the vessel at present are following:

- ITEMS: Fuel oil, Diesel oil, Ammunition, Portable and reserve feed water, Salt water ballast.

Details of the arrival quantities of... aboard are included in Report 3, Stability Department Report, and... by the ships force in accordance with instructions to Target... for Tests and Observations by Ship's Force issued by the Director of Ship's Material. This report is available for inspection in the Bureau of Ships Crossroads.

SECRET

(c) Shock.

Shock came from approximately 150 degrees relative. About seven light bulbs in topside structure, starboard were broken. Bulbs in shock mounts were undisturbed.

(c) Pressure.

The apparent direction of the pressure blast was from approximately 165 degrees relative.

(e) Effects peculiar to the Atom Bomb.

None.

III. Effects of Damage.

(a) Effect on machinery, electrical, and ship control.

None.

(a) Effect on gunnery and fire control.

None.

(c) Effect on watertight integrity and stability.

The watertight integrity and stability of the vessel were not affected by the Test.

(c) Effect on personnel and habitability.

Some injury to personnel would have probably resulted from the blast pressure or from the cargo hatch covers being blown into the holds. Habitability was negligibly affected.

(e) Effect on fighting efficiency.

The blast pressure did not impair either the hull strength or its seaworthiness. The superficial damage done to the gunnery structure did not affect the operability of equipment.

SECRET

EXTENSIVE DESCRIPTION OF BATTLE DAMAGE

Damage Description of Main Deck

The vessel sustained light superficial damage to the starboard side of the superstructure. Paint is generally charred and blistered throughout the starboard side of the vessel. General views of the vessel are shown on pages 26 to 47, inclusive.

A. Superstructure.

Stackheads (7.5 point) facing to starboard and all lower deck tops and damage consisting of one to two inch dishing. The forward weather plate at frame 22, starboard was bent slightly forward and back the welds connecting the angle bar stiffeners to the superstructure deck. The after stack has a maximum dish of ten inches on the starboard after face and six inches on the port side. (Photo, 1733-4; Page 48). The forward stack has lighter damage. Weather decks in the general area of the superstructure are sprung and operable. An exposed 1.5 pound signal bridge is dished and bent. (Photo, 1733-4; page 48). Gun tugs on 10 pound plate are dished.

A fire started by heat radiation destroyed the starboard lighting, searchlights, portable announcing equipment, and various electrical cables and junction boxes on the starboard signal bridge. (Photo, 1733-1; page 45). Signal lanterns were burned, exposed cables were scorched.

Paint scorching and blistering although wide spread, is confined to deck. There was no blistering of deck plating. Black ash on canvas wrapping of ladder structure and rails at frame 27, starboard, upper deck, was almost completely scorched and white similar material nearby was white.

B. Turrets, Guns, and Directors.

No damage.

C. Torpedo Mounts, Depth Charge Crates.

Not applicable.

2. Weather Deck.

Damage sustained on the weather deck was principally restricted to the portion which carries the main mast. Blast caused the main covers to deflect downwards sufficiently to injure port main supports. None of the covers are bent. The mainmast deck was installed in the mainmast frame at the weather deck and measured as page 51.

F. Exterior Hull.

No damage.

G. Interior Compartments (above deck).

Upper deck main covers fell into main hold, and damaged covers at lower levels (photos 1812-11 and 1812-10, page 47). In the after hold the blast reached on the mainmast frame main covers, deflecting them until they dropped into the hold. Similar damage to main covers occurred in the forward hold. Many small markers were ripped or broken in bulkheads and mainmast. Pipe, stanchion supporting beams also dished or bent (photos 1812-10, 11 and 9, page 45, 46 and 50).

In the after hold, main deck stanchion, a small metal lightbox was blown apart.

H. Armor Deck and Miscellaneous Areas.

Not applicable.

I. Interior Compartments (below W.L.).

No damage.

J. Underwater Hull.

No damage.

SECRET

Final Condition After Tests

- (a) Electric after being tested under conditions contained in paragraph 10 of this report.
- (b) Structural Damage.

The other contents of both chambers were immediately sealed on both sides, etc.

(c) Other damage.

An electric drilling (containing a primary battery opening into the after cargo space) was subjected to high pressure entering via the cargo hatch opening.

L. Forces Evidenced and Effects Noted.

- (a) Heat. Not evidenced in remaining spaces.
- (b) Fires and explosions. Not evidenced.
- (c) Shock. Not evidenced.
- (d) Pressure. Not evidenced.

High pressure moderately deformed the outer casing of both chambers, and smashed an electric drilling mechanism exposed to the direct effect of the pressure.

SECRET

USS BANNER (AP-80)

... in the ... of the ...

A large amount of granular material, similar to that used in the tests, was found in the ... The material was ...

1. High Pressure

By ...

2. Fire and Explosions

No damage.

3. Shock

No damage.

4. Temperature

No damage.

5. Strength

No damage.

6. Miscellaneous

No damage.

SECRET

USS BANNER (AP-80)

(b) Effects reportedly from the atomic bomb.

None.

(c) Effects of Damage.

(1) Effect on machinery and ship control.

The damage had no effect on the operation of the machinery installation. Ship control was not affected insofar as machinery was concerned.

(2) Effect on gunnery and fire control.

No comment.

(3) Effect on water-tight integrity and stability.

No comment.

(4) Effect on personnel and habitability.

The test would have had no effect on personnel or habitability insofar as machinery is concerned.

(5) Total effect on fighting capability.

None, insofar as machinery is concerned.

IV. General Summary.

The BANNER was capable of effective range of the explosion in West A.

V. Preliminary Recommendations.

None.

SECRET

USS BANNER (APAG)

DETAILED DESCRIPTION OF MACHINERY DAMAGE

A. General Description of Machinery Damage.

(a) Overall condition.

The outer casings of both units were severely dented. This does not impair operation. One electric driving shaft, main deck, frame 185 amidships, was cracked by the shock pressure exerted via the cargo hatch opening. Otherwise, the overall condition of the machinery was not changed by test A.

(b) Areas of major damage.

None.

(c) Primary cause of damage.

Not applicable.

(d) Effect of target test on overall condition of machinery plant.

The test had no effect on the overall condition of the machinery plant. Normal operation was resumed immediately after the test. All machinery has been operated since West A and Ammunition normally.

B. BOILERS.

1. The boilers were not damaged by West A. Both boilers have been steamed since the test, and performed normally.

2. Boiler #2 was left under hydrostatic pressure of 80 lbs/sq. in. when the ship was abandoned at 1145 June 29. Upon return of the crew at 1500 July 2 a pressure of 60 lbs/sq. in. remained.

3. Boiler #1 was left under steam pressure of 450 lbs/sq. in. when the ship was abandoned. No pressure remained when the crew returned.

SECRET

USS BANNER (APAG)

The main details of both tests were moderately successful on both tests. The tests did not affect operation (see photos 2001-1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100).

C. Blowers.
Undamaged. All blowers were operated under normal conditions after Test A.

D. Fuel Oil Equipment.
Undamaged. All equipment was inspected and operated under service conditions.

E. Boiler Feedwater Equipment.
Undamaged. All equipment was inspected and operated under service conditions.

F. Main Propulsion Machinery.
Undamaged. Turbogenerator No. 2 was operated as requested in both tests. After Test A, visual inspection of the propeller, No. 2 revealed no damage.

G. Electrical Tests.
Not Applicable.

H. Engines and Bearings.
Undamaged. All cylinders and bearings were tested with the 100% burners.

I. Refrigeration Plant.
Undamaged. All equipment was inspected and operated under service conditions after Test A.

SECRET
USS BARNIER (APASG)
Page 21 of 75 Pages

J. Condensers and Air Heaters.
Undamaged. The condensers were inspected and operated under service conditions after Test A and maintained a vacuum of 28.5 in. Hg.

K. Pumps.
Undamaged. All pumps were operated under normal conditions and auxiliary condensers were left open during the tests.

L. Auxiliary Generators (Franklin and Geare).
Undamaged. All ship's service turbo generators (6) were satisfactorily operated under load after Test A.

M. Propellers.
Undamaged. The starboard propeller was inspected from the water surface. The port propeller was not visible. The propellers were checked while the main engines were in operation.

N. Distilling Plant.
Undamaged. The distilling plant has been in operation since Test A with no change in the quantity or quality of water distilled.

O. Refrigeration Plant.
Undamaged. Two cold boxes were inspected before Test A. Their contents were not changed by the tests. The remainder of the refrigeration plant has been in operation since Test A, and functions normally.

SECRET
USS BARNIER (APASG)
Page 22 of 75 Pages

W. Miscellaneous.

Laundry, galley, and machine shop equipment operated satisfactorily after Test A.

One electric drinking fountain, main deck, frame 136, amidships, was smashed by effect of blast which came down the cargo hatch opening.

2. Watch, W. L. L. System, Systems.

Undamaged. All White Davis and watches, the watch windows, and the systems have been operated since Test A, and functioned normally.

3. Electric Engines.

Undamaged. Both steering systems operated satisfactorily while throwing the rudder from full right to full left.

4. Generators, Auxiliary (No. 4, 5, 6).

Undamaged. The generator No. 4 and all four communication lights have been operated since Test A. Operation was normal.

5. Ventilation (Machinery).

Undamaged. All blowers have been operated satisfactorily since Test A.

6. Compressor Air Plant.

Undamaged. The air compressor operated satisfactorily at rated pressure since Test A.

7. Pumps (Aspirators and Bells).

Undamaged. The diesel generator and the two aspirator pumps were operated satisfactorily at rated load after Test A.

8. Signal Systems.

Undamaged. The piping was tested at rated pressure. No leaks were observed.

SECRET

USS BANBER (APAGO)

Page 23 of 75 Pages

SECRET

USS BANBER (APAGO)

Page 24 of 75 Pages

TECHNICAL INSPECTION REPORT

SECTION II - ELECTRICAL

GENERAL SUMMARY OF ELECTRICAL DAMAGE

I. Target Condition After Test.

(a) Drafts after test; list; general areas of flooding, sources.
Drafts and lists were not observed. There was no flooding.

(b) Structural damage.

Not observed.

(c) Other damage.

12' searchlights were damaged by blast. A number of lamps were broken by shock. A small amount of cable was scorched by blast heat. The P.A.B. amplifier on the signal bridge was destroyed by fire.

II. Forces Evidenced and Effects Noted.

(a) Heat.

Exposed paint work was scorched by the blast heat. A small amount of electrical cable had the surface scorched by the heat.

(b) Fires and explosions.

A fire occurred in the starboard flag bag on the signal bridge. There were no explosions.

SECRET

USS BANNER (APA60)

(c) Shock.

A number of lamps were broken by shock. Most of these were located above the main deck.

(d) Pressure.

There were no effects of pressure noted in electrical equipment.

(e) Any effects apparently peculiar to the atom bomb.

The scorching by vinyl was apparently radiant heat is the only effect noted as being peculiar to the atom bomb.

II. Effects of Damage.

(a) Effect on propulsion and ship control.

There was no effect on propulsion and ship control.

(b) Effect on gunnery and fire control.

There was no effect on gunnery and fire control.

(c) Effect on water-tight integrity and stability.

There was no effect on water-tight integrity and stability.

(d) Effect on personnel and habitability.

Electrical damage would have had no effect on the personnel nor on the habitability of the vessel.

(e) Total effect on fighting efficiency.

Electrical damage would have had no effect on the fighting efficiency of the vessel.

SECRET

USS BANNER (AP480)

Page 28 of 75 Pages

IV. General Summary of Observations, Impressions, and Conclusions.

The vessel suffered moderate blast in the weather areas and moderate shock to the superstructure areas. There was sufficient heat to ignite inflammable materials.

V. Any Preliminary General or Specific Recommendations of the Inspecting Group.

Lightweight galvanized steel should have its exposed area reduced as much as possible. Combustible material should not be exposed to the shock. The shock should be used throughout the vessel.

SECRET

USS BANNER (AP480)

Page 27 of 75 Pages

DETAILED DESCRIPTION OF ELECTRICAL DAMAGE

General Description of Electrical Damage

(a) Overall condition.

(b) Areas of major damage.

(c) Primary causes of damage in each area of major damage.

(d) Effect of target test on overall operation of electric plant.

(e) Ship's service generator plant - no effect.

(f) Engine and boiler auxiliaries - no effect.

(g) Electrical propulsion - no effect.

(h) Communications - fire on the signal bridge

caused one main powered telephone handset and four (4) jackbox

circuits.

(i) Fire control circuits - no effect.

(j) Ventilation - no effect.

(k) Lighting - about seventy (70) bulbs were broken

on main deck and below.

SECRET

USS BANNER (AP-60)

(e) Types of equipment most affected.

1. Substancards and motor gear - no effect.
2. Solenoid machinery - no effect.
3. Motor controllers - no effect.
4. Cables and supports - no effect, except for a very small amount of lightly stretched cable.
5. Wiring equipment - a small number of drawings burned on the signal bridge.
6. Lamps - about seventy (70) standard and rough service lamps were broken by shock.

B. Electric Propulsion Rotating Equipment

Propulsion motors, generators and alternators showed no damage on inspection after the test. During deck trials, motors and alternators were operated in all combinations.

C. Electric Propulsion Control Equipment

Inspection and a deck trial revealed no damage in the control equipment.

D. Generators - Ships Service.

Machines showed no damage on inspection and operated satisfactorily.

E. Generators - Emergency.

The Diesel emergency generator was used to supply power upon the return of the ship's force to the vessel after the test. No damage was apparent.

SECRET

USS BANNER (AP-60)

F. Switchboards, Distribution and Transfer Panels.

All switchboards were examined and energized. All circuits and from the boards were given insulation resistance tests. No change or abnormal condition was found.

G. Wiring, Wiring Equipment and Wireways.

1. Rubber covered cables, when exposed in locations adjacent to the surrounding paint work was blistered, showed evidence of weather cracking although cables was still serviceable. Armor cables in the same location showed no heat damage.

2. Rubber watertight seals for pushbuttons showed the same charring as the rubber covered cable when exposed to the enemy boat.

3. At frame 110, main deck starboard, a sheet metal bulkhead collapsed, shearing two lighting cables, running from the overhead down the bulkhead. At the first bulkhead strap the break occurred. This damage was obviously not due to faulty electrical design.

H. Transformers.

Inspection and normal tests revealed no damage in any transformers. All transformers are located well away from all blast areas.

I. Submarine Propelling Batteries.

This item does not apply to the vessel.

J. Portable Batteries.

No portable battery was damaged in any way. No battery gave any indication of having failed. The emergency Diesel starting battery functioned properly on return of the ship's force following the test.

SECRET

USS BANNER (APA30)

Page 50 of 75 Pages

K. Motors, Motor Generator Sets and Motor Generator Sets.

No damage was found to any motor, motor controller or motor generator. All units were checked and performed satisfactorily.

L. Lighting Equipment.

1. About seventy (70) standard and searchlight lamps were broken throughout the ship. Most of the breakages were on main deck and above, although a number occurred in the engine quarters on the second deck.

2. No lighting fixtures or wiring were damaged by the blast.

3. A Cross-Strut 500 W. Type AOB-44 Cal. No. 42740X, cargo flood light had front glass, bulb and mirror broken, and one point of the three point mounting broken. The light was broadside to the blast.

M. Searchlights.

1. Two (2) 24" signal searchlights above the signal bridge, port and starboard on the forward stack, were undamaged. These lights were of the latest welded steel construction.

2. Two (2) 12" signal searchlights were mounted on the wings of the signal bridge. Both lights were well exposed to the blast. The starboard light had the lamp broken. The port light was mounted on the hard rail which collapsed, allowing the light to fall against the adjacent blast grange cover. The detector, front door glass, lamp and lamp base were broken; and a similar handle jammed so as to be inoperable. The damage is not a fault of lamp design but of mounting.

SECRET

USS BANNER (APA30)

Page 51 of 75 Pages

D. Indicating System.

No damage was noted in the indicating system.

E. Indicating System.

Only one (1) indicating system was inspected. The 'Edwards' fire alarm annunciator, Div. 6227, Type B, 12 neon indicator lights projecting through holes in the front panel were broken. It is believed that the breakage was caused by the dislodging of a jury-rigged metal shield, installed to prevent light from showing during darkened ship conditions. This shield was not a part of the original design. It was noted that the holes in the panel itself were small and that any misalignment of bulbs would result in contact with the panel and danger from breakage due to vibration on shocks. The panel was mounted on the forward port wheel house bulkhead.

F. Indicating System.

The combined I.C. and A.C.O. switchboard was inspected. No damage was found and the board operated satisfactorily.

G. Indicating System.

This item does not apply to the vessel.

SECRET

USS BANNER (APAGO)

Page 33 of 75 Pages

D. Indicating System.

No damage was noted in the indicating system.

E. Indicating System.

Only one (1) indicating system was inspected. The 'Edwards' fire alarm annunciator, Div. 6227, Type B, 12 neon indicator lights projecting through holes in the front panel were broken. It is believed that the breakage was caused by the dislodging of a jury-rigged metal shield, installed to prevent light from showing during darkened ship conditions. This shield was not a part of the original design. It was noted that the holes in the panel itself were small and that any misalignment of bulbs would result in contact with the panel and danger from breakage due to vibration on shocks. The panel was mounted on the forward port wheel house bulkhead.

F. Indicating System.

The combined I.C. and A.C.O. switchboard was inspected. No damage was found and the board operated satisfactorily.

G. Indicating System.

This item does not apply to the vessel.

SECRET


USS BANNER (APAGO)

Page 33 of 75 Pages

SECTION IV

PHOTOGRAPHS

TEST ABLE



SECRET

USS BANNER (APA60)

Page 84 of 75 Pages

BA-CR-196-158-36. View from port bow before Test A.


SECRET

USS BANNER (APA60)

Page 35 of 75 Pages

SECRET

USS BANNER (APA60)




AA-CR-227-67-84: View from off port beam after Test A.

SECRET

USS BANNER (APA60)

8838

Page 36 of 75 Pages




BA-CR-198-159-84: View from off port quarter before Test A.

SECRET

USS BANNER (APA60)

8838

Page 37 of 75 Pages




AA-CR-227-87-37. View from off port quarter after Test A.

SECRET

Page 88 of 75 Pages

USS BANNER (APA 60)

8838



BA-CR-198-159-40. View from off starboard quarter before Test A.

SECRET

Page 89 of 75 Pages

USS BANNER (APA 60)

8838




EA-CR-227-01-01. View from off starboard quarter after Test A.

USS BANNER (APA 60)

0050

Page 40 of 75 Pages

SECRET



EA-CR-193-159-38. View from off starboard bow before Test A.

SECRET

USS BANNER (APA 60)

0050

Page 41 of 75 Pages




AA-CR-227-87-36. View from off starboard bow after Test A.

SECRET

Page 42 of 75 Pages

USS BANWER (APA-50)
0350




AA-CR-65-1733-5. Starboard side of after stack showing blast damage.

SECRET

Page 43 of 75 Pages

USS BANWER (APA-60)
0350




AA-CR-65-1738-4. Damage to signal shack on signal bridge.

SECRET

Page 44 of 75 Pages

USS BANNER (APA 60)

8858




AA-CR-65-1733-1. Damage caused by fire in starboard flag bag.

SECRET

Page 45 of 75 Pages

USS BANNER (APA 60)

8859



AA-CR-82-1829-11. Holes in pontoons of forward cargo hold.

SECRET

Page 46 of 75 Pages

USS BANNER (APA60)

8858




AA-CR-82-1830-1. Holes and dents in pontoons of after cargo hold.

SECRET

Page 47 of 75 Pages

USS BANNER (APA60)

8853




AA-CR-79-1814-10. Damage to lockers in forward hold on main deck.

SECRET

Page 48 of 75 Pages

USS BANNER (APA60)
8858




AA-CR-79-1814-11. Wreckage on main deck in forward hold.

SECRET

Page 49 of 75 Pages

USS BANNER (APA60)
8858



AA-CR-82-2189-7. After stack, starboard side, looking aft.

USS BANNER (APA60)
8258

Page 51 of 75 Pages

SECRET



AA-CR-79-1814-8. Debris in after hold.

USS BANNER (APA60)
8258

Page 50 of 75 Pages

SECRET




AA-CR-62-2169-8. After stack, starboard side, looking forward.

SECRET

Page 52 of 75 Pages

USS BANNER (APA 60)

8888



AA-CR-62-2169-9. After stack, port side.

SECRET

Page 53 of 75 Pages

USS BANNER (APA 60)

8888

APPENDIX

SHIP MEASUREMENT DATA

TEST ABLE

SECRET

USS BANNER (APA60)

Page 54 of 75 Pages

2

DECK DEFLECTION GAGES

TEST A

COMP USE PAPER (APA-00)

GAGE NO.	LOCATION	TYPE	MAXIMUM COMP.	MAXIMUM EXP.	PERMANENT DISTANCE	SET EXP./COMP.	REMARKS
15	FACE	STB.	0-0-2/16	0-0-9/16	0-0-1/4	Exp.	Due to local condition
16	"	PORT	None	None	None	None	None
17	"	PORT	0-0-1/8	0-0-1/4	None	None	Due to local condition
18	"	STB.	0-0-1/8	0-0-5/8	None	None	Due to local condition
19	"	PORT	None	None	None	None	None
20	"	STB.	0-0-3/16	None	None	None	None

SECTION I

PART A - GENERAL SUMMARY

I. Target Condition After Test.

- 19 feet. List after test 2 degrees port. There was no flooding.
- (a) Draft after test - Forward: 8 feet 2 inches and
- (b) Damage to superstructure was negligible, same to the hull. The bulkheads in the vicinity of the holds were dented slightly. The hatch boards and their supporting structures covering both holds were knocked down into the holds. Some of the 1000 lb. bombarding shells lying up the first platform decks in the holds were picked up and dropped into the very bottoms of the holds. The stacks were dented slightly. The joiner bulkheads in the vicinity of the holds were distorted. A stack of two weather tight and three watertight doors were dented in enough to make them ineffective. The bulkheads at frame 53, port and starboard, on the superstructure deck were bent.

(c) There was very little damage to the machinery, electrical, ship control, fire control, gunnery or electronic equipment.

(c) The starboard side, the stern, and most vertical surfaces exposed to the blast showed evidence of scoring. Only one small hole was started - the starboard flag bag on the signal bridge - which was little damage. It is estimated that all personnel topside, in the other engine room and in the berthing compartments in the vicinity of the holds would have been killed or made ineffective by the sudden increase in pressure or blast.

II. Forces Evidenced and Effects Noted.

(a) The heat from the blast struck the ship from a true five bearing of about 150 degrees. The entire starboard side and the parts of the ship facing aft were scorched slightly, just enough to blister the first layer of paint. There was some evidence of heat on certain mainmast lines in the most exposed parts of the ship and signal bridge masts. The effects did not penetrate the hull nor bulkheads or equipment. There was nothing unusual in the behavior of structure or

SECRET

USS BANNER (APAGC)

Page 57 of 75 Pages

APPENDIX

COM WANDING OFFICERS REPORT

WEST ABLE

USS BANNER (APAGC)

Page 58 of 75 Pages

SECRET

58 on the superstructure deck were bent by the blast and several welds on strengthening frames cracked.

(e) The after starboard part of the ship and the exposed parts of the superstructure and masts were coated with a film of black, greasy soot. An aluminum coffee pot about eighteen inches high and rather unstable was found still erect on a bench topside about fifteen feet from the plane on deck and the after hold and about five feet from a weather tight door that was dished in.

III. Results of Test on Target.

(a) No effect.

(b) No effect.

(c) Three watertight doors were dished in and rendered ineffective.

(d) All personnel in exposed parts of the ship, in the after engine room and in the vicinity of the holds would have been killed or incapacitated for duty. Men in the wardroom, galley, country, closed bridge, troop berthing spaces and forward engine room would probably have survived the blast. The pressure wave knocked out the thin joiner bulkhead separating the after hold from the entrance to the after engine room on the starboard side and entered that space. Only evidence of the effect of the blast in the engine room was the shattering of glass and liquid pressure measuring instrument suspended in that space. It is assumed that the blast would have knocked out or killed the personnel in the after engine room. The galley was filled with soot but readily cleaned. The bunks knocked about half to the holds were useable. My conclusion is that the habitability of the ship was only slightly affected.

(e) The fighting efficiency of the ship would have been reduced only in proportion to the number of men rendered ineffective by the blast. Since all men topside would have had to have been replaced by less experienced personnel it is felt that the fighting efficiency of the ship would have been greatly reduced though the equipment was in no way damaged.

IV. General Summary of Observers' Impressions and Conclusions.

SECRET

USS BANNER (APAG6)
Page 59 of 76 Pages

(f) Only one fire was started and no explosions. The fire was started in the starboard wing and destroyed the Beach Master and the mainmast. The fire was extinguished by the crew and caused no damage. Cause of ignition appeared to be falling layers that were burning.

(g) The direction of the shock is presumed to have come from 150° relative to the ship's heading. The only evidence noted was the opening of locker doors and loose drawers in the vicinity of the holds. This effect was probably caused by the roll of the ship rather than by shock. About twenty light bulbs were broken in the ship, mostly in the topside compartments and along the starboard side aft above the main deck. Bulbs in shock mounts were undisturbed, the shock effect was much less than that noted in a preliminary after moderate depth charge.

(h) The pressure wave hit the ship from about 150° relative to the ship's heading. There was slight evidence of a coming from a reverse direction. The ship rolled 25° to starboard and 19° to port. The areas affected were topside, the holds and vicinity. Most of the light sheet metal structures topside were bent and all the wooden frames in the centers of the life rafts were dished. All the bayards were bent and some of the life rafts were dished. The weather tight and three watertight doors topside and aft and the stocks were dished slightly. The greatest damage was done to the holds and their immediate vicinity below deck. The hatch boards, 2' x 8' x 7', covering the holds were bent, dished and some were failed as much as 50%, and knocked into the first platform deck with such force that they tore several holes about 1/2 inches by 7/8 inches in aluminum plating. The large 1000 pound pentons tearing the first and second platform decks were lifted up and dropped down into the bottom of the holds. The large "C" beam type strongbacks supporting the hatch boards forming the cover of the hold were dished on the side and knocked into the bottom of the holds. Joiner doors of aft and starboard in the vicinity of the holds were ripped off heads, shearing only the hinge screws. Light metal lockers and bulkheads in the area were ripped out or bent. The damage appeared to be not penetrating the transverse blast pressure. Evidence of reverse pressure wave was the damage to the rigging's slack on the signal bridge and the discovery of a main shaft of one tier of life rafts aft and above the other side. The pentons were operated and the pressure waves of one tier of life rafts on the starboard side of frame 58. The pentons were also operated on other side of the ship at frame

SECRET

USS BANNER (APAG6)
Page 60 of 76 Pages

This ship is an attack transport with a primary mission of carrying troops and landing them at a designated spot. If the boats she carried were not damaged beyond repair facilities of the ship's force re- mained effective, the ship could carry out its mission successfully. Damage to the holds and loss of after engine room force and personnel in the vicinity of the holds could have been avoided with improved con- sideration of hatch covers over the holds and heavier metal protecting the openings to the engine rooms. Except for the loss of personnel by the bomb, generally speaking, had little effect on the effectiveness of this ship.

7. Preliminary Recommendations.

The damage to the hull was superficial. Frame structures that would be exposed to similar blasts must be made of heavier metal and reinforced in the strongly. The hatch boards covering the tops of the holds are too light and weak. They should be made much larger and stronger and firmly secured in place rather than just rested in their frames. The large 1000 pound portions forming the first main deck and second platform decks appear to be heavy and strong. Although they must also be firmly anchored in place. The main deck should be strengthened and decked. Living spaces adjoining the holds should be screened from the holds by heavy bulkheads and strong watertight doors. Changes to engineering spaces should be made by heavy flame proof doors. The holds should be closed off both the rest of the ship by heavy watertight doors.

SECRET

Page 30 of 76 Pages

USS BANNER (AP-60)

SECTION I

PART C - INSPECTION REPORT

SECTION A - HULL

A. General Description of Hull Damage.

- (a) Excellent.
- (b) No hull damage.
- (c) No comment.
- (d) None.
- (e) Conditions as they were before the blast.

B. Superstructure (exclusive of gun mounts).

(a) No damage to bridge area. Forward on signal bridge were burned and broken, starboard flag bag burned out, and signalmen's open deck house made of sheet metal badly bent but still usable. The two stacks were dished in slightly but nothing inside was damaged. Light metal structures bent and distorted.

(b) In all cases damage was caused by blast or pressure wave except in the case of the fire in the flag bag. This appeared to have been caused by falling halyards that were burning.

(c) None except for starboard flag bag on signal bridge and the beach master set next to it and probably some signal halyards.

(d) No comment.

(e) The use of light sheet metal anywhere in the superstructure should be discontinued for any blast will bend or rupture it making it unusable as well as a personnel hazard.

SECRET

Page 61 of 76 Pages

USS BANNER (AP-60)

operated by the pressure wave and the raft released. No comment.

F. Exterior Hull Above Waterline.

- (a) Only scorched along starboard side by blast.
- (b) No damage.
- (c) No damage.
- (d) None installed.

G. Interior Compartments Above Waterline.

(a) Only damage was in vicinity of holds. The blast dished the bulkheads of the holds outward slightly.

(b) Joiner bulkheads in the immediate vicinity of the holds were bent or damaged in varying amounts depending on their proximity to the holds. The bulkheads of offices, made of light metal, which formed a passageway with the heavy bulkhead of the holds were bulged outward slightly, that is, bulged towards the hold.

(c) One watertight door in the vicinity of the holds and two on the main deck were dished in slightly by the blast, still operable but no longer effective. Two weatherlight doors in the superstructure were in the same condition. Several joiner doors were ripped out nearly and blown several feet down the passageways. These doors were all pulled out away from the compartments they closed as if sucked along by the blast. These doors were in good condition generally. Only the screws holding their hinges were pulled out or sheered off. Some doors in the same area were unaffected.

(d) In the holds, the living spaces adjoining actual holds were unprotected by any bulkheads. Here bunk frames were scattered about and their supporting stanchions bent. Lockers in this area were crushed or blown apart. In the other compartments protected by doors, only the doors or bulkheads were damaged. Rarely was any damage caused inside the compartments. The blast just ripped the doors out or bulged the bulkheads slightly.

(e) None.

SECRET

USS BANNER (APA60)

Page 63 of 75 Pages

C. Rafts, Cams and Directors.

- (a) Excellent, entirely operable. No comment.
- (b) No comment.
- (c) Operators flash shield distorted so as to prevent clear view through telescope rangefinder. Excellent.
- (d) No comment.

D. Torpedo Mounts, Depth Charge Gear.

- (a) None installed.
- (b) None installed.

E. Weather Deck

(a) The deck was intact. The only damage was to the covering over the two cargo holds. The tops of both holds were crushed in. The hatch boards 1' x 3" x 7' covering the holds were bent downward (some were folded as much as 90°) and knocked onto the first platform deck with such force that they tore several holes about 3" x 6" in fifteen pound plate. The large 1000 pound porticos forming the first and second platform decks were lifted up and dropped down into the bottom of the holds. The large "I" beam type strongbacks supporting the hatch boards forming the cover of the holds were sheered off on one side and knocked into the bottom of the holds. The holds were also covered by three layers of canvas battered down. The holds were empty except for an aircraft in the bottom of No. 2 hold.

(b) The cover for the holds could not be repaired, but the large porticos that made up the platform decks could be lifted back into place.

(c) No comment. The wooden frames forming the center of the life rafts were jarred a little out of place but did not impair the effectiveness of the rafts. The sheet metal guides for tiers of rafts were bent over the rafts and might interfere with their release. This could not be checked as this vessel carried only one raft in each tier. The pressure release on the raft starboard side at frame 88 was

SECRET

USS BANNER (APA60)

Page 62 of 75 Pages

(c) Only one shell had part of its insulation torn. The wire was tested and found to be safe and trap of sections.

(d) Damage to lower water-tight doors involved the water-tight integrity. All damage in living spaces could be quickly repaired.

K. Armor Deck: (Not fitted).

(a) No comment.

L. Interior Compartments Below Waterline.

(a) No damage.

(b) No damage.

(c) No damage.

(d) Excellent and normal.

(e) None.

(f) None.

(g) None.

(h) Underwater Hull.

(a) Conditions normal.

(b) None.

(c) No damage.

(d) None ascertained.

(e) None.

(f) Conditions normal.

(g) None.

SECRET

USS BANNER (AP-60)

(c) None.

M. Flooding.

(a) None.

(b) None.

(c) None.

N. Ventilation.

(a) Emergency diesel exhaust duct cover dented in slightly on upper deck all the way aft closest to center of blast.

(b) A large amount of greasy soot was found in the galley which was similar to that found topside which apparently entered compartment via exhaust in No. 2 stack.

(c) None.

(d) Strengthen exposed ducts and duct covers by using heavier reinforced metal. Install closure in galley exhaust through No. 2 stack.

O. Ship Control.

(a) None to parts 1 through 5.

(b) None.

(c) Fire Control.

(d) None.

(e) All stations are exposed on this ship. It is felt that the blast would have incapacitated all men at their stations topside thus leaving the ship unable to man its guns until the crews could be replaced.

(f) I consider the locations of the various stations satisfactory, but a blast proof cover, if practical should be installed to protect the operators.

SECRET

USS BANNER (AP-60)

Ammunition Behavior.

(a) Ready service ammunition lockers located throughout the ship in accordance with approved design. No damage to any ammunition through one five inch ready box, all the way aft on the upper deck, but the door closed in slightly. Extent of lockers were searched but no evidence of heat found inside.

(b) Magazines located below decks in accordance with approved design and undamaged.

(c) No comment.

(d) No comment.

Ammunition Handling.

(a) Conditions normal.

(b) None.

(c) None.

Strength.

None.

Miscellaneous.

None.

SECRET

USS BANNER (AP-60)

SECTION I

PART C - INSPECTION REPORT

SECTION B - MACHINERY

A. General Description of Machinery Damage.

None.

B. Boilers.

No comment.

C. Blowers.

No comment.

D. Fuel Oil Equipment.

No comment.

E. Boiler Feedwater Equipment.

No comment.

F. Main Turbines.

No comment.

G. Reduction Gears.

No comment.

H. Shafting and Bearings

No comment.

SECRET

USS BANNER (AP-60)

1. Lube Oil System.

No comment.

2. Motors and Air Systems.

No comment.

3. Pumps.

No comment.

4. Auxiliary Components (Pulleys and Gears).

No comment.

5. Propellers.

No comment.

6. Steering Plant.

No comment.

7. Refrigerating Plant.

No comment.

8. Winches, Windlasses and Capstans.

No comment.

9. Steering Engine.

No comment.

10. Hoists, Ammunition Hoists, Etc.

No comment.

11. Ventilation (Machinery).

No comment.

(SEE APPENDIX FOR COMMENT.)

SECRET

USS BANNER (APA60)

Page 58 of 75 Pages

12. Air Compressors.

No comment.

13. Diesels (Generators and Pumps).

No comment.

14. Pumps.

No comment.

15. Miscellaneous.

No comment.

SECRET

USS BANNER (APA60)

Page 69 of 76 Pages

SECTION I

PART C - INSPECTION REPORT

SECTION C - ELECTRICAL

A. General Description of Electrical Damage.

(a) Overall comments.

All the electrical equipment was in excellent shape showing no effects of the blast whatsoever. No comments.

B. Electric Propulsion Rotating Equipment.

No comment.

C. Electric Propulsion Control Equipment.

No comment.

D. Generators - Ship's Service.

No comment.

E. Generators - Emergency.

No comment.

F. Switchboards, Distribution and Transfer Panels.

No comment.

G. Wiring, Wiring Equipment and Wireways.

No comment.

H. Transformers.

No comment.

SECRET

No comment.

I. Submarine Propelling Batteries.

Not installed.

J. Portable Batteries.

No comment.

K. Motors, Motor Generator Sets, and Controllers.

No comment.

L. Lighting Equipment.

(a) - (e) No comment.

(f) About 70 light bulbs shattered, all in torpedo compartments.

M. Searchlights.

No comment. One port 12" light swing and inoperative. One port 12" light broken and base started loose.

N. Degaussing Equipment.

No comment.

O. Gyro Compass Equipment.

No comment.

P. Sound Powered Telephones.

No comment.

Q. Ship's Service Telephones.

Not installed.

R. Announcing System.

SECRET

No comment.

S. Telegraphy.

No comment.

T. Indicator Systems.

No comment.

V. I. C. and A. C. O. Switchboards.

No comment.

W. F. C. Switchboards.

No comment.

SECTION I

PART C - INSPECTION REPORT

SECTION D - ELECTRONICS

A. General Description of Electronics Damage.

(a) Excellent.

(b) None

(c) No comment.

(d) 1. Excellent.

2. Insulators on four antennas shattered.

3. None installed.

4. None installed.

5. No comment.

B. Fire Control Radar.

No comment.

C. Surface Search Radar.

No comment.

D. Air Search Radar.

No comment.

E. Radar Repeaters.

No comment.

F. Radar Counter Measures Equipment.

No comment.

USS BANNER (APA60)

Page 72 of 75 Pages

USS BANNER (APA60)

Page 75 of 75 Pages

CONFIDENTIAL

- G. Radar and Radio Beacons.
No comment.
- H. IFF Equipment.
No comment.
- I. Communication Transmitters (Radio).
No comment.
- J. Communication Receivers (Radio).
No comment.
- K. Communication Antennae (Radio).
No comment.
- L. Radio Transmitters.
No comment.
- M. Sonar Echo Ranging and Listening Equipment.
No comment.
- N. Sonar Echo Sounding Equipment and Altimeters.
No comment.
- O. Lorenz Navigation Equipment.
No comment.
- P. Power Supplies (Motor Generators and Filters).
No comment.
- Q. Not applicable.

~~SECRET~~
USS BANNER (ARAGO)
Page 74 of 75 Pages

CONFIDENTIAL

CONFIDENTIAL

- R. Test Equipment.
No comment.
- S. Instruments.
No comment.
- T. Telephone Equipment.
No comment.
- U. Direction Finders (Radio).
No comment.
- V. Spare Parts.
No comment.

~~SECRET~~
USS BANNER (ARAGO)
Page 75 of 75 Pages

CONFIDENTIAL

CAUTION

This Document Contains
ATOMIC WEAPONS INFORMATION

NOTICE

This document contains atomic weapons information. Distribution is limited to recipients authorized by the Defense Atomic Support Agency (DOD) and/or the Division of Military Application (AEC)



Defense Special Weapons Agency
6801 Telegraph Road
Alexandria, Virginia 22310-3398

TRC

9 April 1997

MEMORANDUM FOR DEFENSE TECHNICAL INFORMATION CENTER
ATTENTION: OMI/Mr. William Bush

SUBJECT: Declassification of Reports

The Defense Special Weapons Agency (formerly Defense Nuclear Agency) Security Office has reviewed and declassified the following reports:

+ ST-A

AD-366748 -	XRD-65
AD-366747 ~	XRD-64
AD-366746 /	XRD-63
AD-376826 ~	XRD-60
AD-376824 ~	XRD-58
AD-376825 -	XRD-59
AD-376823 -	XRD-57
AD-376822 -	XRD-56
AD-376821 ~	XRD-55
AD-366743 ~	XRD-54
AD-376820 ~	XRD-53
AD-366742 ~	XRD-52
AD-366741 ~	XRD-51
AD-366740 -	XRD-50-Volume-2
AD-366739 -	XRD-49-Volume-1
AD-366738 -	XRD-48
AD-366737 /	XRD-47

TRC

9 April 1997

SUBJECT: Declassification of Reports

AD-366736 -	XRD-46
AD-366735 -	XRD-45
AD-366723 -	XRD-37
AD-366721 -	XRD-35
AD-366717 -	XRD-31-Volume-2
AD-366716 -	XRD-30-Volume-1
AD-366751 -	XRD-68-Volume-2
AD-366750 -	XRD-67-Volume-1
AD-366752 -	XRD-69
AD-366744 -	XRD-61.

All of the cited reports are now **approved for public release**. **Distribution statement "A"** now applies.

Ardith Jarrett
ARDITH JARRETT
Chief, Technical Resource Center

*Completed
1 Mar 2000
B.W.*