

UNCLASSIFIED

AD NUMBER: AD0842100

LIMITATION CHANGES

TO:

Approved for public release; distribution is unlimited.

FROM:

This document is subject to special export controls (11 Aug 1960) and each transmittal to foreign governments or foreign nationals may be made only with prior approval of: Hq. SAMSO, Los Angeles, CA 90045, Attn: SMSD

AUTHORITY

ST-A SAMSO, USAF LTR, 28 FEB 1972

AD842100

a

OCT 8 1950

AD842100

REPORT NO 27A589
DATE 11 August 1960
NO OF PAGES 15

CONVAIR ASTRONAUTICS
CONVAIR DIVISION OF GENERAL DYNAMICS CORPORATION

REPORT NO. 27A589
4C & 11D Failure Analysis
of
HELIUM PRESSURE REGULATOR
(FUEL TANK)

DWR. NO. 27-08217-3

CONVAIR
ASTRONAUTICS
SEP 15 1960
LIBRARY

This document is subject
to special export controls and
each transmittal to foreign
governments or foreign
nationals may be made only
with prior approval of:
Hq.SAMSO, LA., Ca. 90045
Attn: SMSD

PREPARED BY *D. J. Melvin*
D. J. Melvin, Test Engineer
CHECKED BY *C. F. Johnson*
For R. T. Tutobene, Lead Engineer

APPROVED BY *R. S. Campbell*
R. S. Campbell, Jr.
Test Lab Group Engineer
APPROVED BY *R. S. Campbell*
R. S. Campbell
Chief of Test Lab.

Checked By: *A. Mollenkopf*
A. Mollenkopf
Qualification Coordinator

REVISIONS

NO. DATE BY CHANGE

OCT 31 1968
PAGES AFFECTED

T A B L E O F C O N T E N T S

<u>SUBJECT</u>	<u>PAGE NO.</u>
Introduction	1
Object	1
Conclusion	1
Test Specimen	1
Test Procedure	1
Discussion of Results	2
Instrumentation Used	4
Figure 1 - Schematic of Test Setup	5
Figure 2 - Regulator Inlet Pressure vs Flight Time	6
Figure 3 - Specimen Ambient Pressure (psia) vs Flight Time	7
Figure 4 - Water Flow vs Flight Time	8
Figure 5 - Ullage Pressure vs Time, Run No. 1 and Run No. 2	9
Figure 6 - Ullage Pressure vs Time, Run No. 3 and Run No. 4	10
Figure 7 - Tube Temperature vs Time Run No. 5	11
Figure 8 - Run No. 5 and Typical Program Curves	12
Figure 9 - Tube Heater Schematic	13
Photo Index	14
Figure 10	15

INTRODUCTION: This test was conducted at the Gas Flow Laboratory to analyze failures that occurred in the airborne pressurization system of missiles 4C and 11D.

OBJECT: - The object of this test was to determine if the heating of the motor section pressure/bleed line on the regulator would result in a condition similar to that which caused the failures.

CONCLUSION: Although the heating conditions that were suspected of causing the failures were not duplicated exactly, the regulator functioned properly under the heating conditions that were obtained which were near the temperature desired.

TEST SPECIMEN: The test specimen was a Hadley "C" Series regulator, Specification Number 7-08217-3, Hadley P/N 10542-3. A coil designed to heat the motor section pressure/bleed tube to a temperature of 1500°F within 110 seconds of the program start was put on the regulator. The regulator was installed in the pressurization system of the 7-31-34 Fuel Battleship Tank. A schematic of this system is shown in Figure 1.

TEST PROCEDURE: The following is an outline of the procedure used during the test:

1. The fuel tank was filled with water to an ullage volume of 27±5 cu ft.
2. The tank was pressurized by means of the Facility pressurization control unit to a pressure between 62.0 and 63.3 psig.
3. With the specimen locked-up, the pressurization control unit was secured and 3100 ±100 psig helium was applied to the inlet port of the specimen.
4. The specimen was allowed a minimum of three leakage fills prior to the start of the flow program.
5. At the end of this period, the inlet pressure, altitude water flow, and altitude programs per figures 2, 3, and 4 were started along with the tube heater and the helium heat exchanger. The temperature of the helium was to reach +450°F within 90 seconds and the tube was to reach +1500°F within 110 seconds of the start.

DISCUSSION OF RESULTS:

It was suspected that the failures were caused by the heating of an external tube on the airborne fuel tank pressure regulator. This tube was the meter section pressure/bleed line from the pressurization duct to the metering cavity of the regulator. It was ~~thought~~ that the heating of the tube would cause the gas to expand and indicate to the metering device that there was a higher than desired pressure in the duct. This would cause the regulator to completely close with a resulting decrease in tank pressure.

Conversely, with the tube vented to ambient conditions, the regulator would go wide open to compensate for what seemed to be an extremely low tank pressure.

There were five operating cycles run on this specimen. The first run was made without the tube heater to obtain the operating characteristics of the regulator. The band chosen for the ullage pressure (58-63 psig) was found to be too high. The ullage pressure went off scale about midway through the run but it was considered that the run accomplished its purpose. The ullage pressure band was changed first to 53-63 psig and then to 55-60 psig.

Runs No. 2 and 3 were the first attempts made to heat the tube during an operating cycle. Both runs were unsatisfactory because the tube heater melted holes in the tube at approximately 90 sec. with a tube temperature of approximately 1050°F. This allowed the regulator to go wide open on Run No. 2 and partially wide open on Run No. 3, the difference being due to the size of the melted holes. The reason the heater melted holes in the tube was that the vacuum in which the regulator was operating caused an arc to jump from the heater to the tube.


The heater was redesigned and Runs No. 4 and 5 were made. Although no holes were melted in the tube, Run No. 4 was considered unsatisfactory because the tube temperature reached only 800°F. Run No. 5, with a hole melted in the tube, was considered to have accomplished the purpose of this test. The tube temperature had reached 1340°F before arcing caused holes to be melted in the tube. Under the circumstances it was decided that the temperature was near enough to the required temperature to satisfy the objective of the test.

Run No. 5 showed a gradual decrease of tank ullage pressure from 59.2 psig to about 56.5 psig. This was considered normal for this regulator because Run No. 1, the control run, showed a similar decrease. Therefore it was concluded that the heating of the tube had little or no effect upon the performance of the regulator.

THE INSTRUMENTATION USED FOR THIS TEST WAS AS FOLLOWS:

<u>MEASUREMENT</u>	<u>INSTRUMENT</u>	<u>GAL RANGE</u>
1. Ullage Pressure	Wiancko Transducer 0-100 psig	58-63 psig 53-63 psig 55-60 psig
2. Regulator Inlet Pressure	Statham Transducer 0-5000 psig	0-5000 psig 0-500 psig
3. Water Flow Rate	Hagan Ring Balance	0-5000 GPM
4. Regulator Inlet Temperature	Convair Astronautics (Dept. 756) Thermocouple; Ceramo, Copper-Constantin	0-500°F
5. Altitude Chamber Pressure	Wiancko Transducer \pm 15 psid	14.7-0 psia
6. Tube Temperature	Convair Astronautics (Dept. 562-1) Thermocouple; Chromel-Alumel	0-2400°F

4C 110 FAILURE ANALY
SCHEMATIC OF



A

ANALYSIS OF HELIUM PRESSURE REGULATOR OF TEST SET-UP




FIGURE 1

PREPARED BY

DATE

CHECKED BY

DATE

REVISED BY

DATE

2




FIG. 2

REF 10410 TO THE INCH 350-11




FIG. 3

MoS 10x1070740-1174 303-11




FIGURE 4





FIGURE 5

4C 5' 11.0 FAILURE ANALYSIS OF HELIUM PRESSURE REGULATOR
VILLAGE PRESSURE VS TIME
RUN NO 3, MARCH 15, 1960



VILLAGE PRESSURE VS TIME
RUN NO 4, APRIL 5, 1960




FIGURE 6

K&E 10X10 TO THE 1/8 INCH 359-11
KENTFLA TERNER CO. PAID 10/6/61

4C & 110 FAILURE ANALYSIS OF HELIUM PRESSURE REGULATORY
TUBE TEMPERATURE VS TIME
RUN NO 5, APRIL 5, 1960





FIGURE 7

4C EIID FAILURE ANALYSIS OF

RUN NO 5,
AND
TYPICAL PROGRAM



A

10 X 10 TO THE CM 359.14 LG
J. E. P. I. A. ENGINE CO.

GE HELIUM PRESSURE REGULATOR

D. S., APRIL 5, 1960

LOGGING CURVES

VACUUM CHAMBER PRESSURE
VS
TIME

WATER FLOW
VS
TIME

REGULATOR INLET PRESSURE
VS
TIME

ULLAGE PRESSURE
VS
TIME

80 90 100 110 120 130 140 150 160 170
TIME (SEC)

FIGURE B

B

TUBE HEATER SCHEMATIC




FIGURE 9

P H O T O I N D E X

FIGURE NUMBER

PHOTO NUMBER

PAGE NUMBER

10

52635A

15




FIGURE NO. 10