

AD-A032 915 ARMY ENGINEER WATERWAYS EXPERIMENT STATION VICKSBURG MISS F/G 1/5
CONDITION SURVEY, MCCONNELL AIR FORCE BASE, KANSAS.(U)
MAY 73 R D JACKSON

UNCLASSIFIED

WES-MP-S-73-29

NL

1 of 1
ADA032915



END

DATE
FILMED
1 - 77

ADA 032915




1
②
NW

MISCELLANEOUS PAPER S-73-29

CONDITION SURVEY, MCCONNELL AIR FORCE BASE, KANSAS

by

R. D. Jackson



May 1973

Sponsored by Office, Chief of Engineers, U. S. Army

Conducted by U. S. Army Engineer Waterways Experiment Station
Soils and Pavements Laboratory
Vicksburg, Mississippi

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED

**Destroy this report when no longer needed. Do not return
it to the originator.**

**The findings in this report are not to be construed as an official
Department of the Army position unless so designated
by other authorized documents.**



14

WES-MP-S-73-29

6
9 MISCELLANEOUS PAPER S-73-29 ✓
CONDITION SURVEY, MCCONNELL AIR FORCE BASE, KANSAS,

10 by R. D. Jackson

12 25p.



ACCOUNT FOR	White Section	<input checked="" type="checkbox"/>
AVC	Butt Section	<input type="checkbox"/>
ED		
DATE		
BY DISTRIBUTION/AVAILABILITY CODES		
Dist.	APPROV. BY	DATE
A		

11 May 1973

Sponsored by Office, Chief of Engineers, U. S. Army

Conducted by U. S. Army Engineer Waterways Experiment Station ✓
Soils and Pavements Laboratory
Vicksburg, Mississippi

ARMY-MRC VICKSBURG, MISS.

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED

038 100 B

Foreword

The study reported herein was conducted under the general supervision of the Engineering Design Criteria Branch, Soils and Pavements Laboratory, of the U. S. Army Engineer Waterways Experiment Station (WES), Vicksburg, Mississippi. Personnel involved in the condition survey were Messrs. R. D. Jackson, K. A. O'Connor, and S. R. Rowland, Jr., of the WES and Mr. R. A. Eaton of the U. S. Army Cold Regions Research and Engineering Laboratory (CRREL), Hanover, New Hampshire. The main portion of this report was prepared by Mr. Jackson under the general supervision of Messrs. J. P. Sale, R. G. Ahlvin, R. L. Hutchinson, and P. J. Vedros of the Soils and Pavements Laboratory. The section of this report concerning frost action was prepared by Mr. Eaton and by Mr. G. D. Gilman of CRREL.

COL Ernest D. Peixotto, CE, was Director of the WES during the conduct of the study and preparation of the report. Mr. F. R. Brown was Technical Director.

Contents

	<u>Page</u>
Foreword	iii
Conversion Factors, British to Metric Units of Measurement . . .	vii
Authority	1
Purpose and Scope	1
Pertinent Background Data	1
General description of airfield	1
Previous reports	2
History of Airfield Pavements	2
Design and construction history	2
Traffic history	3
Conditions of Pavement Surfaces	3
Pavement inspection procedure	3
Runways	4
Taxiways	4
Aprons	4
Frost Action	4
Objectives of inspection	4
Frost heave	5
Freezing indices	5
Groundwater	6
Low-temperature contraction cracking	6
Thaw weakening	7
Maintenance	8
Evaluation	9
Conclusions	9
Tables 1-4	
Plate 1	

Conversion Factors, British to Metric Units of Measurement

British units of measurement used in this report can be converted to metric units as follows:

<u>Multiply</u>	<u>By</u>	<u>To Obtain</u>
inches	2.54	centimeters
feet	0.3048	meters
miles (U. S. statute)	1.609344	kilometers
square inches	6.4516	square centimeters
pounds (mass)	0.45359237	kilograms
pounds (force) per square inch	0.6894757	newtons per square centimeter
Fahrenheit degrees	*	Celsius or Kelvin degrees

* To obtain Celsius (C) temperature readings from Fahrenheit (F) readings, use the following formula: $C = (5/9)(F - 32)$. To obtain Kelvin (K) readings, use: $K = (5/9)(F - 32) + 273.15$.

CONDITION SURVEY, McCONNELL AIR FORCE BASE, KANSAS

Authority

1. Authority for conducting condition surveys at selected airfields is contained in amendment to FY 1972 RDTE Funding Authorization (MFS-MC-5, 16 February 1972), subject: "Air Force Airfield Pavement Research Program," from the Office, Chief of Engineers, U. S. Army, Directorate of Military Construction, dated 18 February 1972.

Purpose and Scope

2. The purpose of this report is to present the results of a condition survey performed at McConnell Air Force Base (MAFB), Kansas, during 8-12 May 1972. The following three major areas of interest were considered in this condition survey:

- ① The structural condition of the primary airfield pavements.
- ② The condition of pavement repairs and the types of maintenance materials that have been used at this airfield.
- ③ Any detrimental effects of frost action to the pavement facilities.

3. This report is limited to a presentation of visual observations of the pavement conditions, discussion of these observations, and pertinent remarks with regard to the performance of the pavements. No physical tests of the pavements, foundations, or patching materials were performed during this survey.

Pertinent Background Data

General description of airfield

4. MAFB is located in Sedgwick County, Kansas, approximately 5 miles* southeast of Wichita, Kansas. A vicinity map is shown in plate 1.

* A table of factors for converting British units of measurement to metric units is presented on page vii.

5. In May 1972, the airfield facilities consisted of parallel NE-SW runways (18L-36R and 18R-36L), two parallel taxiways, an apron taxiway, connecting taxiways, three warm-up aprons, and a large parking apron. The 18L-36R runway was 300 ft wide and 12,000 ft long. The 18R-36L runway was 200 ft wide and 12,000 ft long. The taxiways were 75 ft wide and of various lengths. The parking apron was 775 ft wide and approximately 4,860 ft long. A layout of the airfield and a pavement plan indicating the type pavement on each facility are shown in plate 1.

Previous reports

6. Previous reports concerning the facilities at MAFB are listed below. Pertinent data were extracted from them for use in this condition survey report.

a. Condition survey reports:

- (1) Ohio River Division Laboratories, CE, "Report on Rigid Pavement Condition Survey, McConnell AFB, Kansas," September 1956, Cincinnati, Ohio.
- (2) Missouri River Division Laboratory, CE, "Rigid Pavement Condition Survey, McConnell AFB, Wichita, Kansas," 1959, Omaha, Nebraska.

b. Pavement evaluation reports.

- (1) U. S. Army Engineer District, Kansas City, CE, "Evaluation Report, McConnell Air Force Base, Kansas," Kansas City, Missouri.
- (2) _____, "Airfield Evaluation Report, McConnell Air Force Base, Wichita, Kansas," March 1959, Kansas City, Missouri.

History of Airfield Pavements

Design and construction history

7. Details of the construction history (since 1949) of the airfield pavements (extracted from the reports referenced in paragraph 6) are presented in table 1. Records of construction at the airfield prior to 1950 are incomplete; however, the previous reports indicate that the 10-in. portland cement concrete (PCC) pavements were constructed in 1943. Pavement thicknesses, descriptions, and other details are presented in table 2.

8. No record of the design criteria for the original pavements was available; however, the pavements constructed during 1943 were designed to support operations of the B-29 aircraft that were being produced at the Boeing plant. From the time of the construction and reconstruction in 1955, the airfield pavements have been designed to support a landing-gear loading of 100,000 lb supported on dual wheels spaced 37.5 in. center to center, with each wheel having a tire contact area of 267 sq in.

Traffic history

9. Since 1955, MAFB has been used primarily as a pilot training base. During the period 1955-58, the airfield received approximately 3,500 cycles* per month of B-47 traffic. During the next 5 yr (1958-63), there were approximately 2,800 cycles of B-47 traffic per month. Since July 1963, the airfield has been used primarily for fighter pilot training. The estimated number of monthly cycles for all aircraft since this time is 2,400. The heavier aircraft included in this number of cycles are B-52's, KC-135's, 707's, and 727's; however, the KC-135 is the only aircraft presently using the field to any great extent (120 cycles per month since July 1971). Traffic at the base is about equally divided between the two runways, and more than 50 percent of the take-offs and landings are from the north ends of the runways.

Conditions of Pavement Surfaces

Pavement inspection procedure

10. The following procedure was used in conducting the inspection of the rigid pavements. Representative features were selected for detailed inspection. The features were then inspected slab** by slab, and the defects were recorded. The locations of the individual pavement features, the inspection starting points, and the directions in which the pavements were inspected (shown by arrows) are indicated in plate 1.

* A cycle of operation is one landing and one takeoff.

** A slab is the smallest unit, containing no joints, of a given pavement feature.

The results of the rigid pavement survey for those features that were inspected in detail are presented in table 3. This table shows a quantitative breakdown of the various types of defects and a condition rating for each pavement feature inspected in detail. The procedures used for determining the condition rating of a pavement are given in Appendix III of Department of the Army Technical Manual TM 5-827-3, "Rigid Airfield Pavement Evaluation," dated September 1965.

Runways

11. The 18L-36R runway was in very good to excellent condition, with only limited major defects recorded. This runway contained many spalls that were a result of "D" cracking* at the corners and edges of the slabs. The 18R-36L runway was also in very good to excellent condition based on the percentage of slabs containing no major defects.

Taxiways

12. All the primary taxiways were in very good condition; however, each contained numerous spalls that were results of "D" cracking.

Aprons

13. The aprons surveyed contained numerous spalls but were considered to be in very good to excellent condition.

14. Those pavements not surveyed in detail were considered to be in good to excellent condition. However, there were a considerable number of spalls in these areas, and practically all of the slabs contained some degree of "D" cracking.

Frost Action

Objectives of inspection

15. One member of the team inspected the pavement facilities for

* "D" cracking is defined in Bulletin 47 of the Highway Research Board, "Salvaging Old Pavement by Resurfacing," as follows: "A form of disintegration characterized by the successive formation of a series of fine cracks at rather close intervals paralleling edges, joints, and cracks and usually curving across slab corners, the initial cracks forming very close to slab edge and additional cracks progressively developing, each a little farther from the edge than the preceding one. Ordinarily the cracks are filled with a calcareous deposit."

evidence of detrimental frost effects. The objectives of the inspection were to determine:

- a. Any adverse effects of frost heave to the pavements during the winter months.
- b. Any traffic-induced failures that might be related to thaw weakening of the subgrades or base courses.
- c. Any adverse effects of low-temperature contraction cracking to the flexible pavements.

Frost heave

16. Since the inspection was conducted during the period 8-11 May, which was approximately 3 months after the end of the 1971-72 thawing period, evidence of any adverse effects of differential frost heaving could be determined only by an inspection of the pavements for surface irregularities. All of the pavements, including the nontraffic areas, were inspected in this respect, but no evidence of marked differential frost heaving was observed. Personnel of the Base Civil Engineering Office reported that no undesirable pavement surface roughness had developed during the winter months.

Freezing indices

17. A design freezing index of 365 degree-days has been determined for MAFB. This value is based on temperature data from the Wichita, Kansas, Airport Weather Station and is the average of the three coldest winters in the past 30 years (1948-49, 1961-62, and 1962-63). In the design index determination, average monthly temperatures were used for months entirely within the freezing seasons and average daily temperatures were considered for the transition months at both ends of the freezing seasons.

18. Seasonal indices for Wichita since 1955, when B-47 aircraft began operations (approximately 3500 cycles per month), are tabulated below. These indices, which were determined entirely from average monthly temperatures, do not properly account for the below freezing portions of the two transition months and generally reflect somewhat lower numerical values than do indices which consider average daily temperatures for these two periods. The tabulated indices do, however, indicate the relative severity of winters during B-47 aircraft operations at MAFB.

<u>Freezing Season</u>	<u>Freezing Index degree-days</u>	<u>Freezing Season</u>	<u>Freezing Index degree-days</u>
1955-56	78	1964-65	25
1956-57	174	1965-66	115
1957-58	64	1966-67	0
1958-59	171	1967-68	0
1959-60	130	1968-69	99
1960-61	19	1969-70	146
1961-62	279	1970-71	189
1962-63	304	1971-72	155
1963-64	167		

19. The existing pavements at MAFB provide a maximum thickness of protection over the subgrade of 23 in., which is not sufficient to prevent subgrade frost penetration during a design year in excess of the depth allowable in accordance with limited subgrade frost-penetration design criteria. Most of the PCC pavements, which range from 13 to 17 in. in thickness, were constructed directly on the clay subgrade. Thus, frost penetration into this material occurs during most years, and a substantial amount of penetration probably occurs during the colder years. Therefore, pavement design and performance must be compared with the reduced subgrade strength design and evaluation criteria.

Groundwater

20. Personnel of the Base Civil Engineering Office reported that the groundwater table is located at a depth of approximately 8 ft during the fall and winter months.

Low-temperature contraction cracking

21. Although the winters in this vicinity are usually mild, the area is subject to frequent and abrupt temperature changes. While these changes generally prevent large freezing index accumulations, below zero readings are not uncommon. The extreme low temperature on record at the Wichita Weather Station is -22 F. Only the overruns and shoulders at MAFB are of flexible pavement construction (2-in. asphaltic concrete (AC)), and all of these areas had low-temperature contraction cracks. At the time of this survey, both overruns of the primary runway and the south overrun of runway 18L-36R had numerous longitudinal and transverse cracks. Cracking on the north overrun of runway 18L-36R was relatively minor. In most areas, the taxiway shoulders had transverse cracks

spaced at 6- to 8-ft intervals, with longitudinal cracks in the center.

Thaw weakening

22. The extent of thaw weakening of underlying materials could not be readily determined by inspection of pavements. Pavement failures usually are repaired or otherwise corrected as they occur and usually are not easily examined during a condition survey. At MAFB, the primary type of pavement distress noted was spalling, which was attributed to "D" cracking. Extensive repairs have been made to slab corners and longitudinal joints that have been affected by this type of distress (see paragraphs 11-14 and photos 1-3). Although "D" cracking cannot be related to thaw weakening, it is possible that some of the failures (such as corner breaking) were due to overloading during the thawing period. Under similar traffic conditions, distress due to overloading is accelerated during and following the thawing of underlying frost-susceptible materials. However, the absence of distress (other than low-temperature contraction cracking) on the shoulder pavements suggests that significant thaw weakening has not occurred at MAFB despite the presence of a frost-susceptible subgrade within the depth of the seasonal frost penetration.

23. Rigid pavements. The primary rigid pavement slab thicknesses are adequate for "normal" period operations of the present Air Force medium-load aircraft, except for a slight deficiency (1 in.) for traffic area A slabs (see plate 1). However, for frost condition operations under the same loadings, the traffic area A and B pavement slabs are from 3 to 5 in. deficient in thickness, while the area C pavements are still adequate (except for a portion of runway 18L-36R interior (feature R6C), which has 13-in.-thick slabs). The reduced subgrade strength design criteria specify, however, that, in areas where subgrade conditions are uniform and the design freezing index is less than 1000, a minimum base thickness of 4 in. must be used. Yet all of the rigid pavements at MAFB have been constructed directly on the subgrade, except for two taxiways (features T3A and T4A) and two aprons (features A1B and A2B), which have 6-in. sand bases. The field has not been subjected to B-52 traffic to any extent (see paragraph 9); and, as is indicated by

the capacities shown in table 4, operations of this aircraft at normal gross weights would significantly overload the pavements for either the normal or the frost-melting periods.

24. Flexible pavements. The 2-in. AC pavement of the overruns and shoulders is adequate for the loads imposed; however, the base course thicknesses (4 to 13 in.) are insufficient for either the limited subgrade frost-penetration design or reduced subgrade strength design. Despite the deficiency, however, no distress other than the low-temperature contraction cracking mentioned above was noted during this survey.

Maintenance

25. The pavements at MAFB require yearly maintenance to repair surface spalls that result from "D" cracking. The depth of the deteriorated pavement removed is usually about 2 in. near the interior of a slab tapering to a depth of approximately 6 to 8 in. at the edge of a slab. A slab is repaired using an epoxy cement and PCC to replace the deteriorated section. In most of the apron areas, the deteriorated pavement has been replaced with AC.

26. Maintenance costs at MAFB since FY 1957 are tabulated below:

<u>Fiscal Year</u>	<u>Contract Costs</u>	<u>In-House Expenditures</u>
1957	\$ 28,000	Not available
1958	44,700	Not available
1959	229,000	Not available
1960	227,000	Not available
1961	119,800	Not available
1962	166,700	Not available
1963	136,100	Not available
1964	None	\$ 82,200 (Estimated)
1965	None	68,700 (Estimated)
1966	175,000	70,800
1967	None	71,700
1968	None	104,595
1969	185,671	49,131
1970	345,780	52,955
1971	120,066	49,767
1972 (3 quarters)	61,927	46,874

27. Maintenance performed in addition to the repair of surface spalls has included replacing a considerable number of slabs, sealing joints, and slurry sealing the AC shoulder pavements.

Evaluation

28. A summary of the pavement evaluation is presented in table 4. Previously published pavement evaluations were updated to eliminate aircraft that are no longer in the Air Force inventory and to include aircraft that have been added to the inventory since the last pavement evaluation. The evaluation is based on the pavement thickness, flexural strength (PCC), base and subbase thickness and strength, strength of the subgrade (CBR or K value), and the structural condition of the pavement.

Conclusions

29. The following statements summarize the findings of this investigation:

- a. The primary pavements were in very good to excellent condition based on the percentage of slabs containing no major defects.
- b. Spalls caused by "D" cracking are a continuing maintenance problem.
- c. Repair of spalls on the runways is accomplished using epoxy cement and PCC. Apron repairs are usually completed using AC.
- d. Contraction cracks were noted in all AC pavements; however, the only AC pavements are shoulders and runway overruns, so the problem is not extensive.
- e. Frost action has not been a major factor in causing pavement defects.

Table 1

Airfield Construction History*

<u>Pavement Facility</u>	<u>Pavement</u>		<u>Construction Year(s)</u>
	<u>Thickness in.</u>	<u>Type</u>	
NE-SW (18L-36R) runway (150- by 2000-ft section of S end and 150- by 400-ft section of N end)	13 and 16	PCC	1950
NE-SW (18L-36R) runway (150- by 2000-ft section of S end)	15 and 17	PCC	1951
NE-SW (18L-36R) runway (reconstruction and widening to 300 ft)	15 and 17	PCC	1955
NE-SW (18R-36L) runway	15 and 17	PCC	1953
NW-SE (12-30) runway	17-15	PCC	1953
Taxiways 3 and 8	17	PCC	1951
North and south taxiways	17	PCC	1951
Parking apron	17	PCC	1951
Parking apron extension	17	PCC	1957
Parking apron (reconstruction)	17	PCC	1954-55
Taxiway 1	17	PCC	1955
Taxiway 2	17	PCC	1954
Hangar aprons	17	PCC	1953
Nose dock aprons	15	PCC	1955

* Since 1949.

Table 2
SUMMARY OF PHYSICAL PROPERTY DATA

FACILITY			OVERLAY PAVEMENT			PAVEMENT			BASE			SUBGRADE		GENERAL CONDITION OF AREA CONSIDERED
FACILITY NUMBER AND IDENTIFICATION	LENGTH FT	WIDTH FT	THICK. IN.	DESCRIPTION	FLEX. STR. PSI	THICK. IN.	DESCRIPTION	FLEX. STR. PSI	THICK. IN.	CLASSIFICATION	CBR OR K	CLASSIFICATION	CBR OR K	
Runway 18L-36R, SW end; 1st 500 ft R1A	500	300	17	Portland cement concrete	730	17	Portland cement concrete	730				CLAY (CL-OH) Frost group F3	75 K ₂₅	Excellent
Runway 18L-36R, SW end; 2nd 500 ft R1B	500	300	17	Portland cement concrete	730	17	Portland cement concrete	730				CLAY (CL-OH) Frost group F3	75 K ₂₅	Excellent
Runway 18L-36R Interior R1C	10,000	Varies	15	Portland cement concrete	730	15	Portland cement concrete	730				CLAY (CL-OH) Frost group F3	75 K ₂₅	Excellent to very good
Runway 18L-36R Interior R1C	500	150	16	Portland cement concrete	730	16	Portland cement concrete	730				CLAY (OH) Frost group F3	75 K ₂₅	Very good
Runway 18L-36R Interior R1C	2,000	50	16	Portland cement concrete	730	16	Portland cement concrete	730				CLAY (CL) Frost group F3	75 K ₂₅	Very good
Runway 18L-36R Interior R1C	2,000	100	13	Portland cement concrete	730	13	Portland cement concrete	730				CLAY (CL) Frost group F3	75 K ₂₅	Very good
Runway 18L-36R, NE end; 1st 500 ft R1A	500	Varies	17	Portland cement concrete	730	17	Portland cement concrete	730				CLAY (CL) Frost group F3	75 K ₂₅	Very good
Runway 18L-36R, NE end; 1st 500 ft R1A	400	150	16	Portland cement concrete	730	16	Portland cement concrete	730				CLAY (CL-OH) Frost group F3	75 K ₂₅	Very good
Runway 18L-36R, NE end; 2nd 500 ft R1B	500	300	17	Portland cement concrete	730	17	Portland cement concrete	730				CLAY (CL-OH) Frost group F3	75 K ₂₅	Good
Runway 12-30 R1C	8,000	200	17-15	Portland cement concrete	730	17-15	Portland cement concrete	730				CLAY (CL-OH) Frost group F3	75 K ₂₅	Good
Runway 18R-36L, SW end; 1st 500 ft R1A	500	200	17	Portland cement concrete	730	17	Portland cement concrete	730				CLAY (CL) Frost group F3	75 K ₂₅	
Runway 18R-36L, SW end; 2nd 500 ft R1B	500	200	17	Portland cement concrete	730	17	Portland cement concrete	730				CLAY (CL) Frost group F3	75 K ₂₅	
Runway 18R-36L Interior R1C	10,000	200	15	Portland cement concrete	730	15	Portland cement concrete	730				CLAY (CL-OH) Frost group F3	75 K ₂₅	
Runway 18R-36L, NE end; 1st 500 ft R1A	500	200	17	Portland cement concrete	730	17	Portland cement concrete	730				CLAY (CL-OH) Frost group F3	75 K ₂₅	
Runway 18R-36L, NE end; 2nd 500 ft R1B	500	200	17	Portland cement concrete	730	17	Portland cement concrete	730				CLAY (CL-OH) Frost group F3	75 K ₂₅	

(1 of 2 sheets)

REC FORM 1000
MAY 1955

COPY AVAILABLE TO DDC DOES NOT PERMIT FULLY LEGIBLE PRODUCTION

Table 2 (Continued)
SUMMARY OF PHYSICAL PROPERTY DATA

FACILITY			OVERLAY PAVEMENT			PAVEMENT			BASE			SUBGRADE		GENERAL CONDITION OF AREA CONSIDERED
FACILITY NUMBER AND IDENTIFICATION	LENGTH FT	WIDTH FT	THICK. IN.	DESCRIPTION	FLEX. STR. PSI	THICK. IN.	DESCRIPTION	FLEX. STR. PSI	THICK. IN.	CLASSIFICATION	CBR OR K	CLASSIFICATION	CBR OR K	
Roadway 1	5,140	75	10-17-10-15-17	Portland cement concrete	730	10-17-10-15-17	Portland cement concrete	730	6	Clay (CL-CH) Frost group F3	75 K _p 25	Clay (CL-CH) Frost group F3	75 K _p 25	Very good
Roadway 3	3,380	Varies	17	Portland cement concrete	730	17	Portland cement concrete	730	6	Sand	75 K _p 25	Clay (CL) Frost group F3	75 K _p 25	Very good
South taxiway and taxiway 8	6,720	Varies	17	Portland cement concrete	730	17	Portland cement concrete	730	6	Sand	75 K _p 25	Clay (CL) Frost group F3	75 K _p 25	Very good
Taxiway 5	5,365	75	17	Portland cement concrete	730	17	Portland cement concrete	730	6	Sand	75 K _p 25	Clay (CL-CH) Frost group F3	75 K _p 25	Excellent
North taxiway	1,550	Varies	17	Portland cement concrete	730	17	Portland cement concrete	730	6	Sand	75 K _p 25	Clay (CL) Frost group F3	75 K _p 25	Very good
Taxiway 2 (center lane)	5,090	Varies	17	Portland cement concrete	730	17	Portland cement concrete	730	6	Sand	75 K _p 25	Clay (CL) Frost group F3	75 K _p 25	
Taxiway 2 (outside lanes)	8,800	25	10-15	Portland cement concrete	730	10-15	Portland cement concrete	730	6	Sand	75 K _p 25	Clay (CL) Frost group F3	75 K _p 25	
Parking apron	4,335	775	17	Portland cement concrete	730	17	Portland cement concrete	730	6	Sand	75 K _p 25	Clay (CL-CH) Frost group F3	75 K _p 25	Excellent
South warm-up apron C	1,000	225	17	Portland cement concrete	730	17	Portland cement concrete	730	6	Sand	75 K _p 25	Clay (CL) Frost group F2	75 K _p 25	Very good
South warm-up apron B	440	290	17	Portland cement concrete	730	17	Portland cement concrete	730	6	Sand	75 K _p 25	Clay (CL-CH) Frost group F3	75 K _p 25	Excellent
North warm-up apron A	280	290	17	Portland cement concrete	730	17	Portland cement concrete	730	6	Sand	75 K _p 25	Clay (CL-CH) Frost group F3	75 K _p 25	Ex. Lent
Hangar apron	200	115	15	Portland cement concrete	730	15	Portland cement concrete	730	6	Sand	75 K _p 25	Clay (CL-CH) Frost group F3	75 K _p 25	Excellent
Hangar apron	225	190	15	Portland cement concrete	730	15	Portland cement concrete	730	6	Sand	75 K _p 25	Clay (CL-CH) Frost group F3	75 K _p 25	
Hangar apron	700	200	17	Portland cement concrete	730	17	Portland cement concrete	730	6	Sand	75 K _p 25	Clay (CL-CH) Frost group F3	75 K _p 25	

RES FORM 1000
MAR 1958

COPY AVAILABLE TO DDC DOES NOT PERMIT FULLY LEGIBLE PRODUCTION

Table 3 (Continued)

DATE: 9 May 1972		SUMMARY OF DATA - RIGID PAVEMENT CONDITION SURVEY													AIRFIELD: McConnell AFB, Kansas												
NO.	FEATURE DESIGNATION	SLAB SIZE FT	APPROX NO. OF SLABS	PAVE. THICK. IN.	NO. OF SLABS CONTAINING INDICATED DEFECTS													% OF SLABS NO MAJOR DEFECTS	CONDITION								
					I	-	\	Δ	*	K	w	S	J	↓	J	Φ	M			P	O	C	D				
RL2B	Runway 18R-36L, SW end; 2nd 500 ft	25x25	160	17	1							1				4								8	91.3	Excel- lent	
T1A	Taxiway 1	25x25	1995	10-17- 10-15- 17	14	15	7	21				12	1	14	29	168					5			77	10	95.8	Very good
T2A	Taxiway 3	25x25	387	17	12	4	3	5				8		22	17	43					1			60		93.5	Very good
T3A	South taxiway and taxiway 8	25x25	1114	17	25	2	7	21				22		10	51	155							63		77.9	Very good	
T4A	Taxiway 5	25x25	711	17	2		1	3				6		14	49	43							21		82.4	Excel- lent	
T5A	North taxiway	25x25	188	17	7	1		8				4		4	22	28							10	1	81.4	Very good	
A1B	Parking apron	25x25	5549	17	32	8	16	15				115	5	68	29	407							201	384	2	79.8	Excel- lent
A2B	South warm-up apron C	25x25	361	17	2	7	5	4				9		2	1	39							36		73.1	Very good	
A3B	South warm-up apron B	25x25	216		1			1						1	6	35							28	2	72.7	Excel- lent	
A4B	North warm-up apron A	25x25	145	17	1	1						1		13	15								6	1	76.6	Excel- lent	

REMARKS:

- LEGEND:
- I LONGITUDINAL CRACK
 - TRANSVERSE CRACK
 - \ DIAGONAL CRACK
 - Δ CORNER BREAK
 - * SHATTERED SLAB
 - K KEYED JOINT FAILURE
 - w SHRINKAGE CRACK
 - S SCALING
 - J SPALL ON TRANSVERSE JOINT
 - ↓ SPALL ON LONGITUDINAL JOINT
 - J CORNER SPALL
 - Φ SETTLEMENT
 - M MAP CRACKING
 - P PUMPING JOINT
 - O POP-OUT
 - C UNCONTROLLED CONTRACTION CRACK
 - D "D" CRACKING

COPY AVAILABLE TO DDC DOES NOT PERMIT FULLY LEGIBLE PRODUCTION

Table 4
SUMMARY OF PAVEMENT EVALUATION

NAME OF AIRFIELD: McConnell AFB		LOAD-CARRYING CAPACITY IN LB OF GROSS PLANE LOAD FOR INDICATED LANDING GEAR TYPES AND CONFIGURATIONS										REMARKS	
DATE OF EVALUATION MONTH: May		TRICYCLE ARRANGEMENT											
NO.	FEATURE DESIGNATION	PAVEMENT OPERATIONAL USE	TRICYCLE ARRANGEMENT										
			1	2	3	4	5	6	7	8	9	10	
			SINGLE 100-PSI TIRES CONTACT AREA	SINGLE 100-PSI TIRES CONTACT AREA	SINGLE 241-SQ-IN. CONTACT AREA	TR 2 IN. C-C 28-SQ-IN. CONTACT AREA EACH TIRE	SINGLE TANDEM 400-SQ-IN. CONTACT AREA	TR 2 IN. C-C 28-SQ-IN. CONTACT AREA EACH TIRE	TR 4 IN. C-C 28-SQ-IN. CONTACT AREA EACH TIRE	TR 4 IN. C-C 28-SQ-IN. CONTACT AREA EACH TIRE	TR 4 IN. C-C 28-SQ-IN. CONTACT AREA EACH TIRE	C-S-A GEAR CONFIGURATION	TWIN TWIN SPEC 3742-J 287-SQ-IN. CONTACT AREA EACH TIRE
RIA	Runway 18L-36R, SW end; 1st 500 ft	Capacity Frost capacity	155,000+ 140,000	85,000+ 85,000+	155,000+ 155,000	220,000 185,000	200,000+ 200,000+	200,000 200,000	230,000+ 230,000	330,000 300,000	800,000+ 800,000+	800,000+ 800,000+	295,000 250,000
R2B	Runway 18L-36R, SW end; 2nd 500 ft	Capacity Frost capacity	155,000+ 140,000	85,000+ 85,000+	155,000+ 155,000+	220,000 185,000	200,000+ 200,000+	240,000 200,000	230,000+ 230,000+	350,000+ 300,000	800,000+ 800,000+	800,000+ 800,000+	310,000 250,000
R3C	Runway 18L-36R interior (15- in. FCC)	Capacity Frost capacity	155,000+ 150,000	85,000+ 85,000+	155,000+ 155,000+	220,000+ 200,000	200,000+ 200,000+	270,000 220,000	230,000+ 230,000+	380,000+ 340,000	800,000+ 800,000+	800,000+ 800,000+	350,000 280,000
R4C	Runway 18L-36R interior (16- in. FCC)	Capacity Frost capacity	155,000+ 155,000+	85,000+ 85,000+	155,000+ 155,000	220,000+ 220,000	200,000+ 200,000+	290,000 245,000	230,000+ 230,000+	380,000+ 370,000	800,000+ 800,000+	800,000+ 800,000+	350,000 310,000
R5C	Runway 18L-36R interior (13- in. FCC)	Capacity Frost capacity	140,000 120,000	85,000+ 85,000+	155,000+ 155,000+	195,000 165,000	200,000+ 200,000+	220,000 180,000	230,000+ 225,000	370,000 285,000	800,000+ 800,000+	800,000+ 800,000+	290,000 230,000
R6A	Runway 18L-36R, NE end; 1st 500 ft (17-in. FCC)	Capacity Frost capacity	155,000+ 140,000	85,000+ 85,000+	155,000+ 145,000	220,000 185,000	200,000+ 200,000+	200,000 170,000	230,000+ 210,000	330,000 295,000	800,000+ 740,000	800,000+ 740,000	295,000 235,000
R7A	Runway 18L-36R, NE end; 1st 500 ft (16-in. FCC)	Capacity Frost capacity	145,000 130,000	85,000+ 85,000+	155,000 130,000	200,000 170,000	200,000+ 200,000	185,000 155,000	230,000 190,000	300,000 235,000	800,000+ 690,000	800,000+ 690,000	270,000 (a)
R10C	Runway 18L-36R, SW end; 2nd 500 ft	Capacity Frost capacity	155,000+ 140,000	85,000+ 85,000+	155,000+ 155,000+	220,000 185,000	200,000+ 200,000+	240,000 200,000	230,000+ 230,000+	380,000+ 300,000	800,000+ 800,000+	800,000+ 800,000+	310,000 250,000
R7C	Runway 12-30	Capacity Frost capacity	155,000+ 140,000	85,000+ 85,000+	155,000+ 155,000+	220,000+ 200,000	200,000+ 200,000+	270,000 220,000	230,000+ 230,000+	380,000+ 340,000	800,000+ 800,000+	800,000+ 800,000+	350,000 280,000
R11A	Runway 18R-36L, SW end; 1st 500 ft	Capacity Frost capacity	155,000+ 140,000	85,000+ 85,000+	155,000+ 155,000+	220,000 185,000	200,000+ 200,000+	200,000 180,000	230,000+ 230,000+	330,000 300,000	800,000+ 800,000+	800,000+ 800,000+	295,000 250,000

Note: + sign denotes allowable gross loading greater than maximum gross weight of any existing aircraft having indicated gear configuration.
(a) denotes allowable gross loading less than minimum gross weight of any existing aircraft having indicated gear configuration.

COPY AVAILABLE TO DDC DOES NOT PERMIT FULLY LEGIBLE PRODUCTION

Table 4 (Continued)
SUMMARY OF PAVEMENT EVALUATION

NAME OF AIRFIELD: McConnell AFB		LOAD-CARRYING CAPACITY IN LB OF GROSS PLANE LOAD FOR INDICATED LANDING GEAR TYPES AND CONFIGURATIONS										REMARKS	
DATE OF EVALUATION MONTH: May YR: 1972		TRICYCLE ARRANGEMENT											
NO.	FEATURE DESIGNATION	PAVEMENT OPERATIONAL USE	TRICYCLE ARRANGEMENT										
			1 SINGLE 100-PSI TIRE PRESSURE	2 SINGLE 100-SQ-IN. CONTACT AREA	3 SINGLE 241-SQ-IN. CONTACT AREA	4 TW 28-IN. C-C 228-SQ-IN. CONTACT AREA EACH TIRE	5 SINGLE TANDEM 80-IN. SPACING 400-SQ-IN. CONTACT AREA	6 TW 37-IN. C-C 287-SQ-IN. CONTACT AREA EACH TIRE	7 TW 44-IN. C-C 630-SQ-IN. CONTACT AREA EACH TIRE	8 TWIN TANDEM 32 IN. x 40 IN. 208-SQ-IN. CONTACT AREA EACH TIRE	9 C-3A GEAR CONFIGURATION	10 TWIN TWIN SPCG 37.42 37 287-SQ-IN. CONTACT AREA EACH TIRE	
R12B	Runway 18R-36L, SW end; 2nd 500 ft	Capacity Frost capacity	155,000+ 140,000	85,000+ 85,000+	155,000+ 155,000+	220,000 185,000	200,000+ 200,000+	240,000 200,000	230,000+ 230,000+	380,000+ 300,000	800,000+ 800,000+	310,000 250,000	
R13C	Runway 18R-36L Interior	Capacity Frost capacity	155,000+ 150,000	85,000+ 85,000+	155,000+ 155,000+	220,000+ 200,000	200,000+ 200,000+	270,000 220,000	230,000+ 230,000+	380,000+ 340,000	800,000+ 800,000+	350,000 280,000	
R14A	Runway 18R-36L NE end; 2nd 500 ft	Capacity Frost capacity	155,000+ 140,000	85,000+ 85,000+	155,000+ 145,000	220,000 185,000	200,000+ 200,000+	200,000 170,000	230,000+ 210,000	330,000 255,000	800,000+ 740,000	295,000 235,000	
R15B	Runway 18R-36L NE end; 2nd 500 ft	Capacity Frost capacity	155,000+ 140,000	85,000+ 85,000+	155,000+ 155,000+	220,000 185,000	200,000+ 200,000+	240,000 200,000	230,000+ 230,000+	380,000+ 300,000	800,000+ 800,000+	310,000 250,000	
T1A	Taxiway 1 15-in. PCC	Capacity Frost capacity	155,000+ 140,000	85,000+ 85,000+	140,000 120,000	220,000 185,000	200,000+ 200,000+	200,000 170,000	230,000+ 210,000	330,000 255,000	800,000+ 740,000	295,000 235,000	
T1A	Taxiway 1 17-in. PCC	Capacity Frost capacity	155,000+ 150,000	85,000+ 85,000+	155,000+ 145,000	220,000+ 200,000	200,000+ 200,000+	270,000 220,000	230,000+ 230,000+	380,000+ 340,000	800,000+ 800,000+	350,000 280,000	
T2A	Taxiway 3	Capacity Frost capacity	155,000+ 140,000	85,000+ 85,000+	155,000+ 145,000	220,000 185,000	200,000+ 200,000+	200,000 170,000	230,000+ 210,000	330,000 255,000	800,000+ 740,000	295,000 235,000	
T3A	South taxiway and taxiway 8	Capacity Frost capacity	155,000+ 155,000+	85,000+ 85,000+	155,000+ 155,000+	220,000 195,000	200,000+ 200,000+	200,000 200,000	230,000+ 230,000+	330,000 330,000	800,000+ 800,000+	295,000 270,000	
T4A	Taxiway 5	Capacity Frost capacity	155,000+ 155,000+	85,000+ 85,000+	155,000+ 155,000+	220,000 195,000	200,000+ 200,000+	200,000 200,000	230,000+ 230,000+	330,000 330,000	800,000+ 800,000+	295,000 270,000	
T5A	North taxiway	Capacity Frost capacity	155,000+ 140,000	85,000+ 85,000+	155,000+ 145,000	220,000 185,000	200,000+ 200,000+	200,000 170,000	230,000+ 210,000	330,000 255,000	800,000+ 740,000	295,000 235,000	

COPY AVAILABLE TO DDC DOES NOT PERMIT FULLY LEGIBLE PRODUCTION

Table 4 (Continued)
SUMMARY OF PAVEMENT EVALUATION


NAME OF AIRFIELD: McConnell AFB		LOAD-CARRYING CAPACITY IN LB OF GROSS PLANE LOAD FOR INDICATED LANDING GEAR TYPES AND CONFIGURATIONS										REMARKS
DATE OF EVALUATION: MONTH: May YR: 1972		TRICYCLE ARRANGEMENT										
NO.	FEATURE DESIGNATION	PAVEMENT OPERATIONAL USE	TRICYCLE ARRANGEMENT									
			1	2	3	4	5	6	7	8	9	10
			SINGLE 100-PSI TIME PRESSURE	SINGLE 100-PSI CONTACT AREA	SINGLE 84-PSI CONTACT AREA	TW 28-IN. C-C 226-PSI IN. CONTACT AREA EACH TIRE	SINGLE TANDEM 60-IN. SPACING 400-PSI IN. CONTACT AREA	TW 37-IN. C-C 287-PSI IN. CONTACT AREA EACH TIRE	TW 44-IN. C-C 430-PSI IN. CONTACT AREA EACH TIRE	TW TANDEM 174-PSI IN. CONTACT AREA EACH TIRE	TW TANDEM 174-PSI IN. CONTACT AREA EACH TIRE	C-14 GEAR CONFIGURATION
A1B	Parking apron	Capacity Frost capacity	155,000+ 155,000+	85,000+ 85,000+	155,000+ 155,000+	195,000 195,000	200,000+ 200,000+	240,000 220,000	230,000+ 230,000+	380,000+ 350,000	800,000+ 800,000+	310,000 270,000
A2B	South warm-up apron C	Capacity Frost capacity	155,000+ 155,000+	85,000+ 85,000+	155,000+ 155,000+	195,000 195,000	200,000+ 200,000+	240,000 220,000	230,000+ 230,000+	380,000+ 350,000	800,000+ 800,000+	310,000 270,000
A3B	South warm-up apron B	Capacity Frost capacity	155,000+ 140,000	85,000+ 85,000+	155,000+ 155,000+	185,000 185,000	200,000+ 200,000+	240,000 200,000	230,000+ 230,000+	380,000+ 300,000	800,000+ 800,000+	310,000 290,000
A4B	North warm-up apron A	Capacity Frost capacity	155,000+ 140,000	85,000+ 85,000+	155,000+ 155,000+	185,000 185,000	200,000+ 200,000+	240,000 200,000	230,000+ 230,000+	380,000+ 300,000	800,000+ 800,000+	310,000 290,000
A5B	Hangar apron	Capacity Frost capacity	130,000 115,000	85,000+ 85,000+	155,000+ 140,000	180,000 150,000	200,000+ 200,000+	200,000 165,000	230,000+ 200,000	320,000 255,000	800,000+ 750,000	260,000 (a)
A6B	Hangar apron	Capacity Frost capacity	130,000 115,000	85,000+ 85,000+	155,000+ 140,000	180,000 150,000	200,000+ 200,000+	200,000 165,000	230,000+ 200,000	320,000 255,000	800,000+ 730,000	260,000 (a)
A7B	Hangar apron	Capacity Frost capacity	155,000+ 140,000	85,000+ 85,000+	155,000+ 155,000+	220,000 185,000	200,000+ 200,000+	240,000 200,000	230,000+ 230,000+	380,000+ 300,000	800,000+ 800,000+	310,000 290,000

(3 of 3 sheets)

RES FORM NO. 999
JUNE 1972

EDITION OF AUG 1966 IS OBSOLETE.

COPY AVAILABLE TO DDC DOES NOT PERMIT FULLY LEGIBLE PRODUCTION



HANGAR APRONS



PARKING APRON

SERVICE APRON

NORTH WARM-UP APRON A

TO CESSNA

LEGEND

- $\frac{R2X}{2" AC}$ ← FEATURE DESIGNATION (SEE NOTE 1)
- ← SURFACE PAVEMENT THICKNESS AND TYPE

TYPE OF FEATURE

- R - RUNWAY
- T - TAXIWAY
- A - APRON

TYPE TRAFFIC AREA (SEE NOTE 2)

- A - A TYPE TRAFFIC
- B - B TYPE TRAFFIC
- C - C TYPE TRAFFIC
- X - NO TRAFFIC TYPE ASSIGNED


- AC - ASPHALTIC CONCRETE
- PCC - PORTLAND CEMENT CONCRETE
- DBST - DOUBLE BITUMINOUS SURFACE TREATMENT
- DIRECTION OF SURVEY


- PORTLAND CEMENT CONCRETE
- BLAST PAVEMENT (AC - NON TRAFFIC)

NOTES: 1. FEATURE DESIGNATION DENOTES TYPE OF FEATURE, NUMBER OF FEATURE FOR GIVEN TYPE, AND TYPE TRAFFIC AREA.
 2. TRAFFIC AREA DESIGNATIONS ARE BASED ON HEAVY-LOAD CRITERIA.



BOEING AIRPLANE CO

SCALE IN FEET





VICINITY MAP
SCALE IN MILES



2