

AD-A032 919


ARMY ENGINEER WATERWAYS EXPERIMENT STATION VICKSBURG MISS F/G 1/5  
CONDITION SURVEY, PEASE AIR FORCE BASE, NEW HAMPSHIRE.(U)  
MAY 73 R D JACKSON

UNCLASSIFIED

WES-MP-S-73-34

NL


1 of 1  
ADA032919



END

DATE  
FILMED  
1 - 77

ADA U32919



1  
D  
NW


MISCELLANEOUS PAPER S-73-34

# CONDITION SURVEY, PEASE AIR FORCE BASE, NEW HAMPSHIRE

by

R. D. Jackson

D.D.C.  
DEC 3 1973  
RECEIVED



May 1973

Sponsored by Office, Chief of Engineers, U. S. Army

Conducted by U. S. Army Engineer Waterways Experiment Station  
Soils and Pavements Laboratory  
Vicksburg, Mississippi

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED

**Destroy this report when no longer needed. Do not return  
it to the originator.**

**The findings in this report are not to be construed as an official  
Department of the Army position unless so designated  
by other authorized documents.**



9 MISCELLANEOUS PAPER S-73-34 ✓

6  
CONDITION SURVEY, PEASE AIR FORCE  
BASE, NEW HAMPSHIRE.

by

10 R. D./Jackson

14 WES-MP-S-73-34



12 35p.

11 May 1973

ADDITIONAL		
WES	✓	
DIS		
ORIGINATOR		
DATE		
BY	DISTRIBUTION/AVAILABILITY STATE	
DIS	APP	STATION SYMBOL
A		

Sponsored by Office, Chief of Engineers, U. S. Army

Conducted by U. S. Army Engineer Waterways Experiment Station ✓  
Soils and Pavements Laboratory  
Vicksburg, Mississippi

ARMY-MRC VICKSBURG, MISS

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED

038100 AB

## Foreword

The study reported herein was conducted under the general supervision of the Engineering Design Criteria Branch, Soils and Pavements Laboratory, of the U. S. Army Engineer Waterways Experiment Station (WES), Vicksburg, Mississippi. Personnel involved in the condition survey were Messrs. R. D. Jackson, P. S. McCaffrey, Jr., and W. J. McRay of the WES and Messrs. H. H. Baker and J. Razza of the U. S. Army Engineer Division, New England (NED), Waltham, Massachusetts. The main portion of this report was prepared by Mr. Jackson under the general supervision of Messrs. J. P. Sale, R. G. Ahlvin, R. L. Hutchinson, and P. J. Vedros of the Soils and Pavements Laboratory. That portion of the study pertaining to frost action was carried out by the U. S. Army Cold Regions Research and Engineering Laboratory (CRREL), Hanover, New Hampshire, with the assistance of the Foundations and Materials Branch, NED. The section of this report concerning frost action was prepared by Mr. Baker and by Mr. G. D. Gilman of CRREL.

COL Ernest D. Peixotto, CE, was Director of the WES during the conduct of the study and preparation of the report. Mr. F. R. Brown was Technical Director.

Contents

	<u>Page</u>
Foreword . . . . .	iii
Conversion Factors, British to Metric Units of Measurement . . . .	vii
Authority . . . . .	1
Purpose and Scope . . . . .	1
Pertinent Background Data . . . . .	1
General description of airfield . . . . .	1
Previous reports . . . . .	2
History of Airfield Pavements . . . . .	3
Design and construction history . . . . .	3
Traffic history . . . . .	3
Conditions of Pavement Surfaces . . . . .	3
Pavement inspection procedure . . . . .	3
Runway . . . . .	4
Taxiways . . . . .	5
Aprons . . . . .	5
Frost Action . . . . .	6
Objectives of inspection . . . . .	6
Frost heave . . . . .	6
Freezing indices . . . . .	6
Thaw weakening . . . . .	8
Maintenance . . . . .	9
Evaluation . . . . .	10
Conclusions . . . . .	10
Tables 1-4	
Photos 1-11	
Plates 1 and 2	

Conversion Factors, British to Metric Units of Measurement

British units of measurement used in this report can be converted to metric units as follows:

<u>Multiply</u>	<u>By</u>	<u>To Obtain</u>
inches	2.54	centimeters
feet	0.3048	meters
miles (U. S. statute)	1.609344	kilometers
square inches	6.4516	square centimeters
pounds	0.45359237	kilograms
pounds (force) per square inch	0.6894757	newtons per square centimeter

CONDITION SURVEY, PEASE AIR FORCE BASE, NEW HAMPSHIRE

Authority

1. Authority for conducting condition surveys at selected airfields is contained in amendment to FY 1972 RDTE Funding Authorization (MFS-MC-5, 16 February 1972), subject: "Air Force Airfield Pavement Research Program," from the Office, Chief of Engineers, U. S. Army, Directorate of Military Construction, dated 18 February 1972.

Purpose and Scope

↓  
2. The purpose of this report is to present the results of a condition survey performed at Pease Air Force Base (PAFB), New Hampshire, during 14-18 August 1972. The inspection for effects of frost action was performed on 1 June 1972. The following three major areas of interest were considered in this condition survey:

- ↳ (1) The structural condition of the primary airfield pavements.
- ↳ (2) The condition of pavement repairs and the types of maintenance materials that have been used at this airfield.
- ↳ (3) Any detrimental effects of frost action to the pavement facilities.

↖  
3. This report is limited to a presentation of visual observations of the pavement conditions, discussion of these observations, and pertinent remarks with regard to the performance of the pavements. No physical tests of the pavements, foundations, or patching materials were performed during this survey.

Pertinent Background Data

General description of airfield

4. PAFB is located in Rockingham County, New Hampshire,

approximately 2 miles\* west of the city of Portsmouth, New Hampshire. A vicinity map is shown in plates 1 and 2.

5. In August 1972, the airfield facilities consisted of a NW-SE (16-34) runway, a parallel taxiway, parking aprons A and B, two warm-up aprons, taxiways connecting the runway to the parallel taxiway, a calibration hardstand, a taxiway through apron B, three maintenance access aprons, and two DC aprons. The NW-SE runway was 11,320 ft long and 300 ft wide; parking apron A was 8,745 ft long and 935 ft wide; parking apron B was 2,025 ft long and 925 ft wide; the parallel taxiway was 12,915 ft long and 75 ft wide; the two warm-up aprons were irregular in shape; the taxiways connecting the runway to the parallel taxiway were 900 ft long and 75 ft wide; the calibration hardstand was 137.5 ft in diameter; the taxiway through apron B was 2,025 ft long and 75 ft wide; and the maintenance access and DC aprons were of various sizes. A lay-out of the airfield is shown in plate 1. A pavement plan indicating the type pavement on each facility is shown in plate 2.

Previous reports

6. Previous reports concerning the airfield pavements at PAFB are listed below. Pertinent data were extracted from them for use in this condition survey report.

7. Condition survey reports:

- a. Ohio River Division Laboratories, CE, "Condition Survey Report, Pease Air Force Base, New Hampshire," February 1962, Cincinnati, Ohio.
- b. \_\_\_\_\_, "Condition Survey Report, Pease Air Force Base, New Hampshire," January 1964, Cincinnati, Ohio.
- c. U. S. Army Engineer Waterways Experiment Station, CE, "Pavement Condition Survey Report, Pease Air Force Base, Portsmouth, New Hampshire," April 1967, Vicksburg, Mississippi.

8. Pavement evaluation report: U. S. Army Engineer Division, New England, CE, "Airfield Evaluation Report, Pease Air Force Base, Portsmouth, New Hampshire," May 1959, Waltham, Massachusetts.

---

\* A table of factors for converting British units of measurement to metric units is presented on page vii.

## History of Airfield Pavements

### Design and construction history

9. Details of the design and construction history of the airfield pavements are presented in table 1. Pavement thicknesses, descriptions, and other details are presented in table 2.

### Traffic history

10. A detailed traffic record was not available; however, based on the incomplete records for the period April 1957-June 1970, it is reasonable to assume that the airfield has received at least the following number of cycles\* per type of aircraft: B-47's, 38,114 cycles; B-52's, 1,860 cycles; KC-97's, 18,165 cycles; KC-135's, 5,569 cycles; heavy cargo aircraft, 3,787 cycles; and all other aircraft, 31,018 cycles. In addition to this traffic, a portion of the airfield has been subjected to a number of alert taxiing movements. These movements consisted of taxiing from parking apron A to the taxiway through this apron, along taxiway A to the end of the runway, and then returning to apron A by the same route. The number of alert operations conducted using this pattern were as follows: B-47's, 97 movements; KC-97's, 307 movements; B-52's, 219 movements; and KC-135's, 645 movements. Gross aircraft loadings for the taxiing movements were as follows: B-47's, 190,000 lb; KC-97's, 175,000 lb; B-52's, 455,000 lb; and KC-135's, 290,000 lb. Approximately 75 percent of the takeoffs are from the SE end of the runway.

## Conditions of Pavement Surfaces

### Pavement inspection procedure

11. The following procedure was used in conducting the inspection of the rigid pavements. Representative features were selected for detailed inspection. The features were then inspected slab\*\* by slab, and

---

\* A cycle of operation is one landing and one takeoff.

\*\* A slab is the smallest unit, containing no joints, of a given pavement feature.

the defects were recorded. The locations of the individual pavement features, the inspection starting points, and the directions in which the pavements were inspected (shown by arrows) are indicated in plate 1. The results of the rigid pavement survey for those features that were inspected in detail are presented in table 3. This table shows a quantitative breakdown of the various types of defects and a condition rating for each pavement feature inspected in detail. The procedures used for determining the condition rating of a pavement are given in Appendix III of Department of the Army Technical Manual TM 5-827-3, "Rigid Airfield Pavement Evaluation," dated September 1965.

#### Runway

12. The NW end of the runway (features R1A and R2B) was structurally in very good condition based on the percentage of slabs containing no major defects. A total of 26 major defects were noted in feature R1A, all of which were longitudinal cracks. Of the 26 defects, 12 were in the two outer lanes on each side, and the other 14 were about equally divided among the other 8 lanes. Feature R2B contained 46 major defects, 45 longitudinal cracks and 1 transverse crack. Twenty-eight of the defects were located in the two outer lanes on each side; the other 18 were about equally divided among the other eight lanes. The asphaltic concrete (AC) interior portion of the runway (feature R3C) between the 1000-ft portland cement concrete (PCC) ends was in only fair condition because of longitudinal cracking (photos 1 and 2) and slight rutting. (This feature should now be in good condition, since a 3/4-in. friction overlay has been applied.) The SE end of the runway (features R5A and R4B) was in a poor to failed condition based on the number of slabs containing major defects. These two features contained a total of 332 major defects, of which 209 were located in the two outer lanes on each side. Twenty-seven slabs are scheduled for replacement in these features. Photo 3 shows the condition of the PCC pavement at the junction of the AC pavement at the SE end of the runway. The general conditions of the PCC pavements in features R5A and R4B (SE end of the runway) are shown in photos 4 and 5.

### Taxiways

13. Taxiways A, B, C, and D were in fair to good condition, even though there was some longitudinal cracking and slight rutting in the AC comprising them. The taxiway through parking apron A (feature T1A) was in fair condition based on the number of slabs containing major defects. This feature contained 521 major defects, of which 515 were longitudinal cracks. These longitudinal cracks appeared to be the result of channeled traffic, since 60 percent of them were in the center lane. The taxiway through parking apron B (feature T2A) was in poor condition. This feature contained 123 major defects, of which approximately 50 percent were in the center lane.

### Aprons

14. The north warm-up apron (feature A1B) was in very good condition based on the percentage of slabs containing no major defects. Jet blast had caused scaling on approximately 10 percent of the slabs. Photo 6 shows some of the scaling in feature A1B. The south warm-up apron (feature A2B) was in fair condition. There were 110 major defects in this feature, of which 100 were longitudinal cracks. Most of the longitudinal cracks were of the type shown in photo 7. They appeared to be caused by the manner in which the pavement had been placed rather than by overloading. Scaling was also prevalent in this feature, with approximately 20 percent of the slabs containing this defect (photo 8). Parking aprons A and B (features A3B and A4B) were in very good condition based on the percentages of slabs containing no major defects. Approximately 10 percent of the slabs in these features contained longitudinal cracks, which were the predominant defect. A large percentage of these longitudinal cracks were of the type shown in photo 9, and they did not appear to be load related. Considerable expansion of these aprons has resulted in upheaval of the shoulder pavements (photo 10) and the removal of the PCC pavement around embedded features, such as the fueling hydrants and drainage structures (photo 11).

15. Those pavement features not specifically mentioned above were in very good to excellent structural condition.

## Frost Action

### Objectives of inspection

16. The airfield pavements at PAFB were inspected for evidence of detrimental frost effects on 1 June 1972 by a team from the New England Division. One member of this team also participated in the WES condition survey of 14-18 August 1972. The objectives of the frost effects inspections were to determine:

- a. Any adverse effects of frost heave to the pavements during the winter months.
- b. Any traffic-induced pavement failures that might be related to thaw weakening of the subgrades or base courses.

### Frost heave

17. The airfield pavements were examined for surface irregularities indicative of differential frost heaving. Both of the frost action inspections were conducted long after the spring thaw at times when the effects of nonuniform frost heave would not be apparent except in severe cases. Inquiries were made of the base personnel regarding the development of undesirable surface roughness during the winter months.

18. The rigid pavement ends of the runway were free of detectable roughness of the type associated with frost heaving. The flexible pavement runway interior, which was smooth longitudinally, was noticeably uneven transversely as a result of shallow rutting. Except for certain of the shoulder pavements, the remaining airfield pavement features were found to be smooth. Base personnel reported that frost heaving had occurred in the west shoulder of taxiway D near sta 150+00. Although the heave had subsided completely by the time of the inspections, a crack pattern consistent with frost heaving was evident. It is significant that the area where the heave occurred was the only one in which groundwater was located within 5 ft of the pavement surface. The upheaval of the apron shoulders discussed in paragraph 14 was not considered to be frost related.

### Freezing indices

19. A freezing index of 1000 degree-days was used for the design

of the airfield pavements. The basis for this index is not known, but it was probably based on the coldest winter of the preceding 10 years as indicated by temperature data from the Portsmouth, New Hampshire, Weather Station. On the basis of temperature records up to and including the 1971-72 season, a design freezing index of 1114 degree-days is representative of the coldest season in the past ten. Seasonal freezing indices since the 1957-58 winter are tabulated below:

<u>Freezing Season</u>	<u>Freezing Index degree-days</u>	<u>Freezing Season</u>	<u>Freezing Index degree-days</u>
1958-59	958	1965-66	583
1959-60	418	1966-67	826
1960-61	996	1967-68	973
1961-62	782	1968-69	664
1962-63	877	1969-70	791
1963-64	888	1970-71	1003
1964-65	816	1971-72	569

These tabulated indices were determined solely on the basis of average monthly temperatures. Indices thus determined are generally somewhat lower than those computed with consideration given to average daily temperatures for the transition months at both ends of the freezing season. For example, the index for 1970-71, which was determined on the basis of average monthly temperatures, is 1003 degree-days, whereas the design index computation, which was determined with consideration to the transition months, is 1114 degree-days. The tabulated seasonal indices, however, do indicate the relative severity of winters during the 1958-72 period.

20. Since the airfield pavements at this base were constructed, the experienced freezing index has been near design magnitude (above +900 degree-days) on four occasions. In view of this fact, the general absence of evidence of differential frost heaving is significant. For the design index, a combined pavement and base thickness of about 65 in. would be required for the prevention of subgrade freezing, and combined thicknesses of 45 to 48 in. would be needed to meet current criteria for limited subgrade frost penetration design. Since all of the primary pavements at this base meet the latter criteria, actual subgrade frost

penetrations of from 8 to 12 in. are presumed to have occurred during the colder winters. In view of the low frost susceptibility of the subgrade soils and the fact that groundwater levels generally occur more than 20 ft below the pavement surfaces, little or no frost heaving would be expected. The results of this survey bear this conclusion out. The only known instance of frost heaving at PAFB has occurred in a non-traffic feature (with only a 12-in. combined pavement thickness) in the only area of shallow groundwater depth. It is significant that the adjacent taxiway pavement (with 48-in. combined pavement thickness) showed no signs of differential frost heaving.

#### Thaw weakening

21. The extent of thaw weakening of the subgrade and base courses could not be readily determined by inspection of the pavements. Pavement failures usually are repaired soon after they occur and usually are not easily examined during a condition survey. However, even where examination is possible, it is often impossible to establish by visual observations whether a failure is the result of thaw weakening or of deficiencies in the thickness of the pavement components with respect to the "normal" period loadings. The depletion of the fatigue resistance of a pavement system is progressive under repeated loadings and, in frost areas, is related to thaw weakening in that the rate of depletion is greater during and directly following the frost-melting period. This rate of pavement weakening holds true whether the evidence of fatigue or failure becomes apparent during the melting period or at some other time. The degree of thaw weakening and its effects, if any, on the condition of the pavements at PAFB consequently could not be appraised solely by this inspection. Some limited perception of the severity of thaw weakening effects can be gained, however, by comparing the performance of certain pavement features with what might be expected in the light of current frost design criteria.

22. The primary flexible pavement features at this base are the runway interior (feature R3C), taxiway A (feature T3A), and taxiway D (feature T6A). All of these features have a combined pavement thickness of 48 in., which is adequate in accordance with the current

criteria for limited subgrade frost penetration design, and no reduction in the evaluations for frost condition operation is warranted (table 4). The runway interior pavement, however, is deficient by 3 in. in the thickness of the crushed-stone base course relative to current normal (nonfrost) heavy-load design criteria (265,000-lb gear loads). Similarly, the two taxiways are deficient by 1 in. in pavement thickness and by 4 in. in crushed-stone base course thickness. All of these pavements show some load-induced defects, principally shallow rutting and longitudinal cracking, as shown in photos 1 and 2. Rigid pavement slab thicknesses of primary pavements are also from 3 to 4 in. less than those required by current normal (nonfrost) heavy-load design criteria, and load-induced defects were noted in all of these features to degrees roughly proportional to exposure to traffic channelization (photo 5).

23. PAFB was designed for medium-load aircraft (100,000-lb gear loads), and the principal aircraft using the airfield (B-47's and KC-97's) have not overloaded the pavements. B-52 aircraft (which have applied approximately 2000 cycles of traffic and alert taxiing movements, paragraph 10), however, have significantly overloaded the traffic area A and B pavements (see plate 1). The performance of these pavements is consistent with what might be expected considering the design and traffic, and it does not appear that frost weakening has been a significant factor in the development of the defects observed.

#### Maintenance

24. Maintenance of the airfield pavements at PAFB generally has consisted of seal coating the AC pavements and sealing joints and patching spalls in the PCC pavements. However, continued movement of the PCC pavements of the aprons due to horizontal expansion has caused an increase in the cost of maintenance. This type of movement necessitates the removal of the PCC pavements around an embedded feature and replacement with a flexible material such as the AC shown in photo 11. As an experiment, polyurethane foam has been recently used as a fill material between embedded features and the PCC pavements. A tabulation

of the costs of contract maintenance of the airfield pavements is presented below for the period 1961-72.

<u>Year</u>	<u>Amount</u>	<u>Year</u>	<u>Amount</u>
1961	\$58,726	1966	\$ 13,363
1962	47,585	1968	16,800
1963	29,531	1969	81,902
1964	16,724	1971	32,524
1965	96,006	1972	360,000*

\* Friction overlay.

The above amounts do not account for some maintenance that has been performed by base personnel.

#### Evaluation

25. A summary of the pavement evaluation is presented in table 4. Previously published pavement evaluations were updated to eliminate aircraft that are no longer in the Air Force inventory and to include aircraft that have been added to the inventory since the last pavement evaluation. The evaluation is based on the pavement thickness, flexural strength (PCC), base and subbase thickness and strength, strength of the subgrade (CBR or k value), and the structural condition of the pavement.

#### Conclusions

26. The following statements summarize the findings of this inspection:

- a. Considerable longitudinal cracking in the PCC pavements of the runway and aprons was noted; however, this cracking did not appear to be load related.
- b. The AC pavement of the runway interior was in only fair condition at the time of the survey because of cracking and rutting. Since the survey, a friction-type, 3/4-in. AC overlay has been applied to this feature that should upgrade its general condition to good.
- c. The taxiways through parking aprons A and B contained numerous structural defects that appeared to have been caused by channelized traffic.

- d. Expansion of the PCC pavements of the aprons had caused upheaval of the shoulder pavements and displacement of drainage structures and fueling facilities. The PCC pavement around some of these facilities had been removed and replaced with AC pavement.
- e. Around some of the drainage structures, polyurethane foam was used to replace the PCC pavement.
- f. Spall repair has generally been accomplished by removing the damaged pavements and replacing them with new PCC.
- g. Evidence of detrimental effects of frost action was observed in only one area, the shoulder of taxiway D. (The water table in this area was within 5 ft of the pavement surface.)

Table 1

## Airfield Design and Construction History

Pavement Facility	Dimensions			Pavement		Construction		Design Criteria	
	Length ft	Width ft	Thickness in.	Type	Year(s)	Agency	Weight lb	Gear Configuration	
NW-SE runway interior	9300	300	4	AC	1954-56	CE*	100,000	Twin wheels spaced 37.5 in. c-c with 267-sq-in. tire contact area (tricycle)	
Taxiway A	1570	75	4	AC	1954-56	CE			
Taxiway B	900	75	4	AC	1954-56	CE			
Taxiway C	900	75	4	AC	1954-56	CE			
Taxiway D	2600	75	4	AC	1954-56	CE			
NW-SE runway ends	1000	300	14	PCC	1954-56	CE			
North warm-up apron	Varies	Varies	14	PCC	1954-56	CE			
South warm-up apron	Varies	Varies	14	PCC	1954-56	CE			
Parking apron A	8745±	935	14	PCC	1954-56	CE			
Parallel taxiway through parking apron A	8745	75	14	PCC	1954-56	CE			
Calibration hardstand and taxiway	Varies	Varies	14	PCC	1954-56	CE			
Maintenance access apron 2	Varies	Varies	13	PCC	1954-56	CE	80,000	Twin wheels (tricycle)	
Maintenance access apron 3	260	170	13	PCC	1954-56	CE	160,000	Twin-twin wheels (tricycle)	
Maintenance access apron 5	Varies	Varies	13	PCC	1954-56	CE	80,000	Twin wheels (tricycle)	
DC aprons (2)	Varies	Varies	13	PCC	1956	CE	100,000	Twin wheels	
Parking apron B	2025±	925	13	PCC	1956	CE	100,000	Twin wheels	
Taxiway through parking apron B	2025±	75	13-15-13	PCC	1956	CE	100,000	Twin wheels	

\* -CE denotes Corps of Engineers.

**COPY AVAILABLE TO DDC DOES NOT  
PERMIT FULLY LEGIBLE PRODUCTION**

Table 8  
SUMMARY OF PHYSICAL PROPERTY DATA

FACILITY		OVERLAY PAVEMENT			PAVEMENT			BASE			SUBGRADE		GENERAL CONDITION OF AREA OR CONSIDERED		
FACILITY NUMBER AND IDENTIFICATION	LENGTH FT	WIDTH FT	THICK. IN.	DESCRIPTION	FLEX. STR PSI	THICK. IN.	DESCRIPTION	FLEX. STR PSI	THICK. IN.	CLASSIFICATION	CBR OR K	CLASSIFICATION		CBR OR K	
81A IM-SE runway, IM end; sta 150+00 to 155+00	500	300	14			14	Portland cement concrete	675	8 26	Sand (SM-SM) NPS Sand (SP-SM) NPS subbase	425	Sand (SF) F2	425	Sand (SF) F2	Very good
82B IM-SE runway, IM end; sta 145+00 to 150+00	500	300	14			14	Portland cement concrete	675	8 26	Sand (SM-SM) NPS Sand (SP-SM) NPS	425	Sand (SF) F2	425	Sand (SF) F2	Very good
83C IM-SE runway interior	9300	300	4			4	Asphaltic concrete		6 8 30	Crushed stone (SP) NPS Gravelly sand (SM-SM) NPS Gravelly sand (SM-SM) NPS	90 50 30	Silty sand (SM) F2 Sand (SF) F2 Sand (SF) F2	Com- Pact- 15 15 10		
84B IM-SE runway, SE end; sta 146+80 to 14+80	500	300	14			14	Portland cement concrete	675	8 26	Sand (SM-SM) NPS Sand (SP-SM) NPS	425	Sand (SF) F2	425	Sand (SF) F2	Poor
85A IM-SE runway, SE end; sta 14+80 to 146+80	500	300	14			14	Portland cement concrete	675	8 26	Sand (SM-SM) NPS Sand (SP-SM) NPS	425	Sand (SF) F2	425	Sand (SF) F2	Poor to fair
T1A Parallel taxiway through parking apron A	8745	75	14			14	Portland cement concrete	690	8 26	Sand (SM-SM) NPS Sand (SP-SM) NPS	425	Sand (SF) F2	425	Sand (SF) F2	Fair
T5A Taxiway through parking apron B	2025	75	15			15	Portland cement concrete (13 in.-15 in., 13 in.)	600	8 25	Sand (SM-SM) NPS Sand (SP-SM) NPS	425	Sand (SF) F2	425	Sand (SF) F2	Poor
T6A Taxiway A (connecting) Taxiway B (cutoff) Taxiway C (cutoff) Taxiway D (connecting)	1370 900 900 2000	75 75 75 75	4			4	Asphaltic concrete		6 10 28	Crushed stone (SP-SM) NPS Sand (SM-SM) NPS Sand (SP-SM) NPS	90 50 30	Sand (SM) F2	90	Sand (SM) F2	15
A1B North warm-up apron	11- regular	11- regular	14			14	Portland cement concrete	690	8 26	Sand (SM-SM) NPS Sand (SP-SM) NPS	425	Sand (SM) F2	425	Sand (SM) F2	Very good
A2B South warm-up apron	11- regular	11- regular	14			14	Portland cement concrete	690	8 26	Sand (SM-SM) NPS Sand (SP-SM) NPS	425	Sand (SM) F2	425	Sand (SM) F2	Fair
A3B Parking apron A	8745	95	14			14	Portland cement concrete	690	8 26	Sand (SM-SM) NPS Sand (SP-SM) NPS	425	Sand (SM) F2	425	Sand (SM) F2	Very good
A4B Parking apron B	2025	95	13			13	Portland cement concrete	695	8 27	Sand (SM-SM) NPS Sand (SP-SM) NPS	425	Sand (SM) F2	425	Sand (SM) F2	Very good
A5B Maintenance access apron 2	300	230	13			13	Portland cement concrete	695	8 27	Sand (SM-SM) NPS Sand (SP-SM) NPS	400	Sand (SM) F2	400	Sand (SM) F2	Excellent
A6B Maintenance access apron 3	150	100	13			13	Portland cement concrete	695	8 27	Sand (SM-SM) NPS Sand (SP-SM) NPS	400	Sand (SM) F2	400	Sand (SM) F2	Excellent
A7B DC hangar aprons	300 500	150 150	13			13	Portland cement concrete	695	8 27	Sand (SM-SM) NPS Sand (SP-SM) NPS	400	Sand (SM) F2	400	Sand (SM) F2	Very good
A8B Maintenance access apron 5	300	230	13			13	Portland cement concrete	695	8 27	Sand (SM-SM) NPS Sand (SP-SM) NPS	400	Sand (SM) F2	400	Sand (SM) F2	Very good

RES FORM 1000  
MAR 1955

(1 of 2 sheets)

COPY AVAILABLE TO DDC DOES NOT  
PERMIT FULLY LEGIBLE PRODUCTION

Table 2 (Continued)  
SUMMARY OF PHYSICAL PROPERTY DATA

FACILITY				OVERLAY PAVEMENT			PAVEMENT			BASE			SUBGRADE		GENERAL CONDITION OF AREA CONSIDERED
Facility Name	Location	Length ft	Width ft	Thick. in.	Description	Flex. Str. PSI	Thick. in.	Description	Flex. Str. PSI	Thick. in.	Classification	CBR CBR %	Classification	CBR CBR %	
APC	Calibration track and taxiway (137x5 ft diam)	625	75				14	Portland cement concrete	675	6	Sand (SM-3M) 10S	40%	Sand (SM) 10S		Excellent
BCX	3M-3E runway blast pads	150	300				2	Asphaltic concrete		6	Sand (SM-3M) 10S	50	Sand (SM) 10S	15	Good
BTX	3M-3E runway overruns ends	850	350				6	Double bituminous surface treatment			Gravel crushed stone	80	Sand (SM-3M)	30	Fair

COPY AVAILABLE TO DDC DOES NOT  
PERMIT FULLY LEGIBLE PRODUCTION

Table 3

DATE: August 1972		SUMMARY OF DATA - RIGID PAVEMENT CONDITION SURVEY											AIRFIELD: Fosse AFB Portsmouth, N. H.										
FEATURE	SLAB SIZE FT	APPROX NO. OF SLABS	PAV. THICK. IN.	NO. OF SLABS CONTAINING INDICATED DEFECTS													% OF SLABS NO. MAJOR DEFECTS	CONDITION					
				I	-	\	Δ	*	K	w	S	J	J	J	⊕	M			P	O	C	D	
R1A NW-SE runway NW end, 1st 500 ft	25 by 25	240	14	26							11											89.4	Very good
R2B NW-SE runway SW end, 2nd 500 ft	25 by 25	240	14	45	1						2		3									76.3	Very good
R4B NW-SE runway SE end, 2nd 500 ft	25 by 25	240	14	144					7		25	2	10	3	3							50.4	POOR
R5A NW-SE runway SE end, 1st 500 ft	25 by 25	240	14	170	2			3	6		35	1	12		4							19.2	POOR to failed
T1A Taxiway through parking apron A	25 by 25	1,057	14	515	1			5			150		42	8	9							52.0	Fair
T2A Taxiway through parking apron B	25 by 25	264	13-15 13	121	1		1				114		1	1	2							37.0	POOR
A1B N warm-up apron	25 by 25	250	14	38	9		6		1		82	25	5	6	2							56.0	Very good
A2B S warm-up apron	25 by 25	250	14	100	9		1				98	55	7	1	4							35.6	Fair
A3B Parking apron A	25 by 25	12,025	14	1,633	30		15		8	5	751	36	188	27	65							80.9	Very good
A4B Parking apron B	25 by 25	3,266	13	174	41		16		3		451	40	40	6	13							76.8	Very good

REMARKS: \* Practically all slabs contained map cracking to some degree.

- LEGEND:
- I LONGITUDINAL CRACK
  - TRANSVERSE CRACK
  - \ DIAGONAL CRACK
  - Δ CORNER BREAK
  - \* SHATTERED SLAB
  - K KEYED JOINT FAILURE
  - w SHRIMPAGE CRACK
  - S SCALING
  - J SPALL ON TRANSVERSE JOINT
  - J SPALL ON LONGITUDINAL JOINT
  - J CORNER SPALL
  - ⊕ SETTLEMENT
  - M MAP CRACKING
  - P PUMPING JOINT
  - O POP-OUT
  - C UNCONTROLLED CONTRACTION CRACK
  - D "D" CRACKING

COPY AVAILABLE TO DDC DOES NOT PERMIT FULLY LEGIBLE PRODUCTION



Table 4  
SUMMARY OF PAVEMENT EVALUATION

NAME OF AIRFIELD: Pensac AFB		DATE OF EVALUATION		LOAD-CARRYING CAPACITY IN LB OF GROSS PLANE LOAD FOR INDICATED LANDING GEAR TYPES AND CONFIGURATIONS												REMARKS
MONTH: August		YR: 1972		TRICYCLE ARRANGEMENT												
NO.	FEATURE DESIGNATION	PAVEMENT OPERATIONAL USE	SINGLE 100-PSI TIRE PRESSURE	SINGLE 100-PSI CONTACT AREA	SINGLE 241-SQ-IN. CONTACT AREA	TW 24IN. C-C 226-SQ-IN. CONTACT AREA EACH TIRE	SINGLE TANDEM 40-IN. SPACING 400-SQ-IN. CONTACT AREA	TW 37IN. C-C 267-SQ-IN. CONTACT AREA EACH TIRE	TW 44IN. C-C 430-SQ-IN. CONTACT AREA EACH TIRE	TW 50IN. C-C 500-SQ-IN. CONTACT AREA EACH TIRE	TW 56IN. C-C 580-SQ-IN. CONTACT AREA EACH TIRE	TW 60IN. C-C 600-SQ-IN. CONTACT AREA EACH TIRE	TW 66IN. C-C 680-SQ-IN. CONTACT AREA EACH TIRE	TW 70IN. C-C 700-SQ-IN. CONTACT AREA EACH TIRE		
RLA	NW-SE runway 1st 500 ft NW end	Capacity	155,000+	155,000+	155,000+	220,000+	200,000+	240,000	330,000	380,000+	380,000+	380,000	380,000+	380,000	380,000	
REA	1st 500 ft SE end															
REB	NW-SE runway 2nd 500 ft	Capacity	155,000+	155,000+	155,000+	220,000+	200,000+	330,000+	330,000+	380,000+	380,000+	380,000+	380,000+	380,000	380,000	
RHB	NW-end															
RHC	2nd 500 ft SE end															
RXC	NW-SE runway interior	Capacity	155,000+	155,000+	155,000+	220,000+	200,000+	330,000	330,000	380,000+	380,000+	380,000	380,000+	380,000	380,000	
T1A	Taxiway through parking apron A	Capacity	155,000+	155,000+	155,000+	220,000+	200,000+	230,000	320,000	360,000+	360,000+	360,000	360,000+	360,000	360,000	
T2A	Taxiway through parking apron B	Capacity	155,000+	155,000+	155,000+	220,000+	200,000+	235,000	320,000	380,000+	380,000+	380,000	380,000+	380,000	380,000	
T3A	Taxiway A (connecting)	Capacity	155,000+	155,000+	155,000+	220,000+	200,000+	225,000	275,000	320,000	320,000	320,000	320,000	320,000	320,000	
T4A	Taxiway B (connecting)	Capacity	155,000+	155,000+	155,000+	220,000+	200,000+	225,000	275,000	320,000	320,000	320,000	320,000	320,000	320,000	
T4C	Taxiway B (cutoff)	Capacity	155,000+	155,000+	155,000+	220,000+	200,000+	225,000	275,000	320,000	320,000	320,000	320,000	320,000	320,000	
T5C	Taxiway C (cutoff)	Capacity	155,000+	155,000+	155,000+	220,000+	200,000+	225,000	275,000	320,000	320,000	320,000	320,000	320,000	320,000	
A1B	North and south warm-up aprons	Capacity	155,000+	155,000+	155,000+	220,000+	200,000+	275,000	330,000+	380,000+	380,000+	380,000	380,000+	380,000	380,000	
A2B	Parking apron A	Capacity	140,000	155,000+	155,000+	210,000	200,000+	240,000	320,000	380,000+	380,000+	380,000	380,000+	380,000	380,000	
A3B	Parking apron B	Capacity	140,000	155,000+	155,000+	210,000	200,000+	240,000	320,000	380,000+	380,000+	380,000	380,000+	380,000	380,000	
A4B	Parking apron B	Capacity	140,000	155,000+	155,000+	210,000	200,000+	240,000	320,000	380,000+	380,000+	380,000	380,000+	380,000	380,000	

Note: + sign denotes allowable gross loading greater than maximum gross weight of any existing aircraft having indicated gear configuration.  
Frost evaluations are not shown, since combined pavement thicknesses are adequate for limited subgrade frost penetration criteria.

COPY AVAILABLE TO DDC DOES NOT PERMIT FULLY LEGIBLE PRODUCTION

Table 4 (Continued)  
SUMMARY OF PAVEMENT EVALUATION

NAME OF AIRFIELD: Pease AFB		LOAD-CARRYING CAPACITY IN LB OF GROSS PLANE LOAD FOR INDICATED LANDING GEAR TYPES AND CONFIGURATIONS		TRICYCLE ARRANGEMENT										BICYCLE	REMARKS
DATE OF EVALUATION MONTH: August YR: 1972		PAVEMENT OPERATIONAL USE		SINGLE 100-PSI TIRES	SINGLE 100-SQ-IN. CONTACT AREA	SINGLE 241-SQ-IN. CONTACT AREA	TR 28 IN. C-C 33 IN. X 46 IN. CONTACT AREA EACH TIRE	TR 33 IN. C-C 33 IN. X 46 IN. CONTACT AREA EACH TIRE	TR 44 IN. C-C 33 IN. X 46 IN. CONTACT AREA EACH TIRE	TWIN TANDEM 33 IN. X 46 IN. CONTACT AREA EACH TIRE	C-5A CLEAR CONFIGURATION	TWIN TANDEM SPCG 374231 207-SQ-IN. CONTACT AREA EACH TIRE			
NO.	DESIGNATION	1	2	3	4	5	6	7	8	9	10				
A7B	Maintenance access apron 2	135,000	85,000+	155,000+	200,000	200,000+	225,000	310,000	380,000+	800,000+	320,000				
A6B	Maintenance access apron 3														
A7B	DC hangar aprons														
A6B	Maintenance access apron 5														
A7C	Calibration hardstand and taxiway	155,000+	85,000+	155,000+	220,000+	200,000+	330,000+	330,000+	380,000+	800,000+	550,000				

(2 of 2 sheets)

WES FORM NO. 989  
JUNE 1972  
EDITION OF AUG 1960 IS OBSOLETE.

COPY AVAILABLE TO DDC DOES NOT PERMIT FULLY LEGIBLE PRODUCTION



Photo 1. General view of cracking on runway approximately  
2500 ft from NW end



Photo 2. General view of runway near SE end  
of AC pavement



Photo 3. Pavement condition at junction of  
PCC and AC at SE end of runway



Photo 4. AC surface patches on PCC pavement  
at SE end of runway




Photo 5. General view of PCC pavement at  
SE end of runway



Photo 6. Sealing of slabs in north warm-up apron




Photo 7. Longitudinal cracks in south warm-up apron



Photo 8. Scaling of slabs in south warm-up apron



Photo 9. Typical longitudinal cracking  
(as in parking aprons A and B)



Photo 10. Upheaval of shoulder pavement at  
north end of parking apron A





Photo 11. AC replacement of PCC pavement  
at drainage structure



**LEGEND**

**TYPE OF FEATURE**





- R - RUNWAY
- T - TAXIWAY
- A - APRON

**TYPE TRAFFIC AREA (SEE NOTE 2)**

- A - A TYPE TRAFFIC
- B - B TYPE TRAFFIC
- C - C TYPE TRAFFIC
- X - NO TRAFFIC TYPE ASSIGNED


- AC - ASPHALTIC CONCRETE
- PCC - PORTLAND CEMENT CONCRETE
- DBST - DOUBLE BITUMINOUS SURFACE TREATMENT
- DIRECTION OF SURVEY

500  
 NOTES: 1. FE  
 FE  
 TY  
 2. TR  
 HE




NOTES: 1. FEATURE DESIGNATION DENOTES TYPE OF FEATURE, NUMBER OF FEATURE FOR GIVEN TYPE, AND TYPE TRAFFIC AREA.  
 2. TRAFFIC AREA DESIGNATIONS ARE BASED ON HEAVY-LOAD CRITERIA.

2







PEASE AFB  
AIRFIELD LAYOUT

3



**LEGEND**

-  PORTLAND CEMENT CONCRETE PCC
-  ASPHALTIC CONCRETE AC
-  BLAST PAVEMENT (AC - NONTRAFFIC)
-  DOUBLE BITUMINOUS SURFACE TREATMENT

500



MAINTENANCE  
ACCESS APRON 3

DC APRONS

MAINTENANCE  
ACCESS APRON 5

PARKING APRON A

TAXIWAY B

TAXIWAY A


NW - SE RUNWAY 11,320' x 300'

STA 51+80


STA 46+80

34


CALIBRATION  
HARDSTAN



2




VICINITY MAP



OWNS

MAINTENANCE  
ACCESS APRON 5



PEASE AFB  
PAVEMENT PLAN