

AD A 058008

AD No. _____
DDC FILE COPY

410163
↓

LEVEL II

LARGE CALIBER WEAPON SYSTEMS LABORATORY

ENGINEERING REPORT LCR-E-1004

(14) AR LCR-E-1004

(E) **DUD INVESTIGATION OF
M69 ELECTRIC DETONATOR**

(10) BY: JOSEPH O. JULIANO

JUL 20 1978
RESOLVED

(11) APR 1978

(12) 49p

EXHIBIT A
Approved for release
Distribution Unlimited

US ARMY ARMAMENT RESEARCH AND DEVELOPMENT COMMAND

STANDARD TRUNK MUNITIONS



DOVER, . . . RSEY 07801

410163

TABLE OF CONTENTS

12

- I. INTRODUCTION
- II. BACKGROUND
- III. ANALYSIS OF PROBLEM
- IV. CORRECTIVE DESIGN REVISION
- V. DISCUSSION OF RESULTS
- VI. RECOMMENDATIONS
- VII. FIGURES
- VIII. DATA TABLES
- IX. REFERENCES
- X. DISTRIBUTION LIST



ADDRESS	12
NTIS	☒
DOC	☐
UNCLASSIFIED	☐
EXCLUDED	☐
BY	DATE/INITIALS
DATE/INITIALS	DATE/INITIALS
DATE/INITIALS	DATE/INITIALS

ABSTRACT

During the MIF³ investigation on the 105MM M456A1 HEAT Cartridge, it was found that the M509A1 Fuze containing the M48 Detonator was not Detonator Safe when initiated in the unarmed position. Since the M48 Detonator was found to be the primary source of the problem, the smaller M69 Detonator was selected to replace it in the M509A1 Fuze to assure out-of-line detonator safety. Initial Laboratory and ballistic testing of the fuze with the M69 Detonator in the M456A1 Cartridge resulted in an abnormally high dud rate. An intensive investigation of the problem over approximately a two month period revealed an inherent deficiency in the M69 Detonator Technical Data Package which allowed inadequate consolidation of the Lead Azide Charge. This results in a shift of the Lead Azide Charge during high "g" ballistic firing causing a separation at the Carbon Bridge Interface and subsequent non-initiation upon electrical pulsing of the Carbon Bridge. Resolution of the dud problem required implementation of a number of revisions to the TDP, the most significant of which were to increase the Lead Azide Charge thereby increasing the consolidation pressure to the proper level, and to control the manufacturing parameters and loading procedures to guarantee and maintain the integrity of the detonator design during production.

I. INTRODUCTION

The M69 Detonator is a Carbon Bridge Electric Detonator utilized in the M530 Series PIBD Fuzes designed for use in the 90MM and 106MM Recoilless Rifle HEAT Cartridges. The recoilless rifle projectiles are characteristically low acceleration (less than 10,000 g's setback) and low velocity (less than 2,000 fps) projectiles. The M69 Detonator has also been utilized in very limited quantity in a modified M530 Fuze (XM559E1) being developed for use in the 90MM and 105MM HEAT Cartridges fired from the respective tank guns. In contrast, the projectiles fired from these weapons are high acceleration (setback greater than 35,000 g's) and high velocity (greater than 3,800 fps). This program, however, never proceeded to completion, consequently the M69 Detonator was never actually qualified in the tank guns.

A recent malfunction investigation on the 105MM M456A1 HEAT Cartridge, included among other things, an evaluation of the M509A1 Fuze as a potential contributor to the malfunction. One of the results of that investigation was the discovery that the M509A1 Fuze was not out-of-line detonator safe. This condition was traceable to the M48 Detonator, whose output cannot be contained by the fuze metal parts when it functions in the normally safe out-of-line position.

Consequently, a Product Improvement Program was authorized to rectify this condition as well as several others related to reliability.

Since the M530 Series Fuzes are detonator safe utilizing almost identical metal parts, design arrangement and the same explosive components (lead and booster) except for the detonator, it was decided that replacement of the M48 Detonator with the M69 Detonator offered the most expedient resolution of the detonator safety problem. Initial fuzes containing M69 Detonators assembled for test indicated satisfactory resolution of the detonator safety problem, but uncovered an unsatisfactory dud problem during ballistic firings. This report presents the problem experienced, the investigation and evaluation of that problem, the outcome of the corrective actions implemented and a discussion of the results.

II. BACKGROUND

The M509A1 PIBD Fuze (Figure 1) is currently used in a number of HEAT Cartridges, specifically the 105MM M456A1; the 106MM M344A1 and the 90MM M431E2. Recently, the M456A1 and M344A1 Cartridges have been the subjects of in-bore premature malfunction investigations. As such, the M509A1 Fuze became an inherent part of those investigations with regard to its relationship as a potential contributor to the malfunctions. The culmination of the fuze investigation was the discovery of a number of M509A1 Fuze Technical Data Package inadequacies affecting both the safety and reliability of the fuzing system.

The primary discovery relative to safety, was the absence of adequate out-of-line detonator safety in the M509A1 Fuze. Static detonator safety tests conducted during the investigation, resulted in initiation of the HE filler of an M456A1 Cartridge (Figures 2a and 2b). Additional detonator safety tests conducted on the fuze alone, showed that the M48 Detonator, when in the safe out-of-line position, was able to blast through the steel fuze housing shield with sufficient force to initiate the HE projectile filler directly. Research on the past history of the M509A1 Fuze, revealed that the fuze was considered only marginally detonator safe in the out-of-line position because of bulging and cracking of the fuze housing shield. It was also found that during the ensuing years of production, an

engineering change was implemented to allow a free machining steel for the housing shield. The higher lead content resulted in a softer more ductile material which in the most recent tests suffered severe damage due to the detonator blast alone (Figure 3). This resulted in an even further degradation of an already marginally safe condition.

Another condition uncovered, was the location of the fuze in the projectile. The original version of the M456A1 Cartridge, was designed such that the fuze was completely encapsulated within the metal of the projectile body as shown for the 90MM Projectile in Figure 4. Only the output end of the fuze booster was exposed to the explosive filler. An engineering change implemented as the result of an earlier (1961) premature investigation modified the projectile assembly from a two piece to a one piece body design (Figure 5). This change shortened the overall projectile length and resulted in the fuze location being shifted such that over half the fuze is now encapsulated within the HE filler. The same situation also exists by design in the 106MM M344A1 HEAT Cartridge (Figure 6). Ultimately it was found that this fuze location combined with the weaker housing shield material and excessive output M48 Detonator, collectively resulted in the M509A1 Fuze not being detonator safe.

In attempting to correct the detonator safety condition, it was considered that the M48 Detonator with its excessive

output was basically the problem. It was decided that a lower output detonator would provide the most expeditious resolution. Toward this end, the M69 Detonator used in the M530 Series Fuzes seemed to be the most logical choice for replacement of the M48 Detonator. The M509 and M530 Fuzes are almost identical in size, metal parts design, operation (share common arming mechanism) and electrical characteristics. The explosive trains consist of common lead and booster charge components except for the detonators. The M48 Detonator (Figure 7) is a relatively large (.274" dia x .490") detonator, has wire leads and contains approximately 160 mg's of output charge. The M69 Detonator (Figure 8) is smaller (.195" dia x .370"), has a button lead and approximately an 85 mg output charge. Both detonators were considered to be interchangeable with regard to end item utilization. Consequently, design revisions were instituted in the M509A1 Fuze, to replace the M48 Detonator with the M69 Detonator.

A quantity of 2,000 M69 Detonators (Lot AM2-3-4) was purchased from AMRAM Corporation, Vineland, New Jersey for evaluation purposes in the M509A1E1 Fuze Product Improvement Program. The required acceptance tests were conducted in accordance with the specification, and produced satisfactory results (Table I).

The first group of 100 M509A1E1 Fuzes containing M69 Detonators was assembled for laboratory type tests. Fifty (50)

were first subjected to an air gun test for arming evaluation and then divided into two groups; 25 for static detonator only functioning and 25 for complete explosive train propagation (detonator through booster) at ambient temperature. The balance of 50 were to be divided such that 10 would be subjected to detonator safety tests and 40 to complete explosive train propagation, half each at -35°F and +125°F.

These tests were conducted, with the results as shown in Table II. Of the 10 units assembled for static detonator safety, three were unusable due to problems peculiar to the specially modified assembly necessary to initiate the detonator in the out-of-line position. The seven remaining units subjected to the out-of-line detonator safety tests showed successful resolution of the detonator safety problem. The units tested with M69 Detonators (Figure 9) show virtually no parts deformation as compared to those tested with the M48 Detonator (Figure 10) which were completely blown apart.

The results of the detonator and complete explosive train functioning tests, both static and after being subjected to the simulated setback of the air gun, demonstrated an uncharacteristically high number of duds. A number of these duds were subsequently fired by subjecting the detonator to voltage levels in excess of the detonator specification level. Upon investigation as to the cause of this abnormal dud rate, it was found that one of the electrical cables being used for the

firing lines was faulty. This resulted in an unreliable voltage signal being delivered to the detonator, thereby causing a corresponding degradation in functioning performance.

In order to confirm this fact, the faulty cable was replaced and a number of retests conducted for verification (Table III). A group of 50 detonators from Lot AM2-3-4, not in fuzes, was temperature conditioned at +125°F and subjected to functioning tests. All 50 functioned properly, with no duds. An additional quantity of 60 detonators was assembled into fuzes and subjected to static initiation tests, 20 each at -35°F, ambient and +125°F. Again all 60 functioned properly, with no duds. A final group of 60 detonators was also assembled into fuzes and subjected to a simulated ballistic environment in the air gun. This was followed by static initiation after temperature conditioning at -35°F, ambient and +125°F. Functioning performance was within acceptance level requirements with two duds occurring in the ambient group. At this point, however, there was still some apprehension over the two duds experienced after the air gun tests. Consequently, it was decided to evaluate the product improved M509A1E1 Fuze with the M69 Detonator for performance in an actual ballistic environment.

A total of 150 M509A1E1 Fuzes was delivered to Camp Edwards, Massachusetts, for assembly into 105MM M456A1 HEAT Cartridges. These rounds were to be tested for an evaluation

of fuze arming distance and armor plate functioning performance. The results of this test are detailed in Table IV. A total of 42 rounds was fired to determine the arming distance limits. This test was considered necessary since the addition of the M69 Detonator resulted in a change in the rotor and detonator contact assembly. The results, however, indicated no change in the arming distance due to these configuration changes. The balance of the test consisted of an evaluation of functioning performance against armor plate at 60° obliquity. Here again, as can be seen in the test data, an unacceptable dud rate (4 duds in 29 rounds fired) was experienced.

Evaluation of the results at that time indicated that the performance may have been influenced by the yaw of the round during flight. Excessive yaw combined with the 60° obliquity of the plate could result in an angle of impact such that the piezoelectric element in the nose of the projectile makes contact at such a shallow angle that insufficient voltage is generated to reliably initiate the detonator. In order to evaluate this theory, the armor plate target was raised to 0° obliquity. A total of 20 rounds was fired at this condition resulting in only one dud, well within acceptable performance limits.

In an attempt to further verify this theory, 25 product improved M456A1E2 Projectiles were assembled for test. This

projectile design utilizes the Full Frontal Area Impact Switch (FFAIS), which contains a stored energy power supply (independent of impact angle for voltage generation) and has an 80° obliquity functioning capability. Fifteen (15) of these projectiles were assembled with M509A1E1 Fuzes having M69 Detonators, and the remaining 10 with Standard M509A1 Fuzes containing M48 Detonators. Ballistic tests of these rounds against 60° obliquity plate again resulted in approximately a 20% dud rate (3/15) with the M69 Detonators and no duds with the M48 Detonators, Table V. At this point it was concluded that a dud problem unquestionably existed in the M509A1E1 Fuze that appeared to be related to the use of the M69 Detonator. Consequently, an intensive investigation was initiated to analyze and resolve the problem.

III. ANALYSIS OF PROBLEM

A review of the data available at the start of this investigation revealed the following facts about the problem:

- a. Statically, the M69 Detonator performs satisfactorily.
- b. All failures occurred after the detonators had been subjected to simulated or real ballistic firing environments.
- c. Problem appeared to be predominant when tested against 60° obliquity plate where the voltage generated due to impact is minimal. Results of tests against 0° obliquity plate where voltage generated is maximum, showed little or no indication of a dud problem.
- d. Dud analysis of those detonators which failed to fire, showed that the Carbon Bridge had been pulsed electrically and for all purposes should have resulted in explosive initiation.
- e. X-ray analysis of two duds, indicated what appeared to be a crack in the Lead Azide Charge emanating from the corner of the pin and plug assembly in one of the detonators.
- f. Problem appeared to be localized at the Carbon Bridge/Lead Azide Charge Interface.

A meeting was held to disseminate the details of the problem and the above data to the most knowledgeable detonator

experts at ARRADCOM, namely; Mr. W. Voreck, Mr. D. Seeger and Mr. J. Hershkowitz. Upon reviewing this information, the general consensus of opinion was that the explosive column was shifting or shearing under setback, at the interface with the Carbon Bridge. In the normal out-of-line position, the detonator is in a horizontal position, such that the acceleration force due to firing is applied transversely or perpendicular to the explosive column. It was also indicated that this condition would result in duds when voltage levels are at or below specification levels. However, it was further explained that significantly higher than normal voltages, such as would occur at 0° obliquity impacts, would override the problem by causing an extremely vigorous breakdown of the Carbon Bridge.

Consequently, it was decided that a test program should be outlined to investigate the cause of the duds and evaluate its resolution. Figure 11 represents the test plan implemented. The basic intent of this plan was to evaluate the present M69 Detonator Lot AM2-3-4 with which the problem occurred, an existing supposedly acceptable lot of M69 Detonators as loaded in M530A1 Fuzes and a quantity of Lot AM2-3-4 modified to correct the hypothesized problem.

In accordance with the test plan, 500 M69 Detonators (Lot AM2-3-4) were set aside for evaluation. Of the 500, a sample of 200 were serialized, weighed and subjected to an

electrical resistance check of the Carbon Bridge. These 200 detonators were then x-rayed prior to any subsequent testing. Following x-ray, 100 units were subjected to a simulated ballistic firing environment of 35,000 - 38,000 g's in the air gun. Upon completion of the air gun tests, the detonators were re-x-rayed to determine if any visual damage could be detected. The x-rays showed no visibly detectable flaws due to the simulated ballistic tests. The 100 units were then subjected to static functioning tests using the specification level voltage for all fire conditions. As can be seen in Table VI, 2 of the 100 units failed to function. Again, an electrical check of the Carbon Bridges in the duds, showed a change in resistance values indicative of the fact that the bridges had been electrically pulsed, but the explosive had failed to initiate.

In order to obtain a comparison with previous M69 Detonators produced, a sample of 120 M630A1 Fuzes from Lot AKT-3-2 containing this detonator was down-loaded to remove the lead and booster charges. The rotors containing the detonators were removed from the fuze housings, serialized and checked electrically for bridge resistance. All detonators showed resistances in the acceptable range. Sixty (60) of the 120 were then subjected to static functioning tests resulting in 60/60 proper functioning. The remaining 60 detonators were subjected to air gun tests at 35,000 g's to simulate the

ballistic environment. Following the air gun tests the bridge resistance electrical check was repeated with all values still checking out within the acceptable ranges. The sample was then subjected to static functioning tests resulting in one dud out of the 60 tested. These results appeared to indicate that the dud problem experienced was not peculiar to the new Lot AM2-3-4, but was rather an inherent deficiency existent within this detonator.

On the basis of this data, it was recommended by Mr. W. Voreck that a sample of Lot AM2-3-4 detonators be reconsolidated to a fixed pressure. It was his theory that the Technical Data Package as it existed did not adequately control the consolidation pressure of the Lead Azide Charge. The drawings control the loading to a dimension, thereby resulting in a situation where the explosive is pressed to a fixed stop, resulting in a variation in pressures due to metal parts tolerances and charge weights. Consequently, when the consolidation pressure is too low, the setback force, being applied perpendicular to the explosive column in the unarmed position, causes a shifting or separation to occur between the Carbon Bridge and the explosive, where a tight interface must be maintained.

A total of 100 M69 Detonators from Lot AM2-3-4 was provided for reconsolidation. The reconsolidation pressure was set at the maximum allowable on the drawing, 13,000 psi. A sample of 100 was serialized, weighed and dimensionally

checked prior to reconsolidation. The first 10 detonators were subjected to 13,000 psi and checked. One of the 10 showed an open circuit during the electrical resistance check and was discarded. The remaining 9 showed acceptable resistance readings and were subjected to static functioning tests. All 9 functioned properly.

On the basis of these results, the remaining 90 detonators were subjected to the reconsolidation pressure of 13,000 psi. Following the pressing operation, the detonators were dimensionally and electrically checked. As a result of the reconsolidation, the length of the detonators was reduced a minimum of .006" to a maximum of .019". The average reduction in length was .013". All electrical resistance readings were acceptable. The 90 detonators were also x-rayed and showed no noticeable effects from the reconsolidation operation. The detonators were then subjected to air gun tests at 35,000 g's prior to static functioning. All 90 detonators were then tested for functioning at specification level voltage, resulting in 90/90 proper functioning with no duds.

These results seemed to substantiate the basic theory that the explosive charge separates from the Carbon Bridge due to the rigorous ballistic environment of the 105MM Tank Gun. The separation apparently was caused by inadequate consolidation of the Lead Azide Charge due to deficient

controls within the TDP. At this point it was decided that verification of this condition could best be accomplished by a ballistic test of a sample of M69 Detonators fabricated and assembled to a revised loading procedure to control the consolidation pressure of the Lead Azide.

IV. CORRECTIVE DESIGN REVISIONS

With the aid of Mr. Voreck, a revised loading procedure was established to control the consolidation of the Lead Azide Charge with minimal effect on the manufacturing process. This was done by increasing the nominal Lead Azide Charge weight by 15 mg. This weight was calculated by Mr. Voreck on the basis of the reconsolidation data previously generated and the requirement to maintain a pressure of approximately 13,000 psi. This effort was discussed with the detonator manufacturer (AMRAM Corporation, Vineland, New Jersey) and a quantity of 500 units was fabricated for tests.

The 500 revised M69 Detonators were delivered to the fuze metal parts contractor and assembled into fuzes for tests. Since the dud rate experienced during ballistic tests was relatively high for the small number of rounds fired as compared to the dud rate experienced during laboratory tests, it was decided that a ballistic test would provide a more positive indication of resolution of the problem. Therefore, on the basis of the dud rate previously experienced against 60° obliquity armor, it was considered that a 25 round sample was sufficient to verify resolution. The fuzes were assembled into 105MM M456A1 HEAT Cartridges. One cartridge was rejected during inspection for a damaged obturator, leaving 24 rounds for the test. The 24 rounds were ballistically tested against 60° obliquity armor at Camp Edwards, Massachusetts (Table VII)

under test conditions identical to those which had previously produced the unacceptable dud rate. The test results were highly successful in that 24/24 functioned properly with no duds. These results were in marked contrast to the previous tests in which four duds were experienced in 29 rounds. Consequently, it would appear that the dud problem was properly diagnosed as being attributable to the M69 Detonator, and could be eliminated by the application and control of the proper level of consolidation pressure for the Lead Azide Charge. Subsequent testing in larger quantity further confirmed this.

V. DISCUSSION OF RESULTS

The results of the investigation conducted to determine the cause of the duds experienced with the M69 Detonator in the M509A1E1 Fuze application, have shown the problem to be directly related to a basic inadequacy in the Technical Data Package. The problem was not related to any defect in the detonator design, but rather to the lack of adequate controls in the TDP on the method or process of manufacture. Moreover, from the limited data available in this area, it is felt that this problem was not restricted to any individual lot of detonators produced. In all likelihood it would appear that the majority of M69 Detonators produced to date contain the same basic defect to some degree. Only the use of this detonator exclusively in low acceleration weapons has prevented its being noticed previously.

The problem is the result of two basic factors. First, the TDP for the detonator does not specify and control the loading pressure of the Lead Azide Charge which is critical to maintaining the integrity of the loaded assembly. In addition, the present specification for the detonator requires only a static test sequence for acceptance. If a dynamic test sequence had been in force, the detonator deficiency would have been discovered much earlier and the time and cost expended in firing complete fuzeed projectiles could have been

avoided. Consequently, this also is viewed as an additional TDP deviciency.

The second factor relative to this problem is the method of manufacture. In simplified terms, the loading of these detonators consists first of the assembly and pressing of an 80-84 mg PETN pellet into the detonator cup to a height of .128" - .140". The colloidal Lead Azide spot is then applied to the bridge assembly. Then 82-92 mg of dextrinated Lead Azide is added to the cup and the bridge assembly is pressed to a stop, to produce a header height of .353" - .358". If the Lead Azide by weight is on the low side and the metal parts assembly is at maximum metal conditions (detonator cup diameter and length is at the maximum end) a low density charge will result. During acceleration this low density charge can slide sideways over the spotting charge, breaking it away from the bridge, and causing misfires. Thus the present method of manufacture is geared to assemble and check detonators to heights by fixed stops in the loading presses. This facilitates manufacturing and inspection, but does not guarantee adequate charge consolidation pressure. Consequently, to provide and maintain an acceptable detonator revisions to one or both of these factors must be addressed.

VI. RECOMMENDATIONS

Based upon the findings of this investigation, it is recommended that the M69 Detonator TDP be revised to correct the deficiencies discovered. Briefly, these changes will include an increase in the weight of the Lead Azide Charge (Dwg No. 8857199) to guarantee, under the fixed stop loading procedure, that the consolidation pressure would be no less than 12,000-13,000 psi. This method would not require any revision in present manufacturing or inspection procedures in order to maintain the required loading density. In addition, the specification acceptance criteria (Spec No. MIL-D-60031) will be revised to incorporate a series of dynamic functioning tests as well as the usual static functioning tests. The dynamic tests will simulate the acceleration levels associated with the most severe ballistic environment in which the detonator will be used, and will be patterned after those successfully utilized in Navy detonator specifications. Implementation of these changes will result in a high quality, reliable detonator capable of uniform performance across its ballistic utilization spectrum. It is additionally recommended that TDPs for other detonators, requiring operation within similar ballistic environments, be given consideration for incorporation of dynamic tests for acceptance. Implementation of such a procedure would conceivably reject potentially defective detonators prior to costly fuze or projectile acceptance tests.

VII. FIGURES

FUZE M509A1




FIGURE 1




FIGURE 2a



FIGURE 2b




M509A1

W/M48DET

OUT OF LINE TEST

FIGURE 3

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC



二

**105MM M456 HEAT PROJECTILE
W/M509A1 PIBD FUZE**




FIGURE 5

! 2000-2001




FIGURE 6

M48 (T18E4) DETONATOR

DESCRIPTION

CUP Aluminum
CONTACTS Stainless steel wire leads
BATTERY Carbon
RESISTANCE 1000 - 10,000 ohms
CODE NO. Wnt7a1m
DWG. NO. 73-1-240
SPEC. NO. NO. PA-PD-197
MANUF. Atlas Powder Co.



SENSITIVITY

SPECIFICATION
0.0022 μ f
300 volt

FUNC. PROB'Y	CHARGED CAPACITOR
0.95*	0.0022 μ f 195 v
0.50	0.0022 μ f 85 v
0.05*	0.0022 μ f 37 v
DATE FIRED	March 1954

RELIABILITY WITH 90% CONF.

NO. TESTED FIRED NO. MISFIRED AVG. FUNC. TIME

LOT NO.
AVG. RESIST.

OUTPUT **Minimum hole in lead disk is 5/8 in.

REFERENCES

* With 90% confidence.
** These data were not obtained at Franklin Institute.

THE FRANKLIN INSTITUTE • Laboratories for Research and Development

Electric Initiator Handbook


March 1962
(Revision 1)

T21E1 T74 DETONATOR

M69

DESCRIPTION

CUP Stainless steel
CONTACTS Stainless steel button
BRIDGE Carbon
RESISTANCE 1000 - 10,000 ohm
CODE NO. SU7efm
DWG. NO. P-85443
SPEC. NO. X-PA-PD-686 (assembly)
X-PA-PD-841 (metal parts)
MANUF. Atlas Powder Co.



SENSITIVITY

SPECIFICATION
0.0022 μ f
300 volt

FUNCT. PROB'Y	CHARGED CAPACITOR	CONSTANT VOLTAGE
0.95*	0.0022 μ f	18 v
0.50	0.0022 μ f	Pulse
0.05*	0.0022 μ f	10 v
		Duration
		6.0 v
		1 msec
DATE FIRED	December, '953	January 1958

RELIABILITY WITH 90% CONF. 99.5% TEST CONDITIONS .0022 mfd capacitor at 300 v LOT NO. AAP 45-6
NO. TESTED 500 FIRED 100% NO. MISFIRED 0 AVG. FUNCT. TIME 1.79 μ sec AVG. RESIST. 4400 ohms

OUTPUT **Initiates tetryl lead across 0.090 in. air gap.


REFERENCES Notes on Development Type Materiel, Detonator, Electric, Picatinny Arsenal Notes No. 113.

* With 90% confidence.
** These data were not obtained at Franklin Institute.

IV-4.2.4A


FIGURE 8

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC



11509A/E1
DETONATOR OUT OF
LINE SAFETY TEST
(AMBIENT)

FIGURE 9



M509A1

W/M48DET

OUT OF LINE TEST

M69 DETONATOR INVESTIGATION PLAN




FIGURE 11

VIII. DATA TABLES

TABLE I.

M69 DETONATOR ACCEPTANCE TESTS
SPECIFICATION MIL-D-60031 (MU)
AMRAM LOT AM-2-3-4

- A. SPECIFICATION TEST REQUIREMENT: Functioning Time,
Para. 4.3.4

Requirement - Functioning within 5 microseconds
Units Tested - 35
Mean Functioning Time - 2.115 microseconds

- B. SPECIFICATION TEST REQUIREMENT: Waterproofness and
Output, Para. 4.3.5

Requirement - Reject on one or more duds
Units Tested - 50
Conditions - Immersion in water maintained @20°C
for not less than 48 hours at a depth
of 2-3 inches
Functioning - 50/50, no duds

- C. SPECIFICATION TEST REQUIREMENT: Duds, Para. 4.3.6

Requirement - Accept on one dud, reject on two or
more
Units Tested - 100
Functioning - 99/100, 1 dud

TABLE II.

STATIC LABORATORY TESTS
M509A1E1 FUZE W/M69 DETONATOR

A. DETONATOR SAFETY: MIL-STD-331A, Test 115

10 units assembled for test, 3 rejected electrically
for malassembly

7 units tested and found completely acceptable in
accordance with MIL-STD-331 requirement

B. DETONATOR FUNCTIONING: (300V @ .0022 μ fd Firing Pulse)

25 units initiated @ ambient temperature

22/25 functioned properly
3/25 duds

* Attempts to fire 3 duds @ 500V - failed 0/3

C. PROPAGATION: Detonator Through Booster

25 units initiated @ ambient temperature

18/25 functioned properly
7/25 detonator duds

* Attempts to fire 7 duds @ 500V

2/7 functioned @ 500V
5/7 duds @ 500V

20 units initiated @ -35°F

14/20 functioned properly
6/20 detonator duds

* Attempts to fire 6 duds @ 500V - failed 0/6

20 units initiated @ 125°F

12/20 functioned properly
8/20 detonator duds

* Attempts to fire 8 duds @ 500V

4/8 functioned
4/8 duds

TABLE III.
STATIC LABORATORY RETEST
M69 DETONATORS

A. DETONATOR FUNCTIONING (Bare Detonators)

50 units initiated @ +125°F

50/50 functioned properly
0/50 duds

B. DETONATOR FUNCTIONING (Detonators Assembled in Fuzes)

20 units initiated @ -35°F

20/20 functioned properly
0/20 duds

20 units initiated @ ambient temperature

20/20 functioned properly
0/20 duds

20 units initiated @ +125°F

20/20 functioned properly
0/20 duds

C. DETONATOR FUNCTIONING AFTER AIR GUN TESTING

60 units subjected to 35,000 g's

All fuzes armed properly

20 units conditioned @ -35°F & initiated

20/20 functioned properly; 0 duds

20 units initiated @ ambient temperature

18/20 functioned properly
2 duds

20 units conditioned @ +125°F and initiated

20/20 functioned properly; 0 duds

- BALLISTIC DATA SHEET

TABLE IV

SHEET / OF 9

TEST ITEM:		PURPOSE OF TEST:		ADDITIONAL COMMENTS	
M16A1 M16A2 M16A3		1. RANGE DATA 2. RANGE DATA 3. RANGE DATA		1. RANGE DATA 2. RANGE DATA 3. RANGE DATA	
1	1210	1210	1210	1210	1210
2	1210	1210	1210	1210	1210
3	1210	1210	1210	1210	1210
4	1210	1210	1210	1210	1210
5	1210	1210	1210	1210	1210
6	1210	1210	1210	1210	1210
7	1210	1210	1210	1210	1210
8	1210	1210	1210	1210	1210
9	1210	1210	1210	1210	1210
10	1210	1210	1210	1210	1210
11	1210	1210	1210	1210	1210
12	1210	1210	1210	1210	1210
13	1210	1210	1210	1210	1210
14	1210	1210	1210	1210	1210
15	1210	1210	1210	1210	1210
16	1210	1210	1210	1210	1210
17	1210	1210	1210	1210	1210
18	1210	1210	1210	1210	1210
19	1210	1210	1210	1210	1210
20	1210	1210	1210	1210	1210
21	1210	1210	1210	1210	1210

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DL.

BALLISTIC DATA SHEET

SHEET 2 OF 3

TEST ITEM:		PURPOSE OF TEST				ADDITIONAL COMMENTS					
1. RANGE 2. RANGE 3. RANGE 4. RANGE		1. RANGE 2. RANGE 3. RANGE 4. RANGE									
GUN		TUBE		RECOIL		TEST SITE		DATE		OBSERVERS	
103mm M45		103mm M45		103mm M45		103mm M45		103mm M45		103mm M45	
ROUND NO.		PROJECTILE		FUZE		TARGET		RANGE		TEMP. CONDITION	
TEST PROJ.		TYPE		LOT		TYPE		LOT		RESULTS	
1	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
2	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
3	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
4	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
5	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
6	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
7	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
8	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
9	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
10	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
11	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
12	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
13	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
14	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
15	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
16	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
17	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
18	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
19	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
20	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
21	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
22	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
23	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
24	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
25	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
26	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
27	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
28	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
29	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
30	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
31	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
32	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
33	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
34	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
35	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
36	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
37	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
38	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
39	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
40	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
41	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21
42	1137	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21	M45-21

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDA

BALLISTIC DATA SHEET

SHEET 2 OF 3

TEST ITEM:		PURPOSE OF TEST		ADDITIONAL COMMENTS					
MAGNUM		1. MACH RATE FUNCTIONING & PENETRATION 2. ARMING DISTANCE NEUTRALIZATION							
GUN	TUBE	PROJECTILE	LOT	TYPE	RECOIL	TEST SITE	DATE	OBSERVERS	
105mm M48	# 18567				M116A1 #747	LOCATION CAMP, MAJES. CAMP COMBAT RANGE JC-1	15-10-1967	J. J. J. / N. C. C. / P. C. C. / R. M. C. C.	
ROUND NO.	TEST PROJ.	TYPE	LOT	TYPE	FUZE	TARGET	RANGE	TEMP CONDITION	RESULTS
43	1212	M48A1	M116A1	M48A1	NO. 724	6" MACH-10"	235'	-38°F	DUO - NO PENETRATION
44	1213	M48A1	SC-1	M48A1	1213	"	"	"	COMPLETE PENETRATION
45	1214	M48A1	SC-1	M48A1	1214	"	"	"	"
46	1215	M48A1	SC-1	M48A1	1215	"	"	"	"
47	1216	M48A1	SC-1	M48A1	1216	"	"	"	"
48	1217	M48A1	SC-1	M48A1	1217	"	"	"	"
49	1218	M48A1	SC-1	M48A1	1218	"	"	"	"
50	1219	M48A1	SC-1	M48A1	1219	"	"	"	"
51	1220	M48A1	SC-1	M48A1	1220	"	"	"	"
52	1221	M48A1	SC-1	M48A1	1221	"	"	"	"
53	1222	M48A1	SC-1	M48A1	1222	"	"	"	"
54	1223	M48A1	SC-1	M48A1	1223	"	"	"	"
55	1224	M48A1	SC-1	M48A1	1224	"	"	"	"
56	1225	M48A1	SC-1	M48A1	1225	"	"	"	"
57	1226	M48A1	SC-1	M48A1	1226	"	"	"	"
58	1227	M48A1	SC-1	M48A1	1227	"	"	"	"
59	1228	M48A1	SC-1	M48A1	1228	"	"	"	"
60	1229	M48A1	SC-1	M48A1	1229	"	"	"	"
61	1230	M48A1	SC-1	M48A1	1230	"	"	"	"
62	1231	M48A1	SC-1	M48A1	1231	"	"	"	"
63	1232	M48A1	SC-1	M48A1	1232	"	"	"	"
64	1233	M48A1	SC-1	M48A1	1233	"	"	"	"
65	1234	M48A1	SC-1	M48A1	1234	"	"	"	"
66	1235	M48A1	SC-1	M48A1	1235	"	"	"	"
67	1236	M48A1	SC-1	M48A1	1236	"	"	"	"
68	1237	M48A1	SC-1	M48A1	1237	"	"	"	"
69	1238	M48A1	SC-1	M48A1	1238	"	"	"	"
70	1239	M48A1	SC-1	M48A1	1239	"	"	"	"
71	1240	M48A1	SC-1	M48A1	1240	"	"	"	"
72	1241	M48A1	SC-1	M48A1	1241	"	"	"	"
73	1242	M48A1	SC-1	M48A1	1242	"	"	"	"
74	1243	M48A1	SC-1	M48A1	1243	"	"	"	"
75	1244	M48A1	SC-1	M48A1	1244	"	"	"	"
76	1245	M48A1	SC-1	M48A1	1245	"	"	"	"
77	1246	M48A1	SC-1	M48A1	1246	"	"	"	"
78	1247	M48A1	SC-1	M48A1	1247	"	"	"	"
79	1248	M48A1	SC-1	M48A1	1248	"	"	"	"
80	1249	M48A1	SC-1	M48A1	1249	"	"	"	"
81	1250	M48A1	SC-1	M48A1	1250	"	"	"	"
82	1251	M48A1	SC-1	M48A1	1251	"	"	"	"
83	1252	M48A1	SC-1	M48A1	1252	"	"	"	"
84	1253	M48A1	SC-1	M48A1	1253	"	"	"	"
85	1254	M48A1	SC-1	M48A1	1254	"	"	"	"
86	1255	M48A1	SC-1	M48A1	1255	"	"	"	"
87	1256	M48A1	SC-1	M48A1	1256	"	"	"	"
88	1257	M48A1	SC-1	M48A1	1257	"	"	"	"
89	1258	M48A1	SC-1	M48A1	1258	"	"	"	"
90	1259	M48A1	SC-1	M48A1	1259	"	"	"	"
91	1260	M48A1	SC-1	M48A1	1260	"	"	"	"
92	1261	M48A1	SC-1	M48A1	1261	"	"	"	"
93	1262	M48A1	SC-1	M48A1	1262	"	"	"	"
94	1263	M48A1	SC-1	M48A1	1263	"	"	"	"
95	1264	M48A1	SC-1	M48A1	1264	"	"	"	"
96	1265	M48A1	SC-1	M48A1	1265	"	"	"	"
97	1266	M48A1	SC-1	M48A1	1266	"	"	"	"
98	1267	M48A1	SC-1	M48A1	1267	"	"	"	"
99	1268	M48A1	SC-1	M48A1	1268	"	"	"	"
100	1269	M48A1	SC-1	M48A1	1269	"	"	"	"
101	1270	M48A1	SC-1	M48A1	1270	"	"	"	"
102	1271	M48A1	SC-1	M48A1	1271	"	"	"	"
103	1272	M48A1	SC-1	M48A1	1272	"	"	"	"
104	1273	M48A1	SC-1	M48A1	1273	"	"	"	"
105	1274	M48A1	SC-1	M48A1	1274	"	"	"	"
106	1275	M48A1	SC-1	M48A1	1275	"	"	"	"
107	1276	M48A1	SC-1	M48A1	1276	"	"	"	"
108	1277	M48A1	SC-1	M48A1	1277	"	"	"	"
109	1278	M48A1	SC-1	M48A1	1278	"	"	"	"
110	1279	M48A1	SC-1	M48A1	1279	"	"	"	"
111	1280	M48A1	SC-1	M48A1	1280	"	"	"	"
112	1281	M48A1	SC-1	M48A1	1281	"	"	"	"
113	1282	M48A1	SC-1	M48A1	1282	"	"	"	"
114	1283	M48A1	SC-1	M48A1	1283	"	"	"	"
115	1284	M48A1	SC-1	M48A1	1284	"	"	"	"
116	1285	M48A1	SC-1	M48A1	1285	"	"	"	"
117	1286	M48A1	SC-1	M48A1	1286	"	"	"	"
118	1287	M48A1	SC-1	M48A1	1287	"	"	"	"
119	1288	M48A1	SC-1	M48A1	1288	"	"	"	"
120	1289	M48A1	SC-1	M48A1	1289	"	"	"	"
121	1290	M48A1	SC-1	M48A1	1290	"	"	"	"
122	1291	M48A1	SC-1	M48A1	1291	"	"	"	"
123	1292	M48A1	SC-1	M48A1	1292	"	"	"	"
124	1293	M48A1	SC-1	M48A1	1293	"	"	"	"
125	1294	M48A1	SC-1	M48A1	1294	"	"	"	"
126	1295	M48A1	SC-1	M48A1	1295	"	"	"	"
127	1296	M48A1	SC-1	M48A1	1296	"	"	"	"
128	1297	M48A1	SC-1	M48A1	1297	"	"	"	"
129	1298	M48A1	SC-1	M48A1	1298	"	"	"	"
130	1299	M48A1	SC-1	M48A1	1299	"	"	"	"
131	1300	M48A1	SC-1	M48A1	1300	"	"	"	"
132	1301	M48A1	SC-1	M48A1	1301	"	"	"	"
133	1302	M48A1	SC-1	M48A1	1302	"	"	"	"
134	1303	M48A1	SC-1	M48A1	1303	"	"	"	"
135	1304	M48A1	SC-1	M48A1	1304	"	"	"	"
136	1305	M48A1	SC-1	M48A1	1305	"	"	"	"
137	1306	M48A1	SC-1	M48A1	1306	"	"	"	"
138	1307	M48A1	SC-1	M48A1	1307	"	"	"	"
139	1308	M48A1	SC-1	M48A1	1308	"	"	"	"
140	1309	M48A1	SC-1	M48A1	1309	"	"	"	"
141	1310	M48A1	SC-1	M48A1	1310	"	"	"	"
142	1311	M48A1	SC-1	M48A1	1311	"	"	"	"
143	1312	M48A1	SC-1	M48A1	1312	"	"	"	"
144	1313	M48A1	SC-1	M48A1	1313	"	"	"	"
145	1314	M48A1	SC-1	M48A1	1314	"	"	"	"
146	1315	M48A1	SC-1	M48A1	1315	"	"	"	"
147	1316	M48A1	SC-1	M48A1	1316	"	"	"	"
148	1317	M48A1	SC-1	M48A1	1317	"	"	"	"
149	1318	M48A1	SC-1	M48A1	1318	"	"	"	"
150	1319	M48A1	SC-1	M48A1	1319	"	"	"	"
151	1320	M48A1	SC-1	M48A1	1320	"	"	"	"
152	1321	M48A1	SC-1	M48A1	1321	"	"	"	"
153	1322	M48A1	SC-1	M48A1	1322	"	"	"	"
154	1323	M48A1	SC-1	M48A1	1323	"	"	"	"
155	1324	M48A1	SC-1	M48A1	1324	"	"	"	"
156	1325	M48A1	SC-1	M48A1	1325	"	"	"	"
157	1326	M48A1	SC-1	M48A1	1326	"	"	"	"
158	1327	M48A1	SC-1	M48A1	1327	"	"	"	"
159	1328	M48A1	SC-1	M48A1	1328	"	"	"	"
160	1329	M48A1	SC-1	M48A1	1329	"	"	"	"
161	1330	M48A1	SC-1	M48A1	1330	"	"	"	"
162	1331	M48A1	SC-1	M48A1	1331	"	"	"	"
163	1332	M48A1	SC-1	M48A1	1332	"	"	"	"
164	1333	M48A1	SC-1	M48A1	1333	"	"	"	"
165	1334	M48A1	SC-1	M48A1	1334	"	"	"	"
166	1335	M48A1	SC-1	M48A1	1335	"	"	"	"
167	1336	M48A1	SC-1	M48A1	1336	"	"	"	"
168	1337	M48A1	SC-1	M48A1	1337	"	"	"	"
169	1338	M48A1	SC-1	M48A1	1338	"	"	"	"
170	1339	M48A1	SC-1	M48A1	1339	"	"	"	"
171	1340	M48A1	SC-1	M48A1	1340	"	"	"	"
172	1341	M48A1	SC-1	M48A1	1341	"	"	"	"
173	1342	M48A1	SC-1	M48A1	1342	"	"	"	"
174	1343	M48A1	SC-1	M48A1	1343	"	"	"	"
175	1344	M48A1	SC-1	M48A1	1344	"	"	"	"
176	1345	M48A1	SC-1	M48A1	1345	"	"	"	"
177	1346	M48A1	SC-1	M48A1	1346	"	"	"	"
178	1347	M48A1	SC-1	M48A1	1347	"	"	"	"
179	1348	M48A1	SC-1	M48A1	1348	"	"	"	"
180	1349	M48A1	SC-1	M48A1	1349	"	"	"	"
181	1350	M48A1	SC-1	M48A1	1350	"	"	"	"
182	1351	M48A1	SC-1	M48A1	1351	"	"	"	"
183	1352	M48A1	SC-1	M48A1	1352	"	"	"	"
184	1353	M48A1	SC-1	M48A1	1353	"	"	"	"
185	1354	M48A1	SC-1	M48A1	1354	"	"	"	"
186	1355	M48A1	SC-1	M48A1	1355	"	"	"	"
187	1356	M48A1	SC-1	M48A1	1356	"	"	"	"
188	1357	M48A1	SC-1	M48A1	1357	"	"	"	"
189	1358	M48A1	SC-1	M48A1	1358	"	"	"	"
190	1359	M48A1	SC-1	M48A1	1359	"	"	"	"
191	1360	M48A1	SC-1	M48A1	1360	"	"	"	"
192	1361	M48A1	SC-1	M48A1	1361	"	"	"	"
193	1362	M48A1	SC-1	M48A1	1362	"	"	"	"
194	1363	M48A1	SC-1	M48A1	1363	"	"	"	"
195	1364	M48A1	SC-1	M48A1	1364	"	"	"	"
196	1365	M48A1	SC-1	M48A1	1365	"	"	"	"
197	1366	M48A1	SC-1	M48A1	1366	"	"	"	"
198	1367	M48A1	SC-1	M48A1	1367	"	"	"	"
199	1368	M48A1	SC-1	M48A1	1368	"	"	"	"
200	1369	M48A1	SC-1	M48A1	1369	"	"	"	"
201	1370	M48A1	SC-1	M48A1	1370	"			

- BALLISTIC DATA SHEET
TABLE V

SHEET 1 OF 2

TEST ITEM:		PURPOSE OF TEST		ADDITIONAL COMMENTS				
FUSE, C109, M508A1E1		COMPARE PERFORMANCE OF 105MM M508A1E1/FRANIS CARTRIDGES WITH M508A1E1 AND M508A1 FUSES.						
GUN	TUBE	RECOIL	TEST SITE	DATE 12-15 DEC. 77	OBSERVERS			
105mm NLB	410567	M116A, 4747	LOCATION CAMP, MISS CAMP EQUIPMENTS RANGE 3-1	PROJ. NO. _____ DATA BOOK NO. _____ TASK & ASSIGNMENT: _____	NAME/US JOURNAL PROOF OFFICER R. WOODMAN			
ROUND NO.	PROJECTILE	LOT	TYPE	FUZE	TEMP CONDITION	RANGE	TARGET	RESULTS
1	M508A1E1	M48-71X600	M508A1E1	WIT-775018	+13.5°	2001	4' ARMED	FUNCTIONING, COMPLETE BUNT
2	1817	E042		E002			8 60° 08L	" " "
3	1813							DUD, NO FUNCTIONING
4	1802							FUNCTIONING, COMPLETE BUNT
5	1814							DUD, NO FUNCTIONING
6	1816							FUNCTIONING, COMPLETE BUNT
7	1807							DUD, NO FUNCTIONING
8	1811							FUNCTIONING, COMPLETE BUNT
9	1808							" " "
10	1815							FUNCTIONING, DISTAL W/ BULGE
11	M508A1E1	M48-71X600	M508A1E1	WIT 14-11				COMPLETE BUNT
12	1817	E047						" " "
13	1817							" " "
14	1816							" PARTIAL W/ BULGE
15	1801							" " "
16	1815							" " "
17	M508A1E1	M48-71X600	M508A1E1	WIT-775018				COMPLETE BUNT
18	1805	E043						DISTAL W/ BULGE
19	1811	M48-71X600	M508A1E1	WIT 14-11				COMPLETE BUNT
20	1810	E047						COMPLETE BUNT
21	1819							" DISTAL W/ BULGE

THIS PAGE IS BEST QUALITY
FROM COPY FURNISHED TO DEC

1/14

1/13

[illegible]

TABLE VI

M69 DETONATOR INVESTIGATION TESTS

1. M69 Detonator (Lot AM2-3-4) Functioning

100 Detonators:

Air Gun Test: 35,000 g's
Resistance: All between 1000 - 10,000 Ω
X-ray: No visible defects
Function: 98/100 functioned properly, 2 duds

2. M59 Detonator Functioning from M530A1 Fuze Lot AKT 3-2

a. 60 Detonators:

Function: 60/60 functioned properly

b. 60 Detonators:

Air Gun Test: 35,000 g's
Resistance: 9/10 between 1,000 - 10,000 Ω
Function: 59/60 functioned properly, 1 dud

3. M69 Detonator (Lot AM2-3-4) Reconsolidation and Functioning

a. 10 Detonators:

Reconsolidation: 13,000 psi
Resistance: 9/10 between 1,000 - 10,000 Ω
1 open circuited and rejected
Function: 9/9 functioned properly

b. 90 Detonators:

Reconsolidation: 13,000 psi
Length Reduction: .006"-.019", avg .013"
X-ray: No Visible defects
Resistance: All between 1,000 - 10,000 Ω
Air Gun Test: 35,000 g's
Resistance: All between 1,000 - 10,000 Ω
Function: 90/90 functioned properly

• BALLISTIC DATA SHEET TABLE VII

SHEET 1 OF 2

TEST ITEM:		PURPOSE OF TEST		ADDITIONAL COMMENTS						
M68 100mm		EVALUATE MODIFIED M68 EXTENDING RAC RAC ELIMINATION OF CHOS IN ADVANCE FIVE								
GUN	TUBE	RECOIL	TEST SITE	DATE	OBSERVERS					
M68 100mm	4.244"	M114 8147	LOCATION COMBATANT CAMP RANGE 5-2	PROJ. NO. _____ DATA BODY NO. _____ TASK & AMEND. NO. _____	Amesbury PROF. OTHER K. Nussan					
ROUND NO.	PROJECTILE	LOT	TYPE	FUZE	TYPE	LOT	TARGET	RANGE	TEMP. CONDITION	RESULTS
1376	Q. 8. 100mm M68-1	M68-1	M68-1	M68-1	M68-1	M68-1	6" RANGE	40'	40'	40'
1377	Q. 8. 100mm M68-1	M68-1	M68-1	M68-1	M68-1	M68-1	6" RANGE	40'	40'	40'
1378	Q. 8. 100mm M68-1	M68-1	M68-1	M68-1	M68-1	M68-1	6" RANGE	40'	40'	40'
1379	Q. 8. 100mm M68-1	M68-1	M68-1	M68-1	M68-1	M68-1	6" RANGE	40'	40'	40'
1380	Q. 8. 100mm M68-1	M68-1	M68-1	M68-1	M68-1	M68-1	6" RANGE	40'	40'	40'
1381	Q. 8. 100mm M68-1	M68-1	M68-1	M68-1	M68-1	M68-1	6" RANGE	40'	40'	40'
1382	Q. 8. 100mm M68-1	M68-1	M68-1	M68-1	M68-1	M68-1	6" RANGE	40'	40'	40'
1383	Q. 8. 100mm M68-1	M68-1	M68-1	M68-1	M68-1	M68-1	6" RANGE	40'	40'	40'
1384	Q. 8. 100mm M68-1	M68-1	M68-1	M68-1	M68-1	M68-1	6" RANGE	40'	40'	40'
1385	Q. 8. 100mm M68-1	M68-1	M68-1	M68-1	M68-1	M68-1	6" RANGE	40'	40'	40'
1386	Q. 8. 100mm M68-1	M68-1	M68-1	M68-1	M68-1	M68-1	6" RANGE	40'	40'	40'
1387	Q. 8. 100mm M68-1	M68-1	M68-1	M68-1	M68-1	M68-1	6" RANGE	40'	40'	40'
1388	Q. 8. 100mm M68-1	M68-1	M68-1	M68-1	M68-1	M68-1	6" RANGE	40'	40'	40'
1389	Q. 8. 100mm M68-1	M68-1	M68-1	M68-1	M68-1	M68-1	6" RANGE	40'	40'	40'
1390	Q. 8. 100mm M68-1	M68-1	M68-1	M68-1	M68-1	M68-1	6" RANGE	40'	40'	40'
1391	Q. 8. 100mm M68-1	M68-1	M68-1	M68-1	M68-1	M68-1	6" RANGE	40'	40'	40'
1392	Q. 8. 100mm M68-1	M68-1	M68-1	M68-1	M68-1	M68-1	6" RANGE	40'	40'	40'
1393	Q. 8. 100mm M68-1	M68-1	M68-1	M68-1	M68-1	M68-1	6" RANGE	40'	40'	40'
1394	Q. 8. 100mm M68-1	M68-1	M68-1	M68-1	M68-1	M68-1	6" RANGE	40'	40'	40'
1395	Q. 8. 100mm M68-1	M68-1	M68-1	M68-1	M68-1	M68-1	6" RANGE	40'	40'	40'
1396	Q. 8. 100mm M68-1	M68-1	M68-1	M68-1	M68-1	M68-1	6" RANGE	40'	40'	40'

THIS PAGE IS BEST QUALITY PRACTICALLY
FROM COPY FURNISHED TO DDC

SHEET 7 OF 2

TEST ITEM:		PURPOSE OF TEST		ADDITIONAL COMMENTS	
FUSE, M65A1		EVALUATE PROPOSED M65 DETONATOR FOR EXAMINATION ON DOTS IN MEASUREMENT			
GUN	TUBE	RECOIL	TEST SITE	DATE	OBSERVERS
M59A1 M65	M214B7	M16A 4747	LOCATION Camp 5003 RANGE 5-2	PROJ. NO. DATA BOOK NO. TASK & AMEND. NO.	Observer: [Signature] Proof Officer: [Signature]
ROUND NO.	PROJECTILE	FUZE		TEMP	RESULTS
TEST PROJ.	TYPE	LOT	TYPE	CONDITION	
1351	M59A1	M59A1	M59A1	400	Complete
1352	M59A1	M59A1	M59A1	400	"
1353	M59A1	M59A1	M59A1	400	"
1354	M59A1	M59A1	M59A1	400	"
1355	M59A1	M59A1	M59A1	400	"
1356	M59A1	M59A1	M59A1	400	"
1357	M59A1	M59A1	M59A1	400	"
1358	M59A1	M59A1	M59A1	400	"
1359	M59A1	M59A1	M59A1	400	"
1360	M59A1	M59A1	M59A1	400	"
1361	M59A1	M59A1	M59A1	400	"
1362	M59A1	M59A1	M59A1	400	"
1363	M59A1	M59A1	M59A1	400	"
1364	M59A1	M59A1	M59A1	400	"
1365	M59A1	M59A1	M59A1	400	"
1366	M59A1	M59A1	M59A1	400	"
1367	M59A1	M59A1	M59A1	400	"
1368	M59A1	M59A1	M59A1	400	"
1369	M59A1	M59A1	M59A1	400	"
1370	M59A1	M59A1	M59A1	400	"
1371	M59A1	M59A1	M59A1	400	"
1372	M59A1	M59A1	M59A1	400	"
1373	M59A1	M59A1	M59A1	400	"
1374	M59A1	M59A1	M59A1	400	"
1375	M59A1	M59A1	M59A1	400	"
1376	M59A1	M59A1	M59A1	400	"
1377	M59A1	M59A1	M59A1	400	"
1378	M59A1	M59A1	M59A1	400	"
1379	M59A1	M59A1	M59A1	400	"
1380	M59A1	M59A1	M59A1	400	"
1381	M59A1	M59A1	M59A1	400	"
1382	M59A1	M59A1	M59A1	400	"
1383	M59A1	M59A1	M59A1	400	"
1384	M59A1	M59A1	M59A1	400	"
1385	M59A1	M59A1	M59A1	400	"
1386	M59A1	M59A1	M59A1	400	"
1387	M59A1	M59A1	M59A1	400	"
1388	M59A1	M59A1	M59A1	400	"
1389	M59A1	M59A1	M59A1	400	"
1390	M59A1	M59A1	M59A1	400	"
1391	M59A1	M59A1	M59A1	400	"
1392	M59A1	M59A1	M59A1	400	"
1393	M59A1	M59A1	M59A1	400	"
1394	M59A1	M59A1	M59A1	400	"
1395	M59A1	M59A1	M59A1	400	"
1396	M59A1	M59A1	M59A1	400	"
1397	M59A1	M59A1	M59A1	400	"
1398	M59A1	M59A1	M59A1	400	"
1399	M59A1	M59A1	M59A1	400	"
1400	M59A1	M59A1	M59A1	400	"

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

IX. REFERENCES

1. Technical Memorandum ORDBB-DR2-59, "Investigation of M509E6, PIBD Fuze in Relation to Malfunction of T300E56, 90mm HEAT-T and T384E2 105mm Heat Cartridge", dated March 1962.
2. Product Improvement Proposal GG67630, Fuze, PIBD, M509A1E2 Safety and Reliability.

X. DISTRIBUTION LIST

Commander	Copy No.
US Army Armament Materiel Readiness Command	
ATTN: DRSAR-ASR	1-2
DRSAR-LE	3
DRSAR-QAM	4-5
DRSAR-PCA-F	6
Rock Island, IL 61201	
Commander	
US Army Armament Research & Development Command	
ATTN: DRDAR-LCR	6-17
DRDAR-LCA	18-19
DRDAR-LCE	20-23
DRDAR-LCM	24
DRDAR-LCF	25-27
DRDAR-LCU	28
DRDAR-TSS	29-33
Dover, NJ 07801	
Defense Documentation Center	34-45
Cameron Station	
Alexandria, VA 22314	
Commander	
US Army Test & Evaluation Command	
ATTN: AMSTE	46
Aberdeen Proving Ground, MD 21005	
Commander	
Harry Diamond Laboratories	
ATTN: Library	47
Washington, DC 20438	