

AD-A064 026

GAI CONSULTANTS INC MONROEVILLE PA
NATIONAL DAM INSPECTION PROGRAM. TWO LICK CREEK DAM (NDI PA-285--ETC(U)
AUG 78


F/G 13/2
DACW31-78-C-0052

NL

UNCLASSIFIED

1 OF 1
AD
A0 64 026





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

LEVEL II

1

OHIO RIVER BASIN
TWO LICK CREEK, INDIANA COUNTY

PENNSYLVANIA

TWO LICK CREEK DAM

NDI No. Pa. - 285

DISTRIBUTION STATEMENT A

Approved for public release;
Distribution Unlimited

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM.

Two Lick Creek Dam (NDI PA-285), Ohio
River Basin, Two Lick Creek, Indiana
County, Pennsylvania. Phase I Inspection
Report.

AD A 0 6 4 0 2 6

DDC FILE COPY

15) DACW31-78-C-0052
PREPARED FOR

DEPARTMENT OF THE ARMY
Baltimore District, Corps of Engineers
Baltimore, Maryland 21203

PREPARED BY

GAI CONSULTANTS, INC.
570 BEATTY ROAD
MONROEVILLE, PENNSYLVANIA 15146

DDC
RECEIVED
FEB 1 1979
R
L
L
L
L
L

12) 85p.

11) AUG 1978

70 01 17 09 1 411 002 LB 115

PHASE I REPORT
National Dam Inspection Program

LEVEL II **1**

Two Lick Creek Dam
Pennsylvania
Indiana County
Two Lick Creek Dam
11 August 1978

Inspection Team - GAI Consultants, Inc.
570 Beatty Road
Monroeville, Pennsylvania 15146
Contract No. DACW31-78-C-0052 ✓

ACCESSION FOR	
DTIC	Write Section <input checked="" type="checkbox"/>
DDC	DDC Section <input type="checkbox"/>
ORANNCUNDES	<input type="checkbox"/>
JUSTIFICATION	
Yes DDC Form 90	
BY on file	
DISTRIBUTION/AVAILABILITY CODES	
DIST.	AVAIL. and/or SPECIAL
A	

Based on a visual inspection, past performance, available engineering data, and discussions with a representative of the owner, the facility is considered to be in good condition. The primary spillway is capable of passing the flow resulting from a storm of PMF intensity without overtopping the embankment. As a result, the spillway is deemed adequate.

It is recommended that the owner:

- a. Immediately remove the embankment overgrowth.
- b. Investigate the durability and suitability of the riprap and quarry run rockfill. Conclusions relative to its suitability should be developed and remedial measures taken if necessary.
- c. Drain the water from the toe of the dam and provide positive drainage away from the embankment.
- d. Repair damage to the right abutment downstream of the emergency spillway.
- e. Establish a formal maintenance program.
- f. Develop a formal warning system to provide for the safe evacuation of downstream residents should the need arise.
- g. Establish a program to have the facility inspected on an annual basis by a registered professional engineer to check for the development of hazardous conditions.

DISTRIBUTION STATEMENT A
Approved for public release;
Distribution Unlimited

79 01 17 094
i

GAI Consultants, Inc.

Approved by:

Bernard M. Mihalcin
Bernard M. Mihalcin, P.E.


G. K. Withers
G. K. WITHERS
Colonel, Corps of Engineers
District Engineer



Date 13 Sept 78

Date 22 Sep 78

DDC
RECEIVED
FEB 1 1979
D



Overview Photograph of Two Lick Creek Dam

TABLE OF CONTENTS

	<u>Page</u>
SYNOPSIS	i
OVERVIEW PHOTOGRAPH	iii
TABLE OF CONTENTS	iv
SECTION 1 - GENERAL INFORMATION	1
1.0 Authority	1
1.1 Purpose	1
1.2 Description of Project	1
1.3 Pertinent Data	2
SECTION 2 - ENGINEERING DATA	6
2.1 Design Data	6
2.2 Construction Records	9
2.3 Operational Records	9
2.4 Other Investigations	9
2.5 Evaluation	9
SECTION 3 - VISUAL INSPECTION	10
3.1 Observations	10
3.2 Evaluation	12
SECTION 4 - OPERATIONAL PROCEDURES	13
4.1 Normal Operating Procedure	13
4.2 Maintenance of Dam	13
4.3 Maintenance of Operating Facilities	13
4.4 Warning Systems in Effect	13
4.5 Evaluation	13
SECTION 5 - HYDROLOGIC/HYDRAULIC EVALUATION	14
5.1 Design Data	14
5.2 Experience Data	14
5.3 Visual Observations	15
5.4 Overtopping Potential	15
5.5 Spillway Adequacy	15
SECTION 6 - EVALUATION OF STRUCTURAL INTEGRITY	17
6.1 Visual Observations	17
6.2 Design and Construction Techniques	18
6.3 Past Performance	18
6.4 Seismic Stability	18

TABLE OF CONTENTS

	<u>Page</u>
SECTION 7 - ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES	19
7.1 Dam Assessment	19
7.2 Recommendations/Remedial Measures	19
APPENDIX A - CHECK LIST - VISUAL INSPECTION	
APPENDIX B - CHECK LIST - ENGINEERING DATA	
APPENDIX C - HYDRAULICS AND HYDROLOGY CALCULATIONS	
APPENDIX D - PHOTOGRAPHS	
APPENDIX E - GEOLOGY	
APPENDIX F - FIGURES	
APPENDIX G - REGIONAL VICINITY MAP	

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM
TWO LICK CREEK DAM
NDI# PA-285, PENNDER# 32-75

1.0 Authority.

The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.

~~1.1~~ Purpose.

The purpose is to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project.

a. Dam and Appurtenances. Two Lick Creek Dam is a combination concrete gravity and earth- rockfill embankment. It is approximately 1,200 feet long with a maximum height of 115 feet. The right side of the structure is a concrete gravity dam with six concrete ogee-shaped overflow spillway bays. The three bays located nearest to the right abutment (defined as Bays 1, 2, and 3 of this report) are uncontrolled and function as the emergency spillway. The three bays located to the left of the emergency spillway (defined as Bays 4, 5, and 6 of this report) are equipped with mechanically operated radial gates. These bays function as the primary spillway with crests 33.5 feet lower than the crests of the emergency spillway. In addition, the facility is equipped with a discharge tunnel (concrete box culvert type) located to the right of the junction between the concrete and earth- rockfill sections of the structure. The left side of the structure is an earth- rockfill embankment which wraps around the left extremity of the concrete dam (see Figure 1, Appendix F).

b. Location. Two Lick Creek Dam is located on Two Lick Creek in White Township, approximately 3 miles southeast of the Borough of Indiana, Pennsylvania. U. S. Route 422 is constructed approximately parallel to the reservoir and is less than 1/2 mile south of the embankment at its closest point. The dam, reservoir, and watershed are contained within Barnesboro, Brush Valley, Clymer, Commodore, Marion Center, Rochester Mills, and Strongstown U.S.G.S. 7.5 minute quadrangles (see Appendix G). The coordinates of the dam are N40° 35' 30" and W79° 6.0' 0".

c. Size Classification. Large (115 feet high, 16,200 acre-feet capacity at design pool elevation 1183).

d. Hazard Classification. High (see Section 3.1.c.5).

e. Ownership. New York State Electric and Gas Corporation, Binghamton, New York. Pennsylvania Electric Company, Johnstown, Pennsylvania.

f. Purpose of Dam. Water supply for the Homer City generating station.

g. Historical Data. The facility was designed by Gilbert Associates, Inc., of Reading, Pennsylvania. Construction began in the spring of 1967 and was completed by December of 1968. The dam was built in conjunction with the Homer City Generating Station. Both facilities are jointly owned by the New York State Electric and Gas Corporation of Binghamton, New York, and the Pennsylvania Electric Company of Johnstown, Pennsylvania. Monthly construction progress reports were prepared by Bechtel Corporation of San Francisco, California, acting as construction managers for the project. These reports indicate the project was completed in general accordance with the preliminary schedule and apparently without a major problem.

In July 1977, a storm caused damage to the right abutment downstream of the emergency spillway. Subsequently, the facility was inspected by Gilbert Associates, Inc., and Penelec personnel. A copy of the report detailing their findings is available from Penelec files.

No PennDER inspection reports have been filed on this facility since construction.

1.3 Pertinent Data.

a. Drainage Area. 74 square miles.

b. Discharge at Dam Site. Discharge data is compiled daily at this facility. Conversations with Mr. Gallus of Pennsylvania Electric Company indicate that the maximum flood at this facility occurred on July 20, 1977. An investigation by Gilbert Associates, Inc., subsequent to the flood revealed that maximum high water reached approximately one foot over the emergency spillway (400 cfs). The extent of the opening of each gate is believed to have been approximately two feet. Therefore, the total discharge is estimated to have been 6,000 cfs.

Outlet Works Conduit at Operating Pool Elevation -
Discharge curve not available.

Primary Spillway Capacity at Maximum Gate Opening \approx
62,500 cfs (reservoir level at 1183).

c. Elevation (feet above mean sea level).

Top of Dam - 1195.

Maximum Pool Design Surcharge - 1185.

Maximum Pool of Record \approx 1185.5.

Normal Pool - 1183.

Upstream Portal Invert Outlet Conduit - 1107.5.

Downstream Portal Invert Outlet Conduit - 1105.

Streambed at Centerline of Dam \approx 1105.

Maximum Tailwater - Not known.

d. Reservoir Length (miles).

Maximum Design Pool \approx 5.3 (elevation 1185).

Normal Pool \approx 5.0 (elevation 1183).

Top of Dam \approx 6.7 (elevation 1195).

e. Storage (acre-feet).

Maximum Design Pool \approx 17,000 (elevation 1185).

Normal Pool \approx 16,200 (elevation 1183).

Top of Dam \approx 23,000 (elevation 1195).

f. Reservoir Surface (acres).

Maximum Design Pool \approx 525 (elevation 1185).

Normal Pool \approx 510 (elevation 1183).

Top of Dam \approx 650 (elevation 1195).

g. Dam.

Type - Combination concrete gravity and earth-
rockfill.

Length \approx 1,200 feet.

Height \approx 115 feet.

Top Width - 40 feet.

Side Slopes (earth- rockfill section -
upstream 1.5H:1V
downstream 1.5H:1V

Zoning - See Figures 6 and 7, (Appendix F).

Impervious Core - Figures 6 and 7, Appendix F, indicate the embankment is constructed with an impervious central core of varying cross-section.

Cutoff - A cutoff trench was reportedly extended into sound rock. The bottom width of the cutoff trench is 20 feet.

Grout Curtain - Contract drawings indicate a grout curtain in the center of the cutoff trench under the embankment section of the dam and upstream from the concrete gravity and spillway sections of the dam. The design report indicates the grout curtain was extended to a depth of approximately 80 feet across the valley, and into the abutment to a distance and depth sufficient to minimize appreciable water movement (see Figure 5, Appendix F).

h. Outlet Conduit.

Type - Contract drawings indicate that the discharge tunnel outlet is a 12-foot high by 14-foot wide concrete box type conduit. The conduit has intakes located at three different elevations along the structure. Flow is controlled by mechanical gates operated from within the structure. Two manually operated emergency gates are located atop the dam crest and enable the conduit to be sealed off so that the mechanical gates can be serviced.

Length \approx Approximately 420 feet.

Closure - Gate valves at elevations 1165, 1145, and 1125. Manual emergency slide gates are controlled from atop the dam crest.

Access - The gate valves are accessible by chambers through the interior of the structure. The emergency slide gates are directly accessible at the crest.

Regulating Facilities - Gate valves, mechanically operated. A low level release with intake elevation 1107.5 located in the discharge tunnel provides emergency drawdown capabilities. This release is apparently regulated at the downstream end of the discharge tunnel. (see Figure 9, Appendix F).

i. Spillway.

Type (primary) - Three 30-foot wide overflow spillway bays with concrete ogee-shaped weirs. Mechanically operated 30-foot wide by 32-foot high radial gates regulate discharge.

Weir Length - 90 feet.

Crest Elevation - 1151.

Upstream Channel - Not applicable.

Downstream Channel - The primary spillway discharges into a spillway bucket before entering the natural downstream channel. A dike has been constructed to the left of the natural channel to divert flow away from the embankment toe (see Figure 1, Appendix F).

Type (emergency) - Three 34-foot wide ungated overflow spillway bays with concrete ogee-shaped weirs.

Weir Length - 102 feet.

Crest Elevation - 1184.5.

Upstream Channel - Available drawings indicate the emergency spillway bays have individual approach channels cut into rock on the right abutment (see Figure 1, Appendix F).

Downstream Channel - The emergency spillway bays discharge over a rock cliff on the right abutment before entering the natural downstream drainage as shown on Photograph 11, Appendix D.

j. Regulating Outlets. Flow through the concrete box-type discharge tunnel is mechanically regulated with intakes at elevations 1165, 1145, and 1125. In addition, the drawings indicate a low level release conduit which can apparently be utilized to draw down the reservoir.

SECTION 2
ENGINEERING DATA

2.1 Design Data.

a. Design Data Availability and Sources.

1. Hydrology and Hydraulics. A report prepared by Gilbert Associates, Inc., entitled, "Report No. 1637, Design of Two Lick Creek Dam, Volume I, Design Report, December 15, 1966," contains a synopsis of the hydrology and hydraulics considered for this project. Included are low flow and flood flow hydrology along with spillway design criteria. The report is available from PennDER files. Design calculations are not included.

2. Embankment. Information available relative to the embankment design includes boring logs, foundation and borrow investigations (Volume II, Design Report), and a soils report (Volume III, Design Report). In addition, Volume I of the design report (see 1 above) includes a synopsis of the overall embankment design. Results of the stability analysis are shown on Figure 7 (see Appendix F). This information is available from the Pennsylvania Electric Company, Johnstown, Pennsylvania.

3. Appurtenant Structures. The only design information available pertaining to the appurtenant structures of the facility is contained within Volume I of the design report (see 1 above). No design calculations were obtained.

b. Design Features.

1. Embankment. Design drawings indicate the left side of the embankment is a zoned earth-rockfill structure. It is constructed on a 1.5H on 1V upstream slope and a 1.5H on 1V downstream slope. The outer slopes are composed of riprap and quarry run rockfill. Two 15-foot berms are provided on both the upstream and downstream slopes of the embankment. A sand filter layer is provided immediately beneath the outer rock layers. The filter zones bound the random rolled fill zone on the upstream side of the embankment and the impervious core on the downstream side of the embankment and the impervious core on the upstream side of the structure (see Figure 6, Appendix F).

A 20-foot wide (bottom width) cutoff trench was excavated beneath the impervious core. A grout cap forms the bottom of the cutoff trench beneath the embankment section. The grout curtain is approximately 80 feet deep and extends into the abutments.

The concrete non-overflow portion of the dam consists of Blocks 1, 2, 10, 11, 12, and 13. The minimum top width is 12 feet and the back slope is 0.7 on 1.0 (see Figure 9, Appendix F).

Typically, the concrete section, including the spillway, has a 4.5-foot wide drainage and inspection gallery with a floor elevation of 1130 and a top elevation of 1138. An 18-inch wide gutter, of varying depth is provided at the upstream face of the gallery. Uplift relief drains discharge into this gutter.

Blocks 1 and 2 are straight sections, 12 feet wide, which are primarily abutment connection blocks.

Block 10 has a design height of 68 feet, with a 12-foot top width and with the standard 0.7H on 1V back slope.

Block 11 has a design height of 75 feet, with a nominal top width of 18 feet. A 5-foot wide cantilevered deck is provided upstream of access and installation space for the slide gate hoists. In addition to the drainage and inspection gallery, Block 11 contains access galleries to each of the two higher level water release valves, discharge galleries of the water control system and a stairway connecting the lower level valve access gallery with the inspection and drainage gallery.

Block 12 has a design height of 95 feet, with a top width of 15 feet. The control building is located on the downstream face of Block 12. Block 12 contains the discharge tunnel. The lower 20 feet of this block lies within a trench excavated into sound rock and is restrained on three sides. The lower level water release valves, the low level control room, the discharge gallery, stairs connecting the upper and lower valve access galleries, and an access gallery into the control building are located in Block 12. Sump dewatering is also done from Block 12.

Block 13 has a design height of 90 feet, with a top width of 12 feet. A 6-foot equipment shaft is provided in Block 13 from the top of the dam to the inspection and drainage gallery. Exterior mounted stairs run down the back faces of Blocks 12 and 13 from the top of the dam to the control building. The primary point of design interest of Block 13 is that the impervious fill of the adjoining embankment wraps around the upstream and downstream faces to form a complete water barrier. All faces of Block 13, except where it adjoins Block 12, form a sloped surface for contact with earth.

2. Appurtenant Structures.

a) Primary Spillway. The primary spillway (Bays 4, 5, and 6) was designed with 30-foot wide bays and a crest at elevation 1151. Control is provided by three motor-operated radial gates (see Figures 9, 10, and 11, Appendix F).

b) Emergency Spillway. The emergency spillway (Bays 1, 2, and 3) was designed to be an uncontrolled discharge outlet. The three bays are equipped with concrete ogee-shaped weirs with crest elevations at 1184.5 (see Figure 9, Appendix F).

c) Outlet Conduit. The discharge tunnel outlet is a 12-foot high by 18-foot wide concrete box-type conduit. It is equipped with intakes at three different elevations. These intakes form what is known as the water control system at the facility.

d) Water Control System. The controlled water release system, to furnish make-up water to the power station cooling towers, is located in Blocks 11 and 12. Three individual motor control releases are provided, each at a different elevation, in order to take advantage of differences in chemical quality at different depths in the reservoir. The releases are located at elevation 1165, elevation 1145, and elevation 1125. An emergency, manual release (low level outlet) is located at elevation 1107.5 (see Figure 9, Appendix F, and Section 1.3.J).

c. Design Data.

1. Hydrology and Hydraulics. (see Section 5.1).

2. Embankment. The determining factors in design of the embankment section were availability of materials, and foundation conditions. The design was based on the geologic conditions (Vol. II of the design report) and the laboratory results of the subsurface exploration program (Vol. III of the design report).

Slope stability was performed with an IBM 1620 computer program, utilizing a modified Swedish circle method. Full consideration for saturated and submerged conditions are written into the program. The results obtained by this method are conservative. Nominal factors of safety were the desired results, since conservative soil strengths and method of analysis were used. For final analysis, 24 complete cases were run, many with varying strengths of earth-fill. The results are shown on Figure 7, Appendix F, and are representative of the minimum factors of safety obtained.

The stability of various sections of the concrete structure were analyzed separately. The results are shown on Figure 4, Appendix F.

2.2 Construction Records.

Construction records including weekly status reports, photographs, and memoranda are available in PennDER files.

2.3 Operational Records.

The daily operation of the facility is monitored and recorded continuously at the control room located on the downstream face of Block 12.

2.4 Other Investigations.

Following the flood of July 20, 1977, both the Pennsylvania Electric Company and Gilbert Associates, Inc., conducted separate investigations to review the extent of damage to the facility and its appurtenances. The results of the investigations are available from the Pennsylvania Electric Company.

2.5 Evaluation.

Engineering data were provided by the Pennsylvania Department of Environmental Resources (PennDER) and the Pennsylvania Electric Company. Sufficient data are available to indicate the structure was formally engineered in accordance with accepted modern engineering practice.

SECTION 3
VISUAL INSPECTION

3.1 Observations.

a. General. The general appearance of this project indicates the dam and its appurtenances are currently in good condition. The features which have been incorporated into its design further indicate that the facility was formally engineered in accordance with modern practice.

b. Embankment.

1. Earth- Rockfill Section. The earthen portion of the embankment is in fair condition. No seepage is evident through the embankment or abutments. The embankment is well aligned and no appreciable crest settlement was detected at the time of inspection. Three deficiencies were noted: 1) The upstream and downstream slopes are heavily overgrown. Sizeable trees (6-inch diameter) whose growth have apparently remained unchecked for a number of years are visible over the entire embankment (see Photograph 2, Appendix D); 2) The riprap and quarry run rockfill placed on both the upstream and downstream slopes may be less resistant than intended although specifications were not available which would permit an accurate evaluation of its suitability (see Photograph 9, Appendix D); and 3) The entire length of the earth embankment toe is submerged by a standing pool of water (see Photograph 10, Appendix D). The somewhat triangular shaped pool is impounded by the embankment, the left abutment, and an earth dike located parallel to the discharge channel. Available design drawings reviewed prior to the inspection indicate a 24-inch diameter drain pipe is located through the downstream end of the earth dike. The pipe was not located by the inspection team. Furthermore, the owner apparently has no knowledge of its existence. It was assumed that this pipe is either clogged or non-existent.

2. Non-Overflow Concrete Section. The non-overflow portion of the concrete gravity embankment is in good condition. Several isolated areas of minor cracking and spalling are visible upon close inspection but these are not considered significant. The control room and interior inspection galleries are in good condition. These areas are well maintained. Some condensation is visible on the gallery ceilings and efflorescence is visible at construction joints in several areas. With the exception of one gate valve currently under repair, the operating mechanisms and monitoring systems appear to be in excellent condition. Similarly, the mechanical winch system located atop the crest also appears to be in working order although it was not operated in our presence.

c. Appurtenant Structures.

1. Primary Spillway. The primary spillway bays (Bays 4, 5, and 6) are in good condition. The three radial gates were in a fully closed position during the inspection and were not operated in the presence of the inspection team. A small amount of water was issuing from Bays 5 and 6 indicating an imperfect seal between the spillway gates and wingwall. The mechanical system, including the gates and winches, appeared to be in good condition and are reported to be in proper operating order. Minor spalling and scaling were visible on the surfaces of the ogee-shaped weirs, particularly at the construction joints. The spillway apron is deteriorated in some areas, possibly due to etching action acidic outflow associated with mine drainage.

2. Emergency Spillway. The emergency spillway bays (Bays 1, 2, and 3) are in excellent condition. No signs of concrete deterioration or discoloration were visible. The emergency spillway bays have reportedly discharged only once; during the area flood of July 20, 1977.

3. Outlet Conduit. The outlet conduit appeared to be functioning properly during the inspection. The majority of the conduit is not accessible for inspection; consequently, its overall condition was not ascertainable. The only portion visible to the inspection team was the discharge end. At this point, flow through the conduit is automatically measured and recorded in the control room.

4. Reservoir Area. The general area surrounding the reservoir is characterized by moderate to steep slopes. The area is primarily wooded although a few isolated cleared sections are visible along the shore (see Photograph 5, Appendix D).

5. Downstream Channel. The downstream area considered in this section extends left from the emergency spillway bays at the right abutment to the channel immediately beyond the discharge end of the outlet conduit. For the most part, the downstream channel is in good condition. The channel floor is predominantly a durable sandstone. What appears to be to an excess of loose rocks and boulders are scattered over the downstream area (see Photograph 1, Appendix D). At the present time, however, flow does not appear to be obstructed. It is noted that revised Drawing C-726-412, Exhibit 16, by Gilbert Associates, Inc., (see Figure 8, Appendix F) shows an earth dike (top elevation 1125.0) across the downstream channel perpendicular to the flow located at a point approximately 50 yards beyond the spillway crests. The owner's representative indicated that the dike depicted in this drawing was a temporary structure that was removed prior to project completion.

The portion of the downstream channel which is not in good condition is that area immediately beyond the emergency spillway (Bays 1, 2, and 3). Significant erosional damage occurred as a result of the July 1977, flood (see Photographs 11 and 12, Appendix D). The area, nevertheless, appears sound in spite of the damage. All concrete sections of the embankment remained intact.

A small water works serving Indiana, Pennsylvania, is located approximately 1-1/2 miles downstream of the dam. The facility is situated on the Two Lick Creek floodplain and is undoubtedly in an area that would be affected by a breach of the dam. The communities of Upper Two Lick and Homer City located 3-1/2 and 8 miles, respectively, downstream of the dam contain residences that could easily be affected by a breach of the dam. A conservative estimate of the number of persons that reside within the influence of the flood waters from Two Lick Creek Dam would exceed 100.

Because of the above mentioned considerations the facility was given a "high" hazard rating.

3.2 Evaluation.

The facility has several deficiencies which require attention. These deficiencies include overgrowth of the embankment, apparent poor quality riprap and rockfill, lack of proper drainage at the toe, and an erosion problem downstream of the emergency spillway.

It must be noted that the owner is knowledgeable of the overall condition of the facility and that some of the above mentioned items were scheduled for remedial service prior to our inspection.

SECTION 4
OPERATIONAL PROCEDURES

4.1 Normal Operational Procedures.

According to the owner's representative, the spillway gates at the facility are operated in accordance with the operational procedure presented in Volume I of the design report. However, the system is no longer automatic as originally designed and is now manually operated by on-site personnel.

The water control system, which regulates flow through the discharge tunnel, is reported to be operated remotely from the generating station.

A dam caretaker is on hand at the facility on a 7-day a week, 24-hour a day basis.

4.2 Maintenance of Dam.

The dam has been reportedly maintained on an as-needed basis. The recent advent of a full-time staff has apparently upgraded the maintenance program. In addition, discussions with the owner's representative indicate that remedial maintenance work is scheduled to begin prior to September 1, 1978.

4.3 Maintenance of Operating Facilities.

No formal schedule or manual is available detailing required maintenance of the facility.

4.4 Warning Systems.

There are no formal warning systems in effect.

4.5 Evaluation.

The operational procedures at the facility appear to be clear and well defined. No formal maintenance program is currently in effect. Extensive remedial work is reportedly scheduled to commence prior to September 1, 1978.

SECTION 5
HYDROLOGIC/HYDRAULIC EVALUATION

5.1 Design Data.

The criteria considered in the hydrology and hydraulic evaluation of this project are summarized in a report by Gilbert Associates, Inc., entitled "Report No. 1637, Design of Two Lick Creek Dam" (Volume I, Design Report, December 15, 1966). The main points included in the report are presented below.

The purpose of the facility, as previously stated, is to supply sufficient amounts of water to meet the requirements of the Homer City Generating Station. The required reservoir capacity, as determined from the plant and downstream make up requirements, is 16,200 acre-feet at full pool (elevation 1183). The required reservoir capacity coupled with upstream flooding considerations at the town of Clymer, established the maximum flood pool level to be at elevation 1185.

By use of the Hydrometeorological Report No. 33 and Technical Paper No. 40 (both by the United States Weather Bureau), a "Maximum Probable Storm" was determined for the drainage area of Two Lick Creek Dam. Probable storms for recurrence intervals of 10 years, 25 years, 100 years, and 1,000 years were also determined. Design flood peaks were computed by various empirical formulas and by unitgraph. For the unitgraph flood, a "Maximum Probable Storm" was assumed which produced a rainfall of 26 inches, over the entire drainage basin, in a period of 24 hours, with 14 inches of rainfall occurring the first 3 hours and producing 12.5 inches of runoff. Such a storm produced a flood peak of 66,100 cfs.

Considering the above requirements in combination, it was determined that a gated spillway section was necessary. The spillway was designed with three 30-foot wide bays, with crests at elevation 1151. The spillway capacity, with gates fully open and reservoir level at elevation 1183, is 62,500 cfs. To pass a flood peak of 66,100, the reservoir level is at elevation 1184.2. Additional flood discharge capacity is provided by the emergency spillway whose crest elevation is set at 1184.5, while the top of dam is set at elevation 1195. The capacity of the emergency spillway is approximately 10,500 cfs.

5.2 Experience Data.

Reservoir levels and low flow discharge are monitored on a continuous basis at the facility. The records indicate

the facility has performed adequately in the past. During the flood of July 1977, the emergency spillway inadvertently discharged causing the damage to the right abutment which is visible today. The situation occurred because the automatic radial gate mechanism was wired to shut down when the gate opened two feet. Consequently, the water in the reservoir steadily rose until it discharged through the emergency spillway. The mechanism has since been repaired and the limiting device removed. The gates have been tested and reportedly are capable of opening fully.

5.3 Visual Observations.

On the date of inspection, no conditions were observed that would indicate the appurtenant structures of the dam could not operate satisfactorily during a flood event.

5.4 Overtopping Potential.

The ratio "PMF Peak Flow/Drainage Area" was determined from an empirical curve supplied by the Corps of Engineers, Baltimore District. The curve used was the Ohio River Basin curve. Based on this curve and a drainage area of 74 square miles, Peak PMF $Q/A = 760$ cfs/sq. mi., and Peak PMF $Q = 56,240$ cfs. The size category is "large" and the hazard rating "high". Consequently, the SDF is the PMF.

Calculations were performed to evaluate the overtopping potential using spillway and storage capacities during the PMF.

The discharge capacity of the primary spillway was considered with the reservoir level set at elevation 1183. This corresponds to the top elevation of the maximum opening of the radial gates. When the reservoir level is at or below this elevation, discharge will be solely through the primary spillway. With all three radial gates open full, the primary spillway discharge is equal to 62,560 cfs. A comparison of Peak PMF Q (56,240 cfs) with primary spillway discharge (62,560 cfs) indicates the primary spillway discharge is greater than the peak inflow.

5.5 Spillway Adequacy.

The spillway and dam are capable of passing and/or containing the runoff resulting from a storm of PMF magnitude. This is accomplished solely by the primary spillway (Bays 4, 5, and 6) and without the additional discharge capacity available from the emergency spillway (Bays 1, 2, and 3).

As a result, the spillway system is deemed adequate assuming proper operation of the radial gate system.

SECTION 6
EVALUATION OF STRUCTURAL INTEGRITY

6.1 Visual Observations.

a. Embankment.

1. Earth- Rockfill Section. The visual inspection revealed this area to possess the most serious deficiencies associated with the facility. These are, as discussed in Section 3.1.b.1, the overgrown slopes, the apparent poor quality riprap and quarry run fill, and the lack of adequate drainage at the toe. Project specifications were not available; consequently, the design requirements for the riprap and quarry run rock are not known. Nevertheless, there is considerable slaking of the riprap on the upstream face as well as the quarry run rockfill on the downstream slope. The owner is currently considering alternate solutions to the riprap problem. It is not known if the random rock beneath the surface is also degraded which would affect the need for necessary immediate remedial action.

As for the overgrowth, the owner is aware of the problem and reportedly plans to remove the trees before winter. The water at the toe of the dam is apparently the result of surface runoff being impounded by the earth dike that parallels the stream channel. Periodically, the water reportedly evaporates, temporarily drying the area.

Presently, the above conditions are considered undesirable but do not appear to present an immediate threat to the stability of the structure.

2. Non-Overflow Concrete Section. Based on the visual inspection, this portion of the facility appears to be well designed, stable, and presently in good condition.

b. Appurtenant Structures. The appurtenances of this facility, including both the primary and emergency spillway, and the low discharge tunnel, appear to be in good condition. A complete evaluation of their overall structural integrity is not possible without first hand observation of the associated mechanisms in operation. However, based on the general appearance of the appurtenances, no structural deficiencies are apparent. The July 1977, flood caused significant damage to the area just downstream of the emergency spillway. Conversations with the owner's representative indicates that provisions to repair the damage are presently under consideration and that corrective work should commence by September 1978.

6.2 Design and Construction Techniques.

The design reports and information received from PennDER and the Pennsylvania Electric Company indicate the facility has been adequately designed in conformance with accepted modern engineering practice. Additional information in the form of "revised" design drawings, construction photographs, and reports reinforce our opinion that the structure is stable in both concept and construction.

6.3 Past Performance.

The facility has survived the storm which resulted in the Johnstown flood on July 1977. Available records indicate the facility performed as designed throughout its short history.

6.4 Seismic Stability.

The dam is located within Seismic Zone No. 1 and it is thought that the static stability is sufficient to withstand minor earthquake induced dynamic forces. However, no calculations, investigations, etc., were performed to confirm this opinion.

SECTION 7
ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES

7.1 Dam Assessment.

a. Safety. The visual inspection, operational history, and available engineering data suggest that certain conditions at the facility require further study while others require immediate attention. Conversations with the owner's representative indicate that the owner is knowledgeable of the deficiencies at the facility. Furthermore, the owner appears to possess a positive attitude relative to their resolution. The overall condition of the facility is considered good.

Hydraulic and hydrologic calculations indicate that the spillway is capable of passing and/or storing the flow resulting from a storm of PMF intensity and consequently the spillway capacity can be considered adequate.

b. Adequacy of Information. The available data are considered sufficient to make an accurate assessment of the facility.

c. Urgency. It is suggested that the recommendations listed below be implemented immediately.

d. Necessity for Additional Investigations. An investigation (refer to Section 7.2) of the durability and/or suitability of the riprap and quarry run rockfill is considered necessary.

7.2 Recommendations/Remedial Measures.

It is recommended that:

a. The owner investigate the physical characteristics of the riprap and quarry run rockfill. Conclusions relative to its suitability should be developed and remedial action implemented, if necessary.

b. Positive drainage be provided to eliminate the ponding condition along the downstream toe of the earth-rockfill portion of the embankment.

c. The owner immediately remove the overgrowth visible on both sides of the earth-rockfill embankment.

d. The owner implement remedial measures to repair damage to the right abutment (emergency spillway outlet).

- e. The owner formalize a regular maintenance program.
- f. The owner develop a warning system that will provide for the safe evacuation of all downstream inhabitants in the event of an inordinantly heavy rainfall.
- g. The facility be inspected on a periodic basis by a registered professional engineer to check for deleterious conditions which might develop.

APPENDIX A

CHECK LIST - ENGINEERING DATA

CHECK LIST NAME OF DAM Two Lick Creek Dam

ENGINEERING DATA

DESIGN, CONSTRUCTION, OPERATION
PHASE I

ID # NDI# PA-285 PennDer 32-75

ITEM:

REMARKS

SHEET 1

AS-BUILT DRAWINGS

Specific "as-built" drawings are not available. Design drawings are available in the Appendix of the design report, Volume I entitled "Report No. 1637, Design of Two Lick Creek Dam". The report is available from both Penelec and PennDer.

REGIONAL VICINITY MAP

See Appendix G.

CONSTRUCTION HISTORY

Construction status report, memoranda, and photographs are available from PennDer.

TYPICAL SECTIONS OF DAM

See Figures 6, 7, 9, 10, and 1 in Appendix F.

OUTLETS - PLAN See Figure 3 in Appendix F.

- DETAILS See Figures 9, 10, and 1 in Appendix F.

- DISCHARGE RATINGS See Figure 2 in Appendix F.

RAINFALL/RESERVOIR RECORDS

Reservoir levels are monitored continuously and recorded at the facility. Rainfall records are compiled at the Homer City Generating Station. Reports are available from Penelec.

ITEM

REMARKS

ID #

SHEET 2

DESIGN REPORTS

"Report No. 1637, Design of Two Lick Creek Dam": Volumes I, II, and III by Gilbert Associates, Inc. are available from PENNDR.

GEOLOGY REPORTS

Contained within design report Volume II. The report is subtitled "Foundation and Borrow Investigation."

DESIGN COMPUTATIONS

HYDROLOGY & HYDRAULICS

DAM STABILITY

SEEPAGE STUDIES

A summary of the hydrology and hydraulic design criteria are contained within design report, Volume I.

MATERIALS INVESTIGATIONS

BORING RECORDS

LABORATORY

FIELD

Contained within all three design report volumes.

POST-CONSTRUCTION SURVEYS OF DAM

None

BORROW SOURCES

Discussed in design report Volume II and depicted on one of the design drawings contained in the appendix of design report Volume I.

ITEM

REMARKS

ID #

SHEET 3

MONITORING SYSTEMS

The entire operation of the facility is continuously monitored and recorded. System records are available from Pennder.

MODIFICATIONS

Following the flood of July, 1977, the automatic spillway gate system was modified such that the system is now controlled manually.

HIGH POOL RECORDS

Available from Pennder. The highest pool of record occurred July 20, 1977. At this time the reservoir level was measured to be at approximate elevation 1185.5 or one foot over the emergency spillway.

POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS

Separate investigations were performed by Penelec and Gilbert Associates, Inc., following the flood of July, 1977. The investigations pertained to the damage incurred as a result of flood waters. Results of the investigations are available from Penelec.

PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS

See "Post Construction Engineering Studies and Reports" above.

MAINTENANCE OPERATION RECORDS

Available from Penelec.

ITEM

REMARKS

ID #

SHEET 4

SPILLWAY PLAN See Figures 1, 3, and 8, Appendix F.

SECTIONS See Figure 9, Appendix F.

DETAILS See Figure 1, Appendix F.

OPERATING EQUIPMENT
PLANS & DETAILS

See Figures 10 and 11, Appendix F.

NDI# PA-285
ID # PennDER 32-75

CHECK LIST ID #
HYDROLOGIC AND HYDRAULIC
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: 74 square miles

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 1183 (16,200 acre-feet)

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): 1184.5 (16,700 acre-feet)

ELEVATION MAXIMUM DESIGN POOL: 1185 (17,000 acre-feet)

ELEVATION TOP DAM: 1195 (23,000 acre-feet)

SPILLWAY DATA:

- a. Crest Elevation (primary) 1151; (emergency) 1184.5
- b. Type (primary and emergency) concrete ogee-shaped weirs
- c. Weir Length (primary) 90 feet; (emergency) 102 feet
- d. Channel Length Not applicable.
- e. Location Spillover right abutment
- f. Number and Type of Gates 3 mechanical radial tainter gates

OUTLET WORKS:

- a. Type 12 by 14 foot concrete box-culvert
- b. Location junction of the earth embankment with the concrete
- c. Entrance Inverts gravity dam 1107.5
- d. Exit Inverts 1105
- e. Emergency Draindown Facilities low level release (see Figure 9)

HYDROMETEOROLOGICAL GAGES:

- a. Type Rain gage
- b. Location Homer City Generating Station
- c. Records daily records available from Penelec

MAXIMUM NON-DAMAGING DISCHARGE: Specific data not available.

APPENDIX B

CHECK LIST - VISUAL INSPECTION

CHECK LIST
VISUAL INSPECTION
PHASE 1

NDI# PA-285
ID # PENNDR 32-75

DAM NAME Two Lick Creek Dam COUNTY Indiana STATE PA
TYPE OF DAM Concrete & earth- and rockfill HAZARD CATEGORY high
DATE(S) INSPECTION 8/11/78 WEATHER Hazy & warm TEMPERATURE 73°

POOL ELEVATION AT TIME OF INSPECTION 1176.8 M.S.L. TAILWATER AT TIME OF INSPECTION None at M.S.L.
gates, low flow
in stream throug
outflow.

INSPECTION PERSONNEL:

B. M. Mihalcin (GAI) R. Gallus (Penelec)
J. P. Nairn (GAI)
D. L. Bonk (GAI)

D. L. Bonk RECORDER

SURFACE CRACKS

None observed.

UNUSUAL MOVEMENT OR
CRACKING AT OR BEYOND
THE TOE

None observed. The downstream toe was partially submerged by a pool of water, 1 foot to 3 feet deep, between the toe and discharge channel dike.

SLOUGHING OR EROSION OF
EMBANKMENT AND ABUTMENT
SLOPES

Rock disintegration is profuse across both the upstream and downstream slopes. Many trees have accumulated on the dam slopes.

VERTICAL AND HORIZONTAL
ALIGNMENT OF THE CREST

Good.

RIPRAP FAILURES

Much of the riprap and rockfill zone on the upstream slope has deteriorated and appears to be composed primarily of non-durable siltstones and silty shales.

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

ANY NOTICEABLE SEEPAGE

None observed.

STRUCTURE TO
ABUTMENT/EMBANKMENT
JUNCTIONS

Excellent condition.

DRAINS

Relief drains are visible throughout the concrete section of the structure.

WATER PASSAGES

Outflow structure open. Monitoring weir located at the discharge end was flowing full during the inspection.

FOUNDATION

Not observed. Structure is founded on rock. A grout curtain has been provided beneath the dam.

VISUAL EXAMINATION OF OBSERVATIONS REMARKS OR RECOMMENDATIONS

JUNCTION OF EMBANKMENT
AND ABUTMENT, SPILLWAY
AND DAM

Good condition.

ANY NOTICEABLE SEEPAGE

No visible seepage along the downstream face. The downstream toe is completed inundated by approximately 1 to 3 feet of water.

STAFF GAGE AND RECORDER

A staff gage is attached to the upstream face of the concrete portion of the structure. It is located to the left of Bay 6 (spillway bay furthest from the right abutment) and to the right of the discharge conduit intakes.

DRAINS

No drains were observed through the earth portion of the embankment.

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
-----------------------	--------------	----------------------------

SURFACE CRACKS CONCRETE SURFACES	Minor cracking and some slight spalling and scaling were visible on the crest and the main spillway bays. Extensive scaling is visible on the primary spillway apron.	
-------------------------------------	---	--

STRUCTURAL CRACKING	None observed.	
---------------------	----------------	--

VERTICAL AND HORIZONTAL ALIGNMENT	Good.	
--------------------------------------	-------	--

MONOLITH JOINTS	Good.	
-----------------	-------	--

CONSTRUCTION JOINTS	Good condition. No separation or deterioration observed.	
---------------------	--	--

STAFF GAGE OR RECORDER:	See embankment.	
-------------------------	-----------------	--

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	<p>Concrete surfaces appear to be in good condition. Much of the concrete displays a reddish-orange tint. This is likely to be due to the acidic nature of the water in the reservoir. Deep coal mines are present in the general area and consequently, acid mine drainage is likely to be prevalent.</p>	
INTAKE STRUCTURE	<p>Intakes were submerged during the inspection. Gate valves and gate controls were observed from within the structure via several access chambers. One of the gate valves was in the process of being repaired while the rest of the equipment appeared to be in good condition. None of the equipment was operated in the presence of the inspection team.</p>	
OUTLET STRUCTURE	<p>Good condition. Reddish-orange tinted concrete is visible at and below the flow line. Stainless steel, flow monitoring weir at the discharge end appears to be in good condition. Flow is monitored from the control room situated below the crest and on the left downstream face of the concrete portion of the facility.</p>	
OUTLET CHANNEL	<p>Good condition. The base of the channel appears to be sound bedrock.</p>	
EMERGENCY GATE	<p>The dam is provided with a reservoir drawdown system that is apparently controlled with gates located at the discharge end of the discharge tunnel.</p>	

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

CONCRETE WEIR

Six spillway bays with ogee-shaped weirs. Bays 4, 5, and 6 (left to right) are the main discharge outlets and are controlled by mechanically operated radial gates. The operating mechanisms are located atop the dam crest and directly above their respective bays. Bays 4, 5, and 6 are 30 feet by 32 feet. Bays 1, 2, and 3 are for emergency use only and are uncontrolled. Bays 1, 2, and 3 are 34 feet wide by 7 feet high. None of the bays were discharging during the inspection.

APPROACH CHANNEL

The drawings indicate Bays 1, 2, and 3 to have individual approach channels cut into rock along the right abutment. The channels were submerged and only the channel for Bay 1, which appears to be the most shallow could be observed. It was submerged by approximately 2 feet of water and appears to be in good condition.

DISCHARGE CHANNEL

Bays 1, 2, and 3 have no well defined discharge channels and merely discharge flow onto the right abutment hillside. The rains which caused the Johnstown Flood of 1977 caused Bays 1, 2, and 3 to discharge. The result was extensive damage to the area immediately beyond the spillway bays. Much of the rock was stripped away by the flood waters.

BRIDGE AND PIERS

The dam crest is designed to be used as a serviceway which spans all 6 spillway bays. The elevation of the underside of the serviceway is 1191.36 while the elevation of the top of dam is 1195.

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

CONCRETE SILL

Ogee-shaped weir.

APPROACH CHANNEL

Submerged during inspection. Available drawings do not indicate a clearly defined approach channel for Bays 4, 5, and 6 as is the case for Bays 1, 2, and 3. The drawings do indicate the depth behind the spillway crest to be 21 feet.

DISCHARGE CHANNEL

Main Bays 4, 5, and 6 discharge into a natural channel cut out of rock immediately downstream. A 10-foot dike has been constructed along the left side of the channel to divert flow away from the toe of the earth portion of the embankment. Some large boulders partially obstruct flow and are the likely result of damage caused by the flood of 1977.

BRIDGE AND PIERS

See ungated spillway.

GATES AND OPERATION
EQUIPMENT

Mechanically operated radial spillway gates are manually controlled from atop the crest. Gates for the discharge conduit are also operated from the crest. All other operating mechanisms are controlled from within the interior of the structure.

VISUAL EXAMINATION

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

MONUMENTATION/SURVEYS

None observed.

OBSERVATION WELLS

None observed.

WEIRS

Stainless steel monitoring weir is located at the discharge end of the discharge tunnel. Another weir located at a small dam downstream measures stream flow. Flow from both weirs is recorded at the operations room located on the downstream face to the left of Bay 6.

PIEZOMETERS

Several piezometers are visible at various locations and elevations across the downstream face. They reportedly will be read and recorded on a periodic basis by a private consultant. No formal monitoring program now exists.

OTHERS

The operations room appears to contain the majority of the instrumentation associated with this facility. It is accessible by a stairway from the crest located along the left downstream face of the concrete portion of the structure.

RESERVOIR

ID # PA-285

SHEET 7

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

SLOPES

Generally moderate to steep adjoining hillsides. The majority of the area is heavily wooded with the exception of a few small grassy areas.

SEDIMENTATION

None observed.

REMARKS OR RECOMMENDATIONS

VISUAL EXAMINATION OF

OBSERVATIONS

CONDITION

(OBSTRUCTIONS,
DEBRIS, ETC.)

See "discharge channel, gated and ungated spillways" (Sheets 4 and 5)

SLOPES

Moderate to steep and heavily wooded on left. Moderately sloped and grassy floodplain on right.

APPROXIMATE NO.
OF HOMES AND
POPULATION

Waterworks facilities are located on the floodplain approximately 1-1/2 miles downstream. Homer City, located = 8 miles downstream is also likely to experience significant damage in the event of a breach. Total population affected easily exceeds 100.

APPENDIX C
HYDRAULICS/HYDROLOGY

SUBJECT DAM SAFETY INSPECTION

TWO LICK CREEK DAM

BY DLK DATE 8-9-78 PROJ. NO. 7E-501-285

CHKD. BY EJM DATE 8-25-78 SHEET NO. 1 OF 3



DAM STATISTICS

MAXIMUM HEIGHT OF DAM = 115 FEET (REF 1: PG 3)
DRAINAGE AREA = 74 SQ. MI. (" PG 2)
STORAGE CAPACITY = 16,200 AC-FT (" PGS 2 & 3)
@ EL 1183

SIZE CLASSIFICATION

DAM SIZE - LARGE (REF 2: TABLE 1)
HAZARD RATING - HIGH (POSSIBLE LOSS OF LIFE > 3)
REQUIRED SDF = PMF (REF 2: TABLE 3)

REFERENCES

- 1: "DESIGN OF TWO LICK CREEK DAM", VOLUME I, DESIGN REPORT, GILBERT ASSOCIATES, INC., DECEMBER 15, 1966
- 2: "RECOMMENDED GUIDELINES FOR SAFETY INSPECTION OF DAMS" DEPT. OF THE ARMY - OFFICE OF CHIEF ENGINEER, APPENDIX D
- 3: STANDARD HANDBOOK FOR CIVIL ENGINEERS
F. S. MERRITT, MCGRAW-HILL 1976


THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG

SUBJECT DAM SAFETY INSPECTION
TWO LICK CREEK DAM
 BY DLB DATE 8-9-78 PROJ. NO. 78-501-285
 CHKD. BY EJM DATE 8-25-78 SHEET NO. 2 OF 3



PMF (PEAK FLOW)/AREA = 760 CFS/SQ.MI. (REF: C OF E CURVE, OHIO RIVER BASIN)
 PEAK INFLOW $\Phi = (760 \text{ CFS/SQ.MI}) (74 \text{ SQ.MI}) = 56,240 \text{ CFS}$

SPILLWAY CAPACITY



TYPICAL FOREBAY DEPTH \approx 21 FEET (SEE REFERENCE ON SHEET 3)

NOTE: ALL ELEVATIONS ARE EXTRACTED FROM DRAWG C-726-422 "CONCRETE; GENERAL SECTIONS". DIMENSIONS ARE FROM DRAWG C-726-458 by GILBERT ASSOCIATES, INC. OF READING, PENNSYLVANIA, EXCEPT FOR THE WIDTHS OF SPILLWAY BAYS 1, 2, & 3 WHICH WERE MEASURED IN THE FIELD (REVISION II)

THIS PAGE IS BEST QUALITY PRACTICABLE FROM COPY FURNISHED TO DDG

SUBJECT DAM SAFETY INSPECTION
TWO LICK CREEK DAM
BY DLB DATE 8-14-78 PROJ. NO. 78-501-285
CHKD. BY EJM DATE 8-25-78 SHEET NO. 3 OF 3



$Q_1 = 3CL_1 H_1^{3/2} =$ DISCHARGE OF SPILLWAY BAYS 4, 5 & 6 (REF 3, EQ 21-121)

$L_1 = 30$ FT (SHEET 2)

$H_1 = 32$ FT

(FROM FIG 21-67, REF. 3)

$P/H_1 = 21/32 = 0.66$

NOTE: $P = 21$ FT, IS THE FOREBAY
DEPTH SHOWN ON DRAWG C-726-422

$\therefore C = 3.84$

$Q_1 = (3)(3.84)(30 \text{ FT})(32 \text{ FT})^{3/2} = 62,560 \text{ CFS}$

MAXIMUM PRIMARY SPILLWAY DISCHARGE (62,560 CFS) > . . .

. . . > PMF PEAK INFLOW Q (56,240 CFS)

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG

APPENDIX D
PHOTOGRAPHS

PHOTOGRAPH 1 View of Two Lick Creek Dam taken from a point approximately 500 feet downstream. A portion of the left side of the embankment is not visible on the photograph.

PHOTOGRAPH 2 View of the earth portion of Two Lick Creek Dam taken from downstream of the right abutment.

PHOTOGRAPH 3 View of the crest of Two Lick Creek Dam taken from the left abutment.

PHOTOGRAPH 4 View of the upstream face of Two Lick Creek Dam.



1



2



3




4

PHOTOGRAPH 5 View of the reservoir area showing the wooded slopes surrounding the reservoir.

PHOTOGRAPH 6 View of the mechanically operated radial gates (primary spillway) at the Two Lick Creek facility.

PHOTOGRAPH 7 View of the motor controls for the radial gates shown in the previous photograph.


PHOTOGRAPH 8 View of the outlet end of the discharge tunnel at the Two Lick Creek facility.



6



8



5



7

PHOTOGRAPH 9 Close-up view of materials comprising the downstream face of the earth section of Two Lick Creek Dam.

PHOTOGRAPH 10 View of the standing water at the toe of Two Lick Creek Dam. The water is impounded by an earthen dike which serves as the left bank of the stream just downstream of the dam (see Photograph 11).

PHOTOGRAPH 11 View of erosion in the rock channel at the outlet of the emergency spillway (foreground). The pool of water and earth dike mentioned in the previous photograph can be seen in the left background. Note the character of the valley just downstream of the dam.

PHOTOGRAPH 12 View of erosion damage at the intersection of the emergency spillway and the rock abutment. A coal seam was eroded out in this area.



10



12



9




11

PHOTOGRAPH 13 Close-up view of concrete deterioration on the primary spillway apron. The orange-brown color suggests that the discharge may be corrosive in nature.

PHOTOGRAPH 14 View of the first major obstruction downstream of Two Lick Creek Dam consisting of a concrete bridge over a secondary road approximately 3-1/2 miles downstream of the dam. About six homes are located adjacent to the creek at this point.



14



13

APPENDIX E

GEOLOGY

GEOLOGY

Two Lick Creek Dam is located in the eastern portion of the Appalachian Plateau Physiographic Province.

Soils in the vicinity of the dam are principally alluvial and colluvial. The alluvial soils occupy the floodplain of Two Lick Creek and are sometimes intermixed with colluvial soils which moved down the steep sided slopes characteristic of this valley. The thicknesses of the alluvial materials varied from 0 to 20 feet and the colluvium had a thickness range of 3 to 15 feet. Within the dam's substantial drainage area, the majority of soils are residual and have overburden thicknesses from 2 to 20 feet.

Stratigraphically, the bedrock beneath the dam site consists of strata from the lower portion of the Allegheny Group of Pennsylvanian age. This sequence is composed chiefly of sandstone with some shale, siltstone, and coal. Rocks within the dam's watershed are all Pennsylvanian age and include strata from the Conemaugh Formation and the Allegheny and Pottsville Groups. The extent of mining at the dam site was limited to two small country bank operations in the Lower Kittanning coal upstream of the dam. Numerous mining operations occur within the drainage area of the dam and are chiefly strip mines.


The dam site is located on the west limb of the northeast trending Chestnut Ridge anticline. The rocks are nearly flat lying with minor dip to the northwest. One fault was located upstream of the dam during investigations prior to dam construction. A maximum vertical displacement of 10 feet was estimated for the fault. No major shear zone was associated with this fault and no subsurface faulting was disclosed by the drilling investigation.

APPENDIX F

FIGURES

TABLE OF CONTENTS


<u>Figure</u>	<u>Description/Title</u>
1	General Plan
2	Data Sheet
3	Concrete, General Plan
4	Stability Analysis, Concrete Section
5	Geologic Sections
6	Rock-fill Embankment, Sections
7	Embankment Stability Analysis
8	Plan-1st Stage Construction Diversion, Cofferdam and Earth Core
9	Concrete, General Sections
10	Radial Gates, General Arrangement
11	Radial Gates, General Arrangement (Details)



THIS PAGE IS BEST QUALITY PRACTICABLE
 FROM COPY FURNISHED TO DDG

CONTRACT
 LIMIT

Two Liver Cherry



THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

ADDED GENERATOR P.D.
REVISIONS

FIGURE 1

NEW YORK STATE ELECTRIC & GAS CORPORATION
PENNSYLVANIA ELECTRIC COMPANY

Homer City Station Units 1 & 2

TWO LICK CREEK DAM
General Plan
Roadway, Embankment & Spillway

PLANNED BY: GILBERT ASSOCIATES, INC.
ENGINEERS AND ARCHITECTS

DATE: 11-20-50


4150 C-726-404 I

EXHIBIT 3


REVISIONS	DATE	BY	DESCRIPTION
1	11-20-50	J.M.H.	...
2	11-20-50	J.M.H.	...

A

RESERVOIR CAPACITY AREA CURVES



SPILLWAY





B

C


D

THIS PAGE IS BEST QUALITY PRACTICABLE FROM COPY FURNISHED TO DDC

E




HYDROGRAPHS




F

G

H




MINUS #4 SIEVE SOIL FRACTION




THIS PAGE IS BEST QUALITY PRACTICABLE FROM COPY FURNISHED TO DDC

GRADATION CURVES



CURVE	AVERAGE GRADATION OF:
1	Impervious Core Material - Zone A
2	Transitional Earth Fill - Zone B
3	Fine Filter - Zone C
4	Sand (Fine aggregate) Interior Concrete
5	Coarse aggregate - Face Concrete
6	Coarse Filler (Finer Quarry-run rock)
7	Quarry-run rock (Approx.)
8	Coarse aggregate - Interior Concrete
9	Sand (Fine aggregate) Face Concrete

STRENGTH PARAMETERS



Laboratory results are total stresses obtained from Consolidated Undrained Triaxial Tests.

EXHIBIT 8

Revised Curves 1, 2, 3, 4, 5, 6, 7, 8, 9 added	DATE: 1/11/71	BY: JMS
Curve 3 to Curve 8 truncated	DATE: 1/11/71	BY: JMS
Description, Purpose & Location	DATE: 1/11/71	BY: JMS
Checked by: JMS	DATE: 1/11/71	BY: JMS
Curve 6 Deleted	DATE: 1/11/71	BY: JMS
Curve 8 Deleted	DATE: 1/11/71	BY: JMS

FIGURE 2

NEW YORK STATE ELECTRIC
PENNSYLVANIA ELECTRIC
Homer City Station


TWO LICK C
Data Sheet


NAME: GILBERT ASSO
ENGINEER AND

REVISIONS

NO. 4150, C-

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG





THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG

REFERENCES:-
Sections C-726-422


NOTES:-
1. Drawings C-726-421 and C-726-422 have been revised to indicate over-excavation in the bucket area of the dam. The following drawings would also reflect this change but remain unchanged to show original design layout: C-726-404, C-726-412, C-726-413, C-726-415, C-726-416, C-726-418, C-726-453, C-726-466, C-726-487, C-726-488.
2. Contraction joints shall be painted as described in Paragraph 4:07.6 of the Specifications.

EXHIBIT 9


Added Bucket Drains, added Concrete as indicated in place & added Notes 1 & 2
Added Operating Deck, revised Spillway walls of bucket, and added some face of walls or Dike to 6, 7, 8, 9, 10.
REVISIONS

FIGURE 3

NEW YORK STATE ELECTRIC & GAS CORPORATION	
PENNSYLVANIA ELECTRIC COMPANY	
Number City Station	Units 1 & 2
TWO LICK CREEK DAM	
Concrete	
General Plan	
DESIGNED BY	GILBERT ASSOCIATES, INC.
ENGINEER	GILBERT ASSOCIATES, INC.
DATE	
BY	
CHECKED BY	
DATE	




Block 10





Block 11

BASE	CASE	Z H	Z V	STRESSES LBS/SQ. IN.								
				f _u	f _d	f _a	f _v	f _u	f _d	f _a	f _v	
1163	I	-	46.8	271	271	271	271	0.0				
	II	4.2	43.3	14.8	14.8	35.4	35.4	3.1	63.3			
	III	6.2	43.3	14.8	14.8	35.4	35.4	3.1	63.3			
	IV	10.5	41.1	-13.5	-13.5	46.7	46.7	2.6	63.3			
1128	I	-	222.2	74.0	74.0	3.8	3.8					
	II	10.80	190.0	17.1	17.1	44.6	44.6	11.0	63.9			
	III	10.20	170.0	14.8	14.8	41.3	41.3	10.5	63.8			
	IV	14.00	150.0	-15.0	-15.0	53.8	53.8	22.7	64.6			



BASE AT EL. 1147.0



Block 7 & 8

THIS PAGE IS BEST QUALITY PRACTICABLE FROM COPY FURNISHED TO DDG

BASE EL.	CASE	Z H KIPS	Z V KIPS	STRESSES LBS/SQ. IN.								
				f _u	f _d	f _a	f _v	f _u	f _d	f _a	f _v	
1147.0	I	25	42.83	68.1	71.8	11.9	9.3	0.3	63.2			
	II	14.70	42.13	24.7	25.4	46.9	48.1	15.1	64.7			
	III	14.70	42.13	24.4	25.4	46.9	48.1	15.1	64.7			
	IV	2.298	42.13	1.1	2.5	77.4	83.3	23.5	65.0			
1124	I	14.5	76.42	68.3	67.1	114.0	115.4	0.8	65.5			
	II	3.775	76.93	7.0	5.8	83.2	84.3	15.2	66.0			
	III	3.672	69.71	4.2	3.0	70.5	72.2	18.7	65.0			
	IV	4.720	65.64	8.2	7.0	60.0	61.5	24.0	63.5			

BASE EL.	CASE	Z H KIPS	Z V KIPS
1130	I	150	84.0
	II	2338	71.0
	III	2315	65.8
	IV	3518	72.7
1103	I	439	103.1
	II	4870	158.2
	III	4030	152.2
	IV	6270	155.5

BASE	CASE	Z H KIPS	Z V KIPS	STRESSES LBS/SQ. IN.								
				f _u	f _d	f _a	f _v	f _u	f _d	f _a	f _v	
1127	I	-	4790	48.8	48.8	18.5	15.5	-	63.9			
	II	2103	4328	18.3	18.3	41.0	41.0	9.5	63.4			
	III	1467	3643	16.2	16.2	32.8	32.8	9.5	63.8			
	IV	2796	448	-3.1	-3.1	55.8	55.8	18.9	63.7			


Uplift Assumptions
(100% of Base Area)

- Where drains exist against rock
Upstream-full headwater
At Drains-Tailwater plus $\frac{1}{2}$ (Headwater minus Tailwater)
Downstream-full tailwater
- In concrete (No Drains)
Full headwater to tailwater
Diagram at 67% intensity




- NOTES:-
- Dimensions are for purposes only and
 - Design cases:
Case I: I
Case II: I
Case III: I
Case IV: I
 - In Case II: I
 - 10% passive
 - Seals are at

- SYMBOLS:
- Z H - Algebraic
 - Z V - Algebraic
 - f_u - Base stress
 - f_d - Base stress
 - f_a - Average stress
 - f_v - Allowable stress
 - f_v = 1/6


BASE LINE



OCK 12



Block 13



THIS PAGE IS BEST QUALITY PRACTICABLE FROM COPY FURNISHED TO DDG

BASE EL.	CASE	Σ H PIPS	Σ V KIPS	STRESSES LBS./SQ. IN.					
				f ₁	f ₂	f ₃	f ₄	f _v	f _v
1185	I	160	3855	620	202	2.1	16	55.8	
	II	125	3662	843	47	2.1	7.0	15	66.4
	III	125	3662	843	47	2.1	7.0	15	63.4
	IV	278	4454	483	80	4.8	25.5	33	64.8
1130	I	1570	12331	75.6	56.5	12.5	27.4	5.5	68.0
	II	3200	10231	35.4	53.3	33.6	57.0	11.6	64.0
	III	3200	10107	35.4	52.2	33.1	55.0	11.6	65.0
	IV	3550	10603	25.0	51.1	4.8	71.1	13.1	64.0
1105	I	4870	27082	1013	383	6.1	12.8	9.1	64.6
	II	7200	22410	55.8	4.6	14.9	63.3	17.2	64.8
	III	7500	22166	55.3	0.7	23.2	64.7	14.7	63.8
	IV	8050	23192	50.3	0.4	36.5	54.6	16.2	63.5

V	STRESSES LBS./SQ. IN.					
	f _u	f _d	f ₁	f ₂	f _v	f _v
0.03	82.0	82.0	35.5	35.5	1.0	67.7
0.9	35.5	35.5	55.8	55.4	15.5	65.9
8.5	35.1	35.1	54.3	49.5	16.3	65.6
7.9	17.3	17.3	71.4	71.0	22.0	65.8
1.9	103.2	102.7	77.3	77.3	2.4	71.7
12.7	10.4	9.9	155.1	153.5	24.5	70.8
22.2	8.9	8.4	134.1	134.9	22.0	69.5
55.7	-12.3	-12.3	182.1	182.5	34.1	71.0

and foundation elevations shown are for design and are not to be used for construction.
 Dead load of concrete, fill in place, reservoir empty.
 HW EL. 1183.0', TW EL. 1110.0'.
 HW EL. 1182.0', TW EL. 1135.0'.
 spillway gates fully open.
 HW EL. 1182.0', TW EL. 1125.0'.
 Spillway gates closed, Case IV is an emergency design case only.
 uplift of Case II used.
 pressure used in Case II for block II & III.
 at 4' downstream of base line.

is summation of forces parallel to base of section.
 is summation of forces normal to base of section.
 is at upstream face.
 is at downstream face.
 is shear stress on base.
 is shear stress on base. (Rock surface only; 1000 = 0.65 average vertical stress)


EXHIBIT 10

FIGURE 4


DESCRIPTION	
NO.	DATE
REVISIONS	
NEW YORK STATE ELECTRIC & GAS CORPORATION PENNSYLVANIA ELECTRIC COMPANY Homer City Station Units 1 & 2	
TWO LICK CREEK DAM Stability Analysis Concrete Section	
DESIGNED BY	GILBERT ASSOCIATES, INC.
CHECKED BY	ENGINEERS AND ARCHITECTS
DATE	
SCALE	
BY	
DATE	
BY	
DATE	

A
B
C
D
E
F
G
H

PL 574
\$0555



SECTION A-A





TOP OF POTTSVILLE

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

SECTION B-B

- NOTES:-
1. Refer to Volume II Report No. 1687 for detailed log of individual borings.
 2. Subsurface data is correct at borings only, and conditions may vary between borings.
 3. Water pressure tests were conducted in five foot intervals, exact depth of test interval can be obtained from detailed logs in Volume II Report No. 1687.



THIS PAGE IS BEST QUALITY PRACTICABLE FROM COPY FURNISHED TO DDG

LEGEND

- Overburden
 - Sandstone
 - Siltstone-Some interbedded Sandstone & Shale
 - Coal-(Some Some include Shale Layers)
 - Underclay
 - T.B. - Total Depth
- PRESSURE TEST-PERMEABILITY IN CM/SEC
- 10^{-3}
 - 10^{-4}
 - 10^{-5}
 - Less than 10^{-5}

REFERENCE:-
Plot Plan
C-795-506







EXHIBIT 12

FIGURE 5





NEW YORK STATE ELECTRIC & GAS CORPORATION	
PENNSYLVANIA ELECTRIC COMPANY	
Homer City Station	Units 1 & 2
TWO LICK CREEK DAM	
Geologic Sections	
ENGINEER: GILBERT ASSOCIATES, INC.	
DESIGNED BY: GILBERT ASSOCIATES, INC.	
CHECKED BY: JMS	
DATE: 11-60	


NO.	DATE	DESCRIPTION
1	11-60	AS SHOWN
2	11-60	REVISION

B
C
D
E
F




THIS PAGE IS BEST QUALITY PRACTICABLE FROM COPY FURNISHED TO DDG







SECTION G-G
STA. C+80
BEGIN TRANSITION



SECTION H-H
STA. C+90
TRANSITION ZONE



SECTION J-J
STA. C+40
TRANSITION ZONE



SECTION K-K
STA. C+24
END TRANSITION

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDO

REFERENCES:-
Plan

G-729-418

FIGURE 6

ADDED PERMANENT PIZOMETER LOC	
NO.	DATE
II	10/20/55
Revised Embankment Cord Added Zones A, B, & C	
I	8/30/55

REVISIONS

NEW YORK STATE ELECTRIC & GAS CORPORATION	
PENNSYLVANIA ELECTRIC COMPANY	
Hooper City Station	Units 1 & 2
TWO LICK CREEK DAM	
Rock Fill Embankment	
Sections	
GILBERT ASSOCIATES, INC.	
ENGINEERS AND CONSULTANTS	
DATE	BY
10/20/55	ALM
10/20/55	ALM
10/20/55	ALM
10/20/55	ALM

EXHIBIT 14

A
B
C
D
E
F
G
H

2

THIS PAGE IS BEST QUALITY PRACTICABLE FROM COPY FURNISHED TO DDG





TABLE I

Mode of Circle	Case I	Case II	Case III
I	20°	20°	25°
II	15°	20°	25°
III	15°	20°	25°

$\phi = 15^\circ, \tan 15^\circ = .268, p = 56\%$
 $\phi = 20^\circ, \tan 20^\circ = .364, p = 58\%$
 $\phi = 25^\circ, \tan 25^\circ = .466, p = 20\%$

SUMMARY - CIRCLE ANALYSIS

Section	Circle	Case	X Feet	Y Feet	Z Feet	Σ Ton's Pounds	Lc	Σ T Pounds	Fs	Mode
Maximum	1	I	120.6	41.8	141.8	456,290	0	370,780	1.25	III
"	2	I	124.0	70.0	170.0	521,680	0	380,550	1.37	III
"	3	II	164.6	81.8	181.8	406,220	0	225,150	1.39	III
"	4	III	148.6	83.8	183.8	433,950	0	286,460	1.52	III
Abutment	5	I	84.0	84.0	112.0	31,120	0	22,710	1.37	I
"	6	I	76.0	26.0	102.0	277,180	0	215,340	1.29	II
"	7	II	76.0	68.0	96.0	34,810	0	25,050	1.39	I
"	8	III	96.0	70.0	142.0	290,070	0	211,510	1.37	II

PROPERTIES OF MAT

Material	Moist Weight lb/cu.ft	Saturated Weight lb/cu.ft	Buoyant Weight lb/cu.ft
Rip-Rap	110	-	70
Quarry Eun Rock	110	-	70
Finer Quarry Eun Rock	110	-	70
Filter Material	110	-	70
Impervious Core	129	141	78.5
Random Fill	129	141	78.5
Overburden	118	135	78.5

DESIGN STRENGTH
 $S = (W-U) \tan \phi + c$
 $P = 100\%$

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

PROFESSION
INTAKE CHANNEL
FINISHED GRADE
ELEV. 1105

RUBBLE PROTECTION
FROM ROCK EXCAVATION
12" THICK MIN.

NOTE: COPPERDAM
SUGGESTS
SHOWS IN
STEEL CR

8 SHEET PILE COPPERDAM
20' 18 CELLS - U.S. MP 112 OR EQUAL
TOP ELEV. 1140

1.0' CAMBER
TOP ELEV. 1190

BACKFILL TUNNEL EXCAVATION
TO EL. 1130.0 WITH ROCK FILL

APPROX. 1

Rock FILL


ROCK FILL FOR EDG
SEE DWG. C-726-416

STEEL SHEET PILE, TOP ELEV. 1170.0
U.S. MP 112 OR EQUAL
ROCK FILL BEHIND PILE


STORM WATER
STORAGE LAGOON
(For General Plan)
(See DWG. C-726-411)

CONTACT
STA. 50+00

LIMIT



THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG




Revised Interceptor Ditch			
REVISIONS			
II	2/1/54	EG & JMS	ADD
ADD Interceptor Ditch & Storm Water Storage Lagoon			
I	1/20/54	J.D.M. JMS	ADD

FIGURE 8

NEW YORK STATE ELECTRIC & GAS CORPORATION	
PENNSYLVANIA ELECTRIC COMPANY	
Monter City Station	Units 1 & 2
TWO LICK CREEK DAM	
Plan-1st Stage Construction	
Diversion, Cofferdam & Earth Core	
DESIGNED BY	GILBERT ASSOCIATES, INC.
CHECKED BY	ENGINEERS AND CONSULTANTS

EXHIBIT 17


REVISIONS	DATE	BY	DESCRIPTION




THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG

SECTION A-A

1165
1145
1125




SECTION B-B




SECTION C-C

NOTE:
FOR ADDITIONAL CONCRETE DETAILS
IN SPILLWAY APRON, SEE DWGS
C-116-501, 503 & 504.



THIS PAGE IS FIRST QUALITY REPRODUCTION FROM COPY FURNISHED BY DDC

1183.07



ADDED NOTE	
1	As Shown
2	As Shown
3	As Shown
4	As Shown
5	As Shown
6	As Shown
7	As Shown
8	As Shown
9	As Shown
10	As Shown
11	As Shown
12	As Shown
13	As Shown
14	As Shown
15	As Shown
16	As Shown
17	As Shown
18	As Shown
19	As Shown
20	As Shown
21	As Shown
22	As Shown
23	As Shown
24	As Shown
25	As Shown
26	As Shown
27	As Shown
28	As Shown
29	As Shown
30	As Shown
31	As Shown
32	As Shown
33	As Shown
34	As Shown
35	As Shown
36	As Shown
37	As Shown
38	As Shown
39	As Shown
40	As Shown
41	As Shown
42	As Shown
43	As Shown
44	As Shown
45	As Shown
46	As Shown
47	As Shown
48	As Shown
49	As Shown
50	As Shown
51	As Shown
52	As Shown
53	As Shown
54	As Shown
55	As Shown
56	As Shown
57	As Shown
58	As Shown
59	As Shown
60	As Shown
61	As Shown
62	As Shown
63	As Shown
64	As Shown
65	As Shown
66	As Shown
67	As Shown
68	As Shown
69	As Shown
70	As Shown
71	As Shown
72	As Shown
73	As Shown
74	As Shown
75	As Shown
76	As Shown
77	As Shown
78	As Shown
79	As Shown
80	As Shown
81	As Shown
82	As Shown
83	As Shown
84	As Shown
85	As Shown
86	As Shown
87	As Shown
88	As Shown
89	As Shown
90	As Shown
91	As Shown
92	As Shown
93	As Shown
94	As Shown
95	As Shown
96	As Shown
97	As Shown
98	As Shown
99	As Shown
100	As Shown

REFERENCES:
 General Plan
 Plan-Excavation Contours
 Sections-Additional Concrete
 Sections-Additional Concrete

6-728-422
 6-728-505
 6-728-503
 6-728-508


FIGURE 9

EXHIBIT 18


NEW YORK STATE ELECTRIC & GAS CORPORATION	
PENNSYLVANIA ELECTRIC COMPANY	
Hooper City Station	Units 1 & 2
TWO LICK CREEK DAM	
Concrete	
General Sections	
DESIGNED BY	GILBERT ASSOCIATES, INC.
CHECKED BY	ENGINEERS AND ARCHITECTS
DATE	9-22-63

Vertical Edge of Skin R shall not Depart from a Vertical Line by More than 1/8" in Full Height of Gate.


THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG




PLAN B-B
Scale 1/8"=1'-0"




ASSEMBLY TOLERANCES
(FOR ANY RADIAL PLANE)
Scale 1/8"=1'-0"



SECTION A-A
(3 GATES REQ.)
Scale 1/4"=1'-0"



UPSTREAM ELEVATION
Scale 1/4"=1'-0"



KEY PLAN-GATES & ANCHORAGES
Scale 1"=20'-0"

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

BILL OF MATERIAL				BILL OF MATERIAL			
MARK	DESCRIPTION	NO. REQD.	MATERIAL	MARK	DESCRIPTION	NO. REQD.	MATERIAL
	Gate Structure	2	Structural Steel	726-464-1	Guide Roller Bearing	18	Steel Casting
726-462-1	Lifting Bar	6	Steel Forging	2	Guide Roller	18	Steel Forging
2	Clevis	6	Steel Forging	3	Guide Roller Bushing	18	Bronze & Graphite
3	Pin & Cotter	12	Steel Forging	6	Guide Roller Pin	18	Steel Forging
				5	Lock Plate	18	Steel
				6	Hex Head Cap Screw 5/8"Øx1 1/2" lg.	36	Bronze
726-463-1	Gate Trunnion Bearing	6	Steel Casting	7	Dowel Pin 3/8"Øx5/8" lg.	108	Steel
2	Trunnion Bearing Bushing	6	Bronze	8	Finished Bolt	72	Bolt Steel
3	Finished Bolt	144	Bolt Steel	9	Hex Head Cap Screw 7/8"Øx2 1/2" lg.	36	Bronze
4	Fixed Trunnion Bearing	6	Steel Casting	10	Shims	18	Steel
5	Trunnion Pin	6	Steel Forging				
6	Lock Plate	12	Steel	726-465-1	Bottom Rubber Seal	2	Rubber
7	Hex Head Cap Screw 1"Øx2 1/2" lg.	24	Bronze	2	Corner Rubber Seal	6	Rubber
8	Flat Point Set Screw 5/8"Øx1 1/2" lg.	24	Bolt Steel	3	Side Rubber Seal	3	Rubber
9	Flat Point Set Screw 5/8"Øx2 1/2" lg.	36	Bolt Steel	4	Side Rubber Seal	3	Rubber
10	Dowel Pin 1"Øx1" lg.	48	Steel	5	Side Seal Bar	6	Steel
11	Machine Bolts	72	Bolt Steel	6	Bottom Seal Bar	3	Steel
				7	Seal Bolt (Side)	624	Bolt Steel
				8	Seal Bolt (Bottom)	288	Bolt Steel
				9	Bevel Hanner	208	Steel

REFERENCES:-
Details C-726-460

FIGURE 10

Revised Top of Wall
Elevation

I
REVISIONS

EXHIBIT 19

NEW YORK STATE ELECTRIC & GAS CORPORATION
PENNSYLVANIA ELECTRIC COMPANY
Homer City Station Units 1 & 2


TWO LICK CREEK DAM
Radial Gates

General Arrangement


GILBERT ASSOCIATES, INC.
ENGINEERS AND CONSULTANTS

REVISIONS


THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG




DETAIL "A"
Scale 1/2"=1'-0"




DETAIL "B"
Scale 1/2"=1'-0"



DETAIL "C"
Scale 1/2"=1'-0"




SECTION
Scale 1/2"=1'-0"



ELEVATION-TUBE FOR HEATING ELEMENT


18'-10" c.to.c. Lifting Assemblies




THIS PAGE IS BEST QUALITY PRACTICABLE FROM COPY FURNISHED TO DDG

1" Wire Rope (Socket)
(By Others)
Wearing R
Lifting Assy.
MK726-AGE


SECTION D-D



DETAIL "E-E"
Scale 1/2"=1'-0"



SECTION E-E
Scale 3/4"=1'-0"



DETAIL "D"
Scale 1/2"=1'-0"

Changed Wire Rope Size
I
REVISIONS

FIGURE 11


REFERENCES:-
General Arrangement C-726-450

EXHIBIT 20


NEW YORK STATE ELECTRIC & GAS CORPORATION	
PENNSYLVANIA ELECTRIC COMPANY	
Homer City Station	Units 1 & 2
TWO LICK CREEK DAM	
Radial Gates	
General Arrangement (Detail)	
GILBERT ASSOCIATES, INC.	
4150 C-726-459 E	

Checked by	Checked by
Drawn by	Drawn by
Scale	Scale
Notes	Notes

APPENDIX G
REGIONAL VICINITY MAP



TWO LICK CREEK DAM



CLYMER, PA.

N4037.5—W7900/7.5

1963

PHOTOREVISED 1973
AMS 5165 II NE—SERIES V831

BRUSH VALLEY, PA.

N4030—W7900/7.5

1963

PHOTOREVISED 1973
AMS 5165 II SE—SERIES V831