


AD-A068 828

D'APPOLONIA CONSULTING ENGINEERS INC PITTSBURGH PA
NATIONAL DAM INSPECTION PROGRAM. LAKE ALTOONA DAM. NDI ID NUMBE--ETC(U)
SEP 78

F/G 13/2
DACW31-78-C-0049
NL

UNCLASSIFIED

1 OF 1
AD
A068828



END
DATE
FILMED
6 --79
DDC



LEVEL

41

AD A 068828

SUSQUEHANNA RIVER BASIN
BURGOON RUN, BLAIR COUNTY

PENNSYLVANIA

LAKE ALTOONA DAM

NDI I.D. NO: 532

DDC
REGISTRY
MAY 23 1979

PHASE I INSPECTION REPORT

6 NATIONAL DAM INSPECTION PROGRAM.


Lake Altoona Dam. NDI ID Number 532.
Susquehanna River Basin. Burgoon Run, Blair
County, Pennsylvania. Phase I Inspection
Report.

Distribution Unlimited
Approved for Public Release
Contract No. DACW31-78-C-0049

15

12 76 p.

DDC FILE COPY



PREPARED FOR

DEPARTMENT OF THE ARMY
BALTIMORE DISTRICT, CORPS OF ENGINEERS
BALTIMORE, MARYLAND 21203

BY

D'APPOLONIA CONSULTING ENGINEERS
10 DUFF ROAD

PITTSBURGH, PA. 15235

11

SEPTEMBER 1978

ORIGINAL CONTAINS COLOR PLATES: ALL DDC
PRODUCTIONS WILL BE IN BLACK AND WHITE

411001

79 03 14 10

134
+32

This document has been approved
for public release and sale; its
distribution is unlimited.

PHASE I REPORT
NATIONAL DAM INSPECTION PROGRAM

NAME OF DAM: Lake Altoona
STATE LOCATED: Pennsylvania
COUNTY LOCATED: Blair
STREAM: Burgoon Run, secondary tributary to Beaverdam Branch of
Juniata River
DATE OF INSPECTION: August 9 and 16, 1978

ASSESSMENT: Based on the evaluation of the conditions as they existed on the dates of inspection and as revealed by visual observation, the condition of Lake Altoona Dam is considered to be fair. However, city personnel reported that the upstream controls for the lake blow-off valve are not functional. Therefore, it is recommended that the owner immediately evaluate the functional condition of the blow-off valve and perform necessary maintenance. It is also recommended that the ponded water below the toe of the dam be drained and that the flow from this area be monitored and recorded.

Because sudden release of water in the event of a failure of the Fabridam spillway gates may cause property damage downstream and because of the unique nature of these gates, this appurtenance should be frequently inspected by personnel experienced in design, construction, maintenance, and operation of such equipment.

The spillway capacity is classified to be "seriously inadequate" (48 percent PMF if the Fabridam gates deflate, 29 percent PMF if they do not), because it is estimated that overtopping would result in failure of the dam and damage potential would be significantly higher than would exist prior to overtopping.

Since the spillway capacity was determined based on the Corps of Engineers' approximate analysis procedure, it is recommended that the owner reevaluate the spillway capacity using more accurate analysis techniques.

It is recommended that the owner provide around-the-clock surveillance during unusually heavy runoff to detect possible problems and develop a formal warning system to alert the downstream residents in the event of an emergency.



Lawrence D. Andersen
Lawrence D. Andersen, P.E.
Vice President

APPROVED BY:

G. K. Withers

G. K. WITHERS
Colonel, Corps of Engineers
District Engineer

28 Sep 78

Date

ACCESSION for	
NTIS	White Section <input checked="" type="checkbox"/>
DDC	Buff Section <input type="checkbox"/>
UNANNOUNCED	<input type="checkbox"/>
JUSTIFICATION	
BY	
DISTRIBUTION/AVAILABILITY CODES	
	SPECIAL
A	

LAKE ALTOONA DAM
NDI I.D. NO. 532
AUGUST 9, 1978



Upstream Face



Downstream Face

TABLE OF CONTENTS

	<u>PAGE</u>
SECTION 1 - PROJECT INFORMATION	1
1.1 General	1
1.2 Description of Project	1
1.3 Pertinent Data	2
SECTION 2 - ENGINEERING DATA	5
2.1 Design	5
2.2 Construction	6
2.3 Operation	7
2.4 Other Investigations	7
2.5 Evaluation	7
SECTION 3 - VISUAL INSPECTION	9
3.1 Findings	9
3.2 Evaluation	10
SECTION 4 - OPERATIONAL FEATURES	11
4.1 Procedures	11
4.2 Maintenance of the Dam	11
4.3 Maintenance of Operating Facilities	11
4.4 Warning System	11
4.5 Evaluation	11
SECTION 5 - HYDRAULICS AND HYDROLOGY	12
5.1 Evaluation	12
SECTION 6 - STRUCTURAL STABILITY	14
6.1 Evaluation of Structural Stability	14
SECTION 7 - ASSESSMENT AND RECOMMENDATIONS/REMEDIAL MEASURES	15
7.1 Dam Assessment	15
7.2 Recommendations/Remedial Measures	15

TABLE OF CONTENTS
(Continued)

PLATES
APPENDIX A - CHECKLIST, VISUAL INSPECTION, PHASE I
APPENDIX B - CHECKLIST, ENGINEERING DATA, DESIGN, CONSTRUCTION,
OPERATION, PHASE I
APPENDIX C - PHOTOGRAPHS
APPENDIX D - CALCULATIONS
APPENDIX E - REGIONAL GEOLOGY

PHASE I REPORT
NATIONAL DAM INSPECTION PROGRAM
LAKE ALTOONA DAM
NDI I.D. NO. 532
DER I.D. NO. 7-8

SECTION 1
PROJECT INFORMATION

1.1 General

a. Authority. The inspection was performed pursuant to the authority granted by The National Dam Inspection Act, Public Law 92-367, to the Secretary of the Army, through the Corps of Engineers, to conduct inspections of dams throughout the United States.

b. Purpose. The purpose of this inspection was to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project

a. Dam and Appurtenances. The Lake Altoona Dam consists of an earth embankment 1600 feet long and with a maximum height of 73 feet from the downstream toe. The dam essentially forms an offstream reservoir. A 20-foot-wide trapezoidal channel along the north side of the reservoir diverts the normal flow of Burgoon Run past the reservoir. The reservoir receives controlled inflow from the diversion channel. The reservoir would also receive any discharge from the primary spillway of Lower Dam, which in turn receives controlled inflow from the diversion channel and from the spillway of the Upper Kittanning Reservoir. The combined primary and emergency spillway is located on the left abutment (looking downstream). As designed, the spillway is an overflow section 8.5 feet below the dam crest. The spillway is equipped with inflatable Fabridam gates which can be raised four feet, leaving a freeboard of 4.5 feet to the dam crest. The spillway exit channel is a trapezoidal concrete channel which discharges into the diversion channel. The outlet works for the dam consist of an intake tower, 60-inch-diameter blow-off pipe, and 36-inch-diameter supply line. Flow from these pipes is controlled by the valve located in the intake tower. The 60-inch blow-off pipe constitutes the emergency drawdown facility for the dam.

b. Location. Lake Altoona Dam is located in Burgoon Run Valley, about one mile downstream from the tunnels under the Penn-Central railroad Horseshoe Curve in Logan Township, Blair County, Pennsylvania. The dam is the lowermost reservoir in the series of three reservoirs in the Burgoon Valley and is located about three miles upstream from the city line of Altoona (Plate 1).

The normal runoff from the Burgoon Run watershed is diverted through a channel bypassing the reservoir (Plate 2). The excess flow into the reservoir is discharged over the spillway into the diversion channel which terminates at a plunge pool at the toe of the dam.

Downstream from the dam, Burgoon Run follows a rocky channel and flows through residential areas of Altoona. It is estimated that the failure of this dam would cause large loss of life and property damage in Altoona and further downstream. It is further estimated that the failure of the upper two reservoirs would result in the failure of this dam.

c. Size Classification. Intermediate (based on 73-foot height).

d. Hazard Classification. High.

e. Owner. City of Altoona (address: Mr. William L. Cochran, Director, Water, Parks, and Public Property, City of Altoona, Altoona, Pennsylvania 16601).

f. Purpose of Dam. Water supply.

g. Design and Construction History. The dam was designed in 1906 by Mr. C. W. Knight, a consulting engineer from Rome, New York, to be a 90-foot-high embankment. However, it was only completed to a 73-foot height. The dam was constructed by O'Rorke Construction Company of Altoona and Carothers Construction Company of Greensburg, Pennsylvania. The construction of the dam was completed in 1913.

h. Normal Operating Procedure. The normal operating procedure is to maintain the lake level at the crest level of the inflatable gates, which would leave 4.5 feet of freeboard to the top of the dam. The flow occurring when the pool level is at or above the crest of the inflatable gates will be discharged over the spillway into the diversion channel.

1.3 Pertinent Data

a. Drainage Area (square miles) - 1.7 (direct) + 11.2 (diversion channel)

b. Discharge at Dam Site (cfs)

Maximum known flood at dam site - Unknown

Warm water outlet at pool elevation - N/A --

Diversion tunnel low pool outlet at pool elevation - N/A

Diversion tunnel outlet at pool elevation - N/A

Gated spillway capacity at pool elevation - N/A

Gated spillway capacity at maximum pool elevation -

9,300 (without Fabridam), 5200 (with Fabridam inflated)
at Elevation 1364

Total spillway capacity at maximum pool elevation -
9,300 (without Fabridam), 5200 (with Fabridam
inflated) at Elevation 1364

c. Elevation (USGS Datum) (feet)

Top of dam - 1364
Maximum pool-design surcharge - N/A
Full flood control pool - N/A
Recreation pool (normal pool) - 1355.5 (spillway crest)
Spillway crest - 1355.5 (concrete crest); 1359.5
(Fabridam inflated)
Upstream portal invert diversion tunnel - N/A
Downstream portal invert diversion tunnel - N/A
Streambed at center line of dam - 1285 (estimated)
Minimum tailwater - Unknown

d. Reservoir (feet)

Length of maximum pool - 2700 at Elevation 1364
Length of recreation pool (normal pool) - 2500 at
Elevation 1355.5
Length of flood control pool - N/A

e. Storage (acre-feet)

Recreation pool (normal) - 1842 at Elevation 1355.5
Flood control pool - N/A
Design surcharge (maximum) - 2790 at Elevation 1364
Top of dam - 2790 at Elevation 1364

f. Reservoir Surface (acres)

Top of dam - 107± (estimated)
Maximum pool - N/A
Flood control pool - N/A
Recreation pool (normal) - 85 at Elevation 1355.5
Spillway crest - 85 at Elevation 1355.5

g. Dam

Type - Earth
Length - 1650 feet
Height - 73 feet
Top width - 20 feet
Side slopes - 2H:1V (upstream and downstream)
Zoning - Yes
Impervious core - None
Cutoff - Concrete cutoff wall
Grout curtain - No

h. Diversion and Regulating Tunnel

Type - 60-inch-diameter cast iron

Length - 200± feet

Closure - Valve

Access - Gates at intake tower

Regulating facilities - Gates

i. Spillway

Type - Broad-crested overflow section

Length of weir - 132 feet (as measured)

Crest elevation - 1359.5 (top of inflated Fabridams), 1355.5
(concrete crest)

Gates - Inflatable Fabridams

Upstream channel - Lake

Downstream channel - Trapezoidal concrete channel

SECTION 2
ENGINEERING DATA

2.1 Design

a. Data Available

(1) Hydrology and Hydraulics. No original design data were found relative to the hydrology and hydraulics for the dam. A report prepared by Hazen, Whipple and Fuller Consulting Engineers of New York, New York, dated May 27, 1921, includes a recommended capacity for enlargement of the spillway.

(2) Embankment. State and owner files include a limited number of design drawings for the dam.

(3) Appurtenant Structures. Limited design drawings were found for the outlet works and spillway.

b. Design Features

(1) Embankment

- a. As designed, the dam was supposed to be a 90-foot-high embankment with its crest at Elevation 1383 (Plate 3). However, the dam was only completed to Elevation 1364.
- b. As designed, the dam is essentially a homogeneous embankment with a concrete cutoff wall extending from six feet below the present crest elevation to about 20 feet into the original ground level (Plate 4). As constructed the cutoff wall is about 20 feet downstream of the dam center line.
- c. The embankment, as it exists, has two to one (horizontal to vertical) slopes on both the downstream and upstream slopes (Plate 5). The downstream slope of the dam is broken by two benches: a 40-foot-wide bench 33 feet below the dam, and a 25-foot-wide bench 58 feet below the dam crest.
- d. A design drawing (Plate 6) indicates at least six holes were drilled to investigate the subsurface conditions at the site. The borings indicate that the typical subsurface condition at the site consists of 10 to 30 feet of overburden underlain by alternating layers of

sandstone and shale. The borings were extended from 30 to 70 feet into the foundation rock.

c. Appurtenant Structures. The appurtenant structures for the dam consist of the combined primary and emergency spillway and the outlet works (Plate 7). The spillway crest is equipped with inflatable Fabridams which were installed to increase storage capacity of the reservoir. The combined primary and emergency spillway for the dam is located on the left abutment and discharges into the diversion channel which terminates at a plunge pool at the toe of the dam (Plate 8). The inflatable Fabridam gates on the spillway were designed by N. M. Imberson and Associates, Inc., of Burbank, California, and were installed in 1968. These gates were designed to be inflated either by water or air. However, city personnel reported that only air has been used in the past. Controls for the gates are located in a control house on the right side of the spillway.

Design reports indicate that when the Fabridam gates are under automatic operation, they start to deflate when the water depth over the bags reaches six inches and completely deflate when the water depth over the bags reaches three feet. The bags may also be deflated manually.

The outlet works for the dam consist of an intake tower, a 60-inch cast-iron blow-off pipe, and 36-inch supply line. The flows through these lines are controlled by valves and sluice gates located at the intake tower. Plates 9 and 10 illustrate the cross section and details of the intake tower.

d. Design Data

(1) Hydrology and Hydraulics. The 1921 report by Hazen, Whipple and Fuller Consulting Engineers recommended the design capacity of the spillway be increased to 3000 cubic feet per second (cfs) which would bring the total flood discharge capacity of the reservoir and diversion channel to 4000 cfs.

(2) Embankment. Other than the available design drawings, no other data were found on the design of the dam.

(3) Appurtenant Structures. There are no design data on the appurtenant structures.

2.2 Construction. Very limited information is available on the construction of the dam. Available information indicates that construction of the dam was under the supervision of Mr. C. W. Knight, the consulting engineer and designer of the dam. To the extent that can be determined, the construction of the dam was apparently conducted in accordance with the plans and specifications. No reference was

found to indicate that any unusual problems were encountered during construction of the dam.

2.3 Operation. As reported by city personnel, no formal operating procedures exist for the dam. It is understood that when the reservoir level rises above the concrete spillway level, the spillway gates are inflated to increase the storage capacity of the dam. The Fabridams are deflated when the reservoir level falls below the concrete spillway level. These gates are controlled from a control house adjacent to the spillway.

The 60-inch blow-off pipe for the dam is controlled by a sluice gate located in the intake tower. However, city personnel reported that the gate is not functional.

2.4 Other Investigations. Available information includes the following two investigation reports: Altoona Water Works Report on the Spillway and Flood Channels, May 27, 1921, by Mr. Allen Hazen of Hazen, Whipple and Fuller Consulting Engineers, New York, New York; and a letter report addressed to the Water Commission of Pennsylvania, dated October 4, 1920, by Mr. Arthur E. Morgan, Morgan Consulting Company, Dayton, Ohio.

2.5 Evaluation

a. Availability. The available information was obtained from the owner and PennDER files.

b. Adequacy

(1) Hydrology and Hydraulics. Available information includes design capacities of the spillways.

(2) Embankment. Available information consists of a limited number of construction drawings. No quantitative geotechnical information is available to aid the assessment of the adequacy of the design.

(3) Appurtenant Structures. Limited information is available on the design of the outlet works and the spillway. Plates 9 and 10 show the details of the intake tower and the arrangements of the control valves. No information is available on the structural details of the pipes through the embankment, such as concrete encasements or the like.

c. Operating Records. No formal operating records are available.

d. Post-Construction Changes. The available information indicates that the present spillway for the reservoir was constructed in 1929, about 13 years after completion of the dam. No other reference was found to indicate changes to the dam after its completion.

e. Seismic Stability. The dam is located in Seismic Zone 1, and based on visual observations, the static stability of the dam is considered to be adequate. Therefore, according to the recommended criteria for evaluation of seismic stability of dams, the structure is presumed to present no hazard from earthquakes.

SECTION 3
VISUAL INSPECTION

3.1 Findings

a. General. The on-site inspection of the Lake Altoona Dam consisted of:

1. Visual inspection of the embankment, abutments, and embankment toe.
2. Visual examination of the spillway and its components, the downstream end of the outlet pipe, and other appurtenant features.
3. Observation of factors affecting the runoff potential of the drainage basin.
4. Evaluation of downstream area hazard potential.

The specific observations are illustrated in Plate 7 and in the photographs in Appendix C.

b. Embankment. The general inspection of the embankment consists of searching for indications of structural distress, such as cracks, subsidence, bulging, wet areas, seeps and boils, and observing general maintenance conditions, vegetative cover, erosion and other surficial features. Extensive wet areas were found downstream from the toe of the dam. The wet areas included numerous pools of perched water. Although no significant flow was observed, it is possible that perched water is fed by seepage through the dam.

Although large trees and brush have been recently removed from the downstream face of the embankment, in some areas the brush is two to three feet high and requires further clearing. High brush and fallen trees obstructed the adequate inspection of the area below the toe of the dam.

c. Appurtenant Structures. The spillway crests, channels, and plunge pool were examined for deterioration, other signs of distress, and any obstruction that would limit flow. In general, the structures were found to be in fair condition. The concrete in the spillway discharge channel was found to be deteriorating, requiring maintenance. The concrete and diversion channel was also found to be deteriorating due to the action of acid mine drainage. A portion of the spillway channel wall was missing, and the dam tender reported that this section of the wall had been removed during the construction of the Fabridam gates and has never been replaced. This condition poses a potential for flow from the spillway to discharge over the embankment which may cause erosion on the dam face.

The operation of the Fabridam spillway gates was explained by the dam tender, identifying manual deflation procedures. It was reported that although the Fabridams can be inflated either by air or water only the air is being used.

d. Reservoir Area. A map review indicates that the watershed area is predominantly covered by woodland; however, some portions have been strip mined. A review of the regional geology (Appendix E) indicates that the shorelines are not likely to be susceptible to massive landslides which would affect the storage volume of the reservoir or cause overtopping of the dam by displaced water.

e. Downstream Channel. Downstream from the dam, Burgoon Run follows a course through residential areas of Altoona, obstructed by numerous bridges. The stream joins Mill Run, which is a tributary of Beaverdam Branch of Juniata River, three miles downstream of Altoona Dam, south of the city limits of Altoona. Photographs in Appendix C illustrate the course of the stream through Altoona.

3.2 Evaluation. In general, while the condition of the dam is considered to be good, the condition of the operating facilities is considered to be poor. City maintenance personnel reported that the blow-off valve is not functional, requiring immediate maintenance and necessary repairs. Although extensive wet areas were observed below the toe of the dam, the amount of seepage from these areas was considered to be small. Observed seepage was clear and no signs of internal erosion were found.

The maintenance condition of the control equipment for the Fabridam spillway gate is considered to be satisfactory. However, because a sudden release of water in the event of failure of the spillway gates may cause property damage downstream and considering the unique nature of the Fabridam spillway gates, it is considered advisable that these facilities be periodically inspected by engineers experienced in design, installation, and maintenance of such equipment.

SECTION 4
OPERATIONAL FEATURES

4.1 Procedures. City personnel reported that there are no formal operating procedures for the dam. When the reservoir level rises to the spillway crest elevation, the Fabridam gates are inflated to increase the storage capacity for the reservoir. The Fabridams are deflated when the reservoir level falls below the concrete spillway level. Two operational features of the dam which may affect safety are the drainpipe valve, if it is required to lower the reservoir, and the Fabridam spillway gates in the event of large floods.

4.2 Maintenance of the Dam. The general condition of the dam is considered to be satisfactory. Periodic removal of the brush from the downstream face of the dam and the area below the toe is required.

4.3 Maintenance of Operating Facilities. City maintenance personnel reported that the blow-off valve has not been functional. Visual observations indicate that the operating equipment is in poor condition.

4.4 Warning System. No formal warning system exists for the dam. The dam is maintained by city personnel operating from Altoona, about four miles from the site. Telephone communication is available at the dam tender's residence at the dam site.

4.5 Evaluation. While the condition of the embankment is considered to be fair, requiring periodic removal of the brush from the downstream face of the dam and the area below the toe, the condition of the operating equipment is considered to be poor. It is reported that the valve for the blow-off pipe is not functional, and this requires immediate maintenance and necessary repairs. The maintenance condition of the operating equipment for the Fabridam gates is considered to be satisfactory.

However, in view of the unique nature of these Fabridam spillway gates, it is considered advisable that these facilities be periodically inspected by personnel experienced in design, construction, operation, and maintenance of such facilities.

SECTION 5
HYDRAULICS AND HYDROLOGY

5.1 Evaluation

a. Design Data. Lake Altoona Dam has a direct watershed area of 1.7 square miles and impounds a reservoir with a surface area of 107 acres. A diversion channel along the left side of the reservoir carries the normal flow from the watershed past the reservoir. Under normal flow conditions, the reservoir only receives controlled inflow from the diversion channel. The diversion channel at Lake Altoona Dam has a watershed of 11.2 square miles.

Excess inflow into Lake Altoona would be discharged through the combined primary and emergency spillway. The capacity of the spillway is estimated to be 5200 cfs with the spillway gates fully inflated and 9300 cfs with the spillway gates deflated, with no freeboard.

In the event of a flood which exceeds the discharge capacity of the diversion channel, Lake Altoona would receive uncontrolled inflow through the spillway of Lower Kittanning Dam and the diversion overflow section on Scotch Gap Run. The flood flow into the reservoir would be discharged over the spillway of the dam.

There are two reservoirs upstream from Lake Altoona. The combined full storage volume of the Upper Kittanning and Lower Kittanning Dams is estimated to be 1380 acre-feet which is greater than the surcharge storage volume of Lake Altoona (920 acre-feet, Fabridams deflated). Therefore, it is estimated that failure of one of the upper dams would result in the overtopping and failure of Lake Altoona Dam. The combined flood discharge would cause large loss of life and property damage in Altoona.

The spillway capacities of the two upstream reservoirs were classified to be "seriously inadequate."

b. Experience Data. Lake Altoona Dam is classified to be an "intermediate" size dam in the "high" hazard category. Under recommended criteria for evaluating spillway capacity, such impoundments are required to pass full PMF. The adequacy of the spillway was analyzed based on the simplified procedure developed by the Baltimore District, Corps of Engineers (Appendix D). Based on this procedure, it was determined that the PMF hydrograph would have a peak flow of 28,000 cfs and a total volume of approximately 17,800 acre-feet. Since the surcharge storage volume of the upstream reservoirs (320 acre-feet) is much smaller than the total volume of the PMF, the effect of the upstream reservoirs in reducing the peak flow rate would be negligible.

The spillway capacity of the upstream reservoirs was determined to be 28 percent PMF. Since the failure of the upper reservoir would result in failure of Lake Altoona Dam, the flood discharge capacity would also be 28 percent. A further analysis was conducted assuming that the overtopping of the upstream reservoirs would not result in a dam failure. In that event, it was determined that the spillway can pass a maximum flow of 48 percent PMF without overtopping the dam when the spillway gates are fully deflated and 29 percent PMF if the gates are fully inflated.

c. Visual Observations. On the dates of inspection, no conditions were observed that would indicate that the spillway of the dam would not function satisfactorily in the event of a flood. If the automatic deflation systems of the Fabridams fail, they can be deflated by the operation of manual controls.

d. Overtopping Potential. As stated above, the spillway can pass 48 percent PMF without overtopping when the Fabridam spillway gates are fully deflated.

e. Spillway Adequacy. As previously stated, the capacity of the spillway is less than 50 percent PMF. It is estimated that overtopping of the dam would result in failure of the dam and downstream damage potential would significantly increase compared to that which would exist just before overtopping failure.

Based on the above results, the spillway is classified to be "seriously inadequate" according to the recommended criteria.

SECTION 6
STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations. As discussed in Section 3, the field observations did not reveal any signs of distress that would significantly affect the short-term stability of the dam at this time. Review of available information and visual observations in the field indicate that the dam has been built with reasonable care, and no unsatisfactory conditions were reported in the past. Extensive areas of ponded water exist downstream of the dam, but the seepage quantity appeared to be small and no signs of internal erosion of the embankment were observed.

b. Design and Construction Data

(1) Embankment. The dam was designed at a time (1906 and 1913) when limited understanding of the geotechnical behavior of earth structures existed. Consequently, the available design and construction information includes no quantitative data to aid the assessment of embankment stability.

(2) Appurtenant Structures. No information is available on the structural design of the outlet works.

c. Operating Records. The structural stability is not considered to be affected by the operational features of the dam.

d. Post-Construction Changes. No post-construction changes were reported that would significantly affect the structural stability of the dam.

SECTION 7
ASSESSMENT AND RECOMMENDATIONS/REMEDIAL MEASURES

7.1 Dam Assessment

a. Assessment. The visual observations and review of available information indicate that Lake Altoona Dam is in fair condition. It appears that the dam was constructed with reasonable care. Field observations did not reveal any significant signs of distress and none were reported in the past.

The condition of the operational facilities is considered to be poor. It was reported that the blow-off valve is not functional.

The spillway is considered to be "seriously inadequate" because its capacity (48 percent PMF if the Fabridam gates deflate, 29 percent if the gates do not deflate) is less than 50 percent PMF and because it is estimated that overtopping of the embankment would result in failure, significantly increasing the downstream hazard potential which existed just prior to overtopping.

b. Adequacy of Information. The available information in conjunction with visual observations and previous experience of the inspectors are considered to be sufficient to make a reasonable assessment of the dam.

c. Urgency. The first four recommendations should be implemented immediately and the other recommendations should be acted upon as soon as practicable or on a continuing basis.

d. Necessity for Further Investigation. The adequacy of the spillway is considered to require immediate further investigation. The embankment is considered to require no further investigation.


7.2 Recommendations/Remedial Measures

1. The owner should initiate additional hydrology and hydraulic studies to more accurately ascertain the spillway capacity and to determine the nature and extent of remedial measures required to increase the spillway capacity.
2. It is recommended that the owner immediately evaluate the operational condition of the blow-off pipe valve and perform necessary maintenance and adequately maintain the equipment.

3. Brush and trees below the toe of the dam should be cleared to the limit of the ponded area and this area regraded to drain the ponded water. The quantity of flow from this area should be measured and recorded, and the turbidity of the flow should be noted. If flow increases, a detailed study and necessary remedial action should be undertaken.
4. The portion of the spillway wall that was reported as removed during the construction of the Fabridam gates should be replaced to eliminate the potential threat of high flows from the spillway discharging over the embankment and causing erosion of the downstream face of the dam.
5. Due to the unique nature of the Fabridam spillway gates and since a sudden release of water in the event of their failure may cause property damage downstream by overflowing the channel in a residential area of Altoona, this appurtenance should be frequently inspected by personnel experienced in design, construction, maintenance, and operation of such equipment.
6. It is recommended that the owner provide around-the-clock surveillance during unusually heavy runoff and develop a formal warning system to alert the downstream residents in the event of an emergency.
7. It is recommended that the owner be advised that the dam and appurtenant structures be inspected regularly and necessary maintenance be performed.

PLATES

DRAWN BY **DJD** CHECKED BY **BE** DRAWING NUMBER **78-114-B154**
 APPROVED BY **AMP** DATE **9-7-78**



REFERENCE:
 U.S.G.S., 7.5', ASHVILLE, ALTOONA AND CRESSON QUADRANGLE. PHOTOREVISED 1972, SCALE - 1:2000.
 U.S.G.S., 7.5', HOLLIDAYSBURG PA. QUADRANGLE DATE: 1963, SCALE - 1:2000.







PLATE I

LAKE ALTOONA DAM
VICINITY, FLOOD PLAIN AND WATERSHED MAP

D'APPOLONIA

8

DRAWN BY	Tfs	CHECKED BY	9-7-78	DRAWING NUMBER	78-114-B160
BY	9-5-78	APPROVED BY	JHP	NUMBER	9-7-78



LEGEND
 → COURSE OF NORMAL FLOW

DO NOT SCALE THIS DRAWING.






PLATE 2
 LAKE ALTOONA DAM
 DIVERSION CHANNEL PLAN
D'APPOLONIA

DRAWN BY	Trs	CHECKED BY	RF	DATE	9-7-78	DRAWING NUMBER	78-114-B161
BY	9-5-78	APPROVED BY	JMP	DATE	9-7-78		



Section of Stall
 Scale 1"

CITY OF ALTOONA, PA.
DEPARTMENT OF WATER.




Top of Embankment.
 All too Proj 3003.
 Scale 1" = 10'.


PLATE 3

D'APPOLONIA

DRAWN BY D.J.D. 8-30-78 CHECKED BY *BE* 9-7-78 DRAWING NUMBER 78-1-B140
 APPROVED BY *JHP* 9-7-78



CITY OF ALTOONA, PA.
DEPARTMENT OF WATER.
PROFILE OF CORE WALL.
1909.



Knight and Hopkins, Consulting Engineers, Rome, N.Y. Dwg. No. 3271.

PLATE 4

D'APPOLONIA

2

DRAWN BY
 D.J.D.
 8-30-78

CHECKED BY
 B.F.


APPROVED BY
 J.H.P.

DRAWING NUMBER
 78-114-B148


9-7-78
 9-7-78

SECTIONS OF MAIN
 LAKE ALTOUR

As Originally designed for
 Completed Dam



PROFILE OF BY WASH CHANNEL



THIS PAGE IS BEST QUALITY PRACTICABLE
 AND COPY FURNISHED TO DDC





PLATE 5

D'APPOLONIA

DRAWN BY D.J.D. 8-30-78
 CHECKED BY R.F. 9-7-78
 APPROVED BY J.H.P. 9-7-78
 DRAWING NUMBER 78-114-B144




CITY OF ALTOONA
DEPARTMENT OF WATER
 Profile: Showing Bore Holes for
 also Assumed Rock Surface
 Bottom of Core Wall.
 1906.


THIS DRAWING IS BEST QUALITY PRACTICE
 FROM COPY FURNISHED TO DDC

COONA, PA. OF WATER.



Plan for Core Wall
 Rock Surface and
 Wall.



DRAWN BY D.J.D. 8-30-78 CHECKED BY JHO 9-7-78 APPROVED BY JHO 9-7-78 DRAWING NUMBER 78-114-B147



THIS PAGE IS BEST QUALITY PRACTICABLE FROM COPY FURNISHED TO DDG



This Plan shows Details for Contract. Elevations will change for 5(a) in general, shown on Profile of By Wash and Cross Section of Dam Plan No. 3129.

SCHEDULE OF QUANTITIES

Item	QUANTITIES		ITEMS
	Contract No. 5-A	Contract No. 5	
34001 .30	700	3115	Cu. Yards Excavation in Rolled Fills
34027 .30	39000	3500	Fills in Rolled Embankment
.30	13	86	Removal of Concrete Caisson and Bridge Abutment
1922 14.00	160	108	1-2-4 Concrete in Core Wall
1962.2 14.00	1870	15	1-2-5 " " " "
30.36 19.00	11	11	1-2-4 " " in Wall Converting Vertical to Slope Section
136.5 3.00	225	225	Cu. Yards Stone Masonry
2784.3 3.00	1200	1200	Sq. Yards 8" Reinforced Concrete Paving 1-2-3 1/2 Bottom of Channel
57.5 3.50	830	830	" " 8" Reinforced Concrete Slope Paving 1-2-3 1/2
46.8 22.00	40	40	Cu. Yards 1-2-3 1/2 Cohesive in Vertical 2 Feet of Wall
3014.6 1.50	4900	2100	Sq. Yards 12" Stone Paving in front of Spillway
			12" Stone Slope Retention face of dam

\$37,507.88 - Total Contract Cost



LEGEND:
 - - - - - Top of Completed Dam Proposed
 - - - - - Existing Structures
 - - - - - Proposed

CITY OF ALTOONA
 BUREAU OF ENGINEERING
 TEMPORARY SPILLWAY
 LAKE ALTOONA
 Scale Top Map 1/2" = 1'-0"
 Details Scales As Shown

CITY OF ALTOONA, PA.
DEPARTMENT OF WATER
DETAILS OF SHEET A

1906

PLAN OF LOWER END OF BY-WASH
Scale 1"=8'







Knight and Hopkins, Engineers, Rome, N.Y. Dwg #2970


PLATE 8

D'APPOLONIA

DRAWN BY D.J.D.
 CHECKED BY B.E.
 APPROVED BY J.P.P.
 8.30.78
 9.7.78
 9.7.78
 DRAWING NUMBER 78-114-B142



PLAN OF GATE HOUSE AND BRIDGE
Scale 1"=8'





THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

CITY OF ALTOONA, PA.
DEPARTMENT OF WATER
DETAILS OF SHEET A
1906

Knight and Hopkins, Engineers, Rome, N.Y. Drawg 2968

DRAWN BY: DJ.D. CHECKED BY: BE 9-7-78 DRAWING NUMBER: 78-114-B141
 APPROVED BY: JHP 5-7-78





CITY OF ALTOONA, PA.
 DEPARTMENT OF WATER
 DETAILS OF SHEET A

1906

THIS PAGE IS BEST QUALITY PRACTICABLE
 FROM COPY FURNISHED TO DDC


PLAN OF GATE CHAMBER
 Scale 1" = 4'



SECTION E-F
 Scale 1" = 8'

Knight and Hopkins, Engineers, Rome, N.Y. Ord. #2966

DRAWN BY: MBM
 CHECKED BY: [Signature]
 8-21-78 APPROVED BY: [Signature]
 9-7-78 DRAWING NUMBER: 14-A23
 9-7-78



NOT TO SCALE

POOL LEVEL DATE OF INSPECTION: 5'-8" BELOW DAM CREST

PLATE II
 LAKE ALTOONA DAM NDI ID 532
 GENERAL PLAN
 FIELD INSPECTION NOTES
 FIELD INSPECTION DATE: AUGUST 9, 1978

D'APPOLONIA

APPENDIX A
CHECKLIST
VISUAL INSPECTION
PHASE I

VISUAL INSPECTION
 PHASE I
 EMBANKMENT

NAME OF DAM LAKE ALGONA DAM
 ID# NDI: 532 DER: 7-8

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	NONE FOUND	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	NONE FOUND	
SLOUCHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	NONE FOUND	
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	NO PERCEIVABLE MISALIGNMENT	
RIPRAP FAILURES	NONE FOUND.	

VISUAL INSPECTION
 PHASE I
 EMBANKMENT
 OBSERVATIONS

NAME OF DAM LAKE ALTOONA DAM

ID# NDI : S32 DER: 7-8

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	NO VISUAL SIGNS OF DISTRESS, NO SEEPAGE.	
ANY NOTICEABLE SEEPAGE	PERCHED WATER POOLS BELOW TOE	SEE PLATE II
STAFF GAGE AND RECORDER	NONE	
DRAINS	NONE	

VISUAL INSPECTION
 PHASE I
 CONCRETE/MASONRY DAMS

NAME OF DAM LAKE ALTOONA DAM
 ID# NDI: 532 DEC: '78

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
ANY NOTICEABLE SEEPAGE	EARTH FILL DAM N/A	
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS	N/A	
DRAINS	N/A	
WATER PASSAGES	N/A	
FOUNDATION	N/A	

VISUAL INSPECTION
 PHASE I
 CONCRETE/MASONRY DAMS

NAME OF DAM LAKE ALTONA DAM
 IN# NDI: 532 DCR: 7-8

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES	EARTH FILL DAM N/A	
STRUCTURAL CRACKING	N/A	
VERTICAL AND HORIZONTAL ALIGNMENT	N/A	
MONOLITH JOINTS	N/A	
CONSTRUCTION JOINTS STAFF GAGE OF RECORDER:	N/A	

VISUAL INSPECTION
 PHASE I
 OUTLET WORKS

NAME OF DAM LAKE ALTOONA DAM
 ID# NDI: 532 DER: 7-8

VISUAL EXAMINATION OF CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
INTAKE STRUCTURE	Φ60-INCH CAST IRON BLOW-OFF PIPE.	
INTAKE STRUCTURE	INTAKE TOWER (WET)	
OUTLET STRUCTURE	NO OUTLET STRUCTURE. PIPE WOULD DISCHARGE DIRECTLY INTO THE DIVERSION CHANNEL PLUNGE POOL.	
OUTLET CHANNEL	NATURAL STREAM CHANNEL.	
EMERGENCY GATE	CITY PERSONNEL REPORTED THAT THE BLOW-OFF PIPE SLUICE GATE IS NOT FUNCTIONAL.	

THIS PAGE IS BEST QUALITY PRACTICABLE
 FROM COPY FURNISHED TO DDC

VISUAL INSPECTION
 PHASE I
 UNGATED SPILLWAY

NAME OF DAM LAKE ALTOONA DAM
 ID# NDI: 532 DCR: 7-8

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	SPILLWAY IS GATED. N/A.	
APPROACH CHANNEL	N/A	
DISCHARGE CHANNEL	N/A	
BRIDGE AND PIERS	N/A.	

VISUAL INSPECTION
 PHASE I
 GATED SPILLWAY

NAME OF DAM LAKE ALTOONA DAM
 ID# NDI: 532 DER: 7-8

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE SILL	CONCRETE OVER-FLOW SECTION, EQUIPED WITH INFLATABLE FABRIDAMS.	
APPROACH CHANNEL	LAKE.	
DISCHARGE CHANNEL	TRIANGULAR CONCRETE CHANNEL DETERIORATING CONCRETE IN DISCHARGE CHANNEL.	
BRIDGE PIERS	NO BRIDGE ACROSS THE CONTROL SECTION.	
GATES AND OPERATION EQUIPMENT	INFLATABLE FABRIDAM GATES. INFLATED BY AIR DATE OF INSPECTION GATE CAN ALSO BE INFLATED BY WATER.	

VISUAL INSPECTION
 PHASE I
 INSTRUMENTATION

NAME OF DAM LAKE ALTOONA DAM
 ID# NDI: 532 DER: 7-8

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
MONUMENTATION/SURVEYS	NONE	
OBSERVATION WELLS	NONE	
WEIRS	NONE	
PIEZOMETERS	NONE	
OTHER	NONE	

VISUAL INSPECTION
 PHASE I
 RESERVOIR
 OBSERVATIONS

NAME OF DAM LAKE ALTOONA DAM

ID# NDI: 532 PER: 7-8

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	WOODED, MILD SLOPES.	
SEDIMENTATION	UNKNOWN.	

VISUAL INSPECTION
 PHASE I
 DOWNSTREAM CHANNEL

NAME OF DAM LAKE ALTOONA DAM
 ID# NDI: 532 DER: 7-8

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	ROCKY NATURAL OUTCROP, OBSTRUCTED BY NUMEROUS RIDGES.	
SLOPES	N/A	
APPROXIMATE NUMBER OF HOMES AND POPULATION	MAIN IMPACT AREA OF FLOOD IN THE EVENT OF DAM FAILURE: RESI- DENTIAL AREAS OF ALTOONA, ~ 500 HOMES, POPULATION ~ 2000.	

**THIS PAGE IS BEST QUALITY PRACTICABLE
 FROM COPY FURNISHED TO DDC**

APPENDIX B
CHECKLIST
ENGINEERING DATA, DESIGN,
CONSTRUCTION, OPERATION
PHASE I

CHECKLIST
 ENGINEERING DATA
 DESIGN, CONSTRUCTION, OPERATION
 PHASE 1

NAME OF DAM LAKE ALTOONA DAM
 ID# NDI: 532 DER: 7-8

ITEM	REMARKS
AS-BUILT DRAWINGS	LIMITED NUMBER OF DRAWINGS ARE AVAILABLE IN OWNER'S FILES.
REGIONAL VICINITY MAP	SEE PLATE 1
CONSTRUCTION HISTORY	THE DAM WAS DESIGNED BY MR. C. W. KNIGHT A CONSULTING ENGINEER FROM BONE, NY IN 1906. THE DAM WAS COMPLETED IN 1913.
TYPICAL SECTIONS OF DAM	SEE PLATE .3.
OUTLETS - PLAN - DETAILS - CONSTRAINTS - DISCHARGE RATINGS	SEE PLATES 9 & 10

CHECKLIST
 ENGINEERING DATA
 DESIGN, CONSTRUCTION, OPERATION
 PHASE I

NAME OF DAM LAKE ALTOONA DAM
 ID# NDI:532 DER:7-8

ITEM	REMARKS
RAINFALL/RESERVOIR RECORDS	RECORDED BY DAM TENDER AT THE DAM SITE.
DESIGN REPORTS	NOT AVAILABLE.
GEOLOGY REPORTS	NOT AVAILABLE.
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	NOT AVAILABLE.
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	NOT AVAILABLE.

CHECKLIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION
PHASE I

NAME OF DAM LAKE ALTOONA DAM
ID# NDI:532 DER:78

ITEM	REMARKS
POST CONSTRUCTION SURVEYS OF DAM	NONE REPORTED.
BORROW SOURCES	UNKNOWN.
MONITORING SYSTEMS	NONE.
MODIFICATIONS	THE SPILLWAY ENLARGED IN 1929.
HIGH POOL RECORDS	NOT AVAILABLE.

CHECKLIST
 ENGINEERING DATA
 DESIGN, CONSTRUCTION, OPERATION
 PHASE I

NAME OF DAM LAKE ALTOONA DAM
 ID# NDI:532 DER:7-B

ITEM	REMARKS
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	<u>ALTOONA WATER WORKS: REPORT ON SPILLWAYS AND FLOOD CHANNEL MAY 27, 1921 BY ALLEN HAZEN</u> A LETTER REPORT ON SPILLWAY AND FLOOD CHANNEL OCT, 4, 1921 BY ARTHUR E. MORGAN.
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	NONE REPORTED.
MAINTENANCE OPERATION RECORDS	NOT AVAILABLE.
SPILLWAY PLAN SECTIONS DETAILS	SEE PLATE 5 & 7
OPERATING EQUIPMENT PLANS AND DETAILS	SEE PLATE 9 & 10

NAME OF DAM LAKE ALTONA DAM

ID# NDI: 532 DER: 7-B

CHECKLIST
HYDROLOGIC AND HYDRAULIC
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: WOODED, SOME STRIP MINING 13.2 SQ. MI.
ELEVATION; TOP NORMAL POOL AND STORAGE CAPACITY: 1842 AC-FT @ EL 1355.5
ELEVATION; TOP FLOOD CONTROL POOL AND STORAGE CAPACITY: SAME AS ABOVE.
ELEVATION; MAXIMUM DESIGN POOL: EL 1359.5 (TOP OF FABRIDAMS)
ELEVATION; TOP DAM: EL 1364

CREST: SPILLWAY

- a. Elevation 1355.5
- b. Type OVERFLOW SECTION
- c. Width N/A.
- d. Length 133 FT
- e. Location Spillover N/A.
- f. Number and Type of Gates INFLATABLE FABRIDAM GATES.

OUTLET WORKS:

- a. Type Φ60" BLOW-OFF PIPE
- b. Location NEAR LEFT ABUTMENT.
- c. Entrance Inverts UNKNOWN
- d. Exit Inverts UNKNOWN
- e. Emergency Draindown Facilities Φ60" BLOW-OFF PIPE

HYDROMETEOROLOGICAL GAGES:


- a. Type RAIN GAGE
- b. Location AT THE DAM SITE
- c. Records AVAILABLE IN CITY RECORDS.

MAXIMUM NONDAMAGING DISCHARGE: _____

APPENDIX C
PHOTOGRAPHS

LIST OF PHOTOGRAPHS
LAKE ALTOONA DAM
NDI I.D. NO. 532
AUGUST 9, 1978


<u>PHOTOGRAPH NO.</u>	<u>DESCRIPTION</u>
1	Crest (looking north).
2	Intake tower and spillway entrance.
3	Fabridam spillway gates.
4	Spillway chute.
5	Valve controls at intake tower.
6	Blow-off pipe.
7	Perched water along the toe.
8	Typical downstream channel (through Altoona).



Photograph No. 1
Crest (looking north).




Photograph No. 2
Intake tower and spillway entrance.




Photograph No. 3
Fabridam spillway gates.



Photograph No. 4
Spillway chute.




Photograph No. 5
Valve controls at intake tower.



Photograph No. 6
Blow-off pipe.



Photograph No. 7
Perched water along the toe.



Photograph No. 8
Typical downstream channel (through Altoona).

APPENDIX D
CALCULATIONS

DAMPOLONA

CONSULTING ENGINEERS, INC



By WTC Date 8.21.78 Subject LAKE ALTOONA Sheet No. 1 of 1
 Chkd. By MS Date 8/23/78 WATERSHED & LAKE AREA Proj. No. 78-114-21

REF: USGS ALTOONA, HOLLIDAYSBURG, CRESSON, and ASHVILLE
 QUADRANGLE, 7.5 MIN. SERIES

A) WATERSHED AREA FOR LAKE

$$= 11.8 \text{ IN}^2 \times \left(\frac{2000}{5280} \text{ MILE}^2/\text{IN}^2 \right)^2$$

$$= 1.69 \text{ SQ MILE}$$

WATERSHED AREA FOR DIVERSION CHANNEL

$$= (200 - 122.3) \text{ IN}^2$$

$$= 77.7 \text{ IN}^2 \left(\frac{2000}{5280} \right)^2$$

$$= 11.15 \text{ SQ MILE}$$

FOR FLOOD EXCEED DIVERSION CHANNEL CAPACITY, THE
 WATERSHED FOR DAM WILL BE

$$1.69 + 11.15 = 12.84 \text{ SQ MILE}$$

say 12.8 SQ MILE

B) LAKE AREA (1355.5) Dam EL 1364.4

LAKE AREA (1355.5)	= 0.92 IN ²	= 84.48 ACRES	say 85 ac
@ EL 1360	= 1.12	= 102.85 ..	say 100 ac
@ EL 1380	= 1.40	= 128.56 ..	say 130 ac

C) VOLUME

ELEV.	ΔH ft	Area, ac	ΔV, ac-ft	ΣV, ac-ft
1355.5	4.5	85	416	0
1360	20	100	2294	416
1380		130		2710

INTERPOLATING BETWEEN 1360 & 1380 ⇒ Vol @ 1364.4 = 920 ac-ft.

D'AMICO & DONNA

CONSULTING ENGINEERS, INC

By WTC Date 8-29-78 Subject LAKE ALTOONA DAM Sheet No. 1 of 5
Chkd. By MC Date 9/8/78 HYDROLOGY & HYDRAULIC Proj. No. 78-114-21

DAM: LAKE ALTOONA DAM

WATERSHED AREA $A_1 = 1.7$ SQ MILE FOR LAKES

Where 0.4 SQ MILES FROM UPPER LAKE
1.3 SQ MILES FROM ITS OWN

$A_2 = 11.1$ SQ MILE FOR CHANNEL
(INCLUDING 1.3 SQ MILE OF SCOTCH RUN)

TOTAL AREA = 12.8 SQ. MILES

ACCORDING TO THE CHARTS PROVIDED BY COE BALTIMORE DIST
FOR SUSQUEHANNA (REGION 1) BASIN

$$\text{PMF MAX Peak inflow} = 2200 \text{ cfs/SQ MILE} \\ = 28160 \text{ cfs}$$

Say 28000 cfs

TOTAL 26" RUNOFF WATER VOLUME

$$V_i = \frac{26}{12} \times 12.8 \times 640$$

$$= 17749 \text{ AC-FT}$$

Say 17800 ac-ft

SURCHARGE STORAGE VOLUME ABOVE NORMAL POOL EL 1355.5
AND DAM CREST EL 1364.4

$$\text{Vol} = 920 \text{ ac-ft} \quad (\text{See Vol calc.})$$

WITH FABRIC DAM

$$\text{Vol} = \frac{4.9}{8.9} \times 920 = 5065 \text{ ac-ft}$$

Say
920 ac-ft w/o FAB.
510 ac-ft w/FAB.

D'APOLONIA

CONSULTING ENGINEERS, INC.

By WJC Date 8-29-78 Subject LAKE ALTOONA DAM Sheet No. 2 of 5
 Chkd. By mc Date 9/8/78 HYDROLOGY & HYDRAULIC Proj. No. 78-114-24

SPILLWAY DISCHARGE CAPACITY


TYPE BROAD CRESTED CONCRETE OVERFLOW W/B.R. W/4'
 FABRIC DAM
 LENGTH = 132 FT (FIELD MEASURED)

$$\begin{aligned}
 Q_{13} &= Q_s \text{ (FABRIC DAM DEFLATED)} \\
 &= (2.65)(132)(1364.4 - 1355.5)^{1.5} \\
 &= 9288 \text{ cfs}
 \end{aligned}$$

Say 9300 cfs

$$\begin{aligned}
 Q_{13} &= Q_s \text{ (FABRIC DAM INFLATED)} \\
 &= (3.6)(132)(8.9 - 4)^{1.5} \text{ (APPROXIMATE FABRIC DAM HEIGHT)} \\
 &= 5154 \text{ cfs}
 \end{aligned}$$

Say 5200 cfs



DAMPOLONA

CONSULTING ENGINEERS, INC

By WTC Date 9-2-78 Subject LAKE ALTOONA DAM Sheet No. 3 of 5
 Chkd. By me Date 9/11/78 HYDROLOGY & HYDRAULIC Proj. No. 78-114-21

DISCHARGE CAPACITY OF Q_{11} & Q_{12} (SCOTCH RUN BRIDGE)

a) Q_{11} (DIVERSION CHANNEL)
 INV EL 1397 (BOTTOM)

B (WIDTH) = 16'-6"

MAX HEAD BEFORE OVERTFLOW TO LAKE ALTOONA = 1402 - 1397
 (FROM SCOTCH RUN & TUNNEL) = 5 FT

CRITICAL DEPTH OCCUR @ $1/3$ SIDE OF BRIDGE (CONTROL)




$$\frac{Q^2}{g} = \frac{a^3}{T} = \frac{(T \times h)^3}{T}$$

$$\left(\frac{Q}{T}\right)^2 = h^3 \times g$$

$$g = \sqrt{g h^3} \quad \text{cfs/FT} = \sqrt{(322)(5)^3} = 634 \text{ cfs/FT}$$

$$Q_{11} = g \cdot T = 634 \times 165 = 1047 \text{ cfs} \quad \text{Say } 1050 \text{ cfs}$$

also $Q_{11} = 93.63 \sqrt{h^3} \text{ cfs}$



THIS PAGE IS BEST QUALITY PRACTICABLE
 FROM COPY FURNISHED TO DDG

D'AMICO & DONNA

CONSULTING ENGINEERS INC

By WTC Date 9-2-78 Subject LAKE ALTOONA DAM Sheet No. 4 of 5
 Chkd. By me Date 9/11/78 HYDROLOGY & HYDRAULIC Proj. No. 78-114-21

b) Q_{12} (WEIR OVERFLOW TO LAKE ALTOONA)

$$L = 95'$$

$$Q_{12} = C L H^{1.5} \text{ (SHARP CRISI WEIR) (See P 3 SKETCH)}$$

$$= (3.2)(95)(H)^{1.5}$$

$$= 304 H^{1.5} \text{ cfs} \quad (h = H + 5)$$

EL	DIVERSION		WEIR OVERFLOW TO LAKE		TOTAL INFLOW $Q_{11} + Q_{12}$ cfs
	h	Q_{11} cfs	H	Q_{12} cfs	
1397	0	0	—	—	0
1402	5	1047	0	0	1047
1403	6	1376	1	304	1680
1404*	7	1734	2	860	2594
1405*	8*	2119*	3	1580	3698
1406*	9*	2528*	4	2432	4960
1407*	10*	2961*	5	3399	6360

* BOTTOM OF BRIDGE EL 1404 ($\Delta h = 7$ ft) ASSUMING INLET CONTROL
(OR CRITICAL DEPTH CONTROL)

THE MAX INFLOW AT THIS POINT IS

$$\text{TUNNEL FLOW} = 1200 \text{ cfs} \quad \text{see P 1/5, SCOTCH GAP RUN WATERSHED}$$

$$\text{WATERSHED INFLOW} = 1.3 \text{ SQ. MILE} \times 2400 \text{ cfs/SQ MILE}$$

$$= 3120 \text{ cfs}$$

$$Q_{\text{MAX}} = 4320 \text{ cfs}$$

$< 6360 \text{ cfs}$
OK

Say 4300 cfs

BACK FIGURE h, H and ELEV. FOR $Q = 4300$ cfs

@ ELEV 1405.5 $h = 8.50$ $Q_{11} = 2320$ cfs
 $H = 3.50$ $Q_{12} = 1991$ cfs

$$\Sigma Q = Q_{11} + Q_{12} = 4311 \approx 4300 \text{ OK}$$

IDMPTOLONLA

CONSULTING ENGINEERS, INC

By UIC Date 9-2-78 Subject LAKE ALTOONA DAM Sheet No. 3 of 5
 Chkd. By UIC Date 7/11/78 HYDROLOGY & HYDRAULIC Proj. No. 78-114-21

D/S CHANNEL CAN CARRY MORE THAN 4300 CFS
 AND THE SPILLWAY CAPACITY IS LIMITED TO
 9300 CFS FABRIC DEFLATED
 5200 CFS FABRIC INFLATED

ESTIMATE THE PERCENT OF PMF W/O OVERTOPPING

$$\% \text{ PMF} = \left(\frac{9300 + 1200 + (\% \text{ PMF})(3100)}{28000} + \frac{920}{17800} \right) \text{ (SEE NOTE 1)}$$

$$\% \text{ PMF} = 48.0\% \text{ (WITHOUT FABRIC DAM)}$$

Say 48% PMF W/O FABRIC

$$\text{OR } \left(\frac{5200 \text{ CFS} + 1200 + (\% \text{ PMF})(3100)}{28000} + \frac{510}{17800} \right) 100\%$$

$$= 28.9\% \text{ (WITH FABRIC DAM)}$$

Say 29% PMF W/FABRIC

NOTE(1) SINCE THE SURCHARGE STORAGE CAPACITY OF TWO U/S DAM (70 + 250 = 320 AC-FT) IS RELATIVELY SMALLER THAN THE VOLUME OF PMF (28000 AC-FT), THE AFFECT OF TWO U/S DAM IN REDUCING THE PEAK OF PMF IS NEGLECTED

* FLOW IN DIVERSION CHANNEL

THIS PAGE IS BEST QUALITY PRACTICABLE
 FROM COPY FURNISHED TO DDC

APPENDIX E
REGIONAL GEOLOGY

APPENDIX E
REGIONAL GEOLOGY

Lake Altoona Dam and its reservoir are situated on strata of the Upper Devonian Age Catskill Red Beds and Upper Devonian Age Chemung Shales. The red beds consist of reddish-brown highly fractured shale and claystone. The Chemung Shale is a thin-bedded greenish-gray shale with some thin interbedded sandstone layers. The rock strikes northeast and dips approximately 15 to 20 degrees to the northwest. The shale is less resistant to weathering than the overlying red beds and forms more gentle slopes. The south slope of the valley is hummocky and may have experienced landslides in the past. However, no evidence was found indicating recent movement.