

AD-A069 615


















NEW JERSEY STATE DEPT OF ENVIRONMENTAL PROTECTION TRENTON F/G 13/2
NATIONAL DAM SAFETY PROGRAM. SKYLINE LAKE DAM NUMBER 2 (NJ00200--ETC(U)
MAY 79 R J JENNY


UNCLASSIFIED

DACW61-78-C-0124

NL

1 OF 2
AD
AO59615





NATIONAL BUREAU OF STANDARDS
MICROCOPY RESOLUTION TEST CHART

~~LEVEL~~

(1)
P.S.

PASSAIC RIVER BASIN
SHEPARD BROOK, PASSAIC COUNTY
NEW JERSEY

MA A 069615

SKYLINE LAKE DAM NO. 2 NJ 00200

DDC
RECEIVED
JUN 11 1979
C

PHASE 1 INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM

DDC FILE COPY



Approved for public release;
distribution unlimited

DEPARTMENT OF THE ARMY

Philadelphia District
Corps of Engineers
Philadelphia, Pennsylvania

May, 1979

79-00-01-060

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DDC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

NOTICE

**THIS DOCUMENT HAS BEEN REPRODUCED
FROM THE BEST COPY FURNISHED US BY
THE SPONSORING AGENCY. ALTHOUGH IT
IS RECOGNIZED THAT CERTAIN PORTIONS
ARE ILLEGIBLE, IT IS BEING RELEASED
IN THE INTEREST OF MAKING AVAILABLE
AS MUCH INFORMATION AS POSSIBLE.**

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NJ00200	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program Skyline Lake Dam No. 2 Passaic County, N.J.		5. TYPE OF REPORT & PERIOD COVERED ⑨ FINAL rept.
7. AUTHOR(s) ⑩ Robert J. Jenny, P.E.		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS Jenny-Leedshill Engineering 318 South Orange Ave. South Orange, N.J. 07079 410 891		8. CONTRACT OR GRANT NUMBER(s) ⑮ DACW61-78-C-0124
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, Philadelphia Custom House, 2d & Chestnut Streets Philadelphia, Pennsylvania 19106		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) ⑫ 148 p.		12. REPORT DATE ⑪ May 1979
		13. NUMBER OF PAGES 103
		15. SECURITY CLASS. (of this report) Unclassified
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) ⑬ National Dam Safety Program, Skyline Lake Dam Number 2 (NJ00200), Passaic River Basin, Shepard Brook, Passaic County, New Jersey, Phase I Inspection Report.		
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia, 22151.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dams Erosion Embankments Bridge Piers Structural Analysis Visual Inspection Spillways National Dam Inspection Act Report Skyline Lake Dam #2, N.J.		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report cites results of a technical investigation as to the dam's ade- quacy. The inspection and evaluation of the dam is as prescribed by the National Dam Inspection Act, Public Law 92-367. The technical investigation includes visual inspection, review of available design and construction records, and preliminary structural and hydraulic and hydrologic calculations, as applicable. An assessment of the dam's general condition is included in the report. 410 891		



DEPARTMENT OF THE ARMY
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS
CUSTOM HOUSE--2 D & CHESTNUT STREETS
PHILADELPHIA, PENNSYLVANIA 19106

IN REPLY REFER TO

NAPEN-D

24 MAY 1979

Honorable Brendan T. Byrne
Governor of New Jersey
Trenton, NJ 08621

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for Skyline Lake Dam No. 2 in Passaic County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Skyline Lake Dam No. 2 a high hazard potential structure, is judged to be in fair overall condition. However, the spillway is considered seriously inadequate since 11 percent of the Probable Maximum Flood (PMF) would overtop the dam. The seriously inadequate spillway is assessed as an UNSAFE, non-emergency condition, until more detailed studies prove otherwise or corrective measures are completed. The classification of UNSAFE applied to a dam because of a seriously inadequate spillway is not meant to indicate the same degree of emergency as would be associated with an UNSAFE classification applied for a structural deficiency. It does mean, however, that based on an initial screening, and preliminary computations, there appears to be a serious deficiency in spillway capacity so that if a severe storm were to occur, overtopping and failure of the dam would take place, significantly increasing the hazard to loss of life downstream from the dam. To insure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Any remedial measures necessary to insure the adequacy of the spillway and to prevent overtopping should be initiated within calendar year 1980. In the interim, a detailed emergency operation plan

NAPEN-D

Honorable Brendan T. Byrne

and warning system, should be promptly developed. Also, during periods of unusually heavy precipitation, around-the-clock surveillance should be provided.

b. Within six months from the date of approval of this report, engineering studies and analyses should be performed to determine the dam's embankment condition and structural stability. This should include test borings to determine material properties relative to stability and seepage and installation of piezometers to facilitate seepage studies. Any remedial measures found necessary should be initiated within calendar year 1980.

c. The following remedial actions should be completed within three months from the date of approval of this report:

- (1) All brush and small trees should be removed from the embankment.
- (2) The upstream embankment should be graded to the design slope and riprap or other suitable slope protection should be placed on the embankment to prevent further wave erosion.
- (3) Erosion scars on the downstream face of the embankment and the eroded section of embankment adjacent to the west wingwall should be filled and compacted with a suitable earthfill. If inspection of the embankment when the upper reservoir is full indicates that the erosion on the downstream face is caused by seepage, remedial measures to eliminate the seepage should be performed.
- (4) The eroded portion of the downstream toe of the spillway apron should be replaced and resurfaced in such a manner as to avoid further deterioration.
- (5) Remove the bridge piers from the spillway.
- (6) The cracks and spalling in the spillway wingwall should be repaired.
- (7) A trash rack should be placed over the intake to the outlet conduit.

d. Within six months from the date of approval of this report, the following actions should be taken:

- (1) The seismicity at the dam site and its effect on the stability

NAPER-D

Honorable Brendan T. Byrne

of the dam should be investigated.

(2) The dam should be surveyed to confirm its as-built geometry.

e. A program of annual inspections of the dam should be initiated by the owners, utilizing the standard visual checklist in this report. Timely corrective action should be taken as necessary. A permanent record should be kept of all maintenance and operating events of the dam and reservoir.

A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressman Robert A. Roe of the Eighth District. Under the provision of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, five days after the date of this letter.

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.

An important aspect of the Dam Safety Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely,

James G. Ton
JAMES G. TON
Colonel, Corps of Engineers
for District Engineer

1 Incl
As stated

Copies furnished:
Dirk C. Hofman, P.E., Deputy Director
Division of Water Resources
N. J. Dept. of Environmental Protection
P. O. Box CN029
Trenton, NJ 08625

John O'Dowd, Acting Chief
Bureau of Flood Plain Management
Division of Water Resources
N. J. Dept. of Environmental Protection
P. O. Box CN029
Trenton, NJ 08625

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DDC TAB	<input type="checkbox"/>
Unannounced Justification	<input type="checkbox"/>
By	
Distribution/	
Availability Codes	
Dist	Avail and/or special
A	23

SKYLINE LAKE DAM NO. 2 (NJ00200)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 1 and 20 December 1978 by Jenny-Leedshill Engineers under contract to the State of New Jersey. The State, under agreement with the U. S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

Skyline Lake Dam No. 2 a high hazard potential structure, is judged to be in fair overall condition. However, the spillway is considered seriously inadequate since 11 percent of the Probable Maximum Flood (PMF) would overtop the dam. The seriously inadequate spillway is assessed as an UNSAFE, non-emergency condition, until more detailed studies prove otherwise or corrective measures are completed. The classification of UNSAFE applied to a dam because of a seriously inadequate spillway is not meant to indicate the same degree of emergency as would be associated with an UNSAFE classification applied for a structural deficiency. It does mean, however, that based on an initial screening, and preliminary computations, there appears to be a serious deficiency in spillway capacity so that if a severe storm were to occur, overtopping and failure of the dam would take place, significantly increasing the hazard to loss of life downstream from the dam. To insure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Any remedial measures necessary to insure the adequacy of the spillway and to prevent overtopping should be initiated within calendar year 1980. In the interim, a detailed emergency operation plan and warning system, should be promptly developed. Also, during periods of unusually heavy precipitation, around-the-clock surveillance should be provided.

b. Within six months from the date of approval of this report, engineering studies and analyses should be performed to determine the dam's embankment condition and structural stability. This should include test borings to determine material properties relative to stability and seepage and installation of piezometers to facilitate seepage studies. Any remedial measures found necessary should be initiated within calendar year 1980.

c. The following remedial actions should be completed within three

months from the date of approval of this report:

- (1) All brush and small trees should be removed from the embankment.
- (2) The upstream embankment should be graded to the design slope and riprap or other suitable slope protection should be placed on the embankment to prevent further wave erosion.
- (3) Erosion scars on the downstream face of the embankment and the eroded section of embankment adjacent to the west wingwall should be filled and compacted with a suitable earthfill. If inspection of the embankment when the upper reservoir is full indicates that the erosion on the downstream face is caused by seepage, remedial measures to eliminate the seepage should be performed.
- (4) The eroded portion of the downstream toe of the spillway apron should be replaced and resurfaced in such a manner as to avoid further deterioration.
- (5) Remove the bridge piers from the spillway.
- (6) The cracks and spalling in the spillway wingwall should be repaired.
- (7) A trash rack should be placed over the intake to the outlet conduit.

d. Within six months from the date of approval of this report, the following actions should be taken:

- (1) The seismicity at the dam site and its effect on the stability of the dam should be investigated.
- (2) The dam should be surveyed to confirm its as-built geometry.

e. A program of annual inspections of the dam should be initiated by the owners, utilizing the standard visual checklist in this report. Timely corrective action should be taken as necessary. A permanent record should be kept of all maintenance and operating events of the dam and reservoir.

APPROVED:

James G. Ton
JAMES G. TON
Colonel, Corps of Engineers
District Engineer

DATE:

24 May 1975



DEPARTMENT OF THE ARMY
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS
CUSTOM HOUSE-2 D & CHESTNUT STREETS
PHILADELPHIA, PENNSYLVANIA 19106

IN REPLY REFER TO

NAPEN

Honorable Brendan T. Byrne
Governor of New Jersey
Trenton, NJ 08621

.....
17 MAY 1979

Dear Governor Byrne:

This is in reference to our ongoing National Program for Inspection of Non-Federal Dams with the State of New Jersey. Skyline Lake Dam No. 2 (Federal I.D. No. NJ00200), a high hazard potential structure has recently been inspected. The dam is owned by the Skyline Lake Property Owners Association and is located on Shephard Brook approximately one mile northeast of the Borough of Manaque-Midvale in Passaic County.

Using Corps of Engineers screening criteria, it has been determined that the dam's spillway is seriously inadequate since approximately 11 percent of the Probable Maximum Flood would overtop the dam. The seriously inadequate spillway is assessed as an UNSAFE, non-emergency condition, until more detailed studies prove otherwise, or corrective measures are completed. The classification of UNSAFE applied to a dam because of a seriously inadequate spillway is not meant to indicate the same degree of emergency as would be associated with an UNSAFE classification applied for a structural deficiency. It does mean, however, that based on an initial screening and preliminary computations, there appears to be a serious deficiency in spillway capacity so that if a severe storm were to occur, overtopping and failure of the dam could take place, significantly increasing the hazard potential to loss of life downstream from the dam. As a result of this UNSAFE determination, it is recommended that the dam's owner take the following measures within 30 days of the date of this letter:

- a. Engage the services of a qualified professional consultant to more accurately determine the spillway adequacy by using more detailed and sophisticated hydrologic and hydraulic analyses, and to recommend any remedial measures required to prevent overtopping of the dam.


NAPEN-D

Honorable Brendan T. Byrne

b. In the interim, a detailed emergency operation plan and downstream warning system should be developed. Also, round-the-clock surveillance should be provided during periods of unusually heavy precipitation.

A final report on this Phase I Inspection will be forwarded to you within two months.

Sincerely,



JAMES G. TON
Colonel, Corps of Engineers
District Engineer

Cy Furn:

Dirk C. Hofman, Actg Deputy Director
Division of Water Resources
N. J. Dept of Environmental Protection
P. O. Box CN029
Trenton, NJ 08625

John O'Dowd, Acting Chief
Bureau of Flood Plain Management
Division of Water Resources
N. J. Dept of Environmental Protection
P. O. Box CN029
Trenton, NJ 08625

UNSAFE DAM
NATIONAL PROGRAM OF INSPECTION OF DAMS

a. NAME: Skyline Lake Dam No. 2 b. ID NO.: NJ00200 c. LOCATION State: New Jersey County: Passaic

d. HEIGHT: 24 feet e. MAXIMUM IMPOUNDMENT CAPACITY: 400 ac. ft.

River or Stream: Shephard Brook

Nearest D/S City or Town: Wanaque-Midvale

f. TYPE: Earthfill with steel sheet pile core g. OWNER: Skyline Lake Property Owners Assoc.

h. DATE GOVERNOR NOTIFIED OF UNSAFE CONDITIONS: 17 May 78 i. CONDITION OF DAM RESULTING IN UNSAFE ASSESSMENT Preliminary report calculations indicate 11% of PMF would overtop the dam.

l. URGENCY CATEGORY: UNSAFE, Non-Emergency

m. EMERGENCY ACTIONS TAKEN: Gov. notified of this condition by District Engineer's letter of 17 May 78.

n. REMEDIAL ACTIONS TAKEN: M.J.D.E.P. will notify dam's owner upon receipt of our letter

o. REMARKS: Final report, to be issued within six weeks, will have WHITE cover.

k. RECOMMENDATIONS GIVEN TO GOVERNOR: Within 30 days of date of District Engineer letter the owner do the following:

- a. Engage the services of a qualified professional consultant to more accurately determine the spillway adequacy by using more detailed and sophisticated hydrologic and hydraulic analyses, and to recommend any remedial measures required to prevent overtopping of the dam.
- b. In the interim, a detailed emergency operation plan and downstream warning system should be developed. Also, around-the-clock surveillance should be provided during periods of unusually heavy precipitation.

F. J. B. ...
for
W. H. ZINK, Coordinator
Dam Inspection Program
U.S.A.E.D., Philadelphia

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Skyline Lake Dam No. 2
Federal I.D. No. NJ 00200
New Jersey I.D. No. 398
State Located: New Jersey
County Located: Passaic
Stream: Shephard Brook
Dates of Inspection: December 1 and 20, 1978

Brief Assessment of General Condition of Dam

The dam appears to be in fair overall condition structurally based on visual inspection.


The spillway of Skyline Lake Dam No. 2 can pass approximately 10 percent of the Probable Maximum Flood and is considered seriously inadequate.


There are certain maintenance deficiencies which, if left unattended, could imperil the structural integrity of the dam. The available engineering data are not sufficient to quantitatively analyze the structural stability of the dam.


Recommendations and the urgency of their implementation are as follows:

1. More sophisticated and detailed hydrologic and hydraulic analyses of the spillway capacity should be performed as soon as possible. From this, a positive action program of corrective measures should be developed and implemented as necessary.
2. Field and laboratory investigations should be initiated in the near future, so that seepage and

- stability analyses may be performed. The seismicity at the dam site and its effect on the stability of the dam should also be investigated.
3. The dam should be surveyed in the near future to confirm its as-built geometry.
 4. All brush and small trees should be removed from the embankment as soon as possible. The embankment should be regraded to the design slope and any erosion scars should be filled and compacted with a suitable earthfill as soon as possible. Riprap or other suitable slope protection should be placed on the upstream embankment in the near future.
 5. If inspection of the embankment when the upper reservoir is full indicates that the erosion on the downstream face is caused by seepage, remedial measures to eliminate the seepage should be performed.
 6. The eroded portion of the downstream toe of the spillway apron should be repaired soon and the bridge piers removed from the spillway crest.
 7. An effective warning system should be implemented in the near future.
 8. A program to inspect the dam annually and after critical floods should be initiated in the near future.
 9. A trash rack should be placed over the intake to the outlet conduit as soon as possible.


Frank L. Panuzio, P.E.
Project Engineer


Robert J. Jenny
Project Director
N.J. License No. 9878



SKYLINE LAKE DAM #2

View of dam from downstream. (Dec. 1, 1978)

TABLE OF CONTENTS

	Page
BRIEF ASSESSMENT OF GENERAL CONDITION OF DAM	i
OVERVIEW PHOTOGRAPH OF DAM	
PREFACE	iii
SECTION 1 PROJECT INFORMATION	
1.1 General	1
1.2 Description of Project	1
1.3 Pertinent Data	4
SECTION 2 ENGINEERING DATA	
2.1 Design	6
2.2 Construction	8
2.3 Operation	8
2.4 Evaluation	8
SECTION 3 VISUAL INSPECTION	
3.1 Findings	10
SECTION 4 OPERATIONAL PROCEDURES	
4.1 Procedures	15
4.2 Maintenance of Dam	15
4.3 Maintenance of Operating Facilities	15
4.4 Description of Warning System	
4.5 Evaluation of Operational Adequacy	16
SECTION 5 HYDRAULIC/HYDROLOGIC	
5.1 Evaluation of Features	17

TABLE OF CONTENTS

(Continued)

	Page
SECTION 6 STRUCTURAL STABILITY	
6.1 Evaluation of Structural Stability	24
SECTION 7 ASSESSMENT/REMEDIAL MEASURES	
7.1 Dam Assessment	26
7.2 Remedial Measures	28

PLATES

1. Vicinity Map
2. Plan and Profile of Dam
3. Plan and Section of Spillway
4. Typical Section of Fill Showing Core

APPENDICES

APPENDIX A - Check List - Visual Observations
 Check List - Engineering, Construction
 Maintenance Data

APPENDIX B - Photographs

1. Embankment crest
2. Upstream face
3. Erosion of downstream face
4. Erosion of downstream face
5. Spillway overview

TABLE OF CONTENTS

(Continued)

6. Left wingwall
7. Spillway apron
8. Intake to outlet pipe
9. Outlet pipe and valve chamber
10. Upstream reservoir
11. Downstream reservoir

APPENDIX C - Regional Geology - Highlands

APPENDIX D - Hydrologic and Hydraulic Computations

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D. C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Skyline Lake Dam No. 2
Federal I.D. No. NJ 00200
New Jersey I.D. No. 398

SECTION 1: PROJECT INFORMATION

1.1 General

a. Authority

The National Dam Inspection Act, Public Law 92-367, 1972, provides for the National Inventory and Inspection Program by the U. S. Army Corps of Engineers. This report has been prepared in accordance with this authority, through contract between the State of New Jersey and Jenny-Leedshill Engineers. The State of New Jersey has also entered into an agreement with the U. S. Army Engineer District, Philadelphia, to have this work performed.

b. Purpose of Inspection

The purpose of this inspection was to evaluate the general structural integrity and hydraulic adequacy of the dam, and to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project

a. Description of Dam and Appurtenances

Skyline Lake Dam No. 2 is located between the upper

and lower Skyline Lakes. The dam is an earthfill structure with a steel sheet pile core wall. The length of the dam is 230 feet and the maximum height is 24 feet. The crest of the dam is at elevation 284.3 feet and has a width of 8 feet. The slope of both the upstream and downstream face is 2 horizontal on 1 vertical.

A core wall of steel sheet piles extends along the center line of the dam, extending from the top of the dam to approximately 12 feet beneath the base of the dam. The remnant of a concrete cap approximately 30 feet long and 2 to 3 feet thick was found on top of a section of the steel sheet piles which were driven below the dam crest near the center of the dam.

The spillway structure is located on the left (east) abutment of the dam. The spillway crest length is 50 feet and there is 4 feet of freeboard between the crest and top of the concrete spillway walls. The downstream channel has an asphalt macadam surface and discharges at the normal water surface of the lower reservoir.

A 20-inch diameter cast iron outlet pipe passes between the upper and lower reservoirs beneath the base of the dam approximately 50 feet west of the spillway. The outlet pipe valve is housed in a reinforced concrete chamber with a steel manhole cover located at the downstream toe of the dam.

b. Location

Skyline Lake Dam No. 2 is located in north central New Jersey on Shephard Brook, approximately 1 mile north-east of the Borough of Wanaque-Midvale, in Passaic County, New Jersey. The dam is situated between the upper and lower Skyline Lakes. The regional vicinity plan is presented on Plate 1.

c. Size Classification

When the dredging of the reservoir, which is now in progress, is completed, the storage capacity will be 400 acre-feet when the reservoir stage is at the crest of the dam. The dam is 24 feet high, therefore, the size classification of the dam is small.

The criteria for size classification of dams are set forth in the Corps' Guidelines. A small size dam is one in which the reservoir capacity is greater than or equal to 50 acre-feet and less than 1000 acre feet, and/or the maximum height is greater than or equal to 25 feet and less than 40 feet.

d. Hazard Classification

Failure of the Skyline Lake Dam No. 2 would result in the overtopping and possible failure of Skyline Lake Dam No. 1 which impounds the lower Skyline Lake reservoir. A road and playground were visible immediately downstream from the lower dam and at least six houses in the Borough of Wanaque-Midvale (population 8,500) are in the downstream flood path. Failure or misoperation of the dam could result in the loss of more than a few lives and excessive economic loss; therefore, the Skyline Lake Dam No. 2 merits a high hazard classification.

e. Ownership

The dam is owned by the Skyline Lake Property Owners Association, Skyline Lake, Ringwood, New Jersey, 07456.

f. Purpose of Dam

The dam is used for aesthetics and recreation.

g. Design and Construction History

The application for construction of Skyline Lake Dam No. 2, including design drawings, was filed on June 29, 1945. The dam was constructed in 1945 and 1946 and

the dam was accepted by the State on May 20, 1947 following remedial construction during 1947.

h. Normal Operational Procedures

There is typically no regulation of the dam or reservoir other than to empty it every few years for cleaning. The reservoir can be emptied via the 20-inch diameter pipe providing, the lower reservoir is drawn down below the intake to the outlet pipe.

1.3 Pertinent Data

a. Drainage Area (sq. mi.)	2.8
b. Discharge at Damsite (cfs)	
. Ungated spillway capacity at maximum pool elevation	1040
c. Elevation (ft. above MSL)*	
. Top Dam	284.3
. Spillway crest	280.3
. Streambed at centerline of dam	260.3
d. Reservoir Length (ft.)	
. Maximum pool (El. 284.3)	3500
. Recreation pool (El. 280.3)	3400
e. Storage (acre-feet)	
. Spillway crest	330
. Top of dam	400
f. Reservoir Surface (acres)	
. Top dam	24
. Spillway crest	18

*A contour map prepared for the recent dredging of reservoir No. 2, dated Jan. 31, 1978, indicates that 158.3 feet should be added to the design drawing elevations to obtain MSL elevations.

g. Dam

- . Type Earthfill
- . Length 230 ft.
- . Height 24 ft.
- . Top Width 8 ft.
- . Side Slopes - upstream 2H:1V
- downstream 2H:1V
- . Zoning Impervious earthfill upstream of core and pervious earthfill on downstream side.
- . Impervious Core Steel sheet pile core wall driven 12 ft. below base of dam. Concrete cap poured on top of piles at center of dam.

h. Spillway

- . Type Chute
- . Length of weir 50 ft.
- . Crest elevation 280.3 ft.
- . U/S Channel Reservoir
- . D/S Channel Asphalt concrete chute

i. Regulating Outlets

20-inch diameter cast iron outlet pipe and gate valve

SECTION 2: ENGINEERING DATA

2.1 Design

a. Geologic Conditions

Skyline Lake No. 2 is situated just upstream of Skyline Lake No. 1 in the north-central portion of the New Jersey Highlands physiographic province. The regional geology of this province is discussed in Appendix C to this report.

The dam is located in an approximately north-south oriented narrow "U" shaped valley with steeply rising bedrock surfaces above both abutments. The valley is part of a longer north-south linear feature which appears to be controlled by the structural geology of the region. The valley lies north of the Wisconsin Age terminal moraine and exhibits evidence of glacial plucking and scouring. Numerous large boulders, up to 10 feet in diameter litter the adjacent slopes, some the result of glacial deposition and some talus from the exposed bedrock farther up the slope. Bedrock exposed at the surface on both high abutments is a lightly weathered, slightly foliated granite gneiss.

The valley bottom itself is composed of what appears to be recent alluvium in the old stream course and a highly bouldery till up to the steeper rock slopes. Work being conducted in the area has exposed some of the embankment material which appears to be primarily reworked till.

The dam is located in Seismic Zone 1 indicating only a slight possibility of damage due to distant earthquakes. However, the dam is near the seismically active Ramapo Fault, and the valley in which the dam is located is possibly structurally controlled.

b. Design Data

The permit application No. 399 to construct the Skyline Lake Dam No. 2 was filed with the State on June 27, 1945 and was approved on August 2, 1945. The plans, dated July 10, 1945, consist of 3 sheets showing plans and sections of the dam and spillway and an isometric detail of the left wall of the spillway. Copies of these drawings are included as Plates 2, 3, and 4 of this report.

The embankment was designed to have upstream and downstream slopes of 2 horizontal on 1 vertical. Steel sheet piles were driven at the center of the dam to a penetration of 12 feet beneath the base of the dam and extending along the length of the dam. The section of the dam (Plate 4) indicates that the embankment downstream of the core is pervious earthfill and the material upstream is impervious earthfill. This section also shows riprap extending from the crest approximately 17 feet down the upstream face of the embankment.

The spillway is a 50 foot wide chute. The crest is a 2-foot wide and 6.5-foot high concrete wall extending between side walls of the spillway which retain the embankment at 4 feet above spillway crest (Plate 3). The discharge channel is a 40 to 50 foot long asphalt macadam pavement between concrete training walls extending downstream to the discharge end at the normal lake level of Skyline Lake Dam No. 1, about elevation 268 MSL. The spillway design flood was reported as 300 cfs/sq. mi. based on 125% Central New Jersey Curve for a drainage area of 2.8 square miles.

Specifications for the construction of Skyline Lake Dams No. 1 and No. 2 were prepared by Newell C. Harrison, P.E., Butler, New Jersey. The earthfill was specified to be placed in horizontal layers not exceeding 6 inches in thickness and thoroughly rolled and tamped with heavy rammers. Specifications were given for concrete preparation and placement, slope paving, riprap and steel sheet piling.

2.2 Construction

Eight dam inspection reports prepared by the State engineers between December 1945 and May 1947 are available. These reports describe the general construction progress and performance of the dam following the first filling of the reservoir. Leakage at the base of the left abutment of the spillway and deterioration of the spillway apron occurred soon after the initial filling of the reservoir. The leakage reportedly decreased with time and the spillway apron was covered with 3 inches of asphalt macadam compacted with a 20-ton roller. The dam was subsequently accepted by the Water Policy and Supply Council on May 20, 1947.

2.3 Operations

The reservoir is normally uncontrolled except for occasional drawdown in anticipation of a storm or for maintenance work. There is no instrumentation of the dam, and there are few records of maintenance work.

2.4 Evaluation

a. Availability

Available engineering data for the dam consist of plans and sections which include a qualitative description of the material in the embankment and specified steel

sheet pile size. Specifications for the construction of the dam are also available. Some construction inspection reports are available but there is no information on as-built conditions.

b. Adequacy

The available design and construction data are inadequate to evaluate the structural stability of the dam because of the lack of information on as-built conditions and materials properties. Specifications were qualitative and no field tests were performed and no detailed construction reports were filed.

c. Validity

Inspection reports prepared during the dam construction indicate that the dam was constructed generally as shown on the available drawings and in accordance with the specifications. However, the present inspection indicates that the spillway cross-section is horizontal and not concave as shown on Plate 3, Section A-A.

SECTION 3: VISUAL INSPECTION

3.1 Findings

a. General

Visual inspections of Skyline Lake Dam No. 2 were made on December 1 and 20, 1978. The reservoir was empty and was being excavated at the time of the inspection. Water entering the reservoir was being pumped over the right abutment of the dam into Reservoir No. 1 located immediately downstream of the dam. Reservoir No. 1 had been lowered below the toe of Dam No. 2 during the first inspection. Several inches of snow covered most of the upstream face of the dam at the time of the first inspection.

The visual inspections did not reveal any critical signs of distress in the dam, but, in general, maintenance has been deficient. There is evidence of erosion on the upstream and downstream face of the embankment and the toe of the spillway apron has been seriously eroded. Some cracking and spalling of the spillway's concrete wingwalls were observed.

Detailed inspection was made of the dam, appurtenant structures and the upper and lower reservoir areas. Descriptions of the findings of these inspections are summarized in the paragraphs which follow. The check list of visual inspection items is included in Appendix A. Geologic and foundation conditions observed at the time of inspection are noted in greater detail in Section 2.1-a.

b. Dam

The dam was inspected for signs of settlement, seepage, erosion, cracking and any other evidence of undesirable behavior which might affect the stability of the structure.

The steel sheet piling and concrete cap of the core wall were exposed along the longitudinal axis of the dam protruding approximately 6 inches above the earth fill (Photo 1). Some minor cracking of the concrete which caps the steel sheet piling was noted. The top of the embankment has been eroded up to a depth of about 2.5 feet adjacent to the right spillway wall. This erosion has presumably been aggravated by pedestrian traffic. The top and upstream and downstream faces of the dam are covered with a heavy growth of trees and brush extending down to the water line. The left abutment is also heavily wooded.

Two wavecut benches 1 to 2 feet deep were observed on the upstream face of the dam as shown in Photo 2. These benches were apparently caused by wave erosion when the reservoir was at approximately the same elevation as the benches. The majority of the visible surface of the upstream face of the dam consisted of a sandy clay soil with some gravel. No riprap was observed on the upstream face of the dam.

Two significant erosion gullies were observed on the downstream face of the embankment. One gully, located in the center of the embankment, begins at the high water level of the lower reservoir and extends down to the toe of the dam (Photo 3). This gully has been filled with

riprap; however, erosion appears to be continuing at the upper end. The erosion forming this scar may be the result of wave action from the lower reservoir or possibly seepage through the embankment. The local extent of the erosion indicates that seepage is the most probable cause. The second gully is located above the outlet works as shown in Photo 4.

Both the upstream and downstream face of the embankment appear to be sloping more steeply than the 2 horizontal to 1 vertical indicated on design plans.

c. Appurtenant Structures

Spillway

The spillway appears to have been constructed generally as shown on the design plans (Plate 4), with the exception of four concrete cylindrical piers 10 inches in diameter and 4.5 feet high located adjacent to the spillway crest (Photo 5). These piers reportedly supported a foot bridge across the spillway which was damaged and removed.

There has been minor spalling at the top of the construction joint in the left (east) wingwall, directly above the spillway crest. A vertical crack at the downstream end of the left wingwall and spalling at the top of the adjacent retaining wall was also noted (Photo 6).

There has been minor cracking with no significant displacement of the spillway crest. The construction joint between the west spillway wingwall and training wall has been displaced by about 1/2 inch. The erosion at the toe at the spillway apron, discussed below, is beginning to undermine the foundations of the downstream end of the training walls.

The macadam spillway apron has a slightly undulating surface with a few minor cracks. The most severe irregularities in the apron surface appear to be caused by tree roots. A 1-foot diameter tree is growing in the spillway chute a few feet downstream from the left wingwall.

The downstream toe of the spillway apron has been severely eroded as shown in Photo 7. The abutment on which the apron is founded has been eroded up to a depth of about 4 to 5 feet just downstream of the apron toe. The present toe of the macadam surface is very irregular and has been eroded from 3 to 10 feet upstream from the downstream end of the training walls.

Outlet Works

The upstream and downstream ends of the 20-inch diameter outlet pipe are surrounded by concrete collars and appear to be in satisfactory condition. The upstream reservoir level was below the intake to the outlet pipe at the time of the first inspection. There was miscellaneous debris around the intake to the outlet pipe (Photo 8) and there are no trashracks or similar guards over the intake.

The water level of the lower reservoir was about 6 inches above the invert of the outlet pipe. The outlet pipe valve is housed in a concrete manhole (Photo 9). The steel manhole cover was locked at the time of the inspection; therefore, the valve could not be observed.

d. Reservoir Area

The reservoir was empty at the time of both inspection (Photo 10) and the water flowing into the

reservoir was being pumped over the west abutment of the dam into Reservoir No. 1. The reservoir was being excavated during the inspection. The excavation was reportedly to extend down to a clay layer at a depth of approximately 25 feet below the present reservoir bottom, and thus removing a permeable sand stratum which has caused leakage from the reservoir. Presumably, this sand stratum will be blanketed where it is exposed in the excavation face.

The perimeter of the reservoir generally has moderately steep slopes with local, gently sloping areas. The adjacent area is heavily wooded and populated with single family residences.

e. Downstream Channel

Flow over the spillway empties into Reservoir No. 1, located immediately downstream from the dam. The perimeter of this reservoir is similar to Reservoir No. 2, described above (Photo 11).

SECTION 4: OPERATION PROCEDURES

4.1 Procedures

Normal operation of the reservoir is to maintain maximum storage for recreation purposes. It is reported that the reservoir is lowered when heavy storms are forecast.

The 20-inch diameter outlet pipe is operated by a valve located at the downstream toe of the dam and is used to drain the reservoir for maintenance of the dam and reservoir. Reservoir No. 1 must be emptied to a level at or below the intake to the outlet pipe in order to empty Reservoir No. 2.

It was reported that the reservoir is chemically treated for algae and is drained every few years for cleaning. The reservoir was emptied and cleaned in 1972, 1973 and 1974.

4.2 Maintenance of Dam

The Skyline Lake Property Owners Association are responsible for the maintenance of the dam and reservoir. No records are available regarding the maintenance of the dam, and, based on the visual inspection, little maintenance work has been done.

4.3 Maintenance of Operating Facilities

No maintenance records of operating facilities are available. The outlet works appear to be in satisfactory condition and are reported to function properly.

4.5 Evaluation of Operational Adequacy

It appears that there has been little maintenance of the dam. There is no instrumentation of the dam and records are not kept of maintenance work or operation of the reservoir. A warning system is needed to alert downstream inhabitants in time of floods and possible overtopping or failure of the dam.

SECTION 5: HYDROLOGY/HYDRAULICS

5.1 Evaluation of Features

a. Design

As already stated in Section 1.2, Skyline Lake Dam No. 2 is classified as high hazard and small in size. In accordance with the Corps of Engineers' "Recommended Guidelines for Safety Inspection of Dams", the Spillway Design Flood (SDF) is the Probable Maximum Flood (PMF).

Data obtained from State files indicate the drainage basin area of the dam is 2.8 square miles. Elevations within the basin range from about 1150 feet above mean sea level along the perimeter to about 280 feet in the valley floor. Land use pattern within the watershed consist mainly of forested areas, with only a minor portion of the basin area being residential developments. About 0.6 percent of the watershed area is the surface of Skyline Lake No. 1 and about 1.0 percent of the watershed area is Skyline Lake No. 2. The drainage basin is delineated on U.S.G.S. topographic map and is presented on Plate D-1, Appendix D.

The hydraulic and hydrologic features of the dam were evaluated using criteria set forth in the Corps of Engineers' "Recommended Guidelines for Safety Inspection of Dams", and additional guidance and criteria provided by the Philadelphia District, Corps of Engineers. The Probable Maximum Precipitation (PMP) was calculated using Hydrometeorological Report No. 33 and the Hop

Brook reduction factor of 0.80 for misalignment of the storm. The Probable Maximum Flood (PMF) was calculated using the Corps' computer program HEC-1, Dam Break Version. In computing the PMF the Corps requested that the SCS triangular unit hydrograph with curvilinear transformation be used. The computer program was used to calculate this unit hydrograph from the basin lag. A lag time of 1.0 hour was calculated for the basin and used in the program.

An initial infiltration loss of 1.0 inch and a final infiltration loss rate of 0.10 inch per hour were used in the HEC-1 program to give the rainfall excess. Using the excess rainfall and the unit hydrograph, the program computed the peak discharges of the 15 percent, 25 percent, 50 percent and 100 percent PMF. These discharges are approximately 1,580 cfs, 2,640 cfs, 5,270 cfs and 10,540 cfs, respectively.

The various percentages of the PMF inflow hydrograph were routed through Skyline Lake No. 2 assuming the dam does not breach. The routings were made using the Modified Puls Method by the HEC-1 program. The peak discharges of the 15 percent, 25 percent, 50 percent, and 100 percent PMF were calculated to be approximately 1,470 cfs, 2,550 cfs, 5,170 cfs, and 10,430 cfs. The flood routings indicate that all floods greater than about 10 percent of the PMF will overtop the dam. A plot of percent PMF versus peak outflow discharge is presented as Plate D-2 in Appendix D.

The various percentages of the PMF outflow from Skyline Lake No. 2 were routed through Skyline Lake No. 1, which is immediately downstream, using the Modified

Puls Method by the HEC-1 program. The 15 percent, 25 percent, 50 percent, and 100 percent PMF peak discharges from Skyline Lake Dam No. 1 were calculated to be approximately 1,320 cfs, 2480 cfs, 5,110 cfs, and 10,350 cfs. These flood routings indicate that all floods greater than about 15 percent of the PMF will overtop Skyline Lake Dam No. 1 if Skyline Lake Dam No. 2 does not fail. A plot of percent PMF versus peak outflow from Skyline Lake Dam No. 1 is presented as Plate D-5 in Appendix D.

Because the spillways for both Skyline Lake Dam No. 2 and Skyline Lake Dam No. 1 cannot pass one-half the PMF, the various percentage non-breach PMF flows were routed 0.5 miles downstream through two successive reaches to the Borough of Wanaque-Midvale. A second set of flood routings using the same PMF's were routed through both reservoirs and downstream using the assumption that both dams would breach. These routings were made in order to assess the degree of increased flood hazard caused by breaching due to an inadequate spillway. For the downstream channel routings estimates of channel shapes, slopes and roughnesses were made based on conditions observed in the field and on U.S.G.S. topographic maps. The locations of the cross-sections used in the channel routings are shown on page D-7, Appendix D.

Estimates of spillway and overtop stage-discharge curves, reservoir stage-storage curves, and dam breach parameters were used to route the various floods through the two reservoirs. Assumptions and data used in these estimates are described, for each dam, in the following paragraphs.

Skyline Lake No. 2

The spillway and overtop discharge rating curve used in the flood routing through Skyline Lake No. 2 was calculated using the weir equation and assuming free overflow across the whole length of the dam and spillway. The spillway is a broad-crested weir and has an estimated discharge coefficient of 2.6. The dam crest is a broad-crested weir with heavy overgrowth, and has an estimated discharge coefficient of 2.6. The reservoir stage-storage curve was determined from U. S. Geological Survey 7.5 - minute topographic maps and contour maps of proposed excavation of the lake that were obtained from the owner. At the time of the field inspection a significant portion of the proposed excavation was complete and, therefore, in this analysis the ultimate proposed lake topography was assumed. This stage-storage curve was extended above the dam crest to include surcharge storage during peak discharges. In the reservoir routing computations possible discharges through the outlet works were excluded because their capacity is small compared to the PMF and because of the possibility that the outlet valve may be closed. The stage-storage and the spillway and overtop stage-discharge curves for Skyline Lake Dam No. 2 are presented in Appendix D as Plates D-3 and D-4, respectively.

The breach parameters used in the HEC-1 analysis for Skyline Lake No. 2 are: the breach is rectangular in shape, 180 feet long, will extend to the original reservoir floor elevation (260 ft), will begin breaching when the dam is first overtopped, and will develop to its maximum size in 3.0 hours. The peak outflow from Skyline Lake No. 2 for the 15 percent, 25 percent, 50 percent, and 100 percent PMF, assuming failure, were calculated to be approximately 2,620 cfs, 4,020 cfs, 6,580 cfs, and 10,750 cfs, respectively.

Skyline Lake Dam No. 1

The spillway and overtop stage-discharge rating curve used in the flood routings through Skyline Lake No. 1 was calculated using the weir equation and assuming free overflow across the whole length of the dam and spillway. The spillway has an ogee cross-section and from data in the State files has a calculated discharge coefficient of 3.5. The dam crest is a broad crested weir with heavy overgrowth and has an estimated discharge coefficient of 2.6. The reservoir stage-storage curve was estimated from U. S. Geological Survey 7.5 - minute topographic maps. This stage-storage curve was extended above the dam crest to include surcharge storage during peak flood discharges. In the reservoir routing computations possible discharges through the outlet works were excluded because their capacity is small compared to the PMF and because of the possibility that the outlet valves may be closed. The stage-storage and the spillway and overtop stage-discharge curves for Skyline Lake Dam No. 1 are presented in Appendix D as Plates D-6 and D-7, respectively.

The breach parameters used in the HEC-1 analysis for Skyline Lake No. 1 are: the breach is rectangular in shape, 160 feet long, will extend to the approximate original reservoir floor elevation (259.3'), will begin breaching when the dam is first overtopped, and will develop to its maximum size in 1 hour. The peak outflow from Skyline Lake for the 15 percent, 25 percent, 50 percent and 100 percent PMF assuming failure, were calculated to be approximately 4,570 cfs, 5,910 cfs, 6,550 cfs, and 10,610 cfs, respectively.

The above described analyses resulted in the flooding characteristics at the Borough of Wanaque-Midvale that are summarized in the following tabulation.

<u>No Breaching</u>	<u>15% PMF</u>	<u>25% PMF</u>	<u>50% PMF</u>	<u>100% PMF</u>
Peak Discharge, cfs	1,305	2,450	5,080	10,240
Peak Flow Depth, ft.	5.8	7.1	9.1	11.5
Peak Flow Width, ft.	135	185	265	400
Peak Flow Velocity, fps	4.4	4.9	5.3	5.9

Breaching

Peak Discharge, cfs	4,490	5,840	6,410	10,560
Peak Flow Depth, ft.	8.7	9.5	9.8	11.6
Peak Flow Width, ft.	250	280	290	405
Peak Flow Velocity, fps	5.2	5.5	5.6	5.9

The reservoir drain intake for Skyline Lake No. 2 is at the floor of the lake near the dam and is 20 inches in diameter. Using the orifice flow equation, and assuming no tailwater and no inflows into the lake, the time required to drain the reservoir from a spillway full condition was calculated to be a little over 4 days.

b. Experience Data

Records of lake levels are not maintained for this site. The reservoir is operated to maintain maximum water levels for aesthetic and recreational purposes.

c. Visual Observations

The perimeter of the reservoir has generally moderately steep slopes with local, gently sloping areas. The adjacent area is heavily wooded and populated with single family residences.

A stilling basin is located immediately downstream of Skyline Lake Dam No. 1 and a bridge and playground are located approximately 300 and 500 feet downstream, respectively. The banks of the flood plain are moderately steep immediately downstream from the dams. The flood plain becomes wider and the banks less steep farther downstream from the dam.

d. Overtopping Potential

As indicated in Section 5.1-a, the spillway can pass only 10 percent of the PMF. During the PMF the embankment would be overtopped for about 7.0 hours and would have a maximum overtopping stage of about 5.8 feet above the dam crest. This overtopping height assumes the dam remains in its current condition. During the PMF, Skyline Lake Dam No. 2 would probably fail due to overtopping and cause overtopping and failure of downstream Dam No. 1. This would result in a significantly larger flood downstream and a significantly higher hazard to several residences in the Borough of Wanaque-Midvale that are near the stream banks and at elevations below the maximum flood stage. Thus, in accordance with the Corps' guidelines, the spillway for Skyline Lake Dam No. 2 is classified as Seriously Inadequate.

SECTION 6: STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations

Visual inspection indicates that the dam is need of maintenance work to assure continued structural integrity. There is significant local erosion of the downstream face of the embankment and the toe of the spillway apron is badly eroded. Some cracking and spalling at the concrete wingwalls was also observed. These factors are not presently severe enough to affect the structural strength or stability of the dam, but could jeopardize the integrity of the structure if left unchecked.

The outlet works appear to be in satisfactory condition based on visual observations.

b. Design and Construction Data

The available design and construction data are inadequate to evaluate the structural stability, since little is known of design criteria, construction methods or as-built material properties.

c. Operating Records

There is no instrumentation of the dam. The reservoir is essentially uncontrolled except for occasional draining of the reservoir for repairs of the dam and cleaning of the reservoir. Records of reservoir levels and water withdrawals are not available.

d. Post-Construction Changes

A 3-inch thick layer of macadam was placed over the original spillway apron which was severely eroded shortly after the initial filling of the reservoir. The toe of this new apron has since been severely eroded. In addition, a clay blanket was reportedly placed on the upstream face of the dam to reduce seepage observed under the spillway.

e. Seismic Stability

The dam is located in Seismic Zone 1, in which it may generally be assumed that there is no hazard from earthquakes, provided static stability conditions are satisfactory and conventional safety margins exist. However, as pointed out in Section 2.1-a, the dam is close to the seismically active Ramapo Fault, and the valley in which the dam is located may be structurally controlled. Data are insufficient at this time to assess seismic stability, should a significant earthquake occur in the vicinity of the dam.

SECTION 7: ASSESSMENT, RECOMMENDATIONS,
PROPOSED REMEDIAL MEASURES

7.1 Dam Assessment

a. Safety

The structural stability of Skyline Lake Dam No. 2 cannot be quantitatively analyzed due to lack of available data. However, visual inspection indicates that the dam is in need of repairs to assure continued structural integrity. Significant local erosion of the downstream face of the embankment and toe of the spillway apron was noted. In addition, there has been wave erosion of the upstream face of the embankment causing local steepening of the slope. There has been minor cracking and spalling of the concrete spillway wingwalls.

The spillway of the dam can pass only 10 percent of the Probable Maximum Flood and is classified as seriously inadequate.

b. Adequacy of Information

The information available is not adequate to perform a comprehensive, definitive evaluation of the dam's structural stability because of the lack of data regarding as-built conditions and physical properties of the dam and foundation materials.

c. Urgency

The deficiencies revealed by the visual inspection do not appear to be critical; however, they could imperil the integrity of the structure if left unchecked. Therefore, it is recommended that the owners perform the remedial measures discussed below, the most urgent of which should be done as soon as possible.

d. Necessity for Additional Data/Evaluation

At the present time there is insufficient information available to fully evaluate the structural stability of the dam. The Corps of Engineers Guidelines require that, in general, seepage and stability analyses should be on record for all dams in the high hazard category. There is presently no information about the as-built properties of the embankment. In addition, seepage at the toe of the dam has been previously noted by others. Therefore, a program of borings and laboratory tests should be performed to confirm the as-built properties of the embankment materials. Piezometers should also be installed to establish internal water levels in the downstream slope. These data should be evaluated by an experienced geotechnical engineer. The piezometers should be permanent and read periodically. The field investigation should begin in the near future and the evaluation performed soon after completion of the field work and testing. In addition, the dam should be surveyed in the near future to confirm the as-built geometry of the dam. As a result of the foregoing, necessary corrective steps should be taken in a timely manner.

The hydrologic analysis indicates that the spillway is seriously inadequate. Therefore, more sophisticated and detailed hydrologic analyses should be performed as soon as possible. From this a positive action program of corrective measures should be developed and implemented as necessary.

Although the dam is located in Seismic Zone 1, it is situated in a valley which was possibly formed as the result of faulting and is in close proximity to the seismically active Ramapo Fault. Therefore, the potential seismicity at the dam site and its effect on the stability of the dam should be investigated.

7.2 Remedial Measures

a. Corrective Procedures

It is recommended that the following remedial measures be performed as soon as possible:

1. The upstream embankment should be graded to the design slope and riprap or other suitable slope protection should be placed on the embankment to prevent further wave erosion.
2. Erosion scars on the downstream face of the embankment and the eroded section of embankment adjacent to the west wingwall should be filled and compacted with a suitable earthfill. If inspection of the embankment when the upper reservoir is full indicates that the erosion on the downstream face is caused by seepage, remedial measures to eliminate the seepage should be performed.
3. The eroded portion of the downstream toe of the spillway apron should be replaced and resurfaced in such a manner as to avoid further deterioration.
4. Remove the bridge piers from the spillway.

b. Operation and Maintenance Procedures

A program of inspections of the dam during and after critical floods and annually should be initiated by the owners, utilizing the standard visual checklist in this report.

The cracking and spalling of the spillway wingwalls should be carefully observed, and remedial work performed, should the deterioration continue.


A permanent record should be kept of all maintenance and operating events of the dam and reservoir.

All brush and small trees should be removed from the embankment soon, in order to facilitate inspection of the embankment and prevent root damage. Clearing of the embankment should continue as a standard maintenance procedure.

A warning system in coordination with Skyline Lake Dam No. 1 should be established whereby downstream inhabitants may be notified and evacuated in the event of possible dam failure.

A trash rack should be placed over the intake to the outlet conduit as soon as possible.

PLATES



AREA LOCATION

VICINITY MAP


JENNY-LEEDSHILL

JANUARY 1979

PLATE 2




PLAN - DAM 2
SCALE 1" = 40'




PROFILE - DAM 2
SCALE 1" = 40'

0+50 0+70 0+90 0+100


PLAN OF EAST ABUTMENT WALL
SCALE - 1" = 4'-0"




PLAN OF WEST ABUTMENT WALL
SCALE - 1" = 4'-0"



ELEVATION OF EAST ABUTMENT WALL
SCALE - 1" = 3'-0"




ELEVATION OF WEST ABUTMENT WALL
SCALE - 1" = 3'-0"





DAM 2 SH

PLATE 3




ELEVATION OF SPILLWAY
SCALE 1/16"




21-128-25

2




HEAD WALLS
SCALE - 1/32"




TYPICAL SECTION OF
SCALE 1/50"

PLAN OF VALVE WELL
SCALE - 6/30"



4' 0" DIA. - 12'
4' 6" DIA. - 12'
4' 0" DIA. - 12'
4' 6" DIA. - 12'

SECTION - VALVE WELL
SCALE - 4/30"



FILL SHOWING CORE

2

1:30"

23.5'

6' 0" DIA. - 12'

6' 0" DIA. - 12'

6' 0" DIA. - 12'

20' DIA. - 12'

APPENDIX A

CHECK LIST - VISUAL OBSERVATIONS

CHECK LIST - ENGINEERING, CONSTRUCTION
MAINTENANCE DATA

55

Check List
Visual Inspection
Phase 1

Name Dam Skyline Lake No. 2 County Passaic State New Jersey Coordinators NJDEP

Coordinates: Lat. 41° 04' 10" N
Long. 74° 16' 27" W

Date(s) Inspection Dec. 1, 1978
& Dec. 20, 1978

Weather Clear Temperature 42°F

Pool Elevation at Time of Inspection Empty M.S.L. Tailwater at Time of Inspection 282 ft. M.S.L.
(approx.)

Inspection Personnel:
(December 1, 1978)

R. C. Gaffin
P. L. Wagner
A. R. Slaughter

(December 20, 1978)
R. J. Jenny
D. J. Lachel

(December 20, 1978)
F. L. Panuzio
A. R. Slaughter

R. C. Gaffin Recorder

Owner Representative:
(December 1, 1978)

Mrs. K. Rausch, Skyline Lake Property Owners Assoc.

CONCRETE/MASONRY DAMS

Skyline Lake Dam No. 2

<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
SEEPAGE OR LEAKAGE	Not Applicable	
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS	Not Applicable	
DRAINS	Not Applicable	
WATER PASSAGES	Not Applicable	
FOUNDATION	Not Applicable	

CONCRETE/MASONRY DAMS

Skyline Lake Dam No. 2

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES	Not Applicable	
STRUCTURAL CRACKING	Not Applicable	
VERTICAL AND HORIZONTAL ALIGNMENT	Not Applicable	
MONOLITH JOINTS	Not Applicable	
CONSTRUCTION JOINTS	Not Applicable	

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	<p>Minor cracking of concrete wall which caps steel sheet piling near center of embankment. One crack has approximately 1/2" separation. No cracking of embankment noted.</p>	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	<p>None observed</p>	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES P 4	<p>-Two benches cut in upstream face of dam presumably due to reservoir wave action. -Erosional gully extends from outlet valve chamber to top of dam. A second gully which has been partly filled with riprap was observed in the center of the downstream face. Embankment has been eroded to a maximum of approximately 2.5 feet deep adjacent to the right spillway wingwalls.</p>	<p>Fill and compact eroded areas with suitable earth fill.</p>
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	<p>Horizontal alignment of crest appear to be as shown on plans. Steel sheet piling and concrete wall extend up to 6 inches above crest, indicating possible settlement or erosion of fill.</p>	
RIPRAP FAILURES	<p>No riprap was observed or upstream face of dam contrary to plans. Scattered cobble to boulder size stones on lower downstream face of dam.</p>	<p>Place riprap on upstream face of dam from the crest to approximately 5 feet below the lowest standard reservoir level.</p>

Skyline Lake Dam No. 2

EMBANKMENT

VISUAL EXAMINATION OF VEGETATION	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
	<p>Numerous trees up to 2 feet in diameter, and undergrowth on embankment and left abutment.</p>	
<p>JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM</p>	<p>Embankment has been eroded up to 2.5 feet deep adjacent to the right (west) spillway wingwall.</p>	<p>Fill and compact with suitable earth fill to the top of wingwalls.</p>
<p>ANY NOTICEABLE SEEPAGE</p>	<p>None observed. Reservoir was empty during inspection.</p>	
<p>STAFF GAGE AND RECORDER</p>	<p>None</p>	
<p>DRAINS</p>	<p>None</p>	

60

OUTLET WORKS

Skyline Lake Dam No. 2

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	None observed	
INTAKE STRUCTURE A-7	Concrete collar around end of 20-inch diameter cast iron outlet pipe in good condition. No trashrack. Empty oil drum, automobile tire and other rubbish in vicinity of intake.	Place trashrack over intake to outlet pipe.
OUTLET STRUCTURE	Concrete collar around end of 20-inch diameter cast iron outlet pipe at downstream toe of dam. Approximately 6 inches of water at outlet but no flow was noted. Concrete valve chamber with locked steel manhole cover located approximately 20 ft. upstream from outlet. Outlet pipe and of valve chamber appear to be in good condi-	tion. Could not observe outlet valve due to locked cover.
OUTLET CHANNEL	None. Reservoir located immediately downstream.	
EMERGENCY GATE	None.	

UNGATED SPILLWAY

Skyline Lake Dam No. 2

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	Minor cracking with no offset noted in spillway crest.	
APPROACH CHANNEL	Earth fill extends to spillway crest.	
DISCHARGE CHANNEL	Coarse aggregate macadam covered chute approximately 8 inches thick with concrete training walls. Severe erosion of downstream toe of chute. Undulating apron surface due to tree roots and/or settlement and minor cracking. Tree in spillway chute near east wingwall.	Toe of apron should be repaired.
BRIDGE AND PIERS	Four cylindrical concrete posts, 10 inches in diameter and 4.5 feet high, are located adjacent to the spillway crest; two upstream and two downstream.	These posts reportedly were used to support a foot bridge which was damaged and removed.
	Spalling noted at top of construction joint in center of west wingwall. Approximately 1/2-inch displacement between west wingwall and training wall. Vertical cracking and spalling noted at downstream end of east wingwall.	

GATED SPILLWAY

Skyline Lake Dam No. 2

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE SILL	Not Applicable	
APPROACH CHANNEL	Not Applicable	
DISCHARGE CHANNEL	Not Applicable	
BRIDGE AND PIERS	Not Applicable	
GATES AND OPERATION EQUIPMENT	Not Applicable	

INSTRUMENTATION

Skyline Lake Dam No. 2

VISUAL EXAMINATION MONUMENTATION/SURVEYS	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
OBSERVATION WELLS A-10	None	
WEIRS	None	
PIEZOMETERS	None	
OTHER	None	

RESERVOIR

Skyline Lake Dam No. 2

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	Generally moderately steep slopes with local gentle slopes; heavily wooded with single family residences.	
SEDIMENTATION	Reservoir was drained and being dredged during inspection. Sedimentation does not appear to be serious.	Reservoir is reportedly drained and cleaned every few years.

DOWNSTREAM CHANNEL

Skyline Lake Dam No. 2

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	Reservoir No. 1, located immediately downstream from Dam No. 2 was receiving water pumped from Reservoir No. 2 over the right abutment of dam.	
SLOPES	Slopes of the downstream reservoir are similar to those of the upstream reservoir. See 'Reservoir'.	
APPROXIMATE NO. OF HOMES AND POPULATION	Numerous single family residences around perimeter of lower reservoir. Approximately 6 houses in the Borough of Wanaque-Midvale are within the downstream flood path below Skyline Lake Dam No. 1.	

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION

ITEM	REMARKS
PLAN OF DAM	Sheets 2, 4, and 5 together with title sheet entitled "Plan and Profile for Construction of Dams at Skyline Lake, Borough of Ringwood, Passaic County, July 10, 1945", prepared by Newell Harrison, P.E., submitted with Report on Dam Application No. 399.
REGIONAL VICINITY MAP	Dam and reservoir are shown on U.S. Geological Survey, Wanaque Quadrangle (Scale: 1:24,000).
CONSTRUCTION HISTORY	Twelve Monthly Progress Reports on the construction of the dam prepared by the design engineer are available.
TYPICAL SECTIONS OF DAM	See 'Plan of Dam'
HYDROLOGIC/HYDRAULIC DATA	An estimated probable maximum flood runoff of 730 cfs was used to determine required spillway dimensions by the State Water Policy Commission. (letter dated June 20, 1944)
OUTLETS - PLAN	
- DETAILS - CONSTRAINTS - DISCHARGE RATINGS	See 'Plan of Dam' None None Available
RAINFALL/RESERVOIR RECORDS	None Available

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION

Skyline Lake Dam No. 2

ITEM	REMARKS
DESIGN REPORTS	None Available
GEOLOGY REPORTS	None Available
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES P-1-4	None Available
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	Application for Permit for Construction or Repair of Dam No. 399 dated June 27, 1945 indicates that the foundation material is 'sand, gravel, clay and hardpan as determined by test holes'. However, no boring records, laboratory or field data are available.
POST-CONSTRUCTION SURVEYS OF DAM	Contour maps and sections of Reservoir No. 2, prepared for dredging the reservoir by William Warring, dated Jan. 31, 1978.
BORROW SOURCES	Unknown

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION

Skyline Lake Dam No. 2

ITEM	REMARKS
SPILLWAY - PLAN - SECTIONS - DETAILS	See 'Plan of Dam'
OPERATING EQUIPMENT PLANS & DETAILS P I U	See 'Plan of Dam'
MONITORING SYSTEMS	None
MODIFICATIONS	Three inches of bituminous macadam was added to the surface of the spillway chute after construction as noted in the State's inspection report dated May 20, 1947.
HIGH POOL RECORDS	None Available
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	None
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	None

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION

Skyline Lake Dam No. 2

ITEM

REMARKS

MAINTENANCE
OPERATION
RECORDS

None

70

APPENDIX B

PHOTOGRAPHS

(Note: All photographs were taken on Dec. 1, 1978)



Photo 1
View of embankment
crest looking west
from spillway



Photo 2 View of upstream face of dam looking east



Photo 3 View of stone filled gully in central section of the downstream face of embankment



Photo 4 View of gully at eastern end of the downstream face of embankment looking down from dam crest




Photo 5 View of spillway looking east



Photo 6 View of
downstream
end of left
(east) wing
wall




Photo 7 View of spillway apron



Photo 8 View of intake to outlet pipe



Photo 9 View of outlet pipe and valve chamber at
downstream toe of dam




Photo 10 View looking upstream from dam




Photo 11 View of downstream reservoir area looking upstream from Dam #1

APPENDIX C

REGIONAL GEOLOGY - HIGHLANDS PROVINCE

REGIONAL GEOLOGY - HIGHLANDS PROVINCE

Physiography

The New Jersey Highlands extend northeast-southwest across the state from the New York border to the Delaware River. Included in the province are the northwest portions of Hunterdon, Passaic and Morris Counties and the southeastern portions of Warren and Sussex Counties. This province lies between the Appalachian Ridge and Valley Province to the northwest and the Piedmont Lowlands Province to the southeast (See Figure C-1) and is part of the larger New England Physiographic Province.

The Highlands are characterized by rounded and flat-topped northeast-southwest ridges and mountains up to 1,400 feet high separated by narrow valleys. The orientation of the valleys is usually, but not always, controlled by the underlying geologic structure.

Bedrock

Bedrock of the region is predominantly Precambrian gneisses, schists and metasediments. Some sedimentary rocks, typically sandstones, shales and conglomerate have been infolded and infaulted into the valley bottoms.


The regional geologic structure reflects the very old age of bedrock. A number of regional faults cross the area in a northeast-southwest direction. The Ramapo Fault scarp, forming the eastern border of the province, is more than 30 miles long. Faults also control many of the river valley orientations.

Mountain crests slope uniformly from northwest to southwest, a direct result of the fact that the entire area was once part of the now dissected Schooley peneplain.

Overburden

Much of the province was covered by the Pleistocene age Wisconsin glacier. The glacier stripped most of the existing overburden and weathered rock and uncovered the numerous hard bedrock knobs and ridges seen throughout the province. Most of the side-slopes in the area are covered with heavy boulder tills (ground moraine), while glacial outwash and recent alluvium cover the valleys. South of the terminal moraine extending from Morristown to Belvidere, scattered remnants of earlier stages of glaciation (Illinoian and Kansan) have deposited ground moraine (glacial tills) over the bedrock. In the valleys and over some of the ground moraine, recent and glacio-fluvial alluviums have been deposited.

80



SCHEMATIC CROSS-SECTION OF
 NEW JERSEY HIGHLANDS
 PHYSIOGRAPHIC PROVINCE
 (AFTER WOLFE, 1977)

JENNY/LEEDSHILL
 JANUARY 1979

FIGURE C-1

APPENDIX D

HYDROLOGIC AND HYDRAULIC COMPUTATIONS

SKYLINE LAKE No. 2

CHECK LIST
HYDROLOGIC AND HYDRAULIC DATA
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: 2.8 SQUARE MILES

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 280.3 FT (330 AF)

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): 284.3 (400 AF)

ELEVATION MAXIMUM DESIGN POOL: —

ELEVATION TOP DAM: 284.3 FT

CREST: SPILLWAY

- a. Elevation 280.3
- b. Type CONCRETE WALL
- c. Width 12
- d. Length 50 FT
- e. Location Spillover LEFT ABUTMENT (LOOKING DOWNSTREAM)
- f. Number and Type of Gates NONE

OUTLET WORKS: _____

- a. Type 20" PIPE & GATE VALVE
- b. Location RIGHT SIDE OF SPILLWAY (LOOKING DOWNSTREAM)
- c. Entrance inverts 261.8
- d. Exit inverts —
- e. Emergency draindown facilities _____

HYDROMETEOROLOGICAL GAGES: NONE

- a. Type _____
- b. Location _____
- c. Records _____

MAXIMUM NON-DAMAGING DISCHARGE: 1040 CFS

SKYLINE LAKE No. 1 & 2

CHAMPION LINE NO. 838-P LEEDS, HILL AND JEWETT, INC

BY RBE DATE 7/22/20 CLIENT N.J.

SHEET NO. 1 OF 2

CHRD DATE JOB TIME OF CONCENTRATION

JOB NO. 302

	1	2	3	4	5	6	7	8	9
1	DATA								
2	L = STREAM LENGTH FROM WATERSHED OUTLET TO THE MOST DISTANT RIDGE = 4.05 mi								
3									
4									
5	LCA = STREAM LENGTH FROM BASIN CENTROID = 2.25 mi								
6									
7	H = DIFF BETWEEN ELEV AT OUTLET AND ELEV AT MOST DISTANT POINT = 839 - 245 = 585'								
8									
9									
10	T _c = TIME OF CONCENTRATION OR TIME FOR WATER TO FLOW FROM THE MOST DISTANT POINT IN THE WATERSHED TO THE WATERSHED OUTLET								
11									
12									
13									
14									
15	T _L = LAG TIME FROM CENTER OF EXCESS RAINFALL TO TIME OF PEAK = 0.6 T _c								
16									
17									
18	METHOD 1	T _c = $\frac{L^{1.15}}{7700 H^{0.38}}$			L IN FT		H IN FT		
19									
20									
21		T _L = $\frac{0.6 L^{1.15}}{7700 H^{0.38}}$							
22									
23									
24									
25	METHOD 2	T _c = $\left(\frac{11.913}{H}\right)^{0.385}$			L IN MILES		H IN FT		
26									
27									
28		T _L = $0.6 \left(\frac{11.913}{H}\right)^{0.385}$							
29									
30									
31									
32	METHOD 3	T _L = C _t $\left(\frac{L L_c}{S^{1/2}}\right)^{0.38}$			S IN FT/MI		S = H/L = 2.7'		
33									
34									
35		T _L = C _t $\left(\frac{L L_c}{(H/L)^{1/2}}\right)^{0.38}$			C _t = 1.2		MOUNTAIN		
36					= 0.72		FOOTHILL		
37					= 0.35		VALLEY DRAINAGE AREA		
38									
39									
40	METHOD 4	T _c = L/V			V = AVG VELOCITY FROM CURVE OF V VS. AVG SLOP				
41									
42		T _L = 0.6 L/V			V = 2.8 fps				
43									
44									
45	DATA				LAG IN HOURS				
46									
47	SKYLINE # 2				METHODS				
48					1	2	3	4	USE
49					0.7	0.7	1.1	1.3	1.0
50					D-3				



RBF

781220

302

SKYJNE LAKE NO. 1 & 2

2/2



Average Velocity (ft/sec)

D-4

AVG SLOPE OF CHANNEL

90

BY DSE DATE

CLIENT N.J. DAM SAFETY

SHEET NO. OF

CHKD DATE

JOB

JOB NO. 302-03

1	2	3	4	5	6	7	8	9
1								
2	<u>REFERENCES</u>							
3								
4								
5	METHOD 1 - FROM "HANDBOOK OF APPLIED HYDROLOGY"							
6								
7								
8								
9								
10	METHOD 2 - FROM CALIFORNIA CULVERTS PRACTICE, CALIF							
11								
12								
13								
14								
15								
16	METHOD 3 - FROM HYDROLOGY FOR ENGINEERS							
17								
18								
19	METHOD 4 - FROM U.S. NAVY - TECHNICAL PUBLICATION							
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								
31								
32								
33								
34								
35								
36								
37								
38								
39								
40								
41								
42								
43								
44								
45								
46								
47								
48								
49								
50								

EMULATION LINE NO. 0304

LOCATION MAP OF CROSS-SECTIONS USED
FM ROUTING CALCULATIONS

31 33 35 37 39 41 43 45 47 49 51 53 55 57 59 61 63 65 67 69 71 73 75 77 79 81 83 85 87 89 91 93 95 97 99 101 103 105 107 109 111 113 115 117 119 121 123 125 127 129 131 133 135 137 139 141 143 145 147 149 151 153 155 157 159 161 163 165 167 169 171 173 175 177 179 181 183 185 187 189 191 193 195 197 199 201 203 205 207 209 211 213 215 217 219 221 223 225 227 229 231 233 235 237 239 241 243 245 247 249 251 253 255 257 259 261 263 265 267 269 271 273 275 277 279 281 283 285 287 289 291 293 295 297 299 301 303 305 307 309 311 313 315 317 319 321 323 325 327 329 331 333 335 337 339 341 343 345 347 349 351 353 355 357 359 361 363 365 367 369 371 373 375 377 379 381 383 385 387 389 391 393 395 397 399 401 403 405 407 409 411 413 415 417 419 421 423 425 427 429 431 433 435 437 439 441 443 445 447 449 451 453 455 457 459 461 463 465 467 469 471 473 475 477 479 481 483 485 487 489 491 493 495 497 499 501 503 505 507 509 511 513 515 517 519 521 523 525 527 529 531 533 535 537 539 541 543 545 547 549 551 553 555 557 559 561 563 565 567 569 571 573 575 577 579 581 583 585 587 589 591 593 595 597 599 601 603 605 607 609 611 613 615 617 619 621 623 625 627 629 631 633 635 637 639 641 643 645 647 649 651 653 655 657 659 661 663 665 667 669 671 673 675 677 679 681 683 685 687 689 691 693 695 697 699 701 703 705 707 709 711 713 715 717 719 721 723 725 727 729 731 733 735 737 739 741 743 745 747 749 751 753 755 757 759 761 763 765 767 769 771 773 775 777 779 781 783 785 787 789 791 793 795 797 799 801 803 805 807 809 811 813 815 817 819 821 823 825 827 829 831 833 835 837 839 841 843 845 847 849 851 853 855 857 859 861 863 865 867 869 871 873 875 877 879 881 883 885 887 889 891 893 895 897 899 901 903 905 907 909 911 913 915 917 919 921 923 925 927 929 931 933 935 937 939 941 943 945 947 949 951 953 955 957 959 961 963 965 967 969 971 973 975 977 979 981 983 985 987 989 991 993 995 997 999



TABLE 6-0. VALUES OF THE ROUGHNESS COEFFICIENT n (continued)

Type of channel and description	Minimum	Normal	Maximum
C. EXCAVATED OR DREDGED			
a. Earth, straight and uniform			
1. Clean, recently completed	0.016	0.018	0.020
2. Clean, after weathering	0.018	0.023	0.025
3. Gravel, uniform section, clean	0.022	0.025	0.030
4. With short grass, few weeds	0.022	0.027	0.033
b. Earth, winding and sluggish			
1. No vegetation	0.023	0.025	0.030
2. Grass, some weeds	0.025	0.030	0.033
3. Dense weeds or aquatic plants in deep channels	0.030	0.035	0.040
4. Earth bottom and rubble sides	0.028	0.030	0.035
5. Stony bottom and weedy banks	0.025	0.035	0.040
6. Cobble bottom and clean sides	0.030	0.040	0.050
c. Dragline-excavated or dredged			
1. No vegetation	0.025	0.028	0.033
2. Light brush on banks	0.035	0.050	0.060
4. Rock cuts			
1. Smooth and uniform	0.025	0.035	0.040
2. Jagged and irregular	0.035	0.040	0.050
d. Channels not maintained, weeds and brush over			
1. Dense weeds, high as flow depth	0.050	0.090	0.120
2. Clean bottom, brush on sides	0.040	0.050	0.080
3. Same, highest stage of flow	0.045	0.070	0.110
4. Dense brush, high stage	0.080	0.100	0.140
D. NATURAL STREAMS			
D-1. Minor streams (top width at flood stage <100 ft)			
a. Streams on plain			
1. Clean, straight, full stage, no rifts or deep pools	0.025	0.030	0.033
2. Same as above, but more stones and weeds	0.030	0.035	0.040
3. Clean, winding, some pools and shoals	0.033	0.040	0.045
4. Same as above, but some weeds and stones	0.035	0.045	0.050
5. Same as above, lower stages, more ineffective slopes and sections	0.040	0.048	0.055
6. Same as 4, but more stony	0.045	0.050	0.060
7. Sluggish reaches, weedy, deep pools	0.050	0.070	0.080
8. Very weedy reaches, deep pools, or floodways with heavy stand of timber and underbrush	0.075	0.100	0.150

MATCH CHANNEL
STATIONS 455

TABLE 6-1. VALUES OF THE ROUGHNESS COEFFICIENT n (continued)

Type of channel and description	Minimum	Normal	Maximum
b. Mountain streams, no vegetation in channel, banks usually steep, trees and brush along banks submerged at high stages	0.030	0.040	0.060
1. Bottom: gravel, cobbles, and few boulders	0.040	0.050	0.070
2. Bottom: cobbles with large boulders			
D-2. Flood plains			
a. Pasture, no brush			
1. Short grass	0.025	0.030	0.035
2. High grass	0.030	0.035	0.050
b. Cultivated areas			
1. No crop	0.020	0.030	0.040
2. Mature row crops	0.025	0.035	0.045
3. Mature field crops	0.030	0.040	0.050
4. Brush			
1. Scattered brush, heavy weeds	0.035	0.050	0.070
2. Light brush and trees, in winter	0.035	0.050	0.060
3. Light brush and trees, in summer	0.040	0.060	0.080
4. Medium to dense brush, in winter	0.045	0.070	0.110
5. Medium to dense brush, in summer	0.070	0.100	0.150
d. Trees			
1. Dense willows, summer, straight	0.110	0.150	0.200
2. Cleared land with tree stumps, no sprouts	0.030	0.040	0.050
3. Same as above, but with heavy growth of sprouts	0.050	0.060	0.090
4. Heavy stand of timber, a few down trees, little undergrowth, flood stage below branches	0.080	0.100	0.120
5. Same as above, but with flood stage reaching branches	0.100	0.120	0.160
D-3. Major streams (top width at flood stage >100 ft). The n value is less than that for minor streams of similar description, because banks offer less resistance.			
a. Regular section with no boulders or brush	0.025	0.060
b. Irregular and rough section	0.035	0.100

OPEN-CHANNEL HYDRAULICS

VEN TE CHOW, Ph.D.
Professor of Hydraulic Engineering
University of Illinois

790219

790219

Skyline Lake #2

302.03

Breach Parameters ^{1/}

Breach width = 180 ft.

Breach Shape = Rectangular

Time to maximum Breach size = 3 hours.

Begin Breach when first overtopped

Breach to elevation 262.8

^{1/} Based on previous studies of actual dam failures



Jan 790219

Skyline Lake #1

Breach Parameters

Breach width = 160 ft.

Breach shape = Rectangular

Time to Maximum Breach size = 1 hour

Begin Breach when first overtopped.

Breach to Elevation 259.3

↓ Based on previous studies of actual dam failures



RBC

790130

SKYLINE LAKE No. 2

302-03

DRAWDOWN CALCULATION ^U

ELEV. (FT)	STO. (AF)	Δ STO (AF)	MEAN HEAD (FT)	Δ TIME HR	Σ TIME HR
280.3	330				
		90	15.9	26.0	
275	240				26
		65	10.7	22.9	48.9
270	175				
		60	5.7	29.0	77.9
265	115				
		30	1.6	27.3	105.2
261.8	85				

20" PIPE & GATE VALUE

USE ORIFICE EQUATION

$$Q = CA \sqrt{2gH}$$

ASSUME $C = 0.6$

$$Q = 0.6 \left(\frac{\pi}{4} \left(\frac{20}{12} \right)^2 \right) \sqrt{2g} \sqrt{H}$$

$$Q = 10.5 H^{1/2}$$

$$\Delta \text{STORAGE} / \Delta \text{TIME} = 10.5 H^{1/2} \left(\frac{1}{43560} \text{ FT}^3/\text{AF} \right) (3600 \text{ SEC}/\text{HR})$$

$$\Delta \text{TIME} = \Delta \text{STORAGE} / 0.868 H^{1/2}$$

$$\Sigma \text{ TIME TO DRAIN} = 105.2 \text{ hrs} / 24 \text{ hr}/\text{DAY} = \underline{\underline{4.4 \text{ DAYS}}}$$

- U ASSUMES 1) NO INFLOWS TO LAKE
2) NO TAILWATER EFFECTS

RBE

790130

SKYLINE LAKE No. 1

302-03

DRAWDOWN CALCULATION^U

ELEV. (FT)	STO. (AF)	Δ STO (AF)	MEAN HEAD (FT)	Δ TIME (HR)	Σ TIME HRS
268.2	85				
		40	9.3	15.1	
265	45				15.1
		40	5.2	20.2	
260	5				35.3
		5	1.35	5.0	
257.3	0				40.3

20" PIPE AND GATE VALVE

USE ORIFICE EQUATION

$$Q = CA \sqrt{2gH}$$

ASSUME $C = 0.6$

$$Q = 0.6 \left(\frac{\pi}{4} \left(\frac{20}{12} \right)^2 \right) \sqrt{2gH}$$

$$\frac{\Delta \text{STORAGE}}{\Delta \text{TIME}} = 10.5 \text{ H}^{-1/2} \left(\frac{1}{4} 3560 \text{ FT}^3/\text{AF} \right) \left(3600 \text{ SEC}/\text{HR} \right)$$

$$\Delta \text{TIME} = \Delta \text{STORAGE} / 0.868 \text{ H}^{-1/2}$$

$$\Sigma \text{ TIME TO DRAIN} = 40.3 \text{ HR} / 24 \text{ HR}/\text{DAY} = 1.7 \text{ DAYS}$$

- ^U ASSUMES, 1) NO INFLOWS TO LAKE
2) NO TAILWATER EFFECTS

No Breach

```

*****
FLOOD HYDROGRAPH PACKAGE (MFC-11)
DAM SAFETY VERSION JULY 1978
LAST MODIFICATION 25 SEP 78
*****
AL NEW JERSEY DAM SAFETY - SKYLINE NO. 1 + 2, I.O. NO. 00293 + 00299
A2 HYDRAULIC-HYDROLOGIC ANALYSIS 302-02
A3 PROBABLE MAXIMUM FLOOD -PMS-
  3 144
  4 13
  5 1
  6 1
  7 1
  8 1
  9 1
 10 1
 11 1
 12 1
 13 1
 14 1
 15 1
 16 1
 17 1
 18 1
 19 1
 20 1
 21 1
 22 1
 23 1
 24 1
 25 1
 26 1
 27 1
 28 1
 29 1
 30 1
 31 1
 32 1
 33 1
 34 1
 35 1
 36 1
 37 1
 38 1
 39 1
 40 1
 41 1
 42 1
 43 1
 44 1
 45 1
 46 1
 47 1
 48 1
 49 1
 50 1
 51 1
 52 1
 53 1
 54 1
 55 1
 56 1
 57 1
 58 1
 59 1
 60 1
 61 1
 62 1
 63 1
 64 1
 65 1
 66 1
 67 1
 68 1
 69 1
 70 1
 71 1
 72 1
 73 1
 74 1
 75 1
 76 1
 77 1
 78 1
 79 1
 80 1
 81 1
 82 1
 83 1
 84 1
 85 1
 86 1
 87 1
 88 1
 89 1
 90 1
 91 1
 92 1
 93 1
 94 1
 95 1
 96 1
 97 1
 98 1
 99 1
100 1
101 1
102 1
103 1
104 1
105 1
106 1
107 1
108 1
109 1
110 1
111 1
112 1
113 1
114 1
115 1
116 1
117 1
118 1
119 1
120 1
121 1
122 1
123 1
124 1
125 1
126 1
127 1
128 1
129 1
130 1
131 1
132 1
133 1
134 1
135 1
136 1
137 1
138 1
139 1
140 1
141 1
142 1
143 1
144 1
145 1
146 1
147 1
148 1
149 1
150 1
151 1
152 1
153 1
154 1
155 1
156 1
157 1
158 1
159 1
160 1
161 1
162 1
163 1
164 1
165 1
166 1
167 1
168 1
169 1
170 1
171 1
172 1
173 1
174 1
175 1
176 1
177 1
178 1
179 1
180 1
181 1
182 1
183 1
184 1
185 1
186 1
187 1
188 1
189 1
190 1
191 1
192 1
193 1
194 1
195 1
196 1
197 1
198 1
199 1
200 1
201 1
202 1
203 1
204 1
205 1
206 1
207 1
208 1
209 1
210 1
211 1
212 1
213 1
214 1
215 1
216 1
217 1
218 1
219 1
220 1
221 1
222 1
223 1
224 1
225 1
226 1
227 1
228 1
229 1
230 1
231 1
232 1
233 1
234 1
235 1
236 1
237 1
238 1
239 1
240 1
241 1
242 1
243 1
244 1
245 1
246 1
247 1
248 1
249 1
250 1
251 1
252 1
253 1
254 1
255 1
256 1
257 1
258 1
259 1
260 1
261 1
262 1
263 1
264 1
265 1
266 1
267 1
268 1
269 1
270 1
271 1
272 1
273 1
274 1
275 1
276 1
277 1
278 1
279 1
280 1
281 1
282 1
283 1
284 1
285 1
286 1
287 1
288 1
289 1
290 1
291 1
292 1
293 1
294 1
295 1
296 1
297 1
298 1
299 1
300 1
301 1
302 1
303 1
304 1
305 1
306 1
307 1
308 1
309 1
310 1
311 1
312 1
313 1
314 1
315 1
316 1
317 1
318 1
319 1
320 1
321 1
322 1
323 1
324 1
325 1
326 1
327 1
328 1
329 1
330 1
331 1
332 1
333 1
334 1
335 1
336 1
337 1
338 1
339 1
340 1
341 1
342 1
343 1
344 1
345 1
346 1
347 1
348 1
349 1
350 1
351 1
352 1
353 1
354 1
355 1
356 1
357 1
358 1
359 1
360 1
361 1
362 1
363 1
364 1
365 1
366 1
367 1
368 1
369 1
370 1
371 1
372 1
373 1
374 1
375 1
376 1
377 1
378 1
379 1
380 1
381 1
382 1
383 1
384 1
385 1
386 1
387 1
388 1
389 1
390 1
391 1
392 1
393 1
394 1
395 1
396 1
397 1
398 1
399 1
400 1
401 1
402 1
403 1
404 1
405 1
406 1
407 1
408 1
409 1
410 1
411 1
412 1
413 1
414 1
415 1
416 1
417 1
418 1
419 1
420 1
421 1
422 1
423 1
424 1
425 1
426 1
427 1
428 1
429 1
430 1
431 1
432 1
433 1
434 1
435 1
436 1
437 1
438 1
439 1
440 1
441 1
442 1
443 1
444 1
445 1
446 1
447 1
448 1
449 1
450 1
451 1
452 1
453 1
454 1
455 1
456 1
457 1
458 1
459 1
460 1
461 1
462 1
463 1
464 1
465 1
466 1
467 1
468 1
469 1
470 1
471 1
472 1
473 1
474 1
475 1
476 1
477 1
478 1
479 1
480 1
481 1
482 1
483 1
484 1
485 1
486 1
487 1
488 1
489 1
490 1
491 1
492 1
493 1
494 1
495 1
496 1
497 1
498 1
499 1
500 1
501 1
502 1
503 1
504 1
505 1
506 1
507 1
508 1
509 1
510 1
511 1
512 1
513 1
514 1
515 1
516 1
517 1
518 1
519 1
520 1
521 1
522 1
523 1
524 1
525 1
526 1
527 1
528 1
529 1
530 1
531 1
532 1
533 1
534 1
535 1
536 1
537 1
538 1
539 1
540 1
541 1
542 1
543 1
544 1
545 1
546 1
547 1
548 1
549 1
550 1
551 1
552 1
553 1
554 1
555 1
556 1
557 1
558 1
559 1
560 1
561 1
562 1
563 1
564 1
565 1
566 1
567 1
568 1
569 1
570 1
571 1
572 1
573 1
574 1
575 1
576 1
577 1
578 1
579 1
580 1
581 1
582 1
583 1
584 1
585 1
586 1
587 1
588 1
589 1
590 1
591 1
592 1
593 1
594 1
595 1
596 1
597 1
598 1
599 1
600 1
601 1
602 1
603 1
604 1
605 1
606 1
607 1
608 1
609 1
610 1
611 1
612 1
613 1
614 1
615 1
616 1
617 1
618 1
619 1
620 1
621 1
622 1
623 1
624 1
625 1
626 1
627 1
628 1
629 1
630 1
631 1
632 1
633 1
634 1
635 1
636 1
637 1
638 1
639 1
640 1
641 1
642 1
643 1
644 1
645 1
646 1
647 1
648 1
649 1
650 1
651 1
652 1
653 1
654 1
655 1
656 1
657 1
658 1
659 1
660 1
661 1
662 1
663 1
664 1
665 1
666 1
667 1
668 1
669 1
670 1
671 1
672 1
673 1
674 1
675 1
676 1
677 1
678 1
679 1
680 1
681 1
682 1
683 1
684 1
685 1
686 1
687 1
688 1
689 1
690 1
691 1
692 1
693 1
694 1
695 1
696 1
697 1
698 1
699 1
700 1
701 1
702 1
703 1
704 1
705 1
706 1
707 1
708 1
709 1
710 1
711 1
712 1
713 1
714 1
715 1
716 1
717 1
718 1
719 1
720 1
721 1
722 1
723 1
724 1
725 1
726 1
727 1
728 1
729 1
730 1
731 1
732 1
733 1
734 1
735 1
736 1
737 1
738 1
739 1
740 1
741 1
742 1
743 1
744 1
745 1
746 1
747 1
748 1
749 1
750 1
751 1
752 1
753 1
754 1
755 1
756 1
757 1
758 1
759 1
760 1
761 1
762 1
763 1
764 1
765 1
766 1
767 1
768 1
769 1
770 1
771 1
772 1
773 1
774 1
775 1
776 1
777 1
778 1
779 1
780 1
781 1
782 1
783 1
784 1
785 1
786 1
787 1
788 1
789 1
790 1
791 1
792 1
793 1
794 1
795 1
796 1
797 1
798 1
799 1
800 1
801 1
802 1
803 1
804 1
805 1
806 1
807 1
808 1
809 1
810 1
811 1
812 1
813 1
814 1
815 1
816 1
817 1
818 1
819 1
820 1
821 1
822 1
823 1
824 1
825 1
826 1
827 1
828 1
829 1
830 1
831 1
832 1
833 1
834 1
835 1
836 1
837 1
838 1
839 1
840 1
841 1
842 1
843 1
844 1
845 1
846 1
847 1
848 1
849 1
850 1
851 1
852 1
853 1
854 1
855 1
856 1
857 1
858 1
859 1
860 1
861 1
862 1
863 1
864 1
865 1
866 1
867 1
868 1
869 1
870 1
871 1
872 1
873 1
874 1
875 1
876 1
877 1
878 1
879 1
880 1
881 1
882 1
883 1
884 1
885 1
886 1
887 1
888 1
889 1
890 1
891 1
892 1
893 1
894 1
895 1
896 1
897 1
898 1
899 1
900 1
901 1
902 1
903 1
904 1
905 1
906 1
907 1
908 1
909 1
910 1
911 1
912 1
913 1
914 1
915 1
916 1
917 1
918 1
919 1
920 1
921 1
922 1
923 1
924 1
925 1
926 1
927 1
928 1
929 1
930 1
931 1
932 1
933 1
934 1
935 1
936 1
937 1
938 1
939 1
940 1
941 1
942 1
943 1
944 1
945 1
946 1
947 1
948 1
949 1
950 1
951 1
952 1
953 1
954 1
955 1
956 1
957 1
958 1
959 1
960 1
961 1
962 1
963 1
964 1
965 1
966 1
967 1
968 1
969 1
970 1
971 1
972 1
973 1
974 1
975 1
976 1
977 1
978 1
979 1
980 1
981 1
982 1
983 1
984 1
985 1
986 1
987 1
988 1
989 1
990 1
991 1
992 1
993 1
994 1
995 1
996 1
997 1
998 1
999 1
1000 1

```

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

HYDROGRAPH AT 1
 HYDROGRAPH TO 2
 HYDROGRAPH TO 3
 HYDROGRAPH TO 4
 HYDROGRAPH TO 5
 END OF NETWORK


AD-A069 615

NEW JERSEY STATE DEPT OF ENVIRONMENTAL PROTECTION TRENTON F/G 13/2
NATIONAL DAM SAFETY PROGRAM. SKYLINE LAKE DAM NUMBER 2 (NJ00200--ETC(U)
MAY 79 R J JENNY DACW61-78-C-0124


UNCLASSIFIED

2 OF 2
AD
AO99615

NL



END
DATE
FILMED
7-79
DDC



NATIONAL BUREAU OF STANDARDS
MICROCOPY RESOLUTION TEST CHART

 FLOOD HYDROGRAPH PACKAGE (MFC-1)
 DAN SAFETY VERSION JULY 1974
 LAST MODIFICATION 25 SEP 74

RUN DATED 01/24/79
 TIME 09:57:23.

NEW JERSEY DAN SAFETY - SKYLINE NO. 1 + 2, I.O. NO. 00203 + 00200
 HYDRAULIC-HYDROLOGIC ANALYSIS 302-93
 PROBABLE MAXIMUM FLOOD -REF-

NO	NUM	WHEN	IDAY	TIME	METRIC	IPLT	IPRT	INSTAN
144	0	10	JUNE	0	LEOPT TRACE	0	0	0

JOB SPECIFICATION
 MULTIS-PLAN ANALYSES TO BE PERFORMED
 RATIO= .15 .25 .35 1.00
 PPLD= 1 RATIO= 4 LRTIO= 1

***** SUB-AREA RUNDOFF COMPUTATION *****

RUNOFF FROM AREA ABOVE SKYLINE LAKE NO. 2

ESTAQ	ICOMP	IECON	IEAPE	JPLT	JMPE	ESTAGE	LAUTO
1	0	0	0	0	1	0	0

INVAR	IUNG	TAREA	SNAP	TPSDA	TRSPC	RATIO	ISHOW	ISAVE	LOCAL
1	2	2.83	0.00	2.86	0.00	0.000	0	0	0

SPCE	PMS	MS	RZ	RZA	R48	R72	P%
0.00	22.00	112.00	123.00	133.00	0.00	0.00	0.00

TRSPC COMPUTED BY THE PROGRAM IS .000

LEOPT	STAGE	OLTR	RETR	ERAIN	SINCS	RTIQR	SINFL	CHSTL	ALSM	RTIMP
1	0.00	0.00	1.00	0.00	0.00	1.00	1.00	.10	0.00	3.00

UNIT HYDROGRAPH DATA
 TC= 0.00 LAG= 1.00

RECESSION DATA
 SINTO= -1.00 OCSM= -.05 RTIQR= 2.00

UNIT	HYDROGRAPH	32	END	OF	PERIOD	ORDINATES,	TC=	0.00	HOURS,	LAG=	1.00	VOL=	1.00	TOTL
84.	249.	510.	555.	1119.	1230.	1134.	79.	900.	701.					
94.	452.	240.	279.	210.	111.	112.	7.	01.	01.					
44.	37.	20.	23.	14.	11.	11.	7.	5.	5.					
3.	1.													

MO,DA	HR,MP	PERIOD	RAIN	ETCS	LOSS	COMP 0	END-OF-PERIOD FLD	COMP 0	HR,14	PERIOD	RAIN	ETCS	LOSS	COMP 0
1-01	1-01	1	.02	6.00	.02	2	1-01	1	12-10	73	.33	.31	.02	423
1-01	1-01	2	.02	6.00	.02	2	1-01	2	12-10	74	.33	.31	.02	423
1-01	1-01	3	.02	6.00	.02	2	1-01	3	12-10	75	.33	.31	.02	423
1-01	1-01	4	.02	6.00	.02	2	1-01	4	12-10	76	.33	.31	.02	423
1-01	1-01	5	.02	6.00	.02	2	1-01	5	12-10	77	.33	.31	.02	423
1-01	1-01	6	.02	6.00	.02	2	1-01	6	12-10	78	.33	.31	.02	423
1-01	1-01	7	.02	6.00	.02	2	1-01	7	12-10	79	.33	.31	.02	423
1-01	1-01	8	.02	6.00	.02	2	1-01	8	12-10	80	.33	.31	.02	423
1-01	1-01	9	.02	6.00	.02	2	1-01	9	12-10	81	.33	.31	.02	423
1-01	1-01	10	.02	6.00	.02	2	1-01	10	12-10	82	.33	.31	.02	423
1-01	1-01	11	.02	6.00	.02	2	1-01	11	12-10	83	.33	.31	.02	423
1-01	1-01	12	.02	6.00	.02	2	1-01	12	12-10	84	.33	.31	.02	423
1-01	1-01	13	.02	6.00	.02	2	1-01	13	12-10	85	.33	.31	.02	423
1-01	1-01	14	.02	6.00	.02	2	1-01	14	12-10	86	.33	.31	.02	423
1-01	1-01	15	.02	6.00	.02	2	1-01	15	12-10	87	.33	.31	.02	423
1-01	1-01	16	.02	6.00	.02	2	1-01	16	12-10	88	.33	.31	.02	423
1-01	1-01	17	.02	6.00	.02	2	1-01	17	12-10	89	.33	.31	.02	423
1-01	1-01	18	.02	6.00	.02	2	1-01	18	12-10	90	.33	.31	.02	423
1-01	1-01	19	.02	6.00	.02	2	1-01	19	12-10	91	.33	.31	.02	423
1-01	1-01	20	.02	6.00	.02	2	1-01	20	12-10	92	.33	.31	.02	423
1-01	1-01	21	.02	6.00	.02	2	1-01	21	12-10	93	.33	.31	.02	423
1-01	1-01	22	.02	6.00	.02	2	1-01	22	12-10	94	.33	.31	.02	423
1-01	1-01	23	.02	6.00	.02	2	1-01	23	12-10	95	.33	.31	.02	423
1-01	1-01	24	.02	6.00	.02	2	1-01	24	12-10	96	.33	.31	.02	423
1-01	1-01	25	.02	6.00	.02	2	1-01	25	12-10	97	.33	.31	.02	423
1-01	1-01	26	.02	6.00	.02	2	1-01	26	12-10	98	.33	.31	.02	423
1-01	1-01	27	.02	6.00	.02	2	1-01	27	12-10	99	.33	.31	.02	423
1-01	1-01	28	.02	6.00	.02	2	1-01	28	12-10	100	.33	.31	.02	423
1-01	1-01	29	.02	6.00	.02	2	1-01	29	12-10	101	.33	.31	.02	423
1-01	1-01	30	.02	6.00	.02	2	1-01	30	12-10	102	.33	.31	.02	423
1-01	1-01	31	.02	6.00	.02	2	1-01	31	12-10	103	.33	.31	.02	423
1-01	1-01	32	.02	6.00	.02	2	1-01	32	12-10	104	.33	.31	.02	423
1-01	1-01	33	.02	6.00	.02	2	1-01	33	12-10	105	.33	.31	.02	423
1-01	1-01	34	.02	6.00	.02	2	1-01	34	12-10	106	.33	.31	.02	423
1-01	1-01	35	.02	6.00	.02	2	1-01	35	12-10	107	.33	.31	.02	423
1-01	1-01	36	.02	6.00	.02	2	1-01	36	12-10	108	.33	.31	.02	423
1-01	1-01	37	.02	6.00	.02	2	1-01	37	12-10	109	.33	.31	.02	423
1-01	1-01	38	.02	6.00	.02	2	1-01	38	12-10	110	.33	.31	.02	423
1-01	1-01	39	.02	6.00	.02	2	1-01	39	12-10	111	.33	.31	.02	423
1-01	1-01	40	.02	6.00	.02	2	1-01	40	12-10	112	.33	.31	.02	423
1-01	1-01	41	.02	6.00	.02	2	1-01	41	12-10	113	.33	.31	.02	423
1-01	1-01	42	.02	6.00	.02	2	1-01	42	12-10	114	.33	.31	.02	423
1-01	1-01	43	.02	6.00	.02	2	1-01	43	12-10	115	.33	.31	.02	423
1-01	1-01	44	.02	6.00	.02	2	1-01	44	12-10	116	.33	.31	.02	423
1-01	1-01	45	.02	6.00	.02	2	1-01	45	12-10	117	.33	.31	.02	423
1-01	1-01	46	.02	6.00	.02	2	1-01	46	12-10	118	.33	.31	.02	423
1-01	1-01	47	.02	6.00	.02	2	1-01	47	12-10	119	.33	.31	.02	423
1-01	1-01	48	.02	6.00	.02	2	1-01	48	12-10	120	.33	.31	.02	423
1-01	1-01	49	.02	6.00	.02	2	1-01	49	12-10	121	.33	.31	.02	423
1-01	1-01	50	.02	6.00	.02	2	1-01	50	12-10	122	.33	.31	.02	423
1-01	1-01	51	.02	6.00	.02	2	1-01	51	12-10	123	.33	.31	.02	423
1-01	1-01	52	.02	6.00	.02	2	1-01	52	12-10	124	.33	.31	.02	423
1-01	1-01	53	.02	6.00	.02	2	1-01	53	12-10	125	.33	.31	.02	423
1-01	1-01	54	.02	6.00	.02	2	1-01	54	12-10	126	.33	.31	.02	423
1-01	1-01	55	.02	6.00	.02	2	1-01	55	12-10	127	.33	.31	.02	423
1-01	1-01	56	.02	6.00	.02	2	1-01	56	12-10	128	.33	.31	.02	423
1-01	1-01	57	.02	6.00	.02	2	1-01	57	12-10	129	.33	.31	.02	423
1-01	1-01	58	.02	6.00	.02	2	1-01	58	12-10	130	.33	.31	.02	423
1-01	1-01	59	.02	6.00	.02	2	1-01	59	12-10	131	.33	.31	.02	423
1-01	1-01	60	.02	6.00	.02	2	1-01	60	12-10	132	.33	.31	.02	423
1-01	1-01	61	.02	6.00	.02	2	1-01	61	12-10	133	.33	.31	.02	423
1-01	1-01	62	.02	6.00	.02	2	1-01	62	12-10	134	.33	.31	.02	423
1-01	1-01	63	.02	6.00	.02	2	1-01	63	12-10	135	.33	.31	.02	423
1-01	1-01	64	.02	6.00	.02	2	1-01	64	12-10	136	.33	.31	.02	423
1-01	1-01	65	.02	6.00	.02	2	1-01	65	12-10	137	.33	.31	.02	423
1-01	1-01	66	.02	6.00	.02	2	1-01	66	12-10	138	.33	.31	.02	423
1-01	1-01	67	.02	6.00	.02	2	1-01	67	12-10	139	.33	.31	.02	423
1-01	1-01	68	.02	6.00	.02	2	1-01	68	12-10	140	.33	.31	.02	423
1-01	1-01	69	.02	6.00	.02	2	1-01	69	12-10	141	.33	.31	.02	423
1-01	1-01	70	.02	6.00	.02	2	1-01	70	12-10	142	.33	.31	.02	423
1-01	1-01	71	.02	6.00	.02	2	1-01	71	12-10	143	.33	.31	.02	423
1-01	1-01	72	.02	6.00	.02	2	1-01	72	12-10	144	.33	.31	.02	423

SUN 23-01 20-70 2-71 224907
 (595.31 526.31 6-31 6366.37)

HYDROGRAPH ROUTING

CHANNEL ROUTING - MODIFIED PULS - STATION 3 TO 4

ISTAQ 0
 IECOM 1
 ITRAP 0
 JPLT 0
 JPRF 0
 IMANE 1
 ISTAGE 0
 IMAUTO 0
 ROUTING DATA
 IMAE 1
 ISAME 1
 ISPT 0
 ISPR 0
 LSTR 0
 MSPTS 1
 MSTR 0
 LAG 0
 ANSK 0
 X 0
 TSK 0
 STORA 0
 ESPRAY 0

NORMAL DEPTH CHANNEL ROUTING

Q411 Q412 Q413 ELWY ELMAX RLWTH SEL
 .1800 .0450 .1800 237.0 298.0 150. .00000

GROSS SECTION COORDINATES--STALEY, STA. ELEV--CIG
 0.00 250.00 150.00 200.00 250.00 261.00 500.00 257.00 525.00 257.00
 535.00 261.00 700.00 200.00 1150.00 250.00

STORAGE	0.00	10.75	13.26	18.26	16.87	19.16	17.4	22.02	2.21	26.69	31.35	36.71	42.59	49.22
OUTFLOW	0.00	170.02	276.75	276.75	263.51	1310.03	2066.02	5021.17	4050.91	78756.67	6209.69	8992.66	12469.11	16039.90
STAGE	297.00	276.37	276.11	268.47	277.06	275.00	281.32	283.95	269.08	267.42	266.79	266.16	270.30	272.63
FLOW	0.00	170.02	276.75	263.51	276.75	1310.03	2066.02	5021.17	4050.91	78756.67	6209.69	8992.66	12469.11	16039.90

STATION 4, PLAN 1, RTIO 1

HYDROGRAPH ROUTING

CHANNEL ROUTING -MODIFIED PULS- STATION 4 TO 5

ISTAG	ICOMP	ISECM	IFRPE	JPR1	JPR2	IMAGE	ISTAGE	IAUTO
1	1	1	1	0	0	1	0	0
ROUTING DATA								
CLASS	AVG	IRCS	ISAME	ISPT	ISPK	ISSTG	ISPPAT	
0.0	0.000	0.000	1	1	0	0	0	
RSTOR								
1	0	0	0.000	0.000	0.000	0.000	0.000	0.000

NORMAL CHANNEL ROUTING

0M111	0M121	0M131	FLNVT	ELNAT	PLNFM	SEL
.0000	.0000	.0000	240.0	280.0	225.0	.00000

CROSS SECTION COMPUTATIONS--11-2-54
 0.00 240.00 1000.00 240.00 225.00 1150.00 250.00 1175.00 250.00
 1175.00 240.00 1000.00 240.00 225.00 1150.00 250.00

STORAGE	0.00	208.61	257.73	294.10	332.67	411.75	486.21	558.50	600.23	640.23	678.00	714.00	749.00	783.00	816.00	848.00	879.00	909.00	938.00	966.00	993.00	1019.00	1044.00	1068.00	1091.00	1113.00	1134.00	1154.00	1173.00	1191.00	1208.00	1224.00	1240.00	1255.00	1270.00	1284.00	1298.00	1312.00	1326.00	1340.00	1354.00	1368.00	1382.00	1396.00	1410.00	1424.00	1438.00	1452.00	1466.00	1480.00	1494.00	1508.00	1522.00	1536.00	1550.00	1564.00	1578.00	1592.00	1606.00	1620.00	1634.00	1648.00	1662.00	1676.00	1690.00	1704.00	1718.00	1732.00	1746.00	1760.00	1774.00	1788.00	1802.00	1816.00	1830.00	1844.00	1858.00	1872.00	1886.00	1900.00	1914.00	1928.00	1942.00	1956.00	1970.00	1984.00	1998.00	2012.00	2026.00	2040.00	2054.00	2068.00	2082.00	2096.00	2110.00	2124.00	2138.00	2152.00	2166.00	2180.00	2194.00	2208.00	2222.00	2236.00	2250.00	2264.00	2278.00	2292.00	2306.00	2320.00	2334.00	2348.00	2362.00	2376.00	2390.00	2404.00	2418.00	2432.00	2446.00	2460.00	2474.00	2488.00	2502.00	2516.00	2530.00	2544.00	2558.00	2572.00	2586.00	2600.00	2614.00	2628.00	2642.00	2656.00	2670.00	2684.00	2698.00	2712.00	2726.00	2740.00	2754.00	2768.00	2782.00	2796.00	2810.00	2824.00	2838.00	2852.00	2866.00	2880.00	2894.00	2908.00	2922.00	2936.00	2950.00	2964.00	2978.00	2992.00	3006.00	3020.00	3034.00	3048.00	3062.00	3076.00	3090.00	3104.00	3118.00	3132.00	3146.00	3160.00	3174.00	3188.00	3202.00	3216.00	3230.00	3244.00	3258.00	3272.00	3286.00	3300.00	3314.00	3328.00	3342.00	3356.00	3370.00	3384.00	3398.00	3412.00	3426.00	3440.00	3454.00	3468.00	3482.00	3496.00	3510.00	3524.00	3538.00	3552.00	3566.00	3580.00	3594.00	3608.00	3622.00	3636.00	3650.00	3664.00	3678.00	3692.00	3706.00	3720.00	3734.00	3748.00	3762.00	3776.00	3790.00	3804.00	3818.00	3832.00	3846.00	3860.00	3874.00	3888.00	3902.00	3916.00	3930.00	3944.00	3958.00	3972.00	3986.00	4000.00	4014.00	4028.00	4042.00	4056.00	4070.00	4084.00	4098.00	4112.00	4126.00	4140.00	4154.00	4168.00	4182.00	4196.00	4210.00	4224.00	4238.00	4252.00	4266.00	4280.00	4294.00	4308.00	4322.00	4336.00	4350.00	4364.00	4378.00	4392.00	4406.00	4420.00	4434.00	4448.00	4462.00	4476.00	4490.00	4504.00	4518.00	4532.00	4546.00	4560.00	4574.00	4588.00	4602.00	4616.00	4630.00	4644.00	4658.00	4672.00	4686.00	4700.00	4714.00	4728.00	4742.00	4756.00	4770.00	4784.00	4798.00	4812.00	4826.00	4840.00	4854.00	4868.00	4882.00	4896.00	4910.00	4924.00	4938.00	4952.00	4966.00	4980.00	4994.00	5008.00	5022.00	5036.00	5050.00	5064.00	5078.00	5092.00	5106.00	5120.00	5134.00	5148.00	5162.00	5176.00	5190.00	5204.00	5218.00	5232.00	5246.00	5260.00	5274.00	5288.00	5302.00	5316.00	5330.00	5344.00	5358.00	5372.00	5386.00	5400.00	5414.00	5428.00	5442.00	5456.00	5470.00	5484.00	5498.00	5512.00	5526.00	5540.00	5554.00	5568.00	5582.00	5596.00	5610.00	5624.00	5638.00	5652.00	5666.00	5680.00	5694.00	5708.00	5722.00	5736.00	5750.00	5764.00	5778.00	5792.00	5806.00	5820.00	5834.00	5848.00	5862.00	5876.00	5890.00	5904.00	5918.00	5932.00	5946.00	5960.00	5974.00	5988.00	6002.00	6016.00	6030.00	6044.00	6058.00	6072.00	6086.00	6100.00	6114.00	6128.00	6142.00	6156.00	6170.00	6184.00	6198.00	6212.00	6226.00	6240.00	6254.00	6268.00	6282.00	6296.00	6310.00	6324.00	6338.00	6352.00	6366.00	6380.00	6394.00	6408.00	6422.00	6436.00	6450.00	6464.00	6478.00	6492.00	6506.00	6520.00	6534.00	6548.00	6562.00	6576.00	6590.00	6604.00	6618.00	6632.00	6646.00	6660.00	6674.00	6688.00	6702.00	6716.00	6730.00	6744.00	6758.00	6772.00	6786.00	6800.00	6814.00	6828.00	6842.00	6856.00	6870.00	6884.00	6898.00	6912.00	6926.00	6940.00	6954.00	6968.00	6982.00	6996.00	7010.00	7024.00	7038.00	7052.00	7066.00	7080.00	7094.00	7108.00	7122.00	7136.00	7150.00	7164.00	7178.00	7192.00	7206.00	7220.00	7234.00	7248.00	7262.00	7276.00	7290.00	7304.00	7318.00	7332.00	7346.00	7360.00	7374.00	7388.00	7402.00	7416.00	7430.00	7444.00	7458.00	7472.00	7486.00	7500.00	7514.00	7528.00	7542.00	7556.00	7570.00	7584.00	7598.00	7612.00	7626.00	7640.00	7654.00	7668.00	7682.00	7696.00	7710.00	7724.00	7738.00	7752.00	7766.00	7780.00	7794.00	7808.00	7822.00	7836.00	7850.00	7864.00	7878.00	7892.00	7906.00	7920.00	7934.00	7948.00	7962.00	7976.00	7990.00	8004.00	8018.00	8032.00	8046.00	8060.00	8074.00	8088.00	8102.00	8116.00	8130.00	8144.00	8158.00	8172.00	8186.00	8200.00	8214.00	8228.00	8242.00	8256.00	8270.00	8284.00	8298.00	8312.00	8326.00	8340.00	8354.00	8368.00	8382.00	8396.00	8410.00	8424.00	8438.00	8452.00	8466.00	8480.00	8494.00	8508.00	8522.00	8536.00	8550.00	8564.00	8578.00	8592.00	8606.00	8620.00	8634.00	8648.00	8662.00	8676.00	8690.00	8704.00	8718.00	8732.00	8746.00	8760.00	8774.00	8788.00	8802.00	8816.00	8830.00	8844.00	8858.00	8872.00	8886.00	8900.00	8914.00	8928.00	8942.00	8956.00	8970.00	8984.00	8998.00	9012.00	9026.00	9040.00	9054.00	9068.00	9082.00	9096.00	9110.00	9124.00	9138.00	9152.00	9166.00	9180.00	9194.00	9208.00	9222.00	9236.00	9250.00	9264.00	9278.00	9292.00	9306.00	9320.00	9334.00	9348.00	9362.00	9376.00	9390.00	9404.00	9418.00	9432.00	9446.00	9460.00	9474.00	9488.00	9502.00	9516.00	9530.00	9544.00	9558.00	9572.00	9586.00	9600.00	9614.00	9628.00	9642.00	9656.00	9670.00	9684.00	9698.00	9712.00	9726.00	9740.00	9754.00	9768.00	9782.00	9796.00	9810.00	9824.00	9838.00	9852.00	9866.00	9880.00	9894.00	9908.00	9922.00	9936.00	9950.00	9964.00	9978.00	9992.00	10006.00	10020.00	10034.00	10048.00	10062.00	10076.00	10090.00	10104.00	10118.00	10132.00	10146.00	10160.00	10174.00	10188.00	10202.00	10216.00	10230.00	10244.00	10258.00	10272.00	10286.00	10300.00	10314.00	10328.00	10342.00	10356.00	10370.00	10384.00	10398.00	10412.00	10426.00	10440.00	10454.00	10468.00	10482.00	10496.00	10510.00	10524.00	10538.00	10552.00	10566.00	10580.00	10594.00	10608.00	10622.00	10636.00	10650.00	10664.00	10678.00	10692.00	10706.00	10720.00	10734.00	10748.00	10762.00	10776.00	10790.00	10804.00	10818.00	10832.00	10846.00	10860.00	10874.00	10888.00	10902.00	10916.00	10930.00	10944.00	10958.00	10972.00	10986.00	11000.00	11014.00	11028.00	11042.00	11056.00	11070.00	11084.00	11098.00	11112.00	11126.00	11140.00	11154.00	11168.00	11182.00	11196.00	11210.00	11224.00	11238.00	11252.00	11266.00	11280.00	11294.00	11308.00	11322.00	11336.00	11350.00	11364.00	11378.00	11392.00	11406.00	11420.00	11434.00	11448.00	11462.00	11476.00	11490.00	11504.00	11518.00	11532.00	11546.00	11560.00	11574.00	11588.00	11602.00	11616.00	11630.00	11644.00	11658.00	11672.00	11686.00	11700.00	11714.00	11728.00	11742.00	11756.00	11770.00	11784.00	11798.00	11812.00	11826.00	11840.00	11854.00	11868.00	11882.00	11896.00	11910.00	11924.00	11938.00	11952.00	11966.00	11980.00	11994.00	12008.00	12022.00	12036.00	12050.00	12064.00	12078.00	12092.00	12106.00	12120.00	12134.00	12148.00	12162.00	12176.00	12190.00	12204.00	12218.00	12232.00	12246.00	12260.00	12274.00	12288.00	12302.00	12316.00	12330.00	12344.00	12358.00	12372.00	12386.00	12400.00	12414.00	12428.00	12442.00	12456.00	12470.00	12484.00	12498.00	12512.00	12526.00	12540.00	12554.00	12568.00	12582.00	12596.00	12610.00	12624.00	12638.00	12652.00	12666.00	12680.00	12694.00	12708.00	12722.00	12736.00	12750.00	12764.00	12778.00	12792.00	12806.00
---------	------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATED ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS			
				RATIO 1	RATIO 2	RATIO 3	RATIO 4
				.15	.25	.50	1.00
HYDROGRAPH AT	1	2.00	1	1541.	2035.	3271.	10942.
		7.251	1	44.781	74.631	144.261	290.321
ROUTED TO	2	2.00	1	1466.	2544.	5103.	10427.
		7.251	1	41.561	72.001	144.201	290.251
ROUTED TO	3	2.00	1	1326.	2484.	5112.	10350.
		7.251	1	37.301	70.331	144.701	293.731
ROUTED TO	4	2.00	1	1320.	2444.	5111.	10351.
		7.251	1	37.301	70.351	144.741	293.101
ROUTED TO	5	2.00	1	1303.	2452.	5077.	10242.
		7.251	1	36.931	69.401	143.761	290.631

No BREACH

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION STORAGE	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
0.00	200.30	290.30	294.30	422.00
0.25	330.00	330.00	330.00	1846.00
0.50	460.00	460.00	460.00	0.00
1.00	590.00	590.00	590.00	0.00

RATIO OF PWF	MAXIMUM REVENUE	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
0.15	206.07	0.37	513.0	1540.0	1.33	16.03	0.00
0.25	245.81	1.51	433.0	2948.0	3.33	16.03	0.00
0.50	297.49	3.19	470.0	3165.0	5.67	16.07	0.00
1.00	200.00	5.76	527.0	10427.0	6.03	16.07	0.00

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 3	ELEVATION STORAGE	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
0.00	200.20	260.20	272.20	1400.00
0.25	49.00	49.00	49.00	1400.00
0.50	98.00	98.00	98.00	1400.00
1.00	196.00	196.00	196.00	1400.00

RATIO OF PWF	MAXIMUM REVENUE	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
0.15	272.09	0.00	193.0	1320.0	0.00	17.33	0.00
0.25	275.29	1.00	146.0	2494.0	2.17	17.00	0.00
0.50	275.04	2.04	196.0	3113.0	4.03	16.03	0.00
1.00	275.04	5.44	249.0	10350.0	6.50	16.03	0.00

PLAN 1 STATION 4

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
0.15	1320.0	262.2	17.33
0.25	2494.0	266.0	17.00
0.50	3113.0	266.3	16.03
1.00	10351.0	269.6	16.03

PLAN 3 STATION 5

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
0.15	1320.0	295.6	17.50
0.25	2494.0	297.1	17.17
0.50	3077.0	298.1	17.00
1.00	10282.0	261.3	16.03

THE BAR BREACH HYDROGRAPH WAS DEVELOPED USING A TIME INTERVAL OF .056 HOURS DURING BREACH FORMATION. DOWNSTREAM CALCULATIONS WILL USE A TIME INTERVAL OF .167 HOURS. THIS TABLE COMPARES THE HYDROGRAPH FOR DOWNSTREAM CALCULATIONS WITH THE COMPUTED BREACH HYDROGRAPH. INTERMEDIATE PLUMS ARE INTERPOLATED FROM END-OF-PERICO VALUES.

TIME (HOURS)	TIME FROM BEGINNING OF BREACH (HOURS)	INTERPOLATED BREACH HYDROGRAPH (CFS)	COMPUTED BREACH HYDROGRAPH (CFS)	ERROR (CFS)	ACCUMULATED ERROR (CFS)	ACCUMULATED ERROR (AU-FT)
14.333	0.000	1570.	1570.	0.	0.	0.
14.369	.056	1972.	2034.	-62.	-62.	-0.
14.406	.111	2374.	2446.	-70.	-132.	-1.
14.442	.167	2776.	2776.	0.	-132.	-1.
14.479	.222	3088.	3041.	247.	-41.	-1.
14.515	.278	3223.	3223.	0.	-237.	-1.
14.552	.333	3466.	3466.	0.	-237.	-1.
14.588	.389	3610.	3610.	0.	-237.	-1.
14.625	.444	3754.	3809.	-95.	-235.	-1.
14.661	.500	3900.	3900.	0.	-235.	-1.
14.698	.556	4046.	4046.	0.	-235.	-1.
14.734	.611	4192.	4284.	-82.	-235.	-1.
14.771	.667	4338.	4338.	0.	-235.	-1.
14.807	.722	4484.	4484.	0.	-235.	-1.
14.844	.778	4630.	4571.	59.	-235.	-1.
14.880	.833	4776.	4658.	118.	-235.	-1.
14.917	.889	4922.	4731.	251.	-235.	-1.
14.953	.944	5068.	4811.	257.	-235.	-1.
14.990	1.000	5214.	4891.	223.	-235.	-1.
15.026	1.056	5360.	4974.	386.	-235.	-1.
15.063	1.111	5506.	5065.	441.	-235.	-1.
15.099	1.167	5652.	5162.	490.	-235.	-1.
15.136	1.222	5798.	5274.	524.	-235.	-1.
15.172	1.278	5944.	5396.	548.	-235.	-1.
15.209	1.333	6090.	5528.	562.	-235.	-1.
15.245	1.389	6236.	5670.	566.	-235.	-1.
15.282	1.444	6382.	5822.	566.	-235.	-1.
15.318	1.500	6528.	5984.	544.	-235.	-1.
15.355	1.556	6674.	6156.	522.	-235.	-1.
15.391	1.611	6820.	6338.	498.	-235.	-1.
15.428	1.667	6966.	6530.	464.	-235.	-1.
15.464	1.722	7112.	6732.	420.	-235.	-1.
15.501	1.778	7258.	6944.	366.	-235.	-1.
15.537	1.833	7404.	7166.	302.	-235.	-1.
15.574	1.889	7550.	7408.	242.	-235.	-1.
15.610	1.944	7696.	7670.	174.	-235.	-1.
15.647	2.000	7842.	7942.	102.	-235.	-1.
15.683	2.056	7988.	8224.	236.	-235.	-1.
15.720	2.111	8134.	8516.	382.	-235.	-1.
15.756	2.167	8280.	8818.	518.	-235.	-1.
15.793	2.222	8426.	9130.	644.	-235.	-1.
15.829	2.278	8572.	9452.	760.	-235.	-1.
15.866	2.333	8718.	9784.	866.	-235.	-1.
15.902	2.389	8864.	10126.	952.	-235.	-1.
15.939	2.444	9010.	10478.	1018.	-235.	-1.
15.975	2.500	9156.	10840.	1064.	-235.	-1.
16.012	2.556	9302.	11212.	1090.	-235.	-1.
16.048	2.611	9448.	11594.	1096.	-235.	-1.
16.085	2.667	9594.	12086.	1092.	-235.	-1.
16.121	2.722	9740.	12588.	1078.	-235.	-1.
16.158	2.778	9886.	13100.	1054.	-235.	-1.
16.194	2.833	10032.	13622.	990.	-235.	-1.
16.231	2.889	10178.	14154.	976.	-235.	-1.
16.267	2.944	10324.	14706.	932.	-235.	-1.
16.304	3.000	10470.	15278.	808.	-235.	-1.
16.340	3.056	10616.	15870.	654.	-235.	-1.
16.377	3.111	10762.	16482.	470.	-235.	-1.
16.413	3.167	10908.	17114.	256.	-235.	-1.
16.450	3.222	11054.	17766.	102.	-235.	-1.
16.486	3.278	11200.	18438.	-152.	-235.	-1.
16.523	3.333	11346.	19130.	-308.	-235.	-1.
16.559	3.389	11492.	19842.	-454.	-235.	-1.
16.596	3.444	11638.	20574.	-590.	-235.	-1.
16.632	3.500	11784.	21326.	-706.	-235.	-1.
16.669	3.556	11930.	22098.	-802.	-235.	-1.
16.705	3.611	12076.	22890.	-878.	-235.	-1.
16.742	3.667	12222.	23702.	-934.	-235.	-1.
16.778	3.722	12368.	24534.	-966.	-235.	-1.
16.815	3.778	12514.	25386.	-870.	-235.	-1.
16.851	3.833	12660.	26258.	-690.	-235.	-1.
16.888	3.889	12806.	27150.	-426.	-235.	-1.
16.924	3.944	12952.	28062.	-110.	-235.	-1.
16.961	4.000	13098.	29004.	102.	-235.	-1.
17.000	4.056	13244.	29976.	432.	-235.	-1.

HYDROGRAPH ROUTING

ROUTED FLOWS THROUGH SKYLINE 1

ISTAQ	3	ICCHF	1	IECOM	0	ITAPE	0	JPLT	0	JPR1	0	INAME	1	ISTAGE	0	IAUTO	0
ROUTING DATA																	
GLSS	0.0	CLSS	0.00	AVG	1	IPES	1	ISARE	1	IOPT	0	IPHP	0	LSTR	0		
MSTPS																	
	1	MSTBL	0	LAG	0	ANSKK	0	X	0.000	TK	0.000	SFORA	0.00	ISPRAT	0		
CAPACITY	0.	5.	45.	85.	110.	155.	200.										
ELEVATION	287.	268.	265.	268.	270.	275.	288.										
DAM DATA																	
CREL	58.0	COON	3.5	EMPH	1.5	ELEVL	0.0	COOL	0.0	CAREA	0.0	EXPL	0.0				
268.2	58.0	3.5	1.5	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0					
DAM BREACH DATA																	
TOPEL	272.2	COOD	2.0	EMPO	1.5	DAMPID	100.										
272.2	2.0	1.5	100.														
DAM BREACH DATA																	
BRNID	100.	Z	0.00	ELON	259.30	1.00	MSL	268.20	FAILL	272.50							
100.	0.00	259.30	1.00	268.20	272.50												

DOWN

STATION 3, PLAN 1, RATIO 4

BEGIN DAM FAILURE AT 13.07 HOURS

EMP-OF-PERIOD HYDROGRAPH ORDINATES

TIME	0	5	10	15	20	25	30	35	40	45	50	55	60	65	70	75	80	85	90	95	100	
0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
10	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
15	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
20	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
25	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
30	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
35	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
40	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
45	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
50	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
55	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
60	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
65	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
70	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
75	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
80	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
85	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
90	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
95	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
100	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

STORAGE

TIME	0	5	10	15	20	25	30	35	40	45	50	55	60	65	70	75	80	85	90	95	100	
0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
10	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
15	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
20	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
25	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
30	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
35	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
40	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
45	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
50	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
55	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
60	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
65	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
70	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
75	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
80	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
85	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
90	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
95	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
100	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

STAGE

TIME	0	5	10	15	20	25	30	35	40	45	50	55	60	65	70	75	80	85	90	95	100	
0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
10	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
15	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
20	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
25	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
30	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
35	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
40	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
45	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
50	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
55	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
60	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
65	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
70	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
75	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
80	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
85	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
90	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
95	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
100	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

PEAK OUTFLOW IS 18632. AT TIME 16.58 HOURS

6-HOUR	1719.	6259.	1719.	24773.
24-HOUR	1719.	1719.	1719.	1719.
72-HOUR	1719.	1719.	1719.	1719.
TOTAL VOLUME	1719.	1719.	1719.	1719.

THE SAN BRECH HYDROGRAPH WAS DEVELOPED USING A TIME INTERVAL OF .021 HOURS DURING BATCH FORMATION. DOMINEAN CALCULATIONS WILL USE A TIME INTERVAL OF .167 HOURS. THIS TABLE COMPARES THE HYDROGRAPH FOR DOMINEAN CALCULATIONS WITH THE COMPUTED BREACH HYDROGRAPH. INTERMEDIATE PLUMS ARE INTERPOLATED FROM END-OF-PERIOD VALUES.

TIME (HOURS)	TIME FROM BEGINNING OF BREACH (HOURS)	TIME FROM INTERPOLATED BEGINNING OF BREACH (HOURS)	COMPUTED BREACH HYDROGRAPH (GFS)	ERROR (GFS)	ACCUMULATED ERROR (GFS)	ACCUMULATED ERROR (AG-FI)
13.667	0.013	2406.	2406.	0.	0.	0.
13.688	0.21	2603.	2765.	-01.	-01.	-0.
13.708	0.42	2968.	3133.	-158.	-231.	-0.
13.729	0.63	3238.	3633.	-195.	-427.	-1.
13.750	0.83	3515.	3726.	-211.	-636.	-1.
13.771	1.04	3782.	3909.	-197.	-835.	-1.
13.792	1.25	4078.	4223.	-155.	-990.	-2.
13.813	1.46	4347.	4438.	0.	-1076.	-2.
13.833	1.67	4628.	4628.	0.	-1676.	-2.
13.854	1.89	4756.	4756.	0.	-1116.	-2.
13.875	2.10	4807.	4907.	-20.	-1174.	-2.
13.896	2.31	5016.	5081.	-83.	-1237.	-2.
13.917	2.52	5149.	5207.	-58.	-1294.	-2.
13.938	2.71	5281.	5322.	-44.	-1339.	-2.
13.959	2.92	5412.	5438.	-27.	-1393.	-2.
14.000	3.13	5551.	5551.	0.	-1477.	-2.
14.021	3.34	5765.	5765.	0.	-1477.	-2.
14.042	3.55	5927.	5927.	0.	-1477.	-2.
14.063	3.76	6083.	6083.	0.	-1477.	-2.
14.084	3.97	6133.	6133.	0.	-1477.	-2.
14.105	4.18	6231.	6231.	0.	-1477.	-2.
14.126	4.39	6288.	6288.	0.	-1477.	-2.
14.147	4.60	6376.	6376.	0.	-1477.	-2.
14.168	4.81	6407.	6407.	0.	-1477.	-2.
14.189	5.02	6437.	6437.	0.	-1477.	-2.
14.210	5.23	6468.	6468.	0.	-1477.	-2.
14.229	5.42	6499.	6499.	0.	-1477.	-2.
14.250	5.63	6530.	6530.	0.	-1477.	-2.
14.271	5.84	6560.	6560.	0.	-1477.	-2.
14.292	6.05	6591.	6591.	0.	-1477.	-2.
14.313	6.26	6622.	6622.	0.	-1477.	-2.
14.333	6.47	6656.	6656.	0.	-1477.	-2.
14.354	6.67	6690.	6690.	0.	-1477.	-2.
14.375	6.88	6728.	6728.	0.	-1477.	-2.
14.396	7.09	6759.	6759.	0.	-1477.	-2.
14.417	7.30	6792.	6792.	0.	-1477.	-2.
14.438	7.51	6832.	6832.	0.	-1477.	-2.
14.459	7.72	6865.	6865.	0.	-1477.	-2.
14.480	7.93	6895.	6895.	0.	-1477.	-2.
14.501	8.14	6928.	6928.	0.	-1477.	-2.
14.521	8.35	6957.	6957.	0.	-1477.	-2.
14.542	8.56	6997.	6997.	0.	-1477.	-2.
14.563	8.77	7018.	7018.	0.	-1477.	-2.
14.583	8.97	7029.	7029.	0.	-1477.	-2.
14.604	9.18	7041.	7041.	0.	-1477.	-2.
14.625	9.39	7045.	7045.	0.	-1477.	-2.
14.646	9.59	7045.	7045.	0.	-1477.	-2.
14.667	9.80	7065.	7065.	0.	-1477.	-2.

HYDROGRAPH ROUTING
CHANNEL ROUTING --NOOIFIELD PALS-- STATION 4 TO 5

STAG 1 ICOMP 1 ISECON 0 IFRAG 0 JPLT 0 JPRF 0 IMAHE 1 ISTAGE 0 ICAUTO 0
 ROUTING DATA
 LOSS FLOSS AVG 1863 ISEAG 1 IAPT 0 IPRP 0 LSTR 0
 0.0 0.000 0.30 1 C
 MSTPS MSTOL LAG AMSK A TSK STORA ISPPAT
 1 0 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000

NORMAL DEPTH CHANNEL ROUTING

Q(1) Q(2) Q(3) FLWT ELNAX ELNIM SEL
 .6450 .6450 .6450 230.0 280.0 225.0 .0000

CROSS SECTION CHARACTERISTICS--STAGE, ELEV, STA, ELEV--ETC
 C-CC 230.00 100.00 266.00 115.00 253.00 1150.00 250.00 1175.00 250.00
 1175.00 275.00 100.00 260.00 1500.00 280.00

STORAGE	0.00	207.81	267.95	335.67	411.75	498.21	595.03	600.23	700.79	800.80	900.79	1000.79	1100.79	1200.79	1300.79	1400.79	1500.79
STAGE	0.00	1.74	2.04	2.34	2.64	2.94	3.24	3.54	3.84	4.14	4.44	4.74	5.04	5.34	5.64	5.94	6.24
FLOW	0.00	207.81	267.95	335.67	411.75	498.21	595.03	600.23	700.79	800.80	900.79	1000.79	1100.79	1200.79	1300.79	1400.79	1500.79

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS			
				RATIO 1	RATIO 2	RATIO 3	RATIO 4
				.15	.25	.56	1.00
HYDROGRAPH AT	1	2.00 7.25	1	1581.	2635.	5271.	10542.
				44,781	76,637	149,261	298,521
ROUTED TO	2	2.00 7.25	1	1616.	3900.	6376.	10008.
				77,911	112,711	166,177	306,841
ROUTED TO	3	2.00 7.25	1	4570.	5904.	6542.	10413.
				128,591	167,101	185,251	301,001
ROUTED TO	4	2.00 7.25	1	4512.	5450.	6520.	10660.
				127,771	155,071	184,071	301,001
ROUTED TO	5	2.00 7.25	1	4405.	5036.	6400.	10555.
				127,011	149,271	181,401	298,001

BREACH ANALYSIS

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 3	INITIAL VALUE	SPILLWAY GUEST	TOP OF DAM	ELEVATION STORAGE OUTFLOW	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME UP MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.....	288.38	268.38	285.30	288.00	0.00	0.00	0.00	0.00	0.00	0.00
RATIO OF PHF	0.15	0.15	0.15	0.15	0.15	0.15	0.15	0.15	0.15	0.15
	0.25	0.25	0.25	0.25	0.25	0.25	0.25	0.25	0.25	0.25
	0.50	0.50	0.50	0.50	0.50	0.50	0.50	0.50	0.50	0.50
	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 4	INITIAL VALUE	SPILLWAY GUEST	TOP OF DAM	ELEVATION STORAGE OUTFLOW	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME UP MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.....	288.38	268.38	282.28	288.00	0.00	0.00	0.00	0.00	0.00	0.00
RATIO OF PHF	0.15	0.15	0.15	0.15	0.15	0.15	0.15	0.15	0.15	0.15
	0.25	0.25	0.25	0.25	0.25	0.25	0.25	0.25	0.25	0.25
	0.50	0.50	0.50	0.50	0.50	0.50	0.50	0.50	0.50	0.50
	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00

PLAN 1 STATION 4

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
0.15	6512.	269.1	17.58
0.25	5428.	267.4	16.88
0.50	4528.	267.4	16.87
1.00	3668.	270.0	16.58

PLAN 1 STATION 5

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
0.15	6485.	260.7	17.58
0.25	5336.	259.5	16.88
0.50	4485.	259.0	16.88
1.00	3655.	261.6	16.67

SKYLINE LANE DAM #2

Dam Application No. 359
(23-73)

State of New Jersey
State Water Policy Commission
REPORT ON DAM APPLICATION

To the State Water Policy Commission,
State of New Jersey.

Gentlemen:

The application of Realty Acquisition Co., Y.E. Winston, President, 27 W. 14th St., N.Y.
filed June 26, 1965 for approval of plans and for a permit to construct a dam
known as Skyline Lane (Dam #2) near Manaque on Shepherd Brook
tributary to Manaque River in Passaic County New Jersey.

has been examined by George R. Shanklin, Hydraulic ~~Structural~~ Engineer.

PRINCIPAL FEATURES

Location	23.71.2.0.1 <input type="checkbox"/>	Site inscribed	7/27/65 - S.R.S.
Purpose of dam	Real Estate Development	Length of dam	240 feet
Drainage area	2.3 sq. mi.	Elevation of low line	177.0 assumed datum
Area of lake	65 acres	Capacity of lake	137 Mill gals.
Type of dam	Earth fill, steel sheet piling core wall.	Top width	9 feet
Upstream slope	2 to 1	Downstream slope	1 to 1
Foundation material	Sand & gravel with blue clay	Max. height	22.0 feet
Type of spillway	Concrete wall with spillway channel below	Length of spillway	50 feet
Minimum spillway	4.0 feet for 1.0 ft. free-board below top of core wall		
Spillway capacity	755 sec. ft.	135 sec. ft. per sq. mi.	
Estimated maximum flood flow	400	sec. ft. per sq. mi.	135 Central Jersey Curve
Outlets other than spillway	20-inch blowoff pipe to right of spillway		
Drawings filed	July 21, 1965 by Joseph T. Harrison, engineer, Butler, N. J.		

It has been found that the site for the dam is suitable and the plans adequate to ensure the construction of a structure which will not be a menace to life or property. It is therefore recommended that the plans be approved and that a permit be issued, subject, however, to the following conditions:

1. That the dam shall not cause any property or other personal state or material, nor any exclusive privileges, neither as it pertains to any private property nor the violation of private rights, nor any infringement of Federal, State or local laws or regulations, nor shall it require the obtaining of Federal assent, when necessary.

SKYLINE LAKE DAM No. 2
RECEIVED

JUN 29 1965

STATE OF NEW JERSEY
STATE WATER POLICY COMMISSION

28 WEST STATE STREET
TRENTON, NEW JERSEY

STATE WATER POLICY
COMMISSION

DAM APPLICATION No. 399

APPLICATION FOR PERMIT FOR CONSTRUCTION (23-73)
OR REPAIR OF DAM

Location 23.31.2.9.4 Butler, Morris Co., N.J., New Jersey
June 27, 1965..... 19.....

To the New Jersey State Water Policy Commission,
Gentlemen:—

In compliance with the provisions of Title 58, Chapter 4, Revised Statutes
Real Estate Development Co. 22 East 46th St. New York, N.Y. H.K. Finster, Pres.
(Here insert name and address of public authority, private person or corporation which will be the owner of the dam.)
hereby makes application for the approval of drawings and for the issuance of a permit to
construct (a dam) a dam known as Skyline Lake (Dam #2)
(Here insert name of dam.)
across Shephard Brook in Pascale County, New Jersey.
(Here insert name of stream.)
at a point 1 mile upstream from Dam #1
(Here give location by distance from mouth of stream, county or municipal boundary or other natural feature.)
for the purpose of Real Estate Development
(Here state the purpose of the proposed lake.)

in accordance with the following information and with the complete specifications and
drawings filed with this application and made part hereof, as follows:

Area of water shed..... 2.8 square miles.
Maximum depth of lake..... approximately 20 feet
Area of water surface..... 65 acres
Capacity of spillway at 24 feet head, is 675 cubic feet per second.
The character of the foundation material is sand, gravel, clay and boulders.

As determined by Kent Holm

SKYLINE LAKE DAM No. 2

2. That the work shall at all times be subject to supervision and inspection by representatives of the State Water Policy Commission and that no changes in plans and specifications as approved shall be made except with written consent of the Commission. The Commission however, reserves the right to require such changes or modifications in the plans and specifications as may be considered necessary, and further reserves the right to suspend or revoke this permit at any time should such action be deemed advisable in the interest of public safety.

3. That the work shall be under the direction of a competent engineer, and that he or a competent representative shall be on the ground daily during the construction and until the completion of the dam.

4. That the Commission shall be notified in advance of the proposed time of the commencement of this work; that no material shall be placed on any portion of the foundation until such portion of the foundation has been approved in writing by a representative of the Commission.

5. That a report, on forms to be submitted by the Commission, on the status of the construction work shall be mailed to the State Water Policy Commission, 28 West State Street, Trenton, New Jersey, on the first day of each month until the work upon the dam has been completed.

6. That no brush or waste timber cleared from the area under this approval shall be burned unless and until the party doing the work shall have obtained a permit from the Firewarden of the district in which the burning is to be done, in accordance with Title 13:9-19 of the Revised Statutes.

7. That no flashboards or other obstruction shall be placed or permitted to remain on the crest of the spillway.

8. That the work shall be started within one year from date of this permit and completed within two years from said date; otherwise, this permit, if not previously revoked or specifically extended, shall cease and be null and void.

9. This permit shall not become operative unless and until the applicant shall file with the Commission within thirty days from date hereof, upon a form furnished by the Commission, its written acceptance of the terms and conditions hereby imposed.

10. Drawings hereby approved are sheets Nos. 2, 4 and 5, Dam 2, together with title sheet entitled "Plan and Profile for Construction of Dams at Skyline Lake, Borough of Ringwood, Passaic County, July 10, 1945".

No Rule "B" Acknowledgment Issued.


George B. Hensler
Hydraulic ~~Assistant~~ District Engineer.

H. I. C. ...
~~Assistant District~~
Chief Engineer

Trenton New Jersey.

July 21, 1945

D-44



State of New Jersey

State Water Policy Commission

REPORT ON DAM APPLICATION

To the State Water Policy Commission,
State of New Jersey.

Gentlemen:

The application of Realty Acquisition Company, H. K. Winston, President, 22 West
121st Street, New York City
filed June 29, 1945 for approval of plans and for a permit to construct a dam

known as Skyline Lake (Dam #1) near Manaque on Shepard Brook
tributary to Manaque River in Passaic County, New Jersey.

has been examined by George R. Shanklin, Hydraulic ~~Assistant~~ Engineer.

PRINCIPAL FEATURES

Location	23.31.5.3.1	Site inspected	7/27/45 - G.R.S.
Purpose of dam	Real Estate Development	Length of dam	160 feet
Drainage area	2.9 sq. mi.	Elevation of flow line	110.0 assumed datum
Area of Lake	47 1/2 acres	Capacity of lake	15 1/2 Mill. gals.
Type of dam	Earth fill. Steel sheet piling core wall.	Top width	9 feet
Upstream slope	2 to 1	Downstream slope	2 to 1
Foundation material	Sand & gravel with blue clay	Max. height	16.0 feet
Type of spillway	Concrete Cree overflow	Length of spillway	50 feet
Max. head on spillway	3.0 feet for 1.0' free-board below top of dam and core wall		
Spillway capacity	905 sec. ft. = 312	sec. ft. per sq. mi.	
Estimated maximum flood flow	295	sec. ft. per sq. mi. (1.5% Central Jersey Curve)	
Outlets other than spillway	20-inch blowoff pipe to left of spillway		
Drawings filed	July 31, 1945 by Howell C. Harrison, Engineer, Butler, N. J.		

It has been found that the site for the dam is suitable and the plans adequate to ensure the construction of a structure which will not be a menace to life or property. It is therefore recommended that the plans be approved and that a permit be issued, subject, however, to the following terms and conditions:—

1. That this permit does not give any property rights, either in real estate or material, nor any exclusive privileges; neither does it authorize any injury to private property nor invasion of private rights, nor any infringement of Federal, State or local laws or regulations, nor does it waive the obtaining of Federal assent, when necessary.

SKYLENE LAKE DAM No. RECEIVED

JUN 29 1945

STATE OF NEW JERSEY STATE WATER POLICY COMMISSION

28 WEST STATE STREET TRENTON, NEW JERSEY

STATE WATER POLICY COMMISSION

DAM APPLICATION No. 398

APPLICATION FOR PERMIT FOR CONSTRUCTION (23-72) OR REPAIR OF DAM

Butler, Morris Co. New Jersey

Location 23.31.5.3.1

Jan. 27, 1945

To the New Jersey State Water Policy Commission.

Gentlemen:—

In compliance with the provisions of Title 58, Chapter 4, Revised Statutes Realty Acquisition Co. 22 West 28th St. New York, N.Y. H. K. Winston, Pres.

hereby makes application for the approval of drawings and for the issuance of a permit to construct a dam known as Skylene Lake (Dam #1)

across Satchard Brook in Passaic County, New Jersey.

at a point approximately 2000 ft. northerly of boundary line of Ringwood & Passaic Bords. for the purpose of Real Estate Development

in accordance with the following information and with the complete specifications and drawings filed with this application and made part hereof, as follows:

- Area of water shed 2.8 square miles
Maximum depth of lake 12 feet
Area of water surface approximately 38 acres
Capacity of spillway at 21 feet head, is 685 cubic feet per second.
The character of the foundation material is SAND, GRAVEL, CLAY and HARD-PAN.

As determined by test holes

See App 398 for general correspondence & location map prior to filing of application D-47


SKYLINE LAKE DAM
No. 1

398

18-76 9' part 1st
36-76 9' part 2nd
63-76 9' part 3rd
32-76 9' part 4th



SECTION-VALVE WELL
SCALE - 1:50





HEAD WALLS
SCALE - 1:50



TYPICAL SECTION OF DAM FILL SHOWING CORE
SCALE - 1:40


D-49




SKYLINE LAKE DAM NO. 2

JENNY-LEEDSHILL

JANUARY 1979




JENNIFER/LEEDSAPPELL JAN. 1979



TEUBNI/LEICHTHIL JAN 1975

JEFFREY/LEEDS/HTL JAN 1971


STAGE - SPILLWAY #1 OVERTOP DISCHARGE CURVE
SKYLINE LAKE #2



DISCHARGE - CUBIC FEET PER SECOND

ELEVATION - FEET

Copyright © 1971 by Jeffrey/Leeds/HTL




JERRY/LEES/HELL FEB. 1977


CONSTRUCTION OF SKYLENE LAKE #1

PERCENT PMF VS PEAK OUTFLOW DISCHARGE - CFS

Plate D-6



JENNIFER / LEEBENHIL JUN 1971



UNITED STATES GOVERNMENT
Geological Survey