

AD-A069 943


NEW JERSEY STATE DEPT OF ENVIRONMENTAL PROTECTION TRENTON F/6 13/2
NATIONAL DAM SAFETY PROGRAM. LAKE INEZ DAM (NJ-00228); PASSAIC --ETC(U)
MAY 79 R J JENNY

DACW61-78-C-0124

NL

UNCLASSIFIED

1 OF 2
AD
A069943



LEVEL

①

PASSAIC RIVER BASIN
WANAQUE RIVER, PASSAIC COUNTY
NEW JERSEY

A069943

LAKE INEZ DAM
NJ 00228

DDC
JUN 15 1979
C

PHASE 1 INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

THIS DOCUMENT IS BEST QUALITY PRODUCT
YOU MAY REQUEST TO DDC COPY AND A
REPRODUCTION SERVICE OF PASSAIC COUNTY IN NJ
FOR FURTHER RELEASE



Approved for public release;
distribution unlimited

DDC FILE COPY

DEPARTMENT OF THE ARMY
Philadelphia District
Corps of Engineers
Philadelphia, Pennsylvania

May, 1979

70 06 74 028

DISCLAIMER NOTICE

THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DDC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

NOTICE

**THIS DOCUMENT HAS BEEN REPRODUCED
FROM THE BEST COPY FURNISHED US BY
THE SPONSORING AGENCY. ALTHOUGH IT
IS RECOGNIZED THAT CERTAIN PORTIONS
ARE ILLEGIBLE, IT IS BEING RELEASED
IN THE INTEREST OF MAKING AVAILABLE
AS MUCH INFORMATION AS POSSIBLE.**

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NJ00228	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program Lake Inez Dam Passaic County, N.J.	5. TYPE OF REPORT & PERIOD COVERED (9) FINAL rept.	6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(s) (10) Robert J. Jenny P.E.	8. CONTRACT OR GRANT NUMBER(s) (15) DACW61-78-C-0124	9. PERFORMING ORGANIZATION NAME AND ADDRESS Jenny-Leedshill Engineering 318 South Orange Ave. South Orange, N.J. 07079
10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS (12) 126p.	11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, Philadelphia Custom House, 2d & Chestnut Streets Philadelphia, Pennsylvania 19106 (11)	12. REPORT DATE May 79
13. NUMBER OF PAGES 75	14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) (6) National Dam Safety Program, Lake Inez Dam (NJ-00228), Passaic River Basin, Wanaque River, Passaic County, New Jer- sey, Phase I Inspection Report.	15. SECURITY CLASS. (of this report) Unclassified
15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.	
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia, 22151.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dams Visual Inspection Spillway Seepage National Dam Inspection Act Report Lake Inez Dam N.J. Structtural Analysis		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report cites results of a technical investigation as to the dam's ade- quacy. The inspection and evaluation of the dam is as prescribed by the National Dam Inspection Act, Public Law 92-367. The technical investigation includes visual inspection, review of available design and construction records, and preliminary structural and hydraulic and hydrologic calculations, as applicable. An assessment of the dam's general condition is included in the report.		

410 891

JOB



DEPARTMENT OF THE ARMY
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS
CUSTOM HOUSE-2 D & CHESTNUT STREETS
PHILADELPHIA, PENNSYLVANIA 19106

IN REPLY REFER TO

NAPEN-D

Honorable Brendan T. Byrne
Governor of New Jersey
Trenton, NJ 08621

29 MAY 1979

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for Lake Inez Dam in Passaic County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Lake Inez Dam, a high hazard potential structure, is judged to be in poor overall condition. Also, the spillway is considered inadequate since 11 percent of the Probable Maximum Flood (PMF) would overtop the dam. To insure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Any remedial measures necessary to insure the adequacy of the spillway and to prevent overtopping should be initiated within calendar year 1980. In the interim, a detailed emergency operation plan and warning system, should be promptly developed. Also, during periods of unusually heavy precipitation, around-the-clock surveillance should be provided.

b. Within six months from the date of approval of this report, engineering studies and analyses should be performed to determine the dam's embankment and foundation condition and structural stability. This should include test borings to determine material properties relative to stability and seepage. Any remedial measures found necessary should be initiated within calendar year 1980. Make a topographic survey of the

NAPEN-D

Honorable Brendan T. Byrne

dam site and monument the results for use in future inspections.

c. The following remedial actions should be initiated within three months from the date of approval of this report:

(1) The present wooden sluice gate should be replaced by a suitable means of control which can be operated from the dam crest.

(2) The foundation of the mill should be repaired and seepage through the foundation should be sealed off.

(3) The cracks adjacent to the left spillway abutment should be repaired to eliminate the leakage.

(4) Leakage through the penstock and 8-inch diameter pipe could eventually lead to piping through the left end of the dam. Therefore, the intake to these outlets should be properly sealed to stop the leakage.

(5) The notch on the left side of the dam should be filled with concrete to the elevation of the crest of the dam.

(6) The trees adjacent to the sluice gate should be removed and the area restored in order to prevent root damage.

(7) The potential seismicity at the dam site and its effect on the stability of the dam should be investigated.

(8) The dam should be inspected with the reservoir drained down below the spillway.

d. A program of inspections of the dam before and after floods and annually should be initiated by the owners, utilizing the standard visual checklist in this report, so that timely repair actions may be taken as necessary. A permanent record should be kept of all maintenance and operating events of the dam and reservoir.

Accession For	
NTIS GR&I	<input checked="" type="checkbox"/>
DDC TAB	<input type="checkbox"/>
Unannounced Justification	<input type="checkbox"/>
By _____	
Distribution/	
Availability Codes	
Dist	Available/or special
A	23

NAPEN-D


Honorable Brendan T. Byrne

A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressman Robert A. Roe of the Eighth District. Under the provision of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, five days after the date of this letter.

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.

An important aspect of the Dam Safety Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely,



JAMES G. TON
Colonel, Corps of Engineers
District Engineer

1 Incl
As stated

Copies furnished:
Dirk C. Hofman, P.E., Deputy Director
Division of Water Resources
N. J. Dept. of Environmental Protection
P. O. Box CNO29
Trenton, NJ 08625

John O'Dowd, Acting Chief
Bureau of Flood Plain Management
Division of Water Resources
N. J. Dept. of Environmental Protection
P. O. Box CNO29
Trenton, NJ 08625

LAKE INEZ DAM (NJ00228)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 3 and 20 December 1978 by Jenny-Leedshill Engineers under contract to the State of New Jersey. The State, under agreement with the U. S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

Lake Inez Dam, a high hazard potential structure, is judged to be in poor overall condition. Also, the spillway is considered inadequate since 11 percent of the Probable Maximum Flood (PMF) would overtop the dam. To insure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Any remedial measures necessary to insure the adequacy of the spillway and to prevent overtopping should be initiated within calendar year 1980. In the interim, a detailed emergency operation plan and warning system, should be promptly developed. Also, during periods of unusually heavy precipitation, around-the-clock surveillance should be provided.

b. Within six months from the date of approval of this report, engineering studies and analyses should be performed to determine the dam's embankment and foundation condition and structural stability. This should include test borings to determine material properties relative to stability and seepage. Any remedial measures found necessary should be initiated within calendar year 1980. Make a topographic survey of the dam site and monument the results for use in future inspections.

c. The following remedial actions should be initiated within three months from the date of approval of this report:

(1) The present wooden sluice gate should be replaced by a suitable means of control which can be operated from the dam crest.

(2) The foundation of the mill should be repaired and seepage through the foundation should be sealed off.

(3) The cracks adjacent to the left spillway abutment should be repaired to eliminate the leakage.

(4) Leakage through the penstock and 8-inch diameter pipe could eventually lead to piping through the left end of the dam. Therefore, the intake to these outlets should be properly sealed to stop the leakage.

(5) The notch on the left side of the dam should be filled with concrete to the elevation of the crest of the dam.


(6) The trees adjacent to the sluice gate should be removed and the area restored in order to prevent root damage.

(7) The potential seismicity at the dam site and its effect on the stability of the dam should be investigated.

(8) The dam should be inspected with the reservoir drained down below the spillway.

d. A program of inspections of the dam before and after floods and annually should be initiated by the owners, utilizing the standard visual checklist in this report, so that timely repair actions may be taken as necessary. A permanent record should be kept of all maintenance and operating events of the dam and reservoir.

APPROVED:


JAMES G. TON
Colonel, Corps of Engineers
District Engineer

DATE:

29 May 1979

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Lake Inez
Federal I.D. No. NJ 00228
New Jersey I.D. No. 23-89
State Located: New Jersey
County Located: Passaic
Stream: Wanaque River
Date of Inspection: December 3 and 20, 1978

Brief Assessment of General Condition of Dam

The visual inspection indicates that the dam is in generally poor overall condition due to lack of maintenance.

The spillway of Lake Inez Dam is capable of passing approximately 10 percent of the Probable Maximum Flood and is considered inadequate.

The wooden sluice gate is inoperable and leaking badly. The stability of the mill, which forms the right end of the dam, is threatened due to severe erosion of its rubble masonry foundation. There is cracking and leakage at the left abutment of the spillway and water is also leaking through the abandoned penstock and 8-inch diameter pipe. The structural stability of the dam cannot be quantitatively analyzed due to lack of available data.

The following recommendations should be implemented as soon as possible:

- 1) More sophisticated and detailed hydrologic and hydraulic analyses of the spillway capacity should be performed. From this, a positive action program of corrective measures should be developed and implemented as necessary.

2) Additional effort should be made to obtain information regarding the dam, including design and construction data from the owners.

3) A program of measurements and borings and laboratory tests should be conducted soon to determine the properties of the dam and foundation materials, so that seepage and stability analyses can be performed.

4) The dam should be inspected after the reservoir has been drained down below the spillway.

5) A warning system to alert downstream inhabitants in case of dam failure should be implemented.

6) The seismicity at the dam site and its effect on the stability of the dam should be investigated.

The following actions should be performed in the near future, taking advantage of the above:

1) The present wooden sluice gate should be replaced by a suitable means of control which can be operated from the dam crest.

2) The foundation of the mill should be repaired.

3) The cracks adjacent to the left spillway abutment should be repaired.

4) The intake to the penstock and 8-inch diameter pipe should be completely sealed.

5) A program of inspections of the dam before and after floods and annually should be initiated.

6) The notch on the left side of the dam should be filled with concrete to elevation of the crest of the dam.

7) The trees adjacent to the the sluiceway should be removed.


Frank L. Panuzio

Frank L. Panuzio, P.E.
Project Engineer


Robert J. Jenny

Robert J. Jenny, P.E.
Project Director

ii New Jersey License #9878




View



LAKE INEZ DAM

2

View of dam looking upstream.
(Dec. 3, 1978)



3

TABLE OF CONTENTS

	Page
BRIEF ASSESSMENT OF GENERAL CONDITION OF DAM	i
OVERVIEW PHOTOGRAPH OF DAM	
PREFACE	iii
SECTION 1 PROJECT INFORMATION	
1.1 General	1
1.2 Description of Project	1
1.3 Pertinent Data	3
SECTION 2 ENGINEERING DATA	
2.1 Design	6
2.2 Construction	7
2.3 Operation	7
2.4 Evaluation	8
SECTION 3 VISUAL INSPECTION	
3.1 Findings	9
SECTION 4 OPERATIONAL PROCEDURES	
4.1 Procedures	13
4.2 Maintenance of Dam	13
4.3 Maintenance of Operating Facilities	13
4.4 Description of Warning System	13
4.5 Evaluation of Operational Adequacy	13
SECTION 5 HYDRAULIC/HYDROLOGIC	
5.1 Evaluation of Features	15
SECTION 6 STRUCTURAL STABILITY	
6.1 Evaluation of Structural Stability	20

TABLE OF CONTENTS

(Continued)

	Page
SECTION 7 ASSESSMENT, RECOMMENDATIONS, PROPOSED REMEDIAL MEASURES	
7.1 Dam Assessment	22
7.2 Remedial Measures	24

PLATES

1. Regional Vicinity Map
2. Generalized Plan

APPENDICES

APPENDIX A - Check List - Visual Observations
 Check List - Engineering, Construction
 Maintenance Data

APPENDIX B - Photographs

1. Left abutment of dam
2. Left spillway abutment
3. Mill at right abutment of dam
4. Mill foundation
5. Spillway crest
6. Spillway face
7. Spillway face
8. Abandoned penstock
9. Sluice gate
10. Reservoir
11. Downstream channel
12. Downstream channel

APPENDIX C - Regional Geology - Highlands

APPENDIX D - Hydrologic and Hydraulic Computations

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D. C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

LAKE INEZ DAM

Federal I.D. No. NJ 00228
New Jersey I.D. No. 23-89

SECTION 1: PROJECT INFORMATION

1.1 General

a. Authority

The National Dam Inspection Act, Public Law 92-367, 1972, provides for the National Inventory and Inspection Program by the U. S. Army Corps of Engineers. This report has been prepared in accordance with this authority, through contract between the State of New Jersey and Jenny-Leedshill Engineers. The State of New Jersey has also entered into an agreement with the U. S. Army Engineer District, Philadelphia, to have this work performed.

b. Purpose of Inspection

The purpose of this inspection was to evaluate the general structural integrity and hydraulic adequacy of the dam, and to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project

a. Description of Dam and Appurtenance

The dam is an ashler masonry structure, the main part of which is a centrally located spillway 206 feet long and approximately 15 feet high. The spillway crest has a 5-foot wide concrete cap, and a concrete apron extends about 15 feet downstream.

The left side of the dam consists of a concrete capped masonry wall which is approximately 65 feet long and 2.6 feet higher than the spillway crest. A masonry wall, the top of which is at the same elevation as the spillway crest, extends 90 feet downstream from the left abutment of the spillway and retains earthfill through which a penstock passes. The end of the now abandoned 5-foot wide oval penstock extends through a masonry wall as shown on Plate 2.

The section of the dam adjacent to the right spillway abutment consists of a masonry wall which extends approximately 5 feet above the crest of the spillway. The configuration of this section of the dam, which also forms the right spillway training wall, is shown on Plate 2. The right side of the dam is formed by the foundation of a now abandoned mill building.

A 9.4-foot wide sluiceway with a slide gate consisting of wooden 4-inch by 8-inch wooden planks is located to the left of the abandoned mill building.

b. Location

Lake Inez Dam is located in north central New Jersey on the Wanague River in the Borough of Pompton Lakes, Passaic County. The regional vicinity plan is presented on Plate 1.

c. Size Classification

The storage capacity of Lake Inez is 470 acre-feet when the reservoir surface is at the top of dam. The dam is 17.6 feet high; therefore, the size classification of the dam is Small.

The criteria for size classification of dams are set forth in the Corps' Guidelines. A small size dam is one in which the reservoir capacity is greater than or equal to 50 acre-feet and less than 1000 acre-feet, and/or the maximum height is greater than or equal to 25 feet and less than 40 feet.

d. Hazard Classification

The dam is located in the Borough of Pompton Lakes

(population 11,500). A road and railroad bridge and at least 30 structures are located within the flood path downstream of the dam. Failure or misoperation of the dam could result in the loss of more than a few lives and excessive economic loss; therefore, the dam merits a High Hazard classification.

e. Owner

The dam is owned by Artistic Identifications Systems, Inc., Pompton Lakes, New Jersey.

f. Purpose of Dam

The dam was originally built to provide power to the owner's weaving factory adjacent to the dam. It is now used only for recreation.

g. Design and Construction History

There is no available information regarding the design of the dam. Drawings of the dam were reportedly destroyed in a fire.

The dam was reportedly built by Julius Smith, and a plaque on the dam adjacent to the mill building indicates that the dam was built in 1889. Discussions with a local resident indicated that the dam was destroyed by a flood in 1903; however, no information is available to confirm this, and the extent of damage is unknown.

h. Normal Operational Procedures

There is no known regulation of the dam or reservoir. The visual inspection indicates that the reservoir is designed to be emptied via the sluice at the right abutment; however, it appears that the gate is presently inoperable.

1.3 Pertinent Data

a. Drainage Areas (sq. Mi.)	98.1
b. Discharge at Damsite (cfs)	
*Ungated spillway capacity at maximum pool elevation	2,805

c. Elevation (ft. above MSL)	
· Top Dam	198.6
· Spillway crest	196
· Streambed at centerline of dam	181
d. Reservoir Length (ft.)	
· Maximum pool (top of dam)	7300
· Recreation pool (Spillway crest)	7200
e. Storage (acre-feet)	
· Top of dam	470
· Spillway crest	300
f. Reservoir Surface (acres)	
· Top dam	60
· Spillway crest	51
g. Dam	
· Type	Ashlar masonry dam
· Length	345 ft. (approx.)
· Height	17.6 ft.
· Top Width	5 feet
· Side Slopes	Unknown
· Zoning	Unknown
· Impervious Core	Unknown
· Cutoff	Unknown
· Grout curtain	Unknown
h. Spillway	
· Type	Masonry Dam
· Length of weir	205.9 ft.
· Crest elevation	196 ft.
· U/S Channel	Reservoir
· D/S Channel	Concrete apron

i. Regulating Outlets

- a) 5 ft. wide steel oval penstock at left abutment
- b) 9.4 ft. wide sluice with 4 in. x 8 in. wooden plank gate

SECTION 2: ENGINEERING DATA

2.1 Design

a. Geologic Conditions

Lake Inez Dam is located in north-central New Jersey very close to the eastern border of the Highlands physiographic province. The regional geology of the Highlands is discussed in Appendix C to this report.

The dam and its reservoir are situated in a long, narrow gorge which appears to be controlled by the underlying geologic structure. The linear, of which the gorge is a part, can be traced for more than 10 miles. A fault approximately one-quarter mile east of the left abutment is shown on New Jersey Geology Department maps, but no fault is shown in the valley bottom. However, a fault has been inferred by others upstream of the dam.

Bedrock is exposed on the left abutment of the dam. The rock appears to be primarily a pink tinted, white and black gneiss with distinct gneissic banding and a high percentage of quartz. A hard, finely crystalline, dark mafic rock is exposed within the gneissic mass which may be a dike, but vegetation and thin soil cover make the surficial tracing of the dike impractical. The bedrock extends all the way to the toe of the left abutment and it would appear that this abutment was constructed directly on the rock.

No bedrock exposures were observed under the dam or on the right abutment which has been completely altered by the construction of roadways and a large factory. Behind the factory, approximately 300 yards from the

abutment, bedrock is exposed, similar to that seen on the left abutment. There are no indications of whether the major part of the dam is built on bedrock or overburden.

Soil in the area appears to be primarily glacial till with recent alluvium in the bottom of the stream and in the flood plain.

The dam is located less than one-half mile from the long, continuous Ramapo Fault which divides the New Jersey Highlands from the Piedmont Lowlands. Several small earthquakes have occurred recently along this fault and it is currently under study as an "active" fault by Columbia University's Lamont-Doherty Geophysical Laboratory.

b. Design Data

There are no available data regarding the design of the dam. Drawings of the dam were reportedly destroyed in a fire.

2.2 Construction

The dam was reportedly built by Julius Smith and a plaque on the dam adjacent to the mill building indicates that the dam was built in 1889. Discussions with a local resident indicate that the dam was destroyed by a flood in 1903; however, no information is available to confirm this and the extent of damage is unknown.

A raceway through the base of the mill at the right abutment has been sealed with concrete blocks. The penstock at the left abutment has been abandoned and the power plant removed.

2.3 Operations

There is no known regulation of the dam or reservoir.

The visual inspection indicates that the reservoir is designed to be emptied via a sluiceway adjacent to the mill; however, the gate lift mechanism is presently broken.

2.4 Evaluation

a. Availability

No data regarding the design, construction or operation of the dam were made available by the owners of the dam. Available data consist of an inspection report prepared by the State in 1960 and "Dams in New Jersey - Reference Data" dated September 14, 1965. These data are included in Appendix D.

b. Adequacy

The structural stability of the dam cannot be evaluated due to the complete absence of any design and construction data.

c. Validity

The observations made during the 1960 inspection were generally confirmed by the present inspection.

Limited information regarding the history of the dam were obtained from a local resident; however, this information could not be substantiated.

SECTION 3: VISUAL INSPECTION

3.1 Findings

a. General

Visual inspections of Lake Inez Dam were made on December 3 and 20, 1978. The level of the reservoir was approximately 2 inches above the crest of the spillway during the December 3, 1978 inspection.

Visual inspection indicates that the dam is in need of remedial work to assure continued structural integrity. The wooden sluice gate is inoperable and leaking badly. The stability of the mill, which forms the right side of the dam, is threatened due to severe erosion of its rubble masonry foundation.

Detailed inspection was made of the dam, appurtenant structures, reservoir and downstream channel. Descriptions of the findings of those inspections are summarized in the paragraphs which follow. The check list of visual inspection items is included in Appendix A. Geologic and foundation conditions observed at the time of inspection are noted in greater detail in Section 2.

b. Dam

The dam was inspected for signs of settlement, seepage, erosion, cracking and any other evidence of undesirable behavior which might affect the stability of the structure.

The wall forming the left side of the dam bends upstream but it appears that this alignment has existed for some time and no signs of recent movement were detected.

The left side of the dam is founded on rock and a deposit of soil has formed a beach on the upstream side at the left abutment. (Photo 1)

Severe cracking and separation between the concrete cap and masonry were observed at the junction of the left side of the spillway and the dam (Photo 2). Water from the reservoir is leaking through these cracks at an estimated rate of 5 gpm, forming a pond 6 to 12 inches deep. (Plate 2). There is a notch in the left side of the dam approximately 2 feet deep and 6 feet long which may have been associated with the penstock which appears to pass beneath the dam at this location.

Some minor seepage was noted through the masonry retaining wall which extends downstream from the left spillway abutment but it otherwise appears to be in good condition.

The section of the dam to the right of the spillway appears to be in generally good condition with the exception of some small trees that are growing next to, and in some places in, the masonry structure.

At the right abutment, the foundation of a mill building acts as part of the dam (Photo 3). A raceway which originally passed through the mill has been sealed with concrete bricks. The rubble masonry foundation of this building on the downstream side has been severely eroded (Photo 4). The erosion is most severe on the east side adjacent to the sluiceway and particularly at the downstream corner of the building. A minor amount of seepage through the foundation of this building was also observed.

c. Appurtenant Structures

Spillway

The spillway occupies the central section of the dam and turns at an angle approximately 30 feet from the right abutment. (Photo 6)

The ashlar masonry spillway structure has a concrete cap approximately 5 feet wide. This cap is generally set upstream of the masonry face except along a section approximately 25 feet long adjacent to the left abutment. This offset in the position of the spillway crest is shown in Photo 6 and is made most obvious by the different characteristics of flow over the spillway. Water flowing over the spillway obscured this structure so that the offset in the spillway crest and the face of the spillway could not be closely observed.

A concrete apron extends 10 to 15 feet downstream from the dam. (Photos 5 through 7) The foundation of the spillway and apron were submerged and therefore could not be observed.

Five loose stones, similar to those that comprise the downstream face of the spillway structure, are lying on the spillway apron (Photo 7). However, due to the flow of water over the spillway, it could not be determined if these stones were dislodged from the spillway.

Outlet Works

An abandoned 5-foot wide steel, oval penstock and an 8-inch diameter steel pipe were observed on the downstream side of the left abutment of the dam (Plate 2 and Photo 8). Water was leaking through both these outlets at a rate of about 10 gpm. There is presently no indication of a power plant or other similar structure in the vicinity

of the penstock.

A 9.4-foot wide sluice gate consisting of 4-inch by 8-inch boards is located to the left of the mill at the right side of the dam. The gate controls are inoperable and there is serious leakage between the boards (Photo 9). A small tree growing in the masonry wall adjacent to the sluice is shown in Photo 9. The discharge from the sluice flows adjacent to the old mill and joins the main channel downstream as shown in Plate 2.

A raceway through the mill has been sealed off as discussed above.

d. Reservoir Area

The reservoir is relatively narrow, and trends north-south. The slopes are generally gentle to moderately steep, and heavily wooded. The owner's factory buildings occupy the right bank immediately upstream from the dam (Photo 10).

There was a minor amount of debris in the reservoir and at the spillway crest. There was no indication that sedimentation is excessive.

d. Downstream Channel

The slopes of the channel directly downstream from the dam are moderately steep and covered with grass and some trees (Photo 11).

A steel road bridge in the Borough of Pompton Lakes is located approximately 500 feet downstream from the dam (Photos 11 and 12).

SECTION 4: OPERATIONAL PROCEDURES

4.1 Procedures

There is no known regulation of the reservoir, since all outlets either have been abandoned or are inoperable. The former raceway through the mill has been sealed off and the penstock at the left abutment has been abandoned. Controls for the timber sluice gate adjacent to the mill are broken and inoperable.

4.2 Maintenance of Dam

There are no records available regarding maintenance of the dam, and, based on the visual inspection, little, if any, maintenance work has been done in recent years. There are no instrumentation or monitoring systems on the dam or reservoir.

4.3 Maintenance of Operating Facilities

No maintenance records of operating facilities are available. The timber sluice gate is leaking and the controls are broken.

4.4 Description of Warning Systems

There is no warning system or emergency contingency plan in event of flooding or possible failure of the dam.

4.5 Evaluation of Operational Adequacy

The present operation and maintenance of the dam is deficient. It appears that there has been little maintenance

of the dam. The disrepair of the sluice gate is a serious operational deficiency since this gate is now the only reservoir outlet.

A warning system is needed to alert downstream inhabitants in time of floods and possible overtopping or failure of the dam.

SECTION 5: HYDRAULIC/HYDROLOGIC

5.1 Evaluation of Features

a. Design Data

As already stated, in Section 1.2, Lake Inez Dam is classified as high hazard and small in size. In accordance with the Corps of Engineers', "Recommended Guidelines for Safety Inspection of Dams," the Spillway Design Flood (SDF) should be 50% to 100% of the Probable Maximum Flood (PMF). The 100% PMF was selected as the SDF because of the high hazard to loss of life immediately downstream of the dam.

Data obtained from the Corps indicates the drainage basin area of Lake Inez Dam is 98.1 square miles. This drainage basin was divided into three sub-basins: one above Skyline Dam No. 1 having a drainage area of 2.9 square miles; another above Raymond Dam, which impounds Wanaque Reservoir, having a drainage area of 90.4 square miles; and the third sub-basin between Wanaque Reservoir, Skyline Lake No. 1 and Lake Inez having a drainage area of 4.8 square miles. The drainage sub-basins are delineated on a U.S.G.S. topographic map and presented on Plate D-1, Appendix D.

The hydraulic and hydrologic features of Lake Inez Dam were evaluated using criteria set forth in the Corps of Engineers' "Recommended Guidelines for Safety Inspection of Dams", and additional guidance and criteria provided by the Philadelphia District, Corps of Engineers. The PMF outflow hydrograph from the Wanaque Reservoir sub-basin was supplied by the Corps and used in the analyses. The PMF outflow hydrograph from Skyline Lake No. 1 was

previously calculated by Jenny-Leedshill and, as requested by the Corps, was used in this analysis. The Probable Maximum Precipitation (PMP) for the sub-basin between Wanaque Reservoir, Skyline Lake No. 1 and Lake Inez was calculated using Hydrometeorological Report No. 33 and the Hop Brook reduction factor for misalignment for the storm. The PMF for this sub-basin was calculated using the Corps' computer program HEC-1, Dam Break Version (HEC-1,DB). The Corps requested that the Snyder Unit Hydrograph with C_t and C_p coefficients of 2.0 hours and 0.63 hours, respectively, be used to calculate the PMF.

In computing the PMF for the sub-basin between Wanaque Lake, Skyline Lake No. 1 and Lake Inez, an initial infiltration loss of 0.5 inch and a final infiltration loss rate of 0.05 inch per hour were used in the HEC-1,DB program to give excess rainfall. Using the excess rainfall and the unit hydrograph, the program computed the peak inflow discharges from the sub-basin of the 10 percent, 25 percent, 50 percent and 100 percent PMF. These discharges are approximately, 1,210 cfs, 3,040 cfs, 6,070 cfs and 12,140 cfs, respectively.

As previously stated, the PMF outflow hydrograph from Wanaque Reservoir was supplied by the Corps. The PMF peak outflow from Wanaque Reservoir is 23,300 cfs. The PMF outflow hydrograph from Skyline Lake No. 1, as previously calculated by Jenny-Leedshill, is 10,600 cfs. This peak outflow was calculated assuming both Skyline Lake Dam No. 1 and the upstream Skyline Lake Dam No. 2 breach due to overtopping. The PMF outflow hydrographs from Wanaque Reservoir and Skyline Lake No. 1 were multiplied by 0.1, 0.25, and 0.5 to provide estimates of the 10 percent, 25 percent and 50 percent PMF.

The various percentages of the PMF hydrograph from Skyline Lake No. 1 were routed downstream through three successive reaches to the Wanaque River. These floods were then combined with the corresponding percentage PMF outflows from Wanaque Reservoir. The combined hydrographs were then routed downstream to Lake Inez and combined with the runoff from the intermediate basin. The peak inflow discharges into Lake Inez for the 10 percent, 25 percent, 50 percent, and 100 percent PMF were calculated to be approximately 2,930 cfs, 7,420 cfs, 15,000 cfs and 30,000 cfs, respectively.

The various percentages of the PMF inflow hydrograph were routed through Lake Inez using the Modified Puls Method by the HEC-1,DB program. The peak outflow discharges of the 10 percent, 25 percent, 50 percent and 100 percent PMF were calculated to be approximately 2,880 cfs, 7,280 cfs, 14,510 cfs and 28,710 cfs, respectively. The flood routings indicate that all floods greater than about 10 percent of the PMF will overtop the dam. A plot of percent PMF versus peak outflow discharge is presented as Plate D-2 in Appendix D.

The spillway and overtop stage-discharge rating curve used in the flood routings through Lake Inez was calculated using the weir equation. Tailwater effects, caused by a constriction in the downstream channel, were considered in developing the rating curve. The spillway and dam crest is a 5-foot wide weir with an estimated discharge coefficient of 3.1. The reservoir stage-storage curve was determined from U.S.G.S. 7.5 - minute topographic maps and data obtained from State files. This stage-storage curve was extended above the dam crest to include surcharge storage

during peak flood discharges. In the reservoir routing computations possible discharges through the outlet works were excluded because their capacity is small compared to the PMF and because of the possibility that they may be closed or inoperable. The stage-storage and the spillway and overtop stage-discharge curves are presented in Appendix D as Plates D-3 and D-4, respectively.

The various percentage PMF outflow hydrographs from Lake Inez were routed 0.5 miles downstream through two successive reaches through the Borough of Pompton Lakes. These routings were made to determine downstream flooding characteristics. These characteristics are presented in the following tabulation. The hydraulic parameters used in the HEC-1,DB program for the downstream routing calculations were estimated based on observations made in the field and information obtained from U.S.G.S. topographic maps.

FLOODING CHARACTERISTICS AT THE BOROUGH OF POMPTON LAKES

	<u>10% PMF</u>	<u>25% PMF</u>	<u>50% PMF</u>	<u>100% PMF</u>
Peak Discharge, cfs.	2,890	7,270	14,510	28,770
Maximum Stage, ft.	190.6	195.2	199.5	204.3

In the Borough of Pompton Lakes there appears to be at least 30 structures below elevation 200 feet. During large floods several of these structures could sustain severe damage and loss of life could result.

There were three outlet structures at Lake Inez. Two of the outlets have been abandoned. The third outlet is a small sluiceway with a timber gate. The gate is in very poor condition but could be removed if lake drawdown were required. A rating curve for the sluiceway, assuming the gate is removed, was estimated using the weir equation.

Using this rating curve and assuming no inflow into the lake and no tailwater effects, the time required to drain the reservoir from a spillway full condition was calculated to be about 13 hours.

b. Experience Data

Records of lake levels are not maintained for this site. The dam which originally was built to supply water and power to an old adjacent mill, is now used for recreational purposes.

c. Visual Observations

There is a well defined channel downstream of the dam. There are structures on both banks. There is a bridge approximately 500 feet downstream of the dam. The banks downstream are tree lined with little undergrowth. The overbank slopes are gentle, and include open areas, wooded areas, and residential and commercial areas.

d. Overtopping Potential

As indicated in Section 5.1-a, the Lake Inez Dam spillway can pass only 10 percent of the PMF. During the PMF the dam would be overtopped 11.8 feet.

During large floods the water surface elevation downstream of the spillway is only slightly less than the upstream elevation because of a constriction in the downstream channel. The tailwater effect limits the flood's capacity to erode a breach in the embankment and limits the static forces on the masonry portion of the dam. There is some question as to whether these forces would be adequate to cause a dam breach. In addition, the channel constriction limits the downstream discharge such that a dam breach would increase the downstream discharge only a small amount. Thus, the spillway for Lake Inez Dam should be classified as inadequate.

SECTION 6: STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations

Visual inspection indicates that the dam is in need of remedial work to assure continued structural integrity. The wooden sluice gate is inoperable and leaking badly. The stability of the mill, which forms the right side of the dam, is threatened due to severe erosion of its rubble masonry foundation, although the upstream face of the foundation is newer and in better condition. Some cracking and leakage was observed at the left abutment of the spillway and water is also leaking through the abandoned penstock and 8-inch diameter pipe.

Water flowing over the spillway obscured inspection of this structure. Several large masonry stones are lying on the concrete apron; however, it could not be determined if these stones have been dislodged from the spillway. In addition, the condition of the spillway foundation could not be inspected.

b. Design and Construction Data

There are no available data regarding the design and construction of the dam or outlet works; therefore, the structural stability of the dam cannot be evaluated. Nothing is known of the core of the dam, the foundation, or the cross sectional configuration.

c. Operating Records

The reservoir is uncontrolled and there is no

instrumentation of the dam. Records of reservoir levels and water withdrawals are not available. A brief inspection report was made by the State in 1960 and is included in Appendix D, page D-41.

d. Post-Construction Changes

The original dam was reportedly destroyed by a flood in 1903; however, there is no documentation to confirm this nor descriptions of re-construction.

A raceway through the foundation of the mill building has been sealed off with concrete blocks. The penstock at the left abutment has been abandoned and the power generating equipment removed.

e. Seismic Stability

The dam is located in Seismic Zone 1, in which it may generally be assumed that there is no hazard from earthquakes, provided static stability conditions are satisfactory and conventional safety margins exist. However, as pointed out in Section 2.1-a, the dam is located less than one-half mile from the seismically active Ramapo Fault. In addition, the reservoir is situated in what is thought to be a structurally controlled valley and a fault has been inferred by others upstream from the reservoir. Data are insufficient at this time to assess seismic stability, should a significant earthquake occur in the vicinity of the dam.

SECTION 7: ASSESSMENT, RECOMMENDATIONS,
PROPOSED REMEDIAL MEASURES

7.1 Dam Assessment

a. Safety

The spillway of Lake Inez Dam can pass only about 10% of the probable Maximum Flood and is considered inadequate.

The structural stability of the dam cannot be quantitatively analyzed due to lack of available data. The visual inspection indicates that the dam is in generally poor condition and has not been well maintained. The wooden sluice gate is leaking badly and the lift mechanism is broken. The foundation of the mill building at the right side of the dam is badly deteriorated, except on the upstream side, and its failure could cause failure of the upstream side which acts as part of the dam. There is some leakage at the left abutment of the spillway, and water is also leaking through the abandoned penstock and 8-inch diameter pipe.

b. Adequacy of Information

The information and data obtained are not adequate to perform a comprehensive evaluation of the dam's structural stability because of an absence of data regarding the design and construction of the dam and as-built conditions.

c. Urgency

The visual inspection revealed deficiencies which

are detrimental to the integrity of the structure. Therefore, it is recommended that the owners perform the remedial measures discussed below as soon as possible. The most urgent items are the repair of the sluice gate and foundation of the mill.

d. Necessity for Additional Data/Evaluation

The main section of the dam was obscured by water overflow and could not be closely observed. Therefore, the dam should be inspected with the reservoir level far below the spillway crest.

The Corps of Engineers Guidelines require that, in general, seepage and stability analyses should be on record for all dams in the high hazard category. At the present time there are inadequate data to perform these analyses. Since none exist, every effort should be made as soon as possible to obtain data regarding the dam including design and construction information, from the owners. At the same time, because so little is known about the as-built condition of the dam and appurtenant structures, and because of the high hazard downstream, a timely program of measurements and borings and laboratory tests of the dam and foundation should be undertaken soon so that seepage and stability analyses can be performed and the safety of the dam evaluated.

The hydrologic analysis indicates that the spillway is inadequate. Therefore, more sophisticated and detailed hydrologic and hydraulic analyses of the spillway capacity should be performed as soon as possible. From this, a positive action program of corrective measures should be developed and implemented as necessary.

Although the dam is located in Seismic Zone 1, it is situated in a valley which was possibly formed as the result of faulting and is in close proximity to the seismically active Ramapo Fault. Therefore, the potential seismicity at the dam site and its effect on the stability of the dam should be investigated.

7.2 Remedial Measures

a. Repair Procedures

It is recommended that the following remedial measures be performed as soon as possible.

- 1) The present wooden sluice gate should be replaced by a suitable means of control which can be operated from the dam crest.
- 2) The foundation of the mill should be repaired and seepage through the foundation should be sealed off.
- 3) The cracks adjacent to the left spillway abutment should be repaired to eliminate the leakage.
- 4) Leakage through the penstock and 8-inch diameter pipe could eventually lead to piping through the left end of the dam. Therefore, the intake to these outlets should be properly sealed to stop the leakage.
- 5) The notch on the left side of the dam should be filled with concrete to the elevation of the crest of the dam.


b. Operation and Maintenance Procedures

A program of inspections of the dam before and after floods and annually should be initiated by the owners, utilizing the standard visual checklist in this report, so that timely repair actions may be taken as necessary.

A permanent record should be kept of all maintenance and operating events of the dam and reservoir.

The trees adjacent to the sluice gate should be removed soon and the area restored in order to prevent root damage.

A warning system should be established whereby downstream inhabitants can be notified and evacuated in the event of possible dam failure.



VICINITY MAP


JENNY-LEEDSHILL

FEBRUARY 1979

LAKE INEZ DAM

GENERALIZED PLAN BASED ON VISUAL INSPECTION, DECEMBER 3, 1978

JENNY - LEEDSHILL JANUARY 1979



Not to scale

APPENDIX A

CHECK LIST - VISUAL OBSERVATIONS

CHECK LIST - ENGINEERING, CONSTRUCTION
MAINTENANCE DATA

Check List
Visual Inspection
Phase 1

Name Dam Lake Inez County Passaic State New Jersey Coordinators NJDEP
Date(s) Inspection Dec. 3 & 20, 1978 Weather Overcast Temperature 36°
Coordinates: Lat. 41° 00' 30"
Long. 74° 17' 30"

Pool Elevation at Time of Inspection 196 M.S.L. Tailwater at Time of Inspection 182 M.S.L.
(approx.) (approx.)

Inspection Personnel:

(Dec. 3, 1978)

R. C. Gaffin

A. R. Slaughter

P. L. Wagner

(Dec. 20, 1978)

R. J. Jenny

D. J. Lachel

F. L. Panuzio

A. R. Slaughter

Robert C. Gaffin Recorder

CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SEEPAGE OR LEAKAGE	<p>-Water was leaking through the left abutment of the spillway at a rate of about 5 gpm</p> <p>-The face of the dam could not be inspected for seepage or leakage due to water passing over the dam.</p>	<p>-Minor seepage through foundation of mill building at right abutment and left wing walls.</p> <p>Left abutment of spillway should be sealed to prevent leaking.</p>
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS	<p>-Left abutment is founded on rock</p> <p>-Old mill building at right abutment. Previous raceway through mill has been walled off with concrete blocks.</p>	
DRAINS A-2	<p>None observed</p>	
WATER PASSAGES	<p>-See 'Outlet Works'</p>	
FOUNDATION	<p>-Rock outcropping at left abutment</p> <p>-Rubble masonry foundation at mill building was significantly eroded</p>	<p>Foundation of abandoned mill at right abutment should be repaired</p>

CONCRETE/MASONRY DAMS

Lake Inez Dam

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
<p>SURFACE CRACKS CONCRETE SURFACES</p>	<p>- Several surface cracks noted in concrete cap of masonry walls at left and right abutments - Some mortar is missing from masonry wall adjacent to sluiceway at right abutment</p>	
<p>STRUCTURAL CRACKING</p>	<p>- Concrete on left wall adjacent to spillway is in poor condition and separating from masonry.</p>	
<p>VERTICAL AND HORIZONTAL ALIGNMENT P-3</p>	<p>a) Wall at left abutment bowed upstream b) Crest of overflow section is set back from masonry face of dam except + 25 ft. section at left where the cap extends further D/S than masonry face</p>	
<p>MONOLITH JOINTS</p>	<p>None observed</p>	
<p>CONSTRUCTION JOINTS</p>	<p>None observed</p>	

EMBANKMENT
(None)

Lake Inez Dam

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	Not applicable	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	Not applicable	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	Not applicable	
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Not applicable	
RIPRAP FAILURES	Not applicable	

EMBANGEMENT
(None)

Lake Inez Dam

<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
VEGETATION	Not applicable	
JUNCTION OF EMBANGEMENT AND ABUTMENT, SPILLWAY AND DAM	Not applicable	
ANY NOTICEABLE SEEPAGE	Not applicable	
STAFF GAGE AND RECORDER	Not applicable	
DRAINS	Not applicable	

OUTLET WORKS

Lake Inez Dam

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	Not applicable	
INTAKE STRUCTURE A-6	Intake to the raceway through base of abandoned mill has been sealed with concrete blocks	
OUTLET STRUCTURE	<p>a) Mechanically operated wooden sluice gate 9.4' wide located to the left of the mill building. Water is leaking between 4" x 8" wooden boards. Small tree is growing from masonry wall to the left of gate.</p> <p>b) Abandoned 5 ft. wide steel oval penstock and 8 in. diameter steel pipe at downstream end of left wing wall, leaking at a rate of approx. 10 gpm.</p>	<p>a) Sluice gate should be replaced and tree should be removed</p> <p>b) Intake to penstock and 8" pipe should be sealed</p>
OUTLET CHANNEL	Unlined channel downstream of sluice gate passes along the foundation of the abandoned mill and enters the main downstream channel. Water was about 1 ft. deep during inspection. Boulder blocking channel 15 ft.	D/S from gate
EMERGENCY GATE	See above	

UNGATED SPILLWAY

Lake Inez Dam

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	<ul style="list-style-type: none"> - Concrete cap approximately 5 ft. wide. Cap is generally upstream of masonry face of dam except the + 25 ft. at left where the crest extends further D/S than face. - Few eroded notches in crest 	
APPROACH CHANNEL	Reservoir	
DISCHARGE CHANNEL	<ul style="list-style-type: none"> - Concrete apron extends 10' to 15' downstream - 5 large masonry stones, similar to those in dam, are on apron - Minor debris at base of spillway 	Stones on spillway apron may have been dislodged from dam.
BRIDGE AND PIERS	None	

GATED SPILLWAY
(None)

Lake Inez Dam

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE SILL	Not applicable	
APPROACH CHANNEL	Not applicable	
DISCHARGE CHANNEL	Not applicable	
BRIDGE AND PIERS	Not applicable	
GATES AND OPERATION EQUIPMENT	Not applicable	

A

**INSTRUMENTATION
(None)**

Lake Inez Dam

VISUAL EXAMINATION MONUMENTATION/SURVEYS	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
OBSERVATION WELLS	None	
WEIRS	None	
PIEZOMETERS	None	
OTHER	None	

RESERVOIR

Lake Inez Dam

<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
<u>SLOPES</u>	Slopes are generally gentle to moderately steep and wooded. Industrial development on right bank.	
<u>SEDIMENTATION</u>	Sedimentation does not appear to be excessive. Minor debris at spillway crest.	

DOWNSTREAM CHANNEL

Lake Inez Dam

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
<p>CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)</p>	<p>Steel road bridge approximately 500 ft. D/S and Borough of Pompton Lakes. Rail-road bridge about 1,000 ft. D/S from road bridge Minor debris</p>	
<p>SLOPES</p>	<p>Moderately steep slopes with grass and moderate growth of trees</p>	
<p>APPROXIMATE NO. OF HOMES AND POPULATION</p>	<p>Numerous homes, businesses and roads in Pompton Lakes at elevations below the crest of the dam.</p>	

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION

ITEM	REMARKS
PLAN OF DAM	None
REGIONAL VICINITY MAP	Dam and reservoir are shown on U.S.G.S. Wanaque Quadrangle, scale 1:24,000
CONSTRUCTION HISTORY A-12	Plaque on dam gives construction date of 1889.
TYPICAL SECTIONS OF DAM	None
HYDROLOGIC/HYDRAULIC DATA	None
OUTLETS - PLAN	None
- DETAILS -CONSTRAINTS -DISCHARGE RATINGS	None None None None
RAINFALL/RESERVOIR RECORDS	None

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION

Lake Inez Dam

ITEM	REMARKS
DESIGN REPORTS	None
GEOLOGY REPORTS	None
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	None
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	None
POST-CONSTRUCTION SURVEYS OF DAM	None
BORROW SOURCES	Unknown

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION

Lake Inez Dam

ITEM	REMARKS
SPILLWAY - PLAN - SECTIONS - DETAILS	None None None
OPERATING EQUIPMENT PLANS & DETAILS	None
MONITORING SYSTEMS P 114	None
MODIFICATIONS	Raceway through mill at right abutment has been sealed off and penstock at left abutment has been abandoned.
HIGH POOL RECORDS	None
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	a) "Report on Dam Inspection", by Michael J. Galley, June 2, 1960 b) "Dams in New Jersey - Reference Data," dated Sept. 14, 1965
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	Verbal report indicates dam was destroyed by flooding in 1903.

APPENDIX B
PHOTOGRAPHS

(Note: All photographs were taken on Dec. 3, 1978)



Photo 1
View of left abutment of dam looking west



Photo 2
View of left spillway abutment looking west



Photo 3
View of mill at right
abutment of dam looking east



Photo 4
View of mill foundation
looking west with sluiceway in foreground



Photo 5
View along spillway crest
looking towards left abutment



Photo 6
View of spillway face
looking west from left abutment



Photo 7
View of spillway face
showing loose stones on apron



Photo 8
View of abandoned penstock and
8 inch diameter pipe looking upstream



Photo 9
View of sluice gate
looking upstream




Photo 10
View of reservoir looking upstream from dam




Photo 11
View of road bridge and
Borough of Pompton Lakes downstream from dam




Photo 12
View of dam looking
upstream from bridge shown in Photo 11

APPENDIX C

REGIONAL GEOLOGY - HIGHLANDS PROVINCE

REGIONAL GEOLOGY - HIGHLANDS PROVINCE

Physiography

The New Jersey Highlands extend northeast-southwest across the state from the New York border to the Delaware River. Included in the province are the northwest portions of Hunterdon, Passaic and Morris Counties and the southeastern portions of Warren and Sussex Counties. This province lies between the Appalachian Ridge and Valley Province to the northwest and the Piedmont Lowlands Province to the southeast (See Figure C-1) and is part of the larger New England Physiographic Province.

The Highlands are characterized by rounded and flat-topped northeast-southwest ridges and mountains up to 1,400 feet high separated by narrow valleys. The orientation of the valleys is usually, but not always, controlled by the underlying geologic structure.

Bedrock


Bedrock of the region is predominantly Precambrian gneisses, schists and metasediments. Some sedimentary rocks, typically sandstones, shales and conglomerate have been infolded and infaulted into the valley bottoms.

The regional geologic structure reflects the very old age of bedrock. A number of regional faults cross the area in a northeast-southwest direction. The Ramapo Fault scarp, forming the eastern border of the province, is more than 30 miles long. Faults also control many of the river valley orientations.

Mountain crests slope uniformly from northwest to southwest, a direct result of the fact that the entire area was once part of the now dissected Schooley peneplain.

Overburden

Much of the province was covered by the Pleistocene age Wisconsin glacier. The glacier stripped most of the existing overburden and weathered rock and uncovered the numerous hard bedrock knobs and ridges seen throughout the province. Most of the side-slopes in the area are covered with heavy boulder tills (ground moraine), while glacial outwash and recent alluvium cover the valleys. South of the terminal moraine extending from Morristown to Belvidere, scattered remnants of earlier stages of glaciation (Illinoian and Kansan) have deposited ground moraine (glacial tills) over the bedrock. In the valleys and over some of the ground moraine, recent and glacio-fluvial alluviums have been deposited.



SCHEMATIC CROSS-SECTION OF
 NEW JERSEY HIGHLANDS
 PHYSIOGRAPHIC PROVINCE
 (AFTER WOLFE, 1977)

JENNY/LEEDSHILL
 JANUARY 1979

FIGURE C-1

APPENDIX D

HYDROLOGIC AND HYDRAULIC COMPUTATIONS

LAKE INEZ

CHECK LIST
HYDROLOGIC AND HYDRAULIC DATA
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: 98.1 SQ. MILES

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 196 FT (300 AF)

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): 198.5 (460 AF)

ELEVATION MAXIMUM DESIGN POOL: _____

ELEVATION TOP DAM: 198.5 FT

CREST: SPILLWAY

- a. Elevation 196.0
- b. Type MASONRY OUTFLOW
- c. Width 5'
- d. Length 206 FT
- e. Location Spillover CENTER OF DAM
- f. Number and Type of Gates NONE

OUTLET WORKS: INDISCERNIBLE

- a. Type TEMBER SLUICE WF
- b. Location _____
- c. Entrance inverts _____
- d. Exit inverts _____
- e. Emergency draindown facilities _____

HYDROMETEOROLOGICAL GAGES: NONE

- a. Type _____
- b. Location _____
- c. Records _____

MAXIMUM NON-DAMAGING DISCHARGE: 2805 CFS (OVER SPILLWAY + OVER SLUICE WAY)

LAKE INEZ






FIGURE 2
SEASONAL VARIATION
DEPTH-AREA-DURATION RELATIONSHIPS
Percentage to be applied to 200 square miles
24 hour probable maximum precipitation values
for: THE-ALL SEASON ENVELOPE



D-2

1000 800 600 400 200 0
6 12 24 48 HOURS
1000 800 600 400 200 0
6 12 24 48 HOURS
1000 800 600 400 200 0
6 12 24 48 HOURS

LEEDA, HILL AND JEWETT, INC.

CLIENT: NEW JERSEY


SHEET NO. 07

DATE: 7/11/80 PROJECT: LAKE JUNE 3

JOB NO. 202-01

STATION	Channel Cross-Sections	Distance Downstream of Downcut Bank	Min Width Left Over- Bank	Min Width Right Over- Bank	Channel Width (ft)	May Elev. (ft)	Bank Length (ft)	Excav Grade Line Slope	11	12	13	14	15	16	17	18	19	20	
1	STARTON																		
2	Sketch #1	150	0.1	0.45	0.1	257	15	0.06	X	Y	0	150	490	500	525	535	700	150	
3		240	0.1	0.45	0.1	250	225	0.04	X	Y	0	280	261	257	257	261	280	290	
4		1080	0.1	0.45	0.1	216	840	0.04	X	Y	0	260	700	700	725	725	900	1200	
5	Lake					203	860	0.02	X	Y	0	220	215	216	216	215	220	230	
6	Downstream	400	0.05	0.45	0.05	123	400	0.01	X	Y	0	220	1150	203	203	207	220	1400	
7	of Lake	2700	0.5	0.45	0.5	181	2300	0.01	X	Y	0	900	950	775	1025	1025	1075	240	
8	Downstream								X	Y	0	50	550	575	625	650	800	2550	
9									X	Y	0	200	190	183	183	190	200	220	
10									X	Y	0	200	190	181	181	190	200	220	

REFERENCE LINE NO. 800

DISCHARGE OVER DAM

$$Q = CLH^{1.5}$$

$C = 3.1$ (BROADCRESTED WEIR) (EXCEPT SLUICWAY $C = 3.3$) ②

ELEV	①		②		③		④		TOTAL (CFS)
	H (FT)	Q (CFS)	H (FT)	Q (CFS)	H (FT)	Q (CFS)	H (FT)	Q (CFS)	
197	1	640	1	30					670
198	2	1810	2	80					1690
198.6	2.6	2680	2.6	125	0	0			2805
199	3	3320	3	155	0.4	50			3525
200	4	5110	4	240	1.4	330			5680
201	5	7140	5	330	2.4	750	0	0	8220
202	6	9390	6	440	3.4	1260	1	200	11290
203	7	11830	7	550	4.4	1860	2	590	14830
206	10	20190	10	940	7.4	4060	5	2250	27440
211	15	37104	15	1725	12.4	8800	10	6370	53995

⌊ THIS DISCHARGE ASSUMES NO TAILWATER EFFECTS. IT WAS FOUND TAILWATER AT HIGHER DISCHARGES AFFECTED THE DISCHARGE.

LEEDS, HILL AND JEWETT, INC.

BY RBT DATE 7-10-42 CLIENT New Jersey SHEET NO. 2 OF 6

CHKD. DATE JOB JOB NO. 302-23

TAILWATER EFFECTS ON SPILLWAY DISCHARGE

DOWNSTREAM OF THE DAM THE CHANNEL NARROWS PRODUCING A BACKWATER WHICH SUBMERGES THE SPILLWAY AND REDUCES DISCHARGE CALCULATED PREVIOUSLY ASSUMING NO SUBMERGENCE. IN ORDER TO DETERMINE THE TAILWATER EFFECTS ON DISCHARGE A NUMBER OF ASSUMPTIONS WERE MADE.


- 1) FOR LARGE FLOWS THE WATER SURFACE ELEVATION @ THE DAM AND AT THE DOWNSTREAM SECTION, 400 FT FROM THE DAM ARE THE SAME.
- 2) FIG 252 IN DESIGN OF SMALL DAMS (USBR) CAN BE USED TO CALCULATE DISCHARGE REDUCTION DUE TO SUBMERGENCE FOR WEIR FLOW
- 3) THE STREAMBED ELEVATION BELOW THE DAM IS 183 EXCEPT AT THE LEFT ABUTMENT WHICH IS 3 FT BELOW THE WALL WITH AN ELEV. OF 185.6

METHOD: FOR A GIVEN DISCHARGE, AT THE DOWNSTREAM STATION THE DEPTH IS OBTAINED FROM A RATING CURVE USING MANNINGS EQU. A HEAD OVER THE DAM IS ASSUMED AND THE % REDUCTION IN DISCHARGE IS DETERMINED GRAPHICALLY (FIG 252 DESIGN OF SMALL DAMS) FOR ALL THREE SPILLWAYS WITH DIFFERENT CREST ELEVATIONS. THE FREE DISCHARGE IS DETERMINED FOR EACH SPILLWAY AND REDUCED BY THE ABOVE %. THE TOTAL CORRECTED DISCHARGE SHOULD EQUAL THE ORIGINAL DISCHARGE, IF NOT A NEW HEAD IS ASSUMED UNTIL THE SAME DISCHARGE IS OBTAINED

CHECKED LINE (IND. 5000)

LEEDS, HILL AND JEWETT, INC.

BY RBE DATE 7/10/42 CLIENT NEW JERSEY SHEET NO 3 OF 6
 CHKD DATE JOB JOB NO. 302-03



- ① From HEC1 Run Assuming no tailwater effects.
- ② From FIG 252 DESIGN OF SMALL DAMS, USBR
- ③ FROM RATING CURVES ASSUMING NO SUBMERGENCE PAGE 4
- ④ SUMMATION OF CORRECTED SPILLWAY DISCHARGES USING % REDUCTION OF Q



LEEDS, HILL AND JEWETT, INC.

BY RBE DATE 7/04/26 CLIENT NEW JERSEY

SHEET NO. 5 OF 6

CHKD. DATE JOB

JOB NO. 302-03

NORMAL DEPTH CHANNELS ROUTING @ BRIDGE HEC-1 OUTPUT

	1	2	3	4	5	6	7	8	9
QNI(1)	0.00	1.07	2.29	3.90	5.57	7.08	11.13	12.93	16.04
QNI(2)	24.61	31.43	40.07	50.34	62.93	76.96	92.91	110.70	130.31
QNI(3)	166.78	16724.25	20487.95	24938.91	30153.95	3320.73	43163.27	6623.50	8648.90
FLNVT	193.0	200.00	200.00	200.00	200.00	200.00	200.00	200.00	200.00
ELMAX	220.0	220.00	220.00	220.00	220.00	220.00	220.00	220.00	220.00
RLNTH	400.	400.	400.	400.	400.	400.	400.	400.	400.
SEL	.60100	.60100	.60100	.60100	.60100	.60100	.60100	.60100	.60100

CROSS SECTION COORDINATES—STA, ELEV, STA, ELEV—ETC	0.00	220.00	900.00	200.00	950.00	190.00	975.00	183.00	1025.00	183.00
	1090.00	190.00	1100.00	200.00	1250.00	220.00				
STORAGE	0.00	1.07	2.29	3.90	5.57	7.08	11.13	12.93	16.04	19.63
	24.61	31.43	40.07	50.34	62.93	76.96	92.91	110.70	130.31	152.74
OUTFLOW	0.00	166.78	16724.25	20487.95	24938.91	30153.95	3320.73	43163.27	6623.50	8648.90
	13569.50	16724.25	20487.95	24938.91	30153.95	36209.67	43163.27	51042.04	60054.37	70122.65
STAGE	183.00	194.05	195.89	188.84	190.74	192.74	194.68	196.63	198.58	200.53
	202.47	204.42	205.37	208.32	210.26	212.21	214.16	216.11	218.05	220.00
FLOW	0.00	166.78	16724.25	20487.95	24938.91	30153.95	3320.73	43163.27	6623.50	8648.90
	13569.50	16724.25	20487.95	24938.91	30153.95	36209.67	43163.27	51042.04	60054.37	70122.65

380

DESIGN OF SMALL DAMS





Figure 252. Effects of downstream influences on flow over weir crests. 288-D-2412.

D-9

SPILLWAY RATING CURVE



AMERICAN SOCIETY OF CIVIL ENGINEERS
NATIONAL SOCIETY OF PROFESSIONAL ENGINEERS

D-10

RBC 740212 302-03 LAKE TNEZ

DRAWDOWN CALCULATIONS

THERE ARE THREE OUTLETS ALL OF WHICH APPEARED INOPERABLE FROM FIELD INSPECTION. ONE OF THESE IS A TIMBER SLUICeway WHICH DOES NOT OPERATE BUT COULD BE EASILY DESTROYED IN CASE OF AN EMERGENCY DRAWDOWN. THEREFORE TIME REQUIRED TO CALCULATE DRAWDOWN WILL USE THIS GATE

$$Q = CLH^{1.5}$$

$C = 3.1$ AT BOTTOM OF SLUICeway/BROADCRESTED WEIR

$L = 9.4$ (94 FEET FROM INSPECTION REPORT JUNE 2 1960)

ASSUME: 1) NO INFLOWS INTO LAKE
2) NO TAILWATER EFFECTS

$$Q = 3.1(9.4) H^{1.5} \quad Q = \Delta S / \Delta t$$

$$\Delta S / \Delta t = 29.1 H^{1.5}$$

$$\Delta t = (\Delta S / 29.1 H^{1.5}) (43560 \text{ FT}^3/\text{AF}) (1/3600 \text{ SEC}/\text{HR})$$

$$\Delta t = 0.42 H^{-1.5} \Delta S$$

ELEV. (FT)	STO (AF)	Δ STO (AF)	MEAN HEAD (FT)	Δ TIME (HR)	Σ TIME (HR)
196	300				
		95	13	0.85	
194	205	70	11	0.81	0.9
192	135	50	9	0.76	1.7
190	85	65	6	1.86	2.4
186	20	20	1	8.40	4.3
182	0				<u>12.7</u>

DRAWDOWN TIME = 12.7 HR

.....
 FLOOD HYDROGRAPH PACKAGE (MFC-1)
 DAM SAFETY VERSION JULY 1979
 LAST MODIFICATION 25 SEP 79

.....
 NEW JERSEY DAM SAFETY / LAKE IMEZ I.O. NO. 00220
 HYDRAULIC-HYDROLOGIC ANALYSIS 302-03
 PROBABLE MAXIMUM FLOOD 0 0 0 0 0 0 0 0 0 0

.....
 1 1
 2 2
 3 3
 4 4
 5 5
 6 6
 7 7
 8 8
 9 9
 10 10
 11 11
 12 12
 13 13
 14 14
 15 15
 16 16
 17 17
 18 18
 19 19
 20 20
 21 21
 22 22
 23 23
 24 24
 25 25
 26 26
 27 27
 28 28
 29 29
 30 30
 31 31
 32 32
 33 33
 34 34
 35 35
 36 36
 37 37
 38 38
 39 39
 40 40
 41 41
 42 42
 43 43
 44 44
 45 45
 46 46
 47 47
 48 48
 49 49
 50 50

.....
 A1 NEW JERSEY DAM SAFETY / LAKE IMEZ I.O. NO. 00220
 A2 HYDRAULIC-HYDROLOGIC ANALYSIS 302-03
 A3 PROBABLE MAXIMUM FLOOD 0 0 0 0 0 0 0 0 0 0
 B 300
 C 30
 D 1
 E 4
 F 1
 G 0.25
 H 3.5
 I 1.0
 J 1
 K 1
 L 0
 M -1
 N OUTFLOWS FROM SKYLINE LAKE NO. 1 AND 2
 O 2.9

1	361	370	399	519	11	51	125	210	282	331
2	10803	9842	7443	5720	2253	5684	6921	5443	5992	7682
3	366	300	234	191	4583	3226	1887	1004	591	449
4					156	149				

.....
 1 CHANNEL ROUTING -MODIFIED PULS- STATION 1 TO 2
 2 1
 3 1
 4 1
 5 1
 6 1
 7 1
 8 1
 9 1
 10 1
 11 1
 12 1
 13 1
 14 1
 15 1
 16 1
 17 1
 18 1
 19 1
 20 1
 21 1
 22 1
 23 1
 24 1
 25 1
 26 1
 27 1
 28 1
 29 1
 30 1
 31 1
 32 1
 33 1
 34 1
 35 1
 36 1
 37 1
 38 1
 39 1
 40 1
 41 1
 42 1
 43 1
 44 1
 45 1
 46 1
 47 1
 48 1
 49 1
 50 1

HYDROGRAPH ROUTING

CHANNEL ROUTING - MODIFIED PULS - STATION 2 TO 3

ESTAG	ICOMP	RECOM	STAGE	JPLT	JFRT	INAME	ISTAGE	EAUTO
0	0	0	0	0	0	0	0	0
ROUTING DATA								
AVG	1	1	1	1	1	1	1	1
MSIPS	1	0	0	0	0	0	0	0
LAG	0	0	0	0	0	0	0	0
MSK	0	0	0	0	0	0	0	0
STIMA	0	0	0	0	0	0	0	0
ISPPAT	0	0	0	0	0	0	0	0

NORMAL OPEN CHANNEL ROUTING

0M111 0M121 0M131 0M141 0M151 0M161 0M171 0M181 0M191 0M201 0M211 0M221 0M231 0M241 0M251 0M261 0M271 0M281 0M291 0M301 0M311 0M321 0M331 0M341 0M351 0M361 0M371 0M381 0M391 0M401 0M411 0M421 0M431 0M441 0M451 0M461 0M471 0M481 0M491 0M501 0M511 0M521 0M531 0M541 0M551 0M561 0M571 0M581 0M591 0M601 0M611 0M621 0M631 0M641 0M651 0M661 0M671 0M681 0M691 0M701 0M711 0M721 0M731 0M741 0M751 0M761 0M771 0M781 0M791 0M801 0M811 0M821 0M831 0M841 0M851 0M861 0M871 0M881 0M891 0M901 0M911 0M921 0M931 0M941 0M951 0M961 0M971 0M981 0M991 0M1001

CROSS SECTION CHARACTERISTICS--STAGE, ELEV., STAGE ELEV.--ETC
 0.00 280.00 1000.00 280.00 1150.00 253.00 1150.00 250.00 1175.00 250.00
 1175.00 253.00 1300.00 280.00 1600.00 280.00

STORAGE	0.00	2.04	267.95	5.10	9.19	19.31	34.50	54.75	79.91	110.13	157.04
OUTFLOW	28773.04	28773.04	28773.04	28773.04	28773.04	28773.04	28773.04	28773.04	28773.04	28773.04	28773.04
STAGE	250.00	251.54	253.16	254.76	256.32	257.89	259.47	261.05	262.63	264.21	265.79
FLOW	28773.04	28773.04	28773.04	28773.04	28773.04	28773.04	28773.04	28773.04	28773.04	28773.04	28773.04

STATION 3, PLAN 1, REID 4

INFLOW	OUTFLOW	STAGE	FLOW	STAGE	FLOW	STAGE	FLOW	STAGE	FLOW	STAGE	FLOW
0.00	0.00	250.00	28773.04	250.00	28773.04	250.00	28773.04	250.00	28773.04	250.00	28773.04
100.00	100.00	251.54	28773.04	251.54	28773.04	251.54	28773.04	251.54	28773.04	251.54	28773.04
200.00	200.00	253.16	28773.04	253.16	28773.04	253.16	28773.04	253.16	28773.04	253.16	28773.04
300.00	300.00	254.76	28773.04	254.76	28773.04	254.76	28773.04	254.76	28773.04	254.76	28773.04
400.00	400.00	256.32	28773.04	256.32	28773.04	256.32	28773.04	256.32	28773.04	256.32	28773.04
500.00	500.00	257.89	28773.04	257.89	28773.04	257.89	28773.04	257.89	28773.04	257.89	28773.04
600.00	600.00	259.47	28773.04	259.47	28773.04	259.47	28773.04	259.47	28773.04	259.47	28773.04
700.00	700.00	261.05	28773.04	261.05	28773.04	261.05	28773.04	261.05	28773.04	261.05	28773.04
800.00	800.00	262.63	28773.04	262.63	28773.04	262.63	28773.04	262.63	28773.04	262.63	28773.04
900.00	900.00	264.21	28773.04	264.21	28773.04	264.21	28773.04	264.21	28773.04	264.21	28773.04
1000.00	1000.00	265.79	28773.04	265.79	28773.04	265.79	28773.04	265.79	28773.04	265.79	28773.04

HYDROGRAPH AT STA 5 FOR PLAN 1P REIO 4

0.	10.	20.	30.	40.	50.	60.	70.	80.
0.	100.	120.	130.	140.	150.	160.	170.	180.
90.	200.	210.	220.	230.	240.	250.	270.	280.
180.	300.	310.	320.	330.	340.	350.	370.	380.
270.	400.	410.	420.	430.	440.	460.	470.	480.
360.	500.	500.	520.	530.	540.	560.	570.	580.
450.	600.	610.	620.	630.	640.	660.	670.	680.
540.	700.	710.	720.	730.	740.	760.	770.	780.
630.	800.	810.	820.	830.	840.	860.	870.	880.
720.	900.	910.	920.	930.	940.	960.	970.	980.
810.	1000.	1010.	1020.	1030.	1040.	1060.	1070.	1080.
900.	1100.	1110.	1120.	1130.	1140.	1160.	1170.	1180.
990.	1200.	1210.	1220.	1230.	1240.	1260.	1270.	1280.
1080.	1300.	1310.	1320.	1330.	1340.	1360.	1370.	1380.
1170.	1400.	1410.	1420.	1430.	1440.	1460.	1470.	1480.
1260.	1500.	1510.	1520.	1530.	1540.	1560.	1570.	1580.
1350.	1600.	1610.	1620.	1630.	1640.	1660.	1670.	1680.
1440.	1700.	1710.	1720.	1730.	1740.	1760.	1770.	1780.
1530.	1800.	1810.	1820.	1830.	1840.	1860.	1870.	1880.
1620.	1900.	1910.	1920.	1930.	1940.	1960.	1970.	1980.
1710.	2000.	2010.	2020.	2030.	2040.	2060.	2070.	2080.
1800.	2100.	2110.	2120.	2130.	2140.	2160.	2170.	2180.
1890.	2200.	2210.	2220.	2230.	2240.	2260.	2270.	2280.
1980.	2300.	2310.	2320.	2330.	2340.	2360.	2370.	2380.
2070.	2400.	2410.	2420.	2430.	2440.	2460.	2470.	2480.
2160.	2500.	2510.	2520.	2530.	2540.	2560.	2570.	2580.
2250.	2600.	2610.	2620.	2630.	2640.	2660.	2670.	2680.
2340.	2700.	2710.	2720.	2730.	2740.	2760.	2770.	2780.
2430.	2800.	2810.	2820.	2830.	2840.	2860.	2870.	2880.
2520.	2900.	2910.	2920.	2930.	2940.	2960.	2970.	2980.
2610.	3000.	3010.	3020.	3030.	3040.	3060.	3070.	3080.
2700.	3100.	3110.	3120.	3130.	3140.	3160.	3170.	3180.
2790.	3200.	3210.	3220.	3230.	3240.	3260.	3270.	3280.
2880.	3300.	3310.	3320.	3330.	3340.	3360.	3370.	3380.
2970.	3400.	3410.	3420.	3430.	3440.	3460.	3470.	3480.
3060.	3500.	3510.	3520.	3530.	3540.	3560.	3570.	3580.
3150.	3600.	3610.	3620.	3630.	3640.	3660.	3670.	3680.
3240.	3700.	3710.	3720.	3730.	3740.	3760.	3770.	3780.
3330.	3800.	3810.	3820.	3830.	3840.	3860.	3870.	3880.
3420.	3900.	3910.	3920.	3930.	3940.	3960.	3970.	3980.
3510.	4000.	4010.	4020.	4030.	4040.	4060.	4070.	4080.
3600.	4100.	4110.	4120.	4130.	4140.	4160.	4170.	4180.
3690.	4200.	4210.	4220.	4230.	4240.	4260.	4270.	4280.
3780.	4300.	4310.	4320.	4330.	4340.	4360.	4370.	4380.
3870.	4400.	4410.	4420.	4430.	4440.	4460.	4470.	4480.
3960.	4500.	4510.	4520.	4530.	4540.	4560.	4570.	4580.
4050.	4600.	4610.	4620.	4630.	4640.	4660.	4670.	4680.
4140.	4700.	4710.	4720.	4730.	4740.	4760.	4770.	4780.
4230.	4800.	4810.	4820.	4830.	4840.	4860.	4870.	4880.
4320.	4900.	4910.	4920.	4930.	4940.	4960.	4970.	4980.
4410.	5000.	5010.	5020.	5030.	5040.	5060.	5070.	5080.
4500.	5100.	5110.	5120.	5130.	5140.	5160.	5170.	5180.
4590.	5200.	5210.	5220.	5230.	5240.	5260.	5270.	5280.
4680.	5300.	5310.	5320.	5330.	5340.	5360.	5370.	5380.
4770.	5400.	5410.	5420.	5430.	5440.	5460.	5470.	5480.
4860.	5500.	5510.	5520.	5530.	5540.	5560.	5570.	5580.
4950.	5600.	5610.	5620.	5630.	5640.	5660.	5670.	5680.
5040.	5700.	5710.	5720.	5730.	5740.	5760.	5770.	5780.
5130.	5800.	5810.	5820.	5830.	5840.	5860.	5870.	5880.
5220.	5900.	5910.	5920.	5930.	5940.	5960.	5970.	5980.
5310.	6000.	6010.	6020.	6030.	6040.	6060.	6070.	6080.
5400.	6100.	6110.	6120.	6130.	6140.	6160.	6170.	6180.
5490.	6200.	6210.	6220.	6230.	6240.	6260.	6270.	6280.
5580.	6300.	6310.	6320.	6330.	6340.	6360.	6370.	6380.
5670.	6400.	6410.	6420.	6430.	6440.	6460.	6470.	6480.
5760.	6500.	6510.	6520.	6530.	6540.	6560.	6570.	6580.
5850.	6600.	6610.	6620.	6630.	6640.	6660.	6670.	6680.
5940.	6700.	6710.	6720.	6730.	6740.	6760.	6770.	6780.
6030.	6800.	6810.	6820.	6830.	6840.	6860.	6870.	6880.
6120.	6900.	6910.	6920.	6930.	6940.	6960.	6970.	6980.
6210.	7000.	7010.	7020.	7030.	7040.	7060.	7070.	7080.
6300.	7100.	7110.	7120.	7130.	7140.	7160.	7170.	7180.
6390.	7200.	7210.	7220.	7230.	7240.	7260.	7270.	7280.
6480.	7300.	7310.	7320.	7330.	7340.	7360.	7370.	7380.
6570.	7400.	7410.	7420.	7430.	7440.	7460.	7470.	7480.
6660.	7500.	7510.	7520.	7530.	7540.	7560.	7570.	7580.
6750.	7600.	7610.	7620.	7630.	7640.	7660.	7670.	7680.
6840.	7700.	7710.	7720.	7730.	7740.	7760.	7770.	7780.
6930.	7800.	7810.	7820.	7830.	7840.	7860.	7870.	7880.
7020.	7900.	7910.	7920.	7930.	7940.	7960.	7970.	7980.
7110.	8000.	8010.	8020.	8030.	8040.	8060.	8070.	8080.
7200.	8100.	8110.	8120.	8130.	8140.	8160.	8170.	8180.
7290.	8200.	8210.	8220.	8230.	8240.	8260.	8270.	8280.
7380.	8300.	8310.	8320.	8330.	8340.	8360.	8370.	8380.
7470.	8400.	8410.	8420.	8430.	8440.	8460.	8470.	8480.
7560.	8500.	8510.	8520.	8530.	8540.	8560.	8570.	8580.
7650.	8600.	8610.	8620.	8630.	8640.	8660.	8670.	8680.
7740.	8700.	8710.	8720.	8730.	8740.	8760.	8770.	8780.
7830.	8800.	8810.	8820.	8830.	8840.	8860.	8870.	8880.
7920.	8900.	8910.	8920.	8930.	8940.	8960.	8970.	8980.
8010.	9000.	9010.	9020.	9030.	9040.	9060.	9070.	9080.
8100.	9100.	9110.	9120.	9130.	9140.	9160.	9170.	9180.
8190.	9200.	9210.	9220.	9230.	9240.	9260.	9270.	9280.
8280.	9300.	9310.	9320.	9330.	9340.	9360.	9370.	9380.
8370.	9400.	9410.	9420.	9430.	9440.	9460.	9470.	9480.
8460.	9500.	9510.	9520.	9530.	9540.	9560.	9570.	9580.
8550.	9600.	9610.	9620.	9630.	9640.	9660.	9670.	9680.
8640.	9700.	9710.	9720.	9730.	9740.	9760.	9770.	9780.
8730.	9800.	9810.	9820.	9830.	9840.	9860.	9870.	9880.
8820.	9900.	9910.	9920.	9930.	9940.	9960.	9970.	9980.
8910.	10000.	10010.	10020.	10030.	10040.	10060.	10070.	10080.
9000.	10100.	10110.	10120.	10130.	10140.	10160.	10170.	10180.
9090.	10200.	10210.	10220.	10230.	10240.	10260.	10270.	10280.
9180.	10300.	10310.	10320.	10330.	10340.	10360.	10370.	10380.
9270.	10400.	10410.	10420.	10430.	10440.	10460.	10470.	10480.
9360.	10500.	10510.	10520.	10530.	10540.	10560.	10570.	10580.
9450.	10600.	10610.	10620.	10630.	10640.	10660.	10670.	10680.
9540.	10700.	10710.	10720.	10730.	10740.	10760.	10770.	10780.
9630.	10800.	10810.	10820.	10830.	10840.	10860.	10870.	10880.
9720.	10900.	10910.	10920.	10930.	10940.	10960.	10970.	10980.
9810.	11000.	11010.	11020.	11030.	11040.	11060.	11070.	11080.
9900.	11100.	11110.	11120.	11130.	11140.	11160.	11170.	11180.
9990.	11200.	11210.	11220.	11230.	11240.	11260.	11270.	11280.
10080.	11300.	11310.	11320.	11330.	11340.	11360.	11370.	11380.
10170.	11400.	11410.	11420.	11430.	11440.	11460.	11470.	11480.
10260.	11500.	11510.	11520.	11530.	11540.	11560.	11570.	11580.
10350.	11600.	11610.	11620.	11630.	11640.	11660.	11670.	11680.
10440.	11700.	11710.	11720.	11730.	11740.	11760.	11770.	11780.
10530.	11800.	11810.	11820.	11830.	11840.	11860.	11870.	11880.
10620.	11900.	11910.	11920.	11930.	11940.	11960.	11970.	11980.
10710.	12000.	12010.	12020.	12030.	12040.	12060.	12070.	12080.
10800.	12100.	12110.	12120.	12130.	12140.	12160.	12170.	12180.
10890.	12200.	12210.	12220.	12230.	12240.	12260.	12270.	12280.
10980.	12300.	12310.	12320.	12330.	12340.	12360.	12370.	12380.
11070.	12400.	12410.	12420.	12430.	12440.	12460.	12470.	12480.
11160.	12500.	12510.	12520.	12530.	12540.	12560.	12570.	12580.
11250.	12600.	12610.	12620.	12630.	12640.	12660.	12670.	12680.
11340.	12700.	12710.	12720.	12730.	12740.	12760.	12770.	12780.
11430.	12800.	12810.	12820.	12830.	12840.	12860.	12870.	12880.
11520.	12900.	12910.	12920.	12930.	12940.	12960.	12970.	12980.
11610.	13000.	13010.	13020.	13030.	13040.	13060.	13070.	13080.
11700.	13100.	13110.	13120.	13130.	13140.	13160.	13170.	13180.
11790.	13200.	13210.	13220.	13230.	13240.	13260.	13270.	13280.
11880.	13300.	13310.	13320.	13330.	13340.	13360.	13370.	13380.
11970.	13400.	13410.	13420.	13430.	13440.	13460.	13470.	13480.
12060.	13500.	13510.	13520.	13530.	13540.	13560.	13570.	13580.
12150.	13600.	13610.	13620.	13630.	13640.	13660.	13670.	13680.
12240.	13700.	13710.	13720.	13730.	13740.	13760.	13770.	13780.
12330.	13800.	13810.	13820.	13830.	13840.	13860.	13870.	13880.
12420.	13900.	13910.	13920.	13930.	13940.	13960.	13970.	


AD-A069 943

NEW JERSEY STATE DEPT OF ENVIRONMENTAL PROTECTION TRENTON F/G 13/2
NATIONAL DAM SAFETY PROGRAM. LAKE INEZ DAM (NJ-00228), PASSAIC --ETC(U)
MAY 79 R J JENNY DACW61-78-C-0124

UNCLASSIFIED

NL

2 OF 2
AD
A069943



END
DATE
FILMED
7 79
DDC

HYDROGRAPH ROUTING

ROUTING CHANNEL OUTFLOWS TO STATION 7 AT LAKE INEZ

I5100 SCMP SECON I51APE JPLT JPR1 I51ARE I51AGE I51AUTO
 0 0 0 0 0 0 0 0
 CROSS CLASS AVG I51S1 I51A4E I51PT I51MP I51R L51R
 0.0 0.000 0.000 1 1 1 0 0 0
 I51T5 I51TDL LAG I51ASK I51 I51K I51OMA I51SPRAT
 1 0 0 0.000 0.000 0.000 0.000 0.

CHANNEL DEPTH CHANNEL ROUTING

Q1111 Q1121 Q1131 ELHWT ELHRAZ ELH1M SEL
 .1000 .4455 .1000 203.0 240.0 0000. .00200

CROSS SECTION COORDINATES--STA=ELEV+STA-ELEV--ETC
 0+00 243.00 1009.30 220.60 1150.00 207.00 1150.00 203.00 1225.00 203.00
 1225.00 237.00 1275.70 220.60 1600.60 246.00

STAGE	Q1111	Q1121	Q1131	ELHWT	ELHRAZ	ELH1M	SEL	STAGE	Q1111	Q1121	Q1131	ELHWT	ELHRAZ	ELH1M	SEL
536.00	0.00	24.04	57.07	91.00	137.19	194.10	262.00	342.73	434.29	536.00	637.55	739.11	840.67	942.23	1043.79
540.00	0.00	26.04	60.07	94.00	140.19	197.10	265.00	345.73	437.29	539.00	640.55	742.11	843.67	945.23	1046.79
544.00	0.00	28.04	63.07	97.00	143.19	200.10	268.00	348.73	440.29	541.00	642.55	744.11	845.67	947.23	1048.79
548.00	0.00	30.04	66.07	100.00	146.19	203.10	271.00	351.73	443.29	544.00	645.55	747.11	848.67	950.23	1051.79
552.00	0.00	32.04	69.07	103.00	149.19	206.10	274.00	354.73	446.29	547.00	648.55	750.11	851.67	953.23	1054.79
556.00	0.00	34.04	72.07	106.00	152.19	209.10	277.00	357.73	449.29	550.00	651.55	753.11	854.67	956.23	1057.79
560.00	0.00	36.04	75.07	109.00	155.19	212.10	280.00	360.73	452.29	553.00	654.55	756.11	857.67	959.23	1060.79
564.00	0.00	38.04	78.07	112.00	158.19	215.10	283.00	363.73	455.29	556.00	657.55	759.11	860.67	962.23	1063.79
568.00	0.00	40.04	81.07	115.00	161.19	218.10	286.00	366.73	458.29	559.00	660.55	762.11	863.67	965.23	1066.79
572.00	0.00	42.04	84.07	118.00	164.19	221.10	289.00	369.73	461.29	562.00	663.55	765.11	866.67	968.23	1069.79
576.00	0.00	44.04	87.07	121.00	167.19	224.10	292.00	372.73	464.29	565.00	666.55	768.11	869.67	971.23	1072.79
580.00	0.00	46.04	90.07	124.00	170.19	227.10	295.00	375.73	467.29	568.00	669.55	771.11	872.67	974.23	1075.79
584.00	0.00	48.04	93.07	127.00	173.19	230.10	298.00	378.73	470.29	571.00	672.55	774.11	875.67	977.23	1078.79
588.00	0.00	50.04	96.07	130.00	176.19	233.10	301.00	381.73	473.29	574.00	675.55	777.11	878.67	980.23	1081.79
592.00	0.00	52.04	99.07	133.00	179.19	236.10	304.00	384.73	476.29	577.00	678.55	780.11	881.67	983.23	1084.79
596.00	0.00	54.04	102.07	136.00	182.19	239.10	307.00	387.73	479.29	580.00	681.55	783.11	884.67	986.23	1087.79
600.00	0.00	56.04	105.07	139.00	185.19	242.10	310.00	390.73	482.29	583.00	684.55	786.11	887.67	989.23	1090.79
604.00	0.00	58.04	108.07	142.00	188.19	245.10	313.00	393.73	485.29	586.00	687.55	789.11	890.67	992.23	1093.79
608.00	0.00	60.04	111.07	145.00	191.19	248.10	316.00	396.73	488.29	589.00	690.55	792.11	893.67	995.23	1096.79
612.00	0.00	62.04	114.07	148.00	194.19	251.10	319.00	399.73	491.29	592.00	693.55	795.11	896.67	998.23	1099.79
616.00	0.00	64.04	117.07	151.00	197.19	254.10	322.00	402.73	494.29	595.00	696.55	798.11	899.67	1001.23	1102.79
620.00	0.00	66.04	120.07	154.00	200.19	257.10	325.00	405.73	497.29	598.00	699.55	801.11	902.67	1004.23	1105.79
624.00	0.00	68.04	123.07	157.00	203.19	260.10	328.00	408.73	500.29	601.00	702.55	804.11	905.67	1007.23	1108.79
628.00	0.00	70.04	126.07	160.00	206.19	263.10	331.00	411.73	503.29	604.00	705.55	807.11	908.67	1010.23	1111.79
632.00	0.00	72.04	129.07	163.00	209.19	266.10	334.00	414.73	506.29	607.00	708.55	810.11	911.67	1013.23	1114.79
636.00	0.00	74.04	132.07	166.00	212.19	269.10	337.00	417.73	509.29	610.00	711.55	813.11	914.67	1016.23	1117.79
640.00	0.00	76.04	135.07	169.00	215.19	272.10	340.00	420.73	512.29	613.00	714.55	816.11	917.67	1019.23	1120.79
644.00	0.00	78.04	138.07	172.00	218.19	275.10	343.00	423.73	515.29	616.00	717.55	819.11	920.67	1022.23	1123.79
648.00	0.00	80.04	141.07	175.00	221.19	278.10	346.00	426.73	518.29	619.00	720.55	822.11	923.67	1025.23	1126.79
652.00	0.00	82.04	144.07	178.00	224.19	281.10	349.00	429.73	521.29	622.00	723.55	825.11	926.67	1028.23	1129.79
656.00	0.00	84.04	147.07	181.00	227.19	284.10	352.00	432.73	524.29	625.00	726.55	828.11	929.67	1031.23	1132.79
660.00	0.00	86.04	150.07	184.00	230.19	287.10	355.00	435.73	527.29	628.00	729.55	831.11	932.67	1034.23	1135.79
664.00	0.00	88.04	153.07	187.00	233.19	290.10	358.00	438.73	530.29	631.00	732.55	834.11	935.67	1037.23	1138.79
668.00	0.00	90.04	156.07	190.00	236.19	293.10	361.00	441.73	533.29	634.00	735.55	837.11	938.67	1040.23	1141.79
672.00	0.00	92.04	159.07	193.00	239.19	296.10	364.00	444.73	536.29	637.00	738.55	840.11	941.67	1043.23	1144.79
676.00	0.00	94.04	162.07	196.00	242.19	299.10	367.00	447.73	539.29	640.00	741.55	843.11	944.67	1046.23	1147.79
680.00	0.00	96.04	165.07	199.00	245.19	302.10	370.00	450.73	542.29	643.00	744.55	846.11	947.67	1049.23	1150.79
684.00	0.00	98.04	168.07	202.00	248.19	305.10	373.00	453.73	545.29	646.00	747.55	849.11	950.67	1052.23	1153.79
688.00	0.00	100.04	171.07	205.00	251.19	308.10	376.00	456.73	548.29	649.00	750.55	852.11	953.67	1055.23	1156.79
692.00	0.00	102.04	174.07	208.00	254.19	311.10	379.00	459.73	551.29	652.00	753.55	855.11	956.67	1058.23	1159.79
696.00	0.00	104.04	177.07	211.00	257.19	314.10	382.00	462.73	554.29	655.00	756.55	858.11	959.67	1061.23	1162.79
700.00	0.00	106.04	180.07	214.00	260.19	317.10	385.00	465.73	557.29	658.00	759.55	861.11	962.67	1064.23	1165.79
704.00	0.00	108.04	183.07	217.00	263.19	320.10	388.00	468.73	560.29	661.00	762.55	864.11	965.67	1067.23	1168.79
708.00	0.00	110.04	186.07	220.00	266.19	323.10	391.00	471.73	563.29	664.00	765.55	867.11	968.67	1070.23	1171.79
712.00	0.00	112.04	189.07	223.00	269.19	326.10	394.00	474.73	566.29	667.00	768.55	870.11	971.67	1073.23	1174.79
716.00	0.00	114.04	192.07	226.00	272.19	329.10	397.00	477.73	569.29	670.00	771.55	873.11	974.67	1076.23	1177.79
720.00	0.00	116.04	195.07	229.00	275.19	332.10	400.00	480.73	572.29	673.00	774.55	876.11	977.67	1079.23	1180.79
724.00	0.00	118.04	198.07	232.00	278.19	335.10	403.00	483.73	575.29	676.00	777.55	879.11	980.67	1082.23	1183.79
728.00	0.00	120.04	201.07	235.00	281.19	338.10	406.00	486.73	578.29	679.00	780.55	882.11	983.67	1085.23	1186.79
732.00	0.00	122.04	204.07	238.00	284.19	341.10	409.00	489.73	581.29	682.00	783.55	885.11	986.67	1088.23	1189.79
736.00	0.00	124.04	207.07	241.00	287.19	344.10	412.00	492.73	584.29	685.00	786.55	888.11	989.67	1091.23	1192.79
740.00	0.00	126.04	210.07	244.00	290.19	347.10	415.00	495.73	587.29	688.00	789.55	891.11	992.67	1094.23	1195.79
744.00	0.00	128.04	213.07	247.00	293.19	350.10	418.00	498.73	590.29	691.00	792.55	894.11	995.67	1097.23	1198.79
748.00	0.00	130.04	216.07	250.00	296.19	353.10	421.00	501.73	593.29	694.00	795.55	897.11	998.67	1100.23	1201.79
752.00	0.00	132.04	219.07	253.00	299.19	356.10	424.00	504.73	596.29	697.00	798.55	900.11	1001.67	1103.23	1204.79
756.00	0.00	134.04	222.07	256.00	302.19	359.10	427.00	507.73	599.29	700.00	801.55	903.11	1004.67	1106.23	1207.79
760.00	0.00	136.04	225.07	259.00	305.19	362.10	430.00	510.73	602.29	703.00	804.55	906.11	1007.67	1109.23	1210.79
764.00	0.00	138.04	228.07	262.00	308.19	365.10	433.00	513.73	605.29	706.00	807.55	909.11	1010.67	1112.23	1213.79
768.00	0.00	140.04</													

STAGE	201.0	201.5	202.0	202.5	203.0	203.5	204.0	204.5	205.0	205.5	206.0	206.5	207.0	207.5	208.0	208.5	209.0	209.5	210.0	210.5	211.0	211.5	212.0	212.5	213.0	213.5	214.0	214.5	215.0	215.5	216.0	216.5	217.0	217.5	218.0	218.5	219.0	219.5	220.0	220.5	221.0	221.5	222.0	222.5	223.0	223.5	224.0	224.5	225.0	225.5	226.0	226.5	227.0	227.5	228.0	228.5	229.0	229.5	230.0	230.5	231.0	231.5	232.0	232.5	233.0	233.5	234.0	234.5	235.0	235.5	236.0	236.5	237.0	237.5	238.0	238.5	239.0	239.5	240.0	240.5	241.0	241.5	242.0	242.5	243.0	243.5	244.0	244.5	245.0	245.5	246.0	246.5	247.0	247.5	248.0	248.5	249.0	249.5	250.0	250.5	251.0	251.5	252.0	252.5	253.0	253.5	254.0	254.5	255.0	255.5	256.0	256.5	257.0	257.5	258.0	258.5	259.0	259.5	260.0
201.0	201.0	201.5	202.0	202.5	203.0	203.5	204.0	204.5	205.0	205.5	206.0	206.5	207.0	207.5	208.0	208.5	209.0	209.5	210.0	210.5	211.0	211.5	212.0	212.5	213.0	213.5	214.0	214.5	215.0	215.5	216.0	216.5	217.0	217.5	218.0	218.5	219.0	219.5	220.0	220.5	221.0	221.5	222.0	222.5	223.0	223.5	224.0	224.5	225.0	225.5	226.0	226.5	227.0	227.5	228.0	228.5	229.0	229.5	230.0	230.5	231.0	231.5	232.0	232.5	233.0	233.5	234.0	234.5	235.0	235.5	236.0	236.5	237.0	237.5	238.0	238.5	239.0	239.5	240.0	240.5	241.0	241.5	242.0	242.5	243.0	243.5	244.0	244.5	245.0	245.5	246.0	246.5	247.0	247.5	248.0	248.5	249.0	249.5	250.0	250.5	251.0	251.5	252.0	252.5	253.0	253.5	254.0	254.5	255.0	255.5	256.0	256.5	257.0	257.5	258.0	258.5	259.0	259.5	260.0

STAGE	24-HOUR	72-HOUR	TOTAL VOLUME
201.0	23092	16367	2361572
201.5	23092	16367	2361572
202.0	23092	16367	2361572
202.5	23092	16367	2361572
203.0	23092	16367	2361572
203.5	23092	16367	2361572
204.0	23092	16367	2361572
204.5	23092	16367	2361572
205.0	23092	16367	2361572
205.5	23092	16367	2361572
206.0	23092	16367	2361572
206.5	23092	16367	2361572
207.0	23092	16367	2361572
207.5	23092	16367	2361572
208.0	23092	16367	2361572
208.5	23092	16367	2361572
209.0	23092	16367	2361572
209.5	23092	16367	2361572
210.0	23092	16367	2361572
210.5	23092	16367	2361572
211.0	23092	16367	2361572
211.5	23092	16367	2361572
212.0	23092	16367	2361572
212.5	23092	16367	2361572
213.0	23092	16367	2361572
213.5	23092	16367	2361572
214.0	23092	16367	2361572
214.5	23092	16367	2361572
215.0	23092	16367	2361572
215.5	23092	16367	2361572
216.0	23092	16367	2361572
216.5	23092	16367	2361572
217.0	23092	16367	2361572
217.5	23092	16367	2361572
218.0	23092	16367	2361572
218.5	23092	16367	2361572
219.0	23092	16367	2361572
219.5	23092	16367	2361572
220.0	23092	16367	2361572
220.5	23092	16367	2361572
221.0	23092	16367	2361572
221.5	23092	16367	2361572
222.0	23092	16367	2361572
222.5	23092	16367	2361572
223.0	23092	16367	2361572
223.5	23092	16367	2361572
224.0	23092	16367	2361572
224.5	23092	16367	2361572
225.0	23092	16367	2361572
225.5	23092	16367	2361572
226.0	23092	16367	2361572
226.5	23092	16367	2361572
227.0	23092	16367	2361572
227.5	23092	16367	2361572
228.0	23092	16367	2361572
228.5	23092	16367	2361572
229.0	23092	16367	2361572
229.5	23092	16367	2361572
230.0	23092	16367	2361572
230.5	23092	16367	2361572
231.0	23092	16367	2361572
231.5	23092	16367	2361572
232.0	23092	16367	2361572
232.5	23092	16367	2361572
233.0	23092	16367	2361572
233.5	23092	16367	2361572
234.0	23092	16367	2361572
234.5	23092	16367	2361572
235.0	23092	16367	2361572
235.5	23092	16367	2361572
236.0	23092	16367	2361572
236.5	23092	16367	2361572
237.0	23092	16367	2361572
237.5	23092	16367	2361572
238.0	23092	16367	2361572
238.5	23092	16367	2361572
239.0	23092	16367	2361572
239.5	23092	16367	2361572
240.0	23092	16367	2361572

MAXIMUM STORAGE - 1000.

MAXIMUM STAGE IS 220.2

D-2B

HYDROGRAPH ROUTING

ROUTINE COMBINED FLOWS THROUGH LAKE INEZ

ESTAG	ICOMP	SECON	ITAVE	JPLT	JPRY	IMANE	ISTAGE	LAUFO		
10	1	0	0	0	0	1	0	0		
ROUTING DATA										
LOSS	AVG	INETS	ISAME	LOPT	IPMP		LSFR			
0.0	0.000	1	1	0	0		0			
MSTPS										
1	0	0	0.000	0.000	0.000	IS4	SIORA	ISPRAT		
						300.	300.	-1		
STAGE	190.00	197.00	199.00	198.60	199.60	201.13	203.30	207.10	230.00	211.10
FLOW	6.02	670.00	1092.00	2005.00	3325.00	4560.00	13550.00	20610.00	24650.60	30690.00
CAPACITY	0.	10.	80.	300.	550.	1000.	1630.	1900.		
ELEVATION	102.	195.	190.	196.	200.	205.	210.	211.		
COEL	3P410	COU	ESPV	ELEV	COOL	CAREA	ENPL			
100.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0			
GAIN DATA										
IBPEL	COOD	ESPV	BARNUD							
211.1	0.0	1.0	0.							

STATION 10, PLAN 1, RATIO 4

ITERATIVE SOLUTION DID NOT CONVERGE 89 1 0.000 2.000E+02 4.675E+02 2.000E+02 -7.342E+32

ITERATIVE SOLUTION DID NOT CONVERGE 119 1 0.000 2.000E+02 4.597E+02 2.000E+02 -7.356E+32

END-OF-PERIOD HYDROGRAPH ORDINATES

OUIFLOW		STORAGE	
2.	3.	3.	3.
300	300	300	300
305	305	305	305
310	310	310	310
315	315	315	315
320	320	320	320
325	325	325	325
330	330	330	330
335	335	335	335
340	340	340	340
345	345	345	345
350	350	350	350
355	355	355	355
360	360	360	360
365	365	365	365
370	370	370	370
375	375	375	375
380	380	380	380
385	385	385	385
390	390	390	390
395	395	395	395
400	400	400	400
405	405	405	405
410	410	410	410
415	415	415	415
420	420	420	420
425	425	425	425
430	430	430	430
435	435	435	435
440	440	440	440
445	445	445	445
450	450	450	450
455	455	455	455
460	460	460	460
465	465	465	465
470	470	470	470
475	475	475	475
480	480	480	480
485	485	485	485
490	490	490	490
495	495	495	495
500	500	500	500
505	505	505	505
510	510	510	510
515	515	515	515
520	520	520	520
525	525	525	525
530	530	530	530
535	535	535	535
540	540	540	540
545	545	545	545
550	550	550	550
555	555	555	555
560	560	560	560
565	565	565	565
570	570	570	570
575	575	575	575
580	580	580	580
585	585	585	585
590	590	590	590
595	595	595	595
600	600	600	600
605	605	605	605
610	610	610	610
615	615	615	615
620	620	620	620
625	625	625	625
630	630	630	630
635	635	635	635
640	640	640	640
645	645	645	645
650	650	650	650
655	655	655	655
660	660	660	660
665	665	665	665
670	670	670	670
675	675	675	675
680	680	680	680
685	685	685	685
690	690	690	690
695	695	695	695
700	700	700	700
705	705	705	705
710	710	710	710
715	715	715	715
720	720	720	720
725	725	725	725
730	730	730	730
735	735	735	735
740	740	740	740
745	745	745	745
750	750	750	750
755	755	755	755
760	760	760	760
765	765	765	765
770	770	770	770
775	775	775	775
780	780	780	780
785	785	785	785
790	790	790	790
795	795	795	795
800	800	800	800
805	805	805	805
810	810	810	810
815	815	815	815
820	820	820	820
825	825	825	825
830	830	830	830
835	835	835	835
840	840	840	840
845	845	845	845
850	850	850	850
855	855	855	855
860	860	860	860
865	865	865	865
870	870	870	870
875	875	875	875
880	880	880	880
885	885	885	885
890	890	890	890
895	895	895	895
900	900	900	900
905	905	905	905
910	910	910	910
915	915	915	915
920	920	920	920
925	925	925	925
930	930	930	930
935	935	935	935
940	940	940	940
945	945	945	945
950	950	950	950
955	955	955	955
960	960	960	960
965	965	965	965
970	970	970	970
975	975	975	975
980	980	980	980
985	985	985	985
990	990	990	990
995	995	995	995
1000	1000	1000	1000

HYDROGRAPH ROUTING

CHANNEL ROUTING -MODIFIED PULS- STATION 10 TO 11

ISFAC 11
 ISECO 1
 ISECA 0
 ISECB 0
 ISECC 0
 ISECD 0
 ISECE 0
 ISECF 0
 ISECG 0
 ISECH 0
 ISECI 0
 ISECK 0
 ISECL 0
 ISECM 0
 ISECN 0
 ISECO 0
 ISECP 0
 ISECQ 0
 ISECR 0
 ISECS 0
 ISECT 0
 ISECU 0
 ISECV 0
 ISECW 0
 ISECX 0
 ISECY 0
 ISECZ 0
 ISECA 0
 ISECB 0
 ISECC 0
 ISECD 0
 ISECE 0
 ISECF 0
 ISECG 0
 ISECH 0
 ISECI 0
 ISECK 0
 ISECL 0
 ISECM 0
 ISECN 0
 ISECO 0
 ISECP 0
 ISECQ 0
 ISECR 0
 ISECS 0
 ISECT 0
 ISECU 0
 ISECV 0
 ISECW 0
 ISECX 0
 ISECY 0
 ISECZ 0
 ISECA 0
 ISECB 0
 ISECC 0
 ISECD 0
 ISECE 0
 ISECF 0
 ISECG 0
 ISECH 0
 ISECI 0
 ISECK 0
 ISECL 0
 ISECM 0
 ISECN 0
 ISECO 0
 ISECP 0
 ISECQ 0
 ISECR 0
 ISECS 0
 ISECT 0
 ISECU 0
 ISECV 0
 ISECW 0
 ISECX 0
 ISECY 0
 ISECZ 0

NORMAL DEPTH CHANNEL ROUTING

0M11 0M12 0M13 0M14 0M15 0M16 0M17 0M18 0M19 0M20
 0.00 220.00 200.00 200.00 200.00 200.00 200.00 200.00 200.00 200.00
 1920.00 1920.00 1920.00 1920.00 1920.00 1920.00 1920.00 1920.00 1920.00 1920.00

CROSS SECTION COORDINATES--STA, LELY, STAGE, ELEV--ETC

STORAGE	0.03	1.02	2.29	4.07	5.54	7.68	10.13	12.92	16.08	19.63
	24.61	31.53	45.07	58.54	72.07	85.54	99.07	112.54	126.07	139.54
STAGE	0.20	1.00	2.00	3.00	4.00	5.00	6.00	7.00	8.00	9.00
FLOW	1350.00	1670.00	2000.00	2330.00	2660.00	2990.00	3320.00	3650.00	3980.00	4310.00
	143.00	144.95	146.89	148.84	150.79	152.74	154.68	156.63	158.58	160.53
	201.07	204.42	208.37	212.32	216.26	220.21	224.16	228.11	232.06	236.01
FLOW	6.00	100.78	560.66	1170.25	2071.81	3120.73	4330.27	5683.50	7188.05	8855.37
	1350.00	1670.00	2000.00	2330.00	2660.00	2990.00	3320.00	3650.00	3980.00	4310.00

STATION 11. PLAN 1. RATIO 4

3.	4.	5.	6.	7.	8.	9.	10.	11.	12.	13.	14.	15.	16.	17.	18.	19.	20.	21.	22.	23.	24.	25.	26.	27.	28.	29.	30.	31.	32.	33.	34.	35.	36.	37.	38.	39.	40.	41.	
156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156	156

STATION

0.	1.	2.	3.	4.	5.	6.	7.	8.	9.	10.	11.	12.	13.	14.	15.	16.	17.	18.	19.	20.	21.	22.	23.	24.	25.	26.	27.	28.	29.	30.	31.	32.	33.	34.	35.	36.	37.	38.	39.	40.	41.
0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

HYDROGRAPH ROUTING

CHANNEL ROUTING --MODIFIED FULL-- STATION 11 TO 12

ISTAB	ICOMP	ISECOM	ITRAPE	JPL1	JPL2	ISAME	ISTAGE	EAUTO
12	1	0	0	0	0	1	0	0
COLDS	CLOSS	AVG	ROUTING	ISPT	ISPP		LSFD	
0.0	0.000	0.000	1	0	0		0	
4ST01	4ST02	LAG	4ST03	4	4SK	4	4ST04	4ST05
1	0	0	0.000	0.000	0.000	0.000	0.000	0.000

NORMAL DEPTH CHANNEL ROUTING

0M11	0M12	0M13	ELBUT	ELMAS	PLMTH	SEL
.1000	.6430	.1107	101.6	220.0	2300.	.68100

CROSS SECTION COORDINATES--STA, ELEV, STAG, ELEV--ETC
 0.00 227.00 59.03 200.00 550.00 190.00
 0.00 132.00 090.09 200.66 2535.00 250.50

STORAGE	6.29	5.99	13.31	21.82	51.26	49.09	72.01	113.94	160.33	239.60
	326.62	432.21	556.61	704.64	870.69	1027.16	1263.66	1499.77	1736.11	2022.67
OUTFLOW	0.85	179.00	595.26	1220.01	2082.01	3307.21	5049.01	7629.97	10532.19	14039.09
	14995.00	26133.92	34137.39	43776.42	55116.64	68300.32	83662.03	100711.17	120166.21	141900.92
STAGE	101.33	103.35	105.11	107.16	109.21	191.26	193.32	195.37	197.42	199.47
	201.33	203.30	205.03	207.68	209.74	211.79	213.84	215.89	217.93	220.00
FLOW	0.00	179.00	596.26	1220.01	2082.01	3109.21	5049.01	7629.97	10532.19	14039.09
	19995.00	26133.92	34137.39	43776.42	55116.64	68300.32	83662.03	100711.17	120166.21	141900.92

STATION 12. PLAN 1. RT10 4

OUTFLOW		STORM	
1.	2.	1.	2.
42	41	0	0
138	148	1	1
232	244	2	2
327	341	3	3
422	440	4	4
517	538	5	5
612	636	6	6
707	734	7	7
802	832	8	8
897	930	9	9
992	1028	10	10
1087	1126	11	11
1182	1224	12	12
1277	1322	13	13
1372	1420	14	14
1467	1518	15	15
1562	1616	16	16
1657	1714	17	17
1752	1812	18	18
1847	1910	19	19
1942	2008	20	20
2037	2106	21	21
2132	2204	22	22
2227	2302	23	23
2322	2400	24	24
2417	2498	25	25
2512	2596	26	26
2607	2694	27	27
2702	2792	28	28
2797	2890	29	29
2892	2988	30	30
2987	3086	31	31
3082	3184	32	32
3177	3282	33	33
3272	3380	34	34
3367	3478	35	35
3462	3576	36	36
3557	3674	37	37
3652	3772	38	38
3747	3870	39	39
3842	3968	40	40
3937	4066	41	41
4032	4164	42	42
4127	4262	43	43
4222	4360	44	44
4317	4458	45	45
4412	4556	46	46
4507	4654	47	47
4602	4752	48	48
4697	4850	49	49
4792	4948	50	50
4887	5046	51	51
4982	5144	52	52
5077	5242	53	53
5172	5340	54	54
5267	5438	55	55
5362	5536	56	56
5457	5634	57	57
5552	5732	58	58
5647	5830	59	59
5742	5928	60	60
5837	6026	61	61
5932	6124	62	62
6027	6222	63	63
6122	6320	64	64
6217	6418	65	65
6312	6516	66	66
6407	6614	67	67
6502	6712	68	68
6597	6810	69	69
6692	6908	70	70
6787	7006	71	71
6882	7104	72	72
6977	7202	73	73
7072	7300	74	74
7167	7398	75	75
7262	7496	76	76
7357	7594	77	77
7452	7692	78	78
7547	7790	79	79
7642	7888	80	80
7737	7986	81	81
7832	8084	82	82
7927	8182	83	83
8022	8280	84	84
8117	8378	85	85
8212	8476	86	86
8307	8574	87	87
8402	8672	88	88
8497	8770	89	89
8592	8868	90	90
8687	8966	91	91
8782	9064	92	92
8877	9162	93	93
8972	9260	94	94
9067	9358	95	95
9162	9456	96	96
9257	9554	97	97
9352	9652	98	98
9447	9750	99	99
9542	9848	100	100

100	110	120	130	140	150	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300	310	320	330	340	350	360	370	380	390	400	410	420	430	440	450	460	470	480	490	500	510	520	530	540	550	560	570	580	590	600	610	620	630	640	650	660	670	680	690	700	710	720	730	740	750	760	770	780	790	800	810	820	830	840	850	860	870	880	890	900	910	920	930	940	950	960	970	980	990	1000
-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	------

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-DATIO ECONOMIC COMPUTATIONS
 FLOW IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE FEET (SQUARE METERS)

OPERATION	STATION	AREA	PLAN RATIO	DATIO APPLIED TO FLOWS			
				1	2	3	
				.10	.25	.50	
HYDROGRAPH AT	1	2,900 7,511	1	100%	2031	3102	10000
ROUTED TO	2	2,900 7,511	1	100%	75,001	100,121	300,251
ROUTED TO	3	2,900 7,511	1	29,901	2032	3102	10102
ROUTED TO	4	2,900 7,511	1	103%	2509	3102	10104
ROUTED TO	5	2,900 7,511	1	701	2502	42%	805%
HYDROGRAPH AT	6	0,000 0,000	1	2,020	7075	1,150	20300
2 COMBINED	7	2,900 7,511	1	60,101	200,101	400,001	801,371
ROUTED TO	8	2,900 7,511	1	2,020	7075	1,150	20300
HYDROGRAPH AT	9	4,000 12,631	1	100%	100,001	100,001	100,001
2 COMBINED	10	2,900 7,511	1	203%	7075	1,150	20300
ROUTED TO	11	2,900 7,511	1	203%	7075	1,150	20300
ROUTED TO	12	2,900 7,511	1	203%	7075	1,150	20300

PLAN 1 STATION 2

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
0.10	1059.	241.0	00.50
0.25	2662.	246.2	00.56
0.50	5205.	246.7	00.50
1.00	10502.	270.0	00.50

PLAN 1 STATION 3

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
0.10	1059.	255.3	01.00
0.25	2599.	257.3	01.00
0.50	5172.	256.2	01.00
1.00	10300.	261.5	01.00

PLAN 1 STATION 4

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
0.10	701.	220.5	01.50
0.25	2662.	221.9	01.50
0.50	5294.	223.3	01.50
1.00	8034.	225.1	01.50

PLAN 1 STATION 7

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
0.10	2625.	210.1	02.50
0.25	10311.	214.	02.50
0.50	19311.	216.7	02.50
1.00	28311.	220.2	02.50

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION STAGE OUTFLOW	INITIAL VALUE 100.00 300. 0.	SPILLWAY CREST 100.00 300. 0.	TOP OF DAM 211.10 3000. 2000.	MAXIMUM RESERVOIR ELEVATION ELEVATION	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
RATIO OF										
1.0	100.04	0.00	2001.	0.00	0.00	2001.	0.00	0.00	0.00	0.00
.75	200.56	0.00	277.	0.00	0.00	277.	0.00	0.00	0.00	0.00
.50	203.00	0.00	1557.	0.00	0.00	1557.	0.00	0.00	0.00	0.00
1.00	210.32	0.00	20721.	0.00	0.00	20721.	0.00	0.00	0.00	0.00

PLAN 1 STATION 11

RATIO	MAXIMUM FLOW.CFS	MAXIMUM STAGE.FT	TIME HOURS
1.0	2002.	192.1	03.00
.75	727.	197.2	02.56
.50	1600.	203.0	02.50
1.00	20707.	209.7	02.50

PLAN 1 STATION 12

RATIO	MAXIMUM FLOW.CFS	MAXIMUM STAGE.FT	TIME HOURS
1.0	2006.	190.9	03.00
.75	720.	195.2	03.00
.50	15203.	199.2	03.00
1.00	20770.	200.3	03.00

DAMS IN NEW JERSEY—REFERENCE DATA Wanacus River No. 23-89

Name of Owner _____ Address _____

Name of Dam Lake Inez County Passaic Location 23-31-9-7-5

CONSTRUCTION: Date _____ By whom _____

Stream Wanacus River Tributary to Powerton River

DRAINAGE BASIN: Area _____ sq. mi. Description _____

Description of valley below dam Residential (Powerton Lakes)

DAMAGE FROM FAILURE: Probable _____

Previous (date) _____

Purpose _____ Type Concrete Wall

Foundation _____

Length _____ ft. Max. height _____ ft. Max. width of top _____ ft.

Upstream slope _____ Downstream slope _____ Volume _____ Cu. yds.

SPILLWAY: Type _____ Length _____ ft.

Depth below top of _____ ft. Capacity _____ c. f. s. per sq. mi.

RESERVOIR: Capacity _____ mill. gals. Area _____ acres. Length _____ ft.

Outlets _____

Remarks _____

Sources of data U.S.G.S. Sheets, Continuous Profile Date Sept. 11, 1965

PFB

Report on Dam Inspection

Dam No. 23-89

Lake Inez Dam

Wanaque River

Willard Kluge, Artistic Weaving Co., Owner
Borough of Pompton Lakes, Passaic Co.

Location 23-31-8-7-5

At the request of Councilman Dwinell Travers, Borough of Pompton Lakes, an inspection of the subject dam was made in his company on May 24, 1960. Also present at the inspection were Mr. Frank Magill of Pompton Lakes, and Steve Dola and James Riley of this office.

The Lake Inez dam which is located upstream of Wanaque Avenue and the main part of the Borough of Pompton Lakes, once supplied water and power for an old adjacent mill which is now being operated as a weaving plant. Basically the dam is of heavy masonry construction with a concrete apron downstream. The main spillway has a length of 205.9 feet with a free board of 2.6 feet above the spillway crest. The old raceway through the powerhouse of the old mill has been walled off. The only other opening is a small sluiceway with timber gates in a span of 9.4 feet.


In the writer's opinion, the over-all structural condition of the dam, with the exception of the timber sluice gate and portions of the easterly end of the dam, is sound.

The timber sluice gate, which is located at the westerly end of the dam, is in very poor condition and failure is only a matter of time. Failure of the gate would only de-water the lake and complete failure of the dam probably would be unlikely. However, failure of the gate in time of a major flood may aggravate flooding conditions downstream.

Portions of the top spillway have shifted out of position in the area directly adjacent to an old forebay at the easterly end of the dam. Indications are, however, that this condition has existed for quite some time. Several points of leakage through the masonry spillway section were also noted in this same area. Grouting with the lake level lowered would probably eliminate these conditions.

A water and sand boil was noted within the old forebay downstream of its upstream wall. Indications are that this condition has also existed for quite some time. Combination of grouting and the placement of a clay blanket directly upstream would probably eliminate this conditions. Filling in of the forebay would also help to eliminate this conditions.

It is recommended that the attached letter be sent to the owner of the Lake Inez dam.



Michael J. Galley
Supervising Engineer Hydraulic

Trenton, New Jersey
June 2, 1960

Note: Stream survey sheet showing details of dam is attached.

D-48

WANAIQUE RESERVOIR
POSSIBLE MAXIMUM FLOOD
OUTFLOW HYDROGRAPH
FROM THE OVERFLOW WEIR
NT00214

PEAK 28300

DISCHARGE IN THOUSAND CFS

TIME IN HOURS

10/0/03

U.S. GEOLOGICAL SURVEY
WATER RESOURCES DIVISION
WASHINGTON, D.C. 20004










PLATE D-2




SENNY/LEWIS/TUL JULY 1979







**DRAINAGE BASIN
BOUNDARY**




AREA LOCATION

LAKE INEZ DAM

JENNY-LEEDSHILL

FEBRUARY 1979






PLATE D-2

Submitted to: US Army, Feb. 1971/02

