

AD-A070 720

D'APPOLONIA CONSULTING ENGINEERS INC PITTSBURGH PA  
NATIONAL DAM INSPECTION PROGRAM. PA-479 DAM (NDI ID NUMBER PA-5--ETC(U)  
MAR 79


F/G 13/2

DACW31-79-C-0014


NL

UNCLASSIFIED

1 OF 1  
AD  
A070720



END  
DATE  
FILMED  
8--79  
DDC



MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

LEVEL

6.5.

OHIO RIVER BASIN  
TRIBUTARY OF HARMON CREEK, WASHINGTON COUNTY

PENNSYLVANIA

See page ii.

PA-479 DAM


NDI I.D. NO: PA-509

DER I.D. NO: 63-71

DDC  
RECEIVED  
JUN 29 1979  
C

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

Distribution Unlimited  
Approved for Public Release  
Contract No. DACW31-79-C-0014 ✓



PREPARED FOR

DEPARTMENT OF THE ARMY  
BALTIMORE DISTRICT, CORPS OF ENGINEERS  
BALTIMORE, MARYLAND 21203

BY

✓ D'APPOLONIA CONSULTING ENGINEERS  
10 DUFF ROAD  
PITTSBURGH, PA. 15235  
MARCH 1979

ORIGINAL CONTAINS COLOR PLATES. ALL DDC  
REPRODUCTIONS WILL BE IN BLACK AND WHITE.

PA 070720

DDC FILE COPY

9 06 28 048

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Department of the Army, Office of Chief of Engineers, Washington, D.C. 20314.

The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon visual observations and review of available data. Detailed investigation and analyses involving topographic mapping, subsurface investigations, material testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the inspection is intended to identify any need for such studies which should be performed by the owner.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of the dam depends on numerous and constantly changing internal and external factors which are evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

The assessment of the conditions and recommendations was made by the consulting engineer in accordance with generally and currently accepted engineering principles and practices.

79 06 28 049

6

National Dam Inspection Program, PA-479  
Dam (NDI ID Number PA-509, DER ID  
Number 63-71), Ohio River Basin, Harmon  
Creek, Washington County, Pennsylvania.  
Phase I Inspection Report.

[CONT'D FROM  
P. 1]

PHASE I REPORT  
NATIONAL DAM INSPECTION PROGRAM

11 Mar 79

12 75 p.

NAME OF DAM: PA-479  
STATE LOCATED: Pennsylvania  
COUNTY LOCATED: Washington  
STREAM: Unnamed tributary of Harmon Creek, a tributary of Ohio River  
DATE OF INSPECTION: December 5 and 21, 1978

ASSESSMENT: Based on the evaluation of the conditions as they existed on the dates of inspection and as revealed by visual observations, the condition of PA-479 dam is assessed to be good.

The hillside west of the emergency spillway channel was found to be wet and irregular, showing signs of potential instability. It is recommended that this area be closely examined and necessary remedial work done to assure that future slides do not block the emergency spillway.

The spillway capacity is classified as adequate according to the recommended criteria.

The following recommendations should be implemented immediately or on a continuing basis:

1. The slope adjacent to the emergency spillway should be stabilized to prevent development of a slide which would block the spillway.
2. The wet area located on the downstream slope should be periodically observed to document if a seepage condition is developing. Necessary remedial work should be performed if such conditions develop.
3. An around-the-clock surveillance should be provided during unusually heavy runoff and a formal warning system should be developed to alert the downstream residents in the event of an emergency.

15  
DACW31-79-C-0014

477 004

elt

4. The dam and appurtenant structures should continue to be inspected regularly and necessary maintenance should be performed.



*Lawrence D. Anderson*  
 \_\_\_\_\_  
 Lawrence D. Andersen, P.E.  
 Vice President

*G. K. Withers*  
 \_\_\_\_\_  
 G. K. WITHERS  
 Colonel, Corps of Engineers  
 District Engineer

DATE: 22 Apr 79

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DDC TAB	<input type="checkbox"/>
Unannounced Justification	<input type="checkbox"/>
By _____	
Distribution/	
Availability Codes	
Dist	Avail and/or special
<i>A</i>	

PA-479 DAM  
NDI I.D. NO. PA-509  
DECEMBER 5, 1978



Upstream Face



Downstream Face

## TABLE OF CONTENTS

	<u>PAGE</u>
SECTION 1 - PROJECT INFORMATION	1
1.1 General	1
1.2 Description of Project	1
1.3 Pertinent Data	2
SECTION 2 - DESIGN DATA	4
2.1 Design	4
2.2 Construction	6
2.3 Operation	7
2.4 Other Investigations	7
2.5 Evaluation	7
SECTION 3 - VISUAL INSPECTION	8
3.1 Findings	8
3.2 Evaluation	9
SECTION 4 - OPERATIONAL FEATURES	10
4.1 Procedure	10
4.2 Maintenance of the Dam	10
4.3 Maintenance of Operating Facilities	10
4.4 Warning System	10
4.5 Evaluation	10
SECTION 5 - HYDRAULICS AND HYDROLOGY	11
5.1 Evaluation of Features	11
SECTION 6 - STRUCTURAL STABILITY	12
6.1 Evaluation of Structural Stability	12
SECTION 7 - ASSESSMENT AND RECOMMENDATIONS/PROPOSED REMEDIAL MEASURES	14
7.1 Dam Assessment	14
7.2 Recommendations/Remedial Measures	14

TABLE OF CONTENTS  
(Continued)

PLATES

- APPENDIX A - CHECKLIST, VISUAL INSPECTION, PHASE I
- APPENDIX B - CHECKLIST, ENGINEERING DATA, DESIGN, CONSTRUCTION,  
OPERATION AND HYDROLOGIC AND HYDRAULIC, PHASE I
- APPENDIX C - PHOTOGRAPHS
- APPENDIX D - CALCULATIONS
- APPENDIX E - REGIONAL GEOLOGY

PHASE I REPORT  
NATIONAL DAM INSPECTION PROGRAM  
PA-479 DAM  
NDI I.D. NO. PA-509  
DER I.D. NO. 63-71

SECTION 1  
PROJECT INFORMATION

1.1 General

a. Authority. The inspection was performed pursuant to the authority granted by The National Dam Inspection Act, Public Law 92-367, to the Secretary of the Army, through the Corps of Engineers, to conduct inspections of dams throughout the United States.

b. Purpose. The purpose of this inspection is to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project

a. Dam and Appurtenances. The PA-479 dam is one of the 14 flood control projects in the Harmon Creek watershed. The dam consists of an earth embankment approximately 650 feet long with a maximum height of 63 feet from the downstream toe and a crest width of 14 feet. The flood discharge facilities for the dam consist of a drop inlet primary spillway located near the left abutment (looking downstream) and an emergency spillway, also located on the left abutment. The primary spillway is a drop inlet structure consisting of a two-stage reinforced concrete riser, a 24-inch-diameter reinforced concrete conduit, terminating at a plunge pool near the left abutment at the downstream toe of the dam. The emergency spillway is a trapezoidal earth channel with a base width of 50 feet excavated into the left abutment. The reservoir outlet facilities for the dam consist of a 15-inch steel pipe extending from the upstream toe of the dam to the drop inlet structure. Flow through the reservoir outlet is controlled by a manually operated sluice gate located in the drop inlet structure.

[CONT'D  
ON P. II]

b. Location. The dam is located on an unnamed tributary of Harmon Creek, approximately one mile west of Hanlin Station in Hanover Township, Washington County, Pennsylvania (Plate 1). Downstream from the dam, the stream flows approximately 1000 feet north, under the Penn-Central Railroad, and joins Harmon Creek. The first development below the dam is located approximately one mile downstream from the dam and consists of three farmhouses. Harmon Creek crosses the West Virginia/Pennsylvania state line two miles downstream from the dam.

In this reach, approximately 15 homes are considered to be within the flood plain of Harmon Creek. Further downstream, Harmon Creek flows near the town of Collier and joins the Ohio River at Weirton, West Virginia. It is estimated that failure of the dam would cause large loss of life and property damage along Harmon Creek.

c. Size Classification. Intermediate (based on 63-foot height and 343 acre-feet maximum storage capacity).

d. Hazard Classification. High.

e. Ownership. County of Washington, Pennsylvania (address: Mr. Joseph Geicek, Administrative Assistant, Courthouse, Washington, Pennsylvania 15301).

f. Purpose of Dam. Flood control.

g. Design and Construction History. The dam was designed by the U.S. Department of Agriculture, Soil Conservation Service, during 1967. The dam was constructed by Windy Hill Construction Company of Burgettstown, Pennsylvania, with completion in August 1969.

h. Normal Operating Procedure. The reservoir is normally maintained at Elevation 902.8, the crest level of an orifice on the upstream face of the drop inlet structure. The crest level of the primary spillway is at Elevation 913.5. The crest of the emergency spillway is at Elevation 922.7. Depending on the rate of inflow, the flood would be discharged through the orifice in combination with the primary and emergency spillways.

### 1.3 Pertinent Data

a. Drainage Area - 1.15 square miles

b. Discharge at Dam Site (cfs)

Maximum known flood at dam site - Unknown  
Outlet conduit at maximum pool - 58  
Gated spillway capacity at maximum pool - N/A  
Ungated spillway capacity at maximum pool - 8037  
Total spillway capacity at maximum pool - 8095

c. Elevation (USGS Datum) (feet)

Top of dam - 934.2  
Maximum pool - 934.2  
Upstream invert outlet works - 885.0  
Downstream invert outlet works - 879.2  
Streambed at center line of dam - 877±  
Maximum tailwater - Unknown

d. Reservoir Length (feet)

Normal pool level - 500  
Maximum pool level - 1000+

e. Storage (acre-feet)

Normal pool level - 26 (estimated)  
Maximum pool level - 343

f. Reservoir Surface (acres)

Normal pool level - 4  
Maximum pool level - 18.5

g. Dam

Type - Earth  
Length - 650 feet  
Height - 63 feet  
Top width - 14 feet  
Side slopes - Downstream: 2H:1V; Upstream: 3H:1V  
Zoning - No  
Impervious core - No  
Cutoff - Yes  
Grout curtain - No

h. Regulating Outlet

Type - 15-inch reservoir outlet pipe  
Length - 50+ feet  
Closure - Sluice gate at drop inlet structure  
Access - Drop inlet structure  
Regulating facilities - Sluice gate

i. Spillway

	<u>Primary</u>	<u>Emergency</u>
Type -	Drop inlet	Trapezoidal earth channel
Length -	N/A	50 feet
Crest elevation -	913.5	922.7
Gates -	None	None
Upstream channel -	Lake	Trapezoidal earth channel
Downstream channel -	24-inch outlet conduit	Trapezoidal earth channel

SECTION 2  
DESIGN DATA

2.1 Design

a. Data Available. The available information was provided by the Pennsylvania Department of Environmental Resources (PennDER) and the Soil Conservation Service (SCS).

(1) Hydrology and Hydraulics. The available information consists of principal freeboard and emergency spillway inflow hydrographs and the results of associated flood routings.

(2) Embankment. The available information consists of design drawings, geology and soils reports, laboratory soil test results, and the results of slope stability analyses.

(3) Appurtenant Structures. Available information includes design drawings and design calculations.

b. Design Features

(1) Embankment

a. As designed, the dam (Plate 2) is a homogeneous embankment with a central cutoff trench and a trench drain beneath the downstream slope (Plate 3). The cutoff trench, with a bottom width of 17 feet, was extended 5 to 10 feet below original ground along the valley floor. On the abutments, the width of the cutoff trench was reduced to 12 feet and the depth was approximately 5 feet. A 4-foot-wide, 10- to 15-foot trench filled with granular material located beneath the downstream slope constitutes the internal drainage system for the embankment (Plate 4). The trench drain starts at a level approximately 30 feet below the dam crest level and 40 feet downstream from the center line of the dam near the right abutment and terminates at a filter blanket near the discharge end of the outlet pipe at an elevation approximately 55 feet below the dam crest and 64 feet downstream from the center line of the dam. Over the lower half of its length, the trench drain is equipped with a 12-inch-diameter perforated drainpipe. On the left abutment, the internal drainage system consists of a minimum 2-foot-thick drainage blanket. This drainage blanket

starts at a level approximately 30 feet below the dam crest and 40 feet downstream from the center line of the dam and terminates at the drainage blanket near the downstream end of the outlet pipe.

Two principal borrow materials for the embankment were classified as follows: clayey sands containing 15 percent gravel and 50 percent fines with a liquid limit of 35 percent and plasticity index of 18, and silty clays containing 83 percent fines with liquid limit of 40 percent and plasticity index of 22.

- b. The dam was designed to have a 3 to 1 (horizontal to vertical) slope on the upstream face with an 8-foot-wide bench at elevation 903.3. The downstream face was designed to have a 2 to 1 slope.
- c. The subsurface investigation conducted for the dam consisted of numerous borings and test pits. The locations of these borings are shown in Plate 2. Selected boring logs are illustrated in Plates 5, 6 and 7. The typical subsurface profile (Plate 8) consists of up to 5 feet of medium to stiff sandy clayey silts on the valley slopes and about 10 to 30 feet of alluvium in the valley bottom. The alluvium is classified as medium dense to dense clayey gravels and clayey sands containing 33 to 56 percent gravel. The bedrock at the dam site consists of thin-bedded Birmingham Shale on the abutments and Pittsburgh Red Bed Shale underlying the valley bottom. The shales were separated by 2- to 3-foot-thick layers of Ames Limestone. The permeability of the bedrock varied between 0.1 foot per day and 8.6 feet per day ( $4 \times 10^{-5}$  to  $3 \times 10^{-3}$  ft/sec). In general, the higher permeability rates were encountered in the valley bottom.

(2) Appurtenant Structures. The appurtenant structures of the dam consist of a drop inlet primary spillway and an emergency spillway. The primary spillway structures consist of a single-stage reinforced concrete riser and a 24-inch-diameter reinforced concrete conduit through the embankment, terminating at a plunge pool at the downstream toe of the dam (Plates 9, 10 and 11). A 15-inch-diameter steel pipe from the upstream toe of the dam discharging into the drop inlet structure

constitutes the reservoir outlet facilities. The outlet conduit through the embankment is supported on concrete bedding and is equipped with six reinforced concrete cutoff collars 25 feet on center.

The emergency spillway is a trapezoidal channel excavated into the left abutment. The bottom width of the trapezoidal channel is 50 feet with 2 to 1 side slopes. A 30-foot level section of the channel bottom constitutes the control section of the emergency spillway. The control section is located at Elevation 922.7. The embankment side of the emergency spillway channel is protected with riprap.

c. Design Data

(1) Hydrology and Hydraulics. Available information indicates that the emergency spillway was designed to pass a hydrograph with a peak of 8612 cfs, corresponding to 25.8 inches of precipitation in 6 hours, without overtopping the embankment. This hydrograph was apparently routed through the reservoir starting at normal pool (Elevation 902.8) and producing a maximum pool at Elevation 934.2 with a peak emergency spillway outflow of 8037 cfs. The top of the dam was established at Elevation 934.2.

(2) Embankment. Available information indicates that laboratory tests for the embankment design consisted of classification, compaction, and shear strength tests. Shear strength parameters for the embankment material were obtained from consolidated-undrained triaxial shear tests conducted on samples compacted to 95 percent of maximum Standard Proctor dry density. Total stress strength parameters of two samples were reported. Internal friction angles were 15.5 and 17 degrees and cohesion 500 and 875 psf. It was reported that a slope stability analysis was conducted utilizing modified Swedish circle and modified sliding block analyses. The stability of the downstream slope under steady-state seepage and stability of the upstream slope under rapid drawdown conditions was considered. For steady-state seepage analysis, the pool level was taken at Elevation 922.7, the emergency spillway crest level. The analysis considered a phreatic line from emergency spillway elevation to the trench drain beneath the downstream slope. The minimum computed factor of safety was 1.48 for the downstream slope under a steady-state seepage condition and 1.77 for the upstream slope under rapid drawdown conditions. A stability analysis for the emergency spillway cut indicated a minimum factor of safety of 1.15.

(3) Appurtenant Structures. Available information indicates that the appurtenant structures were standard SCS designs.

2.2 Construction. As-built drawings and construction progress reports prepared by the Commonwealth of Pennsylvania, Department of Environmental Resources were available for review. To the extent that can be determined, the construction of the dam was in conformance with SCS

specifications. No significant construction changes were noted in the embankment design. The dam was constructed under the supervision of an SCS field representative. It is reported that the earthwork was monitored by field density tests. However, the results were not available for review.

It is reported that both during construction and after completion of the dam several landslides occurred on the hillside adjacent to the emergency spillway. The first slide occurred in June 1969 during the excavation of the emergency spillway. Approximately 2000 cubic yards of material was removed from the hillside and the slopes were regraded. The dam was completed in July 1969. The second slide occurred in September 1969; however, the slide did not progress into the emergency spillway channel. In the spring of 1970, additional slides were observed blocking approximately half of the emergency spillway channel. Again, the material was removed and the slopes regraded. A detailed investigation of the condition was undertaken during 1970, including an additional subsurface investigation. The detailed investigation concluded that the permanent solution would be too costly. Therefore, the slide area was to be periodically monitored and necessary maintenance be undertaken as the slides occur.

2.3 Operation. No records of operation are kept.

2.4 Other Investigations. A report entitled, Harmon Creek, PA-479 Slide, dated April 2, 1971, presents the detailed investigation conducted on the emergency spillway stability problem.

2.5 Evaluation

a. Availability. Available information was obtained from SCS and PennDER.

b. Adequacy

(1) Hydrology and Hydraulics. The available information is considered to be adequate to assess the conformity of the design to the current spillway design criteria.

(2) Embankment. Review of the geotechnical aspects of the design indicates that the design generally followed currently accepted practices for subsurface investigation, laboratory testing, and stability analyses.

(3) Appurtenant Structures. Review of the design drawings indicated that the appurtenant structures were designed and constructed in conformance with currently accepted engineering practices. However, concern exists as to the continued stability of the hillside adjacent the emergency spillway, since post-construction engineering studies did not provide a permanent solution to this problem.

SECTION 3  
VISUAL INSPECTION

3.1 Findings

a. General. The on-site inspection of PA-479 dam consisted of:

1. Visual inspection of the embankment, abutments, and embankment toe.
2. Visual examination of the emergency spillway and visual portions of the primary spillway.
3. Observation of factors affecting the runoff potential of the drainage basin.
4. Evaluation of downstream hazard potential.

The specific observations are illustrated in Plate 12 and in the photographs in Appendix C.

b. Embankment. In general, inspection of the embankment consisted of searching for indications of structural distress, such as cracks, subsidence, bulging, wet areas, seeps and boils, and observing general maintenance conditions, vegetative cover, erosion, and other surficial features.

In general, the condition of the dam is considered to be good. Only one wet area was observed on the downstream slope near the left abutment immediately above the outlet works plunge pool. No perceivable seepage was associated with this wet area. The slope adjacent to the emergency spillway was found to be wet and irregular, suggesting a progressing slide.

The top of the dam was surveyed relative to the emergency spillway crest elevation and was found to be within one-half foot of the cambered crest elevation. Irregularities appeared to be caused by truck tracks on the crest.

c. Appurtenant Structures. The appurtenant structures were examined for deterioration or signs of distress and obstructions that would limit flow. In general, the structures were found to be in good condition. No significant deficiencies were noted at this time.

d. Reservoir Area. A map review indicates that the watershed is predominantly covered with reclaimed strip mines. A review of the regional geology (Appendix E) indicates that the slopes of the reservoir are likely to be susceptible to landslides.

e. Downstream Channel. The description of downstream conditions is included in Section 1.2b.

3.2 Evaluation. The dam is considered to be in good condition. The most significant condition at the dam site is the potential instability of the emergency spillway cut, as demonstrated by past problems. This area should be closely examined and necessary remedial work done to assure that future slides do not block the emergency spillway. The wet spot on the downstream slope should also be periodically observed to document if a seepage condition is developing.

SECTION 4  
OPERATIONAL FEATURES

4.1 Procedure. The reservoir is normally maintained at the crest level of the orifice on the drop inlet structure. The reservoir outlet pipe can be used to draw down the permanent pool when required. The reservoir outlet gate is normally closed.

4.2 Maintenance of the Dam. The maintenance of the dam is considered to be satisfactory. The downstream and upstream faces of the dam are covered with grass and crown vetch. Washington County personnel reported that there is no full-time dam tender responsible for the maintenance of the dam. The maintenance is performed by outside contractors on an as-needed basis.

4.3 Maintenance of Operating Facilities. The only operational feature is the reservoir outlet pipe sluice gate operated by a hoist located on the primary spillway drop inlet structure. Since the drop inlet structure was not accessible, this facility could not be closely examined.

4.4 Warning System. No formal warning system exists for the dam. Telephone communication facilities are available via homes approximately one mile east of the dam near the community of Hanlin Station. The site is not considered to be readily accessible during major storms.

4.5 Evaluation. The maintenance condition of the dam is considered to be satisfactory. The dam and appurtenances should continue to be periodically inspected with emphasis on the wet areas on the slope adjacent to the emergency spillway and on the downstream slope of the dam.

SECTION 5  
HYDRAULICS AND HYDROLOGY

5.1 Evaluation of Features

a. Design Data. PA-479 dam has a watershed of 1.15 square miles and impounds a reservoir with a surface area of 4.3 acres at normal pool level. The emergency spillway of the dam is located on the left abutment. The capacity of the emergency spillway is reported to be 8037 cfs with no freeboard.

b. Experience Data. As previously stated, the PA-479 dam is classified as an intermediate size dam in the high hazard category. Under the recommended criteria for evaluating emergency spillway discharge capacity, such impoundments are required to pass full PMF.

The PMF inflow hydrograph for the reservoir was determined using the Dam Safety Version of the HEC-1 computer program, developed by the Hydrologic Engineering Center of the U.S. Army, Corps of Engineers. The data used for the computer input are presented in Appendix D. The PMF inflow hydrograph was found to have a peak flow of 3081 cfs. The computer outputs are also included in Appendix D.

c. Visual Observations. As observed during the inspection and as reported from previous investigations, the potential exists for the emergency spillway to be blocked (completely or partially) by a slope failure above the spillway. Such a failure would be more likely to occur during heavy rainfall conditions requiring discharge through the spillway.

d. Overtopping Potential. The PMF inflow hydrograph was routed through the reservoir, and it was found that the dam can pass the PMF without overtopping. To obtain an upper bound on the maximum pool level during the passage of PMF, the spillway discharge rating was conservatively based on a rectangular cross section, with the base of the rectangle taken equal to the base of the trapezoidal emergency spillway cross section.

e. Spillway Adequacy. The spillway capacity (greater than 100 percent PMF) is classified to be adequate according to the recommended criteria.

SECTION 6  
STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations

(1) Embankment. As discussed in Section 3, the field observations did not reveal any signs of distress that would significantly affect the stability of the embankment. However, it should be noted that since the dam is a flood control facility, it impounds a relatively small reservoir under normal operating conditions relative to its full storage capacity. Therefore, the dam was not subjected to its maximum loading conditions on the date of inspection.

The wet area on the downstream slope is not considered to be significant relative to the overall stability of the embankment at this time.

(2) Appurtenant Structures. Performance of the appurtenant structures is considered to be satisfactory at this time. However, a potential exists for blockage of the emergency spillway with sliding material from the adjacent slope.

b. Design and Construction Data

(1) Embankment. Available information indicates that the stability of the dam was analyzed for steady-state seepage and rapid drawdown conditions using the modified Swedish circle slope stability analysis procedures. The minimum factor of safety was reported to be 1.77 for the steady-state seepage stability of the downstream slope and 1.48 for the rapid drawdown condition of the upstream slope. Strength parameters were obtained from consolidated-undrained triaxial shear tests. Construction progress reports indicate that the dam was constructed under the supervision of an SCS field representative and the earthwork was monitored by field density tests.

(2) Appurtenant Structures. Review of the design drawings indicates that there are no apparent structural deficiencies that would significantly affect the performance of the appurtenant structures other than the potential slope stability problem in the emergency spillway.

c. Operating Records. There are no operating records kept for the dam.

d. Post-Construction Changes. The only post-construction activity reported at the dam site was the excavation of the slide adjacent to the emergency spillway.

e. Seismic Stability. The dam is located in Seismic Zone 1, and based on visual observations, the static stability of the dam is considered to be adequate. Therefore, based on the recommended criteria for the evaluation of seismic stability of dams, the structure is presumed to present no hazard from earthquakes.

SECTION 7  
ASSESSMENT AND RECOMMENDATIONS/PROPOSED REMEDIAL MEASURES

7.1 Dam Assessment

a. Assessment. The visual observations indicate that the PA-479 dam is in good condition. No conditions were observed that would significantly affect the overall performance of the structure at this time. However, as previously noted, the dam was not inspected under its maximum loading condition.

A wet area observed at the downstream face of the dam is not considered to be significant relative to the overall performance of the dam at this time. However, this area should be periodically observed to determine if a seepage condition is developing.

The slope adjacent to the emergency spillway should be stabilized to prevent a slide from developing which would block the spillway.

The capacity of the spillway was found to be adequate according to the recommended criteria.

b. Adequacy of Information. Available information in conjunction with the visual observations and the previous experience of the inspectors are considered to be sufficient to make a reasonable assessment of the condition of the dam.

c. Urgency. The following recommendations should be implemented immediately or on a continuing basis.

d. Necessity for Additional Data. No additional data are considered required at this time.

7.2 Recommendations/Remedial Measures. It is recommended that:

1. The slope adjacent to the emergency spillway should be stabilized to prevent development of a slide which would block the spillway.
2. The wet area located on the downstream slope should be periodically observed to document if a seepage condition is developing. Necessary remedial work should be performed if such conditions develop.
3. An around-the-clock surveillance should be provided during unusually heavy runoff and

a formal warning system should be developed to alert the downstream residents in the event of an emergency.

4. The dam and appurtenant structures should continue to be inspected regularly and necessary maintenance should be performed.


PLATES

DRAWN BY	ACS	CHECKED BY	BC	DATE	2/1/79	DRAWING NUMBER	78-367-B 52
	1-3-79	APPROVED BY	JMP	DATE	3/1/79		



**REFERENCES:**

- U.S.G.S. 7.5' WEIRTON, PA-OHIO QUADRANGLE DATED 1968, SCALE 1:24000
- U.S.G.S. 7.5' BURGETTSTOWN, PA. QUADRANGLE PHOTOREVISED 1969, SCALE 1:24000
- U.S.G.S. 7.5' STEUBENVILLE EAST, W.VA.-PA. QUADRANGLE, DATED 1968, SCALE 1:24000
- U.S.G.S. 7.5' AVELLA, PA. QUADRANGLE PHOTOREVISED 1969, SCALE 1:24000



**KEY PLAN**




PLATE I

PA. 479 DAM  
VICINITY, FLOOD PLAIN & WATERSHED MAP

**D'APPOLONIA**


DRAWING NUMBER 78-367-B53

CHECKED BY *BE* 2/1/77

APPROVED BY *JMP* 3.1.77

DATE 2/1/77

BY *JMP*



EMERGENCY SPILLWAY CURVE DATA  
DOWNSTREAM CURVE


STATION	DEFLECTION	CHORD
PC 5+50.00	0°-00'	—
3+57.85	3°-00'	7.85'
3+65.71	6°-00'	
3+73.56	9°-00'	
3+81.42	12°-00'	
3+89.27	15°-00'	
3+97.12	18°-00'	
3+04.98	21°-00'	
3+12.83	24°-00'	
3+20.69	27°-00'	
PT 6+28.54	30°-00'	

EMERGENCY SPILLWAY CURVE DATA  
UPSTREAM CURVE

STATION	DEFLECTION	CHORD
PC 2+41.58	0°-00'	—
2+49.33	3°-00'	7.85'
2+57.17	6°-00'	
2+65.02	9°-00'	
2+72.88	12°-00'	
2+80.73	15°-00'	
2+88.58	18°-00'	
2+96.44	21°-00'	
3+04.29	24°-00'	
3+12.15	27°-00'	
PT 3+20.00	30°-00'	

CONSTRUCTION NOTES

1. For logs of test holes see shts. 17 thru 20.
2. E Dam - E Cut-off trench
3. Contour interval - 5'
4. For E dam layout see sh. 2.



**'AS BUILT PLANS**

- LEGEND**
- Design high water El 927.0
  - - - Normal pool El 902.8
  - ~~~~~ Stream
  - ▬▬▬▬▬ Blanket drain
  - ▨▨▨▨▨ Rock riprap

**HARMON CREEK WATERSHED  
FLOODWATER RETARDING DAM PA-479  
WASHINGTON COUNTY, PENNSYLVANIA  
PLAN OF STRUCTURAL WORKS**


**U. S. DEPARTMENT OF AGRICULTURE  
SOIL CONSERVATION SERVICE**

DATE 12-67	APPROVED BY DEC 27
DESIGNED BY C. CRISE	DATE 12-67
PA-479-P	

PLATE 2

**D'APPOLONIA**






**CONSTRUCTION NOTES**

- 1 Constructed slopes are 2:1:1 upstream and 1:1:1 downstream
- 2 For constructed fill elevations see sheet 7

ZONE	MATERIAL	MAX. ROCK SIZE	MAX. LIFT THICKNESS	REQUIRED WATER CONTENT	COMPACTION	
					CLASS	DEFINITION
I	Material as represented by TP 102.1, depth 4-5.5' classified as CL; by TP 118.1, depth 15-3' classified as CL.	6"	9"	Optimum +4% 0%	A	95% Max dens. by ASTM D698 Method A

- L1 For fill adjacent to structures, max rock size = 3"
- L2 Maximum permissible lift thickness before compaction
- L3 Water content of fill matrix at time of compaction
- L4 For typical compaction curves, see sheet 21

**AS BUILT PLANS**




**HARMON CREEK WATERSHED**  
 FLOOD WATER RETARDING DAM PA - 479  
 WASHINGTON COUNTY, PENNSYLVANIA  
**FILL PLACEMENT**  
 U. S. DEPARTMENT OF AGRICULTURE  
 SOIL CONSERVATION SERVICE  
*Edward R. ... 11-57*  
 C. CRISK 11-57  
 PA-479-P

PLATE 3


**D'APPOLONIA**

2

DRAWING 78-367-B55  
 NUMBER 3.1.79  
 CHECKED BY BC  
 APPROVED BY JHP  
 ACS 1-4-79  
 DRAWN BY



**PROFILE ALONG E DRAIN TRENCH  
& UPSTREAM EDGE OF BLANKET**




**PLAN VIEW OF DRAINAGE SYSTEM**  
 0 20 40 80  
 SCALE IN FEET

**CONSTRUCTION NOTE.**  
 All drain pipe shall be 12" dia., class I, shape I, type D, 16 gage (material spec. 110)


**QUANTITY SUMMARY.**  
 2 - 12' sections of 12" dia. perf. pipe  
 30 - 10' sections of 12" dia. perf. pipe  
 2 - 10' sections of 12" dia. non-perf. pipe  
 2 - 90° elbows (1' x 1-1/2")  
 2 - End caps  
 2 - Small animal guards details see sht. 16  
 349' - Total

**GRADATION LIMITS FOR DRAIN FILL**


FINE DRAIN FILL		COARSE DRAIN FILL	
Sieve No.	% Passing (based on dry weight)	Sieve No.	% Passing (based on dry weight)
1/2"	100	3"	100
3/8"	94 - 100	1-1/2"	87 - 100
no. 4	82 - 100	1"	83 - 100
no. 8	64 - 94	1/2"	24 - 72
no. 15	42 - 82	3/8"	12 - 63
no. 30	22 - 62	no. 4	0 - 19
no. 50	6 - 38	no. 8	< 5
no. 100	0 - 17		
no. 200	< 3		




**SECTION A-A**




**SECTION B-B**




**SECTION C-C**



**SECTION D-D**



**SECTION E-E**



**TYPICAL SECTION AROUND ALL PERFORATED DRAIN PIPE**

SECTIONS NOT TO SCALE

**AS BUILT PLANS**

HARMON CREEK WATERSHED  
 FLOODWATER RETARDING DAM PA-479  
 WASHINGTON COUNTY, PENNSYLVANIA  
 DRAINAGE DETAILS  
 U. S. DEPARTMENT OF AGRICULTURE  
 SOIL CONSERVATION SERVICE  
 Donald R. Wilby 10/51  
 C. CRUSE 10-67  
 3/1/1957 PA-479-P

PLATE 4

**D'APPOLONIA**

1	2	3	4	5	6	7	8	9	10
---	---	---	---	---	---	---	---	---	----



10-5 Cont'd

SAMPLES			Hole Depth From To	Description of Materials	Type Soil Class	Hit No.	From To	%	
From To	Fe.	Sec.							
0.0	1.5	55	14.5	22.5	Clay shale, gray to gray, easily scratched with fingernail, cored pieces up to 0.5' long, below 1.0' core very highly broken with some broken ones 1.5-1.0', thin bedded. Some vertical fractures, iron staining noted along bedding planes.	X1	14.5	22.5	50
1.5	3.0	70							
3.0	4.5	65	22.5	26.5	Shale-coal, black, easily scratched with fingernail, highly weathered and broken, clay same, limy from 25.0', some iron staining.		22.5	26.5	50
4.5	6.0	80							
6.0	7.5	35	26.5	50.0	Clay shale, gray to gray, red-brown 15.0-16.5', can be scratched with fingernail, core very highly broken with clay strata to 2.0' and in some 16.5 to 15.5'. Below 15.5 core above now broken ones with some clay strata, especially from 11.5-11.0', 5.1-5.0', and 5.2-5.1' and it appears to be less weathered. Core pieces 1.5-1.0' 0.75 to 0.5' long with one piece 1.5' long, rock is thin bedded approx. 0.02" thick, vertical fractures present, iron staining noted to 10.0', some calcite fracture filler, core to 10.0' and 16.5-16.0' and 16.5-16.0' in zone, planes of weakness appear in core horizontally along bedding planes and vertical along small fractures.		26.5	50.0	55
7.5	9.5	50							
9.5	11.5	95							
11.5	13.0	65							
13.0	15.0	55							
15.0	17.0	50							
17.0	18.0	0							
18.0	20.0	55							
20.0	22.0	65							
22.0	24.0	55							
24.0	26.0	40							
26.0	28.0	55							
28.0	30.0	55							
30.0	32.0	15							
32.0	34.0	35							
34.0	36.0	40							
36.0	37.0	80							
37.0	40.5	75							
40.5	45.5	90							

10-5, FLY, 8th, 5, 10th, Containing  
 Logged by: G. C. Ripley 7/27/66  
 Drilling Equipment: Sverdrup - Homewood

SAMPLES			Hole Depth From To	Description of Materials	Inf. Soil Class	Type Hit No.	From To	%		
From To	Fe.	Sec.								
0.0	0.5		0.0	0.5	Forest litter, roots, etc.	Spl	1	0.0	2.0	15
0.5	2.0		0.5	2.0	Clay, sandy, brown, moist, trace of gravel, 20' sand, fines are moderately plastic, grades into OC below.	Cl	2	0.5	2.0	50
2.0	3.5		2.0	3.5	Gravel, sand with clay, brown, wet, trace of cobbles, 40' gravel, 25' sand, 30' plastic fines, coarse particles are sub-round and fairly well-sorted sandstone.			2.0	3.5	70
3.5	10.2		3.5	10.2	Shale, clay, med. to dk. gray, can be scratched with fingers (some easily scratched), some zones are limy. Core highly broken with clay strata. Pieces up to 0.25' long, core contains vertical fractures with iron staining.			3.5	10.2	100
10.2	12.0		10.2	12.0	Limestone, (Lima Formation), lt. gray, can be scratched with knife, cored pieces up to 0.5' long, fossiliferous.			10.2	12.0	60
12.0	25.0		12.0	25.0	Clay-shale, gray to gray, red-gray from 1.5' to 21.0', can be barely scratched with knife, limy, contains clay strata, some vertical fractures, no iron staining noted this section, cored pieces up to 0.7' long, some broken on a slant core to 22.0', below 22.0' core fine fairly well top-dog.			12.0	25.0	50
25.0			25.0		Bottom of hole - wet hole Wt. (22/66) 1.5'			25.0		

10-7, FLY, 8th, 5, 10th, Containing  
 Logged by: G. C. Ripley 7/26/66  
 Drilling Equipment: Sverdrup - Homewood

SAMPLES			Hole Depth From To	Description of Materials	Inf. Soil Class	Type Hit No.	From To	%		
From To	Fe.	Sec.								
0.0	5.0		0.0	5.0	Estimated to be similar to 10-5, 0.0' to 1.5', clay, sand with gravel, red-brown, 10' gravel, 25' sand, 65' plastic fines.	Cl	1	0.0	12.5	50
5.0	23.0		5.0	23.0	Estimated to be similar to 10-5, 2.5 to 21.5' and 10-5, 0.5 to 11.0', sand, clay with gravel, moist and wet, brown, 20' gravel, 45' sand, 15' cobbles and 30' plastic fines, Spt sample 12.5 to 11.0' confirm estimate.	SC	X1	5.0	23.0	50

Continued

See note, 10-21

**HARMON CREEK WATERSHED**  
 FLOODWATER RETARDING DAM PA-419  
 WASHINGTON COUNTY, PENNSYLVANIA  
**LOGS OF DRILL HOLES AND TEST PITS**

**U. S. DEPARTMENT OF AGRICULTURE**  
**SOIL CONSERVATION SERVICE**

Designed by: R. M. Hines Date: 6-67  
 Drawn by: \_\_\_\_\_  
 Title: \_\_\_\_\_  
 Checked by: \_\_\_\_\_  
 PA-479-P

PLATE 5

**D'APPOLONIA**

DRAWING 78-367-B57  
 NUMBER 3/1/99  
 CHECKED BY JSE  
 APPROVED BY JMD  
 1-4-79  
 DRAWN BY

**MI 7 Core'd**  
 21.0 40.0 Highly weathered bedrock, clay with sand and gravel, gry, wet. Thin black coal-shale noted in wash water of 23.0'.  
 30.0 6.0 Clay shale, grn-gry, very highly weathered, easily scratched with fingernail, limy, clay strata, very poor recovery.  
 36.0 42.0 Clay stone, med. gry, some red-gry, 1.3 to 2.0', can be scratched with knife, cored pieces up to 0.7' long, below 38.5' core fits fairly well together with some breaks and clayey zones, some iron staining to 37.5', some clay strata.  
 42.0 Bottom of hole - wet hole  
 WL (7/22/66) 17.6'

**MI 101. ELEV. 885.7, 644'. Centerline**  
 Logged by: R. G. Hirniasey 8/30/66  
 Drilling Equipment: Sargus & Hammond M.C.

Hole Depth From To	Description of Materials	Unif. Soil Class	STANDARD PENETRATION			SAMPLES		
			Blows Per 6"	Type	Used No.	From To	Fe. Hrs.	
0.0 0.4	Forest litter, roots, etc.	CL	3-5-10	Spt	1	Jan	0.0 1.5	85
0.4 3.1	Clay, sand with gravel, brn, moist, average composition, 1% gravel, 20% sand, fines are plastic, trace of small cobbles, percent of gravel ranges from trace to 25%, coarse particles are moderately durable with some nondurable.	CL	3-6-9	"	2	"	1.5 3.0	85
			5-6-12	"	3	"	3.0 4.5	85
			2-3-5	"	4	"	4.5 6.0	80
			3-7	"	5	"	6.0 7.5	80
			3-6	"	6	"	7.5 9.0	25
			6-100	"	7	"	9.0 10.0	80
7.1 9.4	sand, gravel with clay, grn, wet, 30% gravel, 35% sand, fines are plastic, coarse particles are fairly well graded and moderately durable.	SC					10.0 11.0	70
							11.0 12.0	100
							12.0 17.0	40
							17.0 21.0	85
							21.0 26.0	100
							26.0 30.5	90
							30.5 34.5	70
							34.5 38.5	100
0.0 14.0	Limestone (Ams formation), lt. gry, can be scratched with knife, fossiliferous. Contains clay and coal seams, core is highly broken to 11.0', pieces up to 0.4' long, clay strata up to 0.2' long.							
14.0 38.5	Clay shale, lt. to med. gry, 14.0-17.5' and 22.3-25.0', red-brn to grn-gry remainder of core, limy, conglomerate with sand and gravel size inclusions, core contained clay strata and highly broken - cores, below 30.5' core fits fairly well together, slicken sides noted at 26.0' dipping 50% from horizontal, cored pieces up to 0.5' long, core can be easily scratched with knife.							
	Setting of hole - wet hole WL (7/2/66) 5.5' WL (9/7/66) 2.6'							

**MI 102. ELEV. 881.3, 645. 130' D.S.**  
 Logged by: R. G. Hirniasey 9/7/66  
 Drilling Equipment: Sargus & Hammond M.C.

Hole Depth From To	Description of Materials	Unif. Soil Class	STANDARD PENETRATION			SAMPLES		
			Blows Per 6"	Type	Used No.	From To	Fe. Hrs.	
0.0 0.3	Forest litter, roots		2-3-4	Spt	1	Jan	0.0 1.5	55
0.3 3.4	gravel, sand with clay and cobbles, brn, moist to wet, average, 15% cobbles, 35% gravel, 25% sand, 25% plastic fines, coarse particles are thin and platy.	GC	5-3-2	"	3	"	3.0 4.5	100
			12-20-70	"	"	"	4.5 6.0	100
							6.0 8.0	70
3.4 5.4	Clay, gravel with sand, brn, wet, 20% gravel, 20% sand, fines are plastic, coarse particles are thin and platy.	CL						
5.4 9.0	Limestone, from 5.4' to 6.0' highly weathered to CL with trace of fine gravel and 20% sand, fines are plastic, from 6.0 to 8.0' limestone, lt. gry, limy, can be scratched with fingernail, cored pieces up to 0.15' long with numerous gravel size pieces.							
9.0	Bottom of hole - wet hole WL (9/7/66) 2.5'							

**MI 103. ELEV. 887.7, 645. 75' D.S.**  
 Logged by: R. G. Hirniasey 9/2/66  
 Drilling Equipment: Sargus & Hammond M.C.

Hole Depth From To	Description of Materials	Unif. Soil Class	STANDARD PENETRATION			SAMPLES		
			Blows Per 6"	Type	Used No.	From To	Fe. Hrs.	
0.0 0.5	Forest litter, roots, etc.		1-2-2	Spt	1	Jan	0.0 1.5	55
0.5 2.5	Clay, sand, brn to gry, moist to wet, trace of gravel, 20% fine sand, fines are plastic.	CL	4-2-3	"	2	"	1.5 3.0	45
			5-7-10	"	3	"	3.0 4.5	80
			5-7-100	"	4	"	4.5 6.0	100
							6.0 8.0	55
2.5 4.8	Sand, gravel with clay and cobbles, brn, wet, 10% cobbles, 25% gravel, 3% sand, 30% plastic fines.	SC						
4.8 6.0	Clay, sand with gravel, brn to gry, wet, 10% gravel, 25% sand, fines are plastic, coarse particles are shale.	CL						
6.0 8.0	Shale, gry to grn-gry, wet, can be scratched with fingernail, core piece up to 0.025' long with numerous gravel size pieces, contains flat smooth bedding planes, bedrock appears to be fine at 7.95'. limy.							
8.0	Bottom of pit - wet WL (9/7/66) 2.2'							

**TP 801. ELEV. 884.5, 4480. 125' D.S.**  
 0.0 0.4 Topsoil, roots, etc.  
 0.4 2.5 Clay, sand with gravel, red-brn, moist, 10% fine gravel, 15% sand, fines are plastic.  
 2.5 5.0 Gravel, sand with clay, red-brn, moist, wet from approx. 1.5', very slight seepage evident, trace of cobbles, 35% gravel, 20% sand, 40% plastic fines, coarse particles are thin and platy sandstone particles, moderately durable, sandstone can be scratched with knife, this material graded into SC below  
 5.0 9.5 Sand, gravel with clay, red-brn, wet, slight seepage noted from this horizon, fines noted grading from 40 to 30% 5.0 to 6.0' fines are plastic, trace of sandstone cobbles, 20% gravel, 40% sand, coarse particles thin and platy sandstone and shale, gravel particles are fine to med. with some large, particles are nondurable with some moderately durable.  
 9.5 Bottom of pit - wet WL (7/22/66) 5.5' WL (7/25/66) 8.0'

**TP 802. ELEV. 890.5, 4480. 115' D.S.**  
 0.0 0.5 Topsoil, roots, etc. with some forest litter.  
 0.5 8.0 Gravel, sand with clay and cobbles, red-brn, moist 0.5 to 5.5', coarse of cobbles 45% gravel, 20% sand, fines are plastic coarse particles are thin and platy moderately durable sandstone with some nondurable shale, 5.5 to 8.0' wet, with lenses of platy cobbles, cobbles about 15% thin Lenses 0.1' thick of CL containing 85% plastic fines noted between and this material grades into SC proportionate at 8.0'.  
 8.0 10.5 Sand, clay with gravel, red-brn, wet, slow seepage noted in this horizon. Trace of sandstone cobbles (3-6'), 25% gravel, 40% sand, 30% plastic gravel particles fine to med. with some large coarse particles thin and platy nondurable shale and sandstone.  
 10.5 Bottom of pit - wet

**TP 803. ELEV. 891.4, 3555. 115' D.S.**  
 0.0 0.5 Topsoil, forest litter, roots, etc.  
 0.5 3.0 Clay, sand with gravel, brn, slightly moist, 10% gravel, 15% sand, fines are plastic.  
 3.0 6.5 Gravel, clay with sand, red-brn, moist, trace of small cobbles, 35% gravel, 20% sand, 40% plastic fines, coarse particles are moderately durable thin and platy sandstone with some shale, cobbles in this horizon.  
 6.5 10.5 Sand, clay with gravel, red-brn, moist, appears SC to be wet below 8.0', trace of platy cobbles, 20% gravel, 20% sand, 45% plastic fines, coarse thin and platy, nondurable with some moderately durable, gravel is fine to med. with some large, no seepage noted into pit.  
 10.5 Bottom of pit - wet

**TP 101. ELEV. 937.1, 1480. 100' D.S.**  
 0.0 0.5 Heavy brush litter, roots with some small blocky boulders, sandstone  
 0.5 5.5 Clay, sand with gravel, brn, moist, 25 sand, 20 gravel, 55 plastic fines, (average composition). Coarse particles are platy and in random orientation, particles are nondurable shale with some sandstone (highly weathered)  
 5.5 6.4 Clay, sandy, red, moist, 15% fine sand, fines are plastic  
 6.4 10.5 Shale, highly weathered, calcareous to platy gravel size pieces, shale thin bedded and ranges from grn-gry to red, particles are nondurable, readily breaks along cleavage and bedding planes.  
 10.5 Bottom of pit - dry

**TP 102. ELEV. 921.6, 1480. 100' D.S.**  
 0.0 0.5 Topsoil, forest litter, roots, etc.  
 0.5 12.0 Clay, sand with gravel, brn, moist, 20% gravel, 50% 15 sand, fines are plastic, coarse particles are platy and nondurable shale with some sandstone, calcareous sandstone, material contains some coal particles.  
 12.0 Bottom of pit - dry

**TP 103. ELEV. 950.5, 0-20. 100' D.S.**  
 0.0 0.5 Forest litter, roots with a few small sandstone boulders.  
 0.5 11.0 Clay, gravel with sand, brn with some red 3 to 4', moist, average comp. 20 gravel, 1% sand, fines are plastic, coarse particles are thin and platy nondurable shale with some sandstone, trace of small cobbles and boulders, sandstone is moderately durable, cobbles found in thin lenses test pit, material contains some coal particles.  
 11.0 Bottom of pit - dry WL (7/22/66) 10.0'

**TP 104. ELEV. 981.0, 0-20. 500' D.S.**  
 0.0 0.5 Topsoil, roots, etc., some small boulders noted.  
 0.5 6.0 Clay, gravel with sand, brn to red, moist, trace of small sandstone and shale with some sandstone, coarse particles are thin and broken with fingernail, material contains some coal particles.  
 6.0 7.5 Gravel, sand with clay, red to gry, wet from 7.0', highly weathered shale bedrock containing 30 plastic fines, shale particles are thin and platy, easily broken with fingernail, nondurable.  
 7.5 12.5 Gravel with sand, red to gry, wet, highly weathered shale bedrock, sand readily along bedding and cleavage planes, particles are nondurable, can be scratched with fingernail.  
 12.5 Bottom of pit - wet WL (7/22/66) 8.0'

SEE NOTE: TEST PITS ARE TO BE MADE OF 1" DIA. 17" DEEP

**TP 105. ELEV. 928.8. 0-20. 1100' U.S.**

0.0 1.0 Forest litter, roots with cedar C1 and GP fill  
 1.0 11.0 Clay, gravel with sand, cobbles and boulders, red-brn to yellow-brn, moist, appears to be wet below 8.0', boulder, sandstone, highly weathered noted from 1.0 to 5.5', average composition, 10 small boulders, trace of s-all sandstone cobbles, 20 gravel, 10 sand, fines are plastic, one lens of SC containing "C" fines noted along test pit, some coal particles found in this material.  
 11.0 Bottom of pit - dry ML (7/22/66) dry

**TP 106. ELEV. 900.1. 0-40. 300' U.S.**

0.0 0.5 Topsoil with some forest litter, roots, etc.  
 0.5 4.5 Gravel, sand with clay, red-brn, slightly moist to 4.0, moist from 4.0, average composition, trace of cobbles, 15 gravel, 20 sand, fines are plastic, coarse particles thin and platy sandstone with some shale, fine and sand portion of material increases to CL proportions at 4.5', some coal particles within material.  
 4.5 10.5 Clay, sand with gravel, red-brn, moist, appears to be wet from 7.0', no seepage into pit, trace of small cobbles, 15 fine to med. gravel, 30 sand, fines are plastic, coarse particles are thin and platy and nondurable.  
 10.5 Bottom of pit - wet M (7/22/66) dry

**TP 107. ELEV. 903.9. 1-20. 500' U.S.**

0.0 0.5 Topsoil, roots with some forest litter.  
 0.5 10.0 Clay, gravel, sand with cobbles and boulders, red-brn, slightly moist to 3.0', moist 3.0 to 6.5', wet 6.5 to bottom of hole, average composition for entire hole, trace of boulders, 10 cobbles, 25 gravel, 15 sand, fines are plastic, below 8.0' pit contained 10 small boulders and 15 small cobble-sandstone, with lenses of CL with 45% fines and -C  
 10.0 Bottom of hole - wet ML (7/22/66) 7.5'

**TP 108. ELEV. 910.7. 5-80. 700' U.S.**

0.0 0.5 Forest litter, roots, etc.  
 0.5 5.0 Clay, gravel and sand, red, brn, slightly moist to 1.5', moist below 1.5' average composition, 15 gravel, 15 sand, fines are plastic, gravel is fine to med.  
 5.0 11.0 Clay, sand and gravel with cobbles, red-brn with some black, moist, appears to be wet below 8.0', trace of sandstone cobbles, cobbles are thin and platy, 25 sand, 20 gravel, fines are plastic, below 8.0' fines decrease to 45% (SC proportions) and gravel is fine to med. Some 0.5' lenses of CL with organic inclusions are found below 8.0', cobbles are found in thin lenses, coarse particles are moderately durable with some nondurable, no seepage noted in test pit.  
 11.0 Bottom of pit - dry

**TP 109. ELEV. 926.2. 5-20. 700' U.S.**

0.0 0.3 Forest litter  
 0.3 10.0 Shale, highly weathered, olive to red-brn, readily breaks along bedding and joint and cleavage planes into fine to med. gravel size pieces, trace of clay present, shale is easily scratched with fingernail and pieces are nondurable.  
 10.0 Bottom of pit - dry

**TP 110. ELEV. 924.2. 1-20. 900' U.S.**

0.0 0.5 Topsoil, roots, etc.  
 0.5 10.0 Clay, sand with gravel, brn to red-brn and yellow-brn; blue-gray 1.0-10.0', moist, thin lenses of platy shale cobbles at 4.0', a few small cobbles noted within material, average matrix, 10 gravel, 15 sand, fines are plastic, coarse particles are nondurable, soil is liny from 1.0 to 6.0'.  
 10.0 Bottom of pit - dry

**TP 111. ELEV. 925.0. 1-30. 1100' U.S.**

0.0 0.5 Forest litter, roots, etc.  
 0.5 2.5 Clay, gravel with sand, brn, slightly moist, 15 gravel, 15 sand, fines are plastic.  
 2.5 5.5 Gravel, sand with clay, red-brn to yellow-brn, moist, trace of small cobbles, 30 gravel, 20 sand, 45 plastic fines, coarse particles are thin and platy and angular, random orientation, particles are sandstone, nondurable.  
 5.5 8.0 Clay, gravel with sand, red-brn to yellow-brn, moist, 15 gravel, 15 sand, fines are plastic, coarse particles are sandstone and slate, large blocky sandstone boulder 6.0-6.5', coarse particles are nondurable.  
 8.0 Bottom of hole - wet M (7/22/66) 7.2'

**TP 112. ELEV. 1011.6. 5-80. 1100' U.S.**

0.0 0.5 Forest litter, roots, etc.  
 0.5 5.0 Clay with gravel and sand, red and yellow-brn, moist, 10 nondurable sand, 15 gravel, fines are plastic, highly weathered bedrock.  
 5.0 10.5 Silt with gravel and sand, red and yellow-brn with some lt. gray, lmy, highly weathered siltstone bedrock with about 75 low plastic fines, coarse particles appear in thin beds through material.  
 10.5 Bottom of pit - dry

See note, see 21  
 Unified classification by laboratory analysis

<b>HARMON CREEK WATERSHED</b> FLOODWATER RETARDING DAM PA-479 WASHINGTON COUNTY, PENNSYLVANIA <b>LOGS OF DRILL HOLES AND TEST PITS</b>	
<b>U. S. DEPARTMENT OF AGRICULTURE</b> <b>SOIL CONSERVATION SERVICE</b>	
Date Designed R. Harperry 1-67	Approved by Title Date
Drawn Titled	Checked PA-479-P

DRAWN BY ACS CHECKED BY BE 3/1/73 APPROVED BY JHP 3.1.73 NUMBER 78-367-B58

**TP 113. ELEV. 971.5. 2+80. 1100' U.S.**

0.0 0.5 Forest litter, roots, etc.  
 0.3 2.5 Clay, gravel with sand, brn, slightly moist, 20% gravel, 15' sand, fines are plastic, coarse particles are thin and platy sandstone.  
 2.5 6.0 Clay with gravel and sand, red-brn, with yellow and grey mottling, 10' gravel, 10' sand, fines are plastic, coarse particles are nondurable siltstone, highly weathered siltstone bedrock?  
 6.0 8.5 Clay with gravel and sand, red-brn with yellow and grey mottling, 20' fine gravel, 25' sand, fines are plastic, coarse particles are nondurable siltstone particles, highly weathered siltstone bedrock?  
 8.5 Bottom of pit - dry

**TP 114. ELEV. 949.2. 2+80. 700' U.S.**

0.0 0.8 Swamp muck, roots, etc. - wet  
 0.8 5.5 Gravel, clay with sand and cobbles and boulders, brn, wet, 10' small boulders, 15' cobbles (1-6"), 15' gravel, 20' sand, 50 plastic fines, coarse particles are thin and platy, angular, sandstone, moderately durable to durable.  
 5.5 Bottom of pit - wet hole - Swamp conditions noted immediately upstream from treat pit, between small streams

**TP 115. ELEV. 891.2. 5+80. 300' U.S.**

0.0 0.5 Forest litter, roots, etc.  
 0.5 5.0 Silt, gravel with sand, brn, slightly moist to 3.5', moist from 3.5 to 5.0', 20' gravel, 15' sand, fines are nonplastic  
 5.0 9.5 Gravel, sand with clay, cobbles and boulders, brn, wet below 6.0', moderate seepage into pit, 10' small boulders, 15' small cobbles, 30' gravel, 20' sand, 30' plastic fines, coarse particles are thin and platy, moderately durable with some durable, gravel and sand size pieces show evidence of rounding, some coal particles are present.  
 9.5 Bottom of pit - wet hole. WC (7/22/66) 5.0'

**TP 116. ELEV. 897.3. 5+80. 500' U.S.**

0.0 0.5 Forest litter, roots, etc.  
 0.5 2.5 Silt, gravel with sand, brn, moist, 20' gravel, 15' sand, fines are nonplastic, coarse particles are platy and moderately durable.  
 2.5 8.5 Gravel, clay with sand and cobbles, brn, wet below 3.0', trace of small boulders, 15' cobbles (1/2 over 6"), 10' gravel, 20' sand, 30' plastic fines, coarse particles are thin and platy sandstone, moderately durable, some rounding evident on gravel and sand size particles, moderate seepage into pit. Some black organic deposits were found around some boulders and cobbles, some coal particles are present.  
 8.5 Bottom of pit - wet hole. WC (7/22/66) 4.0'

**TP 117. ELEV. 910.6. 7+80. 700' U.S.**

0.0 0.5 Forest litter, roots, etc.  
 0.5 9.5 Gravel, sand with clay, cobbles, red-brn, slightly moist to 2.0', moist from 2.0' to bottom of pit, trace of boulders, 10' cobbles (1/2 over 6"), 10' gravel, 20% sand, 35' plastic fines, material variable along pit, the above is an average composition, cobbles and boulders are found in thin lenses, coarse particles are thin and platy sandstone moderately durable with some durable. Some black organic deposits were found around some cobbles and boulders. Some coal present.  
 9.5 Bottom of pit - dry hole.

**TP 118. ELEV. 907.2. 7+80. 500' U.S.**

0.0 0.5 Forest litter, roots, etc.  
 0.3 0.0 Clay with gravel and sand, red-brn with some yellow mottling, moist, 10' gravel, 15' sand, fines are plastic, coarse particles are platy, thin, and nondurable shale with some sandstone.  
 6.0 7.5 Gravel, cobbles with sand, boulders and clay, red-brn, wet below 6.5', moderate seepage into pit, approx. 10' boulders, 30' cobbles (1/2 over 6") 25' gravel, 15' sand, 20' plastic fines, coarse particles are sandstone, platy, moderately durable with some durable.  
 9.5 Sample - 1 L Bag from 1.5 to 3.0'  
 Bottom of pit - wet hole. WC (7/22/66) 3.5'

**TP 119. ELEV. 935.5. 7+80. 300' U.S.**

0.0 0.5 Forest litter, roots, etc.  
 0.5 6.3 Clay with gravel and sand, red-brn with yellow mottling, moist, 15' gravel, 15' sand, fines are plastic, coarse particles are nondurable shale, easily scratched with fingernail, a few sandstone cobbles noted.  
 6.8 10.0 Siltstone, grn-gry to red-brn, moist, barely scratched with fingernail, moderately durable, bedrock highly weathered and excavated as gravel size pieces, breaking along bedding and joint planes.  
 10.0 Bottom of pit - dry hole.

**TP 120. ELEV. 921.0. 7+80. 700' U.S.**

0.0 0.5 Forest litter, roots, etc.  
 0.5 10.0 Clay gravel with sand and cobbles, red-brn with some yellow and black mottling. Clay moist, trace of boulders, 10' cobbles (1/2 over 6"), cobbles and boulders, durable sandstone, 15' gravel, 10' sand, fines are plastic, coarse particles are sandstone and siltstone, cobbles occur in lenses within material.  
 10.0 Bottom of pit - dry hole.

**TP 121. ELEV. 1016.6. 9+80. 300' U.S.**

0.0 0.4 Forest litter, roots, etc.  
 0.4 2.0 Clay with sand, red-brn, slightly moist, trace of gravel, 15' sand, fines are plastic.  
 2.0 6.0 Siltstone, silt to very fine grained sand size particles, moderately durable particles, grn-gry, moist, excavates as gravel with small cobbles and sand containing some thin clay seams, can be barely scratched with fingernail.  
 6.0 Bottom of pit - dry hole.

**TP 122. ELEV. 947.9. 11+80. 1100' U.S.**

0.0 0.5 Forest litter.  
 0.5 5.5 Clay, gravel with sand, brn, slightly moist, 20% gravel, 15' sand, plastic, coarse particles are platy sandstone, moderately durable, small cobbles in material and some coal noted.  
 5.5 9.0 Clay, sand, red-brn, moist, trace of gravel, 10' fine sand, fines are coarse particles are nondurable.  
 9.0 Bottom of pit - dry hole.

**TP 123. ELEV. 979.0. 7+80. 1100' U.S.**

0.0 0.4 Topsoil, roots, etc.  
 0.4 7.5 Clay, sandy; red-brn to 7.0', grn-gry below 7.0', moist, trace of 20' fine sand, fines are plastic, coarse particles are nondurable, plastic fines are plastic, 15' below 5.5'.  
 7.5 Bottom of pit - dry hole.

**TP 124. ELEV. 918.1. 7+80. 700' U.S.**

0.0 0.5 Forest litter, roots, etc.  
 0.5 6.0 Clay, sand with gravel, red-brn to yellow, moist, average composition 25' fine to sand, gravel, 20' sand, fines are plastic, coarse particles are nondurable siltstone, coarse particles increase 2.0 to 5.0'.  
 6.0 7.5 Clay, sandy, dk. red-brn, wet below 6.5', trace of gravel, 20' sand, are plastic, coarse particles are nondurable, very slight seepage into pit.  
 7.5 10.0 Siltstone, bedrock, brn to grn-gry, wet, 7.5 to 8.5' excavates as GC 15' plastic fines and 35' sand, from 8.5 to 10.0' material excavated as with 5 plastic fines. Coarse particles are nondurable, easily scratched and broken with fingernail.  
 10.0 Bottom of pit - wet hole. Hole appears dry, little or no seepage present.

**TP 125. ELEV. 921.0. 7+80. 700' U.S.**

0.0 0.5 Forest litter, roots, etc.  
 0.5 3.5 Gravel, clay with sand, brn, slightly moist, 20' gravel, 25% sand, 45' plastic fines, coarse particles are platy, moderate to nondurable. Coal some coal particles.  
 3.5 9.5 Clay, gravel with sand, red-brn, moist, 15' gravel, 20' sand, fines are plastic, coarse particles are nondurable, contain thin beds of sandstone with small cobble size pieces. Sandstone is moderately durable.  
 9.5 Bottom of pit - dry hole.

**TP 126. ELEV. 922.8. 11+80. 700' U.S.**

0.0 0.5 Forest litter, roots, etc.  
 0.5 10.0 Sand, gravel, clay with cobbles, brn, wet below 3.4', moderate seepage into pit, trace of large boulders, 15' cobbles (1/2 over 6"), 25' gravel, 30' sand, 25' plastic fines, coarse particles are shale and sandstone, thin platy and in random orientation, particles are moderate to nondurable.  
 10.0 Bottom of pit - wet hole, pit collapsing.

**TP 201. ELEV. 937.0. 9+10. 100' U.S.**

0.0 0.5 Forest litter, roots, some cobbles.  
 0.5 6.0 Gravel, clay with sand, brn, slightly moist, 10' gravel, 10' sand, fines are plastic, coarse particles are shale and sandstone, thin platy and in random orientation, particles are moderate to nondurable.  
 6.0 9.0 Siltstone, olive with some yellow and grey, moist, scratched with fingernail to moderately durable, readily breaks along bedding and cleavage planes to gravel and sand size particles.  
 9.0 Bottom of pit - dry hole.

**TP 202. ELEV. 940.8. 8+30. 50' U.S.**

0.0 0.5 Forest litter, roots, etc.  
 0.5 9.5 Clay with gravel and sand, red-brn with some yellow mottling to 7.0', red-brn from 7.0-7.5', moist, a few sandstone cobbles noted, 20' gravel, sand, fines are plastic, from 7.0-7.5' gravel decreases to 10%. Coarse particles are platy, nondurable shale with some sandstone, material is GC  
 9.5 Bottom of pit - dry hole.

**TP 203. ELEV. 925.7. 7+0. 60' U.S.**

0.0 0.5 Forest litter, roots, etc.  
 0.5 5.5 Clay with sand and gravel, red-brn with some yellow and brn mottling, moist, 10' gravel, 10' sand, fines are plastic, coarse particles are nondurable siltstone, material is compact, a few small sandstone cobbles noted to 3.0', material graded into recognizable siltstone bedrock at 3.5'.  
 5.5 10.0 Siltstone, olive, moist, bedrock highly weathered and breaks readily into sandstone and gravel size pieces, from 5.5 to 8.5' siltstone breaks down to GC material with about 20 plastic fines. From 8.0 to 10.0' material excavates as GC. Bedrock breaks readily along thin bedding planes and cleavage planes. GC material contains up to GC sand and grades into GC.  
 10.0 Bottom of pit - wet hole.

**TP 204. ELEV. 958.7. 7+50. 60' U.S.**

0.0 0.5 Forest litter, roots, etc.  
 0.5 9.5 Clay, gravel with sand, red-brn with some yellow, moist, average composition 15' gravel, 10' sand, fines are plastic, coarse particles are nondurable siltstone, thin bed of sandstone cobble size pieces at 5.5'. Percent of coarse particles increase with depth of pit from a trace of gravel to 20' gravel 8.0-8.5'.  
 9.5 Bottom of pit - dry

SAMPLES		From	To		
No.	Type	ft.	ft.	PK.	Rec.
		0.5	1.5		
		1 L Bag			

SAMPLES		From	To		
No.	Type	ft.	ft.	PK.	Rec.
		1	3 L		
		1 L Bag			

H. 205, ELEV. 841.8, 845.5, Centerline  
 Logged by: R. C. Hirshey 1/2/66  
 Drilling Equipment: Sargent & Lundy "X"

From To	Description of Materials	Soil Class	STANDARD PENETRATION				SAMPLE	
			Blows	Pen. C	Type	From To	Depth	
0.0 0.4	Forest litter, roots, etc.		1-7-7		Sp	1	0.0 2.0	85
0.4 2.0	Clay, sand, brn, moist, trace of cobbles, trace of gravel, 20 sand, fines are plastic, coarse particles are nondurable	CL	1-16-16-15			2	2.0 4.0	55
			12-11-11			3	4.0 6.0	70
			1-7-11			4	6.0 8.0	100
			12-1-1-1			5	8.0 10.0	70
2.0 6.5	Clay, sand with gravel, brn to red-brn, moist, 15 gravel, 25 sand, fines are plastic, contains approx. 10 small cobbles, coarse particles are nondurable	CL	31-71		Trl.	6	10.0 11.2	70
					Trl.		11.2 12.4	70
					Trl.		12.4 15.6	25
6.5 9.0	Clay, sand with gravel, red-brn, moist, 20 gravel, 20 sand, fines are plastic, coarse particles are thin and platy and nondurable	CL					15.6 21.8	100
							21.8 26.0	5
9.0 13.5	Sand, clay with gravel, brn and red-brn below 10', 25 gravel, 15 sand, fines are plastic, contains from a trace to 10 cobbles, contains some highly weathered coal particles. Coarse particles are moderate and nondurable	CL						
13.5 26.0	Clay, shale, red-gry to gry, thin bedded, cored pieces .05 to 0.1' long, core breaks readily along smooth horizontal bedding planes, core fit fairly well together with some broken conch, some vertical fractures noted with some iron staining, very thin clay strata noted. Clay not-d 0.1' thick at 25.0'. Core can be scratched with fingernail (core easily scratched from 24.3 to 25.1').	CL						
26.0	bottom of hole - wet hole							

H. 206, ELEV. 846.3, 846.75, S.S.  
 Logged by: R. C. Hirshey 1/2/66  
 Drilling Equipment: Sargent & Lundy "X"

From To	Description of Materials	Soil Class	STANDARD PENETRATION				SAMPLE	
			Blows	Pen. C	Type	From To	Depth	
0.0 0.5	Forest litter, roots, etc.		4-6-6-6		Sp	1	0.0 2.0	85
0.5 2.0	Clay, sand with gravel, brn, moist, 10 fine gravel, 20 sand, fines are plastic.	CL	7-18-18-18			2	2.0 4.0	55
			8-8-10-10			3	4.0 6.0	70
			10-11-10-21			4	6.0 8.0	100
			8-10-1-16			5	8.0 10.0	60
			10-10-12-1			6	10.0 12.0	25
2.0 4.5	Clay, gravel with sand, brn to red-brn, moist, 10 small cobbles, 15 gravel, 25 sand, fines are plastic, cobbles are moderately durable and gravel is nondurable shale.	CL	11-17-70		Sp	7	12.0 15.0	65
					Trl.		15.0 17.5	0
					Trl.		17.5 19.0	100
4.5 10.0	Clay, sand with gravel, red-brn with some yellow and gry, appears to be laminated below 5.5', 15 gravel, 20 sand, fines are plastic, some strata of CL with trace of gravel and 15 sand, contains trace of cobbles, composition variable according to degree of weathering of different shale units.	CL					18.0 21.0	5
							21.0 26.0	5
							26.0 32.0	100
10.0 15.1	Clay, sand with gravel, brn, to yellow-brn, moist, 10 gravel, 25 sand, fines are plastic, coarse particles are nondurable shale.	CL						
15.1 22.0	Shale-clayey, red-brn to 25.1' and med. gry to 32.0', easily scratched with fingernail, easily broken along smooth flat bedding planes, contains vertical fractures. Two pronounced planes of weakness, bedding planes and vertical fractures. Shale is thin bedded, beds 0.03' thick, cored pieces up to 0.2' long. Core highly broken to 20.2' with numerous gravel str. pieces, some broken and noted to bottom of hole. Some iron staining noted. Contains some thin clay strata.	CL						
22.0	bottom of hole - wet hole							

H. 207, ELEV. 846.3, 846.80, S.S.

From To	Description of Materials	Type	From To	Depth
0.0 8.0	Earth boring	Sp	0.0 8.0	0
8.0 10.5	Penon sample - 2 ft. sampler, top of bottom 0.2' discarded	ML	8.0 10.5	100
10.5 13.0	Penon sample - 2 ft. sampler, top of bottom 0.2' discarded	CL	10.5 13.0	100
13.0	bottom of hole - dry hole.			

See note, sh. 21.

Unified classification by laboratory analysis.

**HARMON CREEK WATERSHED**  
 FLOODWATER RETARDING DAM PA-479  
 WASHINGTON COUNTY, PENNSYLVANIA  
**LOGS OF DRILL HOLES AND TEST PITS**


**U. S. DEPARTMENT OF AGRICULTURE**  
**SOIL CONSERVATION SERVICE**

Operator	R. Hirshey	Date	1-67
Approved by			
Project			
Field No.		Station No.	
			PA-479-P


PLATE 7

**D'APPOLONIA**


DRAWN BY ACS  
 CHECKED BY BE  
 APPROVED BY JHD  
 DATE 3/1/79  
 DRAWING NUMBER 78-367-B 59




TYPICAL BETWEEN & DAM STATIONS  
 1+46 TO 2+80 @ 7+22 TO 7+88




TRANSITION SECTION  
 TYPICAL BETWEEN & DAM STATIONS  
 2+80 TO 2+85 @ 7+17 TO 7+22




TYPICAL BETWEEN & DAM STATIONS  
 2+85 TO 7+17




PROFILE ALONG & CUT-OFF TRENCH





TRENCH AND DOWNSTREAM EDGE OF LEVEL SECTION



**PLAN VIEW**  
 0 25 50 100  
 SCALE IN FEET

- CONSTRUCTION NOTES**
1. For tops of test holes see sheets J.L. Nov. 20.
  2. E. Dam = E. Cut-off trench

**AS BUILT PLANS**

HARMON CREEK WATERSHED  
 FLOODWATER RETARDING DAM PA-479  
 WASHINGTON COUNTY, PENNSYLVANIA  
 CUT-OFF TRENCH DETAILS

U. S. DEPARTMENT OF AGRICULTURE  
 SOIL CONSERVATION SERVICE



Drawn by *Donald R. Sholly* 11-67  
 Checked by *C. CRISE* 11-67  
 PA-479-P

PLATE 8

**D'APPOLONIA**

2

DRAWN BY ACS CHECKED BY BE DRAWING NUMBER 78-367-B60  
 1-4-79 APPROVED BY JMS 3.1.79



AS BUILT  
24" ID PIPE JOINT DATA

JOINT	DIST FROM RISER WALL	INVERT EL
A	0	880.50
B	20.03	880.38
C	40.06	880.27
D	60.09	880.18
E	80.12	880.09
F	100.15	879.98
G	120.18	879.89
H	140.21	879.78
I	160.26	879.66
J	180.27	879.55
K	200.30	879.43
L	220.33	879.32
M	240.37	879.20

AS BUILT  
COLLAR DATA FOR 24" ID PIPE

COLLAR	DIST FROM RISER WALL	INVERT EL
1	26.5	880.36
2	48.0	880.23
3	71.3	880.09
4	92.9	879.96
5	118.2	879.81
6	141.4	879.68

PROFILE ALONG E PRINCIPAL SPILLWAY

24" ID Reinforced concrete pressure pipe spillway conduit.

224' - Straight sections

1 - Spigot ring wall fitting (for 15' wall)

Maximum Pressure Head = 43'. Minimum Pressure Head = 0

Load = 48,120 lbs per lin ft, based on O.D. of 2.67'

Min. 3 edge bearing strength for



0.01" Crack non-pressurized pipe = 25,200 lbs per lin. ft

0.001" Crack prestressed pipe = 18,950 lbs per lin. ft

224.33' Total

CONSTRUCTION

1. Outlet end of pipe to no metal is exposed.
2. Pipe layout data will the engineer



**CONSTRUCTION DETAILS**  
 All pipe to be finished so that  
 exposed  
 data will be furnished by

### AS BUILT PLANS

HARMON CREEK WATERSHED  
 FLOODWATER RETARDING DAM PA - 479  
 WASHINGTON COUNTY, PENNSYLVANIA  
 PRINCIPAL SPILLWAY  
 U. S. DEPARTMENT OF AGRICULTURE  
 SOIL CONSERVATION SERVICE

*Donald C. Shelby* 10-57  
 C. CRISE 10-57

PA-479-P

PLATE 9

**D'APPOLONIA**

DRAWING NUMBER 78-367-B61

3/1/79

BE

CHECKED BY


ACS

APPROVED BY

JHP

1-4-79


DRAWN BY




TOP PLAN

ANGLE FRAME FOR DETAIL SEE SHEET 16

FOR DETAIL OF TRASH RACK ANGLES AND GRATING SEE SHEET 14



SECTION A-A



SECTION B-B

PLATE CONSTRUCTION JOINT. SEE DETAIL THIS SHEET

1/4" x 6" Steel Plate Continuous Thru Constr Joint. Splices Shall Be Either:  
 1. Butt Welded  
 2. Lapped 3" And Bolted  
 3. Lapped 3" And Fillet Welded





PLATE CONSTR. JOINT



CONSTR. JOINT



SIDEWALL ELEVATION

0 2 4 6  
SCALE IN FEET

NOTE: For Construction Details see sheet 18.

STEEL SCHEDULE

MARK	SIZE	QUANTITY	LENGTH	TYPE	B	C	TOTAL LENGTH	MARK	SIZE	QUANTITY	LENGTH	TYPE	B	C	TOTAL LENGTH
B1	5	12	11-0				132-0								
B2	6	5	11-0				55-0								
B3	6	12	12-0				144-0								
B4	7	11	7-3				81-3								
B5	6	24	6-7	21	3-0	3-7	158-0								
B6	6	12	12-0				144-0								
B7	6	18	11-0				198-0								
B8	6	2	4-4				8-8								
B9	5	5	4-6	21	1-0	3-6	22-6								
B10	5	3	6-7	21	1-0	5-7	19-9								
B11	5	16	6-7	21	1-0	5-7	105-4								
B12	5	2	4-6	21	1-0	3-6	9-0								
B13	5	8	6-8				53-4								
B14	5	4	3-0				12-0								
B15	5	10	7-10	21	2-11	4-11	78-4								
B16	5	4	5-9	21	0-10	4-11	23-0								
B17	5	4	5-7	21	0-8	4-11	22-4								
B18	5	2	6-5	21	7-6	4-11	12-10								
B19	6	4	7-8	21	2-10	4-10	30-8								
B20	6	24	4-0				96-0								
B21	5	5	3-8				18-4								
B22	5	2	5-8				7-4								
B23	5	2	2-5				4-10								
B24	5	2	2-7				5-2								
B25	5	12	7-7				115-0								
B26	5	4	9-7				38-4								
B27	5	16	7-6				120-0								
B28	5	8	7-6				60-0								
B29	5	12	4-8				80-0								
B30	5	6	2-8				18-0								
B31	6	24	7-8	21	2-10	4-10	228-0								
B32	5	16	6-8				106-8								
B33	5	10	2-8				26-8								
B34	5	36	7-4	21	2-8	4-8	264-0								
B35	5	16	3-8				58-8								
B36	5	8	3-8				29-4								
B37	5	4	7-0	21	2-6	4-6	28-0								
B38	5	10	11-7				115-10								
B39	5	4	11-7				46-4								
B40	5	12	11-7				139-0								
B41	5	6	11-7				69-6								
B42	5	16	6-8				106-8								
B43	5	8	2-8				21-4								
B44	5	40	7-0	21	2-6	4-6	280-0								
B45	5	10	6-8				66-8								
B46	5	8	2-8				21-4								
B47	5	32	7-0	21	2-6	4-6	224-0								
B48	5	10	6-7				65-10								
B49	5	4	6-7				21-4								
B50	5	12	6-7				79-0								
B51	5	6	6-7				39-6								
B52	5	8	6-8				53-4								
B53	5	8	2-8				21-4								
B54	5	20	7-0	21	2-6	4-6	140-0								
B55	5	8	1-10				14-8								
B56	5	8	2-4				18-8								
B57	5	10	6-6				66-0								
B58	5	2	5-11	21	1-5	4-6	118-4								
B59	5	2	4-10	21	1-5	3-5	9-8								
B60	5	2	2-8	21	1-5	0-10	4-6								
B61	5	2	11-2				22-4								
B62	5	2	11-2				22-4								
B63	5	2	11-2				22-4								
B64	5	2	11-2				22-4								
B65	5	2	11-2				22-4								
B66	5	2	11-2				22-4								
B67	5	2	11-2				22-4								
B68	5	2	11-2				22-4								
B69	5	2	11-2				22-4								
B70	5	2	11-2				22-4								
B71	5	2	11-2				22-4								
B72	5	2	11-2				22-4								
B73	5	2	11-2				22-4								
B74	5	2	11-2				22-4								
B75	5	2	11-2				22-4								
B76	5	2	11-2				22-4								
B77	5	2	11-2				22-4								
B78	5	2	11-2				22-4								
B79	5	2	11-2				22-4								
B80	5	2	11-2				22-4								
B81	5	2	11-2				22-4								
B82	5	2	11-2				22-4								
B83	5	2	11-2				22-4								
B84	5	2	11-2				22-4								
B85	5	2	11-2				22-4								
B86	5	2	11-2				22-4								
B87	5	2	11-2				22-4								
B88	5	2	11-2				22-4								
B89	5	2	11-2				22-4								
B90	5	2	11-2				22-4								
B91	5	2	11-2				22-4								
B92	5	2	11-2				22-4								
B93	5	2	11-2				22-4								
B94	5	2	11-2				22-4								
B95	5	2	11-2				22-4								
B96	5	2	11-2				22-4								
B97	5	2	11-2				22-4								
B98	5	2	11-2				22-4								
B99	5	2	11-2				22-4								
B100	5	2	11-2				22-4								

QUANTITIES

\* 4 BARS 254-4 170 LBS.  
 \* 5 BARS 5044-5 4114 LBS.  
 \* 6 BARS 98-2 140 1343 LBS.  
 \* 7 BARS 79-9 79-9 763 LBS.  
 345 CU. YDS.


AS BUILT PLANS

HARMON CREEK WATERSHED  
 FLOODWATER RETARDING DAM PA-479  
 WASHINGTON COUNTY, PENNSYLVANIA  
 RISER STRUCTURAL DETAILS


U. S. DEPARTMENT OF AGRICULTURE  
 SOIL CONSERVATION SERVICE

Date: \_\_\_\_\_  
 Drawn by: *Donald R. Kelly*  
 Checked by: \_\_\_\_\_  
 Title: \_\_\_\_\_  
 Scale: \_\_\_\_\_  
 Project: \_\_\_\_\_  
 No. \_\_\_\_\_  
 PA-479-A

DRAWN BY	ACS	CHECKED BY	3/1/79	DRAWING NUMBER	78-367-B62
BY	1-4-79	APPROVED BY	JHP		




PLAN VIEW



PROFILE ALONG PLUNGE POOL

- CONSTRUCTION NOTES**
1. Minimum top of plunge pool = el. 878.2. Fill with zero 1 material as required to obtain min. elevation.
  2. Grade area in vicinity of plunge pool and exit channel to obtain free drainage.



**AS BUILT PLANS**


0 1 3 5 0  
SCALE IN FEET

HARMON CREEK WATERSHED  
 FLOODWATER RETARDING DAM PA - 479  
 WASHINGTON COUNTY, PENNSYLVANIA  
 PLUNGE POOL DETAILS  
 U. S. DEPARTMENT OF AGRICULTURE  
 SOIL CONSERVATION SERVICE  
*Donald R. Shady*  
 C. CRIZE 11-67  
 PA-479-P

PLATE II

**D'APPOLONIA**

DRAWN BY	MBM	CHECKED BY	DRAWING NUMBER
BY	1-3-79	JHP	78-367-AB
			3/1/79
			3.1.79



- NOTES:**
1. EMERGENCY SPILLWAY FREEBOARD: 5.1 FT.
  2. POOL LEVEL DATE OF INSPECTION: 30.3 FT. BELOW CREST OF DAM

PLATE 12  
 PA.479 DAM  
 GENERAL PLAN  
 FIELD INSPECTION NOTES  
 FIELD INSPECTION DATE: DEC. 5, 1978

**D'APPOLONIA**

APPENDIX A  
CHECKLIST  
VISUAL INSPECTION  
PHASE I

APPENDIX A  
CHECKLIST  
VISUAL INSPECTION  
PHASE I

NAME OF DAM PA-479 COUNTY Washington STATE Pennsylvania ID# NDI I.D. NO. PA-509  
DER I.D. NO. 63-71

TYPE OF DAM Earth HAZARD CATEGORY High

DATE(S) INSPECTION December 5, 1978 WEATHER Sunny TEMPERATURE 40s

POOL ELEVATION AT TIME OF INSPECTION 903.8 M.S.L. TAILWATER AT TIME OF INSPECTION 876.5 M.S.L.

INSPECTION PERSONNEL:

Bilgin Erel  
Wah-Tak Chan

REVIEW INSPECTION PERSONNEL:  
(December 21, 1978)

L. D. Andersen  
J. H. Poellot  
Bilgin Erel

Bilgin Erel RECORDER

VISUAL INSPECTION  
 PHASE I  
 EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	None.	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None.	
SLOUCHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	None.	
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Crest elevation is within 1/2 foot of the as-built crest elevation relative to the spillway crest elevation.	The irregularities appeared to be from truck tracks.
RIPRAP FAILURES	No riprap on the dam.	

VISUAL INSPECTION  
 PHASE I  
 EMBANKMENT

VISUAL EXAMINATION OF JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
	No signs of distress.	
ANY NOTICEABLE SEEPAGE	One wet area on the downstream slope near the left abutment above the outlet works.	The wet area should be periodically observed to document if a seepage condition is developing.
STAFF GAGE AND RECORDER	None.	
DRAINS	Drainage blanket drainpipes are located adjacent to the outlet pipe. There is no flow in the drainpipes.	

VISUAL INSPECTION  
 PHASE I  
 OUTLET WORKS

VISUAL EXAMINATION OF CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
INTAKE STRUCTURE	The visible portions of the outlet works are in good condition.	
OUTLET STRUCTURE	In good condition.	
OUTLET CHANNEL	Minor scour in the plunge pool beneath the outlet pipe.	Maintenance should be performed if scour conditions worsen.
EMERGENCY GATE	No significant obstructions.	
	Reservoir drainpipe gate hoist is located on the drop inlet structure. Not accessible for inspection.	The operational condition of the reservoir drainpipe gate should be periodically evaluated.

VISUAL INSPECTION  
 PHASE I  
 UNGATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	There is no concrete overflow structure in the emergency spillway.	
APPROACH CHANNEL	Trapezoidal earth channel. The slope adjacent to the emergency spillway is wet and irregular, indicating potential slope instability.	The slopes adjacent to the emergency spillway should be stabilized to prevent development of a slide which would block the spillway.
DISCHARGE CHANNEL	Trapezoidal earth channel (see remarks above).	See remarks above.
BRIDGE AND PIERS	None.	

VISUAL INSPECTION  
 PHASE I  
 GATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE SILL	N/A.	
APPROACH CHANNEL	N/A.	
DISCHARGE CHANNEL	N/A.	
BRIDGE PIERS	N/A.	
GATES AND OPERATION EQUIPMENT	N/A.	

VISUAL INSPECTION  
 PHASE I  
 INSTRUMENTATION

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
MONUMENTATION/SURVEYS	None found.	
OBSERVATION WELLS	None.	
WEIRS	None.	
PIEZOMETERS	None.	
OTHER	Two drainpipes discharging into the plunge pool. No flow in the drainpipes.	

VISUAL INSPECTION  
 PHASE I  
 RESERVOIR  
 OBSERVATIONS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	Steep to moderate.	
SEDIMENTATION	Unknown.	
UPSTREAM RESERVOIRS	None.	

VISUAL INSPECTION  
 PHASE I  
 DOWNSTREAM CHANNEL

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	No apparent obstructions immediately downstream from the dam.	
SLOPES	No apparent instability (immediately downstream from the dam).	
APPROXIMATE NUMBER OF HOMES AND POPULATION	There are three homes approximately one mile downstream and 20 homes approximately two miles downstream. Population: Approximately 125 (initial impact area).	

APPENDIX B  
CHECKLIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION  
AND HYDROLOGIC AND HYDRAULIC  
PHASE I

APPENDIX B  
CHECKLIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION  
PHASE I

NAME OF DAM PA-479  
ID# NDI I.D. NO. PA-509  
DER I.D. NO. 63-71

ITEM	REMARKS
AS-BUILT DRAWINGS	The drawings are available in state and Soil Conservation Service files.
REGIONAL VICINITY MAP	See Plate 1.
CONSTRUCTION HISTORY	The dam was designed by the U.S. Department of Agriculture, Soil Conservation Service. It was constructed by Windy Hill Construction Company of Burgettstown, Pennsylvania, with completion in July 1969.
TYPICAL SECTIONS OF DAM	See Plate 3.
OUTLETS - PLAN - DETAILS - CONSTRAINTS - DISCHARGE RATINGS	See Plates 9, 10, and 11.

CHECKLIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION  
PHASE I

ITEM	REMARKS
RAINFALL/RESERVOIR RECORDS	Not available.
DESIGN REPORTS	Soil Conservation Service internal memo dated April 3, 1967.
GEOLOGY REPORTS	Detailed Geologic Investigation of Dam Sites, SCS Form 376 (undated).
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	Hydrology, hydraulics, geotechnical, and structural calculations are available in SCS files.
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	Included in design and geology reports (see Plate 8 for typical subsurface profile and Plates 5, 6, and 7 for boring logs).

CHECKLIST  
 ENGINEERING DATA  
 DESIGN, CONSTRUCTION, OPERATION  
 PHASE I

ITEM	REMARKS
POST CONSTRUCTION SURVEYS OF DAM	None reported.
BORROW SOURCES	Described in engineer's report.
MONITORING SYSTEMS	None.
MODIFICATIONS	None reported.
HIGH POOL RECORDS	Not recorded.

CHECKLIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION  
PHASE I

ITEM	REMARKS
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	An SCS report entitled, <u>Harmon Creek, PA-479 Slide</u> , dated April 2, 1971.
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	Landslides on the slope adjacent to the emergency spillway (see Section 2.2 of the report).
MAINTENANCE OPERATION RECORDS	Not available.
SPILLWAY PLAN SECTIONS DETAILS	Primary spillway: See Plates 9, 10, and 11. Emergency spillway: See Plates 2 and 3.
OPERATING EQUIPMENT PLANS AND DETAILS	Available in SCS files.

**CHECKLIST  
ENGINEERING DATA  
HYDROLOGIC AND HYDRAULIC**

DRAINAGE AREA CHARACTERISTICS: 1.15 square miles (reclaimed strip mines)  
ELEVATION; TOP NORMAL POOL AND STORAGE CAPACITY: 902.8 (5<sup>+</sup> acre-feet)  
ELEVATION; TOP FLOOD CONTROL POOL AND STORAGE CAPACITY: 922.7 (166 acre-feet)  
ELEVATION; MAXIMUM DESIGN POOL: 934.2  
ELEVATION; TOP DAM: 935.7 (top of overflow)  
SPILLWAY: (Emergency Spillway)

- a. Elevation 922.7
- b. Type Trapezoidal open channel (critical depth overflow section)
- c. Width 50 feet (base width perpendicular to flow direction)
- d. Length 250<sup>+</sup> feet (from crest to the end of the trapezoidal section)
- e. Location Spillover Adjacent to emergency spillway
- f. Number and Type of Gates None

OUTLET WORKS:

- a. Type 24-inch reinforced concrete conduit
- b. Location Near left abutment
- c. Entrance Inverts El. 880.5
- d. Exit Inverts El. 879.2
- e. Emergency Draindown Facilities 15-inch reservoir drainpipe

HYDROMETEOROLOGICAL GAGES:

- a. Type None
- b. Location None
- c. Records None

MAXIMUM NONDAMAGING DISCHARGE: Emergency spillway discharge capacity (80,000<sup>+</sup> cfs)

APPENDIX C  
PHOTOGRAPHS

LIST OF PHOTOGRAPHS  
PA-479 DAM  
NDI I.D. NO. PA-509  
DECEMBER 5, 1978


<u>PHOTOGRAPH NO.</u>	<u>DESCRIPTION</u>
1	Emergency spillway approach channel.
2	Emergency spillway discharge channel.
3	Primary spillway drop inlet structure.
4	Outlet pipe.



Photograph No. 1  
Emergency spillway approach channel.



Photograph No. 2  
Emergency spillway discharge channel.



Photograph No. 3  
Primary spillway drop inlet structure.



Photograph No. 4  
Outlet pipe.

APPENDIX D  
CALCULATIONS

HYDROLOGY AND HYDRAULIC ANALYSIS  
DATA BASE

NAME OF DAM: PA-479 (NDI I.D. PA-469)

PROBABLE MAXIMUM PRECIPITATION (PMP) = 24.2 INCHES/24 HOURS <sup>(1)</sup>

STATION	1	2	3	4	5
Station Description	Reservoir	Dam			
Drainage Area (square miles)	1.15	0			
Cumulative Drainage Area (square miles)	1.15	1.15			
Adjustment of PMF <sup>(1)</sup> for Drainage Area (%) <sup>(2)</sup>					
6 Hours	102	-			
12 Hours	120	-			
24 Hours	130	-			
48 Hours	140	-			
72 Hours	-	-			
Snyder Hydrograph Parameters					
Zone <sup>(3)</sup>	28B	-			
C <sub>p</sub> /C <sub>t</sub> <sup>(4)</sup>	0.57/1.7	-			
L (miles) <sup>(5)</sup>	1.3	-			
L <sub>ca</sub> (miles) <sup>(5)</sup>	0.6	-			
t <sub>p</sub> = C <sub>t</sub> (L·L <sub>ca</sub> ) <sup>0.3</sup> (hours)	1.6	-			
Spillway Data					
Crest Length (ft)	-	50			
Freeboard (ft)	-	11.5			
Discharge Coefficient	-	3.1			
Exponent	-	1.5			

(1) Hydrometeorological Report 33 (Figure 1), U.S. Army, Corps of Engineers, 1956.

(2) Hydrometeorological Report 33 (Figure 2), U.S. Army, Corps of Engineers, 1956.

(3) Hydrological zone defined by Corps of Engineers, Baltimore District, for determining Snyder's Coefficients (C<sub>p</sub> and C<sub>t</sub>).

(4) Snyder's Coefficients.

(5) L = Length of longest water course from outlet to basin divide.

L<sub>ca</sub> = Length of water course from outlet to point opposite the centroid of drainage area.

\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 DAM SAFETY VERSION    JULY 1978  
 LAST MODIFICATION 11 JAN 79  
 \*\*\*\*\*

1	A1	SNYDER UNIT HYDROGRAPH, FLOOD ROUTING	DAM	OVERTOPPING ANALYSES	
2	A2	PA.479 DAM, WASHINGTON COUNTY, NDI-ID.PA469			PROJECT NO 78-367-08
3	A3	FOR 30%, 40%, 50%, 60%, 70%, 80%, 90%, AND 100% PMF			
4	B	50	0	0	0
5	B1	0	10	0	0
6	J	1	1	0.90	1.00
7	J1	0.30	0.40	0.50	0.60
8	K	0	1	0.70	0.80
9	K1	0	1	0.90	1.00
10	M	1	1.15	1.15	1
11	P	1	24.2	102	120
12	T	1	1.6	0.57	130
13	W	1	-1.0	-0.05	140
14	Y	1	2	2.0	1.0
15	Y1	1	1	1	0.05
16	K1				
17	Y				
18	Y1				
19	Y5	26.4	200.0	420.0	26.4
20	Y8	502.0	924.0	935.0	
21	Y8	422.7	500.0	3.1	1.5
22	Y8	934.2	3.1	1.5	550.0
23	A	99			

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS							
				RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7	RATIO 8
				.30	.40	.50	.60	.70	.80	.90	1.00
HYDROGRAPH AT	1	1.15 ( 2.09)	1	926. ( 26.78)	1234. ( 34.91)	1541. ( 43.63)	1849. ( 52.33)	2157. ( 61.08)	2465. ( 69.80)	2773. ( 78.53)	3081. ( 87.25)
ROUTED TO	2	1.15 ( 2.09)	1	801. ( 22.68)	1127. ( 31.97)	1435. ( 40.64)	1736. ( 49.16)	2036. ( 57.64)	2335. ( 66.12)	2636. ( 74.59)	2935. ( 83.11)

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 .....	ELEVATION STORAGE OUTFLOW		INITIAL VALUE	SPILLWAY CREST		TOP OF DAM		TIME OF FAILURE HOURS
	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	912.80	922.70	934.20	406.	6045.	
			26.	189.				
			0.	0.				
RATIO OF PMF	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS			
.50	925.69	831.	0.00	42.00	0.00			0.00
.40	926.66	1129.	256.	41.83	0.00			0.00
.50	927.11	1435.	262.	41.67	0.00			0.00
.60	927.71	1736.	274.	41.67	0.00			0.00
.70	928.27	2036.	283.	41.67	0.00			0.00
.80	928.80	2335.	296.	41.67	0.00			0.00
.90	929.31	2634.	306.	41.67	0.00			0.00
1.00	929.80	2935.	316.	41.50	0.00			0.00

OVERTOPPING ANALYSIS SUMMARY

PAGE D4 of 4

APPENDIX E  
REGIONAL GEOLOGY

APPENDIX E  
REGIONAL GEOLOGY


Pennsylvania Dam 479 is located between the Aunt Clara Dome and the Gillespie Dome. The strata strike northeast and dip approximately 70 feet per mile to the northwest. The stratigraphic column consists of members of the Upper Conemaugh Group, with shale, siltstone, and sandstone the primary rock type.

The lowest stratigraphic member of interest is the Pittsburgh red beds, a thick sequence of reddish claystone and shale. Above the red bed material is the Ames Limestone, a thin gray marine limestone which acts as a marker bed. The Ames Limestone crops at the surface or may be up to 15 feet below the surface in the vicinity of the dam. The Ames Limestone is usually highly jointed, and these joints may be open or filled with clay. These joints are usually interconnected with a possibility of piping along the fractures. Above the Ames are 22 feet of green-gray siltstone, 10 feet of calcareous shale, and 3 to 4 feet of a carbonaceous shale, which is equivalent to the Duquesne coal seam. Above the black shale is the Birmingham Shale, approximately 35 feet thick and consisting of a reddish claystone and shale, and then the Morgantown Sandstone. The Pittsburgh coal seam occurs approximately 215 feet above the Duquesne coal seam.

The only coal seam of economic interest is the Pittsburgh seam, which has been strip mined and deep mined on the ridges south of the dam and reservoir by the Superior Mining Company.

The Birmingham Shale is easily eroded and is known to be slide prone in the region. Approximately 20 percent of the surrounding area is covered by slide deposits and several recent as well as older slides have occurred near the dam.

DRAWING NUMBER 78 37-A 19  
 2-6-77  
 CHECKED BY **BF**  
 APPROVED BY  
 ACS  
 2-5-79  
 DRAWN BY



PA 479, PA 482, PA 484, NEW, OLD  
 AND CHERRY VALLEY DAMS  
 GEOLOGY MAP

**REFERENCE.**  
 GREATER PITTSBURGH REGION GEOLOGIC MAP  
 COMPILED BY W. R. WAGNER, J. L. CRAFT, L. HEYMAN  
 AND J. A. HARPER, DATED 1975, SCALE 1:125,000

**IDAHPIDILONLA**

DRAWING NUMBER 78-17-A22  
 2-4-79  
 CHECKED BY BE  
 APPROVED BY [Signature]  
 2-5-79  
 ACS  
 DRAWN BY [Signature]

**GROUP FORMATION**

**DESCRIPTION**

	Alluvium	Ol	Sand, gravel, clay.
	Terrace deposits		Sand, clay, gravel on terraces above present rivers; includes Carmichaels Formation.
DUNKARD	Greene		Cyclic sequences of sandstone, shale, red beds, thin limestones and coals.
	Washington	Pw	Cyclic sequences of sandstone, shale, limestone, and coal; contains Washington coal bed at base.
	Waynesburg		Cyclic sequences of sandstone, shale, limestone and coal; contains Waynesburg coal bed at base.
	MONONGAHELA	Pm	Cyclic sequences of shale, limestone, sandstone and coal; contains Pittsburgh coal bed at base.
P: CONEMAUGH	Casselman	Pcc	Cyclic sequence of sandstone, shale, red beds and thin limestone and coal.
	Ames		
	Glenshaw	Pcg	Cyclic sequences of sandstone, shale, red beds and thin limestone and coal; several fossiliferous limestone; Ames limestone bed at top.
ALLEGHENY	Vanport		Cyclic sequences of shale, sandstone, limestone, and coal; contains Brookville coal at base and Upper Freeport coal at top; within group are the commercial Vanport limestone and Kittanning and Clarion coals.
		Pa	

**GEOLOGY MAP LEGEND**

**REFERENCE:**

GREATER PITTSBURGH REGION GEOLOGIC MAP  
 COMPILED BY W. R. WAGNER, J. L. CRAFT, L. HEYMAN  
 AND J. A. HARPER, DATED 1975, SCALE 1:125 000

**IDAVIDAIDONLA**