

AD-A072 238

O'BRIEN AND GERE ENGINEERS INC PHILADELPHIA PA JUSTIN--ETC F/G 13/2
NATIONAL DAM INSPECTION PROGRAM. PROMISED LAND DAM (NDI-PA 0030--ETC(U)
MAY 79

DACW31-79-C-0010

UNCLASSIFIED


NL

| OF |
AD
A072238

13



END
DATE
FILMED
9 79
DDC



1.0

2.8

2.5

E
E
E
E
E

3.15

2.2

1.1

3.5

2.0

4.0

4.5

1.8

1.25

1.4

1.6

DELAWARE RIVER BASIN
EAST BRANCH WALLENPAUPACK CREEK, PIKE COUNTY

1

A072238


PENNSYLVANIA

PROMISED LAND DAM

NDI - PA 00308
PA DER 52-12

LEVEL

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM



Distribution Unlimited
Approved for Public Release
Contract No. DACW31-79-C-0010

OK

DDC FILE COPY



Prepared By

O'BRIEN & GERE

Justin & Courtney Division
PHILADELPHIA, PENNSYLVANIA
19103

DDC
AUG 6 1979

ORIGINAL CONTAINS COLOR PLATES: ALL DDC
REPRODUCTIONS WILL BE IN BLACK AND WHITE
FOR

DEPARTMENT OF THE ARMY
BALTIMORE DISTRICT CORPS OF ENGINEERS
BALTIMORE, MARYLAND
21203

MAY 1979

79 08 06 06 7

DISCLAIMER NOTICE

THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DDC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

11 May 79

DELAWARE RIVER BASIN

12 78 p.

Name of Dam: Promised Land Dam

County and State: Pike County, Pennsylvania

Inventory Number: PA 00308

15 DACW31-79-C-0010

PHASE I INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM

6 National Dam Inspection Program.
Promised Land Dam (NDI-PA 00308, PA
DER 52-12), Delaware River Basin, East
Branch Wallenpaupack Creek, Pike County,
Pennsylvania. Phase I Inspection Report.

Prepared by:

O'BRIEN & GERE ENGINEERS, INC.
JUSTIN & COURTNEY DIVISION

For:

DEPARTMENT OF THE ARMY
Baltimore District, Corps of Engineers
Baltimore, Maryland 21203

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DDC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By _____	
Distribution/	
Availability Codes	
Dist.	Availand/or special
A	23 OP

410 760
79 08 06 067 *Sm*

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigations, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected, and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I REPORT
NATIONAL DAM INSPECTION PROGRAM

Name of Dam: Promised Land Dam ID # PA 00308
State Located: Pennsylvania
County Located: Pike
Stream: East Branch Wallenpaupack Creek
Coordinates: Latitude 41° 19.1', Longitude 75° 12.6'
Date of Inspection: December 6, 1978

ASSESSMENT

ABSTRACT ↘
Promised Land Dam is an earth embankment approximately 125 feet long with a maximum height of 16 feet. The spillway is a broadcrested weir, approximately 33 feet long, located in the center of the embankment. The reservoir drain system consists of a 48 inch square conduit controlled by means of a stop-log structure. The dam impounds a 422 acre reservoir for recreation within the Promised Land State Park.

↘ Examination of the results of the hydrologic and hydraulic analyses indicates that the spillway is capable of passing 45 percent of the Probable Maximum Flood (PMF) without overtopping the embankment. Since the spillway cannot pass 50 percent of the PMF, which is the Spillway Design Flood (SDF), the spillway system is classified as "inadequate".

↘ Based on visual observations made during the date of the inspection, the dam and its appurtenant structures are considered to be in fair condition. There is a low area at the top of dam near the right abutment, and bulges in the dry stone wall are evident. Seeps exist near the downstream toe on the right side of the dam. A large (50 foot high, 24 inch diameter) tree is adjacent to the downstream toe of the dam on the right side. Riprap protection on the upstream slope is missing. Some concrete surfaces have deteriorated due to spalling.

Recommendations and remedial measures are as follows: *ABSTRACT* ↙

1. Detailed analyses should be initiated to determine the stability of the dam and need for structural improvements. Evaluate the significance of the seepage and the cause of discoloration of seepage downstream of the dam to the right of the spillway. The stability analyses and seepage evaluation should be performed by a licensed professional engineer experienced in the design and construction of dams.
2. The large tree adjacent to the downstream toe of the right embankment should be cut below ground level and the hole filled and compacted.

3. The parking lot should be regraded so that runoff drains away from the dam.
4. The stop-logs should be provided with means to facilitate their removal.
5. Decisions concerning the need to place riprap protection, fill settled areas, raise the top of dam, and construct additional spillway facilities should await the results of stability analyses and further hydrologic and hydraulic studies.
6. Consideration could be given to increasing the capacity of the spillway in accordance with the results of detailed hydrologic and hydraulic studies.


Operation and Maintenance Procedures :

1. A warning system should be developed for Promised Land Dam. During periods of heavy rainfall or rapid snowmelt the dam should be monitored and downstream residents alerted in the event of an impending failure.
2. The stop-logs should be removed every 6 months to remove sediment that may have been deposited against the stop-logs in the conduit.
3. Until the necessary remedial work has been performed and consideration has been given to increasing the spillway capacity based on detailed hydraulic and hydrologic studies, lake levels should be monitored during periods of heavy rain or rapid snowmelt. If during those periods, the lake level rises rapidly, the stop-logs should be removed to minimize the possibility of overtopping the dam.

O'BRIEN & GERE ENGINEERS, INC.
JUSTIN & COURTNEY DIVISION

Will M. Heiser

Will M. Heiser, P.E.
Vice-President
Pennsylvania Registration #006926-E



Date: 14 June 1979

James W. Peck
Approved By

JAMES W. PECK
Colonel, Corps of Engineers
District Engineer

Date: 16 July 1979



*OVERVIEW
PROMISED LAND DAM, PIKE COUNTY, PENNSYLVANIA*

TABLE OF CONTENTS

	<u>PAGE</u>
SECTION 1 - PROJECT INFORMATION	
1.1 General	1
1.2 Description of Project	1
1.3 Pertinent Data	3
SECTION 2 - ENGINEERING DATA	
2.1 Design	5
2.2 Construction	5
2.3 Operation	6
2.4 Evaluation	6
SECTION 3 - VISUAL INSPECTION	
3.1 Findings	7
SECTION 4 - OPERATIONAL FEATURES	
4.1 Procedures	9
4.2 Maintenance of the Dam	9
4.3 Maintenance of Operating Facilities	9
4.4 Warning System in Effect	9
4.5 Evaluation of Operational Adequacy	9
SECTION 5 - HYDRAULICS AND HYDROLOGY	
5.1 Evaluation of Features	10
SECTION 6 - STRUCTURAL STABILITY	
6.1 Evaluation of Structural Stability	12
SECTION 7 - ASSESSMENT, RECOMMENDATIONS AND PROPOSED REMEDIAL MEASURES	
7.1 Dam Assessment	14
7.2 Recommendations and Proposed Remedial Measures	14

TABLE OF CONTENTS
(Continued)

APPENDIX A -	CHECKLIST, ENGINEERING DATA, DESIGN CONSTRUCTION, OPERATION, PHASE I
APPENDIX B -	CHECKLIST, VISUAL INSPECTION, PHASE I
APPENDIX C -	HYDROLOGIC & HYDRAULIC DATA
APPENDIX D -	PHOTOGRAPHS
APPENDIX E -	DRAWINGS
APPENDIX F -	SITE GEOLOGY

PHASE I REPORT
NATIONAL DAM INSPECTION PROGRAM
PROMISED LAND DAM
NDI I.D. NO. 00308
DER # 52-12

SECTION 1

PROJECT INFORMATION

1.1 General

- a. Authority. The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.
- b. Purpose of Inspection. The purpose of this inspection is to evaluate the structural and hydraulic conditions of the Promised Land Dam and to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project

- a. Dam and Appurtenances. (Supplemented by information obtained from the Pennsylvania Department of Environmental Resources (DER), Division of Dam Safety.)

Promised Land Dam is an earth embankment approximately 125 feet long with a maximum height of 16 feet. The dam impounds a reservoir with a volume of 2,554 acre-feet at normal pool level. The top of the dam is 12-14 feet wide; the downstream slope is approximately 0.25 horizontal to 1.0 vertical (0.25H:1V), and the upstream slope is approximately 3H:1V. No information is available concerning the properties of the embankment materials. A dry stone wall (wall built without mortar) is the only visible protection on the downstream slope.

The spillway is a concrete, broad-crested weir that is 33 feet long and 14 feet wide located in the center of the embankment. The discharge flows over the weir and down the dry stone wall to a sloped concrete apron. A wooden footbridge crosses above the weir at the top of the embankment.

The reservoir drain system consists of a conduit controlled by a stop-log structure located on the upstream slope of the left side of the embankment. The conduit is a 48 inch square reinforced concrete section from the outlet to a point 40 feet upstream of the outlet where it becomes a 49 inch square timber section. This section expands to a 72 inch wide by 48 inch high timber section about 23 feet further upstream. The stop-log structure is located approximately 33 feet upstream of the outlet.

- b. Location. Promised Land Dam is located on the East Branch of Wallenpaupak Creek at a point 0.5 mile north of Promised Land, in Greene Township, Pike County, Pennsylvania. The dam site is shown on the USGS Quadrangle entitled "Promised Land, Pennsylvania" at coordinates N $41^{\circ} 19.1'$, W $75^{\circ} 12.6'$. A regional location plan of Promised Land Dam is enclosed as Plate 1, Appendix E.
- c. Size Classification. Promised Land Dam has a maximum storage capacity of 5,048 acre feet and a maximum height of 16 feet. The structure is in the "Intermediate" size category.
- d. Hazard Classification. There is one state owned cabin in the valley between Promised Land Dam and Lower Lake (a distance of about $\frac{1}{2}$ mile). At the present time, Promised Land State park has plans to demolish this cabin this year. There is a possibility of appreciable property damage associated with the one home on the shores of Lower Lake in the event of a dam failure. However, there is little likelihood of loss of life. Therefore, the structure is in the "Significant" hazard category.
- e. Ownership. The dam is owned and operated by the Commonwealth of Pennsylvania, Department of Environmental Resources. All correspondence should be addressed to the Department of Environmental Resources, P.O. Box 1467, Harrisburg, PA 17120.
- f. Purpose of the Dam. The purpose of the dam is to provide a recreation site for Promised Land State Park.
- g. Design and Construction History. The earliest record for Promised Land Dam is an inspection report made in November, 1919. There is no evidence that construction documents or design data prior to that date are available. According to available records, the dam at that time was an earth embankment with the downstream slope protected by riprap. The concrete spillway was a broad-crested weir located in the center of the embankment with concrete abutments.

According to information in the DER files, extensive repairs to the Promised Land Dam were made between November, 1930 and May, 1931, to correct serious defects in the structure. These defects were reported to include excessive leakage at the spillway, settlement of the embankment, inadequate spillway capacity, and a wall along the downstream slope which was about to collapse. The repairs involved the construction of a vertical reinforced concrete cut-off wall, 55 feet long and 15 inches thick, along the upstream edge of the spillway. The wall extends down to solid rock. Additional fill was placed on the upstream slope and the embankment was raised 3 feet to Elevation 1731.1. The dry stone wall on the downstream slope was reconstructed. A reinforced concrete slab was laid in the spillway and joined to the vertical cut-off wall, raising the spillway to Elevation 1726.1. Concrete abutment walls adjacent to the spillway were raised 2.5 feet to a height 5.0 feet above the spillway slab. According to correspondence in the DER files, riprap was placed on the upstream face and loose rockfill placed along the downstream toe.

In September, 1935, construction drawings for an outlet conduit for the Promised Land Dam were completed and construction began in 1936. The rectangular outlet conduit, constructed of timber and concrete, passes through the earth embankment to the left of the spillway. Flow through the conduit is controlled by means of a stop-log structure located on the upstream face of the dam.

- h. Normal Operating Procedures. Under normal operating conditions, the overflow from Promised Land Lake is controlled by the spillway. Carl Rose, the Promised Land State Park foreman, stated that the outlet conduit is opened only to draw the lake down when it is necessary to repair the beaches or dock facilities.

1.3 Pertinent Data.

a. Drainage Area.

Square Miles	6.6
--------------	-----

b. Discharge at Dam Site (cfs.).

Total spillway capacity at top of dam Elev. 1731.1	1,070
--	-------

c. Elevation (feet above MSL).

Spillway Crest (Normal, Recreation Pool)	1726.1
Top of Dam	1731.1
Reservoir Drain Invert (Inlet)	1719.5
Reservoir Drain Invert (Outlet)	1719.5
Apron (Estimated)	1715.1
Streambed at Centerline of Dam (Estimated)	1715.1

d. Reservoir (miles).

Length of Normal, Recreation Pool	1.9
Length of Maximum Non-overtopping Pool	2.0

e. Storage (acre-feet).

Normal, Recreation Pool, Elev. 1726.1	2,554
Top of Dam at Low Point, Elev. 1731.1	5,048

f. Reservoir Surface Area (acres).

Normal, Recreation Pool, Elev. 1726.1	438
Top of Dam at Low Point, Elev. 1731.1	562

g. Dam Data

Type	Earth
Length	125 feet

Height	16 feet (maximum)
Top Width	12 to 14 feet
Side Slopes	3H:1V (upstream); 0.25H:1V (downstream)
Zoning	Not Available
Impervious Core	Not Available
Cutoff	Concrete to rock in spillway area
Grout Curtain	No

h. Spillway

Type	Concrete broad-crested weir
Width	14 feet
Length	33 feet
Crest Elevation	1726.1
Gates	None
Upstream Channel	Promised Land Lake
Downstream Channel	Rocky channel into large masonry culvert.

i. Outlet Works

Type	48 inch square reinforced concrete conduit connected to 49 inch square timber conduit which flares to a 48 inch by 72 inch timber conduit.
Length	68 feet +
Closure	Stop-logs
Access	Concrete manhole on upstream slope of left embankment.
Regulating Facilities	Manual removal of stop-logs

SECTION 2
ENGINEERING DATA

2.1 Design

a. Data Available. The information available in the DER main office files in Harrisburg, Pennsylvania, for review of Promised Land Dam includes the following:

1. Dam inspection reports beginning in 1919 and through the intervening years.
2. Photographs beginning in 1921 and through the intervening years.
3. "Report Upon the Promised Land Dam", Commonwealth of Pennsylvania, Department of Forests and Waters, 1929.
4. "Proposed Repairs of Promised Land Dam", Commonwealth of Pennsylvania, Department of Forests and Waters, 1929, 1930.
5. "Promised Land Dam - Proposed Outlet Conduit", Commonwealth of Pennsylvania, Department of Forests and Waters, 1935.
6. Memorandums and correspondence between Horace H. Heller, the contractor, and the Department of Forests and Waters (October, 1930 to April, 1931).
7. "Progress Report", Commonwealth of Pennsylvania, Department of Forests and Waters, 1930.
8. "Final Report on the Repair of the Promised Land Dam", Commonwealth of Pennsylvania, Department of Forests and Waters, 1931.
9. Correspondence between Civil Conservation Corps, the contractor, and the Department of Forests and Waters (1936).
10. Miscellaneous correspondence.

b. Design Features. The design features are discussed in Section 1.2.a. The repair and additional construction drawings are shown on Plates 2, 3, and 4 of Appendix E.

2.2 Construction

Based on the field investigation and the information available in the construction reports, the dam appears to have been constructed in general conformance with the design drawings.

2.3 Operation

Operation procedures appear to be limited to those necessary to draw down the lake by removal of stop-logs located in the manhole structure on the upstream slope of the dam. There is no evidence that operating procedures have been written for this structure.

2.4 Evaluation

- a. Availability. Limited material is available concerning embankment materials and subsurface conditions. However, data is available concerning inspections and construction history.
- b. Adequacy. A Phase I evaluation is considered reasonable based on the revealing conditions observed during the field inspection and conversations with the owner's representative, although design and construction information is limited concerning embankment materials and subsurface conditions.
- c. Validity. There appears to be no reason to doubt the validity of the data available.

SECTION 3
VISUAL INSPECTION

3.1 Findings

- a. General. The field inspection of the Promised Land Dam was conducted on December 5, 1978. At the time of the inspection, water was flowing over the spillway at a depth of one to two inches. Additional water was observed flowing from the outlet conduit. No underwater areas were inspected. The observations and comment of the field inspection team are included in the checklist which is Appendix B of this report. The appearance of the facility indicates that the dam and its appurtenances are well maintained.

- b. Dam. The upstream face of the dam has a mowed grass cover and is well maintained. Randomly-sized stone has been placed into the earth above the spillway level. Several footpaths, located on the upstream face, appear well compacted and are not causing any erosion at this time. One footpath, adjacent to the right wingwall, has caused some minor erosion.

Two low areas were noted in the top of the dam. Approximately 20 feet from the right wingwall, there is a noticeable depression (3 feet by 30 feet) about 6 inches deep. On the left side, 15 feet from the left wingwall, there is a low area reported to be caused by erosion. This area, about 2 feet by 2 feet, is drained by a hole eroded into the earth embankment. The park foreman stated that this problem is the result of runoff from a parking lot adjacent to the left side of the dam. A wooden and wire mesh fence is located along the downstream side of the top of the dam.

The entire downstream face of the embankment is covered by a dry stonewall with a concrete cap. The masonry has a slight outward bulge midway up the wall across its entire length. The bulge is more apparent in the wall immediately below the low area in the top of the dam to the right of the spillway. Sparse vegetation was observed growing in the masonry wall. Roots from the large tree located at the downstream toe, at the right side of the embankment, are growing in towards the embankment material beneath the stonewall. The roots may be the principal cause of the "bulging" or "heaving" that is evident on the downstream slope near the right abutment.

A flow of water, approximately 2 gallons per minute, was observed coming from the base of the wall adjacent to the spillway on the right side of the dam. On each side of the spillway, there was an ice layer on the stonework. On the right side of the spillway, seepage through the dam was noted flowing under the ice down the masonry wall. It was not

evident that this was due to water from the spillway or seepage through the embankment on the right side. Seepage was observed on the ground surface in several areas to the right of the spillway on the downstream side of the dam. The flow from each seep area is approximately 1/4 gallon per minute and is discolored.

The approach to the spillway has silted such that sandy sediments have reached the spillway crest.

Currents may have removed the sands from a beach a few hundred yards from the spillway and deposited them at the spillway. Spalling is evident at the waterline on both wingwalls. Significant spalling, approximately 1/4 inch deep is apparent on the downstream side of the right wingwall in the spillway channel and where the wingwall contacts the stonework. Minor spalling and erosion has occurred at the downstream edge of the spillway slab, which overhangs the dry stonewall. The concrete underneath the spillway slab and above the stonework has recently been replaced during remedial work. This work included resurfacing portions of the apron slab below the spillway.

- c. Appurtenant Structures. It is reported by the owner's representative that the rectangular channel below the outlet conduit has undergone recent remedial concrete work. The wall on the left side of the channel shows evidence of recent concrete patching, and the last 3 to 4 feet of the concrete channel appear to have been placed recently. The earth adjacent to the left wall of the channel has eroded in an area approximately 2 feet by 15 feet. The probable cause of this erosion is the runoff from the parking area to the left of the dam.

The stop-log structure, which controls the flow through the outlet conduit, was locked and no inspection of these facilities could be made. The water flowing from the outlet conduit may indicate that the stop-logs need replacement.

- d. Reservoir. Siltation of the reservoir was observed in the vicinity of the spillway. The slopes around the reservoir are on mild gradients and are heavily vegetated.
- e. Downstream Channel. Immediately downstream of the dam, the East Branch of Wallenpaupack Creek enters a large stone masonry culvert under Route 390. Approximately one-half mile beyond the culvert, the flow enters Lower Lake. The stream overbanks beyond the culvert are heavily vegetated. The stream channel has a gradient of approximately 0.3 percent in this area. There is one state owned cabin in the valley between Promised Land Dam and Lower Lake (a distance of one-half mile). At the present time, Promised Land State Park has plans to demolish the cabin this year. There is one home on the shores of Lower Lake. During the summer months, as many as a dozen people would be involved.

SECTION 4
OPERATIONAL PROCEDURES

4.1 Procedures

Operational procedures appear to be limited to those necessary to draw the level of the Promised Land Lake down to perform maintenance on the park beaches and dock facilities. There is no evidence of written operating procedures. Normal operating procedures for this structure do not require a dam tender.

4.2 Maintenance of the Dam

The dam appears to be well maintained by the Promised Land State Park personnel. Maintenance inspections are conducted on a regular basis by the Park Superintendent and personnel from the Division of Completed Projects; DER records and photographs of those inspections are available. Maintenance and remedial work to date include: the replacement of masonry, concrete repair, backfill and reseeding of eroded areas of the embankment, and the removal of logs, debris, trees, and brush from the embankment and reservoir area.

4.3 Maintenance of Operating Facilities

The stop-log structure was locked and no inspection could be made. However, this appurtenance was evaluated during the regular maintenance inspections of the dam and the records and photographs of the dam include information of this structure. The records indicate that the stop-logs have been replaced when necessary.

4.4 Warning Systems in Effect

According to the Park Superintendent, no formal procedures have been established for warning downstream residents during periods of high lake levels. However, observations of high lake levels have been recorded in recent years.

4.5 Evaluation of Operational Adequacy

The current operating and maintenance procedures for the Promised Land Dam appear adequate. Operating procedures could be improved by providing for the opening of the stop-log structure during periods of high lake levels to minimize the possibility of overtopping the embankment. Presently, the stop-logs must be removed manually, which is a slow and difficult procedure.

A warning system should be developed. During periods of heavy rainfall the dam should be monitored and downstream residents alerted in the event of an impending failure.

The dam is accessible under all weather conditions for inspection and emergency action.

SECTION 5

HYDRAULICS AND HYDROLOGY

5.1 Evaluation of Features

- a. Design Data. There is reported to be no original design data available. Hydraulic and hydrologic calculations accompany the "Final Report in the Repair of the Promised Land Dam" (1931). These calculations determine the capacity of the spillway after the repairs and estimate the time for the reservoir level to rise from the spillway crest to the top of the dam. The drainage area contributing to the Promised Land Dam is about 3.7 miles long and averages 1.8 miles wide. Ground elevations range from 2012 to 1726. The slopes of the reservoir watershed are all less than ten percent. The watershed is nearly 100 percent wooded.

For further information, refer to the computation, data and printouts included in Appendix C.

- b. Experience Data. There is no evidence that records of reservoir water levels have been maintained until recent years. During Hurricane Agnes, in June, 1972, the stage in the reservoir was reported to be 18 inches above the crest of the spillway. Observations during heavy rains of June 28-29, 1973, indicate that the depth of water over the spillway was approximately 12 inches. Rainfall records for Promised Land State Park are maintained at the Park Office.
- c. Visual Observations. On the date of the inspection, no adverse conditions were observed that would indicate the spillway capacity would be reduced during a flood. The outlet capacity of the dam could be improved by providing a lifting device to expedite the removal of the stop-logs during periods of high reservoir levels.
- d. Overtopping Potential. The spillway is capable of handling a discharge of 1,070 cfs. However, the SDF for this "Intermediate" size dam, with a "Significant" hazard classification, is 50 percent of the Probable Maximum Flood (0.5 PMF), which has a peak inflow of 5,950 cfs. and a peak overflow of 1,430 cfs. The 0.5 PMF hydrograph was routed through the reservoir with the starting water surface 0.2 feet above the crest of the spillway at elevation 1726.3. The maximum water surface elevation in the reservoir resulting from the 0.5 PMF routing would be 5.5 feet above the spillway crest and 0.5 feet above the lowest point at the top of the dam.

Examination of the results of the hydrologic and hydraulic analysis indicates that the spillway is capable of passing 45 percent of the PMF without overtopping of the embankment. (See Appendix C for computations.)

- e. Spillway Adequacy. Based on the results of the hydrologic and hydraulic analysis, the spillway of the Promised Land Dam is capable of handling 45 percent of the PMF while the SDF is 50 percent of the PMF. Therefore, the spillway of the Promised Land Dam is classified as "Inadequate".

SECTION 6

STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

- a. Visual Observations. Several existing conditions indicate potential embankment stability problems. The dry stone wall on the downstream face of the dam has a slight outward bulge. The bulge is more apparent on the right of the dam where a low area is evident along the top of the dam. The tree roots from the large tree located near the downstream toe, may be a principal cause of the heaving action noted on the downstream slope near the right abutment. The hole in the top of the left side of the dam indicates that runoff from the parking lot has removed portions of the earth embankment. Previous reports indicate that this is a reoccurring problem and must be corrected. The visible portion of the upstream face of the dam is in good condition.

Seepage and discolored water were observed near the downstream toe on the right side in several areas. The rate of flow from each area was estimated to 1/4 gallon per minute.

Inspection of exposed concrete work revealed that significant spalling of the concrete has occurred on the spillway. Although no reinforcing steel bars were exposed, remedial work is necessary to prevent further deterioration of the concrete.

- b. Design and Construction Data. Available documentation, calculations, and other data were reviewed. No original design data are available. Structural drawings for repairs to the dam are available; however, no structural calculations or soil data are available. Lists of design and construction data reviewed are given in Sections 2.1.a and 2.2.
- c. Operating Records. There is no evidence that operating records are maintained for the Promised Land Dam.
- d. Post-Construction Changes. The available information indicates that two major modifications to the original structure have been made. In 1930 and 1931, a vertical cut-off wall was added, the embankment was raised 3 feet, and the spillway reconstructed for the new embankment height. In 1935, the outlet conduit and stop-log structure were constructed. Design drawings for these modifications are included in Appendix E as Plates 2, 3, and 4. Information is available in the DER files on maintenance repair work done on the dam through the years.

- c. Seismic Stability. Promised Land Dam is located within Seismic Risk Zone 1 of the "Seismic Zone Map of Contiguous States". Normally, it can be considered that if a dam in this zone is stable under static loading conditions, it can be assumed safe for any expected Zone 1 earthquake conditions.

SECTION 7

ASSESSMENT, RECOMMENDATIONS AND PROPOSED REMEDIAL MEASURES

7.1 Dam Assessment

- a. Evaluation. Based on visual observations made during the date of the inspection, the dam and its appurtenant structures are considered to be in fair condition. There is a low area at the top of dam near the right abutment and bulges in the dry stone wall. Seeps exist near the downstream toe on the right side of the dam. A large (50 foot high, 24 inch diameter) tree is adjacent to the downstream toe of the dam on the right side. Riprap protection on the upstream slope is missing. Some concrete surfaces have deteriorated due to spalling.

The SDF is the 0.5 PMF. Examination of the results of the hydrologic and hydraulic analysis indicates that the spillway is capable of passing 45 percent of the PMF without overtopping the embankment. Since the spillway system is not capable of handling the SDF, it is classified as "Inadequate".

- b. Adequacy of Information. A Phase I evaluation is considered reasonable based on the revealing conditions observed during the field inspection and conversations with the owners representative, although design and construction information is limited.
- c. Urgency. The remedial measures recommended in Section 7.2 should be effected immediately.
- d. Necessity for Further Evaluation. Further investigations should be performed to determine the stability of the dam and the need for structural improvements. Detailed hydrologic and hydraulic studies should be made to determine the extent to which the spillway system should be increased.

7.2 Recommendations and Remedial Measures

- a. Facilities.
 1. Detailed analyses should be initiated to determine the stability of the dam and need for structural improvements. Evaluate the significance of the seepage and the cause of discoloration of seepage downstream of the dam to the right of the spillway. The stability analyses and seepage evaluation should be performed by a licensed professional engineer experienced in the design and construction of dams.
 2. The large tree adjacent to the downstream toe of the right embankment should be cut below ground level and the hole filled and compacted.

3. The parking lot should be regraded so that runoff drains away from the dam.
4. The stop-logs should be provided with means to facilitate their removal.
5. Decisions concerning the need to place riprap protection, fill settled areas, raise the top of dam, and construct additional spillway facilities should await the results of the stability analysis and further hydrologic and hydraulic studies.
6. Consideration could be given to increasing the capacity of the spillway in accordance with the results of detailed hydrologic and hydraulic studies.

b. Operation and Maintenance Procedures.

1. A warning system should be developed for Promised Land Dam. During periods of heavy rainfall or rapid snowmelt the dam should be monitored and downstream residents alerted in the event of an impending failure.
2. The stop-logs should be removed every 6 months to remove sediment that may have been deposited against the stop-logs in the conduit.
3. Until the necessary remedial work has been performed and the spillway capacity has been increased based on detailed hydraulic and hydrologic studies, lake levels should be monitored during periods of heavy rain or rapid snowmelt. If during these periods, the lake level rises rapidly, the stop-logs should be removed to minimize the possibility of overtopping the dam.

APPENDIX

A

Check List Engineering Data
Design, Construction, Operation
Phase I

NAME OF DAM Promised Land
ID # PA 00308

Sheet 1 of 4

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION
PHASE I

REMARKS

ITEM

AS-BUILT DRAWINGS

Not Available.

REGIONAL VICINITY MAP

See Plate 1, Appendix E

CONSTRUCTION HISTORY

Refer to Section 1.2.9

TYPICAL SECTIONS OF DAM

Refer to Appendix E

OUTLETS - PLAN

Refer to Appendix E for plan and details

DETAILS

CONSTRAINTS

DISCHARGE RATINGS

Not Available

RAINFALL/RESERVOIR RECORDS

Rainfall records available at Promised Land State Park

ITEM	REMARKS
DESIGN REPORTS	Refer to Section 2.1
GEOLOGY REPORTS	Not Available, Refer to Appendix F of this report
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	Not Available Refer to Section 5.1a No dam stability analysis or seepage studies available
MATERIALS INVESTIGATIONS BORING RECORDS } LABORATORY } FIELD }	Not Available
POST-CONSTRUCTION SURVEYS OF DAM	Not Available
BORROW SOURCES	Not Available

ITEM

REMARKS

SPILLWAY PLAN

SECTIONS

DETAILS

Refer to Appendix E

OPERATING EQUIPMENT
PLANS & DETAILS

Refer to Appendix E for stop-log details

MISCELLANEOUS

Mentioned in DLE files - refer to Section 2.1a and 2.2

APPENDIX

B

Check List
Visual Inspection
Phase I

CHECK LIST
VISUAL INSPECTION
PHASE I

Sheet 1 of 11

Name Dam Promised Land County Pike State Pennsylvania National ID # PA 00303
Type of Dam Earth Hazard Category Significant
Date(s) Inspection 12/5/73 Weather Clear Temperature 30's - 40's

Pool Elevation at Time of Inspection 1726.3 M.S.L. Tailwater at Time of Inspection 1715 ± M.S.L.

Inspection Personnel:

Gregg C. Elias Thomas C. Abt
David B. Campbell _____
Dana R. Pizarro _____
_____ David B. Campbell Recorder

Remarks:

Earth embankment protected by dry stone wall on downstream side.
Carl Rosa, Promised Land State Park Foreman, accompanied inspection personnel.

CONCRETE/MASONRY DAMS

Sheet 2 of 11

VISUAL EXAMINATION OF OBSERVATIONS REMARKS OR RECOMMENDATIONS

ANY NOTICEABLE SEEPAGE

N/A

STRUCTURE TO
ABUTMENT/EMBANKMENT
JUNCTIONS

N/A

DRAINS

N/A

WATER PASSAGES

N/A

FOUNDATION

N/A

CONCRETE/MASONRY DAMS

Sheet 11 of 11

VISUAL EXAMINATION OF OBSERVATIONS REMARKS OR RECOMMENDATIONS

SURFACE CRACKS
CONCRETE SURFACES

N/A

STRUCTURAL CRACKING

N/A

VERTICAL AND HORIZONTAL
ALIGNMENT

N/A

MONOLITH JOINTS

N/A

CONSTRUCTION JOINTS

N/A

EMBANKMENT

Sheet 4 of 11

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	None Observed	—
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None Observed	—
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	Minor erosion adjacent to wingwall, Erosion through embankment crest on left side, Erosion next to left outlet conduit wingwall	change drainage pattern of adjacent parking area, Fill and resodded gravel areas
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Horizontal alignment - Good Vertical alignment - 6 in. depression on right side, depression cracked on left side of culvert	Initiate boring program to determine composition and setu properties of embankment and foundation materials & to determine dam stability install piezometers in bore holes to evaluate pore pressure develop
RIPRAP FAILURES	None Observed	Place rip-rap on upstream face of embankment

EMBANKMENT

Sheet 5 of 11

<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
------------------------------	---------------------	-----------------------------------

DRAINS

N/A

JUNCTION OF EMBANKMENT
AND ABUTMENT, SPILLWAY
AND DAM

Junction of embankment
and abutment appears to
be in good condition. Concrete
between spillway slab and
stone work on embankment
was unperturbed.

ANY NOTICEABLE SEEPAGE

Seepage coming from stone work on
right side of dam at toe,
several seepage areas
observed downstream of
toe on right side. Seepage
has subsided & flow.

Monitor seepage for
changes in rate of
flow and turbidity.
Install piezometers to aid
in determination of source
of seeps

STAFF GAGE AND RECORDER

None

OUTLET WORKS

Sheet 6 of 11

VISUAL EXAMINATION OF CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
INTAKE STRUCTURE	Interior of outlet conduit not inspected	Drows down lake so that reservoir drain system can be examined
INTAKE STRUCTURE	Not observed, under water	"
OUTLET STRUCTURE	Wingwall on left side has been patched recently	-
OUTLET CHANNEL	Recent concrete patching downward, some flow in outlet channel	-
EMERGENCY GATE	stop-logs function as emergency gate - first removed, manhole was locked	inspect stop logs
BRIDGE	Wooden foot bridge over spillway in good condition	-

UNGATED SPILLWAY

Sheet 7 of 11

<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
CONCRETE WEIR	Spalling on wing wall at waterline. Significant spalling on downstream face of right wing wall. Minor spalling at downstream edge of spillway slab.	Patch spalled areas.
APPROACH CHANNEL	Sandy sediment up to spillway crest level.	Remove sediment when lake is drawn down.
DISCHARGE CHANNEL	Rocky channel to large culvert under Route 370. Wild slope.	—
BRIDGE AND PIERS	Wooden foot bridge over spillway in good condition, no piers.	—

GATED SPILLWAY

Sheet 8 of 11

REMARKS OR RECOMMENDATIONS

OBSERVATIONS

VISUAL EXAMINATION OF

CONCRETE SILL

N/A

APPROACH CHANNEL

N/A

DISCHARGE CHANNEL

N/A

BRIDGE AND PIERS

N/A

GATES AND OPERATION
EQUIPMENT

N/A

INSTRUMENTATION

Sheet 9 of 11

VISUAL EXAMINATION OBSERVATIONS REMARKS OR RECOMMENDATIONS

MONUMENTATION/SURVEYS None Install monuments on crest to observe settlement

OBSERVATION WELLS

None

WEIRS

None

PIEZOMETERS

None

Install piezometers in embankment, particularly on right side, to determine source of seeps

OTHER

RESERVOIR

Sheet 10 of 11

REMARKS OR RECOMMENDATIONS

OBSERVATIONS

VISUAL EXAMINATION OF

SLOPES

Heavily covered
with trees and
brush, mild
slopes

SEDIMENTATION

Sandy sediment
up to spillway
level at reservoir
outlet, probably
from beach near
outlet

Remove when lake
is certain down

DOWNSTREAM CHANNEL

Sheet 11 of 11

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

CONDITION
(OBSTRUCTIONS,
DEBRIS, ETC.)

Route 3570 outlet
approx. 100 feet downstream
of dam, outlet is inside
of natural stream channel
light brush in overbanks
rocky channel

SLOPES

Mid slopes

APPROXIMATE NO.
OF HOMES AND
POPULATION

one stone curved cabin
between Promised
Land Dam and Lower
Lake. 1 private
residence on tower
Lake. Maybe a dozen
people involved during the
September floods when
residents are evacuated.

Develop & implement
formal warning system.

APPENDIX

C

Hydrologic & Hydraulic Data

SUBJECT	SHEET	BY	DATE	JOB NO
---------	-------	----	------	--------

TABLE OF CONTENTS APPENDIX C

Hydraulics & Hydrologic Data

Hydrograph Coefficients & PMP Calculations	Shts. 1 & 2
Stage-Area, Stage-Storage Calculations	Shts. 2, 2a, & 2
Spillway & Embankment Discharge Comp.	Shts. 3 & 4
Route 270 Culvert Storage Computations	Shts. 5-9

HEC-I Dam Safety Version Computer Output without Breach of Dam.	Shts. 10-15
--	-------------

SUBJECT	SHEET	BY	DATE	JOB NO.
Upper Promised Land Dam	1	DRP	12/14/75	1541-010

D.A. Area I + Area II

$$\text{Area I} = 1.015 \text{ in}^2/\text{unit} \times 27.75 \text{ units} \times 4 \times 10^6 \frac{\text{ft}^2}{\text{in}^2} \times 3.587 \times 10^{-9} \frac{\text{m}^2}{\text{ft}^2}$$

$$= 4.04 \text{ m}^2$$

$$\text{Area II} = 1.015 \text{ in}^2/\text{unit} \times 19.53 \text{ units} \times 4 \times 10^6 \frac{\text{ft}^2}{\text{in}^2} \times 3.587 \times 10^{-9} \frac{\text{m}^2}{\text{ft}^2}$$

$$= 2.84 \text{ m}^2$$

D.A. = 6.88 m² × 6.9 m² by planimeter
 6.57 m² by reports use 6.57 m²

Hydrograph Parameters (Snyder method)

$$t_p = C_t (L L_c)^{0.3}$$

C_t = 1.23 (supplied by CCE)
 C_t = 0.45 } Zone 1

L = 4.1 miles
 L_c = 1.9 miles

$$t_p = 1.23 ((4.1)(1.9))^{0.3} = 2.3 \text{ hr.}$$

$$t_r = \frac{2.3 \text{ hr.}}{5.5} = 0.4 \text{ hr}$$

Probable Maximum Storm (PMS) (Hydromet 33)

Zone 1 (Fig. 1)

Probable Max. Flood (PMF) = 22.2 in. (200 m², 24 hr)

Depth - Area - Duration Relationships

- Maximum 6 hr = 111% PMF
- Maximum 12 hr = 123% PMF
- Maximum 24 hr = 133% PMF

Loss Rate

- initial loss = 1"
- uniform loss = 0.02 c/hr

SUBJECT Upper Promised Land Dam	SHEET 1	BY DKP	DATE 12/15/73	JOB NO 1841-010
------------------------------------	------------	-----------	------------------	--------------------

Base flow

$$1.5 \text{ cfs/mi}^2 \times 6.57 \text{ mi}^2 = 9.9 \text{ cfs}$$

Flooding - Area - Capacity Data

<u>Flow</u>	<u>Area (mi²)</u>	<u>Area (acre)</u>	
175.6		422.0	- data
1727	0.72	460.8	
1740	1.27	612.8	planimeter
1760	1.90	1216.0	
1720.4		287	
1715.1 (streambed dry)		0	extension of data see next page



SUBJECT

PLD

SHEET

2a

BY

DRP

DATE

1/19/79

JOB NO

1841-010

Extend Elevation-Area-Capacity Data below spillway crest
using conic method

$$V = 765,000,000 \text{ gallons at Elav 1725.6}$$

$$A = 422 \text{ acres}$$

$$h = 1725.6 - 1715.1 \text{ (streambed elev)} = 10.5 \text{ ft}$$

$$A = 18,352,320 \text{ ft}^2$$

$$\therefore V = 102,272,727 \text{ cf} = 2347 \text{ acre-ft}$$

$$r = \sqrt{A/\pi} = \sqrt{18,352,320 \text{ ft}^2 / \pi} = 2415.9 \text{ ft}$$

$$V = \pi (2415.9)^2 \frac{(10.5)}{3} = 64,335,954 \text{ cf} \quad \text{(single cone)} \\ \text{too low}$$

Break into 2 cones

① assume area at $h/2$ is $1/2$ area at h

$$\text{Upper Cone Volume} = \left(\frac{5.25}{3}\right) (422 + 211 + \sqrt{(422)(211)}) \\ = 1629.9 \text{ acre-ft} \approx 71,000,000 \text{ cf}$$

$$\text{Bottom Cone Volume} = \pi r^2 \frac{h}{3} = A \frac{h}{3} = 211 \left(\frac{5.25}{3}\right) = 569.3 \text{ acre-ft} \\ = 16,000,000 \text{ cf}$$

Total: 87,000,000 cf
too low

② assume area at $h/2$ is 55% area at h

$$\text{Upper Cone Volume} = \left(\frac{5.25}{3}\right) (422 + 232 + \sqrt{(422)(232)}) \\ = 1692 \text{ ac-ft} = 73,700,000 \text{ cf}$$

$$\text{Bottom Cone Volume} = \pi r^2 \frac{h}{3} = (232) \left(\frac{5.25}{3}\right) = 406 \text{ ac-ft} \\ = 17,700,000 \text{ cf}$$

Total = 91,400,000 too low

- (3) assume area at $h/2$ is 65% area at h

$$\text{Upper Cone Volume} = \left(\frac{5.25}{3}\right) (422 + 274 + \sqrt{(422)(274)})$$

$$= 1813 \text{ ac-ft} = 79,000,000 \text{ cu ft}$$

$$\text{Bottom Cone Volume} = \left(\frac{5.25}{3}\right) (274) = 479.5 \text{ ac-ft}$$

$$= 20,900,000 \text{ cu ft}$$

$$\text{Total} = 99,900,000 \text{ cu ft}$$

- (4) assume area at $h/2$ is 68% area at h

$$\text{Volume} = \left(\frac{5.25}{3}\right) (422 + 2(237) + \sqrt{(422)(237)})$$

$$= 2343 \text{ ac-ft} = 102,064,000 \text{ cu ft} \quad \underline{\text{goal}}$$

SUBJECT	SHEET	BY	DATE	JOB NO
Upper Promised Land Dam	3	DRP	12/18/79	1841-010

Rev. 4/15/79

Spillway Discharge Rating

$$Q = CLH^{3/2}$$

broadcrested weir (trapezoidal section)
 $B = 14'$ (width of weir)
 $C = 3.1$ (Brater & King)

Reduce L for abutment effects, no piers

$$L = L' - 2(NK_p + K_a)H_a \quad (\text{Design of Small Dams, 1977})$$

$$N = 0 \quad (\text{no piers})$$

$$K_a = 0.2$$

$$H_a = H$$

$$L = 33 - 0.4H$$

weir elev = 1726.1
 embankment elev = 1731.1

$$Q = 3.1 LH^{3/2}$$

<u>H (ft)</u>	<u>L (ft)</u>	<u>Q (cfs)</u>	<u>WSFL</u>
0.7	32.7	59	1726.5
1.5	32.4	185	1727.6
3.0	31.8	512	1729.1
4.5	31.2	923	1730.6
5.0	31.0	1074	1731.1

Embankment Discharge Rating

$$Q = CLH^{3/2}$$

broadcrested weir (trapezoidal)
 $B = 12 \text{ to } 14'$
 $C = 3.1$

Elev 1731	$L = 140 - 33 = 107'$
1734.6	$L = 160 - 33 = 127'$
1740	$L = 560'$



O'BRIEN & GERE

SUBJECT Cl ₂ per Promised Land Dam	SHEET 4	BY DRP	DATE 12/10/75	JOB NO 1541-010
--	------------	-----------	------------------	--------------------

4/15/79

<u>Height</u>	<u>Length</u>	<u>Quoir</u>	<u>Hamb.</u>	<u>Lamb</u>	<u>Quoir</u>	<u>Quoir + Quoir</u>	<u>Elev.</u>
5	31	1074	0	0	0	1074	1731.1
6.5	31	1593	15	116	661	2254	1732.6
8	31	2174	30	124	1997	4171	1734.1
9.5	31	2814	45	170	5030	7844	1735.6

SUBJECT	SHEET	BY	DATE	JOB NO
Upper Promised Land Dam	5	DRP	12/19/73	1841.010

Rte 390 Bridge

located downstream of dam


could act as a control structure

top of road approx 1733, bottom of culvert approx 1714

semicircular opening $r = 12'$

crowns elev = 1726

Headwater Below Crown (Open Channel flow)



assume critical depth: occurs in channel

$d_c = \frac{2}{3}H$

$Q_c = A_c \sqrt{g D_c}$

$A_c = A_1 = A_2 \therefore A_1 = \frac{\pi r^2}{2} = 574'$

$A_2 = \frac{B}{2} (\sqrt{r^2 - D_c^2}) \cdot D_c = 514'$

θ	$D_c (ft)$	$A_c (ft^2)$	$Q_c (cfs)$	Elev
$22\frac{1}{2}^\circ$	4.6	$57 + 51 = 108$	1314	1720.9
45°	8.5	$113 + 72 = 185$	3061	1726.6
$67\frac{1}{2}^\circ$	11.1	$170 + 51 = 221$	4178	1730.6

centroid = $0.576 R = c = 6.9$

$\star 1714 + H = \text{Elev}$

Headwater Above Crown, $H/D < 0.75$

assume well rounded inlet $C_c = 1, K_c = 0$ (Morris & Wiggert)

$Q = A \sqrt{2g \left(H + \frac{V_a^2}{2g} \right)}$

$A = 226.2 ft^2$

Assume $\frac{V_a^2}{2g} \approx 0$

H_p	H/D	$Q (cfs)$	Elev
6.9	0.575	4768	1726
7.9	0.67	5102	1727
8.9	0.75	5415	1728

SUBJECT Upper Promised Land Dam	SHEET 6	BY DRP	DATE 12/19/75	JOB NO 841-010
------------------------------------	------------	-----------	------------------	-------------------

Rev. 4/15/79

Headwater Above crown, $H/D > 1$ *

* For $0.75 < H/D < 1$ oscillating heads occur, producing slug flow the curve will be interpolated in this region.

$$Q = A \sqrt{\frac{2g \left(H + \frac{V_0^2}{2g} + S_b L \right)}{1 + f \left(\frac{L}{D} \right)}} \quad R^{4/3} = \left(\frac{\frac{1}{2} \pi R^2}{\pi R + 2r} \right)^{4/3} = 5.65$$

$$f \left(\frac{L}{D} \right) \approx \frac{29.1 n^2 L}{R^{4/3}} = \frac{29.1 (0.025)^2 (36)}{5.65} = 0.12$$

$$\frac{V_0^2}{2g} \approx 0 \quad S_b L \approx 0$$

$$Q = A \sqrt{\frac{2gH}{1.12}}$$

H_p	H/D	Q (cfs)	Elev
11.9	0.99	5916	1731
12.9	> 1	6160	1732
13.9	> 1	6395	1733

When $H_p > 13.9$ a combination of weir & pressure flow occurs, see following page for computations

weir length is assumed to be 50' at 1733
 " " " approx. 200' at 1740
 " " " " 800' at 1760



SUBJECT	SHEET	BY	DATE	JOB NO
Upper Promised Land Dam	7	DRP	12/20/75	1341-010

Rev 4/15/79

$H_p > 13.9$

H_p (ft)*	Pressure flow Q_p (cfs)	$H_w = H_p - 13.9$	L	Q_{crit}	$Q_p + Q_w$	Elev
15.4	6781	1.5	82	467	7198	1734.5
16.9	7051	3.0	114	1836	8887	1736.0


* assumes reservoir level over orifice

Combined Discharge Rating Curve for Route 370 Bridge

Elev.	Q (cfs)
1714.0	0
1720.0	1314
1726.0	4768
1727.0	5102
1728.0	5415
1731.0	5916
1732.0	6160
1733.0	6395
1734.5	7198
1736.0	8887

SUBJECT	SHEET	BY	DATE	JOB NO
Upper Promised Land Dam	8	DRF	1/2/75	1341-010

Rev 3/15/79





O'BRIEN & GERE

SUBJECT

Upper Promised Land Dam

SHEET

9

BY

DRP


DATE

5/13/79

JOB NO

1841-010

Note: Model using dam
control only
model to 784 cfs



.....
 FLOOD HYDROGRAPH PACKAGE (NEC-11)
 DAM SAFETY VERSION JULY 1978

 LAST MODIFICATION 25 SEP 78

	NATIONAL DAM INSPECTION PROGRAM		PROMISED LAND DAM PROMISED LAND.PA.		PMF HYDROGRAPH		
1	A1		30	0	0	0	0
2	A2						
3	A3						
4	R	150	0				
5	B1	5					
6	J	1					
7	J1	0.2	0.3	0.5	0.6	0.7	0.8
8	K	0	A1				
9	K1						
10			1				
11	P	0	22.2				
12	T						
13	F	2.3	0.45				
14	X	-1.5	-0.05				
15	K						
16	K1	1	A2				
17	Y						
18	V1						
19	V41726.1	1726.8	1727.6	1729.1	1730.6	1731.1	1732.6
20	Y5	0	59	165	512	923	1074
21	SA	0	287	422	460.8	812.8	1216
22	SE1715.1	1720.4	1725.6	1727	1740	1760	
23	SE1726.1						
24	SE1731.1						
25	K						

RUNOFF TO UPPER PROMISED LAND LAKE

ROUTING THROUGH UPPER PROMISED LAND LAKE

sh. 10

.....
 FLOOD HYDROGRAPH PACKAGE (MEC-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 25 SEP 78

RUN DATE 06/06/79.
 TIME 08.14.03.

Sh. 11

NATIONAL DAM INSPECTION PROGRAM
 PROMISED LAND DAM PROMISED LAND, PA.
 PMF HYDROGRPH

NO	NHW	NMIN	IDAY	JMR	IMIN	MFTSC	IPLT	TPBT	NSTAN
150	0	30	0	0	0	0	0	-4	0
			JOPER	NWT	LWOPT	TRACE			
			5	0	0	0			

MULTI-PLAN ANALYSES TO BE PERFORMED
 NPLAN= 1 NRTIO= 4 LRTIO= 1

RTIOS= .20 .30 .40 .50 .60 .70 .80 .90 1.00

.....

SUR-AREA RUNOFF COMPUTATION

RUNOFF TO UPPER PROMISED LAND LAKE

ISTAD	ICOMP	IECON	ITAPE	JPLT	JPBT	INAME	ISTAGF	IAUTO
A1	0	0	3	0	0	1	0	0

HYDROGRPH DATA

IMYDG	IUMG	TAHRA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
1	1	6.57	0.00	6.57	0.00	0.000	0	1	0

PRECIP DATA

SPFE	PMS	R6	R12	R24	R48	R72	R96
0.00	22.20	111.00	123.00	133.00	0.00	0.00	0.00

TRAPC COMPUTED BY THE PROGRAM IS .800

LOSS DATA

LBOPT	STKR	DLTKR	RTIOL	ERAIN	STPKS	RTIOM	STRTL	CNSTL	ALSMX	RTIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	1.00	.05	0.00	0.00

UNIT HYDROGRAPH DATA

TP= 2.30 CP= .45 NTA= 0

RECESSION DATA

STRTO= -1.50 ORCSN= -.05 RTIOR= 2.00

UNIT HYDROGRAPH 43 END-OF-PERIOD ORIGINATES, LAG= 2.30 HOURS, CP= .45 VOL= 1.00

72.	267.	523.	736.	813.	759.	644.	581.	508.	444.
309.	300.	298.	260.	228.	179.	174.	153.	133.	117.
102.	89.	78.	68.	60.	52.	46.	40.	35.	31.
27.	23.	21.	18.	16.	14.	12.	11.	9.	8.
7.	6.	5.	4.	3.	2.	1.	1.	1.	1.

MO,DA MR,MN PERIOD RAIN EXCS LOSS END-OF-PERIOD FLOW
 COMP 0 MO,DA MR,MN PERIOD RAIN EXCS LOSS COMP 0
 SUM 23.62 21.76 1.86 188666.
 (600.1) (553.1) (47.1) (5367.43)

57.12

.....

HYDROGRAPH ROUTING

ROUTING THROUGH UPPER PROMISED LAND LAKE

STAG	1726.10	1727.00	1729.10	1730.00	1731.10	1732.00	1734.10	1735.00
FLO	0.00	59.00	185.00	461.	813.	1216.	1734.10	7646.00
SURFACE AREA	0.	287.	422.	461.	813.	1216.	1734.10	7646.00
CAPACITY	0.	507.	2339.	2957.	11128.	31281.	4171.00	7646.00
ELEVATION	1715.	1726.	1726.	1727.	1740.	1760.	1734.10	1735.00

ICOMP	1	0	0	0	0	0	0	0
ITAPE	0	0	0	0	0	0	0	0
JPLT	0	0	0	0	0	0	0	0
IPRI	0	0	0	0	0	0	0	0
IPMP	0	0	0	0	0	0	0	0
IPMT	0	0	0	0	0	0	0	0
IPSPRAT	0	0	0	0	0	0	0	0
IPSTOR	0	0	0	0	0	0	0	0
IPRAT	0	0	0	0	0	0	0	0

LAG	0	0	0	0	0	0	0	0
AMSK	0	0	0	0	0	0	0	0
TSK	0	0	0	0	0	0	0	0
STORA	0	0	0	0	0	0	0	0
ISPRAT	0	0	0	0	0	0	0	0
ISPRAT	0	0	0	0	0	0	0	0

CREL	1726.1	0.0	0.0	0.0	0.0	0.0	0.0	0.0
SPR	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
COOL	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
CAREA	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
FEXPL	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

TOPEL	1731.1	0.0	0.0	0.0	0.0	0.0	0.0	0.0
COOL	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
EXPD	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
DAMWID	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

PEAK OUTFLOW IS	419.	AT TIME	26.00 HOURS
PEAK OUTFLOW IS	682.	AT TIME	26.00 HOURS
PEAK OUTFLOW IS	953.	AT TIME	26.00 HOURS
PEAK OUTFLOW IS	1625.	AT TIME	25.00 HOURS
PEAK OUTFLOW IS	1977.	AT TIME	24.50 HOURS
PEAK OUTFLOW IS	2623.	AT TIME	24.00 HOURS
PEAK OUTFLOW IS	3339.	AT TIME	23.50 HOURS

Sh. 13

PEAK OUTFLOW IS 4627. AT TIME 23.00 HOURS

PEAK OUTFLOW IS 5469. AT TIME 22.00 HOURS

.....

St. 14

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS								
				RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7	RATIO 8	RATIO 9
HYDROGRAPH AT	A1	6.57	1	2380.	3571.	4761.	5951.	7141.	8332.	9522.	10712.	11902.
	(17.02)	(67.41)	101.11)	134.82)	168.52)	202.22)	235.93)	269.63)	303.33)	337.04)
ROUTED TO	A2	6.57	1	419.	682.	953.	1425.	1977.	2623.	3339.	4071.	5449.
	(17.02)	(11.88)	19.32)	26.98)	40.35)	56.00)	74.28)	94.56)	114.03)	154.26)

Sh. 15


SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION STORAGE OUTFLOW	INITIAL VALU	SPILLWAY CREST	TOP OF DAM	RATIO OF PMF	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
	1726.30	1726.10	1731.10		.20	1728.68	3762.	419.	0.00	26.00	0.00
	2641.	2554.	5046.		.30	1729.72	4799.	682.	0.00	26.00	0.00
	17.	0.	1074.		.40	1730.70	4825.	953.	0.00	26.00	0.00
					.50	1731.55	5301.	1425.	9.00	25.00	0.00
					.60	1732.25	5710.	1977.	14.00	24.50	0.00
					.70	1732.89	6094.	2623.	17.00	24.00	0.00
					.80	1733.45	6434.	3339.	19.00	23.50	0.00
					.90	1733.99	6778.	4027.	20.50	23.00	0.00
					1.00	1734.31	6988.	5449.	21.50	22.00	0.00

APPENDIX

D


Photographs




**UPSTREAM FACE OF DAM
LOOKING TOWARDS THE SPILLWAY**



**LEFT ABUTMENT OF THE
UPSTREAM FACE OF THE DAM**



**RIGHT ABUTMENT OF THE
UPSTREAM FACE OF THE DAM**



**VIEW OF THE SPILLWAY SHOWING
SPALLING ON THE RIGHT SIDEWALL**




*VIEW OF THE RESERVOIR
FROM THE RIGHT SIDE
OF THE DAM LOOKING
UPSTREAM*




*EROSION ALONG THE
RIGHT WINGWALL OF
THE SPILLWAY LOOK-
ING DOWNSTREAM*



*DOWNSTREAM FACE AND TOE AT THE
RIGHT SIDE OF THE DAM*



*CHANNEL DOWNSTREAM OF THE DAM
SHOWING THE CULVERT UNDER STATE ROUTE 390*



VIEW OF THE OUTLET CONDUIT

APPENDIX

E

Drawings

SUBJECT Promised Land Dam	SHEET	BY	DATE	JOB NO
------------------------------	-------	----	------	--------

TABLE OF CONTENTS APPENDIX E

Regional Vicinity Map	_____	Plate 1
Proposed Repairs (1929 - 1930)	_____	" 2 #3
Proposed Outlet Conduit (1935)	_____	" 4
Plan View of Dam Showing Problem Areas	_____	" 5






PLATE 1
 REGIONAL
 VICINITY MAP
 SCALE 1:24000






PROPOSED REPAIRS
 PROMISED LAND DAM
 PIKE COUNTY PENNA.

FILE NO 22-12
 SEPT 20, 1919
 [Signature]



CROSS SECTIONS
Scale 1" = 10' Vertical
1" = 20' Horizontal





- Notes:
1. Crest Length - Approx. 125'
 2. Crest Width - Approx. 12' to 14'
 3. Spillway Length - Approx. 93'

Plate 5
 Promised Land Dam
 NOT TO SCALE

APPENDIX

F

Site Geology

SITE GEOLOGY
PROMISED LAND DAM

Promised Land Dam is situated in Pike County and within the limits of the Eastern Glaciated section of the Appalachian Plateau physiographic province. Thick deposits of glacially derived debris and till cover the nearly horizontally bedded, red, gray and green shale and sandstone units of the Devonian Catskill group of marine and continental sediments. The dam and lake both rest on glacial till and ground moraine deposits which are dense, compact and relatively impermeable. Prior to construction of the lake the area was covered with high valley swamps and bogs, attesting somewhat to the compactness and impervious nature of the dense, glacial till mantle.

No known faults or major structural defects occur in the bedrock in the vicinity of the dam and lake.

