

AD-A072 250

BAKER (MICHAEL) JR INC BEAVER PA
NATIONAL DAM INSPECTION PROGRAM. MATHAY DAM (NDI NUMBER PA-0024--ETC(U)
JUL 79 C Y CHEN


F/G 13/2
DACW31-79-C-0011
NL

UNCLASSIFIED

| OF |
AD
A072250




END
DATE
FILMED
9-79
DDC



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

ADA 072250

CONROCK BASIN
SOUTH AND CENTER DIVISION
PENNSYLVANIA




ROCKY DAM

LEVEL TH

CONTRACT NO. 3-48
PAGE NO. 4-48
SHEET NO. PA 48


PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM



Distribution Unlimited
Approved for Public Release
Contract No. DACW31-79-C-0011 ✓

DEPARTMENT OF THE ARMY
Engineer District, Corps of Engineers
Beltsville, Maryland 21033

by
MICHAEL BAKER, JR., P.E.
Consulting Engineer
1000 Green Ridge Road
Baltimore, Maryland 21209



THIS REPORT CONTAINS COLOR PLATES; ALL DDC
REPRODUCTIONS WILL BE IN BLACK AND WHITE

79 08 06 074

OHIO RIVER BASIN

MATHAY DAM
MERCER COUNTY, COMMONWEALTH OF PENNSYLVANIA
NDI No. PA 00247
PennDER No. 43-46
SCS No. PA 459

10 Chuan Yuan / Chen

11 Jul 79

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

6 National Dam Inspection Program. Mathay Dam (NDI Number PA-00247, PennDER Number 43-46, SCS Number PA-459), Ohio River Basin, Mathay Run, Mercer County, Pennsylvania. Phase I Inspection Report,

12 79p

Prepared for: DEPARTMENT OF THE ARMY
Baltimore District, Corps of Engineers
Baltimore, Maryland 21203

Prepared by: MICHAEL BAKER, JR., INC.
Consulting Engineers
4301 Dutch Ridge Road
Beaver, Pennsylvania 15009

15 DACW31-79-C-0011

DISTRIBUTION STATEMENT A
Approved for public release;
Distribution Unlimited

JOB

410 795 79 08 06 074

PREFACE

This report was prepared under guidance contained in the "Recommended Guidelines for Safety Inspection of Dams," for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I Inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

Accession For	NTIS GRA&I		
	DDC TAB		
	Unannounced		
	Justification		
By			
Distribution/			
Availability Codes			
Availand/or			
Dist special			
Dist	A		

**PHASE I REPORT
NATIONAL DAM INSPECTION PROGRAM**

**Mathay Dam, Mercer County, Pennsylvania
NDI No. PA 00247, PennDER No. 43-46, SCS No. PA 459
Mathay Run
Inspected 26 April 1979**

**ASSESSMENT OF
GENERAL CONDITIONS**

Mathay Dam is a homogeneous earth floodwater retarding dam designed by the U.S. Department of Agriculture, Soil Conservation Service (SCS) and owned by the Mercer County Commissioners. The dam has a crest length of approximately 3260 feet, a maximum height of 22 feet, and a maximum storage capacity of 755 acre-feet. Mathay Dam is classified as a "High" hazard-"Small" size dam.

Hydraulic/hydrologic evaluations, performed in accordance with procedures established by the Baltimore District, Corps of Engineers, for Phase I Inspection Reports, revealed that the spillway will pass the Probable Maximum Flood (PMF) without overtopping the dam. The spillway is therefore considered "adequate."

The dam was found to be in good overall condition at the time of inspection. Several minor items of remedial work should be performed by the owner as soon as practicable. These include:

- 1) Fill the animal burrows in the embankment and establish a rodent control program.
- 2) Cut the few small scattered clumps of brush on the dam and in the emergency spillway.
- 3) Repair the minor areas of erosion and rutting on the dam.
- 4) Periodically inspect the seepage drain outlets, and the intake and outlet of the principal spillway for buildup of debris which could cause blockage.
- 5) Place riprap around the plunge pool to prevent ongoing erosion.

In addition, the following operational measures are recommended to be undertaken by the owner:

- 1) Develop a detailed emergency operation and warning system.
- 2) During periods of unusually heavy rain, provide around-the-clock surveillance of the dam.
- 3) When warning of a storm of major proportions is given by the National Weather Service, the owner should activate the emergency operation and warning system.

Submitted by:

MICHAEL BAKER, JR., INC.



C. Y. Chen
C. Y. Chen, Ph.D., P.E.
Engineering Manager-Geotechnical

Date: 6 July 1979


Approved by:

DEPARTMENT OF THE ARMY
BALTIMORE DISTRICT, CORPS OF ENGINEERS

James W. Peck
JAMES W. PECK
Colonel, Corps of Engineers
District Engineer

Date: 21 July 1979

MATHAY DAM



Overall View

TABLE OF CONTENTS

	<u>Page</u>
Section 1 - Project Information	1
Section 2 - Engineering Data	6
Section 3 - Visual Inspection	8
Section 4 - Operational Procedures	10
Section 5 - Hydraulic/Hydrologic	11
Section 6 - Structural Stability	13
Section 7 - Assessment, Recommendations/Remedial Measures	14

PLATES

Plate 1 - Location Plan
Plate 2 - Watershed Map
Plate 3 - Plan of Storage Areas
Plate 4 - Plan of Dam Site
Plate 5 - Profiles of Dam
Plate 6 - Plan and Profile of Emergency Spillway
Plate 7 - Seepage Drain Details
Plate 8 - Plan and Profile of Principal Spillway

APPENDICES

Appendix A - Check List - Visual Inspection and Field Sketch
Appendix B - Check List - Engineering Data
Appendix C - Photographs
Appendix D - Hydrologic and Hydraulic Computations
Appendix E - Regional Geology

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM
MATHAY DAM

NDI No. PA 00247, PennDER No. 43-46, SCS No. PA 459

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

- a. Authority - The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.
- b. Purpose of Inspection - The purpose of the inspection is to determine if the dam constitutes a hazard to human life or property.

1.2 DESCRIPTION OF PROJECT

- a. Description of Dam and Appurtenances - Mathay Dam, a flood water retarding dam designed by the U.S. Department of Agriculture, Soil Conservation Service (SCS), is also known by its SCS number PA 459. The dam is a homogeneous earth embankment with a crest length of approximately 3260 feet and a maximum height of about 22 feet. The material available for construction of the dam consisted primarily of silty (ML) and silty clay (ML-CL) soils, with a lesser amount of silty sand (SM) soil. A 5-foot deep foundation cutoff trench with a base width of 15 feet was constructed along the centerline of the dam from Station 13+30 to Station 19+34. A filter trench with two drain outlets was installed in the main embankment from Station 14+94 to Station 18+41 (see Plate 7).

The outlet works (principal spillway in SCS terminology) consists of a two-stage inlet reinforced concrete riser unit and 36-inch reinforced concrete outlet pipe. The concrete riser has a low stage orifice 1 foot by 2 feet in size with invert elevation of 1207.8 feet. This low stage orifice controls the sediment pool level. The second stage is an overflow weir on both sides of the riser unit. These weirs are 9-feet long and have a crest elevation of 1212.0 feet. A pond drain consisting of 20 feet of 24-inch bituminous coated corrugated metal pipe extends upstream from the riser. The entrance of the pond drain to the

riser unit is bolted closed with a steel plate (see Plate 8). [Note: Siphons have been used to drawdown the pool approximately 2 feet for inspection purposes and could easily be used again if necessary.] The outlet pipe, with three reinforced concrete anti-seep collars, was installed on a concrete cradle founded on compacted clay (CL) material. Approximately 5 feet of backfill CL material overlies the bedrock under the outlet pipe.

The spillway (emergency spillway in SCS terminology) consists of a vegetated earth channel curving around the left end of the dam. The elevation of the control section of the spillway is 1218.0 feet or 5.2 feet below the embankment crest level. The emergency spillway is approximately 2500-feet long and 110-feet wide at the base, and has 3H:1V (Horizontal to Vertical) side slopes. Riprap protection was provided at the curve of the emergency spillway channel for the excavated natural slope, the dam embankment slope and the small dike along the left of the emergency spillway channel.

- b. Location - Mathay Dam is located on Mathay Run approximately 2 miles southeast of Greenville in Hempfield Township, Mercer County, Pennsylvania. The dam is located approximately 2 miles east of PA Route 58 and 2.5 miles south of PA Route 358. The coordinates of the dam are N 41° 23.0' and W 80° 20.7'.
- c. Size Classification - The maximum height of the dam is 22 feet and the reservoir volume to the top of dam (El. 1223.2 feet) is approximately 755 acre-feet. The dam is therefore considered to be in the "Small" size category.
- d. Hazard Classification - In the event of failure of Mathay Dam, it is likely that "more than a few" lives would be lost and economic losses would be "excessive." The dam is therefore considered to be in the "High" hazard category.
- e. Ownership - The dam is owned by the Mercer County Commissioners, Mercer County Courthouse, Mercer, Pennsylvania 16137.
- f. Purpose of Dam - The dam is used for floodwater detention.

- g. Design and Construction History - Mathay Dam was designed by the SCS under the authority of the Watershed Protection and Flood Prevention Act, Public Law 566, as amended. The dam was constructed by Hilliard Mining Co., RD #7, Butler, Pennsylvania from early Spring 1961 to final acceptance on 13 August 1962.
- h. Normal Operating Procedures - The spillway is uncontrolled and the sediment pool level is El. 1208+ feet. Mercer County and SCS personnel inspect the dam each year according to standard procedures for SCS dams of this type. Maintenance is performed, when deemed necessary, by Mercer County personnel.

1.3 PERTINENT DATA

- a. Drainage Area (square-miles) - 1.4
- b. Discharge at Dam Site (c.f.s.) -

Maximum Flood -	Unknown
Principal Spillway Capacity (at Pool El. 1223.2 ft.) -	160
Emergency Spillway Capacity (at Pool El. 1223.2 ft.) -	3720
Total Spillway Capacity (at Pool El. 1223.2 ft.) -	3880
- c. Elevation (feet above Mean Sea Level [M.S.L.]) -

Design Top of Dam -	1223.2
Minimum Top of Dam -	1223.2
Sediment Pool -	1207.8
Maximum Pool (Phase I Analysis*) -	1221.1
Emergency Spillway Crest -	1218.0
Streambed at Centerline of Dam -	1201
Maximum Tailwater -	Unknown
- d. Reservoir (feet) -

Length of Maximum Pool -	1150
Length of Sediment Pool -	500
Length of Flood Control Pool -	1050

* See Appendix D.

e. Storage (acre-feet) -

Sediment Pool (El. 1207.8 ft.) -	18.5
Flood Control Pool (El. 1218.0 ft.) -	325
Top of Dam (El. 1223.2 ft.) -	755

f. Reservoir Surface (acres) -

Sediment Pool (El. 1207.8 ft.) -	8
Flood Control Pool (El. 1218.0 ft.) -	70
Top of Dam (El. 1223.2 ft.) -	96

g. Dam -

Type - Homogeneous earthfill

Length (feet) - 3260

Height (feet) - 22

Top Width (feet) - 12

Side Slopes - Upstream - 3H:1V
(with 10-foot berm at El. 1207.5 ft.)
Downstream - 2.5H:1V

Zoning - None

Impervious Core - None

Cutoff - A 5-foot deep compacted fill cutoff trench was constructed from Station 13+30 to Station 19+34. The base width was 15 feet with 1H:1V construction side slopes (see Plate 5).

Grout Curtain - None

Drains - A 5- to 8-foot deep filter trench was installed from Station 14+94 to Station 18+41. Two perforated 8-inch diameter corrugated metal drainpipes were installed to drain the filter trench. These two drains outlet on either side of the principal spillway outlet pipe into the plunge pool.

h. Diversion and Regulating Tunnel - None

i. Spillway (Emergency Spillway in SCS Terminology) -

Type - Vegetated earth channel located at left end of the dam

Length (feet) - 2500

Base Width (feet) - 110

Side Slopes - 3H:1V

Crest Elevation (feet M.S.L.) - 1218.0

Gates - None

Downstream Channel - Well vegetated earth channel flowing into natural streambed

j. Regulating Outlets (Principal Spillway in SCS Terminology) -

Type - Two-stage inlet riser and 36-inch reinforced concrete outlet pipe

First Stage Orifice -

Crest Elevation (feet M.S.L.) - 1207.8

Width (feet) - 2.0

Height (feet) - 1.0

Second Stage Overflow Weir -

Crest Elevation (feet M.S.L.) - 1212.0

Length (feet)* - 9

Vertical Clearance (feet) - 1

Outlet Pipe - Consists of a 36-inch reinforced concrete pipe supported on a concrete cradle. Three reinforced concrete anti-seep collars were provided on approximately 24-foot centers from the downstream edge of the intake riser. The remaining 59 feet of the approximately 130-foot long outlet pipe is not provided with anti-seep collars.

Riser Floor Invert Elevation

(feet M.S.L.) - 1201.0

Outlet Conduit Exit Invert Elevation

(feet M.S.L.) - 1200.0

* On each of two sides of the riser.

SECTION 2 - ENGINEERING DATA

2.1 DESIGN

Mathay Dam was designed by the SCS according to its standard practice for structures of this type, circa 1960. Design data reviewed or included in this report were obtained from:

- 1) SCS Drawings No. PA-459-P, "Saul-Mathay Watershed Project, Floodwater Retarding Dam PA-459, Mercer County, Pennsylvania," April 1961. (Prints of the design drawings are available in the Pennsylvania Department of Environmental Resource's [PennDER] files. Prints of the "as built" drawings are available in both the SCS Harrisburg office and the Mercer County Conservation District Office in Mercer. Sheets 2-7 of the "as built" drawings are included in this report as Plates 3-8.)
- 2) SCS Drawings No. PA-459-H, "Saul-Mathay Watershed Protection Project PA-459, Mercer County, Pennsylvania," June 1961, 2 sheets of hydrograph drawings. (Prints are available in PennDER's files.)
- 3) "Saul-Mathay Watershed Work Plan," report prepared by the Mercer County Commissioners, et. al., March 1960 (copy in file of Mercer County Conservation District Office in Mercer, Pennsylvania).
- 4) Dam Permit Application Report prepared by the Pennsylvania Department of Forests and Waters (predecessor of PennDER) on 7 July 1961.
- 5) Design information (including boring and test pit logs, laboratory soil data, and design calculations in files of the SCS Harrisburg office).
- 6) The PennDER file for the dam (including SCS inspection reports and various correspondence).

2.2 CONSTRUCTION

There was no information reviewed concerning the construction of the dam which indicates concern for the safety of the dam. Resident construction inspection was provided by the SCS. Modifications and the post-construction surveys of the dam were incorporated into

the "as built" drawings. Most of these drawings have been included in this report; however, all additional drawings are available in the files of the SCS Harrisburg office and the Mercer County Conservation District office.

2.3 OPERATION

The "Saul-Mathay Watershed Work Plan" and a subsequent agreement between the Mercer County Commissioners and the SCS detail the provisions for operation and maintenance of this structure.

2.4 EVALUATION

- a. Availability - The information was readily available from PennDER's file No. 43-46, the files of the SCS Harrisburg office and the Mercer County Conservation District office in Mercer, Pennsylvania.
- b. Adequacy - The information available is adequate for a Phase I Inspection of this dam.
- c. Validity - Observations and measurements performed during the visual inspection did not indicate any deviations from the information on the "as built" drawings.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

- a. General - The dam and its appurtenant structures were found to be in good overall condition at the time of the inspection. (During the inspection intermittent rain showers occurred.) Noteworthy deficiencies observed are described briefly in the following paragraphs. The complete visual inspection check list and field sketch are given in Appendix A.
- b. Dam - The two seepage drain outlets on either side of the principal spillway outlet conduit were partially clogged with silt and vegetation. After clearing this debris, a minor amount of flow exited from the drains. A drain outlet along the left side of the upstream portion of the emergency spillway channel was totally clogged with silt and debris. From the volume of water that exited after the drain was opened, it is estimated the drain was completely filled with water.

Rodent holes were observed in the downstream embankment at the following locations:

- 1) Midheight of downstream slope at approximate original Station 12+50.
- 2) Two holes at the midheight of the downstream slope at approximate original Station 17+50.
- 3) Two holes at the toe of the embankment at approximate original Station 24+00.
- 4) On the upstream face approximately 50 feet from the right end of the dam.

A minor amount of brush was present along the toe of the embankment and in the emergency spillway channel. Also observed were a few areas where the vegetation is absent and minor rutting has occurred. These items can be repaired during routine maintenance.

- c. Appurtenant Structures - Overall, the concrete in the intake and outlet structures of the principal spillway is in good condition. A minor amount of debris was on the trash rack of the riser orifice at the time of inspection. Minor erosion is occurring around the outlet plunge pool.

- d. Reservoir Area - The area surrounding the reservoir is moderately sloping farmland. A few wooded areas are located throughout the watershed. No significant amount of sedimentation has occurred; however, a minor amount of the reservoir shoreline is eroding and washing into the reservoir.
- e. Downstream Channel - The original stream channel of Mathay Run forms the downstream outlet channel. Approximately six homes are located in low lying areas in the first 6000 feet downstream of the dam. Several other residences are located along the stream's remaining two mile course to the Shenango River, including areas which were noted to have sustained damage during the 1956 flood in Greenville. Between the dam site and the confluence of the Shenango River and Saul Run are five roadway culverts and two railroad culverts. The Mathay Run and Saul Run confluence is approximately 2.7 miles from the dam, and the Shenango River and Saul Run confluence is approximately 3.5 miles from the dam.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES

There are no formal emergency procedures in the event of impending catastrophic failure of the dam. The condition of the dam is reportedly checked by Mercer County personnel following each occurrence of heavy precipitation. Partial drawdown of the pool was accomplished previous to the inspection by siphoning the reservoir into the intake riser, since the pond drain has a steel plate bolted on its inlet to the riser.

It is recommended that formal emergency procedures be prepared, prominently displayed, and furnished to all operating personnel.

4.2 MAINTENANCE OF DAM AND APPURTENANCES

Maintenance of the dam is the responsibility of Mercer County and is administered through the Mercer County Conservation District. Routine maintenance is performed periodically (when necessary) by Mercer County personnel.

4.3 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT

There is no formal warning system or procedure in the event of a dam failure. A formal warning procedure should be developed.

4.4 EVALUATION OF OPERATIONAL ADEQUACY

The present operational and maintenance procedures are adequate for Mathay Dam.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

- a. Design Data - Design plans for the Saul-Mathay Watershed Project were obtained from PennDER. Contained in these plans were hydrographs for the design flood routing and for the freeboard flood routing. The design flood routing for the emergency spillway was based on a hydrograph developed using a 6-hour rainfall of 9.6 inches, resulting in a peak discharge of 3240 c.f.s. The freeboard flood routing was based on a hydrograph developed using a 6-hour rainfall of 19.2 inches, resulting in a peak discharge of 6685 c.f.s. In accordance with normal SCS design practices, these flood routings were used to establish the elevations of the design high water and design top of dam, respectively.
- b. Experience Data - Prior to the construction of the existing structure, this watershed had experienced several floods resulting in severe damage to downstream bridges and inundation of several homes to various degrees. Since construction of the dam, however, flooding has not been a problem. According to the representative from the Mercer County Conservation District, the reservoir level has never reached the riser crest (El. 1212.0 feet).
- c. Visual Observations - At the time of the inspection, no condition was observed that would indicate that the spillway and outlet works could not operate satisfactorily in the event of a flood.
- d. Overtopping Potential - Mathay Dam is classified as a "High" hazard-"Small" size dam requiring evaluation for a spillway design flood (SDF) in the range of the 1/2 Probable Maximum Flood (1/2 PMF) to the Probable Maximum Flood (PMF). Since the dam has a storage capacity nearly equal to that of an "Intermediate" size dam, the PMF was chosen as the SDF. The spillways consist of a typical SCS concrete riser and a vegetated earth side channel. The hydrologic and hydraulic capabilities of the reservoir and spillways were evaluated by routing the PMF through the reservoir with the aid of the U.S. Army Corps of Engineer's Flood Hydrograph Package, HEC-1. The PMF hydrograph developed as part of this analysis had a peak discharge of 2038 c.f.s., using a 6-hour rainfall of 22.0 inches. The results of this

routing indicate that the reservoir and spillways are capable of passing the PMF with a maximum reservoir level of El. 1221.1 feet, which is about 2.1 feet below the minimum crest of dam El. 1223.2 feet. The maximum discharge from the reservoir under these conditions is 1714 c.f.s.

- e. Spillway Adequacy - The dam, as outlined in the above analysis is capable of passing the PMF without overtopping. Therefore, the spillway is "adequate" according to the recommended criteria.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

- a. Visual Observations - No structural inadequacies were noted during the visual inspection of the dam.
- b. Design and Construction Data - The dam was designed and constructed according to standard SCS procedures for structures of this type. According to the information in the files of the SCS Harrisburg office, the slopes have satisfactory slope stability safety factors for the configuration of the dam as constructed and the type of material available at the dam site for construction. Based upon this information and the visual observations of the dam, it is concluded that no further assessment of the structural stability is necessary.
- c. Operating Records - Nothing in the readily available operating information indicates cause for concern relative to the structural stability of the dam.
- d. Post-Construction Changes - No changes which would affect structural stability of the dam have been made since construction was completed.
- e. Seismic Stability - The dam is located in Seismic Zone 1 of the "Seismic Zone Map of the Contiguous United States," Figure 1, page D-30, "Recommended Guidelines for Safety Inspections of Dams." This is a zone of very low seismic activity. Experience indicates that dams in this zone will have adequate stability under seismic loading conditions provided static stability conditions are satisfied and conventional safety margins exist. Mathay Dam could be shown to meet the conventional static stability requirements and, therefore, further consideration of the seismic stability is not warranted.

SECTION 7 - ASSESSMENT, RECOMMENDATIONS/REMEDIAL MEASURES

7.1 DAM ASSESSMENT

- a. Safety - Mathay Dam was found to be in good overall condition at the time of inspection. Mathay Dam is a "High" hazard-"Small" size dam requiring a spillway capacity equal to the PMF. As presented in Section 5, the spillways and reservoir are adequate to pass the PMF without overtopping the dam.
- b. Adequacy of Information - The information available and the observations made during the field inspection are considered sufficient for this Phase I Inspection Report.
- c. Urgency - The owner should initiate the action discussed in paragraph 7.2 as soon as practicable.
- d. Necessity for Additional Data/Evaluation - No further investigation is necessary.

7.2 RECOMMENDATIONS/REMEDIAL MEASURES

The inspection revealed certain items of remedial work which should be performed by the owner. These include:

- 1) Fill the animal burrows in the embankment and establish a rodent control program.
- 2) Cut the few small scattered clumps of brush on the dam and in the emergency spillway.
- 3) Repair the minor areas of erosion and rutting on the dam.
- 4) Periodically inspect the seepage drain outlets and the intake and outlet of the principal spillway for buildup of debris which could cause blockage.
- 5) Place riprap around the plunge pool to prevent ongoing erosion.

In addition, the following operational measures are recommended to be undertaken by the owner:

- 1) Develop a detailed emergency operation and warning system.

- 2) During periods of unusually heavy rain, provide around-the-clock surveillance of the dam.
- 3) When warning of a storm of major proportions is given by the National Weather Service, the owner should activate the emergency operation and warning system.

PLATES





PLATE I LOCATION PLAN
MATHAY DAM






PLATE 2 WATERSHED MAP
MATHAY DAM



FOUNDATION INVESTIGATION - FEB. '64
 WIPED CLASSIFICATION SYMBOLS BY VISUAL INSPECTION

**TP 103
ELEV. 12122**
 ON TOPSOIL

30 SM - SILTY SAND WITH CONSIDERABLE GRAVEL. MOTTLED FIRST 2'-6" THEN BROWN TO DARK BROWN. MORE SANDS THAN SILT.

45 SM

60 SM

75 SM

90 SM

105 ML

BOTTOM OF HOLE SHOWS GREY, GRANULAR

**TP 102
ELEV. 12081**
 TOPSOIL BROWN

0-2 ML - SILTY SANDY CLAY MOTTLED YELLOW BROWN.

30 IM - DIRTY SANDY GRAVEL SAND FRACTIONS

50 ML

60 SM - COARSE SAND WITH CONSIDERABLE GRAVEL. STRONG JEP

75 SM

90 SM

105 ML

**TP 101
ELEV. 12057**
 TOPSOIL

0-2 ML - SILTY MOTTLED YELLOW BROWN. TOPSOIL WITH SAND

30 ML - THIN SILTY SANDY BLUE SAND. COLOR CHANGING TO BROWN BROWN

45 ML - THIN SILTY SANDY BLUE SAND. COLOR CHANGING TO BROWN BROWN

60 ML

75 ML

90 ML

105 ML

**TP 105
ELEV. 12171**
 TOPSOIL BROWN

0-2 ML - SILTY SANDY MOTTLED YELLOW BROWN

30 ML - SILTY SANDY GRAVEL MOTTLED YELLOW BROWN. BEARING EST. 2-4 TONS PER SQ. FT.

45 ML - SILTY SANDY GRAVEL BROWN GREY WITH FRACTIONS OF SAND GRAVEL

60 ML

75 ML

90 ML

105 ML

**TP 104
ELEV. 12093**
 TOPSOIL

0-2 CL - SILTY SANDY CLAY MOTTLED GREY TO YELLOW. ESTIMATED BEARING 2-4 TONS. HOLE CAME IN RANDOMLY.

30 ML - SILTY BROWN VERY FINE SAND

45 ML - GREY SILTY FINE GRAVEL DARK BROWN GREY

60 ML

75 ML

90 ML

105 ML

**TP 110
ELEV. 12057**
 TOPSOIL - DARK BROWN TO BLACK IN WELLS

0-2 SM - GREY YELLOW SAND WITH SILT

30 SM - GREY YELLOW SAND WITH FRACTIONS OF SILT WITH GRAVEL

45 SM

60 SM - THIN SILTY SAND WITH FINE SAND. FINE SANDS 2-4 TONS BEARING. TOPSOIL BROWN. MORE SANDS THAN SILT.

75 SM - THIN SILTY SAND WITH FINE SAND. FINE SANDS 2-4 TONS BEARING. TOPSOIL BROWN. MORE SANDS THAN SILT.

90 SM - THIN SILTY SAND WITH FINE SAND. FINE SANDS 2-4 TONS BEARING. TOPSOIL BROWN. MORE SANDS THAN SILT.

105 SM

**TP 108
ELEV. 12048**
 TOPSOIL, DARK BROWN

0-2 IM - CLAYEY SAND OR SILTY SAND YELLOW BROWN. BEARING EST. 2-4 TONS

30 ML - SANDY SILTY YELLOW, BROWN.

45 ML

60 ML - SANDY SILTY BLUE GRAY COLOR. HOLE COLLAPSED THIS SAND. MOIST

75 ML - SILTY SANDY BLUE BROWN. BEARING EST. 2-4 TONS. ANGULAR GRAVEL

90 ML

105 ML

**TP 106
ELEV. 12398**
 TOPSOIL

0-2 ML - FINE SILTY SAND

30 ML - SILTY YELLOW BROWN SAND

45 ML - YELLOW GREY IN CLAY

60 SM - SAND SILTY BROWN-TAN DARK HUE COLOR WITH GRAVEL. SAND 50 FRACTIONS

75 SM

90 SM

105 ML - SILTY SANDY GRAVEL WITH FINE SAND.

**TP 107
ELEV. 12115**
 TOPSOIL - BROWN

0-2 ML - SILTY SANDY SILTY BROWN

30 ML - COARSE GRAVEL MOTTLED YELLOW BROWN WITH GRAVEL. FINE SAND


45 ML

60 ML - COARSE GRAVEL BROWN GREY COLOR WITH FRACTIONS OF SILT WITH GRAVEL. FRACTIONS UP TO 10" DIA.

75 ML

90 ML

105 ML



THIS PLAN IS BEST QUALITY REPRODUCTION FROM COPY FURNISHED TO DDO

- LEGEND**
- CENTER LINE
 - TEST PIT
 - CONTROL
 - FENCE LINE

AS BUILT PLANS
PLATE 3 S.C.E. 1200'

SAUL - MATHAY WATERSHED PROJECT
 MERCER COUNTY, PENNSYLVANIA
 FLOODWATER RETARDING DAM PA-459
 MERCER COUNTY
PLAN OF STORAGE AREAS
 U.S. DEPARTMENT OF AGRICULTURE
 SOIL CONSERVATION SERVICE

Drawn by R W DOWOLF	Apr 61	Approved by G E VAN BUREN	Apr 61
Checked by R R DOWOLF	Apr 61	Drawn by G E VAN BUREN	Apr 61
Checked by G E VAN BUREN	Apr 61	Checked by G E VAN BUREN	Apr 61

PA-459-P

TP 105 ELEV 1239

- 05' ML - FINE SAND
- 10' ML - LT YELLOW BROWN SILT
- 15' ML - YELLOW GRAY IN CLAY
- 20' ML - SAND SILEX BROWN-TAN DARK RED CLAY WITH GRAVEL & SOME SD PEBBLES
- 25' ML - SAT OR UNSAT SAND WITH FINE SAND


TP 106 ELEV 1215

- 05' ML - FINE SAND
- 10' ML - LT BROWN SILT
- 15' ML - LT BROWN SILT
- 20' ML - SAND SILEX BROWN-TAN DARK RED CLAY WITH GRAVEL & SOME SD PEBBLES
- 25' ML - SAT OR UNSAT SAND WITH FINE SAND

TP 107 ELEV 1215

- 05' ML - FINE SAND
- 10' ML - LT BROWN SILT
- 15' ML - LT BROWN SILT
- 20' ML - SAND SILEX BROWN-TAN DARK RED CLAY WITH GRAVEL & SOME SD PEBBLES
- 25' ML - SAT OR UNSAT SAND WITH FINE SAND


C.C.V.E DATA
 R=100' M=617
 Δ=135° E
 L=25.76-9.569
 C=1048 FT-7-21.5
 T=5141



LAYOUT OF EMERGENCY SPILLWAY CURVE
 SCALE: 1"=50'

STATION	DEFL. Z	S.P.ORD
PC 7-26.9	0° 00'	-
7-34.5	5° 00'	17.4
7-42.1	10° 00'	17.4
7-49.7	15° 00'	17.4
8-07.3	20° 00'	17.4
8-14.9	25° 00'	17.4
8-22.5	30° 00'	17.4
8-30.1	35° 00'	17.5
8-37.7	40° 00'	17.5
8-45.3	45° 00'	17.5
7-52.9	50° 00'	17.5
7-60.5	55° 00'	17.5
7-68.1	60° 00'	17.4
PT 7-21.5	67° 30'	26.1

- LEGEND**
- CONTOUR 1200
 - SPILLWAY
 - SEC. PCDL
 - TEST FIT
 - BRASS MAN
 - CENTER LINE
 - FENCE




SCALE P=200'

DETAIL 'B'
 NOT TO SCALE

LAYOUT OF

THIS PAGE IS BEST QUALITY REPRODUCTION FROM COPY FURNISHED TO DDC



SCALE: 1" = 100'

DETAIL "A"
SCALE: 1" = 40'

LAYOUT OF PRINCIPAL SPILLWAY
SCALE: 1" = 50'


DETAIL "B"
NOT TO SCALE

PLATE 4

SALL - MATHAY - WATERSHED PROJECT
MERCER COUNTY, PENNSYLVANIA
FLOODWATER RETARDING DAM PA-459
MERCER COUNTY
DAMSITE

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

Designed by R. W. DUNN	Date Apr. 51	Reviewed by []
Checked by R. W. DUNN	Date Apr. 51	Approved by []
Drawn by []	Date []	Project No. PA-459-F



CONSTRUCTION ELEVATIONS

CONSTRUCTION ELEVATIONS

CENTERLINE OF DAM STATIONING

PROFILE ALONG DAM CENTERLINE

SCALE: 1" = 100' HORIZ
1" = 2' VERT

EXTENT OF TRENCH
(LIMIT OF 100' FROM 1+00)

Reference: Telephone call to Civil Dept on 9/1/50
Legend: bottom width 10' with 1:1 side slopes
Using scraper to excavate the contractor made it larger - per legend - 100%
Latest search completed 15' bottom, 1/2/55

Removal with
heavy sand jacket
Sept. 9 - Survey Cont. of
10/7/55


APPROX. WIDTH OF CUTOFF TRENCH
ACTUAL BORDERS TO BE DETERMINED
BY THE ENGINEER IN THE FIELD

CUTOFF CENTERLINE STATIONING
(CONV. OF 7-1414 & 22)


PROFILE ALONG CUTOFF TRENCH CENTERLINE



SCALE: 1" = 100' HORIZ
1" = 2' VERT

RICK RIP-RAP SHALL BE WELL GRADED FROM 6" TO 18" (SEE SPEC 17).




PLAN OF EMERGENCY SPILLWAY DIKES
SCALE = 1" = 60.0'







PLAN OF SEEPAGE DRAIN
SCALE 1" = 40'



PROFILE ALONG & OF FILTER TRENCH
SCALE 1" = 40' HOR. 1" = 4' VERT.




THIS PAGE IS BEST QUALITY PRACTICAL COPY FROM COPY FURNISHED TO DDG



SECTION DD

GRAIN SIZE DISTRIBUTION GRAPH



APPLY ACTION OF DRAIN TRENCH ACTUAL DEPTH TO BE ACCURATELY BY THE ENGINEER IN THE FIELD


PLATE 7

**SAUL-MATHAY WATERSHED PROJECT
MERCER COUNTY, PENNSYLVANIA
FLOODWATER RETARDING DAM #459
MERCER COUNTY
SEEPAGE DRAIN DETAILS
U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE**

AS BUILT PLANS

Designed by Fred B. Theurer	Date June 68	Approved by JOE W.
Drawn by W. BACHMANN, JR.	Title SEEPAGE DRAIN DETAILS	Sheet No. 6 of 6
Checked by	Project No.	Drawing No. PA-459-P

2




36" Ø REINF. CONCRETE WATER PIPE
 60 12'-0" SECTIONS
 10' WALL PIECE FOR 12" WALL
 TOTAL - 129.99'
 MEASURE - 140 - 22 FT
 1" MAX. PER LIN. FT BASED ON 0.01" CRACK
 WALL EDGE BEARING STRENGTH - 0.01" CRACK
 LIN. REINFORCED PIPE - 5929 LB. PER LIN. FT. OR
 0.0007 CRACK PRESTRESSED PIPE - 4450 LB. PER LIN. FT.



PC. WT.	24" DIAM. FROM INVERT TO TOP OF 36" PIPE IN FEET	SLOPE	INVERT ELEV. OF 36" PIPE
RISER	120.99		1201.00
A	118.99	2.00% SLOPE	1205.86
B	96.99		1200.75
C	80.99		1200.27
D	64.99		1200.50
E	48.99		1200.78
F	32.99		1200.25
G	16.99		1200.77
INLET	0.00		1200.00

J	107.99	1200.84
K	89.99	1200.29
M	59.99	1200.86

NOTE: PIPE LENGTHS ARE NOMINAL & DO NOT INCLUDE CREEP.



PROFILE ALONG & OF PRINCIPAL SPILLWAY SCALE 1/8"



SOILS DATA

- TP 300 ELEV 1201.6
 1P TOPSOIL, SANDY GRAY, CLAYEY
 2P NO. 10
 3P NO. 10
 4P NO. 10
 5P NO. 10
 6P NO. 10
 7P NO. 10
 8P NO. 10
 9P NO. 10
 10P NO. 10
 11P NO. 10
 12P NO. 10
 13P NO. 10
 14P NO. 10
 15P NO. 10
 16P NO. 10
 17P NO. 10
 18P NO. 10
 19P NO. 10
 20P NO. 10
 21P NO. 10
 22P NO. 10
 23P NO. 10
 24P NO. 10
 25P NO. 10
 26P NO. 10
 27P NO. 10
 28P NO. 10
 29P NO. 10
 30P NO. 10
 31P NO. 10
 32P NO. 10
 33P NO. 10
 34P NO. 10
 35P NO. 10
 36P NO. 10
 37P NO. 10
 38P NO. 10
 39P NO. 10
 40P NO. 10
 41P NO. 10
 42P NO. 10
 43P NO. 10
 44P NO. 10
 45P NO. 10
 46P NO. 10
 47P NO. 10
 48P NO. 10
 49P NO. 10
 50P NO. 10
 51P NO. 10
 52P NO. 10
 53P NO. 10
 54P NO. 10
 55P NO. 10
 56P NO. 10
 57P NO. 10
 58P NO. 10
 59P NO. 10
 60P NO. 10
 61P NO. 10
 62P NO. 10
 63P NO. 10
 64P NO. 10
 65P NO. 10
 66P NO. 10
 67P NO. 10
 68P NO. 10
 69P NO. 10
 70P NO. 10
 71P NO. 10
 72P NO. 10
 73P NO. 10
 74P NO. 10
 75P NO. 10
 76P NO. 10
 77P NO. 10
 78P NO. 10
 79P NO. 10
 80P NO. 10
 81P NO. 10
 82P NO. 10
 83P NO. 10
 84P NO. 10
 85P NO. 10
 86P NO. 10
 87P NO. 10
 88P NO. 10
 89P NO. 10
 90P NO. 10
 91P NO. 10
 92P NO. 10
 93P NO. 10
 94P NO. 10
 95P NO. 10
 96P NO. 10
 97P NO. 10
 98P NO. 10
 99P NO. 10
 100P NO. 10
- TP 302 ELEV 1202.0
 1P TOPSOIL
 2P NO. 10
 3P NO. 10
 4P NO. 10
 5P NO. 10
 6P NO. 10
 7P NO. 10
 8P NO. 10
 9P NO. 10
 10P NO. 10
 11P NO. 10
 12P NO. 10
 13P NO. 10
 14P NO. 10
 15P NO. 10
 16P NO. 10
 17P NO. 10
 18P NO. 10
 19P NO. 10
 20P NO. 10
 21P NO. 10
 22P NO. 10
 23P NO. 10
 24P NO. 10
 25P NO. 10
 26P NO. 10
 27P NO. 10
 28P NO. 10
 29P NO. 10
 30P NO. 10
 31P NO. 10
 32P NO. 10
 33P NO. 10
 34P NO. 10
 35P NO. 10
 36P NO. 10
 37P NO. 10
 38P NO. 10
 39P NO. 10
 40P NO. 10
 41P NO. 10
 42P NO. 10
 43P NO. 10
 44P NO. 10
 45P NO. 10
 46P NO. 10
 47P NO. 10
 48P NO. 10
 49P NO. 10
 50P NO. 10
 51P NO. 10
 52P NO. 10
 53P NO. 10
 54P NO. 10
 55P NO. 10
 56P NO. 10
 57P NO. 10
 58P NO. 10
 59P NO. 10
 60P NO. 10
 61P NO. 10
 62P NO. 10
 63P NO. 10
 64P NO. 10
 65P NO. 10
 66P NO. 10
 67P NO. 10
 68P NO. 10
 69P NO. 10
 70P NO. 10
 71P NO. 10
 72P NO. 10
 73P NO. 10
 74P NO. 10
 75P NO. 10
 76P NO. 10
 77P NO. 10
 78P NO. 10
 79P NO. 10
 80P NO. 10
 81P NO. 10
 82P NO. 10
 83P NO. 10
 84P NO. 10
 85P NO. 10
 86P NO. 10
 87P NO. 10
 88P NO. 10
 89P NO. 10
 90P NO. 10
 91P NO. 10
 92P NO. 10
 93P NO. 10
 94P NO. 10
 95P NO. 10
 96P NO. 10
 97P NO. 10
 98P NO. 10
 99P NO. 10
 100P NO. 10
- TP 303 ELEV 1203.0
 1P TOPSOIL, DARK BROWN
 2P NO. 10
 3P NO. 10
 4P NO. 10
 5P NO. 10
 6P NO. 10
 7P NO. 10
 8P NO. 10
 9P NO. 10
 10P NO. 10
 11P NO. 10
 12P NO. 10
 13P NO. 10
 14P NO. 10
 15P NO. 10
 16P NO. 10
 17P NO. 10
 18P NO. 10
 19P NO. 10
 20P NO. 10
 21P NO. 10
 22P NO. 10
 23P NO. 10
 24P NO. 10
 25P NO. 10
 26P NO. 10
 27P NO. 10
 28P NO. 10
 29P NO. 10
 30P NO. 10
 31P NO. 10
 32P NO. 10
 33P NO. 10
 34P NO. 10
 35P NO. 10
 36P NO. 10
 37P NO. 10
 38P NO. 10
 39P NO. 10
 40P NO. 10
 41P NO. 10
 42P NO. 10
 43P NO. 10
 44P NO. 10
 45P NO. 10
 46P NO. 10
 47P NO. 10
 48P NO. 10
 49P NO. 10
 50P NO. 10
 51P NO. 10
 52P NO. 10
 53P NO. 10
 54P NO. 10
 55P NO. 10
 56P NO. 10
 57P NO. 10
 58P NO. 10
 59P NO. 10
 60P NO. 10
 61P NO. 10
 62P NO. 10
 63P NO. 10
 64P NO. 10
 65P NO. 10
 66P NO. 10
 67P NO. 10
 68P NO. 10
 69P NO. 10
 70P NO. 10
 71P NO. 10
 72P NO. 10
 73P NO. 10
 74P NO. 10
 75P NO. 10
 76P NO. 10
 77P NO. 10
 78P NO. 10
 79P NO. 10
 80P NO. 10
 81P NO. 10
 82P NO. 10
 83P NO. 10
 84P NO. 10
 85P NO. 10
 86P NO. 10
 87P NO. 10
 88P NO. 10
 89P NO. 10
 90P NO. 10
 91P NO. 10
 92P NO. 10
 93P NO. 10
 94P NO. 10
 95P NO. 10
 96P NO. 10
 97P NO. 10
 98P NO. 10
 99P NO. 10
 100P NO. 10

NOTE: DATE OF GEOLOGIC INVESTIGATION
 UNIFIED SOIL CLASSIFICATIONS BY VISUAL INSPECTION

AS BUILT PLANS
 PLATE 8

SAUL - MATHAY WATERSHED PROJECT
 MERCER COUNTY, PENNSYLVANIA
 FLOODWATER RETARDING DAM PA-459
 MERCER COUNTY
 PLAN - PROFILE OF PRINCIPAL SPILLWAY
 U.S. DEPARTMENT OF AGRICULTURE
 SOIL CONSERVATION SERVICE

Designed by: H. WALL
 Drawn by: J. THURER
 Checked by: J. THURER
 Date: MAY 1961

Approved by: [Signature]
 Date: JUN 1961

Project No.: PA-459-P

THIS PAGE IS BEST QUALITY PRACTICABLE FROM COPY FURNISHED TO EDC

APPENDIX A

**CHECK LIST - VISUAL INSPECTION
AND FIELD SKETCH**

Check List
Visual Inspection
Phase 1

A-1

Name of Dam Mathay Dam County Mercer State PA Coordinates Lat. N 41° 23.0'
NDI # PA 00247 Long. W 80° 20.7'
PENNER # 43-46
SCS # PA 459

Date of Inspection 26 April 1979 Weather Rainy, Windy Temperature 45-50°F.

Pool Elevation at Time of Inspection 1208.3 ft.* M.S.L. Tailwater at Time of Inspection 1198.0 ft.* M.S.L.

*Elevations are referenced to the crest of the riser orifice
(El. 1207.8 ft.).

Inspection Personnel:

Michael Baker, Jr., Inc.:

David Johns
Rodney E. Holderbaum
James G. Ullinski

Owner's Representatives
Mercer County Conservation District:

James Mondok (part-time)

Site Visit (5 June 1979):

Dr. C. Y. Chen
James G. Ullinski

James G. Ullinski Recorder

CONCRETE/MASONRY DAMS - Not Applicable

A-2

Name of Dam: MATHAY DAM
NDI # PA 00247

VISUAL EXAMINATION OF OBSERVATIONS REMARKS OR RECOMMENDATIONS

LEAKAGE

**STRUCTURE TO
ABUTMENT/EMBANKMENT
JUNCTIONS**

DRAINS

WATER PASSAGES

FOUNDATION

CONCRETE/MASONRY DAMS - Not Applicable

A-3

Name of Dam: MATHAY DAM
NDI # PA 00247

VISUAL EXAMINATION OF OBSERVATIONS REMARKS OR RECOMMENDATIONS

**SURFACE CRACKS
CONCRETE SURFACES**

STRUCTURAL CRACKING

**VERTICAL AND HORIZONTAL
ALIGNMENT**

MONOLITH JOINTS

CONSTRUCTION JOINTS

EMBANKMENT

A-4

Name of Dam: WATHAY DAM
DOI # PA 00247

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	None observed	The embankment is well vegetated with grasses. The few small clumps of bushes should be cut during routine maintenance.
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None observed	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	Minor erosion and rutting on crest of dam are due to vehicular and pedestrian traffic.	Should be repaired during routine maintenance of the dam.
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	No problems were observed.	
RIPRAP FAILURES	There is no riprap along the reservoir shore or in the outlet plunge pool. The shoreline of the reservoir is presently eroding and a minor amount of the shore is washing into the reservoir. The riprap in the emergency spillway channel was in good condition.	Plunge pool should be riprapped to prevent on-going erosion. The absence of riprap along the sediment pool shore of the embankment is not a problem at this time.

EMBANKMENT

A-5

Name of Dam: MATHAY DAM
DOI # PA 00247

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
ANIMAL BURROWS/RODENT HOLES	Several rodent holes/animal burrows were observed in the embankment. The locations are shown on the field sketch.	The holes should be repaired and a rodent control program should be implemented.
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	No problems were observed.	
ANY NOTICEABLE SEEPAGE	Several wet areas were observed around the dam site. It is estimated these areas are locations of surface runoff accumulation (and lack of infiltration). The locations and approximate extents are shown on the field sketch.	No noticeable seepage could be found in these areas. They should be checked periodically in future inspections of the dam.
STAFF GAGE AND RECORDER	None	
DRAINS	Both drain outlets to the stilling pool were partially clogged with silt and vegetation. An underdrain along the left upstream portion of the emergency spillway channel was totally clogged with silt and vegetation.	These drains should be checked during routine maintenance.

**OUTLET WORKS
(PRINCIPAL SPILLWAY IN
SCS TERMINOLOGY)**

Name of Dam: MATHAY DAM
NOI # PA 00247

VISUAL EXAMINATION OF OBSERVATIONS REMARKS OR RECOMMENDATIONS

CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT Most of the outlet conduit was inaccessible. The condition of the conduit, at its outlet, appeared to be in good condition.

INTAKE STRUCTURE The intake structure (above the water level) was in good condition. Some minor debris was located on the trash rack around the riser orifice. The debris should be removed periodically.

OUTLET STRUCTURE There is no outlet structure. The 36-in. diameter reinforced concrete outlet pipe discharges directly into the plunge pool.

OUTLET CHANNEL The outlet channel is in good condition. No debris or other obstructions were observed.

EMERGENCY GATE None

**UNGATED SPILLWAY
(EMERGENCY SPILLWAY IN
SCS TERMINOLOGY)**

Name of Dam: MATHAY DAM
NDI # PA 00247

VISUAL EXAMINATION OF OBSERVATIONS REMARKS OR RECOMMENDATIONS

CONCRETE WEIR

There is no concrete weir. The spillway is a well vegetated earth channel.

APPROACH CHANNEL

Well vegetated with thick grasses. Several areas have a minor amount of ponded water (from surface runoff) on the surface.

DISCHARGE CHANNEL

The channel is well vegetated and in good overall condition. No obstructions were observed that could limit discharges from the reservoir.

BRIDGE AND PIERS

None

A-8

GATED SPILLWAY - Not Applicable

Name of Dam:
NDI # PA 00247

MATHAY DAM

VISUAL EXAMINATION OF OBSERVATIONS REMARKS OR RECOMMENDATIONS

CONCRETE SILL

APPROACH CHANNEL

DISCHARGE CHANNEL

BRIDGE AND PIERS

GATES AND OPERATION
EQUIPMENT

INSTRUMENTATION - None

Name of Dam: MATHAY DAM
NDI # PA 00247

VISUAL EXAMINATION **OBSERVATIONS** **REMARKS OR RECOMMENDATIONS**

MONUMENTATION/SURVEYS

OBSERVATION WELLS

WEIRS

PIEZOMETERS

OTHER

A-10

RESERVOIR

Name of Dam: WATHAY DAM
NDI # PA 00247

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

SLOPES

The area surrounding the reservoir is moderately sloping agricultural land. There are a few wooded areas throughout the watershed.

The reservoir slopes are stable from soil mechanics and hydraulics (erosion) standpoints.

SEDIMENTATION

No significant amount of sedimentation has occurred due to the watershed characteristics.

The reservoir was designed by the SCS with allowance for 50 years of sediment accumulation.

A-11

DOWNSTREAM CHANNEL

Name of Dam: MATHAY DAM
MDI # PA 00247

VISUAL EXAMINATION OF OBSERVATIONS **REMARKS OR RECOMMENDATIONS**

CONDITION

(OBSTRUCTIONS,
DEBRIS, ETC.)


Mathay Run flows through primarily wooded and agricultural lands downstream of the dam.

SLOPES

The slope of the downstream channel is moderate, averaging approximately 1%.

APPROXIMATE NO. OF HOMES AND POPULATION

Approximately six homes are located in low lying areas in the first 6000 ft. downstream of the dam. Several other residences are located along the stream's remaining 2 mile course to the Shenango River.



Outlet Channel
(Mathoy Run)

Minor Erosion Around
Plunge Pool

Silt and Vegetation Buildup in Toe
Drain Outlets
Area of Ponded Water
And Cattails

Rodent/Animal
Burrows

Intake Riser

Normal Pool
El. 1207.8 Ft. Extensive
Area of
Animal Burrows

Shoreline
Erosion

FIELD SKETCH
Mathoy Dam
NDI No. PA 00247
Penn DER No. 43-46



Emergency Spillway
Control Section
El. 1218.0 Ft.

Ponded Water

Ponded
Water

SCS
Designed
High
Water
El. 1220.9

El. 1220.9 Ft.

Not to Scale

APPENDIX B

CHECK LIST - ENGINEERING DATA

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION

Name of Dam: MATHAY DAM
NDI # PA 00247

ITEM	REMARKS
PLAN OF DAM	Reference Drawings: "Saul-Mathay Watershed Project, Flood Retarding Dam PA-459, Mercer County, Pennsylvania," U.S. Department of Agriculture, Soil Conservation Service (SCS). April 1961 (12 sheets of the "as built" drawings available in files of SCS Harrisburg office and Mercer County Conservation District office. Prints of the design drawings are available in the PennDER files.) Plan of Dam - Reference Drawings sheets 2 and 3, included in this report as Plates 3 and 4.
REGIONAL VICINITY MAP	Reference Drawings - Sheet 1. Also a portion of a USGS 7.5 minute topographic quadrangle, Greenville East, Pennsylvania, is included in this report as Plate 1.
CONSTRUCTION HISTORY	Mathay Dam was designed by the SCS, circa 1960. The dam was constructed by Hilliard Mining Co. of Butler, Pennsylvania from Spring 1961 to final acceptance on 13 August 1962. The SCS provided resident inspection during construction.
TYPICAL SECTIONS OF DAM	Reference Drawings - Sheets 4-7 (included as Plates 5-8 of this report).
HYDROLOGIC/ HYDRAULIC DATA	Some hydrologic/hydraulic data are included in the "Saul-Mathay Watershed Work Plan" report prepared by the Mercer County Commissioners, et. al., March 1960. Other information is included in the Dam Permit Application Report prepared by the Pennsylvania Department of Forests and Waters (PDFW) on 7 July 1961. This report is in PennDER's files. Prints of SCS drawings "Freeboard Flood Routing" and "Design Flood Routing," June 1961, are also in the PennDER files. Additional hydrologic/hydraulic data are available in files of the SCS Harrisburg office.
OUTLETS	PLAN Reference Drawings - Sheets 2, 3, and 7. (Included in this report as Plates 3, 4, and 8).
DETAILS	Reference Drawings - Sheets 2, 3, 7, 8, 9, and 10.
CONSTRAINTS	No constraints are indicated.
DISCHARGE RATINGS	are included as part of the design flood routing drawings ("Freeboard Flood Routing" and "Design Flood Routing") by the SCS.
RAINFALL/RESERVOIR RECORDS	None are readily available.

Name of Dam: MATHAY DAM
DOI # PA 00247

B-2

ITEM

REMARKS

DESIGN REPORTS	No complete design report is readily available, but design report components are available in the files of the SCS Harrisburg office. Additional design information is included in the "Saul-Mathay Watershed Work Plan" and in the PennDER Dam Permit Application Report.
GEOLOGY REPORTS	No geology report is readily available. Some geology information is included in the following: a) "Saul-Mathay Watershed Work Plan," b) PennDER's Permit Report, c) files of the SCS Harrisburg office, and d) selected references of the Pennsylvania Geological Survey.
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	Design computations are available in the SCS Harrisburg office files.
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	Boring and test pit locations are shown on Sheets 2, 3, 4, and 7 of the Reference Drawings (included as Plates 3, 4, 5, and 8, respectively, in this report). Additional information exists in the files of the SCS Harrisburg office.
POST-CONSTRUCTION SURVEYS OF DAM	Annual inspections are performed by representatives of the Mercer County Commissioners (Conservation District) and the SCS. Copies of the inspections are available in the Mercer County Conservation District office in Mercer and most are available in PennDER's files. A post-construction survey was performed to prepare the "as built" drawings.
BORROW SOURCES	The borrow was obtained primarily from the reservoir area; however, some borrow was from the emergency spillway excavation (see Plate 3 - Plan of Dam). Most of the test pits opened in the borrow areas were classified as predominately ML material. Additional information on borrow sources is available in the files of the SCS Harrisburg office.

Name of Dam: MATHAY DAM

B-3

NDI # PA 00247

ITEM REMARKS

MONITORING SYSTEMS There are no monitoring systems.

MODIFICATIONS No modifications have been performed.

HIGH POOL RECORDS No information is readily available. According to a representative of the Mercer County Conservation District, the reservoir level has never reached the second stage of the riser.

POST-CONSTRUCTION ENGINEERING STUDIES AND REPORTS A study was performed approximately 4 yrs. ago to determine the amount of sediment accumulation in the reservoir. The SCS found the amount of sediment negligible.

PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS There have been no accidents or failures.

MAINTENANCE OPERATION RECORDS No maintenance or operations records are readily available.

Name of Dam: MATHAY DAM
NDI # PA 00247

B-4

ITEM **REMARKS**

EMERGENCY SPILLWAY PLAN Reference Drawings - Sheets 2, 3, and 5 (included as Plates 3, 4, and 6, respectively, of this report).
SECTIONS Reference Drawings - Sheet 5 (included as Plate 6 of this report).
DETAILS Reference Drawings - Sheets 2, 3, and 5 (included as Plates 3, 4, and 6, respectively, of this report).

OPERATING EQUIPMENT PLANS & DETAILS There is no operating equipment.

**CHECK LIST
HYDROLOGIC AND HYDRAULIC DATA
ENGINEERING DATA**

B-5

DRAINAGE AREA CHARACTERISTICS: 1.4 sq.mi. (primarily agricultural lands)

ELEVATION TOP SEDIMENT POOL (STORAGE CAPACITY): 1207.8 ft. (18.5 ac.-ft.)

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): 1218.0 ft. (325 ac.-ft.)

ELEVATION MAXIMUM DESIGN POOL: 1220.9 ft. (Design High Water)

ELEVATION TOP DAM: 1223.2 ft.

CREST: Emergency Spillway (SCS Terminology)

- a. Elevation 1218.0 ft. (level section)
- b. Type Vegetated side channel
- c. Width 100 ft.
- d. Length Approximately 2500 ft.
- e. Location Spillover At left abutment
- f. Number and Type of Gates None

OUTLET WORKS: Principal Spillway (SCS Terminology)

- a. Type Concrete riser and 36 in. R.C.P.
- b. Location Approximately 1900 ft. from right abutment
- c. Entrance inverts El. 1207.8 ft. (orifice), El. 1212.0 ft. (high stage inlet)
- d. Exit inverts El. 1200.0 ft.
- e. Emergency draindown facilities None

HYDROMETEOROLOGICAL GAGES: None

- a. Type _____
- b. Location _____
- c. Records _____

MAXIMUM NON-DAMAGING DISCHARGE Unknown

APPENDIX C

PHOTOGRAPHS

DETAILED PHOTOGRAPH DESCRIPTIONS

**Overall View of Dam - View from Left End of Dam Looking Toward
Main Embankment, Intake Riser and Pond**

**Photo 1 - View Looking Along Crest of Left Wing of
Embankment from Left End of Embankment**

**Photo 2 - View Looking Along Crest of Wing of
Embankment from Junction with Main Embankment**

**Photo 3 - View Looking Toward Pond in Upstream
Portion of Emergency Spillway Channel**

**Photo 4 - View of Downstream Portion of
Emergency Spillway Channel**

**Photo 5 - Upstream View of Main Embankment,
Intake Riser and Pond**

Photo 6 - Close-up View of Intake Riser

Photo 7 - View of Outlet Conduit and Seepage Drain Outlets

**Photo 8 - Close-up View of Seepage Drain Outlet
(Note Buildup of Silt and Vegetation in Outlet)**

Note: Photographs were taken on 26 April 1979.

MATHAY DAM




PHOTO 1. View Looking Along Crest of Left Wing of Embankment from Left End of Embankment





PHOTO 2. View Looking Along Crest of Right Wing of Embankment from Junction with Main Embankment

MATHAY DAM



**PHOTO 3. View Looking Toward Pond in Upstream
Portion of Emergency Spillway Channel**




PHOTO 4. View of Downstream Portion of Emergency Spillway Channel

MATHAY DAM



PHOTO 5. Upstream View of Main Embankment, Intake Riser and Pond




PHOTO 6. Close-up View of Intake Riser

MATHAY DAM




PHOTO 7. View of Outlet Conduit and Seepage Drain Outlets



**PHOTO 8. Close-up of Seepage Drain Outlet
(Note Buildup of Silt and Vegetation in Outlet!)**

APPENDIX D

HYDROLOGIC AND HYDRAULIC COMPUTATIONS

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject Mothay Dam S.O. No. _____
(PA-459) Sheet No. _____ of _____
Drawing No. _____
Computed by _____ Checked by _____ Date _____

Table of Contents

	<u>Page</u>
<u>Preface</u>	<u>1</u>
<u>Rainfall and hydrograph Data</u>	<u>1</u>
<u>Watershed Plan</u>	<u>2</u>
<u>Stage vs. Discharge</u>	<u>3</u>
<u>Stage vs. Storage</u>	<u>4</u>
<u>Downstream Area Map</u>	<u>5</u>
<u>Flood Routing</u>	<u>6-10</u>

PREFACE

HYDROLOGIC AND HYDRAULIC COMPUTATIONS

The hydrologic determinations presented in this Phase I Inspection Report are based on the use of a Snyder's unit hydrograph developed by the U.S. Army Corps of Engineers. Due to the limited number of gaging stations available in this hydrologic region and the wide variation of watershed slopes, the Snyder's coefficients may yield results of limited accuracy for this watershed. As directed however, a further refinement of these coefficients is beyond the scope of this Phase I Investigation.

In addition, the conclusions presented pertain to present conditions, and the effect of future development on the hydrology has not been considered.

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject MATHAY DAM

RAINFALL & HYDROGRAPH DATA

S.O. No. _____

Sheet No. 1 of 10

Drawing No. _____

Computed by J.O.S.

Checked by REH

Date 3-8-79

RAINFALL DATA

FROM HWIR 39

ZONE 2

PMP 24 HR - 200 MI = 23.5 IN.

DA = 1.37 sq. mi.

P(6HR.) = 1.17 PMP

P(12HR.) = 1.27 PMP

P(24 HR.) = 1.47 PMP

P(48 HR.) = 1.51 PMP

HYDROGRAPH COEFFICIENTS

L = 2.22 mi.

DA LOCATED IN ZONE 2T

$L_{eq} = 0.91$ mi.

USE: PLATE 0, $CP = 0.40$

$L_R = 20$ min.

$t_p = 2.7 (L L_{eq})^{0.3}$

(BEAVER RIVER BASIN)

$T_p = 2.7 (L L_{eq})^{0.3}$

$= 2.7 (2.22 \times 0.91)^{0.3}$

$= 3.33$ HRS.

$T_r = T_p / 5.5$



$= 3.33 / 5.5$

$= 0.61$ HR.

$T_{PR} = T_p + 0.25 (T_R - T_r)$

$= 3.33 + 0.25 (\frac{20}{60} - 0.61)$

$= 3.26$ HRS.



U.S.G.S. QUADS:
GREENVILLE WEST
GREENVILLE EAST

DA. = 1.37 MI.²
L = 2.22 MI.
Lca = 0.91 MI.

MATHAY
DAM
WATERSHED

MICHAEL BAKER JR. INC.
Consulting Engineers & Surveyors

DATE: 3-8-79


MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject MATHAY DAM S.O. No. _____
STAGE VS. DISCHARGE Sheet No. 3 of 10
Drawing No. _____
Computed by g.s. Checked by REH Date 3-8-79

STAGE	DISCHARGE
1207.8	0
1208.0	5
1210.0	17
1212.0	22
1213.8	110
1216.0	120
1218.0	127
1219.0	420
1220.0	870
1221.0	1600
1222.0	2480
1223.0	3640
1224.0	4820

NOTE: THE ABOVE DATA WAS TAKEN FROM SCS DESIGN PLANS,
DRAWING NO. PA-459-P (1 of 2)




MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS


Box 280
Beaver, Pa. 15009

Subject MATHAY DAM S.O. No. _____
STAGE VS STORAGE Sheet No. 4 of 10
Drawing No. _____
Computed by G.D.S. Checked by REH Date 3-8-79

STAGE	STORAGE
1207.8	0
1210	28
1212	64
1214	117
1216	196
1218	306
1220	446
1222	618
1223.2	736
1224	814

NOTE: THE ABOVE DATA WAS TAKEN SCS DESIGN PLANS,
DRAWING NO. PA-459-P (2CF2)





MATHAY DAM

SCALE 1:24000



 FLOOD HYDROGRAPH PACKAGE (HFC-1)
 DAM SAFETY VERSION JULY 1979
 LAST MODIFICATION 26 FEB 79
 HBJ UPDATE 04 JUN 79

LINE	DESCRIPTION	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27			
1	A1	NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS																													
2	A2	HYDROLOGIC AND HYDRAULIC ANALYSIS OF PATHWAY DAM NO. 10																													
3	A3	PROBABLE MAXIMUM FLOOD PMF/UNIT GRAPH BY SNYDER'S METHOD																													
4	B	300	0	20	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0		
5	B1	5	2	1																											
6	J	1	0.5																												
7	J1	1.0																													
8	K	0																													
9	K1	0																													
10	M	1																													
11	M1	1	1.37																												
12	P	23.5	117	127	141	151																									
13	T																														
14	M	3.26	0.40																												
15	X	-1.5	-0.05	2.0																											
16	K	1																													
17	K1	1																													
18	V																														
19	V1	1																													
20	V4	1207.8	1210	1212	1213.8	1216																									
21	Y4	1222	1223	1224																											
22	V5	0	5	17	22	110	120	127	420	870	1600																				
23	V5	2480	3640	4820																											
24	S5	0	28	64	117	196	306	446	618	736	814																				
25	S1207.8		1210	1212	1214	1216	1218	1220	1222	1223.2	1224																				
26	S1223.2		2.65	1.5	3260																										
27	K																														

THIS IS A ROUTING FOR PATHWAY DAM

 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 26 FEB 79
 MBJ UPDATE 04 JUN 79

RUN DATE 06/13/79
 TIME 13.31

NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
 HYDROLOGIC AND HYDRAULIC ANALYSIS OF MATHAY DAM MBJ 10
 PROBABLE MAXIMUM FLOOD PMF/UNIT GRAPH BY SNYDERS METHOD

NO NHP NMIN IDAY IHR IMIN METRC IPLT IPRT MSTAN
 300 0 20 0 0 0 0 0 -4 0
 JOPER NHT LROPT TRACE 0 0 0

 MULTI-PLAN ANALYSES TO BE PERFORMED
 MPLAN= 1 MRTIO= 2 LRTIO= 1

PTIOS= 1.00 0.50

 SUB-AREA RUNOFF COMPUTATION

SNYDER'S HYDROGRAPH

ESTAQ ICOMP IECON ITAPE JPLT JPRY INAME ISTAGE IAUTO
 1 0 0 0 0 0 1 0 0

HYDROGRAPH DATA

IHYDG IUNG TARFA SNAP TRSDA TRSPC RATIO ISNOW ISAME LOCAL
 1 1 1.37 0.0 1.37 0.0 0.0 0.0 0 0 0

PRECIP DATA

SPEE PMS R6 R12 R24 R48 R72 R96
 0.0 23.50 117.00 127.00 141.00 151.00 0.0 0.0

TRSPC COMPUTED BY THE PROGRAM IS 0.800

LOSS DATA

LROPT STRKR DLYKR RTIOL ERAIN STRKS RTIOK STRTL CNSTL ALSMRT RTIMP
 0 0.0 0.0 1.00 0.0 0.0 1.00 1.00 1.00 0.05 0.0 0.0

UNIT HYDROGRAPH DATA

TP= 3.26 CP=0.40 MTA= 0

RECESSION DATA
 STRTQ= -1.50 QRC5M= -0.05 RTIOR= 2.00

UNIT	HYDROGRAPH100	END-OF-PERIOD	ORDINATES,	LAG=	3.29	HOURS,	CP=	0.40	VOL=	0.99
3.	12.	24.	39.	55.	72.	87.	99.	107.	110.	
108.	102.	97.	92.	87.	82.	78.	74.	70.	66.	
63.	59.	56.	53.	50.	48.	45.	43.	41.	38.	
36.	34.	33.	31.	29.	28.	26.	25.	24.	22.	

21.	20.	19.	18.	17.	16.	15.	14.	13.
12.	11.	10.	9.	8.	7.	6.	5.	4.
7.	6.	5.	4.	3.	2.	1.	1.	1.
4.	3.	2.	1.	1.	1.	1.	1.	1.
2.	1.	1.	1.	1.	1.	1.	1.	1.
1.	1.	1.	1.	1.	1.	1.	1.	1.

SUM 28.39 25.95 2.44 68617.
(721.11 659.11 62.11 1943.02)

HYDROGRAPH ROUTING

THIS IS A ROUTING FOR MATHAY DAM

ISTAQ	ICOMP	TECOM	ITAPE	JPLT	JPRY	INAME	ISTAGE	IAUTO
DAM	1	0	0	0	0	1	0	0
QLCSS	CLOSS	AVG	IRCS	ISAME	IGPT	IPMP	LSTR	
0.0	0.0	0.0	1	1	0	0	0	
NSTPS	NSTDL	LAG	AMSKK	X	TSK	STORA	ISPRAT	
1	0	0	0.0	0.0	0.0	-1208.	-1	

STAGE	1207.80	1208.00	1210.00	1212.00	1213.80	1216.00	1218.00	1219.00	1220.00	1221.00
FLOW	0.0	5.00	17.00	22.00	110.00	120.00	127.00	420.00	870.00	1600.00
CAPACITY=	0.	28.	64.	117.	196.	306.	446.	736.	814.	
FLEVATION=	1208.	1210.	1212.	1214.	1216.	1218.	1220.	1222.	1223.	1224.

CPEL	SPHID	COQM	EXPM	ELEVL	COQL	CAREA	EXPL
1207.8	0.0	0.0	0.0	0.0	0.0	0.0	0.0

DAM DATA
TOPEL 1223.2
COOD 2.6
EXPD 1.5
DAMMID 3260.

PEAK CUTFLOW IS 1714. AT TIME 45.00 HOURS

PEAK CUTFLOW IS 633. AT TIME 47.33 HOURS

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

RATIOS APPLIED TO FLOWS

OPERATION	STATION	AREA	PLAN	RATIO 1	RATIO 2
				1.00	0.50
HYDROGRAPH AT	1	1.37	1	2038.	1019.
	(3.55)	(57.71)(28.85)(
ROUTED TO	DAM	1.37	1	1714.	633.
	(3.55)	(48.54)(17.92)(

APPENDIX E

REGIONAL GEOLOGY

MATHAY DAM
NDI No. PA 00247, PennDER No. 43-46, SCS No. PA 459


REGIONAL GEOLOGY

Bedrock units beneath this section of the Appalachian Plateaus physiographic province are the upper and lower members of the Shenango formation, Mississippian system. The lower member, on which Mathay Dam is constructed, consists of medium to fine-grained sandstone, shale and siltstone. The upper member, which underlays a portion of the reservoir area, is described in geologic literature as interbedded soft shale and siltstone with lenses of sandstone. Bedrock was not encountered in any of the test pits made for design of the dam.


Because the area has been glaciated, the dam and reservoir site are overlain by glacial drift approximately 15 to 20 feet thick. Most of the soil exposed in the test pits were silts and clays with lenses of fine sand.

One of the test pits along the centerline of the dam encountered groundwater seepage at a depth of 8 feet and one test pit near the stream channel had groundwater at a depth of 3.3 feet.

A geologic map of the area is given on the following page.



LEGEND




SHENANGO FORMATION

The upper member (MSU) is composed of soft medium- to dark-gray shale with interbeds of siltstone and lenses of fine-grained sandstone. Unimportant as an aquifer. The lower member (MSL) is composed of medium- to fine-grained light-gray sandstone and medium- to dark-gray shale and siltstone. Yields moderate to large quantities of water that is locally high in iron content at shallow depths.




MEADVILLE SHALE

Medium- to dark-gray shale, siltstone, and lenses of fine-grained sandstone and occasional thin beds of limestone. Generally yields sufficient water for domestic and stock use.



SHARPSVILLE SANDSTONE

Very fine grained, light-gray sandstone and medium- to dark-gray shale and siltstone. Yields small to large quantities of water. Largest yields are obtained in the Shenango 15' quadrangle; locally contains saline water.



ORANGEVILLE SHALE

Dark-gray shale, occasionally containing some thin siltstone beds. Unimportant as an aquifer.

MISSISSIPPIAN

Cuyahoga Group