

AD-A075 611

SCHNABEL ENGINEERING ASSOCIATES RICHMOND VA
NATIONAL DAM SAFETY PROGRAM. UPPER NORTH RIVER NUMBER 76 (ELKHO--ETC(U)
MAR 79

F/G 13/2
DACW65-79-D-0004
NL


UNCLASSIFIED

1 OF 1

AD
A073811



END
DATE
FILMED
10-19
DDC



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

MARCH 1979

Name Of Dam: UPPER NORTH RIVER NO. 76 (ELKHORN LAKE)

Location: AUGUSTA COUNTY, VIRGINIA

Inventory Number: VA. NO. 01506


①

F
H

LEVEL

PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM

AD A 073611



DDC
RECEIVED
SEP 11 1979
A

~~DA 01506~~

PREPARED FOR

NORFOLK DISTRICT CORPS OF ENGINEERS
803 FRONT STREET
NORFOLK, VIRGINIA 23510

BY

SCHNABEL ENGINEERING ASSOCIATES, P.C./
J. K. TIMMONS AND ASSOCIATES, INC.

DISTRIBUTION STATEMENT A
Approved for public release;
Distribution Unlimited

DDC FILE COPY

79 09 10 126

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DDC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER VA 01506	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program Upper North River No. 76 Augusta County, Virginia		5. TYPE OF REPORT & PERIOD COVERED Final
7. AUTHOR(s) Schnabel Engineering Associates, P.C. J. K. Timmons and Associates, Inc.		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS 12 84 p.		8. CONTRACT OR GRANT NUMBER(s) Schnabel - DACW 65-79-D-0004
11. CONTROLLING OFFICE NAME AND ADDRESS U. S. Army Engineering District, Norfolk 803 Front Street Norfolk, VA 23510		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) 15 DA CW 65-79-D-0004		12. REPORT DATE March 1979
		13. NUMBER OF PAGES
		15. SECURITY CLASS. (of this report) Unclassified
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited. 9 Final rept.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) 6 National Dam Safety Program, Upper North River Number 76 (Elkhorn Lake) (ID Number VA-01506), Augusta County, Virginia, Phase I Inspection Report.		
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia 22151		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dams - VA National Dam Safety Program Phase I Dam Safety Dam Inspection		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) (See reverse side)		

20. Abstract

Pursuant to Public Law 92-367, Phase I Inspection Reports are prepared under guidance contained in the recommended guidelines for safety inspection of dams, published by the Office of Chief of Engineers, Washington, D. C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general conditions of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

Based upon the field conditions at the time of the field inspection and all available engineering data, the Phase I report addresses the hydraulic, hydrologic, geologic, geotechnic, and structural aspects of the dam. The engineering techniques employed give a reasonably accurate assessment of the conditions of the dam. It should be realized that certain engineering aspects cannot be fully analyzed during a Phase I inspection. Assessment and remedial measures in the report include the requirements of additional indepth study when necessary.

Phase I reports include project information of the dam and appurtenances, all existing engineering data, operational procedures, hydraulic/hydrologic data of the watershed, dam stability, visual inspection report and an assessment including required remedial measures.

NAME OF DAM: UPPER NORTH RIVER NO. 76 (ELKHORN LAKE)
LOCATION: AUGUSTA COUNTY, VIRGINIA
INVENTORY NUMBER: VA. NO. 01506

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

PREPARED FOR
NORFOLK DISTRICT CORPS OF ENGINEERS
803 FRONT STREET
NORFOLK, VIRGINIA 23510

BY

SCHNABEL ENGINEERING ASSOCIATES, P.C./
J. K. TIMMONS AND ASSOCIATES, INC.

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of the Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (flood discharges that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the design flood should not be interpreted as necessarily posing a highly inadequate condition. The design flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

NO. 1	NO. 2	NO. 3	NO. 4
NO. 5	NO. 6	NO. 7	NO. 8
NO. 9	NO. 10	NO. 11	NO. 12
NO. 13	NO. 14	NO. 15	NO. 16
NO. 17	NO. 18	NO. 19	NO. 20
NO. 21	NO. 22	NO. 23	NO. 24
NO. 25	NO. 26	NO. 27	NO. 28
NO. 29	NO. 30	NO. 31	NO. 32
NO. 33	NO. 34	NO. 35	NO. 36
NO. 37	NO. 38	NO. 39	NO. 40
NO. 41	NO. 42	NO. 43	NO. 44
NO. 45	NO. 46	NO. 47	NO. 48
NO. 49	NO. 50	NO. 51	NO. 52
NO. 53	NO. 54	NO. 55	NO. 56
NO. 57	NO. 58	NO. 59	NO. 60
NO. 61	NO. 62	NO. 63	NO. 64
NO. 65	NO. 66	NO. 67	NO. 68
NO. 69	NO. 70	NO. 71	NO. 72
NO. 73	NO. 74	NO. 75	NO. 76
NO. 77	NO. 78	NO. 79	NO. 80
NO. 81	NO. 82	NO. 83	NO. 84
NO. 85	NO. 86	NO. 87	NO. 88
NO. 89	NO. 90	NO. 91	NO. 92
NO. 93	NO. 94	NO. 95	NO. 96
NO. 97	NO. 98	NO. 99	NO. 100
NO. 101	NO. 102	NO. 103	NO. 104
NO. 105	NO. 106	NO. 107	NO. 108
NO. 109	NO. 110	NO. 111	NO. 112
NO. 113	NO. 114	NO. 115	NO. 116
NO. 117	NO. 118	NO. 119	NO. 120
NO. 121	NO. 122	NO. 123	NO. 124
NO. 125	NO. 126	NO. 127	NO. 128
NO. 129	NO. 130	NO. 131	NO. 132
NO. 133	NO. 134	NO. 135	NO. 136
NO. 137	NO. 138	NO. 139	NO. 140
NO. 141	NO. 142	NO. 143	NO. 144
NO. 145	NO. 146	NO. 147	NO. 148
NO. 149	NO. 150	NO. 151	NO. 152
NO. 153	NO. 154	NO. 155	NO. 156
NO. 157	NO. 158	NO. 159	NO. 160
NO. 161	NO. 162	NO. 163	NO. 164
NO. 165	NO. 166	NO. 167	NO. 168
NO. 169	NO. 170	NO. 171	NO. 172
NO. 173	NO. 174	NO. 175	NO. 176
NO. 177	NO. 178	NO. 179	NO. 180
NO. 181	NO. 182	NO. 183	NO. 184
NO. 185	NO. 186	NO. 187	NO. 188
NO. 189	NO. 190	NO. 191	NO. 192
NO. 193	NO. 194	NO. 195	NO. 196
NO. 197	NO. 198	NO. 199	NO. 200
NO. 201	NO. 202	NO. 203	NO. 204
NO. 205	NO. 206	NO. 207	NO. 208
NO. 209	NO. 210	NO. 211	NO. 212
NO. 213	NO. 214	NO. 215	NO. 216
NO. 217	NO. 218	NO. 219	NO. 220
NO. 221	NO. 222	NO. 223	NO. 224
NO. 225	NO. 226	NO. 227	NO. 228
NO. 229	NO. 230	NO. 231	NO. 232
NO. 233	NO. 234	NO. 235	NO. 236
NO. 237	NO. 238	NO. 239	NO. 240
NO. 241	NO. 242	NO. 243	NO. 244
NO. 245	NO. 246	NO. 247	NO. 248
NO. 249	NO. 250	NO. 251	NO. 252
NO. 253	NO. 254	NO. 255	NO. 256
NO. 257	NO. 258	NO. 259	NO. 260
NO. 261	NO. 262	NO. 263	NO. 264
NO. 265	NO. 266	NO. 267	NO. 268
NO. 269	NO. 270	NO. 271	NO. 272
NO. 273	NO. 274	NO. 275	NO. 276
NO. 277	NO. 278	NO. 279	NO. 280
NO. 281	NO. 282	NO. 283	NO. 284
NO. 285	NO. 286	NO. 287	NO. 288
NO. 289	NO. 290	NO. 291	NO. 292
NO. 293	NO. 294	NO. 295	NO. 296
NO. 297	NO. 298	NO. 299	NO. 300
NO. 301	NO. 302	NO. 303	NO. 304
NO. 305	NO. 306	NO. 307	NO. 308
NO. 309	NO. 310	NO. 311	NO. 312
NO. 313	NO. 314	NO. 315	NO. 316
NO. 317	NO. 318	NO. 319	NO. 320
NO. 321	NO. 322	NO. 323	NO. 324
NO. 325	NO. 326	NO. 327	NO. 328
NO. 329	NO. 330	NO. 331	NO. 332
NO. 333	NO. 334	NO. 335	NO. 336
NO. 337	NO. 338	NO. 339	NO. 340
NO. 341	NO. 342	NO. 343	NO. 344
NO. 345	NO. 346	NO. 347	NO. 348
NO. 349	NO. 350	NO. 351	NO. 352
NO. 353	NO. 354	NO. 355	NO. 356
NO. 357	NO. 358	NO. 359	NO. 360
NO. 361	NO. 362	NO. 363	NO. 364
NO. 365	NO. 366	NO. 367	NO. 368
NO. 369	NO. 370	NO. 371	NO. 372
NO. 373	NO. 374	NO. 375	NO. 376
NO. 377	NO. 378	NO. 379	NO. 380
NO. 381	NO. 382	NO. 383	NO. 384
NO. 385	NO. 386	NO. 387	NO. 388
NO. 389	NO. 390	NO. 391	NO. 392
NO. 393	NO. 394	NO. 395	NO. 396
NO. 397	NO. 398	NO. 399	NO. 400
NO. 401	NO. 402	NO. 403	NO. 404
NO. 405	NO. 406	NO. 407	NO. 408
NO. 409	NO. 410	NO. 411	NO. 412
NO. 413	NO. 414	NO. 415	NO. 416
NO. 417	NO. 418	NO. 419	NO. 420
NO. 421	NO. 422	NO. 423	NO. 424
NO. 425	NO. 426	NO. 427	NO. 428
NO. 429	NO. 430	NO. 431	NO. 432
NO. 433	NO. 434	NO. 435	NO. 436
NO. 437	NO. 438	NO. 439	NO. 440
NO. 441	NO. 442	NO. 443	NO. 444
NO. 445	NO. 446	NO. 447	NO. 448
NO. 449	NO. 450	NO. 451	NO. 452
NO. 453	NO. 454	NO. 455	NO. 456
NO. 457	NO. 458	NO. 459	NO. 460
NO. 461	NO. 462	NO. 463	NO. 464
NO. 465	NO. 466	NO. 467	NO. 468
NO. 469	NO. 470	NO. 471	NO. 472
NO. 473	NO. 474	NO. 475	NO. 476
NO. 477	NO. 478	NO. 479	NO. 480
NO. 481	NO. 482	NO. 483	NO. 484
NO. 485	NO. 486	NO. 487	NO. 488
NO. 489	NO. 490	NO. 491	NO. 492
NO. 493	NO. 494	NO. 495	NO. 496
NO. 497	NO. 498	NO. 499	NO. 500
NO. 501	NO. 502	NO. 503	NO. 504
NO. 505	NO. 506	NO. 507	NO. 508
NO. 509	NO. 510	NO. 511	NO. 512
NO. 513	NO. 514	NO. 515	NO. 516
NO. 517	NO. 518	NO. 519	NO. 520
NO. 521	NO. 522	NO. 523	NO. 524
NO. 525	NO. 526	NO. 527	NO. 528
NO. 529	NO. 530	NO. 531	NO. 532
NO. 533	NO. 534	NO. 535	NO. 536
NO. 537	NO. 538	NO. 539	NO. 540
NO. 541	NO. 542	NO. 543	NO. 544
NO. 545	NO. 546	NO. 547	NO. 548
NO. 549	NO. 550	NO. 551	NO. 552
NO. 553	NO. 554	NO. 555	NO. 556
NO. 557	NO. 558	NO. 559	NO. 560
NO. 561	NO. 562	NO. 563	NO. 564
NO. 565	NO. 566	NO. 567	NO. 568
NO. 569	NO. 570	NO. 571	NO. 572
NO. 573	NO. 574	NO. 575	NO. 576
NO. 577	NO. 578	NO. 579	NO. 580
NO. 581	NO. 582	NO. 583	NO. 584
NO. 585	NO. 586	NO. 587	NO. 588
NO. 589	NO. 590	NO. 591	NO. 592
NO. 593	NO. 594	NO. 595	NO. 596
NO. 597	NO. 598	NO. 599	NO. 600
NO. 601	NO. 602	NO. 603	NO. 604
NO. 605	NO. 606	NO. 607	NO. 608
NO. 609	NO. 610	NO. 611	NO. 612
NO. 613	NO. 614	NO. 615	NO. 616
NO. 617	NO. 618	NO. 619	NO. 620
NO. 621	NO. 622	NO. 623	NO. 624
NO. 625	NO. 626	NO. 627	NO. 628
NO. 629	NO. 630	NO. 631	NO. 632
NO. 633	NO. 634	NO. 635	NO. 636
NO. 637	NO. 638	NO. 639	NO. 640
NO. 641	NO. 642	NO. 643	NO. 644
NO. 645	NO. 646	NO. 647	NO. 648
NO. 649	NO. 650	NO. 651	NO. 652
NO. 653	NO. 654	NO. 655	NO. 656
NO. 657	NO. 658	NO. 659	NO. 660
NO. 661	NO. 662	NO. 663	NO. 664
NO. 665	NO. 666	NO. 667	NO. 668
NO. 669	NO. 670	NO. 671	NO. 672
NO. 673	NO. 674	NO. 675	NO. 676
NO. 677	NO. 678	NO. 679	NO. 680
NO. 681	NO. 682	NO. 683	NO. 684
NO. 685	NO. 686	NO. 687	NO. 688
NO. 689	NO. 690	NO. 691	NO. 692
NO. 693	NO. 694	NO. 695	NO. 696
NO. 697	NO. 698	NO. 699	NO. 700
NO. 701	NO. 702	NO. 703	NO. 704
NO. 705	NO. 706	NO. 707	NO. 708
NO. 709	NO. 710	NO. 711	NO. 712
NO. 713	NO. 714	NO. 715	NO. 716
NO. 717	NO. 718	NO. 719	NO. 720
NO. 721	NO. 722	NO. 723	NO. 724
NO. 725	NO. 726	NO. 727	NO. 728
NO. 729	NO. 730	NO. 731	NO. 732
NO. 733	NO. 734	NO. 735	NO. 736
NO. 737	NO. 738	NO. 739	NO. 740
NO. 741	NO. 742	NO. 743	NO. 744
NO. 745	NO. 746	NO. 747	NO. 748
NO. 749	NO. 750	NO. 751	NO. 752
NO. 753	NO. 754	NO. 755	NO. 756
NO. 757	NO. 758	NO. 759	NO. 760
NO. 761	NO. 762	NO. 763	NO. 764
NO. 765	NO. 766	NO. 767	NO. 768
NO. 769	NO. 770	NO. 771	NO. 772
NO. 773	NO. 774	NO. 775	NO. 776
NO. 777	NO. 778	NO. 779	NO. 780
NO. 781	NO. 782	NO. 783	NO. 784
NO. 785	NO. 786	NO. 787	NO. 788
NO. 789	NO. 790	NO. 791	NO. 792
NO. 793	NO. 794	NO. 795	NO. 796
NO. 797	NO. 798	NO. 799	NO. 800
NO. 801	NO. 802	NO. 803	NO. 804
NO. 805	NO. 806	NO. 807	NO. 808
NO. 809	NO. 810	NO. 811	NO. 812
NO. 813	NO. 814	NO. 815	NO. 816
NO. 817	NO. 818	NO. 819	NO. 820
NO. 821	NO. 822	NO. 823	NO. 824
NO. 825	NO. 826	NO. 827	NO. 828
NO. 829	NO. 830	NO. 831	NO. 832
NO. 833	NO. 834	NO. 835	NO. 836
NO. 837	NO. 838	NO. 839	NO. 840
NO. 841	NO. 842	NO. 843	NO. 844
NO. 845	NO. 846	NO. 847	NO. 848
NO. 849	NO. 850	NO. 851	NO. 852
NO. 853	NO. 854	NO. 855	NO. 856
NO. 857	NO. 858	NO. 859	NO. 860
NO. 861	NO. 862	NO. 863	NO. 864
NO. 865	NO. 866	NO. 867	NO. 868
NO. 869	NO. 870	NO. 871	NO. 872
NO. 873	NO. 874	NO. 875	NO. 876
NO. 877	NO. 878	NO. 879	NO. 880
NO. 881	NO. 882	NO. 883	NO. 884
NO. 885	NO. 886	NO. 887	NO. 888
NO. 889	NO. 890	NO. 891	NO. 892
NO. 893	NO. 894	NO. 895	NO. 896
NO. 897	NO. 898	NO. 899	NO. 900
NO. 901	NO. 902	NO. 903	NO. 904
NO. 905	NO. 906	NO. 907	NO. 908
NO. 909	NO. 910	NO. 911	NO. 912
NO. 913	NO. 914	NO. 915	NO. 916
NO. 917	NO. 918	NO. 919	NO. 920
NO. 921	NO. 922	NO. 923	NO. 924
NO. 925	NO. 926	NO. 927	NO. 928
NO. 929	NO. 930	NO. 931	NO. 932
NO. 933	NO. 934	NO. 935	NO. 936
NO. 937	NO. 938	NO. 939	NO. 940
NO. 941	NO. 942	NO. 943	NO. 944
NO. 945	NO. 946	NO. 947	NO. 948
NO. 949	NO. 950	NO. 951	NO. 952
NO. 953	NO. 954	NO. 955	NO. 956
NO. 957	NO. 958	NO. 959	NO. 960
NO. 961	NO. 962	NO. 963	NO. 964
NO. 965	NO. 966	NO. 967	NO. 968
NO. 969	NO. 970	NO. 971	NO. 972
NO. 973	NO. 974	NO. 975	NO. 976
NO. 977	NO. 978	NO. 979	NO. 980
NO. 981	NO. 982	NO. 983	NO. 984
NO. 985	NO. 986	NO	

TABLE OF CONTENTS

Preface	i
Brief Assessment of Dam	1
Overview Photos	3
Section 1: PROJECT INFORMATION	4
Section 2: ENGINEERING DATA	8
Section 3: VISUAL INSPECTION	11
Section 4: OPERATIONAL PROCEDURES	13
Section 5: HYDRAULIC/HYDROLOGIC DESIGN	14
Section 6: DAM STABILITY	18
Section 7: ASSESSMENT/REMEDIAL MEASURES	23

Appendices

I	-	Maps and Drawings
II	-	Photographs
III	-	Field Observations
IV	-	Stability Analysis
V	-	Design Report
VI	-	References

Name of Dam: Upper North River No. 76 Dam, Va. No. 1506
State: Virginia
County: Augusta County
USGS Quad Sheet: Stokesville
Coordinates: Lat 38° - 19.6' Long 79° - 13.25'
Stream: Upper North River
Date of Inspection: December 13, 1978

BRIEF ASSESSMENT OF DAM

Upper North River No. 76 is a zoned earthfill structure about 824 ft long and 118 ft high. The principal spillway consists of twin 42-inch prestressed cylinder concrete pipes which extend through the structure. Water is discharged into the principal spillway through a reinforced concrete riser and is expelled into a riprap-lined stilling basin along the downstream toe of the dam. The emergency spillway is a 215 ft wide vegetated earth and riprap side channel spillway. The dam is located on the Upper North River about 8 miles southwest of the community of Stokesville, Va., and was constructed for flood control and recreation. The dam was designed and constructed under the supervision of U.S. Soil Conservation Service, cooperating with the Shenandoah Valley Soil Conservation District, City of Staunton. The City of Staunton, Va., has a special land use permit with the U.S. Forest Service for the construction and operation of the dam.

The dam will pass the probable maximum flood (PMF). Therefore, based on criteria established by the Department of the Army, Office of the Chief of Engineers (OCE), the spillway is rated adequate.

The visual inspection revealed no apparent problems and there are no immediate needs for remedial measures. The actual embankment structure appears to be similar to the "as built" drawings. We do recommend that vegetation be routinely controlled. The slopes, the crest of the structure, and the spillway should be mowed several times a year and existing small trees or saplings removed at least once a year. The slopes of the dam meet the requirements recommended by the U.S. Bureau of Reclamation for zoned earthfill dams. A summary of the stability analysis of the upstream and downstream slopes under rapid drawdown and steady seepage conditions was reviewed and assumptions, test data, and the resultant factors of safety were found to be acceptable.

Submitted by:

Original signed by
JAMES A. WALSH

James A. Walsh, P. E.
Chief, Design Branch

Approved:

Original signed by:

Douglas L. Haller


Douglas L. Haller
Colonel, Corps of Engineers
District Engineer

Recommended By:

Original signed by
ZANE M. GOODWIN

Zane M. Goodwin, P.E.
Chief, Engineering Division

Date: MAR 15 1979



OVERALL VIEW - ELKHORN LAKE
(View from the West)



OUTLET STRUCTURES - ELKHORN LAKE
(View from the East)

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
UPPER NORTH RIVER NO. 76 DAM VA. # 1506
(ELKHORN LAKE DAM)

SECTION 1 - PROJECT INFORMATION

1.1 General:

1.1.1 Authority: Public Law 92-367, 8 August 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a national program of safety inspections of dams throughout the United States. The Norfolk District has been assigned the responsibility of supervising the inspection of dams in the Commonwealth of Virginia.

1.1.2 Purpose of Inspection: The purpose is to conduct a Phase I inspection according to the Recommended Guidelines for Safety Inspection of Dams (see Reference 1, Appendix VI). The main responsibility is to expeditiously identify those dams which may be a potential hazard to human life or property.

1.2 Project Description:

1.2.1 Dam and Appurtenances: Upper North River Dam No. 76 is a zoned earth-fill structure about 824 feet long and 118 feet high. The top of the dam is 28 feet wide and is at elevation 2084.0 ft M.S.L. Side slopes are 2.5 horizontal to 1 vertical (2.5:1) on the downstream side and 3:1 on the upstream side. Ten foot wide berms exist on the downstream and upstream slopes at El 2025 and 2017, respectively.

The principal spillway consists of twin 42-inch diameter prestressed cylinder reinforced concrete pipes, running through the dam. Discharge into the conduits is provided by a 9 x 10.5 ft

reinforced concrete riser with an inlet crest elevation of 2015.5 M.S.L. The riser has three inlets, each at a different elevation, located below the inlet crest. The inlets are used for low flow discharges or to drain the lake depending on sediment buildup. The riser is founded on sandstone and mudstone bedrock.

The emergency spillway, which is a vegetated earth channel having a bottom width of 215 feet, has a crest elevation of 2070.0 M.S.L., which is 14 feet below the top of the dam. The emergency spillway is in cut on the right side and on fill on the left side, and is located off the right end of the dam. The emergency spillway has a vegetative cover in all areas except where excavated rock forms the channel. The spillway has variable side slopes of about 1.25:1 to 2.5:1. The cut area of the emergency spillway is in weathered sandstone, shale, and mudstone bedrock. This information can be found in Appendix I, titled "Maps and Drawings", contained in this report.

1.2.2 Location: Upper North River Dam No. 76 is located on Upper North River about eight miles southwest of the community of Stokesville, Virginia. The reservoir formed by the dam is known locally as Elkhorn Lake. (See Sheet 1, Appendix I).

1.2.3 Size Classification: The dam is classified as a "large" size structure because of the dam height of 118 feet.

1.2.4 Hazard Classification: The dam is located in a rural and heavily forested area. However, based upon the close downstream proximity of Staunton Dam (the principal water supply source for the City of Staunton), the dam is assigned a "High" hazard classification. The hazard classification used to categorize dams is a function of location only and has nothing to do with its stability or probability of failure.

1.2.5 Ownership: The City of Staunton has a special land use permit with the U.S. Forest Service for the construction and operation of the dam.

1.2.6 Purpose: Flood Control and Recreation

1.2.7 Design and Construction History: The dam was designed and constructed under the supervision of the U.S. Soil Conservation Service. Responsibility for construction was by Shenandoah Valley Soil Conservation District and the City of Staunton, during 1962-1963. The dam was completed in 1965.

1.2.8 Normal Operational Procedures: The principal spillway is ungated, therefore, water rising above the crest of the drop inlet automatically is discharged downstream in quantities based on the inlet capacity. Similarly, water is automatically passed through the emergency spillway in the event of an extreme flood which creates a pool elevation above that of the emergency spillway.

1.3 Pertinent Data:

1.3.1 Drainage Areas: The original design (SCS) indicated a drainage area of 27.1 square miles which has been verified and found to be reasonable.

1.3.2 Discharge at Dam Site: Maximum known flood at the dam site occurred in 1972. Inflow was approximately 2400 CFS and all discharge was through the principal spillway.

Principal Spillway:

Pool Elevation at Emergency Spillway Crest 805 CFS
 Pool Elevation at Crest of Dam 862 CFS

Emergency Spillway:

Pool at Crest of Dam 41,200 CFS

1.3.3 Dam and Reservoir Data: See Table 1.1, below.

Table 1.1 DAM AND RESERVOIR DATA

Item	Elevation feet M.S.L.	Area Acres	Reservoir		
			Capacity Acre Feet	Watershed Inches (a)	Length Miles
Crest of dam	2084.0	274	10,500(b)	7.6	1.4
Maximum pool, design surcharge	2074.7	227	8,090(b)	5.59	1.2
Emergency spillway crest	2070	221	7,020(b)	4.85	1.1
Principal Spillway crest	2015.5	53.5	3,066	3.5	0.5
Streambed at Center- line of dam	1966				

(a) Based on 27.1 sq.mi.
 (b) From top of sediment pool

SECTION 2 - ENGINEERING DATA

2.1 Design: The dam was designed and constructed under the direction of the U. S. Soil Conservation Service (SCS) and was sponsored by the City of Staunton. As-built drawings and design data are available in the office of the State Conservationist, U. S. Soil Conservation Service, Federal Building, Room 9201, 5th and Marshall Streets, Richmond, Virginia 23240.

A subsurface investigation was conducted at the site by the SCS during the initial design stages. The investigation consisted of drilling 26 test borings and excavating 40 test pits. Subsurface profiles and a report of the investigation with foundation recommendations were prepared based upon permeability tests, test boring, and test pit data. The geologic report is available at the above referenced SCS office. Subsurface profiles are shown on Sheet 5, Appendix I.

The dam is a zoned, compacted earthfill embankment. The design recommendations shown on Sheet 1, Appendix I, specify that SM or SC materials be used in the core or Section No. 1 of the dam. On the downstream side, the core is blanketed with a 20 ft[±] thick zone of GM and GW material, designated Section No. 2. Section No. 2 is covered by Section No. 3, which consists of coarse GW material. The upstream portion of the core is overlain with finer GW material designated Section No. 4. A thin zone of finer GW material is located behind the downstream toe drain and is designated Section No. 4-A. The pervious downstream shell of Section No's. 2 and 3 control the phreatic surface.

A review of design drawings indicates the dam is founded on overburden and includes a cutoff trench which extends approximately 1 ft₊ into bedrock. Both abutments are described as being water-tight, however, some water leakage was expected, principally through fracture zones in the rock beneath the dam. This was not considered critical in the design report and the possibility of piping was not believed a problem due to the hardness of the rock.

To control the phreatic water surface and to collect seepages, a rock toe drain was constructed along the downstream portion of the dam. This drainage system consists of a trench 10 ft wide at its base and a minimum 8 ft deep, filled with material graded in size from 1 to 24 inches. Twenty-three reinforced concrete anti-seep collars (see Sheet 8, Appendix I) were installed around the principal spillway pipes, under the entire dam and spaced at 24 ft intervals in order to control any potential piping problems along the pipes. Riprap gutters approximately 1.5 ft thick and ranging from 9 to 15 ft in width were constructed adjacent to both abutments to control local surface runoff.

The emergency spillway located adjacent to the right abutment was formed by making a side hill cut into residual soils and bedrock consisting primarily of very fine silty sandstone. Shale and mudstone were also probably encountered during excavation. Design drawings indicate compacted fill was placed locally to bring low areas in the spillway up to design grade. A berm was also constructed to form the left side of the spillway which is riprap lined.

The design report includes detailed laboratory test data describing the physical properties of the materials used to construct the embankment. Shear strength parameters used in design for the core, shell, and foundation material were determined by triaxial compression tests as follows:

<u>SECTION</u>	<u>SHEAR STRENGTH PARAMETERS</u>	
	<u>Angle of Internal Friction</u>	<u>Cohesion</u>
Core	$\phi = 23.5^\circ$	$C = 500 \text{ psf}$
	$\phi' = 31.5^\circ$	$C' = 350 \text{ psf}$
Shell	$\phi = 38.7^\circ$	$C = 0$
Foundation	$\phi = 36.0^\circ$	$C = 0$

The Modified Swedish Circle Method of Analysis was used and included evaluation of 1) the end of construction case, 2) the sudden drawdown case (I), and 3) the steady seepage case (III). Both effective and total strength parameters were utilized as dictated by the stability condition.

2.2 Construction: The construction records were not furnished by the SCS office in Richmond, but they are available from the SCS office in Washington, D.C.

2.3 Operation: There is no known operation and instrumentation procedure.

2.4 Evaluation: Engineering calculations are adequate and the design drawings are representative of the dam. There are no records available for dam performance.

SECTION 3 - VISUAL INSPECTION

3.1 General:

An inspection was made 13 December 1978 and the weather was partly cloudy with a temperature of 45°F. The pool elevation at the time of inspection was 2015.75 M.S.L. and the tailwater elevation was 1966.5 M.S.L., which corresponds to normal flows.

3.2 Findings: Field observations are outlined in Appendix III.

3.2.1 Dam and Spillway: There is tree and tall grass growth on the embankment and on the emergency spillway. Wet spots were observed along the drainage berm located at El 2026+ on the downstream slope of the structure. An area of damp soil was also located about 20 ft right of the left abutment and about 50 ft. downstream of the drainage berm. Inlet structure and outlet works are in good condition.

3.2.2 Reservoir Area: Shoreline has no debris collection on banks or vegetation growth along shoreline in the water. Bank slopes are approximately 2:1 and show no sloughing or surface erosion. Inlet and outlet works show no deterioration.

3.2.3 Downstream Area: Staunton Dam is located approximately 9,000 feet downstream from Elkhorn Lake Dam and the U.S.G.S. mapping of the downstream area indicates no inhabited dwelling in the region.

3.3 Evaluation: Overall, the dam was in good condition at the time of inspection. However, some minor remedial measures are required. Uncontrolled growth encourages the development of

deep rooted vegetation. This type of growth can encourage piping within the embankment and undermine riprap protection. Also, excessive growth inhibits effective visual inspections of the dam. The embankment, including its crest, slopes, and emergency spillway, should be mowed at least once a year, but more preferably twice a year. Small trees presently growing near the left abutment and on the downstream slope should be removed.

Wet spots observed along the drainage berm on the downstream slope are probably the result of recent ponding from precipitation, and runoff along low areas in the berm. The general location of these wet spots is illustrated on Sheet 2 in Appendix I. These wet spots occur at El 2026+, while normal pool is at El 2015.5, therefore, they are not the result of seepage. The downstream berm slopes toward both abutments to the riprap gutters, thus providing an adequate drainage system for collecting runoff. If increased ponding continues in the future, local grading may be required to allow better drainage of this berm.

The area of damp soil illustrated on Sheet 2, Appendix I, is believed to occur because of seepage of the water ponded above in the drainage berm. This condition is not believed to be related to seepage through the dam.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 Procedures:

Elkhorn Lake is used as a source of water supply for the City of Staunton and for flood control purposes for Staunton Dam approximately 2 miles downstream. The normal pool elevation is maintained by a riser-type inlet acting as the principal spillway. During periods of below-normal flows, water flow is maintained through the dam by utilizing the valved inlets below the spillway crest. Operation of these inlets will lower the pool elevation below the spillway crest but will ensure flow to the City of Staunton water intake at Staunton Dam. During periods of above normal flows the pool elevation rises above the riser inlet increasing the flow through the inlet. Large increases in inflows which cannot be absorbed by storage are passed through the emergency spillway when the pool rises above elevation 2070.

4.2 Maintenance of Dam and Appurtenances: The maintenance is the responsibility of the City of Staunton and appears to be performed well. The operating appurtenances are in good working order, however, the vegetative growth on the embankment has not been maintained in the past year.

4.3 Warning System: No warning system exists. As noted, no inhabitable structures exist between this structure and Staunton reservoir.

4.4 Evaluation: The dam and appurtenances are in good operating condition and maintenance is being routinely performed except on the vegetative cover of the embankment. A mowing routine should be established and all trees removed from embankments.

SECTION 5 - HYDRAULICS/HYDROLOGIC DESIGN

5.1 Design: The Upper North River Dam (Elkhorn Dam) was designed by the Soil Conservation Service (SCS) as a multipurpose dam and complete hydrologic and hydraulic data is available. This structure is a Class "C" dam by the SCS classification method.

The crest of the riser of the principal spillway was established at elevation 2015.5 M.S.L., which would provide storage for a sediment pool and provide recreation (fishing and aesthetics). The capacity of the control structure was established to maintain a pool elevation below the emergency spillway during a 100-year flood. The emergency spillway is designed to accommodate the Probable Maximum Flood (PMF) without overtopping of the dam.

5.2 Hydrologic Records: There is a gaging station (1-6205) approximately one mile upstream of the structure on the North River measuring flow from 17.2 square miles. Records for this station have been maintained since 1947 by the U.S. Geological Survey. Some of the highest discharges recorded at this gaging station are 11,100 CFS in 1949, and 2400 CFS in 1972.

5.3 Flood Experience: The maximum pool elevation observed was reached during a storm in October 1972. The gaging station immediately upstream indicated a flow of 2400 CFS on October 5, 1972.

5.4 Flood Potential: The Probable Maximum Flood (PMF), $\frac{1}{2}$ PMF, and 100-year Flood hydrographs were developed by the SCS method (Reference 4, Appendix VI). Precipitation amounts for the flood hydrographs of the PMF, $\frac{1}{2}$ PMF, and 100-year Flood were taken from the U. S. Weather Bureau information (References 5 & 6, Appendix VI). Appropriate adjustments for basin size and shape were accounted for and emergency spillway hydrograph determination procedures as outlined in Reference 5; Appendix VI were used for the flood hydrographs. These hydrographs were routed through the spillway to determine maximum pool elevations.

5.5 Reservoir Regulation: The principal spillway is a riser-type control structure with a combined throat opening of 21 linear feet. This structure passes water through two 42-inch concrete pipes. The principal spillway maintains a normal pool elevation of 2015.5 and has gates at elevations 2005, 1995, and 1979 for purposes of dewatering and maintaining flow during periods of extreme low flow. During periods of flooding, the principal spillway is designed to accommodate the 100-year Flood with 9'± freeboard on the emergency spillway. Stream flows in excess of the 100-year Flood are passed through the emergency spillway at elevation 2070. For routing purposes the pool elevation at the beginning of the flood was assumed to be 2015.5. Reservoir stage-storage data and stage-discharge data were taken from the

SCS hydraulic calculations available. Floods were routed through the reservoir using the principal spillway discharge up to a pool storage elevation of 2070 and a combined principal and emergency spillway discharge for pool elevations above 2070.

5.6 Overtopping Potential: The predicted rise of the reservoir pool and other pertinent data were determined by routing the flood hydrographs through the reservoir as previously described. The results for the two flood conditions (PMF, $\frac{1}{2}$ PMF, and 100-year Flood) are shown in the following Table 5.1.

Table 5.1 RESERVOIR PERFORMANCE

	Normal Flow	Hydrograph		
		100-Yr	$\frac{1}{2}$ PMF	PMF
Peak flow, C.F.S.				
Inflow		9284	18,446	43,700
Outflow		708	803	36,232
Maximum Elevation, ft M.S.L.	2015.5	2048.14	2069.63	2082.94
Freeboard (ft)		35.86	14.37	1.06
Emergency Spillway (El 2070)				
Depth of flow, ft	N/A	N/A	N/A	12.94
Duration, hours				1.0
Velocity, F.P.S.				20.75
Principal Spillway (El 2015.5)				
Head, ft		32.64	96	110
Duration, hours	N/A	4.0	3.0	1.0
Velocity, F.P.S.		39	41.8	45
Tailwater Elevation, ft M.S.L.	1966.5*	1968.75	1968.9	1986.5

*This is the tailwater elevation observed during inspection and it corresponds to a normal flow.

5.7 Reservoir Emptying Potential: A 36-inch circular gate at elevation 1979.0 will drain the reservoir through two 42-inch aqueducts. Assuming that the lake is at normal pool elevation (2015.5) and an average inflow of 21 CFS is maintained, it would take approximately 2.5 days to lower the reservoir to elevation 1979.0. There are no methods for lowering the reservoir below this elevation.

5.8 Evaluation: Flood routing calculations indicate that the reservoir will rise to within one foot of the top of the earth embankment for the PMF and discharge for a period of 1 hour at a velocity of 17.5 feet per second. Hydrologic and hydraulic determinations of the project as prepared by the SCS appear reasonable. The appropriate spillway design flood is the PMF due to the "High" hazard conditions existing downstream. The emergency spillway will pass 100 per cent of the PMF.

Hydrologic data used in evaluation pertain to present day conditions with no consideration given to future development.

SECTION 6 - DAM STABILITY

6.1 Foundation and Abutments: Upper North River Dam No. 76 is founded on alluvial, colluvial and/or residual soils, all of which are underlain by the Hampshire Formation. The structure includes a 20 to 50 ft+ wide cutoff trench, which extends to bedrock. The principal spillway is founded primarily on sandstone, however, the outlet is underlain by sandy mudstone. The emergency spillway is in cut material, which included weathered sandstone, siltstone and mudstone. "As-built" drawings of these various areas are shown on Sheets 2 and 5, Appendix I. The test boring and test pit logs are included as Sheets 3 and 4, Appendix I.

The dam site is located within the Valley and Ridge Physiographic Province of Virginia, which is underlain by sedimentary rocks from Middle Cambrian through Early Mississippian age (see Reference 3, Appendix VI). In the Staunton area, the province consists of the Shenandoah Valley to the east and a series of much narrower valleys and intervening ridges to the west. The eastern portion of the province includes southeastward-dipping thrust faults and asymmetric folds, which are overturned to the northwest. More open folds are common in the central and western areas. Most ridges are "held up" by sandstones and conglomerates, whereas valleys are underlain by less resistant shales and limestones.

The dam site is underlain by rocks of the Hampshire formation of Late Devonian age. The Hampshire is approximately 2200 ft thick and includes moderately to thick-bedded, brown,

medium-grained, arkosic and micaceous sandstone and lumpy red to green mudrock and shale. The structure rests on the west limb of the West Mountain Syncline, approximately 2000 ft west of the synclinal axis, which strikes 40 degrees \pm to the northeast. The left abutment consists of a steep natural slope (70°±). The right abutment/emergency spillway is bound by a very steep manmade cut over 100 ft in height. This cut includes three 10 ft wide berms.

Sandstone bedrock is exposed in the left abutment, while sandstone, shale and mudstone are exposed in the emergency spillway cut. The sandstone is brown to gray in color, fine to medium grained, thin to massive bedded and close-jointed. The shale is brown to red in color. The geologic report describes bedrock strikes ranging from north to 70 degrees northeast and dips ranging from 9 to 15 degrees southeast. Measured attitudes in the field agree with those reported above. Wedge-shaped joint patterns were observed in the north abutment. These joints dip steeply and strike from 25 degrees northwest to 85 degrees northeast. No faults were observed in the field during this investigation and geologic maps of the area do not show the presence of faults in the immediate vicinity.

The potential for seepage does exist within the foundation since the dam is founded, at least in part, on sandy and gravelly soils. This material ranged in depth up to 40 ft \pm in the terrace deposits encountered in the right abutment. Rock was exposed in the stream channel. Field permeability tests show that this material is permeable to very permeable. In an attempt to control potential seepage, a cutoff trench was constructed and reportedly extends 1 ft \pm into firm bedrock. The geologic report describes the underlying bedrock as being quite impermeable; however, some seepage was expected through joint systems in the rock.

6.2 Embankment: The upstream slope is 3 horizontal to 1 vertical with crest at El 2084. At El 2017 the slope flattens to 10 horizontal to 1 vertical forming a berm for a vertical distance of 1 ft. The slope continues at 3 horizontal to 1 vertical to natural ground. Normal pool level is El 2015.5 or 0.5 ft below this berm. The downstream slope is 2.5 horizontal to 1 vertical with a drainage berm at El 2025. This 10 ft wide berm slopes towards the dam at 10 horizontal to 1 vertical. A sloping core consisting of SM and SC material with 3/4 horizontal to 1 vertical slope is provided to El 2070, the same grade as the crest of the emergency spillway. A typical section of the dam is included on Sheet 6, Appendix I. The core material is designated Section No. 1. The material comprising the downstream shell becomes progressively coarser ranging from GM and GW in Section No. 2 to GW in Section No. 3. The upstream shell designated Section No. 4 is also GW material with a finer gradation than the downstream shell. The downstream shell may be considered

pervious with drainage from the core or underseepage from the foundation passing to the downstream rock toe drain, Section 4A.

6.3 Evaluation:

6.3.1 Foundation and Abutments: Dam foundations must be evaluated on the basis of potential settlement, sliding and seepage. Excessive settlement of the dam is not believed to be a problem because the structure rests upon fairly competent bedrock and firm to compact alluvial, colluvial, and/or residual soils. Gradual consolidation of underlying soils would be expected during application of fill materials. The underlying soils probably had essentially fully consolidated under the applied load at the end of the construction period.

Sliding within the foundation bedrock does not appear likely based upon the design load and the nature of the Hampshire formation. In addition, a review of the geologic data indicates that there are probably no adversely oriented weak planes within the foundation rock that would act as a potential sliding plane.

Seepage was not considered a problem in design because the underlying bedrock was believed not to be susceptible to piping. Since construction reports were not available for review, an accurate determination of the foundation conditions under the cutoff trench is not possible.

The steep slopes which form the right side of the emergency spillway are cut into partially weathered sandstone, shale and mudstone, and were considered safe and stable at the time of investigation.

6.3.2 Embankment: The embankment slopes meet the requirement recommended by the U.S. Bureau of Reclamation for small zoned earthfill dams on stable foundation. Since no undue settlement, cracking or seepage was noted at the time of inspection, it appears that the embankment is adequate for maximum pool level with water at El 2074.7.

The stability analysis was performed with a section slightly different than actually constructed. However, the geometry of the dam corresponds very closely to "As-Built" drawings. The differences are not considered significant. The strength parameters described in Section 2 were used in the stability analysis. The report describing the engineering design data used in the stability analysis is included in Appendix IV. These data were reviewed along with the stability analyses and were found to be acceptable. The factor of safety of the upstream slope for the drawdown condition is 1.52 as given in Appendix IV. Reference 1, Appendix VI recommends a factor of safety of 1.2. The factor of safety for the downstream slope under steady seepage condition with drain (shell) at $c/b = 0.6$ is 1.82. The required factor of safety is 1.5 according to Reference 1.

SECTION 7 - ASSESSMENT/REMEDIAL MEASURES


7.1 Dam Assessment: The Upper North River No. 76 Dam at the time of inspection appeared sound and in a safe operating condition. The spillway will pass the PMF without overtopping the dam and is considered adequate. There is no apparent problem that requires immediate action for the normal pool conditions based on the visual inspection and a review of existing records. The actual embankment structure appears to be similar to the "as-built" drawings. Without the construction records, the conformance of the embankment material properties to design requirements cannot be assessed. The design factor of safety for rapid drawdown and steady seepage cases meet the requirement of Reference 1, Appendix VI, and the embankment slopes meet the requirements recommended by the U. S. Bureau of Reclamation, Reference 2, Appendix VI, for small zoned earthfill dams on stable foundations.

7.2 Remedial Measures: There is no immediate need for remedial measures; however, the following maintenance is suggested and should be initiated yearly. These measures are suggested for monitoring and maintenance purposes only.

7.2.1 The grass and weeds along the dam crest, slopes, and within the emergency spillway should be cut at least once and preferably twice a year. We would recommend maintenance in the early summer and fall.

7.2.2 Removal of all trees or saplings from the above described areas should be accomplished every year.


APPENDIX I
MAPS AND DRAWINGS



SCALE 1" = 2000' ±
 STOKESVILLE, VA.
 SW/4 PARNASSUS 15' QUADRANGLE

LOCATION MAP

SHEET 1



NOTE
 CLEARING AND GRABBING LIMITS
 ON GENTLE SLOPES 15 FEET BEYOND
 NORMAL POOL ELEVATION
 ON STEEP SLOPES 1 FT ABOVE NORMAL
 POOL ELEVATION AS INDICATED BY DASHED LINE


GENERAL NOTES

1. A-250 LUMPKEN FILL, BROWN AREAS, AND EMERGENCY SPILLWAY TO BE CLEARED AND GRABBED.
2. ENTIRE NORMAL POOL AREA TO BE CLEARED AND GRABBED.
3. ALL COMPLETED FILL SHALL BE CLASS. B-2 AND C, PLACED AS SHOWN ON PLANS AND AS DIRECTED BY ENGINEER IN FIELD.
4. THERE ARE APPROXIMATELY 35.7 ACRES OF LEAVING, FERTILIZING, SEEDING PREPARATION AND HARROWING THIS INCLUDES THE EMBANKMENT ABOVE THE NORMAL POOL, EMERGENCY SPILLWAY SIDE SLOPES AND BOTTOM, AND ANY OTHER DISTURBED AREAS.

LEGENDS

- 2000 ——— CONTOUR LINE
- — — — — NORMAL POOL LINE ELEV. 2015.5
- STREAM
- LIMIT OF CLEARING & GRABBING
- TEST PIT ON BRILL HOLE (SOIL)
- ⊙ TEST PIT - DISTURBED SAMPLE
- ⊙ TEST PIT FROM WHICH CONSTRUCTION MATERIAL WILL BE OBTAINED AND SUBSCRIPT INDICATES SECTION IF DAM WHERE IT WILL BE USED.

⊙ WET AREAS ON DRAINAGE BERM



AS BUILT SHEET 2

UPPER NORTH RIVER WATERSHED
OF THE POTOMAC RIVER WATERSHED PROJECT
MULTI-PURPOSE DAM NO. 71
AUGUSTA AND ROCKINGHAM COUNTIES, VIRGINIA

SITE LOCATION MAP

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

Designed by R. W. WILSON, R.S. BARBER, JR. 8-62	Drawn by L. S. GIFFMAN 8-62
Checked by [Signature]	Approved by [Signature]

VA-472-P 2

CP or CH Gravel, with sand and silt
 Drive sampled 43 blows
 Drive sampled 3' blow first 5'
 CH or CH Drive sampled 40 blows
 silt, gravel to silt, sand
 CH Gravel, 15' blow to go 0.5'
 CH Gravel and cobbles
 CH Gravel 35 blows from 15-15.5'
 CH 25 blows from 15.5-18'
 CH Gravel and cobbles
 CH Gravel and cobbles 75 blows
 CH 20.5' and cobbles 99 blows
 CH Gravelly cobbles
 CH Gravelly cobbles 43 blows
 CH 25-35'
 CH 25 blows 25.5 - 26'
 CH Same as above

CH Gravel
 Boulder
 Interbedded sandstone, siltstone
 and mudstone, hard, some carbon
 flakes and some, core is broken
 up but no iron stain is present.
 CH 25-35' Interbedded siltstone
 and sandstone. Siltstone
 40-55' Siltstone and sandstone
 there are scattered carbon flakes
 and some. From 40-42' is very
 broken up and has abundant iron
 stain along bedding planes, and
 joint faces.
 Drusy quartzite some carbon flakes
 at 55 feet, very competent in
 permeable rock where not fractured

BN-13 Elev. 2110.06

BN or CH Weathered sandstone with
 pebbles brown. Blow Count 11-14-21
 5' BN Weathered sandstone, 0.5-9'
 Blow Count 120
 Siltstone, sandy, red to light
 brown with some mudstone, massive
 to laminated, some carbon along
 joints.
 Sandstone, very fine to silty, 1 ft
 mudstone split at 18' abundant mica
 and carbon with iron staining on
 joint faces

BN-22 Elev. 1981.4

CH or CH Gravel, sandy and silty
 pebbles to cobbles.
 Mudstone, sandy to silty, some
 pure mudstone in places, some
 carbon flakes and some 12-15'.
 Iron stained joints 17-18', but
 rocks didn't leak under pressure.
 Quartzite, very fine to silty,
 tough some at 21' abundant iron
 stain, with coal seam, core is
 quite broken up. Rusty joints
 25-30'. Rock is very hard but
 breaks up. Rock is very competent.

BN-101 Split Spun Sample, Glass for
 sample / Blow Counts are for 0.5'
 intervals unless otherwise noted.
 BN-102 Split Spun, glass for sample.

As Built

NOTE ALL SOIL AND ROCK
 DESCRIPTIONS AND CLASSIFICATIONS
 DETERMINED BY VISUAL
 INSPECTION.

BN Silty sand with pebbles, silt-
 viol, brown powder of weathered
 sandstone. Blow Count 11-14-21
 BN Silty sand with angular sand-
 stone pebbles like above, slowly
 permeable. Blow Count 19-21-50
 BN Weathered sandstone with inter-
 beds of siltstone. Blow Count 20-40
 -76. Forms an BN
 Weathered sandstone breaks up
 as gravel and sand but can't sample
 will span any deeper. Use 20 as
 backdr. Blow count 21-92-106
 Sandstone, very fine weathered,
 light brown
 Mudstone, silty dark red, weathered
 firm for foundation
 Sandstone very fine to silty,
 massive, some mica dark red to
 dark gray, this rock is almost a
 siltstone
 Mudstone, red, massive
 Sandstone, very fine, hard some
 iron stain along joints, some mica
 Siltstone, sandstone, mudstone,
 massive dark gray to red.
 Mudstone, silty dark red, massive

Mudstone, brown to yellow, very
 fine
 Sandstone, gray, abundant carbon
 flakes and some, some siltstone
 and mudstone interbedded. Similar
 to other gray carbonaceous sand-
 stone in area. Some pyrite present
 with carbon. Black stain on joint
 faces also iron stain particularly
 at 60' Rock is very hard, com-
 petent, well cemented.

BN-15 Elev. 2074.35

BN Weathered very fine sandstone
 with some interbedded siltstone
 and mudstone, brown to yellow.
 Blow Count 11-21-29
 BN Same as above. Blow Count 10-31-
 42
 BN Sandstone, weathered very fine
 to siltstone. Blow Count 21-30-49
 BN Weathered sandstone fine
 grained brown seems to be made up
 of sand with a small amount of
 smaller particles of silt. Blow
 Count 15-34-58
 BN Very fine sandstone to siltstone
 with some mudstone fragments.
 Blow Count 11-64-92
 BN Interbedded sandstone, siltstone
 with a firm sandstone at 30 feet,
 this rock is weathered. Blow Count
 21-76-103
 Sandstone weathered to hard for
 split spoon sampling.

BN-101 Elev. 2013.34

BN Weathered very fine sandstone
 with some silt, forms a silty
 sandstone. Blow Count 17-30-42-55
 This is regular material with some
 fines, may be a CH-CH. Slowly
 permeable to air. Blow
 Count 11-64-92
 BN Same as above with less fines.
 Blow Count 11-64-92
 Weathered sandstone.
 BN Weathered sandstone forms a CH
 or CH. Blow Count 33-30-01
 BN Weathered sandstone, very fine
 to siltstone. Blow Count
 20-44-58-57
 BN Weathered very fine sandstone
 Blow Count 30-45-60
 BN Weathered sandstone - this ap-
 pears to be a CH or CH. This ma-
 terial is quite permeable and colli-
 coidal and residual material from a
 sandstone weathered material.

BN Highly weathered sandstone,
 very fine to silty, forms an BN
 with angular pebbles. Blow count
 11-64-92
 BN Siltstone to mudstone
 highly weathered, sandy, forms a
 BN to CH with some pebbles.
 Blow Count 21-40-52
 BN Sandstone highly weathered,
 dark brown, silty, forms a silty
 sand. Blow Count 20-45-76.
 BN Same as above but more
 mica and clay. Blow Count
 10-40-70.
 BN Same as above but more like
 10-15' less fines more sand, Blow
 Count 33-41-72
 BN Sandstone becoming less weathered
 forms a silty sand with sandstone
 fragments. Blow Count 21-54-108.
 No backdr in this hole. All
 sandstone is highly weathered to
 weathered.

BN-16 Elev. 2099.6

Leaves and top soil
 Silty sand with about 10 percent
 clay with small rounded pebbles,
 weathered sandstone. Blow Count
 5-5.5 - 26, 5.5-6 - 26 (BN or CH)
 BN Same as above - Blow Count
 10-11.5 in 0.5' increments 13-26-48.
 This material is a weathered sand-
 stone.
 BN Weathered sandstone, silty, drilled
 from 11.5 to 15 but got no good
 cutting were very fine, sand, and
 silt. Blow Count 40-3-30. Weathered
 sandstone forms a sand with small
 angular pebbles.
 BN Weathered sandstone, silty,
 Blow count 40-130
 BN Weathered sandstone tried to core
 poor core recovery. Blow Count 31-55
 BN Weathered sandstone very fine
 to silty tried to get sample at 30'
 but too hard. Split spoon sample
 35-30. Blow Count 70-166.

Tried to core 30-30 got foot of
 core
 BN Interbedded sandstone and silt-
 stone. Blow Count 35-35-5 - 60
 Blow Count 35-35-5 - 60
 Interbedded siltstone, sandstone
 and mudstone silty brown, black stain
 along joints, some mica.
 Mudstone, silty gray-green, some
 mica, some is very fine mudstone.
 Mudstone, silty, dark red, massive

BN-102 Elev. 2070.54

BN Weathered sandstone, colloidal
 and alluvial material forms a CH
 or CH. Blow Count 17-30-42-55
 BN or BN Weathered very fine sand-
 stone forms a CH or BN. This ma-
 terial is quite permeable in places.
 Blow Count 20-44-58-57
 BN or BN Weathered sandstone same
 as above. Blow Count 47-52-57
 BN or BN Weathered sandstone and
 colloidal sand and gravel, CH or
 CH. Blow Count 30-45-66
 BN Weathered fine sandstone, per-
 meable, forms a fine to very fine
 pebbly BN. Blow Count 01-75-77
 BN Fine to hard sandstone, very
 fine to silty forms a CH or CH
 Blow Count 43-52-79

SHEET 3

UPPER NORTH RIVER WATERSHED
 OF THE POTOMAC RIVER WATERSHED PROJECT
 MULTIPLE PURPOSE DAM NO 75
 AUGUSTA AND ROCKINGHAM COUNTIES, VIRGINIA
 SOILS INFORMATION

U.S. DEPARTMENT OF AGRICULTURE
 SOIL CONSERVATION SERVICE

Project R. WILSON, R. C. BARNES JR 0-62	Date 0-62
Investigator DORIS PERRYMAN, JEAN J. FEMER A. S. COFFMAN	Date 0-62
Station R.F. FOWLER	Sheet R-2242
Drawing No VA-472-P	2

EM-103 Elev. 2016.69

see at 6' 0"

Colluvial and alluvial material from weathered very fine silty sandstone forms a SN or GN. Blow Count 17-20-42.

SN or GN Colluvial silty and clayey sandy sand and gravel. Blow Count 20-21-22.

SN Silty sand with some clay and pebbles from weathered sandstone. Blow Count 17-18-23.

SN Silty, sandy gravel GN. Blow Count 23-27-43.

Weathered sandstone had to core drill got one foot of core.

EM-104 Elev. 1991.24

SN Colluvial and alluvial silty sand with pebbles. Blow Count 13-24-42.

GN Colluvial silty sandy gravel with angular pebbles. Blow Count 24-25-19.

SN Same as above but less silt and pebbles. Almost an SP. Blow Count 4-3-5.

SN Weathered sandstone forms a silty sand, brown to gray.

SN Weathered sandstone refusal at 20". Blow Count 20-44-100.

EM-105 Elev. 2040

SN Very fine brown, silty sand with some rounded pebbles alluvial and colluvial sand. Blow Count 10-21-20.

SN Same as above but pebbles are angular and some clay is present. Blow Count 33-60-71.

SN Same as above but greater percentage of silt almost an ML. Blow Count 21-24-20 Pebbles are sandstone, siltstone and sandstone.

SN Same as above but may be enough pebbles to make a GN-SN. Blow Count 49-45-40.

SN Same as above but less fines but still a silty sand with pebbles. Blow Count 33-20-17.

SN or SC Very fine silty to clayey sand with pebbles, this is almost an ML from blow count 9-7-10.

SN Silty sand with pebbles, like above. Blow Count 20-46-67.

TP-101 & 102 (See EM-101 & 102)

GN Gravel angular, well graded, colluvial and alluvial, very fine fines

0-12"	1550	212
6-12"	2020	372
3-6"	1930	182
Total	5500	766

Total Weight 7540

* Sample consists of material less than 3" size.

TP-103 (See EM-103) EM-103-1

GN Silty gravel, cobbles 20 percent by weight on

TP-107 Elev. 1995.6

SN or GN Silty gravel to silty sand.

SN Silty gravel with siltstone and sandstone pebbles to boulders.

TP-108 Elev. 1996.8 EM-108-1

Silty gravel, rounded alluvial pebbles to cobbles. Water at 11' G.M.

Sandstone, very fine, brown weathered

Refusal 100 Blows for 0.1 foot. Sample of material that has fallen in hole.

TP-110 (See EM-10)

GN Silty gravel rounded pebbles to cobbles some bigger than 3"

GN Same as above, but 3 percent cobbles 6-12" size.

GN-GP $d_{60} = 6 - 6"$

Refusal at 9' see EM-10.

TP-120 EM-120-1

SN Silty sand very fine and cobbles

GN Silty gravel

Silty sandstone over 12" Field sample over 12" Less than 3" Total Wt.

* Sample consists of material less than 3" size.

TP-124 Elev. 2001.4

GN or GN Silty sand and gravel, rounded alluvial, water at 5'

TP-125 Elev. 2000.0 EM-125-1

GN or GN, rounded alluvial pebbles to cobbles, water at 6'

Field Sample over 12"	220	270
6-12"	120	150
3-6"	100	100
Less than 3"	230	230
Total Wt.	670	650

TP-126 Elev. 2004.6 EM-126-1

GN or GN doesn't appear to be silty water at 7 feet, gravel is rounded to sub-rounded, may be good for filter.

Field Sample over 12"	0	0
6-12"	260	170
3-6"	100	100
Less than 3"	2320	300
Total Wt.	4480	570

TP-127 Elev. 2006.7

GN or GN Silty to well graded gravel, alluvial like TP-127 but not as clean and well rounded. Water at 5', permeable

TP-128 Elev. 2007.7

GN or GN Silty to well graded alluvial pebbles to cobbles, permeable rounded to medium pebbles to cobbles, water

EM-125 & 126-1 Sample consists of material less than 3" size.

TP-132 Elev. 2007.9

GN or GN Well graded to silty gravel, rounded to sub-rounded slowly permeable, water at 4 feet

TP or GN very permeable, 50% greater than 6"

TP-133 Elev. 2012.6

GN or GN, alluvial, rounded pebbles to cobbles, hole dry, very slowly permeable.

TP-134 Elev. 2018.4

SN Silty sand with pebbles

SN Silty sand with pebbles to cobbles, no water.

TP-135 Elev. 2015.0

GN Silty gravel, black GN or GP, water at 5'

TP-136 Elev. 2020.7

GN Silty gravel reddish brown alluvial pebbles to cobbles

GN Silty gravel with very fine hole dry.

TP-140 Elev. 2011.7 EM-140-1

GN Silty to well graded gravel, water at 6'

Field sample over 12"	00	00
6 to 12"	570	120
3 to 6"	730	100
Less than 3"	3120	710
Total Wt.	4420	930

TP-141 Elev. 2013.6

SN Sand, well graded to silty sand

SN or GN pebbles to cobbles, water at 5'

TP-209 Elev. 2096

SN Silty sand, gray brown residual sandstone

SN or GN Silty sand, tan with pebbles to cobbles, weathered silty sandstone.

GN or SN Weathered silty sandstone forms a GN or SN

TP-210 Elev. 2125.2 EM-210-1

SN or GN residual silty sandstone

SN Highly weathered sandy siltstone, forms a pebbly SN

SN or ML Weathered thin bedded silty sandstone, forms a SN or ML can be ripped deeper.

TP-211 EM-211-1

SN Silty sand, gray brown silty sandstone

SN or GN Silty sand, tan with pebbles to cobbles, weathered sandstone

SN or GN Weathered silty of forms a GN or SN

TP-401 EM-401-1

GN or GN Silty to well graded, water at 5'

Field Sample over 12"	00	00
6-12"	200	40
3-6"	100	20
Less than 3"	2100	40
Total Wt.	2400	60

Refusal - Quartzite silty sandstone

TP-402 EM-402-1

SN or SP Well to poorly graded sand to gravel

GN or GN Well graded to silty gravel

Field Sample over 12"	00	00
6-12"	100	20
3-6"	100	20
Less than 3"	3200	90
Total Wt.	3400	130

TP-105 (See SS-105)

TP-105 (See SS-105)
SS-105-1

TP-105 Elev. 2031.0
SS-105-1

OH Silty gravel, alluvial and colluvial with rounded to angular pebbles to boulders. Water at 7'.

OH Silty gravel, with no cobbles larger than 6" most are less than 3".
OH or HL residual OH to HL, some weathers to fine silty clay with pebbles to boulders.
OH or HL weathered, very fine sandstone to siltstone with siliceous nodules 12" See SS-105

OH Colluvial silty gravel, brown with angular to subrounded, sandstone to siltstone cobbles. 50% greater than 3" about 10 percent greater than 12". Very little clay.

TP-106 SS-Split Spoon
J-Glass Jar

TP-121 Elev. 1996.3
SS-121-1

TP-122 Elev. 1995.0

TP-123

OH Silty to well graded gravel, rounded, alluvial. Water at 6'.
Field sample over 12" 0 OH
6-12" 1250 362
3-6" 900 262
Less than 3" 1550 472
Total Wt. 3600
*Sample consists of material less than 3" size.

OH or SP clean alluvial Silty gravel rounded cobbles to boulders
Cobbles and boulders Water at 6'. See 121-1

OH or OH Silty gravel, rounded to subrounded pebbles to boulders. See 121-1

TP-129 Elev. 2003.0

TP-130 Elev. 1997.4
SS-130-1

TP-131 Elev. 2001.0

OH or OH Silty sand to gravel alluvial and colluvial OH or OH
OH or OH alluvial, sub-rounded to rounded. Water at 6', slowly permeable.

OH Silty to well graded gravel, sub to well rounded, slowly permeable. Water at 6'.
Field sample over 12" 250 77
6-12" 1400 417
3-6" 840 212
Less than 3" 1200 308
Total wt. 4090
*Sample consists of material less than 3" size.

OH Silty sand with pebbles to cobbles, alluvial, slowly permeable, rounded to sub-rounded
OH or OH well graded to silty gravel. Water at 5' See TP-120

TP-137 Elev. 2020.2

TP-138 Elev. 2008.5
SS-138-1

TP-139 Elev. 2006.0

OH Silty sand with pebbles, brown to black
OH Gravel, silty with water at 6'

OH Silty sand with pebbles and cobbles
OH Gravel, well graded to silty Water at 3'
Field sample over 12" 950 192
6-12" 610 92
3-6" 950 192
Less than 3" 2050 372
Total Wt. 5160
*Sample consists of material less than 3" size.

OH or OH Silty to well graded gravel. Water at 5'

TP-212 (See SS-10)
SS-212-1

TP-213 (See SS-13)
Elev. 2110.06
SS-213-1

TP-215 Elev. 2060.3
SS-215-1

OH or OH Silty sand to gravel, tan residual silty sandstone.
OH Highly weathered silty sandstone, OH with pebbles.
OH or HL weathered very fine silty sandstone forms a OH or HL with pebbles.

OH or OH Sandy silty gravel, dark brown
OH or OH Highly weathered very fine silty sandstone, brown to red brown very fine in place, rough residual pebbles and cobbles to form a OH
OH or OH weathered very fine sandstone to siltstone, siliceous nodules and residual sandstone pebbles to cobbles to form a silty gravel.


OH or OH Highly weathered silty very fine sandstone forms a OH or OH
OH or OH weathered silty sandstone forms a OH or OH
All holes in spillway were dry and well drained.

NOTE: SOIL & ROCK DESCRIPTIONS DETERMINED BY VISUAL INSPECTION
UNLESS OTHERWISE INDICATED BY LABORATORY INVESTIGATION
GEOLOGICAL INVESTIGATION DATE: DEC 61 - JAN 62 - FEB 62


AS BUILT SHEET 4

UPPER NORTH RIVER WATERSHED
OF THE POTOMAC RIVER WATERSHED PROJECT
MULTI-PHASE PROJECT - AM '76
SUNNYSIDE AND ROCKCREEK TOWNSHIPS, MARYLAND
SOILS INFORMATION

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE





PROFILE ALONG E OF DAM-LOOKING DOWNSTREAM
 SCALE: HOR. 1" = 80.0'
 VERT. 1" = 20.0'




PROFILE ALONG F OF OUTLET CHANNEL

5.12.5
11-0000



TYPICAL EXCAVATION SECTIONS OF LUTOFF TRENCH



PROFILE ALONG & OF VEGETATED WATERWAY

SCALE: HOR. 1" = 40.0' VERT. 1" = 8.0' AS BUILT SHEET 5

UPPER NORTH RIVER WATERSHED OF THE POTOMAC RIVER WATERSHED PROJECT MULTIPLE PURPOSE DAM NO 76 AUGUSTA AND ROCKINGHAM COUNTIES, VIRGINIA PROFILES

U.S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE

Designed by N. WILSON - BARNES 6-22-62	Approved by
Drawn by L.S. COFFMAN AUG 62 W.H. MORGAN OCT 62	Title
Checked by W.H. MORGAN	Date
Drawn by W.H. MORGAN	Sheet 9 of 19
	Drawing No. VA-472-P


Need Coord
(see from
found - 1952)



NOTE:

THE DESCRIBED ACCESS ROAD WILL BE USED FROM P. 27 94 TO THE ELEVATION OF THE NORMAL FEEL DRAINAGE AND A LOW WATER CROSSING OVER WHITE ROCK CANYON WILL BE PROVIDED AS SPECIFIED BY THE U.S. FOREST SERVICE.

THE SURVEY SCHEMATIC INDICATED FROM P. 27 94 (APPROX) TO THE EMERGENCY SPILLWAY ENTRANCE WILL NOT BE CONSTRUCTED OR USED IN THIS PROJECT.




NOTE:

1. ALL ORGANIC MATERIAL, STUMP, LOG AND BRUSH SHALL BE REMOVED FROM UNDER THE FILL AREA AS DIRECTED BY THE ENGINEER.
2. ANY INTERMIXING OF SOIL/TALUS MATERIAL SHALL BE REMOVED FROM UNDER THE FILL AREAS AS DIRECTED BY THE ENGINEER.
3. ALL STEEP SLOPES AND STEEP ROCK FACES SHALL BE CUT BACK TO A 1:1 SLOPE AS DIRECTED BY THE ENGINEER.

4. THE EMBANKMENT SIDE SLOPES SHOWN ARE SETTLED SLOPES. CONSTRUCTED SIDE SLOPES WILL BE ADJUSTED TO MEET THESE REQUIREMENTS.


5. EARTH SURFACE OF DAM TO BE FINISHED BY ROCK BAKING AND SMOOTHING.

ROCKS IN EXCESS OF 12" IN SIZE WILL BE RAMPED TO SECTION NO. 4 & DISPOSED IN THIS AREA TO FORM A DOUBLE PROTECTED SLOPE OF LEAST 1:1 IN SLOPING.




TYPICAL SECTION OF DAM

ADJUSTED SECTION



SECT. 1 (C) : SAND CORE MATERIAL (B-1)
 SECT. 1 (B) : LEAN SANDHURST CORE MATERIAL (B-1)
 SECT. 4, 3 : SAND TO ADJUSTIVE CORE MATERIAL (B-1)
 SECT. 2, 3, 4 : SAND FILL



NOTE: LEAK EXHAUSTED FROM THE EMERGENCY EXHAUST THAT IS INSTALLED IN THE DAM. WATER WILL BE DETERMINED BY THE ENGINEER, ONLY AS SHOWN IN SECTION 5 OF THE DAM AND IN THE EMERGENCY EXHAUST LINE AND NOT FOR AS COMPACTED EARTH FILL. THE REQUIREMENTS OF THE EXHAUSTED DAM WILL BE DISPOSED OF ON THE DAM AND TOE OF THE DAM AND ON THE INTERIOR OF THE DAM. THE LOCATION OF THE EXHAUST LINE IS SHOWN ON THE PLAN AND IN THE AMOUNT OF EXHAUSTION OF THE DAM IS SUBSIDIARY TO LEAK EXHAUSTION.

SAND CLAY (SC)

THE LOSS OF FROM 1 FT TO 12 FT (B-2 FILL)

GRAVELLY (GSA/GW)

ALL (GSA AND GW) MATERIAL BE REPRESENTED BY THE LOSS OF TO 1 FT FROM 1 FT TO 6 FT MATERIAL LARGER THAN TO 125 FROM 1 FT TO 6 FT AND TO 150 FROM 1 FT TO 6 FT (SEE SPEC. 5-D "EARTH FILL", CLASS B-2 FILL)

SECTION NO. 3

ALL (GSA AND GW) MATERIAL FROM THE DESIGNATED BOUNDARY AREAS AS REPRESENTED BY THE LOSS OF TO 1 FT FROM 1 FT TO 6 FT AND TO 150 FROM 1 FT TO 6 FT (SEE SPEC. 5-D "EARTH FILL", CLASS B-2 FILL)

SECTION NO. 4 AND 4A

ALL (GSA AND GW) MATERIAL FROM THE DESIGNATED BOUNDARY AREAS AS REPRESENTED BY THE LOSS OF TO 1 FT FROM 1 FT TO 6 FT AND TO 150 FROM 1 FT TO 6 FT (SEE SPEC. 5-D "EARTH FILL", CLASS B-2 FILL)

ROCK TOE MATERIAL GRADE: INSTG FROM 100 TO 100-0000

AS BUILT SHEET 6


UPPER NORTH RIVER WATERSHED
 OF THE POTOMAC RIVER WATERSHED PROJECT
 MULTIPLE PURPOSE DAM NO. 7
 RESERVOIR AREA MAP

U.S. DEPARTMENT OF AGRICULTURE
 SOIL CONSERVATION SERVICE

H. W. WILSON, R. C. BARNES, JR. 6-66


S. COFFMAN 4-66

W. A. Anderson, VA-472-P2




PROFILE ALONG INNER EDGE OF EMERGENCY SPILLWAY
CENTERLINE STATIONS

SCALE HORIZ. 1" = 100'
VERT. 1" = 10'



AS BUILT SHEET 7

<p>UPPER NORTH RIVER WATERSHED OF THE POTOMAC RIVER WATERSHED PROJECT MULTIPLE PURPOSE DAM NO 76 AUGUSTA AND ROCKINGHAM COUNTIES, VIRGINIA PROFILES</p>	
<p>U.S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE</p>	
<p>Designed WILSON BARNES APR 62</p>	<p>Reviewed by</p>
<p>Drawn L.S. COPPIN AUG 62</p>	<p>Checked</p>
<p>Checked T. Y. BARNHINE, JR. OCT. 62</p>	<p>Approved</p>
<p>Project</p>	<p>Sheet</p>
<p><i>W. A. Adams</i></p>	<p>VA-472-</p>



PLAN
SCALE 1" = 30.0'

42" I.D. REINF. CONC. WATER PIPE
70 16'-0" SECTIONS
2 SIPCOT RING WALL FITTING


TOTAL • 1230.67

44 SECTIONS
J-4 TURN J-40
AND
J-27 TURN OUTLET


24 SECTIONS
J-40 TURN J-27


PRESSURE HEAD = 103'
LOAD = 45,700 LBS. PER LIN. FT. BASED ON O.D. OF 53"
MIN 3 EDGE BEARING STRENGTH FOR 0.001" CRACK
EQUALS 13,700 LBS. PER LIN. FT. FOR PRESTRESSED
PIPE AWWA C-301

PRESSURE HEAD = 103'
LOAD = 111,310 LBS. PER LIN. FT. BASED ON O.D. OF 50"
MIN 3 EDGE BEARING STRENGTH FOR 0.001" CRACK
EQUALS 26,400 LBS. PER LIN. FT. FOR PRESTRESSED
PIPE AWWA C-301




PROFILE ALONG E OF PRINCIPAL SPILL
SCALE HORIZ 1" = 30.0' VERT 1" = 20.0'





CHASSIS	DISTANCE FROM RIVER WALL SETTING	DEPTH	DISTANCE FROM RIVER WALL SETTING	INVERT ELEV. OF 48" CH. RIVER	WATER
1	0	0	0	1972.50	
2	5	10	10	1972.50	
3	10	20	20	1972.50	
4	15	30	30	1972.50	
5	20	40	40	1972.50	
6	25	50	50	1972.50	
7	30	60	60	1972.50	
8	35	70	70	1972.50	
9	40	80	80	1972.50	
10	45	90	90	1972.50	
11	50	100	100	1972.50	
12	55	110	110	1972.50	
13	60	120	120	1972.50	
14	65	130	130	1972.50	
15	70	140	140	1972.50	
16	75	150	150	1972.50	
17	80	160	160	1972.50	
18	85	170	170	1972.50	
19	90	180	180	1972.50	
20	95	190	190	1972.50	
21	100	200	200	1972.50	
22	105	210	210	1972.50	
23	110	220	220	1972.50	
24	115	230	230	1972.50	
25	120	240	240	1972.50	
26	125	250	250	1972.50	
27	130	260	260	1972.50	
28	135	270	270	1972.50	
29	140	280	280	1972.50	
30	145	290	290	1972.50	
31	150	300	300	1972.50	
32	155	310	310	1972.50	
33	160	320	320	1972.50	
34	165	330	330	1972.50	
35	170	340	340	1972.50	
36	175	350	350	1972.50	
37	180	360	360	1972.50	
38	185	370	370	1972.50	
39	190	380	380	1972.50	
40	195	390	390	1972.50	
41	200	400	400	1972.50	
42	205	410	410	1972.50	
43	210	420	420	1972.50	
44	215	430	430	1972.50	
45	220	440	440	1972.50	
46	225	450	450	1972.50	
47	230	460	460	1972.50	
48	235	470	470	1972.50	
49	240	480	480	1972.50	
50	245	490	490	1972.50	
51	250	500	500	1972.50	
52	255	510	510	1972.50	
53	260	520	520	1972.50	
54	265	530	530	1972.50	
55	270	540	540	1972.50	
56	275	550	550	1972.50	
57	280	560	560	1972.50	
58	285	570	570	1972.50	
59	290	580	580	1972.50	
60	295	590	590	1972.50	
61	300	600	600	1972.50	

NOTE:
FIGURES AT RIGHT FOR DISTANCE FROM RIVER WALL FITTING TO JOINT ARE BASED ON NOMINAL LENGTHS AND DO NOT INCLUDE CREEP.



AS BUILT SHEET 6

UPPER NORTH RIVER WATERSHED
OF THE POTOMAC RIVER WATERSHED PROJECT
MULTIPLE PURPOSE DAM NO 76
AUGUSTA AND ROCKINGHAM COUNTIES, VIRGINIA
PLAN - PROFILE OF PRINCIPAL SPILLWAY

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

DESIGNED BY WILSON & BARNES

DATE: M.T. BROWNING & ASSOCIATES

NO. 472


NOTE:
RIPRAP SHALL BE WELL GRADED FROM A MIN. SIZE OF 6" TO A MAX. SIZE OF 18". IT SHALL BE PLACED WITH THE LONGEST DIMENSION PERPENDICULAR TO THE LINE OF FLOW.

APPENDIX II
PHOTOGRAPHS


47



TOP OF EARTHEN BERM
VIEW FROM NORTHEAST
Photo #1




PRINCIPAL SPILLWAY STRUCTURE
(GOOD CONDITION)
Photo #2




STILLING BASIN AND OUTLET PIPE
(NOTE RIP RAP AND STILL WATER SURFACE)
Photo #3



DOWNSTREAM CHANNEL
(GOOD CONDITION)
Photo #4



EMERGENCY SPILLWAY
(NOTE CUT IN BACKGROUND)
Photo #5



LOWER END EMERGENCY SPILLWAY
(NOTE BROAD FLAT AREA)
Photo #6

APPENDIX III
FIELD OBSERVATIONS

FIELD OBSERVATIONS

Name of Dam: Upper North River No. 76 (Elkhorn Lake Dam)

County: Augusta

State: Virginia

Coordinates: Lat 38° - 19.6' Long 79° - 13.25'

Date of Inspection: December 13, 1978

Weather: Fair, temperature 45°

Pool Elevation at Time of Inspection: 2015.75 M.S.L.

Tailwater at Time of Inspection: 1966.5 M.S.L.

Inspection Personnel:

Schnabel Engineering Associates, P. C.
Ray E. Martin, P.E.
Stephen G. Werner (recorder)

J. K. Timmons and Associates, Inc.
Robert G. Roop, P.E.
William A. Johns (recorder)

State Water Control Board
John Hyden

1 Embankment:

1.1 Surface Cracks: The slopes, crest, emergency spillway, and abutment contacts were inspected and no cracks were noted. The embankment portion of the dam and spillway were covered with 3 to 4 ft high, light vegetation, making observations difficult. Small (1 to 2" diameter) trees were growing along the embankment at the north abutment contact and also on the downstream slope near the center of the embankment.

1.2 Unusual Movement: No unusual movements were noted on the dam or downstream beyond the embankment toe.

1.3 Sloughing or Erosion: No sloughing was noted, however, minor erosion was noted along the south and north abutment contacts.

The erosion consisted of approximately 6-inch deep gullies.

1.4 Alignment: The vertical and horizontal alignment of the dam was visually observed to be in accordance with "as built" drawings.

1.5 Riprap: Showed no displacement or washing and appeared to be in proper alignment.

1.6 Junctions: Conditions appear good at the junction of the embankment and the abutments. Numerous sandstone outcrops are exposed throughout the steep ridge which forms the north abutment. The sandstone is brown to gray, fine-grained and is thinly to massively bedded. Crossbeds occur locally. Bedrock strikes $65^{\circ}\text{NE}_{\pm}$ and dips $18^{\circ}\text{SE}_{\pm}$. Wedge-shaped or subrectangular joint sets were also measured: N25W, 90 and N85E, 85SE. The emergency spillway is in cut along the south abutment, which includes steep cut slopes (75-100' \pm high) with benches.

Slopes are not vegetated and the spillway is cut primarily in sandstone. Scattered shale interbeds near the middle of the slopes are capped with red shale. Bedrock strikes $65^{\circ}\text{NE}_{\pm}$ and dips $10^{\circ}\text{SE}_{\pm}$.

1.7 Seepage: One damp spot was noted about 20 ft right of the left abutment and about 50 ft downstream of the midslope drainage berm. We believe this wet area at about EL 2005 is the result of surface water seeping from the drainage berm above.

1.8 Staff Gage: None found.

1.9 Drains: The embankment contains a downstream rock toe drain which extends to about EL 2023 along the north abutment and along the toe of the embankment and a portion of the emergency spillway. This elevation along the left abutment corresponds with the outfall elevation of the downstream drainage berm at the left abutment. No discharge outlets were noted, however, the drain terminates on each side of the principal spillway pipe and is presumed to discharge into the downstream channel at this point. The midslope drainage berm contained a few wet spots which coincided with low areas and these are believed to be trapped surface water from rains which occurred just prior to the inspection. The approximate locations of these wet areas are illustrated on Sheet 2 in Appendix I.

2 . Reservoir:

2.1 Slopes: The upstream end of the reservoir is occupied by the river floodplain. Steep natural rock slopes with numerous sandstone outcrops bound the left side of the reservoir. The right side of the reservoir is graded locally but consists primarily of moderate to steep natural rock slopes, with sandstone and shale outcrops. No slide areas were noted around the perimeter of the reservoir. Sloughing was observed along the toe of the cut slope at the east end of the spillway.

2.2 Sedimentation: Slight sedimentation at stream inflow (alluvial fan of rock and sand). No evidence of any bottom sediment buildup. Water was very clear.

3 Downstream Channel:

3.1 Condition: Good. Channel has rock bottom.

3.2 Slopes: Downstream, steep natural slopes with sandstone and shale outcrops occur along the left and right sides of the stream. The stream valley narrows considerably, below the dam. No slope failures were noted in the valley adjacent to the toe of the dam.

3.3 Population and Facilities: None. Staunton Lake is 9,000' downstream.

4 Principal Spillway:

4.1 Intake Structure: The structure was in good condition. Gates were well greased, however, the lower gate is inoperable. Catwalk was in good condition. Concrete on the structure visually was in good condition.

4.2 Outlet Structure: Was in good condition. This was viewed from the downstream end and pictures of this can be seen in Appendix II.

5 Emergency Spillway:

5.1 Channel Section: Was found to be in uniform shape with exception of one section adjacent to Handkney Mountain, which showed sloughing of side slope. The bottom and side adjacent to berm was well vegetated

and found to be in design configuration. The rip
side slope was in good condition. The lower end
was a broad flat area in uniform design configuration.

6 Instrumentation:

6.1 Monumentation: None

6.2 Observation Wells and Piezometers: No
observation wells or piezometers were noted in the
field.

1. H. C. Turner, State Geologist, Virginia, 1932, p. 100, Richmond, Virginia

2. Roy H. Beards, Soil Mechanics Laboratory, U.S. Marine, 1932

3. Virginia 11-2, Upper West River, site 10, 16

APPENDIX IV

1. Page 125 126, Soil Mechanics Laboratory Note, 1 sheet.
2. Page 125 126, Suspension and Expansion Resistance Report, 17 sheets.
3. Figures 1 and 2, Soil-Mechanics and General Geology, Va. Road Curves, 1 sheet.
4. Page 125 126, Soil-Mechanics Laboratory Note, 1 sheet.
5. Page 125 126, Figure 1, Relation of Large Diameter River Spectra, 1 sheet.
6. Figure 1, Figure 1, Summary of Soil Engineering Properties as Determined by the West Virginia, 1 sheet.
7. Figure 1, Figure 1, Summary - Large Diameter Analysis, 3 sheets.
8. Figure 1, Figure 1, Summary of Large Diameter River Spectra, 1 sheet.
9. Figure 1, Figure 1, Summary of Large Diameter River Spectra, 1 sheet.
10. Figure 1, Figure 1, Summary of Large Diameter River Spectra, 1 sheet.
11. Figure 1, Figure 1, Summary of Large Diameter River Spectra, 1 sheet.
12. Figure 1, Figure 1, Summary of Large Diameter River Spectra, 1 sheet.
13. Figure 1, Figure 1, Summary of Large Diameter River Spectra, 1 sheet.
14. Figure 1, Figure 1, Summary of Large Diameter River Spectra, 1 sheet.
15. Figure 1, Figure 1, Summary of Large Diameter River Spectra, 1 sheet.
16. Figure 1, Figure 1, Summary of Large Diameter River Spectra, 1 sheet.
17. Figure 1, Figure 1, Summary of Large Diameter River Spectra, 1 sheet.
18. Figure 1, Figure 1, Summary of Large Diameter River Spectra, 1 sheet.
19. Figure 1, Figure 1, Summary of Large Diameter River Spectra, 1 sheet.
20. Figure 1, Figure 1, Summary of Large Diameter River Spectra, 1 sheet.
21. Figure 1, Figure 1, Summary of Large Diameter River Spectra, 1 sheet.
22. Figure 1, Figure 1, Summary of Large Diameter River Spectra, 1 sheet.
23. Figure 1, Figure 1, Summary of Large Diameter River Spectra, 1 sheet.

APPENDIX IV

STABILITY ANALYSIS

INTRODUCTION

1. The purpose of this report is to provide a stability analysis of the proposed dam and to determine the safety factor for the dam under various conditions of loading and water level.

The dam is located on the right bank of the river and is a gravity dam. The foundation is on a bed of sandstone. The water level is assumed to be at the top of the dam. The safety factor is calculated as 1.25.

The safety factor is calculated as 1.25. The dam is considered to be safe under all conditions of loading and water level.

2. The purpose of this report is to provide a stability analysis of the proposed dam and to determine the safety factor for the dam under various conditions of loading and water level.

TO : R. C. Barnes, State Conservation Engineer, DATE: June 8, 1952
 SCS, Richmond, Virginia

FROM : Rey S. Decker, Head, Soil Mechanics Laboratory,
 SCS, Lincoln, Nebraska

SUBJECT: Virginia FP-2, Upper North River, Site No. 76

ATTACHMENTS

1. Form SCS 354, Soil Mechanics Laboratory Data, 4 sheets.
2. Form SCS 352, Compaction and Penetration Resistance Report, 15 sheets.
3. Figures 1 and 2, Void-Ratio and Percent Consolidation vs. Load Curves, 2 sheets.
4. Form SCS 355, Triaxial Shear Test Data, 6 sheets.
5. Form SCS 353, Figure 3, Gradation of Large Diameter Shear Specimens, 1 sheet.
6. Form SCS 347, Figure 4, Summary of Soil Engineering Properties on South Fork Watershed, West Virginia, 1 sheet.
7. Form SCS 357, Summary - Slope Stability Analysis, 3 sheets.
8. Figure 5, Estimate of Construction Pore Pressure, 1 sheet.
9. Figure 6, Estimate of Seepage through the Bedrock in the Flood Plain Section, 1 sheet.
10. Form SCS 353, Figure 7, Grain Size Distribution Graph, 1 sheet.
11. Figure 8, Percent Consolidation vs. Load for the Embankment Core, 1 sheet.
12. Form SCS 372, Embankment Placement Recommendations, 2 sheets.
13. Geological Plans and Profiles.

DISCUSSION

FOUNDATION:

- A. Classification: The bedrock at this site consists of alternating beds or stratum of very fine sandstone and siltstone or mudstone. The bedrock in the valley is described as extremely hard.

Bedrock is exposed on the relatively steep left abutment and in the channel section. The bedrock in the flood plain and terrace level to the right of the channel is mantled with gravelly and cobbly material. The thickness of the mantle through these sections ranges from about 8 feet to 40 feet. Samples of the mantle from the vicinity of the toe drain indicate that the material in the flood plain is very coarse (27% finer than No. 4); whereas, the surface material in the terrace is considerably finer with about 55% finer than the No. 4 size and 8% cobbles.

The bedrock in the right abutment is mantled with residual silty sands to depths of about 20 feet.

- B. Shear Strength: Standard penetration tests were made in the alluvial and colluvial gravels. The blow count was high; it is questionable, however, whether blow count can be related to shear strength in a cobbly material.

Ray S. Decker

Subj: Virginia PP-2, Upper North River, Site No. 76

such as this. A triaxial shear test was made on material from the flood plain borrow area. The shear data obtained is discussed under the embankment section of this report. Based on the shear tests made, it appears that $\phi = 35^\circ$ would be a conservative design value for the gravelly and cobbly foundation material.

- C. Permeability: Field permeability tests were made in two locations in the terrace material. Computed permeability rates based on the field permeability test data in the geologic report are in the range of 3 to 5 feet per day in the tighter material and from 37 to 86 feet per day in the somewhat looser (lower blow count zone) material. The computed rates for each field test are shown on the attached profile. The rates were computed from the equation and data given in the open end permeability test procedure in the Bureau of Reclamation's, "Earth Manual". There is a small error involved since the head was not constant. The rates were computed to show ranges of permeability and are believed to be satisfactory for this purpose.

Pressure tests were conducted in the bedrock at several locations. The results of the tests are included in the geology report. Permeability rates were computed from this data in accordance with the equation $k = C_p \frac{Q}{H}$.

given in the Packer test procedure in the Bureau of Reclamation's "Earth Manual". H was considered as the distance from the ground surface to the midpoint of the test zone. No water table was considered, except in test hole # 2 where the water table was considered at 22.5 feet. The diameter of the test hole was considered as NX.

The computed permeability rates are shown on the attached Form BCS 35D.

EMBANKMENT:

- A. Classification: The borrow materials fall into two general categories consisting of (1) weathered sandstone and siltstone from the emergency spillway and the abutment downstream from the spillway and (2) the flood plain material.

Samples of the weathered sandstone ranged from CL-ML to GC-GM. The general range of material appears SC-SM, however, with the percent of fines ranging 23 on the GC-GM to 53 on the CL-ML. The percent of gravel ranged from 15 to 45 percent.

The flood plain gravels can be divided into two general groups, based on the amount of gravel or cobbles larger than 3.0 inches. Samples 62F1108, 62F1109, 62F1110 and 62F1112 contained from 24 to 36 percent material finer than 3.0 inches in diameter. Samples 62F1111, 62F1113 and 62F1114 contain from 53 to 63 percent finer than 3.0 inches in diameter.

- B. Permeability: Estimated permeability rates of the embankment materials are shown in the following table:

3 -- R. C. Lamm -- 6/2/62

Ray S. Becker

Subj: Virginia FP-2, Upper North River, Site No. 76

Type of Material	Lab. Sample No.	k Ft./Day	Size Range Considered
Residual Silty Sandstone	62F1107	0.007	Minus No. 4
(Bankment Core)	62F1103	0.009	Minus No. 4
Coarse Flood Plain Borrow (Shell Section)	62F1108	18.0 0.03	Field Gradation Fraction Finer Than 6.0"
	62F1109	200+ 25.0	Field Gradation Fraction Finer Than 6.0"
	62F1110	180 17.0	Field Gradation Fraction Finer Than 6.0"
	62F1112	200+ 3.0	Field Gradation Fraction Finer Than 6.0"
Finer Flood	62F1111	6.0	Fraction Finer Than 6.0"
Plain and Terrace	62F1113	0.5	Fraction Finer Than 6.0"
Borrow (Shell Section)	62F1114	1.5	Fraction Finer Than 6.0"

The permeability rates shown for the core section were measured rates on the consolidation test specimens. The rates shown for the shell materials were estimated from Hazen's Formula, $k = 2 (D_{10})^2$, where the D_{10} size is in mm. and k is in feet/minute. The computed rates are reported in feet/day and were reduced one order of magnitude, according to the approximate correlation of D_{10} to D_5 size as contained in the preliminary report by Moran, Proctor, Mueser and Rutledge on the "Study of Effective Use of Coarse Grained Soils in Construction of Earth Fill Dams".

- C. Compacted Density: Standard Proctor compaction tests were made on the minus No. 4 size fraction on 15 of the borrow samples submitted. The test data is shown on the attached Forms SCS 352. Corrected density for material larger than No. 4 size is also shown.

The borrow samples were submitted in moisture-proof bags. In order to obtain additional information on the compaction characteristics as well as the field moisture content, a small portion of the moist sample finer than 1 1/2 inches in diameter was compacted in a 1/30 cubic foot mold and also in a 1/13.3 cubic foot mold using Standard Proctor effort. The 1/30 cubic foot mold has a 4.0" diameter and the 1/13.3 cubic foot mold has a 6.0 inch diameter.

Ray S. Becker

Subj: Virginia PP-2, Upper North River, Site No. 76

After completion in this manner, the gradation was determined from the material in the 1/30 cubic foot mold. With percent of material larger than No. 4 known, it was then possible to compute the density and moisture content of the minus No. 4 fraction.

The Standard USER equations for correcting the compacted density and moisture content based on the percent material larger than No. 4 size were used. The density and moisture content of the soil and rock mixture was known. Therefore, the equations were solved for the density and the moisture content of the minus No. 4 fraction. The computed density and moisture content of the minus No. 4 fraction is shown on the compaction reports with relation to the Standard compaction curve.

You will note that there is pretty good agreement between the Standard Proctor curve and the computed densities. It is, therefore, considered that the "rock correction" as normally used by the Laboratory is reasonable for density control of these materials.

D. Consolidation: Consolidation tests were made on two samples that represent the core section of the embankment. The tests were made on the minus No. 4 fraction from Samples 62F1107 and 62F1103. The test samples were compacted to 95 percent of Standard Proctor density. The void-ratio versus load and the percent consolidation of the Laboratory samples are attached, Figures 1 and 2.

E. Shear Strength: Triaxial shear tests were made on Samples 62F1097, 62F1103 and 62F1107 to represent the center section of the embankment. Shear tests were made on a mixture of 62F1108, 62F1111, 62F1113 and 62F1114 to represent the shell sections. A total of three tests were made on this material, consisting of two tests using 4.0 inch diameter test specimens with a maximum particle diameter of 1.0 inch and one test using 6.0 inch diameter test specimens with a maximum particle diameter of 1 1/2 inch. The shear data obtained are summarized as follows:

Sample No.	Emb. Sec. Represented	Diameter of Test Specimen (Inches)	Density (p.c.f.)	% of Standard Proctor	Degree of Saturation (%)	ϕ	c (p.s.f.)
62F1097	Center	1.4	105.5	95.4	98+	23.5°	500
62F1103	Center	1.4	103.6	94.8	95+	23°	350
62F1107	Center	1.4	110.5	95.2	97+	26°	350
62F1108	Shell	4.0	127	95	82-88	36°	0
1111		4.0	132.5	100	91-97	35°	575
1113		6.0	138.5	102	100	43°	1000
1114							

pore pressure was measured during the test on Sample 62F1103 and the effective stress values are recorded on the triaxial shear test data sheet.

Ray S. Decker

Subj: Virginia RF-2, Upper North River, Site No. 76

The gradation used for tests on the shell material is shown on the attached Form SCS 353, Figure 1. The test samples were regraded as shown. Some trouble was encountered with consolidation and glycerine leaks on those large diameter test specimens. The data is believed to be quite consistent, however, in that the strength increased with density as would be expected. The c value obtained is believed to be due primarily to the increased density of the fines. You will note that c was 0 at 95% of Standard, 575 p.s.f. at 100% of Standard and 1000 p.s.f. at 102% of Standard Proctor. The increase in ϕ between the 4.0 inch diameter tests and the 6.0 inch diameter test is due, in part, to the increase in gravel percentage from 44 to 56%, respectively.

The shear data obtained on these gravelly materials are in pretty good agreement with data previously obtained on granular material from the South Fork Watershed in West Virginia. A summary of the average values from the South Fork Watershed is attached for comparison, Figure 4.

SLOPE STABILITY:

The stability of the proposed embankment was checked with a Modified Swedish Circle Method of analysis. Two sections were analyzed -- one at the channel section where the bedrock occurs at a very shallow depth and one on the terrace section where from 30 to 40 feet of gravelly material overlies bedrock.

The analysis considered a zoned embankment with a phreatic line from emergency spillway elevation (2064) to a drain at $c/b = 0.6$. The shear strength of Sample 62F1097 ($\phi = 23.5^\circ$, $c = 500$ p.s.f.) from the emergency spillway was used to represent the core. The shell material was considered to be represented by Samples 62F1108, 62F1111, 62F1113 and 62F1114. The shell was considered at 100% of Standard Proctor with shear strength of $\phi = 36^\circ$, $c = 575$ p.s.f. At the maximum section the analysis considered the embankment only. Satisfactory factors of safety (greater than 1.5) were obtained on a 2 1/2:1 upstream slope when the central core was limited to 3/4:1 (Trial No. 1 and Trial No. 1A). Trial No. 1B shows that a 3:1 slope is required to obtain a factor of safety of 1.50 on the upstream slope when the upstream slope of the central core is 1 1/2:1.

The analysis showed a factor of safety of 1.82 for a 2 1/2:1 downstream slope with the slope of the central core at 1 1/2:1. This factor of safety would be increased somewhat if the shell section, with selective placement, effectively drains the central core.

The analysis on terrace section assumed that the shear strength of the gravelly foundation was $\phi = 36^\circ$, $c = 0$. The central core and the shell were considered the same as at the maximum section. This analysis shows that the proposed 2 1/2:1 upstream slope requires modification to obtain a factor of safety of 1.50. This could be accomplished by wide stabilizing berms as shown by Trial Circles 4A and 5A or by flattening the upstream slope to 3:1 (Trial Circle No. 6). The analysis at this embankment section considered a slope of 3/4:1 on the central core. A flatter slope such as 1:1 or 1 1/2:1 could be used, however, with very little change in the factor of safety, since the trial failure arc was restricted to the central core.

6 -- R. C. Burns -- 6/3/52

Roy S. Decker

Subj: Virginia RP-2, Upper North River, Site No. 76

A 3:1 upstream slope was checked for safety against overflows with an infinite slope analysis. For this purpose, shear strength of $\phi = 36^\circ$, $c = 0$ was used. A factor of safety of 1.15 was obtained when horizontal seepage forces were considered. The factor of safety obtained is considered adequate.

The water forces considered in this analysis are more severe than will result from construction pore pressure if the center section material is placed with a moisture content less than 3 to 4 percent wet of optimum. The construction pore pressure was estimated according to Hill's Method based on the laboratory consolidation curves. A plot of the construction pore pressure versus total stress is attached (Figure 5). The plot shows construction pore pressure for placement moisture contents of 17 percent, 19 percent and 21 percent, which covers the range from about optimum to 4 percent over optimum.

Trial Circle No. 7 on the attached slope stability summary shows the factor of safety obtained ($F_s = 2.2$) when estimated construction pore pressure was based on a placement moisture content of 21 percent.

RECOMMENDATIONS

- A. Site Preparation: Any overhangs or loose talus material that may be present should be removed from the relatively steep left abutment.
- B. Centerline Cutoff: We recommend a cutoff to bedrock at this site. This will involve relatively deep excavation through the moderate to highly permeable terrace gravels.

A minimum trench bottom width of 30 feet is recommended for the flood plain section and a minimum trench bottom width of 20 feet is recommended through the terrace section. Normal foundation preparation will probably remove most of the material overlying bedrock in the channel section; if not, the trench bottom width should be about 30 feet.

The formula $w = h - d$ taken from the Bureau of Reclamation's, "Design of Small Dams", was used as a basis for the suggested trench bottom widths. The reservoir head (h) was considered from normal pool level.

Based on the pressure tests made, it is apparent that seepage may be expected through the bedrock. In order to get some idea of the amount of seepage, the conditions shown on the attached Figure 6 were assumed. The estimated seepage loss through the flood plain section is 0.05 c.f.s. with the conditions assumed. Considering losses through the abutments, this figure may double. This estimate is conservative if the permeability of the bedrock is in the range of 2.5 ft./day or less.

The cutoff trench should be backfilled with SC or CL material and compacted to a minimum of 95 percent of Standard Proctor with the moisture content controlled to near optimum.

C. Principal Spillway: We recommend that the principal spillway be placed on bedrock. It appears that the amount of trench excavation could be reduced by shifting the conduit to the left of the proposed location shown on the attached Form SCS 350.

D. Drain: Drainage is required for embankment stability and also to provide a safe outlet for seepage that bypasses the cutoff trench through the bedrock. We recommend selective placement of the flood plain borrow in the downstream shell to control the phreatic line in the embankment. This may be accomplished by placing the coarse flood plain material in the outer shell of the downstream section with a transition zone of the finer flood plain material like Samples 62F1113 and 62F1114 between the core and the outer shell. The suggested placement for drainage purposes is shown on the attached Form SCS 372. The relation of the gradation of each of the embankment zones and the foundation material is shown on the attached Form SCS 353, Figure 7.

In addition to selective placement of the embankment, we recommend a rock toe drain to provide a safe outlet for seepage through the bedrock. The toe drain should bottom on bedrock through the flood plain and penetrate the terrace material to about an 8.0 foot depth. The coarse flood plain material like Sample 62F1109 should be used as a transition filter between the foundation and the rock toe.

A D₁₅ size of about 3 inches is suggested for the rock toe drain.

E. Settlement: The estimated settlement of the central core is 2 percent or 2 feet at the maximum section. The consolidation tests of the minus No. 4 fraction ~~was~~ used as a basis for this estimate. The percent consolidation versus load obtained on laboratory tests was reduced in proportion to the percentage of material larger than the No. 4 size. An average of 30% gravel was considered. The corrected consolidation curve is shown on the attached Figure 8.

F. Selection of Material: A zoned fill is recommended. Suggested placement of material, minimum density and placement moisture ranges are shown on the attached Form SCS 372. The minimum placement density suggested for the minus No. 4 fraction is 95% of Standard Proctor for the core and 100% of Standard Proctor for the shell.

G. Slopes: The results of the stability analysis are summarized as follows:

Section	Slope of the Outside Shell		Slope of the Core		F _s	Beam Width
	Upstream	Downstream	Upstream	Downstream		
Maximum at Station 21+25	2 1/2:1		1 1/2:1		1.35	10'
		2 1/2:1		1 1/2:1	1.82	Normal 10'
	2 1/2:1		3/4:1		1.63	10'
Terrace Section at Station 19+50	3:1		1 1/2:1		1.55	10'
	2 1/2:1		3/4:1		1.33	10'
	2 1/2:1		3/4:1		1.50	55'
	3:1		3/4:1		1.50	10'

Ray S. Decker

Subj: Virginia PP-2, Upper North River, Site No. 76

We suggest embankment slopes of 3:1 upstream and 2 1/2:1 downstream with the 10 foot berms as originally proposed. The slope of the central core can be as flat as 1 1/2:1, depending on availability of material.

Prepared by:

Lorn P. Dunningan

Reviewed and Approved by:

Roland B. Phillips

Attachments

cc: R. C. Barnes (6 Four are being forwarded now and two the first of next week)
H. M. Keutz, Upper Darby, Pennsylvania (2)
G. W. Gruth, Upper Darby, Pennsylvania

SUMMARY - SLOPE STABILITY ANALYSIS

Sheet 1 of 3

State MISSISSIPPI Project USDA New River

Date 5-16-62 Analysis Made By TRIMMER Checked By CELF

Method of Analysis SWEDISH METHOD

To be used to report to field offices data used for slope stability analyses and the results of the analyses. The right side of the form will be used for a sketch of the embankment on which the analyses have been made.

Location of Material	Date				Soil			
	Emb.		Emb.		Emb.		Emb.	
	95% sat		95% sat		20% sat		10% sat	
	SC		SC		SC		SC	
Sample No.	125 030		125 100		125 107		125 110	
γ_d	113.0		103.5		116.5		122.5	
γ_m	130.0		121.5		125.5		144.5	
γ_s	133.0		126.0		121.5		146.0	
γ_b	70.5							
Condition	Opt.	Sat.	Opt.	Sat.	Opt.	Sat.	Opt.	Sat.
ϕ				23.5°	$\phi' = 31.5$ 26	(FROM TEST DATA SHEET - 02m)		
Tan ϕ				0.435	0.537	0.455		0.777
K								
C				500	$c' = 350$ 250	(")	250	505

UPSTREAM SLOPE			
Trial	Slope	Conditions	Fs
#1	2 1/2:1	Full drawdown - 10' berm @ elev 2015.5' - Ave cut from top shoulder thru second emb. with 3/4:1 slope on core. Sat. shear values only.	1.63
#1A	2 1/2:1	Same as No. 1 but with 1 1/2:1 slope on core	1.35
#2	2 1/2:1	Full drawdown - 10' berm @ elev 2015.5' - Ave cut from top shoulder thru second emb with 3/4:1 slope on core - Sat. shear values only.	1.73
#2A	2 1/2:1	Same as No. 2 but with 1 1/2:1 slope on core	1.44
#1B	3:1	Same as No. 1A but with 3:1 slope on shell	1.55

DOWNSTREAM SLOPE			
Trial	Slope	Conditions	Fs
#3	2 1/2:1	Draw @ 9/16:1 - 10.0' berm @ elev 2026.0' - Ave cut from top shoulder thru second emb with 1 1/2:1 slope on core. Sat shear values only.	1.52
#7	2 1/2:1	Factor of Safety Against Construction Failure - Estimated Pore Pressure Based on Placement Moisture Content of 21% Note: Zoned Emb.; Shell of 62F 1105, 1114, 112, 112 Core of 62F 1097	2.2

SUMMARY - SLOPE STABILITY ANALYSIS

Sheet 2 of 3

State VIRGINIA Project UPPER NORTH RIVER SITE # 76

Date 6-4-62 Analysis Made By GLM Checked By G.N.G


Method of Analysis SWEDISH CIRCLE

To be used to report to field offices data used for slope stability analyses and the results of the analyses. The right side of the form will be used for a sketch of the embankment on which the analyses have been made.

Location of Material	Found				Emb 95% Std		Emb 100% Std			
	Opt.	Sat.	Opt.	Sat.	Opt.	Sat.	Opt.	Sat.	Opt.	Sat.
Sample No.	Assumed				62F1097		1108, 1111, 62F1113, 1114			
γ_d					113.0		132.5			
γ_m					130.0		144.5			
γ_s	146.0				133.0		146.0			
γ_b					70.5		93.5			
Condition	Opt.	Sat.	Opt.	Sat.	Opt.	Sat.	Opt.	Sat.	Opt.	Sat.
ϕ		36°				23.5°		36°		
Tan ϕ		0.727				0.435		0.727		
K										
C		0				500		575		

UPSTREAM SLOPE			
Trial	Slope	Conditions	Fs
4	2 1/2 : 1/3 : 1	Full drawdown; 10' berm @ el. 2015.5; Arc cut from app. shoulder thru zoned emb & 21' into found.	1.33
4A	2 1/2 : 1/3 : 1	Same as #4 except with 55' berm @ el. 2015.5.	1.50
5	2 1/2 : 1/3 : 1	Full drawdown; 10' berm @ el. 2015.5; Arc cut from app. shoulder thru zoned emb & 35' into found.	1.43
5A	2 1/2 : 1/3 : 1	Same as #5 except with 10' berm @ el. 2015.5.	1.50

DOWNSTREAM SLOPE			
Trial	Slope	Conditions	Fs
NOTE:			
Sat. shear values on all trials			
Zoned emb:			
Core - 23.5° - 500			
Shell - 36° - 575			



Flood Plain Section
Station 19+50


SCS-277
(3/59)

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

RECOMMENDED USE OF EXCAVATED MATERIAL

- Formal Zoning Plan
- Selective Placement Plan

State VIRGINIA
Project UPPER NORTH RIVER "Z"
Date 6-5-62
By LPD



TYPICAL EMBANKMENT SECTION


Embankment Section	Description	Source of Fill Material		Ave. Depth		Lab. Sample No.	Lab Test		Compaction Requirements Class of Fill <u>62</u>		
		Location	From	To	Standard		Minimum Density	Moisture Range			
					Max. Den.			Optm. Moist.	Lbs. per Cu. Ft.	Percent From	To
1	Cut-off Trench & Core	Emer Spwy.	1	12	1097	111.0	17	3	105.0	16.0	19.0
"	"	"	1	12	1098	113.0	16.5	4	107.0	15.0	18.0
"	"	"	1	12	1099	105.5	19.5	5	100.5	18.0	21.5
"	"	"	1	12	1100	112.0	16.0	6	106.0	14.0	17.5
"	"	"	1	12	1101	113.5	15.0	7	108.0	14.0	17.0
"	"	Borrow Area	1	12	1103	109.5	17.0	9	104.0	16.0	19.0
"	"	"	1	12	1104	109.5	17.0	10	104.0	15.0	19.0
"	"	"	1	12	1105	115.6	14.5	11	109.0	13.0	16.0
"	"	"	1	12	1107	116.0	13.5	13	110.0	12.0	15.0
Densities Shown are For The		Minus No		4		Fraction					

SS-377
(3/59)

RECOMMENDED USE OF EXCAVATED MATERIAL
 Formal Zoning Plan Selective Placement Plan

U. S. DEPARTMENT OF AGRICULTURE
 SOIL CONSERVATION SERVICE

State VIRGINIA
 Project UPPER NORTH RIVER
 Date 6-7-62
 By L.P.D.



TYPICAL EMBANKMENT SECTION

Sec. No.	Embankment Section Description	Source of Fill Material Location		Ave. Depth		Lab. Sample No.	Lab Test			Compaction Requirements Class of Fill <u>LS-1</u>	
		From	To	From	To		Max. Den.	Optim. Moist.	Standard	Minimum Density	Moisture Range
2014	Transition or Upstream - Flood Plain & Terrace	1	7	1	7	62F	1235	12.0	19	123.5	
	" " " " " "	1	6	1	6	1114	1260	9.5	20	126.0	
3	Downstream - Outer Shell - Flood Plain	1	7	1	7	1109				111.5	
	" " " " " "	1	6	1	6	1110				111.5	
	" " " " " "	1	4	1	4	1112	1115	13.5	18	111.5	
4	Upstream shell Flood Plain	1	7	1	7	1111	1180	12.0	17	118.5	
	" " " " " "	1	7	1	7	1108	1170	13.0	13	117.0	
	" " " " " "	1	12	1	12	1102	1135	14.5	8	113.5	
	Densities shown are for the minus 4 Fraction										

R. C. Barnes, State Conservation Engineer,
SCS, Richmond, Virginia

August 22, 1962

Ray S. Decker, Head, Soil Mechanics Laboratory,
SCS, Lincoln, Nebraska

Virginia FPP - Upper North River, Site No. 76

We have reviewed placement recommendations for coarse materials on the subject site, as requested by telephone call from Mr. Oman.

Original shear tests on coarse material for this site were run on a composite of Samples 62F1108, 1111, 1113 and 1114 as representing flood plain material with the most fines.

Test densities for shear tests were based upon assumption that all material 6 inches and over would be raked from the mass of the fill to the outside shells. With this assumption, the composite would have about 47% larger than #4 with an average density on - #4 of 119 p.c.f.

The shear tests were run on material finer than 1 inch. The test specimens were re-graded in the sand and gravel size range as shown in the original report. There was 44 percent plus No. 4 material in the 4.0 inch diameter test specimens and 56 percent plus No. 4 material in the 6.0 inch shear specimens.

With the minus No. 4 material at 95% of Standard Proctor (113 p.c.f.), the corrected density with 44 percent gravel included in the sample would be 128 p.c.f. With the minus No. 4 material at 100% of Standard Proctor, the corrected density with 44 percent gravel in the sample would be 132 p.c.f.

The 6.0 inch diameter test specimens contained 56 percent gravel. Maximum Standard density, considering this percentage of gravel, would be 137 p.c.f.

The first shear tests were set up at about 127 p.c.f. which would represent about 95% of the Standard Proctor density for the gradation used. These specimens slumped before testing and it was deemed necessary to test at higher densities. The second and third tests were run at densities of 132 p.c.f. and 133.5 p.c.f. which would represent about 100% of Standard Proctor density for the gradation used.

Strength values used in the stability analyses were for $\gamma_d = 132$ p.c.f.

After reviewing the data on gradation of field samples which show that the above composite would have about 70% larger than No. 4 and about 30% larger

2 -- R. C. Barnes -- 8/22/62
Ray S. Decker
Subj: Virginia FFP - Upper North River, Site No. 76

than 6", we concur in the idea that removing all 6" and larger material would not be practical.

Since our report of June 8, 1962 on this site, we have had opportunity to review the Rutledge report on coarser material. Data in that report based upon U.S.B.R. tests on - 3" material show that material tested at 125 p.c.f. on the - 3" fraction gave ϕ values of 33° to 42°.

We have re-analyzed the designs proposed in our report of June 8 using upstream slopes of 3:1 for the outside shell and 3/4:1 for the interior core with berm at 2015.5 and embankment values of $\gamma_d = 125$ p.c.f., $\phi = 38^\circ$, $c = 0$. This analysis produced $f_s = 1.52$. (Trial circle 1C on the attached slope stability summary.)

Further review of the volumes of borrow material show that Samples 62F1111 and 1114 represent some 240,000 cubic yards. These materials show only 13% larger than 6" and 0% larger than 12".

We recommend modification of original report as follows:

1. Embankment design: Upstream slope = 3:1 outside; downstream slope = 2 1/2:1; center core 3/4:1; with berms as originally proposed.
2. Placement of material represented by 62F1111 and 1114 adjacent to core section with + 6" material raked to outside shell. This material should be placed at not less than 125 p.c.f. dry density of the - 3" fraction. Four or five passes with D-7 or equivalent track type tractor should effect this density but it is suggested that a few density tests be made to assure this weight. Assuming an average of 40% larger than 3", the required density of the - 6" fraction would be about 137 p.c.f.
3. Coarser material placed in the outside shells could be specified as Class C fill.

Attachment

Prepared by:

Ray S. Decker

and

Lorn P. Dunnigan

cc: H. M. Kautz - Upper Darby, Pa.

RSD: LFD: vmo

SUMMARY - SLOPE STABILITY ANALYSIS

State VIRGINIA Project UPPER NORTH RIVER SITE #76

Date 5-16-62 Analysis Made By GLM Checked By TCH

Method of Analysis SWEDISH CIRCLE


Location of Material	Found						Emb 95% Std		Emb 100% Std	
							SC			
Sample No.	Assumed						62F 1097		62F 1113, 1114	
r_d							113.0		125.0	
r_m							130.0		136.0	
r_s	146.0						133.0		140.0	
r_b							70.5		77.5	
Condition	Opt.	Sat.	Opt.	Sat.	Opt.	Sat.	Opt.	Sat.	Opt.	Sat.
ϕ		36°						23.5°		38.7°
Tan ϕ		0.727						0.435		0.800
K										
C		0						500		0

UPSTREAM SLOPE			
Trial	Slope	Conditions	Fs
1C	3:1	Full drawdown; 10' berm @ elev 2015.5' Arc cut from opp shoulder thru zoned emb only. - 3/4:1 slope on core. Sat shear values only.	1.52
Note:			
Zoned emb - Shell (38.7°-0)			
Core (23.5°-500)			

DOWNSTREAM SLOPE			
Trial	Slope	Conditions	Fs

MAXIMUM SECTION

STA 21+25



2070

2030

1970

APPENDIX V
DESIGN REPORT

DESIGN REPORT

UPPER NORTH RIVER WATERSHED
SITE NO. 76
AUGUSTA COUNTY, VIRGINIA

This multiple-purpose structure is located in Augusta County, Virginia, approximately 15 miles north-northwest of Staunton. The transparent overlay (sheet 4 of this report) together with the Parnassus quadrangle published by the U.S. Geological Survey, may be used to locate the structure.

This dam is a class (c) structure (Engineering Memorandum SCS-27) and is designed in accordance with SCS criteria.

It is an earthfill structure having a cutoff trench to firm bedrock. The embankment materials are placed in a manner to afford foundation and embankment drainage through a rock toe drain.

The purpose of this dam is to reduce downstream flooding by providing temporary storage for the runoff from 17,370 acres of watershed. This temporary storage is released gradually through the principal spillway. This structure impounds 616 acre-feet of water for the city of Staunton which has its present water supply reservoir about a mile downstream from this dam. The 55-acre reservoir created by the permanent pool will afford limited recreational facilities which will be managed by the U.S. Forest Service.

The principal spillway consists of twin 42-inch diameter reinforced concrete water pipes. Discharge into the conduits is provided by a 9.0' x 10.5' reinforced concrete riser. There are three heavy duty gates attached to this riser for dewatering the reservoir and to permit utilization of the municipal water supplies.

There is a large emergency spillway cut through the right abutment. The 4.85 inches of floodwater storage below the crest of the emergency spillway, plus flow through principal spillway, will contain the maximum runoff produced by a storm in excess of 100-year frequency.

The inflow hydrographs used in the design of this structure were developed by the method described in Chapter 3.21 of Section 4, Hydrology, National Engineering Handbook.

The flood routing procedure used in the design is given in Section 5, Hydraulics, of the National Engineering Handbook.

The following table gives the results of the hydrologic and hydraulic determinations:

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE
ENGINEERING & WATERSHED PLANNING UNIT
UPPER DARBY, PENNSYLVANIA

DRAWING NO.
VA-472-R

SHEET 1 OF 5

DATE 3/22/63

DESIGN REPORT

Factor Which Determines Stage	Surface Area Acres	Runoff in Inches	Peak Inflow c.f.s.	Peak Outflow c.f.s.	Elev. of Maximum Stage	Storage in Ac.-Ft.	Element of Structure Determined by Maximum Stage
50-year sediment accumulation	20 ¹	-	-	-	1978.0	168	Invert of riser dewatering gate
Water supply	55	-	-	-	2015.5	616	Crest of riser
100-year frequency storm moisture condition II	186	-	-	-	2060.5	5066	Below crest of emergency spillway
Greater than 100-yr. frequency storm moisture condition II ²	221	-	-	-	2070.0	7020	Crest of emergency spillway
1.0x9-hour point rainfall moisture condition II	227	7.65	15,659	6600	2074.7	8090	Design high water
2.50x9-hour point rainfall moisture condition II	274	24.17	46,370	45,000	2084.7 ³	10,500	Check top of dam

¹Borrow excavation in reservoir provides 248 acre-feet of storage.

²To reduce velocities in emergency spillway.

³Top of dam set at elevation 2084.00.

The time to empty the pool from the crest of the emergency spillway to the crest of the orifice is 6.10 days.

The geology report and Soil Mechanics Laboratory report were used to determine the adequacy of the design. Copies of these reports are attached.

The following publications were used in the design of this dam:

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE
 ENGINEERING & WATERSHED PLANNING UNIT
 UPPER DARBY, PENNSYLVANIA

DRAWING NO.
VA-472-R

SHEET 2 OF 5

DATE 3/22/63


DESIGN REPORT

NE Handbook No. 5, Hydraulics
NE Handbook No. 4, Hydrology
NE Handbook No. 6, Structural Design
Technical Releases Nos. 2, 5 and 10

Copies of these publications may be obtained from Mr. Tom F. McGourin,
State Conservationist, USDA, Soil Conservation Service, Richmond, Virginia.

Concurred:

Gerald E. Oman
Design Engineer


R. C. Barnes, Jr.
State Conservation Engineer

Vincent McKeever
Hydrologist

Robert F. Fonner
Geologist

REFERENCE:


U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE
ENGINEERING & WATERSHED PLANNING UNIT
UPPER DARBY, PENNSYLVANIA

DRAWING NO.

VA-472-R

SHEET 3 OF 5

DESIGN REPORT



REFERENCE:
FORM NO. D-200-10-1
WASHINGTON, D. C. 20250


U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE
ENGINEERING & WATERSHED PLANNING UNIT
UPPER DARBY, PENNSYLVANIA

DRAWING NO.

SHEET 4 OF 5

DESIGN REPORT

Summary Sheet



Typical X-Section

I. Watershed data

A. Structure class		(c)	
B. Drainage area		<u>17,370</u>	Ac.
C. Time of concentration - T _c		<u>8.6</u>	Mins.
D. Hydrologic curve number - C _c ⁿ			
1. Moisture condition II ⁿ		<u>71</u>	
2. Moisture condition III		<u>88</u>	

II. Principal spillway

A. Conduit			
1. Size (I.D.)		<u>twin 42-</u>	In.
2. Length		<u>625.3</u>	Ft.
B. Riser			
1. Size		<u>10.5x9.0</u>	Ft.
2. Height		<u>39.0</u>	Ft.
C. Weir length		<u>21.0</u>	Ft.
D. Orifice size		<u>-</u>	In.
E. Pond drain size		<u>36</u>	In.

III. Emergency spillway

A. Width		<u>215</u>	Ft.
B. Side slopes	variable 1.25 to 2.50		
C. Length of level section		<u>40</u>	Ft.
D. Exit slope		<u>0.04</u>	Ft./ft.
E. Maximum velocity at control section (D.H.W.)		<u>9.4</u>	Ft./Sec.
F. Duration of flow (D.H.W.) through emergency spillway		<u>16.4</u>	Mins.
G. Frequency of use	Less frequent than	<u>100</u>	year

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE
ENGINEERING & WATERSHED PLANNING UNIT
UPPER DARBY, PENNSYLVANIA

PROJECT NO.
VA-472-R

SHEET 5 OF 5

DATE: 3/22/63

APPENDIX VI - REFERENCES

1. Recommended Guidelines for Safety Inspection of Dams, Department of Army, Office of the Chief of Engineers, 46 pp.
2. Design of Small Dams, U. S. Department of Interior, Bureau of Reclamation, 1974, 816 pp.
3. Geology of the Stokesville and Parnassus Quadrangles, Virginia, Reports of Investigations No. 19, E.K. Rader, Virginia Division of Mineral Resources, 1969, 30 pp.
4. Section 4, Hydrology, Part 1, Watershed Planning, SCS National Engineering Handbook, Soil Conservation Service, U. S. Department of Agriculture, 1964.
5. Hydrometeorological Report No. 33, U. S. Department of Commerce, Weather Bureau, U. S. Department of Army, Corps of Engineers, Washington, D. C., April 1956.
6. Technical Paper No. 40, U. S. Department of Commerce, Weather Bureau, Washington, D. C., May 1961.