


AD-A074 715

NEW YORK STATE DEPT OF ENVIRONMENTAL CONSERVATION ALBANY F/G 13/2  
NATIONAL DAM SAFETY PROGRAM. LOCK 3 DAM AT MECHANICVILLE (INVEN--ETC(U)  
JUN 79 G KOCH DACW51-79-C-0001

UNCLASSIFIED

NL

| OF 2  
AD A074715




1 OF 2

AD  
A074715

A074715

DDC FILE COPY



REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report Lock 3 Dam at Mechanicville Upper Hudson River Basin Rensselaer-Saratoga Co. Inventory No. NY 215		5. TYPE OF REPORT & PERIOD COVERED Phase I Inspection Report National Dam Safety Program
7. AUTHOR(s) George Koch P.E.		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS New York State Department of Environmental- Conservation / 50 Wolf Road Albany, New York 12233		8. CONTRACT OR GRANT NUMBER(s) DACW-51-79-C-0001
11. CONTROLLING OFFICE NAME AND ADDRESS New York State Department of Environmental Con- servation/ 50 Wolf Road Albany, New York 12233		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (If different from Controlling Office) Department of the Army 26 Federal Plaza/ New York District, Coff New York, New York 10007		12. REPORT DATE 22 June 1979
		13. NUMBER OF PAGES
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; Distribution unlimited.		15. SECURITY CLASS. (of this report) UNCLASSIFIED
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
18. SUPPLEMENTARY NOTES National Dam Safety Program, Lock 3 Dam at Mechanicville (Inventory Number NY-215), Upper Hudson River Basin, Rensselaer-Saratoga County, New York. Phase I Inspection Report.		
19. KEY WORDS (including unclassified words if necessary and identify by block number) Dam Safety National Dam Safety Program Visual Inspection Hydrology, Structural Stability Lock 3 Dam at Mechanicville Hudson River Rensselaer County Saratoga County		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization. Lock 3 Dam at Mechanicville was found to have an inadequate spillway capacity, additional investigation to better determine the structural stability of the dam was also recommended.		

DA074715

DDG FILE COPY

4 nu

LEVEL

15

11

12 2467

DDC  
RECEIVED  
OCT 5 1979  
E

6

**UPPER HUDSON RIVER BASIN**

**LOCK 3 DAM AT MECHANICVILLE**  
**RENSSELAER - SARATOGA COUNTY**  
**NEW YORK**

**INVENTORY NO. N.Y. 215**

**PHASE I INSPECTION REPORT**  
**NATIONAL DAM SAFETY PROGRAM**



**APPROVED FOR PUBLIC RELEASE;**  
**DISTRIBUTION UNLIMITED**

---

**CONTRACT NO. DACW-51-79-C0001**

**NEW YORK DISTRICT CORPS OF ENGINEERS**

**FEBRUARY, 1979**

## **DISCLAIMER NOTICE**

**THIS DOCUMENT IS BEST QUALITY  
PRACTICABLE. THE COPY FURNISHED  
TO DDC CONTAINED A SIGNIFICANT  
NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.**

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probably Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

Accession For	
NTIS Grant	<input checked="" type="checkbox"/>
DDC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By _____	
Distribution/	
Availability Codes	
Dist	Avail and/or special
A	23 CP

PHASE 1 INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
LOCK 3 DAM @ MECHANICVILLE  
I.D. No. NY - 215  
(#119 - UH)  
UPPER HUDSON RIVER BASIN  
RENSSELAER - SARATOGA COUNTY, NEW YORK

TABLE OF CONTENTS

	<u>PAGE NO.</u>
- PREFACE	
- ASSESSMENT	
- OVERVIEW PHOTOGRAPH	
1 PROJECT INFORMATION	1
1.1 GENERAL	1
1.2 DESCRIPTION OF PROJECT	1
1.3 PERTINENT DATA	2
2 ENGINEERING DATA	4
2.1 DESIGN	4
2.2 CONSTRUCTION RECORDS	4
2.3 OPERATION RECORD	4
2.4 EVALUATION OF DATA	4
3 VISUAL INSPECTION	5
3.1 FINDINGS	5
3.2 EVALUATION OF OBSERVATIONS	6
4 OPERATION AND MAINTENANCE PROCEDURES	7
4.1 PROCEDURE	7
4.2 MAINTENANCE OF DAM	7
4.3 MAINTENANCE OF APPURTENANT STRUCTURES	7
4.4 WARNING SYSTEM IN EFFECT	7
4.5 EVALUATION	7

	<u>PAGE NO.</u>	
5	HYDROLOGIC/HYDRAULIC	8
5.1	DRAINAGE AREA CHARACTERISTICS	8
5.2	ANALYSIS CRITERIA	8
5.3	SPELLWAY CAPACITY	8
5.4	RESERVOIR CAPACITY	9
5.5	FLOODS OF RECORD	9
5.6	OVERTOPPING POTENTIAL	9
5.7	EVALUATION	9
6	STRUCTURAL STABILITY	10
6.1	EVALUATION OF STRUCTURAL STABILITY	10
7	ASSESSMENT/RECOMMENDATIONS	12
7.1	ASSESSMENT	12
7.2	RECOMMENDED MEASURES	13

APPENDIX

- A. PHOTOGRAPHS
- B. ENGINEERING DATA CHECKLIST
- C. VISUAL INSPECTION CHECKLIST
- D. HYDROLOGIC/HYDRAULIC ENGINEERING DATA AND COMPUTATIONS
- E. STRUCTURAL STABILITY ANALYSES
- F. REFERENCES
- G. CORPS OF ENGINEER GUIDELINES
- H. DRAWINGS

PHASE 1 REPORT  
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Lock 3 Dam @ Mechanicville  
I.D. No. NY-215  
(#119-UH)

State Located: New York

County Located: Rensselaer - Saratoga

Watershed: Upper Hudson River Basin

Stream: Hudson River

Date of Inspection: October 26, 1978

ASSESSMENT

Examination of available documents and a visual inspection of the dam did not reveal conditions which constitute an immediate hazard to human life or property. However, additional studies should be undertaken to further evaluate conditions affecting the dam.

Additional data and analysis is needed to ascertain the condition and stability of the wrought-iron framework supporting the apron slabs. Also, a more detailed structural stability analysis of the dam using the site-specific foundation material characteristics is also recommended. Such analyses should be performed in accordance with the Corps of Engineers Guidelines, Chapter 4, paragraph 4.4, included in Appendix G.

All additional data gathering, investigations, and analyses should be completed within one year of the date of this Phase 1 report. During the interim period, a detailed emergency-operation plan and warning system should be developed and implemented.

The spillway, not having sufficient discharge capacity for passing one-half the Probable Maximum Flood (PMF), is considered to be inadequate. For such a large storm event, a high tailwater condition would most likely occur resulting in the flooding of the downstream hazard areas. Hence, dam failure from overtopping would not significantly increase the hazard to loss of life downstream from that which would exist just before overtopping failure.

Minor deficiencies found during the visual inspection were limited to concrete surface deterioration and cracking and the overgrowth of vegetation on the earth dike. Such deficiencies should be corrected during normal maintenance operations before the next period of anticipated high river flows (Spring 1980).

*George Koch*

George Koch  
Chief, Dam Safety Section  
New York State Department of  
Environmental Conservation  
NY License No. 45937

Approved By:

*Clark H. Benn*

Col. Clark H. Benn  
New York District Engineer

Date:

*22 June 79*



LOCK 3 DAM @ MECHANICVILLE  
(Looking West)



LOCK 3 DAM @ MECHANICVILLE  
(Looking East)

PHASE 1 INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
LOCK 3 DAM @ MECHANICVILLE  
I.D. No. NY - 215  
(#119 - UH)  
UPPER HUDSON RIVER BASIN  
RENSSELAER - SARATOGA COUNTY, NEW YORK

SECTION 1: PROJECT INFORMATION

1.1 GENERAL

a. Authority

The Phase 1 Inspection reported herein was authorized by the Department of the Army, New York District, Corps of Engineers, to fulfill the requirements of the National Dam Inspection Act, Public Law 92-367.

b. Purpose of Inspection

This inspection was conducted to evaluate the existing conditions of the dam, to identify deficiencies and hazardous conditions, determine if they constitute hazards to life and property, and recommend remedial measures where necessary.

1.2 DESCRIPTION OF PROJECT

a. Description of the Dam and Appurtenant Structures

The Lock 3 Dam at Mechanicville is a masonry gravity dam having a reinforced concrete cap and a downstream precast concrete slab apron supported by a wrought iron framework. The masonry overflow section is 700 feet long and 19 feet high. In addition to the masonry "main dam" portion, easterly extensions include the 98 foot wide navigation Lock 3 and a 520 foot long concrete faced earth dike. Extending westerly is a 135 foot wide gatehouse-forebay structure containing 12 gates leading to the West Virginia Pulp and Paper Company manufacturing plant water supply channel.

b. Location

The dam is located on the Hudson River, northeast of the City of Mechanicville and east of State Routes 4, 32, and 67.

c. Size Classification

This dam is 37 feet high and impounds a reservoir of 3420 acre-feet. It is classified as an "intermediate" size dam (storage capacity between 1000 and 50,000 acre-feet).

d. Hazard Classification

The dam is classified "high" hazard because of the immediate downstream populations located at Hemstreet Park in the Town of Schaghticoke and the City of Mechanicville.

e. Ownership

The Lock 3 Dam is owned by the State of New York - Department of Transportation (NYS-DOT), Waterways Maintenance Subdivision. It is located in DOT-Region 1, whose headquarters are in Albany, New York.

The original dam constructor/owner was the Hudson River Water-Power and Paper Company (HRW-PPC). The West Virginia Pulp and Paper Company (WVPPC), successor in title to the dam from HRW-PPC, transferred ownership to New York State in January 1922. In February 1979, the property of the Saratoga Board Mills Corporation, successor in title to the gatehouse-forebay structure from WVPPC, was obtained in a foreclosure sale by the City National Bank of Detroit, Michigan, one of the principal lienholders against the Mechanicville property. More recent developments regarding the gatehouse-forebay structure ownership is contained in a newspaper article included in Appendix D.

Waterways Maintenance Subdivision:

New York State - DOT  
Main Office - State Campus  
1220 Washington Avenue  
Albany, New York 12232

Director - Mr. Joseph Stellato  
(AC - 518) 457-4420

Region One:

New York State - DOT  
84 Holland Avenue  
Albany, New York 12208

Waterways Maintenance:  
Engineer - Mr. John Hulchanski  
(AC 518) 474-6715

f. Purpose of Dam

The primary purpose is for navigation through Lock 3 of the Champlain Barge Canal. The impounded waters of the Hudson River provide a storage pool used for gravity inflow to Lock 3. Supplementary purposes include flood control and possible hydroelectric generation from the presently non-operational power station located on the westerly side of the river.

g. Design and Construction History

The original dam at this site was constructed by the Hudson River Water-Power and Paper Company about the year 1882. In 1912, it existed as a masonry dam with a timber downstream apron supported by an iron-steel framework. The dam was reconstructed to its present reinforced concrete crest cap and precast concrete slab apron in 1965.

h. Normal Operational Procedures

Water flows unregulated over the "main dam" spillway. Flow diversions from the storage pool occur by gravity through the intakes of the Lock during boat passage and minimally through the forebay gates.

1.3

PERTINENT DATA

a. Drainage Area

(square miles) 4500

b. Discharges at Dam

(cfs)

Top of Dam (Top of Earth Dike)	122,100
Top of Lock 3 (River-side Abutment)	77,600
Hydroelectric power station existing machinery (12 units)	
Design:	6,043 (max.)
Operating:	5,893

<u>c. Elevations</u> (Barge Canal Datum - BCD)	
Top of Dam (Top of Earth Dike)	83.0
Top of Lock 3 (River-side Abutment)	77.0
Spillway Crest	67.5
Maximum Tailwater (March 19, 1936)	60.70
Minimum Tailwater (March 7, 1944)	46.55
Reservoir Pool (USGS Datum)	66.0
(USGS Mechanicville, N 7.5' Quad. - 1954)	

Datum Conversion:

USGS 0.0 equals BCD 1.18

<u>d. Reservoir</u>	Surface Area (acres)
Top of Dam (Top of Earth Dike) Max. Pool	350
Top of Lock 3 - Maximum Normal Pool	350
Spillway Crest - Normal Pool	260

<u>e. Storage Capacity</u>	(acre-feet)
Top of Dam (Top of Earth Dike)	8785
Top of Lock 3	6685
Spillway Crest	3420

f. Dam

Type: Masonry, with a reinforced concrete cap and a precast concrete slab apron.

	(feet)
Length: Spillway Crest	700
Lock 3	98
Earth Dike (embankment)	520
Gatehouse - Forebay	135

Height:	(feet)
Structural	37

Width @ Crest:	(feet)
Spillway (radius)	2.3
Earth Dike @ Abutment	39
Normal	60

Slopes:	(V : H)
Spillway - upstream face	1:2
- downstream apron	1:1.75
Earth Dike - upstream face	1:1
- downstream face	1:1

g. Spillway

Type: Uncontrolled, gravity masonry structure with a rounded reinforced concrete cap and a precast concrete slab apron.

Weir Length (feet)	700
Crest Elevation (Barge Canal Datum)	67.5

h. Reservoir Drain

None

## SECTION 2: ENGINEERING DATA

### 2.1 DESIGN

#### a. Geology

The Lock 3 Dam is located in the Hudson Valley Lowlands physiographic province of New York State. Rock in this area was formed during the Ordovician period. The rock in these areas is predominantly limestone and dolostone. The present surficial soils have resulted primarily from glaciations during the Cenozoic Era; the Wisconsin glaciation being the most recent event to affect this area, having occurred approximately 11,000 years ago.

#### b. Subsurface Investigations

No records of subsurface investigations were available. Based on the plans which were available for this structure, it appears that the structure is founded on bedrock.

#### c. Dam and Appurtenant Structures

Records indicate that the dam was constructed about the year 1882. No information was available concerning the original design of the dam. The dam has been reconstructed several times since first constructed. Drawings for the latest reconstruction performed under DOT Contract M65-6 in 1965, are included in Appendix H.

### 2.2 CONSTRUCTION RECORDS

No records were available for the original dam construction. The only records available were from the 1965 reconstruction.

### 2.3 OPERATION RECORD

The dam is visually inspected on an irregular basis by engineers from NYS-DOT. Mean daily water levels are recorded at locations both upstream and downstream of the lock. These records began in 1917 and are on file at the N.Y.S. DOT Region One, Waterways Office.

### 2.4 EVALUATION OF DATA

The data presented in this report was obtained from the files of the Department of Environmental Conservation, the New York State Department of Transportation, the New York State Electric and Gas Corporation and the Federal Energy Regulatory Commission. The information available appears to be adequate and reliable for Phase I inspection purposes.

## SECTION 1: VISUAL INSPECTION

### 3.1 FINDINGS

#### a. General

Visual inspection of the Lock 3 Dam at Mechanicville and the surrounding area was conducted on October 16, 1978. The weather was cloudy and overcast with the temperature near 50° F. Depth of flow over the spillway crest was approximately 1.65 feet.

#### b. Dam - Spillway

The "main portion" of the dam, the spillway, could not be observed because of submergence. However, the vertical and horizontal alignment of the crest appeared to be satisfactory.

The following deficiencies were observed:

1. Concrete spalling on the river-side face of the lock upstream protection pier.
2. Smaller areas of spalled concrete on the outer lock walls both upstream and downstream of the crest, in the zone of flow aeration.
3. At the spillway-gatehouse contact, seepage through one masonry block horizontal joint immediately adjacent to the crest was observed.

#### c. Appurtenant Structures

The navigation Lock 3 was in satisfactory condition. The functioning of the 12 forebay gates could not be ascertained although some flow was occurring downstream of the gatehouse.

The following deficiencies were observed:

1. The concrete surfacing on the Lock-earth dike masonry abutment was deteriorated considerably; having aggregate exposed and surface corners well-rounded from weathering.

#### Earth Dike-Embankment:

2. The concrete facing on the dike embankment's upstream slope protection was cracked.
3. The vertical alignment of the crest was somewhat irregular sloping downward in the upstream direction; a vehicle path existed on the top of the dike.
4. Several large trees existed on the top of the embankment.
5. Small trees and brush existed on the downstream slope of the embankment.

## SECTION 3: VISUAL INSPECTION

### 3.1 FINDINGS

#### a. General

Visual inspection of the Lock 3 Dam at Mechanicville and the surrounding area was conducted on October 26, 1978. The weather was cloudy and overcast with the temperature near 50° F. Depth of flow over the spillway crest was approximately 1.65 feet.

#### b. Dam - Spillway

The "main portion" of the dam, the spillway, could not be observed because of submergence. However, the vertical and horizontal alignment of the crest appeared to be satisfactory.

The following deficiencies were observed:

1. Concrete spalling on the river-side face of the lock upstream protection pier.
2. Smaller areas of spalled concrete on the outer lock walls both upstream and downstream of the crest, in the zone of flow aeration.
3. At the spillway-gatehouse contact, seepage through one masonry block horizontal joint immediately adjacent to the crest was observed.

#### c. Appurtenant Structures

The navigation Lock 3 was in satisfactory condition. The functioning of the 12 forebay gates could not be ascertained although some flow was occurring downstream of the gatehouse.

The following deficiencies were observed:

1. The concrete surfacing on the Lock-earth dike masonry abutment was deteriorated considerably; having aggregate exposed and surface corners well-rounded from weathering.

Earth Dike-Embankment:

2. The concrete facing on the dike embankment's upstream slope protection was cracked.
3. The vertical alignment of the crest was somewhat irregular sloping downward in the upstream direction; a vehicle path existed on the top of the dike.
4. Several large trees existed on the top of the embankment.
5. Small trees and brush existed on the downstream slope of the embankment.

Forebay:

6. Seepage through the east wall was occurring in three areas which were all in excess of 200 feet downstream of the axis of the dam.
7. Cracked concrete and joint separation in the masonry was evident along much of the east wall.

d. Reservoir

A low area exists along the edge of the river due east of the north end of the upstream protection pier, the apparent result of an excavation made to allow vehicle access to the river edge.

There was no noticeable signs of soil instability in the reservoir area.

e. Downstream Channel

No unusual conditions were noticed in the downstream Hudson River channel.

3.2

EVALUATION OF OBSERVATIONS

Visual observations did not reveal any problems which would affect the immediate safety of the dam. The deficiencies observed can be corrected during normal maintenance operations. The functioning of the forebay gates is an uncertainty requiring further investigation.

## SECTION 4: OPERATION AND MAINTENANCE PROCEDURES

### 4.1 PROCEDURE

Normal surface is at or slightly above the uncontrolled spillway crest. Flow diversions occur through the navigation Lock and to a lesser extent, through the forebay gates. Presently, the forebay diversion is minimal since neither the paper mill nor the hydroelectric machinery is operating.

### 4.2 MAINTENANCE OF DAM

Maintenance of the spillway portion of the dam is minimal because of continuous submergence of the crest. During the 1965 reconstruction work, inspection of the iron and steel apron support framework revealed no major structural deterioration.

### 4.3 MAINTENANCE OF APPURTENANT STRUCTURES

Maintenance of Lock 3 is satisfactory. However, the earth dike has not been maintained as evidenced by trees and brush growing on the downstream slope. The concrete slope protection facing also requires some remedial work to prevent further deterioration.

Maintenance work conducted in the gatehouse-forebay area is unknown. However, since the paper mill has been substantially inoperative for several years, maintenance has probably been minimal.

### 4.4 WARNING SYSTEM IN EFFECT

No apparent warning system is present.

### 4.5 EVALUATION

Operation and maintenance of the Lock is satisfactory. Additional maintenance is needed to remedy the earth dike deficiencies stated above. In addition, all masonry and concrete structures including the gatehouse-forebay should be repaired as necessary.

## SECTION 5: HYDROLOGIC/HYDRAULIC

### 5.1 DRAINAGE AREA CHARACTERISTICS

The delineation of the contributing watershed to this dam is shown on the map titled "Drainage Area - Lock 3 @ Mechanicville" (Appendix D). With the drainage area encompassing some 4500 square miles including portions of Vermont and Massachusetts, the Hudson River main stem travels approximately 140 miles from its headwaters south of Lake Placid to the Lock 3 Dam. Major tributaries to the Hudson River are the Cedar, Indian, Boreas, Schroon, Sacandaga, and Hoosic Rivers and the Batten Kill. Numerous lakes including Brant, Schroon, Piseco and Saratoga lie within the basin as well as three major reservoirs; Indian Lake, the Tomhannock, and the Sacandaga Reservoir. Approximately one-half to two-thirds of the basin lies within the Adirondack Mountain area where elevations rise to +5344 at Mount Marcy. Elevations at the east abutment of the dam are near +70. Developed land use has occurred in the lower portion of the basin; the larger developments being the municipalities of Warrensburg, Glens Falls, Hudson Falls, Saratoga Springs; Arlington, Vermont; Greenwich, Schuylerville, Cambridge; Bennington, Vermont; Adams, North Adams, and Williamstown, Massachusetts; and Hoosick Falls.

### 5.2 ANALYSIS CRITERIA

No hydrologic/hydraulic information was available regarding the original design for this dam. Therefore, the analysis of the spillway capacity of the dam was performed using streamflow gaging station records (Appendix D) and data contained in a Corps of Engineer report entitled "Upper Hudson and Mohawk River Basins Hydrologic Flood Routing Models". The methodology described in this report employed the Corps of Engineers HEC-1 computer program in developing a model that correlated well with past known major storm events; i.e., the storms of October, 1945, December, 1948 and June, 1972. No direct computer analysis using HEC-1 was performed. The spillway design flood selected for analysis was the PMF in accordance with recommended guidelines of the U.S. Army Corps of Engineers.

### 5.3 SPILLWAY CAPACITY

The single, masonry and concrete, overflow spillway acts as the dam in forming the reservoir pool for the navigation Lock. The 700 foot long ungated spillway has a rounded reinforced concrete cap and a sloping, precast concrete slab apron on the downstream face.

For computed discharges, a discharge coefficient C, of 3.8 was used, determined from the gage readings of March 28, 1913. Computed discharges are as follows:

<u>STAGE</u>	<u>DISCHARGE (cfs)</u>
Top of Dam (Top of Earth Dike)	122,170
Top of Lock 3 (River-side Abutment)	77,670

Maximum discharges through the hydroelectric power station existing machinery (12 units) was determined to be 6,043 cfs.

The spillway does not have sufficient capacity for discharging the peak outflow from one-half the PMF. For this storm event, the peak inflow and peak outflow is 191,000 cfs, whereas the PMF peak discharge is 382,000 cfs. However, the dam has conveyed a maximum discharge of 120,000 cfs. The computed peak discharge capacity is 122,170 cfs.

5.4 RESERVOIR CAPACITY

The normal water surface is at or slightly above the spillway crest. Storage capacity for that crest elevation is 3420 acre-feet. Surchage storage capacity to the Top-of-Lock elevation is 3265 acre-feet. The total storage capacity to the Top-of-Dike elevation is 8785 acre-feet. The upstream limits of the reservoir are the Lock 4 gates, the low dam across the river approximately 700 feet south of the State Route 67 bridge, and the lower reaches of the Hoosic River.

5.5 FLOODS OF RECORD

The maximum known discharge occurred on March 28, 1913 when a flow of 120,000 cfs was recorded. The computed water surface elevation for this flow is 82.8 (BCD) (81.62 - USGS) or a flow depth to within 5 inches of the top of the earth dike.

5.6 OVERTOPPING POTENTIAL

Analysis indicates the spillway does not have sufficient discharge capacity for either the PMF or one-half the PMF. The computed depths of overtopping are 13.9 feet and 5.7 feet respectively. All storms exceeding approximately 32% of the PMF would result in overtopping of the earth dike.

5.7 EVALUATION

The spillway capacity is inadequate for the peak outflow from one-half the PMF. For such large storm events, a high tailwater condition would most likely occur resulting in the flooding of the downstream hazard areas. Hence, the spillway capacity is not considered to be seriously inadequate since dam failure from overtopping (at elevation of the top of earth dike) would not significantly increase the hazard to loss of life downstream from that which would exist just before overtopping failure.

## SECTION 6: STRUCTURAL STABILITY

### 6.1 EVALUATION OF STRUCTURAL STABILITY

#### a. Visual Observations

No direct visual observation of the spillway crest was possible because of submergence. However, no significant irregularities in the water surface profile along the axis of the crest were observed. There were no indications of instability at the navigation Lock, along the earth dike, or along the riverside forebay wall.

#### b. Design and Construction Data

Design computations or other data for the structural stability of the original dam or as it existed in 1912 were not available.

#### c. Data Review and Stability Evaluation

The NYS-DOT plans (included in Appendix H) show a cross-section of the spillway portion of the dam, both prior to 1965 and the reconstructed portion as it presently exists. A stability analysis was performed using the cross-section information shown plus certain simplifying assumptions made in the analysis. The resistances offered by the toe and the apron sections were calculated and converted to an equivalent passive resistance acting on the downstream face of the spillway masonry section.

Conditions analyzed were:

- 1) Normal conditions with the water level at the spillway crest elevation.
- 2) Conditions as in 1) plus a 5000 lb/ft ice load.
- 3) Water level at the elevation of the maximum known flood (82.8 - BCD); a flow depth of 15.3 feet.
- 4) Water level at the elevation of one-half PMF (88.7 - BCD); a flow depth of 21.2 feet.

The safety factors for overturning and sliding obtained from the analyses are:

<u>CONDITION</u>	<u>FACTORS OF SAFETY</u>	
	<u>OVERTURNING</u>	<u>SLIDING</u>
1) Normal water level	2.11	2.19
2) Ice load plus 1)	1.45	1.57
3) Maximum known flood	1.01	1.03
4) One-half PMF	0.92	0.88

The analyses indicate less than desirable factors of safety for normal water level conditions and a critical deficiency for the occurrence of a large storm event. The PMF storm event (flow depth of 29.4 feet) was not analyzed because of the results obtained during the one-half PMF analysis. The dam did withstand the 1913 storm event flows although the safety factors from the analysis are approximately equal to 1.00. Hence, the analysis is suspect due to the lack of more detailed information necessary to perform a complete in-depth study.

The condition of and the manner in which the wrought-iron framework is connected to the foundation could not be determined. Therefore, a structural analysis of the framework was not done.

d. Post-Construction Changes

The spillway apron portion of the dam was reconstructed in 1965 from a timber plank surface to one of precast reinforced concrete slabs. In addition, the spillway crest was replaced with a broader and thicker reinforced concrete cap. Detailed plans for this work are included in Appendix H.

e. Seismic Stability

This dam is located in seismic Zone 1. A seismic stability analysis is not warranted.

## SECTION 7: ASSESSMENT/RECOMMENDATIONS

### 7.1 ASSESSMENT

#### a. Safety

The Phase 1 inspection of the Lock 3 Dam did not reveal conditions which constitute an immediate hazard to human life or property. The spillway, navigation Lock 3, earth dike, and gatehouse-forebay are not considered to be unstable.

The spillway, not having sufficient discharge capacity for passing one-half the PMF, is considered to be inadequate. During periods of unusually heavy precipitation, continuous surveillance should be provided both at the dam and in the downstream areas to warn of hazardous flooding conditions. Such surveillance procedures and other measures should be documented in a detailed emergency-operation plan for the dam. Also, a warning system should be developed and placed in readiness for future use.

#### b. Adequacy of Information

The information available appears to be adequate for the Phase 1 inspection purposes except for the following:

- 1) The physical condition of the wrought-iron framework supporting the apron slabs and the concrete surfaces of both the crest and apron.
- 2) The physical condition and operational status of the forebay gates.

#### c. Urgency

Those deficiencies within the zone of water level fluctuations (below elevation 77.0 - BCD) should be corrected prior to the next period of anticipated high flows (Spring 1980). All other deficiencies observed during the visual inspection can be corrected during normal maintenance operations.

#### d. Necessity for Additional Investigations

Further structural analysis of the wrought-iron framework and a more detailed structural stability analysis of the dam to include the foundation materials' characteristics is recommended.

Additional investigations are also warranted to determine the following:

- 1) The physical condition of the wrought-iron framework supporting the apron slabs and the concrete surfaces of both the crest and apron.
- 2) The actual method of anchorage between the wrought-iron framework and the underlying foundation.
- 3) The physical condition and operational status of the forebay gates.

7.2

RECOMMENDED MEASURES

The following actions should be undertaken:

- a) Rehabilitate all deteriorated and cracked concrete surfaces.
- b) Remove the trees and brush from the earth dike embankment.
- c) Regrade the top of the earth dike to provide a level embankment crest.
- d) Perform periodic maintenance of the dam and all appurtenant structures.
- e) Develop and implement a detailed emergency-operation plan and warning system.
- f) As a result of the completed additional investigations, remedial measures deemed necessary should be completed within two years of the date of this report.

APPENDIX A

PHOTOGRAPHS



UPSTREAM APPROACH TO LOCK 3



CONCRETE SURFACE DETERIORATION @  
LOCK - SPILLWAY CONTACT



CONCRETE DETERIORATION @ ABUTMENT  
OF EARTH DIKE - LOCK 3



(UPSTREAM)

EARTH DIKE

(DOWNSTREAM)




UPSTREAM SLOPE PROTECTION ON EARTH DIKE



GATEHOUSE - FOREBAY  
(LOOKING UPSTREAM)



OUTER FOREBAY WALL  
(GATEHOUSE - BACKGROUND CENTER)



SLUICE GATE - FOREBAY WALL

APPENDIX B

ENGINEERING DATA CHECKLIST

Check List  
Engineering Data  
Design Construction Operation

Name of Dam LOCK 3 @  
MECHANICVILLE  
I.D. # NY-215  
(#119-UH)

Item	Remarks		
	Plans	Details	Typical Sections
Dam	YES		YES
Spillway(s)	YES		YES
Outlet(s)			
Design Reports			N/A
Design Computations			N/A
Discharge Rating Curves			N/A
Dam Stability			N/A
Seepage Studies			N/A
Subsurface and Materials Investigations			N/A

Item

Remarks

Construction History

LIMITED (1913 & 1916 DAM REPORTS)

Surveys, Modifications,  
Post-Construction Engineering  
Studies and Reports

NA

Accidents or Failure of Dam  
Description, Reports

NONE

Operation and Maintenance Records  
Operation Manual

MEAN ~~DAILY~~ WATER LEVEL RECORDS @ LOCK 3 (NYS-DOT)  
GAGE  
USGS GAGE (RECORDS 10/1887 TO 9/1956)

APPENDIX C

VISUAL INSPECTION CHECKLIST

VISUAL INSPECTION CHECKLIST

1) Basic Data

a. General

Name of Dam LOCK 3 @ MECHANICVILLE

I.D. # NY-215 (#119-UPPER HUDSON)

Location: Town SCHAGHTICOKE ~~STILLWATER~~ County RENSSELAER ~~SARATOGA~~

Stream Name HUDSON RIVER

Tributary of N/A

Longitude (W), Latitude (N) 73°-40'-42" W 42°-54'-42" N

Hazard Category C

Date(s) of Inspection 10/26/78

Weather Conditions ±50°F OVERCAST; RAIN

b. Inspection Personnel J. HUNTINGTON (NYS DOT REGION ONE - WATERWAYS)  
R. WARRENDER W. LYNICK

c. Persons Contacted NYS DOT [WATERWAYS SUBDIV. - MAIN OFFICE & REGION]  
MR. A. B. CARLSON (SARATOGA BOARD MILLS CORP.)

d. History:

Date Constructed [ORIGINALLY - 1882±] 1965

Owner NYS-DOT WATERWAYS MAINT. SUBDIVISION (ONLY TO WEST END OF THE)  
(OWNERSHIP ON 1/18/1932) (SPILLWAY CREST)

Designer NA

Constructed by [ORIGINALLY - HUDSON RIVER WATER-POWER & PAPER COMPANY] ← WEST VIRGINIA PULP & PAPER CO. (SUCCESSOR IN TITLE TO)

2) Technical Data

Type of Dam MASONRY GRAVITY DAM w/ CONC. APRON (IN 1912 - MASONRY w/ TIMBER APRON)

Drainage Area 4500 SQ MILES

Height 37' Length 700' (+)

Upstream Slope 1V: 2H Downstream Slope NA  
EARTH BACKFILL PRECAST CONCRETE SLABS SUPPORTED BY A WROUGHT IRON FRAMEWORK

2) Technical Data (Cont'd.)

External Drains: on Downstream Face N/A @ Downstream Toe N/A

Internal Components:

Impervious Core NONE

Drains NONE

Cutoff Type N/A

Grout Curtain NONE

3) Embankment

EARTH DIKE - EAST OF LOCK 3

a. Crest

(1) Vertical Alignment SATISFACTORY ; SLIGHT DOWNSLOPE FROM THE CENTER OF DIKE TOWARD THE UPSTREAM FACE

(2) Horizontal Alignment SATISFACTORY

(3) Surface Cracks NONE

(4) Miscellaneous \_\_\_\_\_

b. Slopes

(1) Undesirable Growth or Debris, Animal Burrows BRUSH & SEVERAL LARGE TREES (>6" DIAM) ON DOWNSTREAM SLOPE

(2) Sloughing, Subsidence or Depressions NONE

(3) Slope Protection CONCRETE FACED - UPSTREAM SLOPE

(4) Surface Cracks or Movement at Toe NONE

(5) Seepage NONE

(6) Condition Around Outlet Structure N/A

EARTH DIKE - EAST OF LOCK 3

c. Abutments

\_\_\_\_\_  
\_\_\_\_\_

(1) Erosion at Embankment and Abutment Contact NONE

(2) Seepage along Contact of Embankment and Abutment NONE

(3) Seepage at toe or along downstream face NONE

d. Downstream Area - below embankment

\_\_\_\_\_  
\_\_\_\_\_

(1) Subsidence, Depressions, etc. NONE

(2) Seepage, unusual growth SOME BRUSH & WEEDS

(3) Evidence of surface movement beyond embankment toe NONE

(4) Miscellaneous \_\_\_\_\_

e. Drainage System

N/A  
\_\_\_\_\_  
\_\_\_\_\_

4) Instrumentation

(1) Monumentation/Surveys WATER SURFACE STAFF GAGES BOTH ABOVE AND BELOW THE NAVIGATION LOCK

(2) Observation Wells NONE

(3) Weirs NONE

(4) Piezometers NONE

(5) Other \_\_\_\_\_

5) Reservoir

a. Slopes N/A HUDSON RIVER SHORELINE

b. Sedimentation N/A

6) Spillway(s) (including tail race channel)

SUBMERGED @ TIME OF INSPECTION

a. General

b. Principle Spillway A SMOOTH WATER SURFACE PROFILE ALONG THE AXIS OF THE SPILLWAY CREST INDICATES HORIZ & VERT. ALIGNMENT IS SATISFACTORY

c. Emergency or Auxiliary Spillway NONE

d. Condition of <sup>DOWNSTREAM</sup> Tail race channel - HUDSON RIVER SATISFACTORY

e. Stability of Channel side/slopes N/A

7) Downstream Channel

HUDSON RIVER

a. Condition (debris, etc.) ✓ SATISFACTORY

b. Slopes N/A

c. Approximate number of homes 100(+) HEMSTREET PARK IN TOWN  
OF SCHAGHTICOKE & CITY OF MECHANICVILLE

8) Miscellaneous

9) Structural

a. Concrete Surfaces SPALLED AREAS @ RIVER-SIDE OF LOCK UPSTREAM  
PROTECTION PIER, ON OUTER SURFACES OF LOCK WALLS IN THE ZONE  
OF AERATION (DEPTH < 3") EARTH DIKE - LOCK ABUTMENT  
SIGNIFICANT CONCRETE DETERIORATION

b. Structural Cracking NONE APPARENT

c. Movement - Horizontal & Vertical Alignment (Settlement) NONE

<sup>SPILLWAY</sup>  
d. <sup>A</sup> Junctions with Abutments or Embankments \_\_\_\_\_

EAST - SATISFACTORY

WEST - SATISFACTORY

e. Drains - Foundation, Joint, Face N/A

f. Water passages, conduits, sluices \_\_\_\_\_

PAPER MILL - FOREBAY: MASONRY; JOINTS (CRACKING & SOME SEPARATION)

g. Seepage or Leakage EAST - NONE

WEST - SEEPAGE @ ONE HORIZ. JOINT IN STONE BLOCK @ GATEHOUSE-CREST CONTACT

LEAKAGE THROUGH OUTER FOREBAY WALL IN 3 AREAS @

PLACES 200' (+) BELOW CREST OF DAM

- h. Joints - Construction, etc. N/A  
\_\_\_\_\_  
\_\_\_\_\_
- i. Foundation APPEARS TO BE ON ROCK (EVIDENT WHEN LOCK WAS  
DEWATERED; ROCK VISIBLE BENEATH UPSTREAM DOORS WHICH ARE  
IN SAME LOCATION AS AXIS OF CREST)  
\_\_\_\_\_  
\_\_\_\_\_
- j. Abutments N/A  
\_\_\_\_\_  
\_\_\_\_\_
- k. Control Gates NONE  
\_\_\_\_\_  
\_\_\_\_\_
- l. Approach & Outlet Channels N/A  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- m. Energy Dissipators (plunge pool, etc.) NONE  
\_\_\_\_\_  
\_\_\_\_\_
- n. Intake Structures NONE  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- o. Stability N/A  
\_\_\_\_\_  
\_\_\_\_\_
- p. Miscellaneous \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

APPENDIX D  
HYDROLOGIC/HYDRAULIC  
ENGINEERING DATA AND COMPUTATIONS

LOCK 3 DAM @  
MECHANICVILLE

1

CHECK LIST FOR DAMS  
HYDROLOGIC AND HYDRAULIC  
ENGINEERING DATA

AREA-CAPACITY DATA:

	BARGE CANAL DATUM - BCD		
	<u>Elevation</u> (ft.)	<u>Surface Area</u> (acres)	<u>Storage Capacity</u> (acre-ft.)
1) Top of Dam	<u>83.0</u>	<u>350</u>	<u>8785</u>
2) Design High Water (Max. Design Pool)	<u>NA</u>	<u>          </u>	<u>          </u>
3) <del>Auxiliary Spillway</del> Crest TOP OF LOCK	<u><del>83.0</del> 77.0</u>	<u>350</u>	<u>6685</u>
4) Pool Level with Flashboards	<u>NA</u>	<u>          </u>	<u>          </u>
5) Service Spillway Crest	<u>67.5</u>	<u>260</u>	<u>3420</u>

DISCHARGES

	<u>Volume</u> (cfs)
1) Average Daily	<u>NA</u>
2) Spillway @ <del>Maximum High Water</del> TOP OF LOCK	<u>77,600</u>
3) Spillway @ Design High Water	<u>NA</u>
4) Spillway @ Auxiliary Spillway Crest Elevation	<u>NA</u>
5) Low Level Outlet	<u>NA</u>
6) Total (of all facilities) @ Maximum High Water	<u>122,100</u>
7) Maximum Known Flood	<u>120,000</u>
8) HYDROELECTRIC STATION EXISTING MACHINERY ( <sup>12</sup> UNITS)	<u><del>5100 (MAX)</del></u>
DESIGN -	6043 (MAX)
OPERATING -	5893

CREST:

ELEVATION: 67.5 (BCD)

Type: REINFORCED CONCRETE CAP OVER STONE BLOCK ; PRECAST CONC. APRON SLAB  
ON DOWNSTREAM FACE

Width: 36' @ BASE (INCL. APRON) Length: 700' (+)

Spillover ENTIRE LENGTH OF CREST

Location \_\_\_\_\_

SPILLWAY:

PRINCIPAL

EMERGENCY

67.5 BCD Elevation \_\_\_\_\_

REINFORCED CONC. CAP OVER STONE BLOCK Type NONE

36' @ BASE (INCL. APRON) Width \_\_\_\_\_

Type of Control

✓ Uncontrolled \_\_\_\_\_

Controlled:

\_\_\_\_\_ Type  
(Flashboards; gate)

\_\_\_\_\_ Number \_\_\_\_\_

700' Size/Length \_\_\_\_\_

Invert Material \_\_\_\_\_

Anticipated Length  
of operating service \_\_\_\_\_

N/A Chute Length \_\_\_\_\_

4' Height Between Spillway Crest  
& Approach Channel Invert  
(Weir Flow) \_\_\_\_\_

OUTLET STRUCTURES/~~EMERGENCY DRAWDOWN FACILITIES:~~Type: Gate  Sluice \_\_\_\_\_ Conduit \_\_\_\_\_ Penstock \_\_\_\_\_Shape: NAVIGATION LOCK 3Size: 46' x 410'Elevations: Entrance ~~Invert~~ NORMAL POOL @ 67.5+Exit ~~Invert~~ NORMAL TAILWATER @ 48.0±Tailrace Channel: Elevation N/A

## HYDROMETEROLOGICAL GAGES:

Type: STAFF GAGE & WATER-STAGE RECORDER STAFF GAGES @ Lock 3Location: ON RT. BANK JUST UPSTREAM OF DAM UPSTREAM & DOWNSTREAM

Records:

Date - (USGS) 10/1887 TO 9/1956 (NYS-DOT) 10/1916 TO PRESENTMax. Reading - HEAD = 11.67' 3/28/1913 UPSTR: 79.4 on 1/1/1949 Q = 118,000 cfs  
DISCHARGE = 120,000 cfs DOWNSTR: 60.7 on 3/19/1936

## FLOOD WATER CONTROL SYSTEM:

Warning System: NONE

Method of Controlled Releases (mechanisms):

NONE

DRAINAGE AREA: 4500 SQ MILES

DRAINAGE BASIN RUNOFF CHARACTERISTICS:

Land Use - Type: 1/2 - 2/3 OF AREA IN ADIRONDACK MOUNTAIN AREA

Terrain - Relief: ELEVATIONS (+5344 TO +70 @ DAM)

Surface - Soil: VARIES

Runoff Potential (existing or planned extensive alterations to existing (surface or subsurface conditions)

N/A  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Potential Sedimentation problem areas (natural or man-made; present or future)

N/A  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Potential Backwater problem areas for levels at maximum storage capacity including surcharge storage:

N/A  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Dikes - Floodwalls (overflow & non-overflow) - Low reaches along the Reservoir perimeter:

Location: @ SHORELINE, DUE EAST OF END OF THE UPSTREAM PROTECTION PIER

Elevation: 72±

Reservoir:

Length @ Maximum Pool 2± (Miles)

Length of Shoreline (@ Spillway Crest) N/A (Miles)

PROJECT GRID

JOB		SHEET NO.	CHECKED BY	DATE
LOCK 3 DAM @ MECHANICVILLE		1/		
SUBJECT		COMPUTED BY	DATE	
STREAMFLOW GAGE DATA		WCL	2/79	
USGS WSP 1302: (RECORDS TO SEPT. 1950)				
GAGE # 61:	MAX. Q = 120,000 cfs	ON	3/28/1913	
	MAX. Q = 118,000 cfs	ON	1/1/1949	
	[OVER SPILLWAY + THRU WHEELS + THRU LOCK]			
	SINCE 9/30/1915			
USGS WSP 1722: (RECORDS OCT. 1950 TO SEPT. 1960)				
GAGE # 3355: (DISCONTINUED SEPT. 1956)				
MAX. Q - SAME AS ABOVE				
AFTER SEPT. 1956:				
GAGE # 3580 (-) GAGE # 3575 = APPROX. LOCK 3 FLOW				
* 3580 - HUDSON RIVER @ GREEN ISLAND, NY				
* 3575 - MOHAWK RIVER @ COHOES, NY				
APRIL 4 & 5, 1960:				
* 3580	134,900 cfs	}	51,600 cfs	[NOT A MAX. Q]
* 3575	83,300 cfs			
MARCH 6, 1964:				
* 3580	141,000 cfs	}	96,000 cfs	[NOT A MAX. Q]
* 3575	143,000 cfs		77,500 cfs	
RATING CURVE LOGARITHMIC EXTRAPOLATION ABOVE 100,000 cfs 3 cfs DIVERSION THRU LOCK 6 @ BARGE CANAL (WINTER SHUTDOWN)				
JUNE 24, 1972 (HURRICANE AGNES):				
* 3580			78,900 cfs	[NOT A MAX. Q]
* 3575	58,100 cfs		50,900 cfs	

PROJECT GRID

JOB	SHEET NO.	CHECKED BY	DATE
Lock 3 DAM @ MECHANICVILLE	2/		
SUBJECT	COMPUTED BY		DATE
STREAMFLOW GAGE DATA & SIMULATION DATA	WCL		2/79
"UPPER HUDSON & MOHAWK RIVER BASINS HYDROLOGIC FLOOD ROUTING MODELS"			
GREATEST ANNUAL PEAKS OF RECORD - TABLE 4.1			
3/28/1913	119,000 cfs	[APPROX. MAX Q]	
12/31/1948	94,400 cfs		
4/12/1922	72,900 cfs		
TABLE 6.39: (RESULTS FROM SIMULATION)			
SPF = 191,121 cfs		SPS RAINFALL - 9.5"	
TRANPOSED AGNES = 251,604 cfs		PMP RAINFALL - 20" (TP-40)	
PMF ≈ 2 x SPF		(10 SQ MILES - 6HR)	
		TRANPOSED } AGNES } - 11" RAINFALL }	
		HRR # 33 PMP RAINFALL 19.5"	
		78% (1000 SQ MI - 24HR) - 15.2"	
		86% (-48HR) - 16.3"	
∴ PEAK DISCHARGE (PMF) = 382,242 cfs		[USE 382,000 cfs]	

PROJECT GRID

JOB LOCK 3 DAM @ MECHANICVILLE	SHEET NO. 3/	CHECKED BY	DATE
SUBJECT DISCHARGE COEFFICIENT		COMPUTED BY WCL	DATE 2/79
ROUNDED CREST : RADIUS = $2' - 3\frac{5}{8}" = 2.302'$		LENGTH = 700' (MAIN SPILLWAY PORTION)	
DRAWING # M3082 (APPENDIX F):			
GAGE D: WS ELEV. = 82.58'		ON 3/28/1913	
TOP-OF-DAM = 70.91			
HEAD = 11.67'			
UGGS GAGE #61		MAX. Q = 120,000 cfs ON 3/28/1913	
$Q = CLH^{\frac{3}{2}}$	$C = \frac{Q}{LH^{\frac{3}{2}}}$	[ASSUMED: ENTIRE 3/28/1913 Q FLOWED ONLY OVER THE SPILLWAY]	
$= \frac{120000}{(700)(11.67)^{1.5}}$			
C = 4.30		{ INDICATES A SHARP-CRESTED WEIR CONDITION	
$C = \frac{120000}{(795.7)(11.67)^{1.5}}$		{ FOR H = 11.67', INUNDATION OF THE LOCK WOULD HAVE OCCURRED	
C = 3.78		$L = L' - 0.2H \quad L' = 798' \quad H = 11.67'$	
		L = 795.7	
USE C = 3.8			



PROJECT GRID

JOB	SHEET NO.	CHECKED BY	DATE
LOCK 3 DAM @ MECHANICVILLE	4/		
SUBJECT		COMPUTED BY	DATE
DEPTH - FLOWS (COMPUTED)		WCL	2/79
$Q = CLH^{3/2}$	$L = L' - 2(K_p)H$	SPILLWAY CREST ELEV:	
$C = 3.8$	$K_p = 0.1$	USGS (DATUM)	- 66.30
(FOR ANALYSIS - SHT 3)		BARGE CANAL (DATUM)	- 67.5
ELEVATIONS - BARGE CANAL DATUM			
TOP - LOCK 3 (RIVER-SIDE ABUTMENT)	ELEV. = 77.0 (@ PRESENT)		
$Q = (3.8)(698.1)(9.5)^{3/2}$	$H = 9.5'$	$L = 700 - 2(0.1)(9.5)$	
$Q = 77676$ cfs		$L = 698.1$	
TOP - EARTHEN DIKE	ELEV. = 83.0 (@ PRESENT)		
	$H = 9.5 + 6$	$L = 798 - 2(0.1)(6)$	
		$L = 796.8$	
$Q = 77676 + (3.8)(796.8)(6)^{3/2}$			
$= 77676 + 44500$			
$Q = 122176$ cfs		USE 122170 cfs	←
FOR THE GIVEN Q; COMPUTE H:		TOP - EARTHEN DIKE = 83.0	
$Q = 120000$ cfs	$L = 798$		
$H^{3/2} = \frac{Q}{CL} = \frac{(120000 - 77676)}{(3.8)(798)}$		$H = 5.8'$	ELEV = 82.8
(1/2 PMF) $Q = 191000$ cfs	$L = 798 + 520 = 1318$		
$H^{3/2} = \frac{(191000 - 122176)}{(3.8)(1318)}$		$H = 5.7'$	ELEV = 88.7
(PMF) $Q = 382000$ cfs			
$H^{3/2} = \frac{(382000 - 122176)}{(3.8)(1318)}$		$H = 13.9'$	ELEV = 96.9

PROJECT GRID

JOB LOCK 3 DAM @ MECHANICVILLE		SHEET NO. 5/		CHECKED BY		DATE	
SUBJECT FLOW AREAS - PLANIMETERED				COMPUTED BY WCL		DATE 2/79	
MAP (SCALE 1:6000)		1 IN <sup>2</sup> = 5.739 ACRES					
AREA (DAM TO 870)		AREA (870 TO 850)					
15.78 IN <sup>2</sup>		10.26 IN <sup>2</sup>					
AREA (850 TO 820)		AREA (820 TO LOCK 4; DAM @ 790)					
18.53 IN <sup>2</sup>		15.44 IN <sup>2</sup>					
		4.41 IN <sup>2</sup>		- HOOSIC RIVER			
SUB-AREAS (820 - UPSTREAM)				AREA			
ALONG MAIN STEM OF RIVER - TO ELEV ±70 :				1.37 IN <sup>2</sup>			
ALONG LOCK 4 APPROACH - TO ELEV ±70 :				1.48 IN <sup>2</sup>			
ALONG HOOSIC RIVER - TO ELEV ±70 :				0.47 IN <sup>2</sup>			
		STAGE -		AREA (IN <sup>2</sup> )		ACRES	
		66		48.39		278	
		70		48.39		278	
		MAIN STEM - 70+		60.48		347 } 370	
		HOOSIC RIVER - (70-75)		3.94		23 }	
USGS 7.5' QUAD - MECHANICVILLE (1954)		SCALE: 1:24000		1 IN <sup>2</sup> = 91.827 ACRES			
ELEV		AREA					
66		3.11 IN <sup>2</sup>					
		(-) 0.29 IN <sup>2</sup> (GREEN ISLAND)					
66-70 :		2.82 IN <sup>2</sup>					
ABOVE TO:		STAGE -		AREA (IN <sup>2</sup> )		ACRES	
MAIN STEM -		66		2.82		259	
HOOSIC RIVER -		70		2.82		259	
		MAIN STEM - 70+		3.60		331 } 351	
		HOOSIC RIVER - (70-75)		0.22		20 }	

PROJECT GRID

JOB		SHEET NO.			CHECKED BY	DATE
LOCK 3 DAM @ MECHANICVILLE		6/				
SUBJECT					COMPUTED BY	DATE
STAGE - STORAGE DATA					WCL	2/79
SURFACE AREAS (SHT 5):						
STAGE	(ACRES) AREA	(FT) Δh	(AG-FT) ΔVOL.	(AG-FT) STORAGE		
66.5	100	19	3420		{ HT OF DAM ≈ 19' DECREASE AREA @ 5% PER FT ELEV.	
66	260	4	1040	3420	← (SPILLWAY CREST)	
70	360	5	1525	4460		
70+75 (TO LIMITS)	350	2	700	5985		
77	350	6	2100	6085		
83	350			8785		

PROJECT GRID

JOB Lock 3 DAM @ MECHANICVILLE		SHEET NO. 7/	CHECKED BY	DATE
SUBJECT GATE HOUSE - FOREBAY - EXISTING HYDRO : DISCHARGES		COMPUTED BY WCL	DATE 2/79	
[SHT # M-5596]				
11	GATES	8' WIDE x 10' HIGH		
1	GATE	4' WIDE x 10' HIGH		
[SHT # M3265]		[SHT # M3280]		
SPILLWAY CREST - 70.91		BOTTOM OF CANAL @ ELEV. 53.0		
BASE OF DAM - 51.5±				
@ RNER BOTTOM		[SHT # M2990]		
19.4'				
(ASSUMPTION):		HYDRO-ELECTRIC PLANT HEAD		
BOTTOM OF GATES ARE @ ELEV. 53.0		GATES		
∴ CENTER OF GATES @ ELEV. 58.0		6 GATES		
		CLEAR OPENINGS 12' x 12'		
		OPENING INVERT - ELEV. 57.50		
UPSTREAM HEAD = 12.9'				
FERC PERMIT APPLICATION #2793:				
MAXIMUM DISCHARGE (12 UNITS) = 5893 cfs ←				

EXHIBIT M


GENERAL SPECIFICATIONS - EXISTING HYDROELECTRIC POWER STATION

Hydraulic Turbine Information

	#3	#4	#7	#8	#9	#10	#11	#12	#13	#14	#15	#16
Make	S.M.S.	S.M.S.	A.C.	S.M.S.	S.M.S.	S.M.S.	Leffel	S.M.S.	S.M.S.	S.M.S.	Leffel	Leffel
Type	Type UL #8632	8633	AV	-	-	-	-	-	-	-	-	-
Size	1445 HP	-	76"	65"	65"	50"	2-47-1/2	2-45"	2-45"	2-42"	2-47-1/2"	2-47-1/2"
Position	Vert.	Vert.	Vert.	Vert.	Vert.	Vert.	Hor.	Hor.	Hor.	Hor.	Hor.	Hor.
R.P.M.	214	214	187-1/2	250	250	125	150	150	150	150	150	150
Head, feet	19/23	19/23	19/23	19/23	19/23	19/23	19/21	19/21	19/21	19/21	19/21	19/21
C.F.S.	$\frac{775}{780}$	$\frac{775}{760}$	$\frac{636}{646}$	$\frac{440}{475}$	$\frac{440}{475}$	$\frac{400}{425}$	$\frac{393}{413}$	$\frac{443}{466}$	$\frac{433}{466}$	$\frac{372}{291}$	$\frac{393}{413}$	$\frac{393}{413}$
<u>Governor Information</u>												
Make	S.M.S.	S.M.S.	W	W	W	W	W	W	W	W	W	W
Type	TS	TS	HR	HR	HR	HR	LR	VR10	VR10	Mech	LR	LR
Serial	256	257	5363	7364	160466	7381	202529	3123	3122	x	202530	27346
Cap.ft.lbs.	16,500	16,500	16,300	10,500	10,500	8400	10,500	10,000	10,000	x	10500	10,500

fraction values =  $\frac{\text{Operating}}{\text{Design}}$

SMS - S. Morgan Smith  
 A.C. - Allis-Chalmers  
 W - Woodward




DRAINAGE AREA  
 LOCK 3 @  
 MECHANICVILLE  
 NY-215

WSP #1303  
 SCALE  
 1:1,000,000

LOCK 3 DAM @ MECHANICVILLE  
NY-215


RESERVOIR AREA

SARATOGA COUNTY  
TOWN OF STILLWATER



(APPROXIMATE) SCALE: 1:6000

RESERVOIR AREA  
LOCK 3 DAM @ MECHANICVILLE  
NY-215



(APPROXIMATE) SCALE: 1:6000

(APPROXIMATE)

HUDSON RIVER BASIN

61. Hudson River at Mechanicville, N. Y.

Location.--Lat 42°54'45", long 73°40'45", on right bank at dam of West Virginia Pulp & Paper Co., at Mechanicville, Saratoga County, three quarters of a mile upstream from Anthony Kill, and 1 1/2 miles downstream from Roostic River.

Drainage area.--4,500 sq mi.

Gage.--Water-stage recorder. Datum of gage is 66.63 ft above mean sea level, datum of 1929. Prior to 1911, staff gage at same site and datum.

Average discharge.--63 years (1887-1950), 7,370 cfs, revised (unadjusted).

Extremes.--1887-1950: Maximum discharge, 120,000 cfs Mar. 28, 1913; practically no flow for short periods when plant was shut down. Maximum known discharge prior to 1913, 70,000 cfs April, 1869 (Report of U. S. Board of Engineers on Deep Waterways). Since 1930, maximum discharge, 118,000 cfs Jan. 1, 1949.

Remarks.--Discharge computed from flow over spillway, through wheels, and through lock of Champlain Canal since Sept. 30, 1915. Flow appreciably regulated by Indian Lake since 1898 (see p. 45) and Sacandaga Reservoir since Mar. 27, 1930 (see p. 62). During canal navigation season, water is diverted through Glens Falls feeder, Bond Creek (see pp. 66, 67), and Champlain Canal into Lake Champlain basin and occasionally may receive water from that basin through summit level of Champlain Canal at Dunham Basin. No adjustment made for these diversions.

Cooperation.--Records of discharge over spillway and through wheels furnished by West Virginia Pulp & Paper Co.

Monthly and yearly mean discharge, in cu

Water year	Oct.	Nov.	Dec.	Jan.	Feb.
1941	5,760	6,946	8,013	8,006	6,167
1942	7,578	4,068	4,755	5,174	5,287
1943	6,590	6,876	6,597	6,780	7,205
1944	5,555	6,894	5,215	5,026	5,852
1945	4,705	4,785	5,915	6,116	5,250
1946	15,644	17,850	8,678	8,246	5,269
1947	4,813	4,497	5,047	7,528	6,121
1948	5,074	4,156	5,412	7,625	4,725
1949	7,608	4,676	8,478	18,483	10,970
1950	5,525	4,667	7,542	10,893	7,578

Water year	Oct.	Nov.	Dec.	Jan.	Feb.
1888	0.61	1.04	2.05	1.82	0.59
1889	1.18	2.64	2.57	2.81	.89
1890	.96	1.96	5.59	2.89	1.65
1891	2.56	2.94	.63	.55	.55
1892	.58	1.01	2.07	4.33	1.22
1893	.70	1.89	1.05	.82	1.22
1894	.92	.90	1.65	1.75	1.12
1895	.94	1.58	1.12	.99	.82
1896	.69	2.08	2.79	1.74	1.12
1897	1.05	2.87	1.78	1.03	.90

Monthly and yearly mean discharge, in cubic feet per second

Water year	Oct.	Nov.	Dec.	Jan.	Feb.	Mar.	Apr.	May	June	July	Aug.	Sept.	The year
1888	2,553	4,190	8,018	5,567	3,714	6,845	21,760	21,420	4,917	1,553	1,725	2,851	7,096
1889	4,698	6,647	10,014	10,965	3,790	9,280	15,690	5,871	6,869	5,727	4,272	4,965	7,476
1890	3,743	7,896	13,226	11,272	7,913	11,179	15,053	17,951	7,392	1,950	2,019	8,844	9,050
1891	9,215	9,121	5,744	8,284	11,664	17,756	20,021	5,855	5,200	2,557	2,666	2,040	7,922
1892	1,473	4,086	8,573	18,857	9,285	10,979	21,954	19,622	12,595	3,287	5,485	4,448	10,498
1893	2,659	7,604	4,051	5,122	4,805	9,260	17,989	22,265	4,861	2,521	5,035	6,870	7,506
1894	3,865	5,659	7,217	6,757	4,856	14,758	11,155	7,566	7,097	3,168	2,436	1,889	6,137
1895	3,649	6,379	4,567	5,876	5,543	4,204	23,822	6,850	2,816	2,559	3,901	2,629	5,716
1896	2,631	8,421	10,899	6,791	4,664	15,600	24,972	4,610	4,758	2,772	2,442	2,879	7,452
1897	4,194	1,552	6,913	4,007	5,895	12,214	19,074	12,167	11,355	1,129	8,241	7,756	8,974
1898	2,574	9,925	14,382	8,175	6,058	19,617	15,047	10,325	5,069	2,751	5,029	5,810	8,413
1899	7,516	8,978	5,291	6,457	5,147	9,516	14,607	9,021	2,839	2,402	1,417	2,078	7,108
1900	2,616	6,066	7,805	5,841	10,484	7,740	22,614	6,992	4,055	2,352	2,705	1,886	7,058
1901	2,129	5,077	5,551	5,047	2,688	8,025	28,268	11,658	7,806	3,551	4,661	4,024	7,214
1902	4,264	5,732	8,492	15,225	4,741	28,150	15,232	9,749	6,535	8,934	6,286	5,645	18,480
1903	6,894	7,076	9,162	1,054	9,895	30,938	14,013	3,609	6,472	4,863	5,905	4,118	9,522
1904	10,117	5,076	5,297	5,805	6,808	11,058	20,757	13,373	6,765	3,953	15,483	6,660	18,485
1905	11,029	4,644	5,322	6,097	5,544	9,588	22,748	8,171	9,552	6,935	5,631	22,032	18,641
1906	6,075	6,855	18,510	9,510	7,690	9,000	90,600	15,400	9,260	5,780	5,490	5,070	18,500
1907	5,376	5,130	4,870	10,500	4,140	9,570	16,600	13,800	5,560	4,120	42,370	6,150	17,170
1908	8,804	10,800	12,000	8,410	9,690	14,000	22,500	17,900	5,740	2,140	1,770	1,020	9,710
1909	1,380	1,850	2,010	5,210	11,000	9,725	25,800	17,000	6,020	1,990	1,550	1,460	7,090
1910	1,960	1,680	1,570	5,190	5,480	21,400	17,600	9,250	10,200	1,600	1,990	2,270	6,650
1911	2,543	5,280	2,910	5,270	5,780	16,800	9,260	4,450	1,360	1,180	2,000	4,760	4,760
1912	7,243	7,560	10,000	4,760	5,400	10,000	27,600	12,900	5,540	1,510	1,070	22,490	7,850
1913	6,950	10,800	8,640	12,700	5,220	25,500	16,500	16,920	15,940	1,780	1,270	11,170	18,420
1914	2,779	6,790	4,843	2,510	5,070	7,500	55,700	10,900	2,550	2,140	1,450	1,950	6,750
1915	1,243	2,130	2,590	6,480	10,500	9,110	12,900	5,340	1,940	6,580	7,880	5,850	6,010
1916	4,500	4,200	6,650	10,000	10,100	8,210	22,900	15,000	6,900	3,950	1,710	1,920	7,850
1917	2,010	4,020	6,740	4,950	2,750	10,900	21,500	10,100	14,200	4,560	1,870	1,770	7,060
1918	3,660	6,150	2,600	1,440	4,720	12,000	21,800	15,500	4,870	2,510	1,470	3,150	6,210
1919	4,240	6,930	6,160	6,510	5,450	11,000	15,400	15,500	4,780	2,080	1,970	3,710	6,990
1920	5,020	9,280	6,480	2,210	1,970	15,600	26,400	9,550	3,550	2,680	2,660	1,970	7,140
1921	5,980	6,070	13,000	5,110	5,780	21,500	12,700	5,750	1,780	4,390	2,010	1,590	6,850
1922	2,010	5,550	7,070	5,100	4,010	14,800	30,500	11,800	11,800	5,770	5,120	2,450	8,450
1923	2,574	2,470	1,850	4,950	2,980	7,080	29,200	15,100	3,970	1,870	1,300	1,620	5,710
1924	2,400	4,370	9,110	10,500	5,790	5,550	25,400	20,500	3,650	2,040	1,870	3,000	7,640
1925	5,560	5,620	4,520	1,600	9,470	18,200	18,100	8,600	4,810	6,470	4,900	4,750	7,510
1926	6,000	7,800	8,740	4,820	4,090	6,160	27,900	13,500	5,660	3,170	2,510	2,670	7,760
1927	5,510	6,700	3,850	3,210	4,250	10,848	12,900	9,750	4,150	2,970	2,320	2,950	6,510
1928	4,830	7,480	7,800	6,880	7,240	19,254	19,800	16,800	16,800	4,410	4,310	5,290	9,950
1929	2,800	5,270	3,670	5,680	5,620	12,800	14,500	26,000	5,510	5,960	2,040	2,480	7,720
1930	2,980	3,910	4,880	8,500	7,160	12,800	10,700	6,680	6,410	5,110	2,450	2,570	5,990
1931	2,480	2,540	2,700	2,060	1,610	8,440	10,400	5,170	5,190	6,155	3,390	3,690	4,240
1932	4,170	5,990	7,950	10,500	7,580	6,950	14,900	9,560	5,850	4,380	3,780	3,750	6,720
1933	7,050	5,200	7,880	7,610	7,100	1,460	22,500	9,070	3,640	3,970	3,850	4,070	8,000
1934	3,899	4,712	5,515	6,207	5,507	9,518	18,560	5,837	4,687	5,127	2,955	2,867	5,875
1935	5,537	4,423	5,064	9,057	6,085	7,705	9,796	8,669	5,275	12,740	5,579	4,539	7,095
1936	4,337	8,372	8,525	4,997	2,869	25,600	18,740	8,195	5,566	2,756	2,561	3,068	7,595
1937	4,295	8,117	7,586	17,850	7,325	6,509	15,000	15,750	7,264	5,148	4,967	4,727	7,889
1938	4,673	6,928	6,778	7,746	10,450	10,510	8,658	5,517	5,394	4,248	4,408	11,520	7,003
1939	5,799	5,700	17,410	5,965	5,925	10,070	20,510	9,971	4,732	3,582	3,055	2,977	7,519
1940	2,698	5,828	7,781	2,459	2,240	4,483	18,840	15,490	8,404	3,861	3,665	4,756	6,282

\* Corrected.  
† Not previously published; partly estimated on basis of records in reports of State engineer and surveyor of New York.

Year	W.S.F. no.	Yearly discharge	
		Water year	
		Discharge	Date
1888	24	-	-
1889	24	-	-
1890	24	-	-
1891	24	-	-
1892	24	-	-
1893	24	-	-
1894	24	-	-
1895	24	-	-
1896	35	-	-
1897	35	31,060	July 15, 1897
1898	47	59,281	Mar. 14, 1898
1899	47	41,475	Apr. 25, 1899
1900	47	45,546	Apr. 25, 1900
1901	65	54,862	Apr. 24, 1901
1902	80	42,940	Apr. 12, 1902
1903	97	56,763	Mar. 25, 1903
1904	166	56,305	Apr. 11, 1904
1905	166	46,877	Apr. 1, 1905
1906	202	40,500	Apr. 16, 1906
1907	241	56,730	Apr. 1, 1907
1908	241	24,400	Apr. 26, 1908
1909	261	46,300	Apr. 16, 1909
1910	281	57,800	Apr. 5, 1910
1911	501	75,200	May 3, 1911
1912	521	47,275	Apr. 8, 1912
1913	521	110,000	Mar. 28, 1913
1914	581	64,788	Apr. 22, 1914
1915	581	55,185	Feb. 25, 1915
1916	431	56,045	Apr. 7, 1916
1917	451	56,200	June 15, 1917
1918	471	55,500	Apr. 3, 1918
1919	501	51,600	Apr. 15, 1919
1920	501	56,100	Apr. 6, 1920
1921	571	55,000	Mar. 22, 1921
1922	541	72,900	Apr. 17, 1922
1923	581	45,700	Apr. 1, 1923
1924	581	59,800	Apr. 15, 1924
1925	601	44,500	Mar. 25, 1925
1926	621	51,800	Apr. 26, 1926
1927	641	55,600	Mar. 21, 1927
1928	681	70,000	Nov. 4, 1928
1929	681	40,700	Mar. 28, 1929

Monthly and yearly mean discharge, in cubic feet per second, of Hudson River at Mechanicville, N. Y.--Continued

Water year	Oct.	Nov.	Dec.	Jan.	Feb.	Mar.	Apr.	May	June	July	Aug.	Sept.	The year
1941	5,765	6,846	8,013	8,006	6,167	5,395	10,450	7,652	2,009	1,937	1,604	2,169	4,898
1942	3,778	4,006	4,755	5,174	5,367	9,745	15,213	5,937	7,507	5,705	5,075	4,475	5,616
1943	6,894	8,976	8,592	6,780	7,005	13,720	11,540	21,880	7,600	4,564	5,374	5,555	8,890
1944	3,555	6,884	5,213	3,006	3,832	8,929	17,480	9,474	7,472	4,857	3,168	3,287	6,413
1945	4,704	4,785	3,915	6,116	5,230	18,150	11,540	17,690	8,790	7,444	4,747	5,568	8,113
1946	15,843	22,650	8,678	8,146	5,969	15,180	5,654	8,950	7,911	5,856	5,816	3,678	8,210
1947	4,813	4,497	5,047	7,595	9,116	9,592	16,460	20,350	16,750	7,505	4,965	5,181	9,145
1948	2,024	4,156	3,412	2,603	4,275	15,800	13,490	10,490	7,355	4,117	3,470	2,567	6,245
1949	2,274	4,676	3,415	3,480	11,900	10,160	7,746	4,948	2,841	2,566	2,996	3,136	6,657
1950	2,574	4,477	3,415	3,480	11,900	10,160	7,746	4,948	2,841	2,566	2,996	3,136	6,657

West Virginia Pulp & Paper Co. at a mile upstream from  
 an sea level, datum of  
 adjusted).  
 1949: practically no flow  
 1949 (Report of U. S. Board

Monthly and yearly runoff, in inches

Water year	Oct.	Nov.	Dec.	Jan.	Feb.	Mar.	Apr.	May	June	July	Aug.	Sept.	The year
1888	0.61	1.04	2.05	1.62	0.89	1.75	5.26	5.49	1.22	0.39	0.44	0.71	21.47
1889	1.18	2.04	2.57	2.81	1.88	2.12	3.29	1.70	1.47	1.09	1.43	1.43	22.61
1890	.96	1.96	3.39	2.89	1.83	2.85	3.75	4.59	1.85	.50	.52	2.19	27.24
1891	2.56	2.26	.85	2.12	2.70	4.55	4.97	1.42	.79	.60	.68	.51	25.72
1892	.56	1.31	2.27	4.03	2.27	2.80	5.35	5.08	2.38	1.41	1.13	1.13	31.66
1893	.72	1.89	1.05	.82	1.09	2.11	4.44	5.71	1.19	.65	1.28	1.70	22.63
1894	.99	.90	1.85	1.73	1.12	3.78	2.76	1.94	1.76	.81	.65	.47	16.74
1895	.94	1.58	1.12	.99	.82	1.08	5.91	1.76	.70	.66	1.00	.65	17.21
1896	.69	2.06	2.79	1.74	1.12	3.49	6.20	1.18	1.18	.72	.65	.71	22.54
1897	1.05	2.67	1.78	1.03	.30	3.12	4.75	3.11	2.95	2.85	2.11	.68	22.54

meals, and through lock of  
 (see p. 62). During  
 is feeder, Bond Creek (see  
 and occasionally may re-  
 in Canal at Durham Basin.  
 meals furnished by West

Yearly discharge, in cubic feet per second

Year	W.S.P. no.	Water year ending Sept. 30				Calendar year	
		Maximum day		Minimum day	Mean	Per square mile	Runoff in inches
		Discharge	Date				
1888	24	-	-	-	7,096	1.58	21.47
1889	24	-	-	-	7,470	1.66	22.61
1890	24	-	-	-	9,050	2.01	27.24
1891	24	-	-	-	7,922	1.76	25.72
1892	24	-	-	-	10,498	2.55	31.66
1893	24	-	-	-	7,506	1.67	22.63
1894	24	-	-	-	6,197	1.58	18.74
1895	24	-	-	-	5,716	1.27	17.21
1896	36	-	-	-	7,457	1.66	22.55
1897	36	31,060	July 15, 1897	-	7,111	1.59	22.54
1898	47	39,251	Mar. 14, 1898	-	1,163	0.43	24.06
1899	47	41,475	Apr. 26, 1899	-	204	0.07	6.625
1900	47	43,546	Apr. 25, 1900	-	713	0.25	6.770
1901	65	54,862	Apr. 24, 1901	-	1,577	0.53	22.66
1902	87	42,940	Mar. 18, 1902	-	1,400	0.48	19.524
1903	97	56,788	Mar. 25, 1903	-	1,067	0.37	21.60
1904	166	56,505	Apr. 11, 1904	-	705	0.24	19.553
1905	166	48,877	Apr. 11, 1905	-	48,641	0.92	48.711
1906	208	40,500	Apr. 16, 1906	187	48,500	0.89	42.59
1907	241	56,700	Apr. 17, 1907	872	47,170	0.59	42.08
1908	241	54,500	Apr. 28, 1908	673	9,710	0.16	29.55
1909	261	46,300	Apr. 16, 1909	255	7,090	0.18	21.25
1910	281	37,800	Apr. 3, 1910	245	6,650	0.14	20.80
1911	501	26,200	May 2, 1911	553	4,760	0.06	6.190
1912	521	43,275	Mar. 8, 1912	489	7,320	0.14	22.68
1913	581	41,000	Mar. 26, 1913	175	4,470	0.07	12.57
1914	581	44,700	Apr. 22, 1914	474	6,750	0.11	19.25
1915	461	35,180	Feb. 25, 1915	725	6,110	0.14	18.14
1916	451	55,945	Apr. 2, 1916	687	7,850	0.14	23.25
1917	451	56,500	June 15, 1917	899	7,060	0.15	21.31
1918	471	55,500	Apr. 3, 1918	574	6,210	0.18	18.71
1919	501	51,600	Apr. 15, 1919	1,060	6,390	0.15	21.14
1920	501	56,100	Apr. 6, 1920	1,090	7,140	0.19	21.60
1921	521	55,000	Mar. 22, 1921	715	6,850	0.15	20.61
1922	541	72,900	Apr. 17, 1922	725	8,450	0.18	25.50
1923	561	45,700	Apr. 9, 1923	743	5,710	0.17	17.25
1924	581	39,800	Apr. 19, 1924	820	7,640	0.17	23.10
1925	601	44,500	Mar. 30, 1925	696	7,510	0.17	22.65
1926	621	51,800	Apr. 26, 1926	995	7,760	0.17	23.41
1927	641	55,600	Mar. 21, 1927	613	6,510	0.14	19.35
1928	661	70,000	Nov. 4, 1927	953	9,950	0.21	30.15
1929	681	40,200	Mar. 25, 1929	685	7,720	0.17	23.27
1930	696	23,600	Apr. 8, 1930	805	5,990	0.13	18.05
1931	711	24,500	July 22, 1931	614	4,240	0.14	12.77
1932	726	27,700	Apr. 12, 1932	1,470	6,720	0.19	20.55
1933	741	46,700	Apr. 19, 1933	1,420	8,000	0.18	24.14
1934	756	29,400	Apr. 17, 1934	1,170	5,875	0.11	17.71
1935	761	34,000	Jan. 10, 1935	1,520	7,095	0.18	21.45

est per second  
 July Aug. Sept. The year  
 1,537 1,725 2,651 7,096  
 2,727 4,272 1,963 7,476  
 2,350 2,019 8,644 9,030  
 2,557 2,666 2,040 7,922  
 2,287 2,485 4,448 10,498  
 7,221 5,035 6,870 7,506  
 5,188 7,454 1,069 6,197  
 2,559 2,931 2,629 5,716  
 2,732 2,442 2,879 7,452  
 11,129 8,741 7,756 8,974  
 2,751 5,239 8,810 6,433  
 2,432 1,417 2,054 7,108  
 2,367 2,703 1,866 7,058  
 3,551 4,661 4,024 7,214  
 8,234 6,286 3,643 48,480  
 4,853 5,905 4,118 9,372  
 45,353 45,483 4,660 48,485  
 6,955 5,551 22,052 46,641  
 3,780 3,480 3,070 48,500  
 4,220 42,570 6,150 47,170  
 2,142 1,770 1,020 9,710  
 1,880 1,820 1,460 7,090  
 1,620 1,990 2,270 6,650  
 1,560 1,180 2,000 4,760  
 1,150 1,270 42,490 7,850  
 1,780 1,070 1,170 48,420  
 2,140 1,450 1,950 6,750  
 6,530 7,980 3,650 6,010  
 2,820 1,710 1,920 7,850  
 4,120 2,870 1,720 7,060  
 2,751 2,470 3,150 6,210  
 2,622 2,970 3,710 6,390  
 1,820 2,660 1,970 7,140  
 4,590 2,010 1,580 6,850  
 4,710 3,120 2,450 8,450  
 1,870 1,800 1,600 5,710  
 2,240 1,870 3,000 7,640  
 4,470 4,800 4,750 7,510  
 2,170 2,510 2,670 7,760  
 2,070 2,300 2,950 6,510  
 4,410 4,540 3,220 9,950  
 4,920 2,340 2,480 7,720  
 2,112 2,430 2,570 5,990  
 4,130 3,890 3,690 4,240  
 4,290 3,790 3,750 4,720  
 2,870 3,850 4,070 8,000  
 3,127 2,963 2,867 5,875  
 2,740 5,579 4,559 7,095  
 2,756 2,561 3,068 7,759  
 5,148 4,597 4,227 7,889  
 4,248 4,408 3,350 7,005  
 3,862 3,035 2,977 7,519  
 5,861 3,665 4,736 6,282

\* Not previously published.  
 a Maximum peak discharge.

In reports of State engineer and

Yearly discharge, in cubic feet per second, of Hudson River at Mechanicville, N. Y.--Continued

Year	W.S.P. no.	Water year ending Sept. 30					Calendar year			
		Discharge	Momentary maximum		Minimum day	Mean	Per square mile	Runoff in inches	Mean	Runoff in inches
			Date	Date						
1936	801	72,700	Mar. 19, 1936	1,500	7,759	1.72	23.46	7,711	23.31	
1937	851	28,500	May 16, 1937	1,780	7,089	1.75	23.00	7,719	23.30	
1938	851	85,600	Sept. 22, 1938	1,670	7,003	1.56	21.14	7,475	22.56	
1939	871	35,800	Apr. 29, 1939	1,060	7,513	1.67	22.71	6,204	18.97	
1940	890	40,100	Mar. 31, 1940	1,520	6,282	1.40	19.01	7,062	21.57	
1941	971	22,600	Dec. 31, 1940	896	4,898	1.09	14.78	4,274	12.90	
1942	951	27,100	Apr. 8, 1942	845	5,616	1.25	16.86	6,705	20.24	
1943	971	35,100	May 15, 1943	2,050	8,890	1.98	26.80	8,171	24.44	
1944	1001	35,800	Apr. 26, 1944	1,060	6,415	1.45	19.41	6,146	18.60	
1945	1051	32,600	Mar. 25, 1945	1,170	6,115	1.80	24.46	10,040	30.26	
1946	1051	31,500	Mar. 9, 1946	1,070	8,210	1.82	24.75	6,448	19.44	
1947	1081	43,700	June 4, 1947	1,070	9,145	2.03	27.56	8,826	26.60	
1948	1112	40,100	Mar. 25, 1948	775	6,345	1.33	18.88	6,686	20.22	
1949	1142	94,400	Dec. 31, 1948	866	6,657	1.48	20.07	6,634	20.01	
1950	1171	71,000	Apr. 5, 1950	1,640	7,124	1.58	21.50	-	-	

Note.--Monthly figures of discharge per square mile and runoff, in inches, since October 1938, previously published in water-supply papers, may be subject to considerable error because of diversions, and storage and evaporation in Indian Lake since 1939, and in Sacandaga Reservoir since Mar. 27, 1939. These figures are not published herein.

62. Black River Canal (flowing south) near Boonville, N. Y.

Location.--Lat 43°27'20", long 75°19'25", gage 1 on left bank at lock 69, 2 miles south of Boonville, Oneida County, and gage 2 on right bank of Lansitzkill spillway, 103 ft downstream from spillway headgates, 600 ft upstream from lock 70, and half a mile upstream from lock 69.

Gage.--Two water-stage recorders and concrete controls. Datum of gage 1 is 1,105.56 ft above mean sea level, datum of 1929. Prior to June 7, 1929, station was operated as a slope station on summit level of canal. September 1915 to September 1942 station was operated only during canal season.

Extremes.--1915-50: Maximum daily discharge recorded, 323 cfs Nov. 30, 1915; practically no flow at times when no water is being diverted.

Remarks.--Records include combined flow at gages 1 and 2 and represents total diversion from Black River at Forestport, through Forestport feeder, into Delta Reservoir in Mohawk basin. Discharge during periods when no water was diverted is made up of leakage through headgates and runoff from area draining into canal above station.

Monthly and yearly mean discharge, in cubic feet per second

Water year	Oct.	Nov.	Dec.	Jan.	Feb.	Mar.	Apr.	May	June	July	Aug.	Sept.	The year
1916	250	254	-	-	-	-	-	220	206	210	200	-	-
1917	210	205	-	-	-	-	-	189	183	173	169	-	-
1918	176	192	-	-	-	-	-	177	154	161	158	-	-
1919	157	131	-	-	-	-	-	-	176	164	169	-	-
1920	194	-	-	-	-	-	-	-	151	156	118	-	-
1921	144	-	-	-	-	-	-	146	166	156	158	-	-
1922	156	-	-	-	-	-	-	-	123	142	144	-	-
1925	148	-	-	-	-	-	-	-	84.6	97.7	129	-	-
1924	141	-	-	-	-	-	-	-	111	105	109	-	-
1925	125	-	-	-	-	-	-	-	47.6	40.8	37.6	-	-
1926	55.7	-	-	-	-	-	-	108	151	161	153	-	-
1927	130	-	-	-	-	-	-	-	97.5	93.0	87.5	-	-
1928	-	-	-	-	-	-	-	25.5	51.7	85.1	85.7	-	-
1929	-	-	-	-	-	-	-	-	54.7	19.7	7.50	-	-
1930	4.65	-	-	-	-	-	-	29.9	64.9	84.5	91.1	-	-
1931	98.1	-	-	-	-	-	-	12.5	26.8	20.4	49.2	72.5	-
1932	84.1	-	-	-	-	-	-	-	-	50.5	38.0	-	-
1933	47.5	-	-	-	-	-	-	-	78.4	89.2	121	-	-
1934	153	-	-	-	-	-	-	-	52.4	56.5	62.6	-	-
1935	-	-	-	-	-	-	-	22.7	51.1	50.4	60.5	-	-
1936	57.8	45.0	-	-	-	-	-	30.1	41.9	45.6	51.5	-	-
1937	85.4	-	-	-	-	-	-	16.5	35.0	66.0	87.4	-	-
1938	69	-	-	-	-	-	-	28.2	42.3	47.6	51.9	-	-
1939	56.5	-	-	-	-	-	-	43.9	57.0	51.4	54.6	-	-
1940	42.3	-	-	-	-	-	-	6.78	30.5	39.4	42.9	14.2	-
1941	62.5	-	-	-	-	-	-	45.0	46.7	55.5	55.0	58.2	-
1942	62.7	-	-	-	-	-	-	9.2	44.3	55.3	56.6	61.4	-
1943	27.5	34.2	9.66	4.58	4.24	14.5	16.8	19.6	12.6	34.2	47.7	55.7	23.5
1944	62.5	17.1	6.11	2.06	1.81	97.4	16.0	8.29	38.5	21.0	18.1	29.2	19.2
1945	28.7	12.6	4.76	6.42	4.96	16.2	15.8	23.0	14.9	54.5	57.3	48.6	24.3
1946	22.6	9.52	4.86	5.71	5.48	12.1	4.29	7.50	18.5	22.8	25.8	29.8	14.0
1947	46.9	12.6	1.16	.95	.81	.85	1.46	1.29	1.26	7.02	8.45	61.7	12.0
1948	72.0	80.7	4.53	1.88	4.17	12.6	3.52	33.7	36.1	44.1	58.3	66.5	35.0
1949	63.9	50.5	1.65	1.75	1.98	1.87	1.64	27.0	63.1	62.5	62.2	76.5	34.6
1950	62.1	37.9	1.75	1.25	1.65	2.18	4.26	6.39	12.0	55.2	74.7	62.0	21.7

63. Delta Res.

Location.--Lat 43°16'20", long 75°25'20", Mohawk River 4 miles upstream from

Drainage area.--145 sq. mi.

Gage.--Staff gage. Datum of gage is

Remarks.--Dam completed Aug. 3, 1912. Gage began May 1, 1915. Capacity 2,800,000 cu. ft. Reservoir is

Cooperation.--Records not previously published by State Department of Public Works.

Contents, in millions

Water year	Oct.	Nov.	Dec.	Jan.	Feb.	Mar.	Apr.	May	June	July	Aug.	Sept.	The year
1913	540	1,470	1,980	2,150	-	-	-	-	-	-	-	-	-
1914	540	1,470	1,980	2,150	-	-	-	-	-	-	-	-	-
1915	1,470	1,750	1,718	1,530	-	-	-	-	-	-	-	-	-
1916	2,482	2,435	1,874	858	-	-	-	-	-	-	-	-	-
1917	1,438	2,392	1,778	1,174	-	-	-	-	-	-	-	-	-
1918	2,680	1,782	1,334	1,174	-	-	-	-	-	-	-	-	-
1919	1,900	2,205	1,705	1,870	-	-	-	-	-	-	-	-	-
1920	2,848	2,770	2,273	862	-	-	-	-	-	-	-	-	-
1921	1,282	2,180	2,806	2,778	-	-	-	-	-	-	-	-	-
1922	1,920	2,512	839	1,198	-	-	-	-	-	-	-	-	-
1923	2,020	1,935	1,472	1,970	-	-	-	-	-	-	-	-	-
1924	2,145	2,185	2,185	1,300	22	-	-	-	-	-	-	-	-
1925	2,185	2,135	1,935	1,110	-	-	-	-	-	-	-	-	-
1926	5	4	1	2	-	-	-	-	-	-	-	-	-
1927	2,566	2,630	1,486	500	-	-	-	-	-	-	-	-	-
1928	1,718	1,926	2,826	2,534	-	-	-	-	-	-	-	-	-
1929	1,955	1,905	1,790	1,236	-	-	-	-	-	-	-	-	-
1930	1,145	1,229	1,714	1,010	-	-	-	-	-	-	-	-	-
1931	1,286	1,274	1,330	1,170	-	-	-	-	-	-	-	-	-
1932	2,345	2,385	2,818	2,740	-	-	-	-	-	-	-	-	-
1933	2,894	2,666	2,482	2,170	-	-	-	-	-	-	-	-	-
1934	1,872	2,158	2,178	1,802	-	-	-	-	-	-	-	-	-
1935	1,946	1,905	1,975	1,450	-	-	-	-	-	-	-	-	-
1936	1,865	2,608	2,322	1,394	-	-	-	-	-	-	-	-	-
1937	1,865	2,515	2,872	2,581	-	-	-	-	-	-	-	-	-
1938	2,120	2,842	2,405	1,725	-	-	-	-	-	-	-	-	-
1939	1,154	624	11	294	-	-	-	-	-	-	-	-	-
1940	1,114	896	1,013	750	-	-	-	-	-	-	-	-	-
1941	1,606	2,100	2,850	1,458	-	-	-	-	-	-	-	-	-
1942	2,100	1,462	1,826	1,321	-	-	-	-	-	-	-	-	-
1943	2,438	2,559	2,121	1,225	-	-	-	-	-	-	-	-	-
1944	2,385	2,572	1,466	1,122	-	-	-	-	-	-	-	-	-
1945	1,895	1,696	1,678	1,229	-	-	-	-	-	-	-	-	-
1946	2,225	2,150	1,574	1,514	-	-	-	-	-	-	-	-	-
1947	2,539	2,578	2,045	2,642	-	-	-	-	-	-	-	-	-
1948	1,426	1,358	1,130	1,020	-	-	-	-	-	-	-	-	-
1949	1,167	1,843	2,356	1,975	-	-	-	-	-	-	-	-	-
1950	1,916	1,446	2,422	2,434	-	-	-	-	-	-	-	-	-

64. Mohawk River

Location.--Lat 43°15'50", long 75°25'20", 1 mile downstream from Delta Dam.

Drainage area.--150 sq. mi.

Gage.--Water-stage recorder. Datum (datum). Prior to Jan. 24, 1937.

Average discharge.--29 years (1921-49)

Remarks.--1927-29: Station closed. Reopened, 94 cfs Sept. 27, 1948 to Jan. 17, 1951.


Remarks.--During canal navigation at Forestport Feeder and Black River station (see p. 82). Flow about station, small quantity of water, and later returned to river, after

Cooperation.--Records for 1921-27, published by State engineer and sur



LOCK 3 @ MECHANICVILLE  
 NY-215

ANNUAL MEAN HIGH WATER ELEVATION



1911 1912 1913 1914 1915 1916 1917 1918 1919 1920 1921 1922 1923 1924 1925 1926 1927 1928 1929 1930 1931 1932 1933 1934 1935

1935 1938 1940 1942 1948 1948 1946 1950 1952 1954 1956

82

80


78

76

74

72

70



ANNUAL MEAN HIGH WATER ELEVATION

LOCK 3 @ MECHANICVILLE

NY-215


date: February 10, 1965  
drawn by: J. Maloney  
checked by:

2688 101

above Dam 30

77-75-77 77-75-77

1950 1951 1960 1961 1962 1961 1961 1966 1966 1970 1972 1974 1974



ANNUAL MEAN HIGH WATER ELEVATION

LOCK 3 @ MECHANICVILLE  
NY-215

Hudson River

1976

1978

1980

1982

1984

1986

1988

1990

1992

1994

1996

GAGE - # 100

ADVE 2MM # 30

80

78

76


74

72

70

68

66



ANNUAL MEAN HIGH WATER ELEVATION

LOCK 3 @ MECHANICVILLE  
NY-215

DATE-1998-1978  
MADE BY- J.R. BATEMAN


22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1 0

below LOCK 3 C

1920 1921 1922 1923 1924 1925 1926 1927 1928 1929 1930 1931 1932 1933 1934 1935 1936 1937 1938 1939 1940 1941 1942 1943 1944 1945 1946 1947 1948 1949 1950 1951 1952 1953 1954 1955 1956 1957 1958 1959 1960 1961 1962 1963 1964 1965

1922 1924 1926 1928 1930 1932 1934 1936 1938 1940 1942 1944 1946 1948 1950 1952 1954 1956 1958 1960 1962 1964 1965

59.84



ANNUAL MEAN HIGH WATER ELEVATION


LOCK 3 @ MECHANICVILLE  
NY-215

Date: February 5, 1965  
Drawn by: S. Maloney  
Checked by:

62, 60, 58, 56, 54, 52, 50, 48, 46, 44, 42, 40, 38, 36, 34, 32, 30, 28, 26, 24, 22, 20, 18, 16, 14, 12, 10, 8, 6, 4, 2, 0

1936 1938 1940 1942 1944 1946 1948 1950 1952 1954 1956 1958

below LOCK 3



ANNUAL MEAN HIGH WATER ELEVATION

LOCK 3 @ MECHANICVILLE  
NY-215

date: February 5, 1965  
drawn by: J. Mahony  
checked by:



Hudson River

GAGE 205

Below Lock 3

1976	1978	1980	1982	1984	1986	1988	1990	1992	1994	1996
------	------	------	------	------	------	------	------	------	------	------

1291.6  
 1272.5  
 Max 15. 1976 - 58.95

Annual Mean High Water Elevation

LOCK 3 @ MECHANICVILLE

NY-215

DATE - FEB - 1978  
NAME OF J. R. BATEMAN

I. D. No. NY-215

LOCK 3 DAM @ MECHANICVILLE

# Water rights to utility 3/9/79

By RICHARD BANTTARI  
Staff Writer

**MECHANICVILLE** — The water rights of the former Saratoga Board Mills Corporation, described by a study of the New York State Army Engineers as one of the 10 most desirable sources of low-cost energy in the United States, will be sold to the New York State Electric & Gas Corporation.

Robert Lockwood, counsel for the City National Bank of Detroit which owns the paper mill property, said from Detroit Thursday, that the bank has signed a "tentative agreement" with NYSE&G. According to Lockwood, the utility will pay "less than" \$2.1 million for the rights.

Neither Lockwood nor Daniel Collins, Berkshire District Area manager for NYSE&G, would elaborate on the sale. It was not known if the purchase by the utility would involve the Mill's defunct hydroelectric plant which includes 25-cycle regenerative equipment.

Collins said the utility would issue a press release sometime today or Saturday.

Lockwood said one of the officers for NYSE&G, Larry Sweetland, an industrial development manager based in corporate headquarters in Binghamton, has been handling negotiations with the bank since City National successfully bid \$2,000,001 for the mill property Feb. 19.

A spokesman for NYSE&G in Binghamton said Sweetland was unavailable for comment because he was on a Buffalo business trip.

NYSE&G originally filed a letter of intent nearly two years for the purchase of the mill's water rights to former Saratoga Board Mills Corporation President Hy Sweet. According to a Nov. 29 referee's report filed by foreclosure attorney Pat Keniry, the utility was interested in purchasing approximately 1.2 acres of mill land together with certain easements and water rights.

Keniry's report listed the NYSE&G offer at \$2,075,000.

Lockwood said the bank was awaiting finalization from the utility for the offer. Asked when the sale would be made, the attorney could offer no date. "We're ready," he said.

The Detroit lawyer said the bank has received at least three or four offers for the water rights since NYSE&G and the bank began to negotiate. Some of the offers, he said were as high as \$3 and \$4 million. But, Lockwood said, the additional offers

appeared to include contingencies.


"We're not in the paper business," Lockwood said, referring to the bank's willingness to sell off the mill property. He said he is tentatively scheduled to be in Mechanicville Thursday and said the bank is "still open" to any offers from local concerns.

APPENDIX E

STRUCTURAL STABILITY ANALYSES

PROJECT GRID

JOB Loop 43	SHEET NO. 1	CHECKED BY	DATE
SUBJECT ST. ...		COMPUTED BY	DATE



AREA ①	$(9)(7)(\frac{1}{2}) = 76.5$	12'
	$\frac{1}{2}(\pi)(3.3)^2 = 8.3$	6.75'
	$+ (4.5)(17) = 76.5$	6.75'
	<u>84.8</u>	
AREA ②	$= 84.8$	6.75
AREA ③	$(17.5)(2.1) = 36.75$	3.35
AREA ④	$\frac{1}{2}(17)(2.3) = 19.55$	1.53

## PROJECT GRID

JOB	SHEET NO.	CHECKED BY	DATE
Lock No. 3	2		
SUBJECT	COMPUTED BY	DATE	
STABILITY ANALYSIS (cont.)	RLW	3/12/79	
RESOLVE FORCES ACTING ON MAIN SECTION DUE TO STEEL FRAMEWORK & CONCRETE KEY INTO ONE PASSIVE FORCE ACTING AT HEIGHT OF 12.5'			
1. DETERMINE APPROXIMATE WEIGHT FOR APRON			
FRAMEWORK MADE OF 2 ANGLES 3 1/2 X 3 1/2 X 1/2 ∴ 22 #/ft			
FRAMEWORK (117ft) (22 #/ft) = 2.57K			
TRANSVERSE BRACES			
(5 BRACES) (4 MISCELL. PLATE) (1ft) (11 #/ft + ANGLES) = .220K			
(5 BRACES) (13 #/ft OF PLATE) (1ft) = .068K			
.288K			
DETERMINE WEIGHT OF CONCRETE APRON			
(15' - 1.42ft) (23ft) (150 #/ft) = 4.90K			
SLIDING FORCE = (7.76) (.6) = 4.65K			
2. EFFECT OF KEY AT TOE (PASSIVE RESISTANCE)			
<p>11.5'      2.5' ←</p> <p>Limestone &amp; Dolostone <math>\phi = 55^\circ</math> <math>\gamma = 100 \text{ pcf}</math></p>			
$P_p = W \tan(\phi + \alpha) + \frac{SA}{\cos \alpha (1 - \tan \alpha \tan \phi)}$ $= (1.29K) (\tan 72.5) + \frac{(100)(39.12) \left( \frac{11.5^2}{17.5} \right)}{\cos 10 (1 - \tan 72.5)}$			
$P_p = 4.16K$			

## PROJECT GRID

JOB	SHEET NO.	CHECKED BY	DATE
Lock No 3	3		
SUBJECT	COMPUTED BY	DATE	
STABILITY ANALYSIS (CONT)	RLW	3/12/79	
3 EFFECT OF KEY AT TOE (SLIDING RESISTANCE)			
VOLUME OF BLOCK = $(8.5)(11.5)(1) = 63.25 \text{ ft}^3$			
$F_{\text{SLIDING}} = (63.25 \text{ ft}^3)(.15 \text{ K/ft}^3)(.6) = 5.69 \text{ K}$			
TOTAL FORCE TO BE ADDED AS A PASSIVE RESISTANCE			
$4.65 + 4.16 + 5.69 = 14.50 \text{ K}$			
$P_p = 17.61 \text{ K}$ THIS HAS TO BE MODELED AS A			
PASSIVE RESISTANCE ACTING AT POINT			
OF INTERSECTION OF MASONRY			
$P_p = \frac{1}{2} \gamma H^2 K_p \Rightarrow K_p = \frac{P_p}{\frac{1}{2} \gamma H^2} = \frac{14.50 \text{ K}}{\frac{1}{2} (.055)(37.5)^2} = .38$			
$\gamma = .055$ - ALREADY INPUT INTO PROGRAM			
$H = 37.5$ - TO GET RESULTANT TO ACT AT PROPER POINT			
$\therefore K_p = .38 \quad \gamma = .055 \quad H = 37.5$			

INPUT TO STABILITY ANALYSIS PROGRAM

<u>INPUT ENTRY</u>	<u>PROGRAM No.</u>
Unit Weight of Dam (K/ft <sup>3</sup> )	0
Area of Segment No. 1 (ft <sup>2</sup> )	1
Distance from Center of Gravity of Segment No. 1 to Downstream Toe (ft)	2
Area of Segment No. 2 (ft <sup>2</sup> )	3
Distance from Center of Gravity of Segment No. 2 to Downstream Toe (ft)	4
Area of Segment No. 3 (ft <sup>2</sup> )	5
Distance from Center of Gravity of Segment No. 3 to Downstream Toe (ft)	6
Base Width of Dam (Total) (ft)	7
Height of Dam (ft)	8
Ice Loading (K/L ft.)	9
Coefficient of Sliding	10
Unit Weight of Soil (K/ft <sup>3</sup> )	11
Active Soil Coefficient - Ka	12
Passive Soil Coefficient - Kp	13
Height of Water over Top of Dam or Spillway (ft)	14
Height of Soil for Active Pressure (ft)	15
Height of Soil for Passive Pressure (ft)	16
Height of Water in Tailrace Channel (ft)	17
Weight of Water (K/ft <sup>3</sup> )	18
Area of Segment No. 4 (ft <sup>2</sup> )	19
Distance from Center of Gravity of Segment No. 4 to Downstream Toe (ft)	20
Height of Ice Load or Active Water (ft)	46

November 24

Normal Conditions

Ice Load of  
5000 psf

0.15	RCL	0.15	RCL
	1		1
76.5		76.5	
76.5	RCL	76.5	RCL
	2		2
12.		12.	
12.	RCL	12.	RCL
	3		3
84.8		84.8	
84.8	RCL	84.8	RCL
	4		4
6.8		6.8	
6.8	RCL	6.8	RCL
	5		5
36.5		36.5	
36.5	RCL	36.5	RCL
	6		6
3.4		3.4	
3.4	RCL	3.4	RCL
	7		7
18.		18.	
18.	RCL	18.	RCL
	8		8
18.75		18.75	
18.75	RCL	18.75	RCL
	9		9
0.		5.	
0.	RCL	5.	RCL
	10		10
0.6		0.6	
0.6	RCL	0.6	RCL
	11		11
0.055		0.055	
0.055	RCL	0.055	RCL
	12		12
0.3		0.3	
0.3	RCL	0.3	RCL
	13		13
0.38		0.38	
0.38	RCL	0.38	RCL
	14		14
0.		0.	
0.	RCL	0.	RCL
	15		15
14.8		14.8	
14.8	RCL	14.8	RCL
	16		16
37.5		37.5	
37.5	RCL	37.5	RCL
	17		17
0.		0.	
0.	RCL	0.	RCL
	18		18
0.0624		0.0624	
0.0624	RCL	0.0624	RCL
	19		19
19.6		19.6	
19.6	RCL	19.6	RCL
	20		20
1.5		1.5	
1.5	RCL	1.5	RCL
	46		46
18.75		18.75	

2.11-081436 F.S. Overturning  
 10.28454868  
 2.18720134 F.S. Sliding

1.448057541  
 6.03822769  
 1.571983559

Largest Storm  
On Record

1/2 PMF

0.15	RCL	0.15	RCL
	1		1
76.5		76.5	
76.5	RCL	76.5	RCL
	2		2
12.		12.	
12.	RCL	12.	RCL
	3		3
84.8		84.8	
84.8	RCL	84.8	RCL
	4		4
6.8		6.8	
6.8	RCL	6.8	RCL
	5		5
36.5		36.5	
36.5	RCL	36.5	RCL
	6		6
3.4		3.4	
3.4	RCL	3.4	RCL
	7		7
18.		18.	
18.	RCL	18.	RCL
	8		8
18.75		18.75	
18.75	RCL	18.75	RCL
	9		9
0.		0.	
0.	RCL	0.	RCL
	10		10
0.6		0.6	
0.6	RCL	0.6	RCL
	11		11
0.055		0.055	
0.055	RCL	0.055	RCL
	12		12
0.3		0.3	
0.3	RCL	0.3	RCL
	13		13
0.38		0.38	
0.38	RCL	0.38	RCL
	14		14
15.3		21.2	
15.3	RCL	21.2	RCL
	15		15
14.8		14.8	
14.8	RCL	14.8	RCL
	16		16
37.5		37.5	
37.5	RCL	37.5	RCL
	17		17
23.		26.	
23.	RCL	26.	RCL
	18		18
0.0624		0.0624	
0.0624	RCL	0.0624	RCL
	19		19
19.6		19.6	
19.6	RCL	19.6	RCL
	20		20
1.5		1.5	
1.5	RCL	1.5	RCL
	46		46
18.75		18.75	

F.S.-Overturning  
F.S.-Sliding

1.009392542  
9.080790665  
1.028220488

.9203042241  
12.01332223  
.8815699513

136250

75

81

80

78

76

74

72

70

91 km

1105

REC

80

78

76

74

72

70

68

NOVEMBER 22

APPENDIX F

REFERENCES

HUDSON

1976

1978

80

78


76

74

72

70

68



REFERENCES

- 1) US Army Corps of Engineers; New York District; Upper Hudson and Mohawk River Basins Hydrologic Flood Routing Models, October 1976.
- 2) US Geological Survey; Compilation of Records of Surface Waters of the United States, Part 1-B North Atlantic Slope Basins;  
Water Supply Paper 1302 (Through September 1950), 1960.  
Water Supply Paper 1722 (October 1950 to September 1960), 1964.
- 3) H.W. King and E.F. Brater; Handbook of Hydraulics, 5th edition, McGraw - Hill, 1963.
- 4) E.E. Seelye; Design, 3rd edition, John Wiley and Sons, Inc., 1960.
- 5) University of the State of New York; Geology of New York, Education Leaflet 20, Reprinted 1973.
- 6) U.S. Department of the Interior, Bureau of Reclamation; Design of Small Dams, 2nd edition (rev. reprint), 1977.

1245577

1918

09

85

25


15

35

55

40

20



A/

APPENDIX G  
CORPS OF ENGINEERS  
GUIDELINES

Reclamation and Soil Conservation Service. Many other agencies, educational facilities and private consultants can also provide expert advice. Regardless of where such expertise is based, the qualification of those individuals offering to provide it should be carefully examined and evaluated.

4.3.4. Freeboard Allowances. Guidelines on specific minimum freeboard allowances are not considered appropriate because of the many factors involved in such determinations. The investigator will have to assess the critical parameters for each project and develop its minimum requirement. Many projects are reasonably safe without freeboard allowance because they are designed for overtopping, or other factors minimize possible overtopping. Conversely, freeboard allowances of several feet may be necessary to provide a safe condition. Parameters that should be considered include the duration of high water levels in the reservoir during the design flood; the effective wind fetch and reservoir depth available to support wave generation; the probability of high wind speed occurring from a critical direction; the potential wave runup on the dam based on roughness and slope; and the ability of the dam to resist erosion from overtopping waves.

4.4. Stability Investigations. The Phase II stability investigations should be compatible with the guidelines of this paragraph.

4.4.1. Foundation and Material Investigations. The scope of the foundation and materials investigation should be limited to obtaining the information required to analyze the structural stability and to investigate any suspected condition which would adversely affect the safety of the dam. Such investigations may include borings to obtain concrete, embankment, soil foundation, and bedrock samples; testing specimens from these samples to determine the strength and elastic parameters of the materials, including the soft seams, joints, fault gouge and expansive clays or other critical materials in the foundation; determining the character of the bedrock including joints, bedding planes, fractures, faults, voids and caverns, and other geological irregularities; and installing instruments for determining movements, strains, suspected excessive internal seepage pressures, seepage gradients and uplift forces. Special investigations may be necessary where suspect rock types such as limestone, gypsum, salt, basalt, claystone, shales or others are involved in foundations or abutments in order to determine the extent of cavities, piping or other deficiencies in the rock foundation. A concrete core drilling program should be undertaken only when the existence of significant structural cracks is suspected or the general qualitative condition of the concrete is in doubt. The tests of materials will be necessary only where such data are lacking or are outdated.

4.4.2. Stability Assessment. Stability assessments should utilize in situ properties of the structure and its foundation and pertinent geologic

information. Geologic information that should be considered includes groundwater and seepage conditions; lithology, stratigraphy, and geologic details disclosed by borings, "as-built" records, and geologic interpretation; maximum past overburden at site as deduced from geologic evidence; bedding, folding and faulting; joints and joint systems; weathering; slickensides, and field evidence relating to slides, faults, movements and earthquake activity. Foundations may present problems where they contain adversely oriented joints, slickensides or fissured material, faults, seams of soft materials, or weak layers. Such defects and excess pore water pressures may contribute to instability. Special tests may be necessary to determine physical properties of particular materials. The results of stability analyses afford a means of evaluating the structure's existing resistance to failure and also the effects of any proposed modifications. Results of stability analyses should be reviewed for compatibility with performance experience when possible.

4.4.2.1. Seismic Stability. The inertial forces for use in the conventional equivalent static force method of analysis should be obtained by multiplying the weight by the seismic coefficient and should be applied as a horizontal force at the center of gravity of the section or element. The seismic coefficients suggested for use with such analyses are listed in Figures 1 through 4. Seismic stability investigations for all high hazard category dams located in Seismic Zone 4 and high hazard dams of the hydraulic fill type in Zone 3 should include suitable dynamic procedures and analyses. Dynamic analyses for other dams and higher seismic coefficients are appropriate if in the judgment of the investigating engineer they are warranted because of proximity to active faults or other reasons. Seismic stability investigations should utilize "state-of-the-art" procedures involving seismological and geological studies to establish earthquake parameters for use in dynamic stability analyses and, where appropriate, the dynamic testing of materials. Stability analyses may be based upon either time-history or response spectra techniques. The results of dynamic analyses should be assessed on the basis of whether or not the dam would have sufficient residual integrity to retain the reservoir during and after the greatest or most adverse earthquake which might occur near the project location.

4.4.2.2. Clay Shale Foundation. Clay shale is a highly overconsolidated sedimentary rock comprised predominantly of clay minerals, with little or no cementation. Foundations of clay shales require special measures in stability investigations. Clay shales, particularly those containing montmorillonite, may be highly susceptible to expansion and consequent loss of strength upon unloading. The shear strength and the resistance to deformation of clay shales may be quite low and high pore water pressures may develop under increase in load. The presence of slickensides in clay shales is usually an indication of low shear strength. Prediction

of field behavior of clay shales should not be based solely on results of conventional laboratory tests since they may be misleading. The use of peak shear strengths for clay shales in stability analyses may be unconservative because of nonuniform stress distribution and possible progressive failures. Thus the available shear resistance may be less than if the peak shear strength were mobilized simultaneously along the entire failure surface. In such cases, either greater safety factors or residual shear strength should be used.

#### 4.4.3. Embankment Dams.

4.4.3.1. Liquefaction. The phenomenon of liquefaction of loose, saturated sands and silts may occur when such materials are subjected to shear deformation or earthquake shocks. The possibility of liquefaction must presently be evaluated on the basis of empirical knowledge supplemented by special laboratory tests and engineering judgment. The possibility of liquefaction in sands diminishes as the relative density increases above approximately 70 percent. Hydraulic fill dams in Seismic Zones 3 and 4 should receive particular attention since such dams are susceptible to liquefaction under earthquake shocks.

4.4.3.2. Shear Failure. Shear failure is one in which a portion of an embankment or of an embankment and foundation moves by sliding or rotating relative to the remainder of the mass. It is conventionally represented as occurring along a surface and is so assumed in stability analyses, although shearing may occur in a zone of substantial thickness. The circular arc or the sliding wedge method of analyzing stability, as pertinent, should be used. The circular arc method is generally applicable to essentially homogeneous embankments and to soil foundations consisting of thick deposits of fine-grained soil containing no layers significantly weaker than other strata in the foundation. The wedge method is generally applicable to rockfill dams and to earth dams on foundations containing weak layers. Other methods of analysis such as those employing complex shear surfaces may be appropriate depending on the soil and rock in the dam and foundation. Such methods should be in reputable usage in the engineering profession.

4.4.3.3. Loading Conditions. The loading conditions for which the embankment structures should be investigated are (I) Sudden drawdown from spillway crest elevation or top of gates, (II) Partial pool, (III) Steady state seepage from spillway crest elevation or top of gate elevation, and (IV) Earthquake. Cases I and II apply to upstream slopes only; Case III applies to downstream slopes; and Case IV applies to both upstream and downstream slopes. A summary of suggested strengths and safety factors are shown in Table 4.

4.4.3.6. Seepage Analyses. Review and modifications to original seepage design analyses should consider conditions observed in the field inspection and piezometer instrumentation. A seepage analysis should consider the permeability ratios resulting from natural deposition and from compaction placement of materials with appropriate variation between horizontal and vertical permeability. An underseepage analysis of the embankment should provide a critical gradient factor of safety for the maximum head condition of not less than 1.5 in the area downstream of the embankment.

$$F.S = i_c/i = \frac{H_c/D_b}{H/D_b} = D_b \frac{(\gamma_m - \gamma_w)}{H \gamma_w} \quad (2)$$

$i_c$  = Critical gradient

$i$  = Design gradient

$H$  = Uplift head at downstream toe of dam measured above tailwater

$H_c$  = The critical uplift

$D_b$  = The thickness of the top impervious blanket at the downstream toe of the dam

$\gamma_m$  = The estimated saturated unit weight of the material in the top impervious blanket

$\gamma_w$  = The unit weight of water

Where a factor of safety less than 1.5 is obtained the provision of an underseepage control system is indicated. The factor of safety of 1.5 is a recommended minimum and may be adjusted by the responsible engineer based on the competence of the engineering data.

#### 4.4.4. Concrete Dams and Appurtenant Structures.

4.4.4.1. Requirements for Stability. Concrete dams and structures appurtenant to embankment dams should be capable of resisting overturning, sliding and overstressing with adequate factors of safety for normal and maximum loading conditions.

4.4.4.2. Loads. Loadings to be considered in stability analyses include the water load on the upstream face of the dam; the weight of the structure; internal hydrostatic pressures (uplift) within the body of the dam, at the base of the dam and within the foundation; earth and silt loads; ice pressure, seismic and thermal loads, and other loads as applicable. Where tailwater or backwater exists on the downstream side of the structure it should be considered, and assumed uplift pressures should be compatible with drainage provisions and uplift measurements if available. Where applicable, ice pressure should be applied to the contact surface of the structure at normal pool elevation. A unit pressure of not more than 5,000 pounds per square foot should be used. Normally, ice thickness should not be assumed greater than two feet. Earthquake forces should consist of the inertial forces due to the horizontal acceleration of the dam itself and hydrodynamic forces resulting from the reaction of the reservoir water against the structure. Dynamic water pressures for use in conventional methods of analysis may be computed by means of the "Westergaard Formula" using the parabolic approximation (H.M. Westergaard, "Water Pressures on Dams During Earthquakes," Trans., ASCE, Vol 98, 1933, pages 418-433), or similar method.

4.4.4.3. Stresses. The analysis of concrete stresses should be based on in situ properties of the concrete and foundation. Computed maximum compressive stresses for normal operating conditions in the order of 1/3 or less of in situ strengths should be satisfactory. Tensile stresses in unreinforced concrete should be acceptable only in locations where cracks will not adversely affect the overall performance and stability of the structure. Foundation stresses should be such as to provide adequate safety against failure of the foundation material under all loading conditions.

4.4.4.4. Overturning. A gravity structure should be capable of resisting all overturning forces. It can be considered safe against overturning if the resultant of all combinations of horizontal and vertical forces, excluding earthquake forces, acting above any horizontal plane through the structure or at its base is located within the middle third of the section. When earthquake is included the resultant should fall within the limits of the plane or base, and foundation pressures must be acceptable. When these requirements for location of the resultant are not satisfied the investigating engineer should assess the importance to stability of the deviations.

4.4.4.5. Sliding. Sliding of concrete gravity structures and of abutment and foundation rock masses for all types of concrete dams should be evaluated by the shear-friction resistance concept. The available sliding resistance is compared with the driving force which tends to induce sliding to arrive at a sliding stability safety factor. The investigation should be made along all potential sliding paths. The critical path is that plane or combination of planes which offers the least resistance.

4.4.4.5.1. Sliding Resistance. Sliding resistance is a function of the unit shearing strength at no normal load (cohesion) and the angle of friction on a potential failure surface. It is determined by computing the maximum horizontal driving force which could be resisted along the sliding path under investigation. The following general formula is obtained from the principles of statics and may be derived by resolving forces parallel and perpendicular to the sliding plane:

$$R_R = V \tan (\phi + \alpha) + \frac{cA}{\cos \alpha (1 - \tan \phi \tan \alpha)} \quad (3)$$

where

$R_R$  = Sliding Resistance (maximum horizontal driving force which can be resisted by the critical path)

$\phi$  = Angle of internal friction of foundation material or, where applicable, angle of sliding friction

$V$  = Summation of vertical forces (including uplift)

$c$  = Unit shearing strength at zero normal loading along potential failure plane

$A$  = Area of potential failure plane developing unit shear strength "c"

$\alpha$  = Angle between inclined plane and horizontal (positive for uphill sliding)

For sliding downhill the angle  $\alpha$  is negative and Equation (1) becomes:

$$R_R = V \tan (\phi - \alpha) + \frac{cA}{\cos \alpha (1 + \tan \phi \tan \alpha)} \quad (4)$$

When the plane of investigation is horizontal, and the angle  $\alpha$  is zero and Equation (1) reduced to the following:

$$R_R = V \tan \phi + cA \quad (5)$$

4.4.4.5.2. Downstream Resistance. When the base of a concrete structure is embedded in rock or the potential failure plane lies below the base, the passive resistance of the downstream layer of rock may sometimes be utilized for sliding resistance. Rock that may be subjected to high velocity water scouring should not be used. The magnitude of the downstream resistance is the lesser of (a) the shearing resistance along the continuation of the potential sliding plane until it daylights or (b) the resistance available from the downstream rock wedge along an inclined plane. The theoretical resistance offered by the passive wedge can be computed by a formula equivalent to formula (3):

$$P_p = W \tan (\delta + \alpha) + \frac{cA}{\cos \alpha (1 - \tan \delta \tan \alpha)} \quad (6)$$

$P_p$  = passive resistance of rock wedge

$W$  = weight (buoyant weight if applicable) of downstream rock wedge above inclined plane of resistance, plus any superimposed loads

$\delta$  = angle of internal friction or, if applicable, angle of sliding friction

$\alpha$  = angle between inclined failure plane and horizontal

$c$  = unit shearing strength at zero normal load along failure plane

$A$  = area of inclined plane of resistance

When considering cross-bed shear through a relatively shallow, competent rock strut, without adverse jointing or faulting,  $W$  and  $\alpha$  may be taken at zero and  $45^\circ$ , respectively, and an estimate of passive wedge resistance per unit width obtained by the following equation:

$$P_p = 2 cD \quad (7)$$

where

$D$  = Thickness of the rock strut

4.4.4.5.3. Safety Factor. The shear-friction safety factor is obtained by dividing the resistance  $R_R$  by  $H$ , the summation of horizontal service

loads to be applied to the structure:

$$S_{s-f} = \frac{R_R}{H} \quad (8)$$


When the downstream passive wedge contributes to the sliding resistance, the shear friction safety factor formula becomes:

$$S_{s-f} = \frac{R_R + P_D}{H} \quad (9)$$

The above direct superimposition of passive wedge resistance is valid only if shearing rigidities of the foundation components are similar. Also, the compressive strength and buckling resistance of the downstream rock layer must be sufficient to develop the wedge resistance. For example, a foundation with closely spaced, near horizontal, relatively weak seams might not contain sufficient buckling strength to develop the magnitude of wedge resistance computed from the cross-bed shear strength. In this case wedge resistance should not be assumed without resorting to special treatment (such as installing foundation anchors). Computed sliding safety factors approximating 3 or more for all loading conditions without earthquake, and 1.5 including earthquake, should indicate satisfactory stability, depending upon the reliability of the strength parameters used in the analyses. In some cases when the results of comprehensive foundation studies are available, smaller safety factors may be acceptable. The selection of shear strength parameters should be fully substantiated. The bases for any assumptions; the results of applicable testing, studies and investigations; and all pre-existing, pertinent data should be reported and evaluated.

APPENDIX H

DRAWINGS




DAM SITE

VICINITY MAP

LOCK 3 DAM @ MECHANICVILLE

LOCK 3 DAM @ MECHANICVILLE




DATUM:

NYS-DOT BARGE CANAL DATUM (BCD)

USGS

$$1.18 \text{ BCD} = 0.00$$

LOCK 3 DAM @  
MECHANICVILLE  
[FIELD MEASUREMENTS - 10/78]




(In the space below, make one sketch showing the form and dimensions of a cross section through the spillway or waste-weir of this dam, and a second sketch showing the same information for a cross section through the other portion of the dam. Show particularly the greatest height of the dam above the stream bed, its thickness at the top, and thickness at the bottom, as nearly as you can learn.)


LOCK 3 DAM @ MECHANICVILLE, N.Y.

6/24/16

### Spillway Section



M65-6



Location: The project is located at Lock 3-C on the Hudson River Mechanicville, N.Y. East of the West Virginia Paper Co.


ESTIMATE OF QUANTITIES			
NO.	ITEM	UNIT	NO.
60A	Concrete Cylinder Curing Box	Ea.	
65X	Engineers Office, Type A	L.S.	
13AX	3" Steel Conduit	L.F.	
18	Class A Concrete for Structures	C.Y.	
25F	Steel Fabric Reinforcement	S.Y.	
28X	Bar Reinforcement for Structures	Lb.	
81AX	Removing Existing Superstructure	Lb.	
201X	Chipping and Removing Conc. and Stone Masonry	C.Y.	
202	Drilling Holes	L.F.	
208	Precast Concrete Slab	S.F.	

Engineer Dist No 1

2

STATE OF  
 DEPARTMENT OF  
 CHAPTER 542 LAW  
 CONTRACT  
 FOR M 65  
 REHABILITATION OF DAM  
 CHAMPLAIN C.  
 AT  
 MECHANICVILL  
 SARATOGA AND RENSSELA  
 NEW YORK  
 SCALES AS IND  
 SHEETS I TO

ITIES	
NEAT	PROPOSAL
	1
	NEG. 275
	410
	520
	11,700
	NEG. 180
	1500
	15,750



AD-A074 715


NEW YORK STATE DEPT OF ENVIRONMENTAL CONSERVATION ALBANY F/G 13/2  
NATIONAL DAM SAFETY PROGRAM. LOCK 3 DAM AT MECHANICVILLE (INVEN--ETC(U)  
JUN 79 G KOCH

DACW51-79-C-0001

UNCLASSIFIED

NL

2 OF 2  
AD  
A074715




END  
DATE  
FILMED  
10-79  
DDC

2 OF 2

AD.

A074715



NEW  
PUBLI  
S OF  
-6  
A  
ANAI  
E  
AER  
GATE  
4 IN


sting We  
Apr

NEW YORK  
PUBLIC WORKS  
OF 1939

-6  
AT LOCK 3  
CANAL

E  
AER COUNTIES

ICATED  
4 INC.



4 M65-6



H E


31°26'46.6" W  
162.48'

-93.07


I I

DATUM: The elevations shown on this contract are referred to Barge Canal Datum. This datum is based on the Greenbush Bench Mark whose established elevation referred to Barge Canal Datum is 14.730 feet.





S  
T  
I  
L  
L  
W  
A  
T



Fore  
Bay

West Virginia  
Pulp and Paper Co.

10/20/65

N  
O  
S  
O  
N  
H  
U  
D  
S  
O  
N

Saratoga County  
Rensselaer County

U  
S  
A  
S  
E  
S



Department of Public Works, Jan. 2, 1962,  
except as modified by special specifications.

BENCH MARK - 3C Elev 74.40  
Brass Plug - S.E. Thrust Block

### MAINTENANCE TABLE

STRUCTURE	OWNER	MAINTAINED BY	JURISDICTION
Flashboard Structure	West Virginia Pulp & Paper Co.	West Virginia Pulp & Paper Co	By Agreement
Dam at Lock 3C	State of New York	Canals	By Appropriation


1

8

M65-6

S  
C  
H  
A  
G  
H

1




2

Note: Upper Pool Elevation 67.5 Requires  
N.Y.S. Barge Canal System for Maintenance  
30" Flashboards Maintained by  
Pulp & Paper Company.

of flashboards  
maintained by  
Pulp & Paper Co.

Crest Elev. 67.5'




2-A


Upper Pool Elevation 67.5 Required by  
N.Y.S. Barge Canal System for Navigation.

30" Flashboards Maintained by West Virginia  
Pulp & Paper Company.


ing

and under-  
system 81AX






MADE BY Robert Hinder DATED SEPT. '63  
CHECKED BY Robert Hood DATED October 1963  
TRACED BY Robert Hood DATED October 1963  
CHECKED BY Robert Hinder DATED SEPT. '63



18'-0"


Cross Section Showing  
Wooden Apron & Wrought  
At Lock 3-C Existing  
Scale  $\frac{1}{8}$ " = 1'-0"

4 1




Cross Section Showing  
Wooden Apron & Wrought  
At Lock 3-C Existing  
Scale  $\frac{1}{8}'' = 1'-0''$

4 1



5



Tidegater Normal 420

2

6

In accordance with an  
 the West Virginia Pulp and  
 to flash boards are

1/2" x 2" precast joint  
 filler as described on right

Top Of Flashboards

N.I.C

2" Saw Cut  
 ELEV 475

ITEM 201X


Top Of Crest

Note: D  
 period u  
 tained a

Downstream Side

NOTE:  
 BAR R  
 SEEPAGE  
 SEPARATE

ITEM 18



SECTION VIEW OF CREST

SHOWING OLD AND NEW SECTIONS

SCALE 3/4" = 1'

in understanding with  
 and Paper Co. struts  
 not to be replaced


2

During construction  
 upper pool will be main-  
 at E. 67.5"

REINFORCEMENT &  
 PIPE SHOWN ON  
 DATE SECTION BELOW


1/2" precast joint filler  
 conforming to M 36, M 36 B or  
 M 36 C. Cost to be included  
 in price bid for Item  
 515.

PRECAST CONCL. SLAB  
 ITEM 203



NEW CREST  
 SCALE 3/4"

3



ALL BARS & STIRRUPS ITEM 205 & 4  
 LONGITUDINAL BARS ALL 21'-6"  
 LONG. BEGIN STIRRUPS 1' FROM  
 LOWER END OF PRECAST SLAB. #6

CONSTRUCTION NOTE:

THE NEW CREST GRADE SHALL BE SO PLACED  
 AS TO MEET THE GRADE OF THE PRECAST  
 CONCRETE SLABS, A.C.E.E.  
 PRECAST SLABS SHALL BE PLACED BEFORE THE  
 CREST CONCRETE IS PLACED.

CREST PROFILE


SCALE 3/4" = 1'

LOCATE THIS STIRRUP  
 6" FROM END

4

M65-6


REINFORCING BARS & STIRRUPS ITEM 203 #4  
LONGITUDINAL BARS ALL 2'-6"  
BEGIN STIRRUPS 1' FROM  
END OF PRECAST SLAB.



PLACED  
BEFORE THE  
PRECAST

SECTION A-A  
SHOWING BAR REINFORCEMENT  
SCALE 1"=1'

INSTALL THIS STIRRUP  
1" FROM END




CONSTRUCTION NOTE:

THE 3" STEEL SEEPAGE ELECTRICAL CONDUIT SHALL BE INSTALLED SO THAT IT WILL NOT BE DISLOCATED, OR DRAIN HOLES BECOME PLUGGED DURING CONCRETE PLACEMENT. 3" DRAIN HOLES SHALL BE FIELD LOCATED TO COINCIDE WITH MASONRY JOINT SEEPAGE PLAINS.

DRILLING HOLES -  
ITEM 202

ITEM 13AX  
3" STEEL CONDUIT  
12' C.C.

3" DIA. FIELD CUTS



SECTION VIEW OF CREST  
SHOWING CREST POUR, REINFORCE  
SCALE 3/4" = 1'

MADE BY ROBERT KIRNER DATE NOV 14  
CHECKED BY Robert Kirner DATE NOV 14  
TRACED BY ROBERT KIRNER DATE NOV 14  
CHECKED BY Robert Kirner DATE NOV 14

5

ITEM 28X  
BAR REINFORCEMENT FOR STRUCTURES,  
ALL BARS # 6 , 18" CC.

ITEM 25F  
STEEL FABRIC REINFORCEMENT  
6' LONG



CREST  
REINFORCEMENT, PIPE.

*Note: Joints in new crest  
concrete shall meet joints in ex-  
isting crest concrete or  
shall be placed A. O. B. E.*

32' 6"




178 6

NOTE:

SEE SHEET # 4 FOR PLAN VIEW OF PRECAST  
SLABS, SHOWING NON-TYPICAL PRECAST SLAB  
SECTIONS AT W.V.P.P. CO WALL AND APPROX  
CONCRETE POUR AT LOCK WALL.

*Precast concrete slabs are to be  
set in place as close to each other  
as possible*

BAR REINFORCEMENT NOT SHOWN  
SEE SECTIONS A-A, B-B




TYPICAL DAM CROSS SECTION

SHOW WROUGHT IRON BENT  
WITH CONC. SLAB  
1/2\"/>

7

SECTION B-B  
END STIRRUP  
SCALE 1"=1'




ALL BARS #6  
2' LONG  
ITEM 201, DRILLING  
HOLES, ITEM 202

AL KEYWAY AS SHOWN  
ON SHEET # 4


CREST DOWELLING DETAIL AT LOCK & W.V.P.CO. WALLS  
KEYWAY AT CONST. JOINTS  
SCALE 1/4"=1'

8  
3



PLAN OF NEW SECTION  
OF CONCRETE TAILRAGE  
SCALE 1/4" = 1'-0"

2





SECTION (B)-  
TAILRACE KEYWAY  
Scale: 1/2" = 1'-0"

CONSTRUCTION NOTE:  
KEYWAYS TO BE USED ONLY IF CONCRETE  
IS TO BE PLACED IN TWO STAGES.

C6

3




②-②  
KEYWAYS  
= 1'-0"

SEC  
TAILRACE DOWEL  
Scale


CONSTRUCTION

NOTE:  
TWO PRECAST CONCRETE SECTIONS WILL BE PLACED IN THIS AREA WITH CONCRETE CROSS-SECTION AND REINFORCING STEEL SIMILAR TO SECTION A-A, SHEET #3. LENGTH AND WIDTH TO BE MEASURED IN FIELD AND SLAB BEVELED AT UPSTREAM END TO FIT AGAINST W.V.R.P. CO. WALL



4


M 5.6




SECTION ©-©

TAILRACE DOWELING DETAIL AT W.V.P&P CO. WALL

Scale: 1/2" = 1'-0"




5



SECTION A-A  
NEW CONCRETE TAILRACE  
Scale: 1/2" = 1'-0"

MADE BY ROBERT KIRKES DATED Nov. 64  
CHECKED BY Robert Hood DATED Nov. 1964  
TRACED BY ROBERT KIRKES DATED Nov. 64  
CHECKED BY Robert Hood DATED Nov. 1964

6





SECTION (A)-(A)  
CONCRETE TAILRACE  
Scale: 1/2" = 1'-0"

7


TYPICAL KEYWAY

Scale: 1" = 1'-0"



SECTION (D)-(D)  
NEW CONCRETE TAILRACE  
SHOWING OPENINGS  
AND  
JOINT DETAILS  
SCALE 1/2" = 1'

W.V.P.P. Co. Wall



PLAN OF DAM SHOWING IRREGULARITIES OF APRON  
SCALE:  $\frac{1}{8}'' = 1'-0''$

CONST JOINT KEYWAY  
SEE ABOVE NOTE

CONSTRUCTION NOTE:

AT EAST END OF DAM CONCRETE WILL BE PLACED D.O.B.E. TO COMPLETE APRON. THE CONCRETE SHALL BE ITEM 10 AND RE. BARS SHALL CONFORM TO ITEM 201. PAYMENT WILL BE MADE UNDER THESE RESPECTIVE ITEMS.



10" VOIDS CAST IN PLACE

SECTION ②-③  
TYPICAL SECTION - POURED IN PLACE  
SCALE  $\frac{1}{4}'' = 1'$

VERTICAL EVAPORATOR BUILDING

ZARD

45'-0"

22'-3"

RECLAIMED BUILDING

44'-0"

4'-0"

7'-0"

3'-0"

CATERING

SODA SCREEN ROOM

N SODA WHEEL FLUME

9'-0"

9'-7"

32'-0"

WARD WALL ABOVE

MSB EVAPORATOR BLDG

N74°E

74'-0"

2

ALKALI BUILDING

101'-0"

9'-10"

6'-9"

3'-11"

CANAL WALL

Now Goes  
To River

N74°E

WHARF LINE

437'-0"

2°-22'

3

5'-10"

RECLAIMER BUILDING


149'-3"

SPILLWAY

WAT



5



6

BEATER ROOM

So

SOUTH BEATER AND NORTH BEATER LINE WHEEL FLUMES

FILTER PUMP  
INTAKE

"HIGH LINE"

138-6"

5-9"  
5-11"

SMALL HOLE

7

SULPHITE MILL

11" Concrete Reinforcement

SULPHITE WHEEL FLUME

S. SODA WHEEL FLUME

"HIGHLINE" WHEEL FLUME

24'-0"

8'-0"

8'-0"

28'-3"

12'-0"

5'-0"

79'-11"

422

SODA SCREEN RM.

8

N. SODA WIND  
FLUME

SODA MACHINE ROOM


112'-5"

32'-0"

Gate House

WEST VIRGINIA PULP & PAPER CO.  
 MECHANICVILLE, N.Y.  
 PLAN OF HYDRAULIC CANAL  
 SHOWING  
 ADJACENT BUILDING WALLS  
 SHEET NO. 1

House



*All measurements across power canal  
are from top of mark*

WEST VIRGINIA PULP & PAPER CO.  
MECHANICKVILLE, N.Y.  
PLAN OF HYDRAULIC CANAL  
SHOWING  
ADJACENT BUILDING WALLS  
SHEET NO. 1

Scale 1" = 12"

Date MAY 25, 1925

Drawn by WS



No. M 5278

9


1

CUTTER BUILDING


CALENDER BUILDING



201'-6"



2



3

Nos. 1 & 2 PAPER MACHINE BUILDING

507

586 BEATERS

5-11-

14 PAGE

4

BEATER ROOM

24'-0"

9'-4"

28'


11'-6"

55'-4"

BEATER & JORDAN HILL FLORES

38'-6"

603'-6" TO GATE HOUSE



5

FINISHING BUILDING

FIRE PUMP

MANHOLES

Electric

ELECTRIC PLANT

46'-9"

113'-11"

#16

#15

#14

#12

HYDRO-ELECTRIC PLANT

6

CUTTER BUILDING

CALC

CONCRETE

STONE

2'-9"

35'-0"


203'-0"

48'-1"

29'-5"

CONCRETE  
210" x 210"

CONCRETE  
210" x 210"



7

CALENDER BUILDING



D.C. POWER & LIGHT WHEEL FLUMES

57'-5"

43'-8"

CANAL WALL

207  
E.M.

Hook G102  
PAPER NO. 74

8

Floor Alkali Bldg.  
Elev. 92.60

Floor Reclamer Bldg.  
Elev. 90.80

201'-6"

Elev 72.00  
Approx

Bottom 24" in 10 ft.

Walls between  
Gate House and  
S. Soda Wheel Flume  
have this batter

Bottom 18" in 10 ft.

Walls at S Soda Wheel  
Flume and beyond  
have this batter.

SECTION AT  
ALKALI BUILDING.

SECTION AT  
CALENDER BUILDING

Bottom of Canal  
Elev 53.00

### MILL FOUNDATION WALLS

For Section of Canal that see  
Eng. M 2203

WEST VIRGINIA

PLANNING



*Calender Room  
Basement.*


*Wells at S Soda Wheel  
Flume and beyond  
are this better.*

**SECTION AT  
CALENDER BUILDING**

**WEST VIRGINIA PULP & PAPER  
MANUFACTURING CO.  
PLAN OF HYDRAULIC  
SYSTEM**

1

6'-6"



3" BOLTS, COUNTER-8 JOINT HEADS, SPACED ABOUT 14"


EL 78.30

3" 4, 15'-0" LONG

10" x 10" FRAME BOLTED INTO CONCRETE


2

W




5' 9 1/2"

5' 9 1/2"



3

FOR LOCATION OF ANCHOR BOLTS FOR GATE  
RIG. SEE LEVEL DRAWING NO. 13913.



4

78.50

24" 100" I SUPPORTING  
GATE AT CENTER OF OPENING.


24" 100" I


6" x 8"

GATE  
9 1/2" x 10"  
1/2" PLATE

FACE OF WALL

1/2" x 10" -  
SCREW





12'-0" OPENING

EL 57.50


16'

4'-7.25" EL, 15'-0" LEAVE

18'x24" GATE

LET THE TOP OF THE FRAME COME TO WITHIN 2" OF THE TOP OF THE GRAVE

OPENING



21

2 1/2" BOLTS  
(ON EACH PLANK)

13'6"

8"

5 1/2"

8'0" - 12'0" LONG

3" BOLTS

24" - 100" I (AT CENTER OF OPENING) 15'0" LONG

7" ANCHOR BOLTS SPACED  
ABOUT 3'-3"

12'-0"

13'-0"

16"

EL 57.50

LONG EL 58.60

DETAIL

7

GATE OPEN

6'6"

ING 13'0"

GATES 12'-11" WIDE

13'-8"

16"

DETAILS OF HEAD GATES - HYDRO-ELECTRIC PLANT.

WEST VIRGINIA PULP & PAPER CO.


SCALE  $\frac{1}{2}$ " = 14'-0"

MECHANICVILLE, N.Y.


Nov. 16, 1911

8


1




W



2




6'- 2'-4" 3'-6"




A

PLAN

3






SECTION A-A

10'-9"

67



ELEVATI

6

7

WEST VIRGINIA PULP & PAPER CO.  
MECHANICVILLE, N. Y.

SLUICE GATE  
SOUTH END OF FOREBAY

Scale  $\frac{1}{8}$ " = 1 FT.

Date June 18, 1909

Drawn by AFW

No M-426

1

Property Line




NORTH MAIN ST.

Property Line

Ground Elev. 680

Alcohol

WE




2

E. B. & M. R.R.


Property Line

Gauge	WATER SURFACE		A
	5 YEAR PERI		
	Maximum High water	Mean High Water	
A	58.38	57.86	
B	59.50	58.75	
C	76.00	75.75	
D	76.49	76.29	



3

Gauge	5 YEAR PERIOD TO DATE				Highest Water Recorded March 28 1913
	Maximum High water	Mean High Water	Minimum High Water	Lowest Water Recorded	
A	58.38	57.86	57.50	49.00	67.50
B	59.50	58.75	58.00	49.00	68.20
C	76.00	75.75	75.50	65.00	76.00
D	76.49	76.29	76.02	66.91	82.58




H

PLANT  
Ground Elev 62.5



Ground Elev 68.5

H U D S O N



Gauge C. Well  
Gauge B  
Well Elev. = 88.5

HILLS R. CO.

FORE BAY  
Wall Elev. 70.7

NORTH MAIN ST.


Spillway

Gate House Well Elev. = 84.5  
Gauge B

RIVER

Dam. Elev. of Top = 70.7

LOCK  
Lock 5



6

WEST VIRGINIA PULP & PAPER CO.  
 MECHANICVILLE, N. Y.

---

*Dear Sirs:*

---

*Enclosed are...*

---


*Very truly yours,*

---

*W. J. ...*

1


150'-0"



Elev. 70.91 - Top of Dam


ELEVATION OF

2



GATE HOUSE.

SECTION OF CANAL WALL NEAR GATE HOUSE.



3

GATE HOUSE

Elev 80.85


Elev 79.79

Elev 75.94


Elev 74.84

Elev 73.21


70.91



4



SECTION OF CANAL WALL AT A-A.



SECTION OF CANAL WALL AT 5-5

6

SECTION OF CANAL WALL AT

WEST VIRGINIA PULP & PAPER CO.  
MECHANICVILLE, W. V.

HYDRAULIC CANAL WALL  
AND SPILLWAY

Scale  $\frac{1}{2}'' = 1'$  &  $\frac{1}{4}'' = 1'$  Date, March 1944

Drawn by [Signature] No. 10

Rev. July 28, 1944

WALL AT

1

101-0

12342

2

1228

1270

Alcohol

RECEIVED

3

149'-3"

PLAN


3

3A

11 OPENINGS  
5'-0" x 10'-0"

5'-0"

GATE HOUSE



GATE HOUSE

4



14-10

5

CONCRETE WALL


6'-0"

A

6

6-9"

7-10"



7

M i

50'-0"  
MILLWAY

HUDSON RIVER  
— DW

10

8

OPENING  
4'-0" x 12'-0"

20'-0"



WEST VIRGINIA PULP  
MECHANICAL  
PLAN - FORE  
NORTH END  
HYDRO ELECTRIC  
POWER

FOR SECT. A-A & B-B SEE DWG. # M-5597

Scale 1/8" = 1'-0"

8 8

OPENING  
4'-0" X 12'-0"

20'-0"

9

WEST VIRGINIA PULP & PAPER CO.  
MECHANICALS, N.Y.  
PLAN - FOREBAY  
NORTH END  
HYDRO-ELECTRIC  
POWER

A-B SEE DWG. # M-5597

Scale 1/4" = 1'-0"  
Date May 1918  
Drawing Dept. M-5597