

AD-A075 891


NEW YORK STATE DEPT OF ENVIRONMENTAL CONSERVATION ALBANY F/G 13/2
NATIONAL DAM SAFETY PROGRAM DASHVILLE DAM, INVENTORY NUMBER (NY--ETC(U)
SEP 79 6 KOCH DACW51-79-C-0001


UNCLASSIFIED

NL

1 OF 2

AD
A075 891





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DDC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

LOWER HUDSON RIVER BASIN

DASHVILLE DAM

ULSTER COUNTY, NEW YORK

INVENTORY NO. N.Y. 76

**PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM**



APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED
CONTRACT NO. DACW-51-79-C0001

NEW YORK DISTRICT CORPS OF ENGINEERS

MAY, 1979

79 10 31 033

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DDC TAB	
Unannounced Justification	
By _____	
Distribution/	
Availability Codes	
Dist	Avail and/or special
A	23 CP

PHASE 1 INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
DASHVILLE DAM
I.D. No. NY-76
(#759 L.H.)
LOWER HUDSON RIVER BASIN
ULSTER COUNTY, NEW YORK

TABLE OF CONTENTS

	<u>PAGE NO.</u>
- ASSESSMENT	
- OVERVIEW PHOTOGRAPH	
1 PROJECT INFORMATION	1
1.1 GENERAL	1
1.2 DESCRIPTION OF PROJECT	1
1.3 PERTINENT DATA	2
2 ENGINEERING DATA	4
2.1 DESIGN	4
2.2 CONSTRUCTION RECORDS	4
2.3 OPERATION RECORD	4
2.4 EVALUATION OF DATA	4
3 VISUAL INSPECTION	5
3.1 FINDINGS	5
3.2 EVALUATION OF OBSERVATIONS	6
4 OPERATION AND MAINTENANCE PROCEDURES	7
4.1 PROCEDURE	7
4.2 MAINTENANCE OF DAM	7
4.3 MAINTENANCE OF APPURTENANT STRUCTURES	7
4.4 WARNING SYSTEM IN EFFECT	7
4.5 EVALUATION	7

	<u>PAGE NO.</u>	
5	HYDROLOGIC/HYDRAULIC	8
5.1	DRAINAGE AREA CHARACTERISTICS	8
5.2	ANALYSIS CRITERIA	8
5.3	SPILLWAY CAPACITY	9
5.4	RESERVOIR CAPACITY	9
5.5	FLOODS OF RECORD	9
5.6	OVERTOPPING POTENTIAL	9
5.7	EVALUATION	9
6	STRUCTURAL STABILITY	10
6.1	EVALUATION OF STRUCTURAL STABILITY	10
7	ASSESSMENT/RECOMMENDATIONS	12
7.1	ASSESSMENT	12
7.2	RECOMMENDED MEASURES	12

APPENDIX

A.	PHOTOGRAPHS
B.	ENGINEERING DATA CHECKLIST
C.	VISUAL INSPECTION CHECKLIST
D.	HYDROLOGIC/HYDRAULIC ENGINEERING DATA AND COMPUTATIONS
E.	STRUCTURAL STABILITY ANALYSES
F.	REFERENCES
G.	CORPS OF ENGINEERS GUIDELINES
H.	DRAWINGS

PHASE 1 REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Dashville Dam
I.D. No. NY-76
(#759-LH)

State Located: New York

County Located: Ulster

Watershed: Lower Hudson River Basin


Stream: Wallkill River

Date of Inspection: November 13, 1978

ASSESSMENT


Examination of available documents and a visual inspection of the dam did not reveal conditions which constitute an immediate hazard to human life or property. However, additional studies are recommended to further evaluate conditions affecting the dam. Additional detailed structural stability analyses should be commenced within six months and completed within one year of the date of this report. Such analyses should be performed in accordance with the Corps of Engineers Guidelines, included in Appendix G. Appropriate remedial measures deemed necessary should be completed within two years of the date of this report. Minor deficiencies found during the visual inspection were limited to concrete surface deterioration and cracking. Such deficiencies should be corrected during normal maintenance operations.

The spillway, not having sufficient discharge capacity for passing one-half the Probable Maximum Flood (PMF), is considered to be inadequate. Because of relatively insignificant reservoir storage capacity at the dam, both dam non-failure and failure discharges routed over the spillway attain similar water surface elevations in the downstream areas. Hence, dam failure from overtopping would not significantly increase the hazard to loss of life downstream from that which would exist just before overtopping failure.



George Koch
Chief, Dam Safety Section
New York State Department of
Environmental Conservation
NY License No. 45937


Approved By:



Col. Clark H. Benn
New York District Engineer

Date:





OVERVIEW - DASHVILLE DAM

DASHVILLE DAM
I.D. No. NY-76
(#759 L.H.)
LOWER HUDSON RIVER BASIN
ULSTER COUNTY, NEW YORK

SECTION 1: PROJECT INFORMATION

1.1 GENERAL

a. Authority

The Phase 1 inspection reported herein was authorized by the Department of the Army, New York District, Corps of Engineers, to fulfill the requirements of the National Dam Inspection Act, Public Law 92-367.

b. Purpose of Inspection

This inspection was conducted to evaluate the existing conditions of the dam, to identify deficiencies and hazardous conditions, to determine if these deficiencies constitute hazards to life and property, and to recommend remedial measures where required.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam and Appurtenant Structures

The Dashville Dam is a run-of-river, concrete gravity structure part of which forms an ogee section. The dam is 370 feet long and varies in height from 3 feet at the northwestern end to 38 feet at the southeastern end. There are flashboards, 3.5 feet in height, across the spillway crest. An operating hydroelectric power station is located on the southeastern end of the dam. Four gates in the power house control the flow into the hydromachinery units.

b. Location

The dam is located on the Wallkill River, approximately one quarter mile west of the hamlet of Dashville along State Route 213.

c. Size Classification

The dam is 38 feet high and the reservoir has a storage capacity of 92 acre-feet. Therefore, the dam is in the small size category as defined by the Recommended Guidelines for Safety Inspection of Dams.

d. Hazard Classification

The dam is classified as "significant" hazard due to the presence of several houses and the Sturgeon Pool Dam downstream of this structure.

e. Ownership

This dam is owned by the Central Hudson Gas and Electric Corporation of Poughkeepsie, New York. Mr. Donald Otis (914) 452-2000 is the representative of the utility who was contacted.

f. Purpose of Dam

The dam provides a storage pool for the hydroelectric power station.

g. Design and Construction History

The dam was designed in 1919 by the J.G. White Engineering Corporation of New York and constructed between 1920 and 1922.

h. Normal Operating Procedures

Water is discharged primarily through the power house. According to data provided by Central Hudson Gas and Electric, the average discharge is 60 cfs during the summer and 203 cfs during the winter.

1.3

PERTINENT DATA

<u>a. Drainage Area</u>	(square miles)	765
<u>b. Discharge at Dam</u>	(cfs)	
Top of Dam (without flashboards)		14,685
" " (with flashboards)		2,243
<u>c. Elevations</u>		
Top of Dam - Northwest Abutment		174.0
Top of Flashboards		172.5
Spillway Crest		169.0
<u>d. Reservoir</u>	Surface Area (acres)	
Top of Dam		300
Top of Flashboards		300
Spillway Crest		9.6
<u>e. Storage Capacity</u>	(acre-feet)	
Top of Dam		965
Top of Flashboards		515
Spillway Crest		92
<u>f. Dam</u>		
Type:	Concrete gravity with appurtenant structures	
Length (feet)		370
Height	Varies from 3 feet (Northwest End) to 38 feet (Southeast End)	
<u>g. Spillway</u>		
Type:	Uncontrolled, gravity structure with ogee and non-ogee sections and 3.5 foot flashboards.	
	<u>Ogee</u>	<u>Non-Ogee</u>
Weir Length (feet):	140	215
Crest Elevation:	169.0	169.0
Width @ Crest (feet):	—	1.5
Upstream radius	3.0	—
Downstream radius	33.8	—
Slopes (V : H)		
Upstream	Vertical	1:1.25
Downstream	1:0.64	1:1

h. Reservoir Drain
None

i. Appurtenant Structures - Hydroelectric Power Station
4 bays - each opening 10 feet wide

2 hydromachinery units - Total capacity of 2 megawatts

SECTION 2: ENGINEERING DATA

2.1 DESIGN

a. Geology

The Dashville Dam is located in the Wallkill Valley segment of the Hudson-Mohawk lowlands physiographic province of New York State. The valley is broad and covered with glacial drift. The bedrock in the area was formed during the Ordovician era and consists of interbedded greywacke, siltstone and shale. The rock strata has undergone significant folding.

b. Subsurface Information

No records of any subsurface investigations in the vicinity of this dam were available. The only information available was the data submitted with the application to construct the dam. This data indicates that the foundation for the dam is bedrock which is free of objectionable faults and seams.

c. Dam and Appurtenant Structures

The dam and power house were designed by the J.G. White Engineering Corporation. Copies of several drawings from the project have been included in Appendix H.

2.2 CONSTRUCTION RECORDS

Construction plans and some correspondence from 1919 are the only construction records available. The records indicate that the dam was constructed in 1920-1922 under the supervision of the J.G. White Engineering Corporation.

2.3 OPERATING RECORDS

There were no operating or water level records available for this structure.

2.4 EVALUATION OF DATA

The data presented in this report was obtained from the files of the Department of Environmental Conservation and from the Central Hudson Gas and Electric Corporation. The information available appears to be adequate and reliable for Phase 1 inspection purposes.

SECTION 3: VISUAL INSPECTION

3.1 FINDINGS

a. General

Visual inspection of the Dashville Dam was conducted on November 13, 1978. The weather was overcast with the temperature near 35° F. The water surface at the time of inspection was several inches above the crest of the spillway. Approximately 75 feet of flashboards on the northwestern end of the structure had been opened allowing flow over this part of the dam.

b. Dam - Spillway

Inspection of the main portion of the dam did not reveal any major deficiencies. There were several small areas of spalling, surface cracking and separation of the gunite near the downstream toe. Small sections of the gunite had been removed, exposing portions of the steel reinforcing mesh. Near the midpoint of the dam, water flowing along the bedrock foundation at the toe had scoured a channel in the concrete. A triangular section approximately 3 inches high and 3 inches deep had been removed.

With the exception of the minor spalling and cracking of the gunite, the downstream face of the dam appeared to be in satisfactory condition. However, since the face had been treated with gunite, the condition of the concrete could not be observed.

Water flowing over the spillway in the area where the flashboards were opened had scoured some of the backfill from beneath the northwest abutment forming a small void. The abutment is founded on rock, so this hole does not appear to be serious.

c. Appurtenant Structures - Powerhouse

Concrete surfaces on the powerhouse were spalling and deteriorated. The intake structure has been repaired several times in the past 50 years. At the time of the inspection, divers were repairing the trash racks.

The bedrock at the southeastern abutment was decomposed and fractured. However, the concrete abutment appeared to extend far enough into the rock to provide an adequate cutoff.

d. Downstream Channel

Water flowing over the spillway is carried away from the dam in the natural channel of the Walkill River. The channel is cut into bedrock and appeared to be capable of carrying all flows satisfactorily.

3.2

EVALUATION OF OBSERVATIONS

Visual observations did not reveal any serious problems which would affect the immediate safety of the dam. However, the following minor deficiencies were noted.

1. Spalling, surface cracking and separation of the gunite on portions of the downstream face of the dam.
2. The small triangular section of concrete which has been scoured away at the downstream toe.
3. The minor void under the northwest abutment.
4. The spalled concrete surfaces on the powerhouse.

SECTION 4: OPERATION AND MAINTENANCE PROCEDURES

4.1 PROCEDURE

Normal water surface is at or slightly above the spillway crest. Flow is diverted through the power house for power generation.

4.2 MAINTENANCE OF DAM

The downstream face of the dam was replaced in 1942 and 1952 using a gunite process. Maintenance of the flashboards occurs annually.

4.3 MAINTENANCE OF APPURTENANT STRUCTURES

The racks and associated equipment on the power house intake structure have been repaired or replaced several times in the past fifty years. Other maintenance has been performed on the power house as necessary.

4.4 WARNING SYSTEM IN EFFECT

No apparent warning system is in effect.

4.5 EVALUATION

Operation and maintenance of the dam is generally satisfactory; however, additional effort should be placed on maintaining the dam, to correct some of the minor deficiencies which now exist.

SECTION 5: HYDROLOGIC/HYDRAULIC

5.1 DRAINAGE AREA CHARACTERISTICS

The delineation of the contributing watershed to this dam is shown on the maps titled "Drainage Area - Dashville Dam" (Appendix D). With the drainage area encompassing some 765 square miles, the Wallkill River main stem travels approximately 89 miles from its headwaters near Lake Mohawk in the Sparta Mountains of Sussex County, New Jersey to the Dashville Dam site. Major tributaries to the Wallkill River which have been gaged (US Geological Survey streamgages) include Rutgers Creek, Pochuck Creek, Quaker Creek, and the Shawangunk Kill. Although there are no major lakes or reservoirs within the basin, an area of some 25 square miles near Pellets Island Mountain (Middletown, NY) significantly attenuates flood flows on the Wallkill because of its flat and swampy terrain. Much of the entire basin lies within the steep terrain of the Catskill Mountain area, where large population centers relative to the size of the drainage basin are minimal.

5.2 ANALYSIS CRITERIA

A limited amount of hydrologic/hydraulic information was contained in a Conservation Commission review of the application for construction (October 23, 1919) plus a memorandum dated 11/3/1919 summarizing the basic engineering data known about the proposed dam site. This data concerned itself with the drainage area and the maximum flood of record (Basis - 10 years of record), the design spillway capacity, and the use of flashboards on the spillway crest.

A second information source reviewed was a 1973 C.T. Main Inc. report (7) completed for the present owner. The hydrology and flood study portion (Appendix D) established a value for the standard project flood (SPF) for use in determining if the spillway discharge capacity is adequate. A review of a 1978 Phase 1 inspection report (5) for Sturgeon Pool Dam (I.D. No. NY-75), located approximately two miles downstream of Dashville Dam, established a value for the SPF peak inflow. This SPF peak inflow can be considered indicative of the routed SPF peak outflow from Dashville Dam, allowing for the increased drainage area at Sturgeon Pool Dam.

A report (4) prepared in 1977 by Water Resources Engineers, Inc., for the Corps of Engineers established values for the SPF along certain tributaries of the Lower Hudson River. The methodology described in this report employed the HEC-1 computer program in developing a model that correlated well with past known major storm events, i.e., the storms of August 17-20, 1955 and October 14-18, 1955.

The analysis of the spillway capacity of this dam was performed using streamflow gaging station records (Appendix D) and data contained in the 1977 report for the Corps of Engineers. Using the HEC-1 program, unit hydrographs were developed and routed through the Wallkill River valley and over the Dashville spillway. The spillway design flood selected for analysis was the Probable Maximum Flood (PMF; approximately twice the SPF) in accordance with the recommended guidelines of the U.S. Army Corps of Engineers.

5.3

SPILLWAY CAPACITY

The concrete gravity ogee and non-ogee sections with the flashboards act as the dam in forming the reservoir pool for the hydroelectric power station. The ogee section is 140 feet long and the non-ogee section, 215 feet long.

Discharges over the spillway were computed using weir flow relationships for the representative water surface elevations analyzed. The flashboards were designed originally, to fail when the head reached approximately 10 feet above the spillway crest. Hence, all of the analyses performed assumes no flashboards exist. Maximum theoretical discharges through the hydroelectric power station existing machinery (2 units) was determined to be 2800 cfs.

The spillway does not have sufficient capacity for discharging the peak outflow from one-half the PMF. For this storm event, the peak inflow is 68,735 cfs and the peak outflow is 68, 735 cfs, whereas the PMF peak discharge is 147,100 cfs. The computed spillway capacity is 14, 685 cfs.

5.4

RESERVOIR CAPACITY

The normal water surface is at or slightly above the spillway crest. Storage capacity for that water surface elevation is 92 acre-feet and is obtained within 2378 feet upstream of the dam. Little flood flow attenuation is achieved in the shallow-depth reservoir. With 3.5 foot high flashboards in place, the storage capacity increases to 515 acre-feet with the reservoir extending some 9 river miles upstream toward New Paltz. At the top-of-dam elevation (top of the North abutment), the storage is 965 acre-feet.

5.5

FLOODS OF RECORD

The maximum known discharge on the Wallkill River was recorded upstream at Gardiner, NY (DA of 711 sq. miles) on October 16, 1955 when a gaged flow of 30,800 cfs was measured.

5.6

OVERTOPPING POTENTIAL

Analysis indicates the spillway does not have sufficient discharge capacity for either the PMF or one-half the PMF. The computed depths of overtopping are 17.79 feet and 8.79 feet respectively. All storms exceeding approximately 10% of the PMF would result in overtopping of the dam, i.e. above the elevation of the top of the North abutment.

5.7

EVALUATION

The spillway capacity is inadequate for the peak outflow from one-half the PMF. Because of the relatively insignificant storage capacity available during these large storm events, both failure and non-failure discharges routed over the spillway attain similar water surface elevations in the downstream areas. Also, for such large storm events, high water created by the Sturgeon Pool Dam reservoir would most likely occur in the downstream areas. Therefore, the spillway capacity is considered to be inadequate since dam failure from overtopping would not significantly increase the hazard to loss of life downstream from that which would exist just before overtopping failure.

SECTION 6: STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations

Visual observations of the dam did not reveal any signs of major distress. Minor spalling and surface cracking was noted in several spots and water flowing along the downstream toe of the dam had scoured a triangular area in the concrete approximately 3 inches high and 3 inches deep. However, these deficiencies were not serious enough to affect the stability of the structure.

b. Design and Construction Data

No design computations were available concerning the structural stability of this dam. A stability analysis for this structure was performed in 1973 by Chas. T. Main of New York. The only construction records available were plans for the structure prepared by the J.G. White Engineering Corporation.

c. Data Review and Stability Evaluation

Structural and subsurface information was obtained from the 1919 construction plans prepared by the J.G. White Engineering Corporation and from the stability analysis which had been performed by Chas. T. Main.

A structural stability analysis was performed for this report since the Main study did not analyze several of the conditions which are required (ice loading, 1/2 PMF, PMF). The analysis was performed based on the cross sections of the dam shown on the plans. Analyses were made of both the high section on the southeastern end of the dam and the low section on the northwestern end. Conditions analyzed were:

- 1) Normal conditions with the water level at the spillway crest elevation.
- 2) Conditions as in 1), plus a 5000 lb/ft ice load.
- 3) Water level at the elevation of one-half PMF; a flow depth of 13.8 feet over the spillway crest.
- 4) Water level at the elevation of the PMF; a flow depth of 22.8 feet over the spillway crest.

The analyses were performed assuming full uplift at the upstream toe decreasing to a value equal to the hydrostatic pressure due to tailwater at the downstream toe.

The analyses performed (Appendix E) indicate that the factors of safety against overturning and sliding for the high section on the southeastern end of the dam are as follows:

<u>Case</u> - (For 38 ft. high section)	<u>FACTORS OF SAFETY</u>	
	<u>Overturning</u>	<u>Sliding</u>
1) Normal Conditions	1.47	15.88
2) Ice load plus 1)	1.36	14.68
3) One-half PMF - Flow 13.8 feet over spillway	1.06	10.31
4) PMF - Flow 22.8 feet over spillway	0.93	8.40

The factors of safety against overturning and sliding for the low section on the northwestern end of the dam are as follows:

<u>Case - (For 5 ft. high section)</u>	<u>FACTORS OF SAFETY</u>	
	<u>Overturning</u>	<u>Sliding</u>
1) Normal Conditions	1.72	266
2) Ice load plus 1)	0.78	46
3) One-half PMF - Flow 13.8 feet over spillway	1.13	52
4) PMF - Flow 22.8 feet over spillway	0.93	34

The stability analyses indicate a serious deficiency in the safety factors against overturning for both the high and low sections of the dam. The resultant force fell outside the middle third of the base for each of the conditions studied. In several cases, the resultant force acted outside the limits of the base.

The analysis which was performed for the structure under normal conditions agrees reasonably well with the Chas. T. Main analysis. The other analyses were performed for more critical conditions than those which were assumed in the Main study and as a result, the safety factors are substantially less than those listed in the Main report.

d. Post Construction Changes

The downstream face of the dam was replaced in 1942 and 1952 using a gunite process. This has been the only major post construction change.

e. Seismic Stability

This dam is located in Seismic Zone 1. Therefore, since the seismic coefficient is relatively small, a seismic stability analysis is not warranted.

SECTION 7: ASSESSMENT/RECOMMENDATIONS

7.1 ASSESSMENT

a. Safety

The Phase 1 inspection of Dashville Dam did not reveal conditions which constitute an immediate hazard to human life or property. The structure is not considered to be unsafe.

The spillway, although not having sufficient discharge capacity for passing one-half the PMF, is considered to be inadequate. A warning system should be developed and placed in readiness for future use during the occurrence of large storm events.

b. Adequacy of Information

The information available appears to be adequate for the purpose of the Phase 1 inspection except for the following:

- 1) The physical condition of the mass concrete beneath the gunited downstream surface of the spillway.

c. Urgency

All of the deficiencies observed during the visual inspection can be corrected during normal, continued maintenance operations.

d. Necessity for Additional Investigations

Because of the results of the Phase 1 structural stability analyses obtained for the dam, a more detailed structural stability analysis is recommended.

7.2 RECOMMENDED MEASURES

- a) As a result of the detailed structural stability analysis to be completed within one year of the date of this report, remedial measures deemed necessary should be completed within two years of the date of this report.
- b) Ascertain the physical condition and integrity of the mass concrete in the spillway beneath the gunited surfaces, preferably through a coring program.
- c) Correct the minor deficiencies occurring on the concrete surfaces.
- d) Develop and implement a warning system.

APPENDIX A


PHOTOGRAPHS



POWER STATION - UPSTREAM




POWER STATION - DOWNSTREAM



SPILLWAY - OGEE SECTION



SPILLWAY - NON-OGEE SECTION



NORTHWEST ABUTMENT - TOP OF DAM



EROSION OF BEDROCK @ SPILLWAY



CONCRETE SURFACE SPALLING @ SPILLWAY



INTERFACE ALONG FOUNDATION AND
NON-OGEE SPILLWAY SECTION



SUBSURFACE STRATA @ POWER STATION



RESERVOIR @ DASHVILLE DAM

APPENDIX B

ENGINEERING DATA CHECKLIST

Check List
 Engineering Data
 Design Construction Operation

Name of Dam DASHVILLE

I.D. # NY-76

(759-LH)

Item	Remarks
Plans	Typical Sections
Dam	YES
Spillway(s)	YES
Outlet(s)	
Design Reports	N/A
Design Computations	YES - 1919 CONSERVATION COMMISSION REVIEW
Discharge Rating Curves	N/A
Dam Stability	YES - 1973 C.T. MAIN REPORT
Seepage Studies	N/A
Subsurface and Materials Investigations	N/A

Item

Remarks

Construction History

LIMITED (TO CORRESPONDENCE , 1919 -1920)
(APPLICATION FOR CONSTRUCTION)

Surveys, Modifications,
Post-Construction Engineering
Studies and Reports

N/A

Accidents or Failure of Dam
Description, Reports

NONE

Operation and Maintenance Records
Operation Manual

N/A

APPENDIX C

VISUAL INSPECTION CHECKLIST

VISUAL INSPECTION CHECKLIST

1) Basic Data

a. General

Name of Dam DASHVILLE DAM

I.D. # N.Y. 76 (759 L.H.)

Location: Town ESOPUS County ULSTER

Stream Name WALKHILL RIVER

Tributary of ROUNDOUT CREEK

Longitude (W), Latitude (N) W74° 2.9' N 41° 49.4'

Hazard Category SIGNIFICANT

Date(s) of Inspection 11/13/78

Weather Conditions 35° CLOUDY-OVERCAST

b. Inspection Personnel W. LYNICK R. WARRENDER

c. Persons Contacted DONALD OTIS & DICK DEMELSER - C.H. GAS & ELECTRIC

d. History:

Date Constructed 1919-1922

Owner CENTRAL HUDSON GAS & ELECTRIC

Designer J.G. WHITE ENGINEERING CORP.

Constructed by _____

2) Technical Data

Type of Dam CONCRETE GRAVITY W/OGEE SECTION

Drainage Area 765 SQ MILES

Height 38 Length 380

Upstream Slope VARIABLE Downstream Slope VARIABLE

4) Instrumentation

(1) Monumentation/Surveys NONE

(2) Observation Wells NONE

(3) Weirs NONE

(4) Piezometers NONE

(5) Other _____

5) Reservoir

a. Slopes VERTICAL IN SEVERAL SPOTS - DECOMPOSED ROCK

b. Sedimentation NONE APPARENT

6) Spillway(s) (including tail race channel)

a. General FULL LENGTH OF DAM - FLASHBOARDS 3.5' HIGH
ACROSS ALL BUT ONE SECTION ABOUT 10' WIDE
NEAREST THE POWER HOUSE

b. Principle Spillway OVERFLOW DAM WITH FLASHBOARDS
AT TIME OF INSPECTION APPROXIMATELY
1/3 OF FLASHBOARDS WERE TURNED TO ALLOW FLOW TO
PASS THROUGH.

c. Emergency or Auxiliary Spillway NONE

d. Condition of ~~tail race~~ channel NATURAL BEDROCK CHANNEL -
SATISFACTORY

e. Stability of Channel side/slopes SATISFACTORY

7) Downstream Channel

a. Condition (debris, etc.) NONE

b. Slopes PARTLY VERTICAL - BEDROCK

c. Approximate number of homes NONE APPARENTLY IN IMMEDIATE
DANGER UNTIL THE IMPOUNDMENT FOR THE STRURGEW
POND DAM

8) Miscellaneous

9) Structural

a. Concrete Surfaces SPALLING AT CORNER OF POWER HOUSE & OGEE BUTRESS WALL

2 AREAS SURFACES PATCHED FOR ENTIRE HEIGHT OF DAM

b. Structural Cracking NONE APPARENT

SOME SURFACE CRACKING WHERE MESH IS CLOSE TO SURFACE

c. Movement - Horizontal & Vertical Alignment (Settlement) ~~NONE~~ MOVEMENT EVIDENT


d. Junctions with Abutments or Embankments 2. SOUTHWEST END - OKAY
NORTHEAST END - MINOR UNDERMINING AT END CREST OF
ABUTMENT WALL CONTACT WHERE ABUTMENT RESTS ON
NATURAL BEDROCK

e. Drains - Foundation, Joint, Face NONE

f. Water passages, conduits, sluices NONE

g. Seepage or Leakage NEAR MIDDLE - AREA WHERE WATER FLOWS
UNDER FLASHBOARDS & THEN BENEATH THE GUNITE - IT EXITS
AT THE DOWNSTREAM TOE - ROCK INTERFACE.

A TRIANGULAR SECTION OF CONCRETE 3" X 3" HAD
BEEN REMOVED NEAR MID-DAM AS SHOWN IN SKETCH BELOW



h. Joints - Construction, etc. OKAY

i. Foundation ROCK - GOOD CONDITION

j. Abutments DETERIORATING ROCK

k. Control Gates ONLY GATES ARE ON POWER HOUSE

l. Approach & Outlet Channels OKAY

m. Energy Dissipators (plunge pool, etc.) - NONE - NATURAL BEDROCK CHANNEL

n. Intake Structures REPAIRS WERE BEING MADE ON TRASH RACK FOR POWER HOUSE INTAKE AT TIME OF CONSTRUCTION

o. Stability APPEARS TO BE STABLE

p. Miscellaneous _____

APPENDIX D

HYDROLOGIC/HYDRAULIC

ENGINEERING DATA AND COMPUTATIONS

CHECK LIST FOR DAMS
HYDROLOGIC AND HYDRAULIC
ENGINEERING DATA

DASHVILLE
DAM

1

NY-76

AREA-CAPACITY DATA:

	<u>Elevation</u> (ft.)	<u>Surface Area</u> (acres)	<u>Storage Capacity</u> (acre-ft.)
1) Top of Dam (NORTH ABUTMENT)	174.0	300	965
2) Design High Water (Max. Design Pool)	NA		
3) Auxiliary Spillway Crest	NA		
4) Pool Level with Flashboards	172.5	300	515
5) Service Spillway Crest	169	9.6	92

DISCHARGES

	<u>Volume</u> (cfs)
1) Average Daily (PERIOD 1946-1961)	SUMMER - 60 WINTER - 203
2) Spillway @ Maximum High Water (ELEV. 177.0)	30,000
3) Spillway @ Design High Water	NA
4) Spillway @ Auxiliary Spillway Crest Elevation	NA
5) Low Level Outlet	NA
6) Total (of all facilities) @ Maximum High Water	
7) Maximum Known Flood	30,800
8) HYDROELECTRIC STATION EXISTING MACHINERY (2 UNITS)	2800 - (THEORETICAL MAX.)

CREST: ELEVATION: 174.0

Type: CONCRETE GRAVITY (OGEE & NON-OGEE SECTIONS)

Width: _____ Length: SPILLWAY + NORTH ABUTMENT (15')

Spillover ENTIRE LENGTH OF CREST

Location _____

SPILLWAY:

PRINCIPAL

EMERGENCY

169.0 Elevation NONE

OGEE & NON-OGEE Type _____

1.5' Width _____

Type of Control

✓ Uncontrolled _____

Controlled:

3.5' FLASHBOARDS Type _____
(Flashboards;)

ACROSS ENTIRE CREST Number _____

355' /Length _____

Invert Material _____

Anticipated Length of operating service _____

Chute Length _____

VARIES: 3' TO 29' Height Between Spillway Crest & Approach Channel Invert (Weir Flow) _____

OUTLET STRUCTURES/EMERGENCY DRAWDOWN FACILITIES:

Type: Gate _____ Sluice _____ Conduit _____ Penstock _____

Shape: NONE - ONLY THRU HYDROMACHINERY UNITS

Size: _____

Elevations: Entrance Invert 153.0

Exit Invert _____

Tailrace Channel: Elevation (TAILWATER) 128.0

HYDROMETEROLOGICAL GAGES:

Type: WATER-STAGE RECORDER ^{USGS} # 3715Location: GARDINER, N.Y. ¹⁶ ~~10~~ MILES (I) UPSTREAM

Records:

Date - SEPT 1924 TO PRESENTMax. Reading - 30,800 cfs on OCT. 16, 1955

FLOOD WATER CONTROL SYSTEM:

Warning System: NONE

Method of Controlled Releases (mechanisms):

HYDROMACHINERY UNITS

DRAINAGE AREA: 765 SQ MILES

DRAINAGE BASIN RUNOFF CHARACTERISTICS:

Land Use - Type: RURAL - AGRICULTURAL

Terrain - Relief: CATSKILL MOUNTAINS - STEEP

Surface - Soil: SOME EVIDENCE OF SEDIMENTATION IN RIVER BED

Runoff Potential (existing or planned extensive alterations to existing (surface or subsurface conditions)

N/A

Potential Sedimentation problem areas (natural or man-made; present or future)

N/A

Potential Backwater problem areas for levels at maximum storage capacity including surcharge storage:

N/A

Dikes - Floodwalls (overflow & non-overflow) - Low reaches along the Reservoir perimeter:

Location: NONE

Elevation: _____

Reservoir:

		ELEV. 172.5	9.0	
Length @ <u>NORMAL</u> Pool		ELEV. 169	0.45	(Miles)
Length of Shoreline (@ Spillway Crest)	<u>N/A</u>			(Miles)

PROJECT GRID

JOB		SHEET NO.		CHECKED BY		DATE	
DASHVILLE DAM		1/					
SUBJECT				COMPUTED BY		DATE	
DRAINAGE AREA - BELOW USGS GAGE @ GARDINER				WCL		5/15/79	
USGS 7.5' QUAD :		SCALE 1:24000		1" = 2000'			
QUAD		AREA		QUAD		AREA	
SHT NAME				SHT NAME			
WALDEN, NY		0.30		NEWBURGH, NY		1.32	
GARDINER, NY		11.10		CLINTONDALE, NY		35.77	
		23.56				43.07	
		33.46				16.73	
						43.08	
MOHONK LAKE, NY		17.96				21.73	
		<u>86.38</u>					
				ROSENDALE, NY		43.10	
						(-0.27)	
Σ AREAS =		379.97 SQ INS.		= 54.52 SQ MILES		22.47	
						33.64	
1 SQ IN =		21.827 ACRES				34.25	
						<u>293.59</u>	
DRAINAGE AREA @ GARDINER		711.0 SQ MILES					
+ PLANIMETERED AREA		<u>54.5</u>					
DASHVILLE DR. AREA =		765.5					
SUBAREA DIVIDING LINE @ NEW PALTZ:							
QUAD SHT:		AREA					
CLINTONDALE, NY							
NORTH OF RTE 299		7.50					
GARDINER, NY							
NORTH OF RTE 299 & WEST		12.20					
OF LIBERTYVILLE RD							
SUBAREA 12 - AREA =		56.20 + 154.20 = 210.40 SQ INS =>		30.19 SQ MI.			
CORPS OF ENGR REPORT - SUBAREA 12 =>		22.6 SQ MILES		USE			

PROJECT GRID

JOB	SHEET NO.	CHECKED BY	DATE
DASHVILLE DAM	2/		
SUBJECT	COMPUTED BY	DATE	
HYDROGRAPH PARAMETERS	WCL	5/16/79	
WALKILL RIVER BASIN :			
1) ABOVE USGS GAGE @ GARDINER (CORPS OF ENGRS REPORT) #3715			
DR AREA = 711 SQ MILES			
2) SUBAREA 12 (GAGE TO NEW PALTZ) (STA 3722.27)			
DR AREA = 30.19 SQ MILES		KNOWN 3-HR HYDROGRAPH ←	
L = 7.27 MILES (19.65 + 8.55)		INCLUDING 1)	
L _{CA} = 3.64 MILES			
C _u = 1.7			
CP = 3.2			
3) SUBAREA (NEW PALTZ TO DASHVILLE) (DAM - STA 3730.94)			
DR AREA = 24.33 SQ MILES			
L = 8.67 MILES (9.6 + 22.3)			
L _{CA} = 4.34 MILES			
C _u = 3.1			
CP = 5.0			

PROJECT GRID

JOB		SHEET NO.		CHECKED BY		DATE		
DASHVILLE DAM		3/						
SUBJECT				COMPUTED BY		DATE		
HYDROGRAPH PARAMETERS				WCL		5/16/79		
2) SUBAREA 12 (GAGE TO NEW PALTZ) ← KNOWN 3-HR HYDROGRAPH								
LAG TIME = $C_L (L \times L_{2.3})^{0.3} = 4.54 \text{ HRS } t_p$								
UNIT RAIN DURATION $t_r = \frac{t_p}{5.5} = 0.825 \text{ (USE 1-HR)}$								
ADJUSTED LAG $TP = t_p + 0.25(t_r - t_p)$								
$= 4.54 + 0.25(1 - 0.825)$								
TP = 4.58 HRS								
TRANSPOSITION $TF = 1 - \frac{0.3008}{(DA)^{1.7718}} = 1 - \frac{0.3008}{(30.19)^{1.7718}}$								
TF = 0.836								
TABLE 13	LOSS DATA:							
	INITIAL = 1.5" CONSTANT = 0.15"							
	BASE FLOW = 1 cfs/SQ MILE			SPS RAINFALL = 9.18" TOTAL				
QRCSN = 0.35 RTIOR = 3.0			5.08" EXCESS					
3) SUBAREA (NEW PALTZ TO DASHVILLE)								
LAG TIME = 9.20 HRS t_p								
UNIT RAIN DURATION $t_r = 1.67 \text{ (USE 1.5 HR) (OTHER UH @ 3.0 HRS)}$								
ADJUSTED LAG $TP = 9.20 + 0.25(1.5 - 1.67)$								
TP = 9.16 HRS								
TRANSPOSITION $TF = 1 - \frac{0.3008}{(24.33)^{1.7718}}$								
TF = 0.830								
TABLE 13	LOSS DATA:							
	INITIAL = 1.5" CONSTANT = 0.15"			BASE FLOW:		QRCSN		RTIOR
				1 cfs/SQ MILE		0.35		3.0
					8.57" TOTAL			
					4.62 EXCESS			

PROJECT GRID

JOB DASHVILLE DAM	SHEET NO. 4/	CHECKED BY	DATE
SUBJECT HYDROGRAPH PARAMETERS		COMPUTED BY WCL	DATE 5/16/79
DRAINAGE AREA (TO NEW PALTZ) STA 3722.27		KNOWN 3-HR HYDROGRAPH ←	
DR. AREA = 741.2 SQ MILES (711 + 30.2)			
L = 30.07 MILES (NODES $\frac{101-108}{39.2} + 7.27$) + 33.6			
L _{ca} = 40.04 MILES			
$C_t = 1.46$ $C_t = \frac{t_p}{(L \times L_{ca})^{0.3}}$ $t_p = t_r \times 5.5 = 16.5$			
$CP = 16.03$ $WTD\ CP = \frac{\sum A \times CP}{\sum A}$			
$TP = 16.5$			
CHANNEL ROUTING OF THIS HYDROGRAPH TO DAM:			
DISTANCE = 8.67 MILES CLINTONDALE QUAD:			
(ASSUME) VELOCITY = 8 FPS $v = \frac{1.486}{n} r^{2/3} s^{1/2}$ 180 CONTOUR - 16500'			
\therefore TRAVEL TIME \approx 2.16 HRS $v = 0.495 r^{2/3}$ (DIST. TO RTE 299) - 8.25"			
$\#$ OF ROUTING STEPS = $\frac{2.16}{3} \approx 1$ + 8.67 MILES - 45800'			
USE: 300' x 10' MAIN CHANNEL SLOPE = $\frac{\Delta h}{L} = \frac{11}{62300} = 0.0001766$			
2000' TOTAL WIDTH			

PROJECT GRID

JOB		SHEET NO.		CHECKED BY		DATE	
DASHVILLE DAM		5/					
SUBJECT				COMPUTED BY		DATE	
STAGE - STORAGE DATA				WCL		5/17/79	
39.4%	OGEE SECTION	≈ 140'	} L = 355' @ CREST ELEV. 169.0	NORTH ABUTMENT - +5'			
60.6%	GRAVITY SECTION	≈ 215'		@ ELEV. 174.0			
				SOUTH ABUTMENT - +10'			
				@ POWER STATION			
				@ ELEV. 177.0			
STAGE	AREA	AS	(AC-FT)				
STORAGE							
SOUTH ABUT. 177	PROJECTED ↑	300	1865.7				
NORTH ABUT. 174		300	965.7				
		450					
FLASH-BYDS 172.5	↓ 35'	300 ACRES	515.616	← 300 ACRES = 9 MILES X W			
CREST 169		9.55	423.6	275' = WAVE			
				175' x 2378' = 9.55 ACRES			
$\Delta V = \frac{\Delta h}{3} (A_1 + A_2 + \sqrt{A_1 A_2})$							
$AS = \frac{3.5}{3} (9.55 + 300 + \sqrt{(3.55)(300)}) = 423.6$							

PROJECT GRID

JOB DASHVILLE DAM		SHEET NO. 6/		CHECKED BY		DATE	
SUBJECT SPILLWAY DISCHARGE DATA				COMPUTED BY WCL		DATE 5/17/79	
39.4% OGEE SECTION L = 140'		60.6% GRAVITY SECTION L = 215'					
DESIGNER DATA: 10/19/19							
@ 50000 cfs H = 10' ⇒ L = 370' ⇒ ELEV 179 ±				C = 3.5		←	
BOREC - DESIGN OF SMALL DAMS (1977)							
FIG 249 - OGEE SECTION							
P = 29' FOR $H_o < 9.7'$ $C_o > 3.95$							
				ENTIRE DAM - C = 3.7		←	
				(FOR HEC-1 ANALYSIS)		L = 370'	
L = 355'		L = 15'		Q = CLH ^{3/2}			
C = 3.7							
STAGE	H ₁	H ₂	Q ₁	Q ₂	TOTAL		
SOUTH ABUT.	177.0		29721	288	30009		
NORTH ABUT.	174.0		14685	—	14685	TOP-OF-DAM ←	
CREST	169.0	5					

PROJECT GRID

JOB	SHEET NO.	CHECKED BY	DATE
DASHVILLE DAM	7/		
SUBJECT	COMPUTED BY		DATE
SPILLWAY DISCHARGE w/ FLASHBOARDS	WCL		5/17/79
3.5' FLASHBOARDS			ELEV.
SHARP-CRESTED WEIR			174.0
$L/b = 1$			170.5
$Q = C L H^{3/2}$			169.0
$Q = (3.44)(355)(1.5)^{3/2} = 2243 \text{ cfs}$			
L = 215' 5' MIN			
L = 140' 29' MAX			
CONDITION: WATER SURFACE @ TOP OF DAM			
H = 1.5' d = 5' P = 3.5'			
FRANCIS FORMULA:	$(v < 5.0 \text{ fps})$	$C = 3.33 \left(1 + 0.259 \frac{H}{d} \right)$	C = 3.408 1)
	$(v < 1.0 \text{ fps})$	$C = 3.33 \left[\left(1 + \frac{h}{H} \right)^{3/2} - \left(\frac{h}{H} \right)^{3/2} \right]$	C = 3.378 2)
	$h = \frac{v^2}{2g}$	for v = 1 h = 0.0155	
FTELEY & STEARNS:	$(v < 2.0 \text{ fps})$	$C = 3.31 \left(1 + 0.383 \frac{H}{d} + \frac{0.007}{H^{3/2}} \right)$	C = 3.437 3)
BAZIN FORMULA:		$C = \left(3.248 + \frac{0.079}{H} \right) \left(1 + 0.55 \frac{H}{d} \right)$	C = 3.464 4)
FRESE FORMULA:		$C = \left(3.288 + \frac{0.0368}{H} \right) \left(1 + 0.55 \frac{H}{d} \right)$	C = 3.477 5)
KING:		$C = \frac{3.34}{H^{0.02}} \left(1 + 0.51 \frac{H}{d} \right)$	C = 3.412 6)
REHBOCK FORMULA:		$C = 3.235 + \frac{1}{60H - 0.56} + 0.428 \frac{H}{P}$	C = 3.430 7)
SWISS SOCIETY FORMULA:		$C = \left(3.288 + \frac{1}{92.8H - 0.49} \right) \left(1 + 0.5 \frac{H}{d} \right)$	C = 3.443 8)
AVE. VALUE:			
1) - 3) C = 3.438		EXCL C = 3.448	USE C = 3.44
		2) 3)	

PROJECT GRID

JOB	SHEET NO.	CHECKED BY	DATE
DASHVILLE DAM	3/		
SUBJECT	COMPUTED BY	DATE	
DISCHARGE CAPACITY - HYDROMACHINERY UNITS	WCL	5/17/79	
2 EXISTING UNITS - RATED @ 3850 HP EACH			
MAXIMUM THEORETICAL DISCHARGE CAPACITY (100% EFFICIENT):			
CREST ELEV. 169	$HP = \frac{Qh}{8.8}$	OR $Q = \frac{HP(8.8)}{h}$	
$\frac{Q \text{ OF UNIT ELEV. } 145}{24'}$		$= \frac{3850(8.8)}{24}$	
USE $Q_{map} \approx 2800 \text{ cfs}$		$Q = 1411.7 \text{ cfs}$	

Dashville Dam NY-76

Dam Breaching - Downstream Flood Wave Analysis

- 1) HEC-1 DB requires the breached section to not be located at an overflow section. At this site, the entire dam is an overflow section.
- 2) Initial analysis using suggested breach parameters resulted in large errors between the computed and interpolated breach hydrographs.
- 3) Because of the extremely short time intervals used in the breach hydrograph generation and the relatively long storm unit hydrograph time interval, the TFAIL variable selected exceeded the upper limit of the suggested parameter for a concrete gravity dam failure time of 0.5 hours.
- 4) Since both Q (spillway) and Q (breach) are assumed to occur independently at the site in HEC-1 DB analysis, the BRWID value was selected on the smaller side to minimize duplication of the discharges.

 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 26 FEB 79
 MODIFIED FOR HONEYWELL APR 79

 THIS PROGRAM IS CURRENTLY BEING MODIFIED
 TO RUN ON THE OGS HONEYWELL SYSTEM

PLEASE REPORT ANY UNUSUAL OPERATING PROBLEMS
 TO MIKE TILLSON (RM. 423) PH: 7-5666

1 A DASHVILLE DAM NY-76
 2 A
 3 A
 4 B 100 3 0
 5 B1 5
 6 J 1 2 1
 7 J1 1 2
 8 K 0 722.27
 9 K1
 10 M -1 0 741.2
 11 N 1623 1619 1605 1585 1563 1539 1514 1485 1451 1412
 12 N 1366 1320 1269 1252 1437 1949 2742 3456 3634 3509
 13 N 5319 13935 30474 52554 71829 79948 76423 67189 58499 51609
 14 N 46615 43042 40659 39794 39191 38619 37972 37201 36288 35244
 15 N 34101 32889
 16 N 0
 17 N 0
 18 N 0
 19 N 0
 20 N 0
 21 K 1 730.94
 22 K1
 23 Y
 24 Y1 1
 25 Y6 .05 .04 .03 169 200 62300 .000176
 26 Y7 0 200 40 120 900 179 900 169 1100 169

WALLKILL RIVER
 ULSTER COUNTY
 SPF PARAMETERS - CORPS OF ENGRS REPORT(LHRBHRM)
 0 0 0 0 0 0 0 0 0 0

3-HOUR RUNOFF HYDROGRAPH DATA - NEW PALTZ

741.2 0.907
 1
 CHANNEL ROUTING OF HYDROGRAPH TO DAM
 1 1 1
 -169

	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	
	Y7	1100	179	1960	180	2000	200																		
	K	0	730.94																						
	K1			INFLUX HYDROGRAPH TO DAM - SUBAREA (NEW PALTZ TO DAM)																					
	M	1	1	24.3	24.3	0.83																			
	P	8.57																							
	T																								
	M	9.5	5																						
	X	24	69	3																					
	K	2	730.94																						
	K1			COMBINED HYDROGRAPHS AT DAM																					
	K	1	730.94																						
	K1			COMBINED HYDROGRAPH Routed OVER DAM - NO BREACH																					
	Y			1	1																				
	Y1	1																							
	\$S	0	92.06	515.7	965.7	1865.7																			
	\$E	140	169	172.5	174	177																			
	\$S	169	355	3.7	1.5																				
	\$D	174	3.7	1.5	15																				
	K	99																							
	A																								
	A																								
	A																								
	A																								
	A																								

SFF
PRECIP.

QIN(1) QIN(2) QIN(3) ELMHT ELMAX RLIMTH SEL
 0.0500 0.0400 0.0300 169.0 200.0 62300. 0.00018

CROSS SECTION COORDINATES--STA,ELEV,STA,ELEV--ETC
 0. 200.00 40.00 180.00 900.00 179.00 900.00 169.00 1100.00 169.00
 1100.00 179.00 1960.00 180.00 2000.00 200.00

STORAGE	0.	466.70	933.40	1400.10	1866.80	2333.50	2800.20	5333.16	10025.02	14532.12
	19054.45	23592.00	28144.79	32712.80	37296.05	41894.52	46508.22	51137.15	55781.31	60440.70
OUTFLOW	0.	221.09	694.51	1350.91	2159.67	3101.01	4160.42	5964.98	9952.27	15354.44
	22527.27	30734.52	40084.08	50507.61	61951.51	74372.12	87732.89	102002.58	117154.11	133163.61
STAGE	169.00	170.63	172.26	173.89	175.53	177.16	178.79	180.42	182.05	183.68
	185.32	186.95	188.58	190.21	191.84	193.47	195.11	196.74	198.37	200.00
FLOW	0.	221.09	694.51	1350.91	2159.67	3101.01	4160.42	5964.98	9952.27	15354.44
	22527.27	30734.52	40084.08	50507.61	61951.51	74372.12	87732.89	102002.58	117154.11	133163.61

STATION 730.94, PLAN 1, RTIO 1

	180.	460.	725.	984.	1159.	1273.	1350.	1403.	1426.	1428.
	1414.	1390.	1356.	1327.	1332.	1455.	1771.	2251.	2769.	3090.
	3671.	4893.	7993.	16408.	32485.	51004.	62970.	67901.	65364.	60293.
	55007.	50216.	46527.	43746.	41868.	40561.	39504.	38785.	37957.	37068.
	36996.	35040.	27809.	18230.	12913.	9590.	7689.	6164.	5154.	4400.
	2339.	1809.	1199.	843.	618.	480.	372.	289.	225.	198.
	176.	156.	139.	124.	110.	98.	87.	77.	69.	61.
	54.	48.	43.	38.	34.	30.	27.	24.	21.	19.
	17.	15.	13.	12.	10.	9.	8.	7.	7.	6.
	5.	5.	4.	4.	3.	3.	3.	2.	2.	2.
	380.	703.	955.	1139.	1264.	1346.	1399.	1430.	1443.	1444.
	1437.	1422.	1403.	1387.	1387.	1461.	1642.	1912.	2169.	2328.
	2584.	3910.	7818.	15085.	24445.	32911.	38043.	39499.	38559.	36632.
	34515.	32585.	30968.	29750.	26927.	28354.	27911.	27512.	27109.	26076.
	25203.	25089.	21975.	16267.	12407.	9617.	7475.	5758.	4351.	3153.
	2253.	1664.	1039.	656.	356.	222.	183.	133.	145.	129.
	371.	330.	294.	261.	232.	206.	183.	163.	145.	129.
	115.	102.	91.	81.	72.	64.	57.	50.	45.	40.
	35.	31.	28.	25.	22.	20.	17.	16.	14.	12.
	11.	10.	9.	8.	7.	6.	5.	5.	4.	4.

STAGE

170.3	171.5	172.3	173.0	173.4	173.7	173.9	174.0	174.0	174.0	174.0
174.0	174.0	173.9	173.8	173.8	174.1	174.7	175.7	176.6	177.1	177.1
178.0	179.5	181.3	183.9	187.3	190.3	192.1	192.6	192.3	191.6	191.6
190.0	190.2	189.6	189.2	188.9	188.7	188.5	188.4	188.2	188.1	188.1
187.9	187.7	186.4	184.3	182.9	181.9	181.1	180.5	179.7	179.0	179.0
176.9	174.8	173.5	172.6	172.0	171.5	171.2	170.9	170.6	170.5	170.5
170.3	170.2	170.0	169.9	169.8	169.7	169.6	169.6	169.5	169.5	169.5
169.4	169.4	169.3	169.3	169.3	169.2	169.2	169.2	169.2	169.1	169.1
169.1	169.1	169.1	169.1	169.1	169.1	169.1	169.1	169.0	169.0	169.0
169.0	169.0	169.0	169.0	169.0	169.0	169.0	169.0	169.0	169.0	169.0

PEAK	67901.	1923.	66284.	1877.	0.83	21.13	32568.	112220.	232137.	249777.
6-HOUR	67901.	1923.	66284.	1877.	0.83	21.13	32568.	112220.	232137.	249777.
24-HOUR	57082.	1616.	57082.	1616.	1105.	5.88	2.79	1.49.23	160.57	249777.
72-HOUR	39012.	1105.	39012.	1105.	5.88	1.49.23	160.57	249777.	249777.	249777.
TOTAL VOLUME	1007434.	26527.	1007434.	26527.	6.32	6.32	6.32	6.32	6.32	6.32

CFS
 CM5
 INCHES
 MM
 AC-FT

HYDROGRAPH DATA

IHYDG	IUMG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNDW	ISAMH	LOCAL
1	1	24.30	0.	24.30	0.83	0.	0	1	0

PRECIP DATA

SPFE	PMS	R6	R12	R24	R48	R72	R96
8.57	0.	0.	0.	0.	0.	0.	0.

LOSS DATA

LROPT	STRKR	DLTKR	RTIDL	ERAIN	STRKS	RTIDK	STRTL	CNSTL	ALSHX	RTIMP
0	0.	0.	1.00	0.	0.	1.00	1.50	0.15	0.	0.

UNIT HYDROGRAPH DATA

TP= 9.50 CP=5.00 NTA# 0

RECESSION DATA

STRTQ# 24.00 RTIDR= 3.00

GRCSN# 69.00

CLARK DID NOT CONVERGE TO GIVEN SNYDER COEFFICIENTS

APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNYDER CP AND TP ARE TC= 5.70 AND R= 0.50 INTERVALS

UNIT HYDROGRAPH 7 END-OF-PERIOD ORDINATES, LAG= 9.50 HOURS, CP= 0.78 VOL= 1.00

271. 768. 1136. 1242. 1045. 159. 602.

MO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	END-OF-PERIOD FLOW	COMP Q	MO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	COMP Q
1.01	3.00	1	0.00	0.	0.00	1.07	22.	1.07	9.00	51	0.	0.	0.	6.
1.01	6.00	2	0.00	0.	0.00	1.07	19.	1.07	12.00	52	0.	0.	0.	5.
1.01	9.00	3	0.01	0.	0.01	1.07	17.	1.07	15.00	53	0.	0.	0.	4.
1.01	12.00	4	0.01	0.	0.01	1.07	15.	1.07	18.00	54	0.	0.	0.	4.
1.01	15.00	5	0.07	0.	0.07	1.07	14.	1.07	21.00	55	0.	0.	0.	4.
1.01	18.00	6	0.14	0.	0.14	1.08	12.	1.08	0.	56	0.	0.	0.	4.
1.01	21.00	7	0.01	0.	0.01	1.08	11.	1.08	3.00	57	0.	0.	0.	3.
1.02	0.	8	0.01	0.	0.01	1.08	10.	1.08	6.00	58	0.	0.	0.	3.
1.02	3.00	9	0.01	0.	0.01	1.08	9.	1.08	9.00	59	0.	0.	0.	3.
1.02	6.00	10	0.01	0.	0.01	1.08	8.	1.08	12.00	60	0.	0.	0.	2.
1.02	9.00	11	0.05	0.	0.05	1.08	7.	1.08	15.00	61	0.	0.	0.	2.
1.02	12.00	12	0.05	0.	0.05	1.08	6.	1.08	18.00	62	0.	0.	0.	2.
1.02	15.00	13	0.31	0.	0.31	1.08	6.	1.08	21.00	63	0.	0.	0.	2.
1.02	18.00	14	0.62	0.	0.62	1.09	5.	1.09	0.	64	0.	0.	0.	1.
1.02	21.00	15	0.03	0.	0.03	1.09	5.	1.09	3.00	65	0.	0.	0.	1.
1.03	0.	16	0.03	0.	0.03	1.09	4.	1.09	6.00	66	0.	0.	0.	1.
1.03	3.00	17	0.07	0.	0.07	1.09	4.	1.09	9.00	67	0.	0.	0.	1.
1.03	6.00	18	0.07	0.	0.07	1.09	3.	1.09	12.00	68	0.	0.	0.	1.
1.03	9.00	19	0.37	0.	0.37	1.09	3.	1.09	15.00	69	0.	0.	0.	1.
1.03	12.00	20	0.37	0.	0.37	1.09	3.	1.09	18.00	70	0.	0.	0.	1.
1.03	15.00	21	2.29	1.84	0.45	1.09	501.	1.09	21.00	71	0.	0.	0.	1.
1.03	18.00	22	4.65	4.20	0.45	2552.	5311.	1.10	0.	72	0.	0.	0.	1.
1.03	21.00	23	0.	0.	0.20	7053.	7137.	1.10	3.00	73	0.	0.	0.	1.
1.04	0.	24	0.20	0.	0.20	5495.	2821.	1.10	6.00	74	0.	0.	0.	1.
1.04	3.00	25	0.00	0.	0.00	670.	68.	1.10	9.00	75	0.	0.	0.	0.
1.04	6.00	26	0.00	0.	0.00	1.10	61.	1.10	12.00	76	0.	0.	0.	0.
1.04	9.00	27	0.02	0.	0.02	1.10	55.	1.10	15.00	77	0.	0.	0.	0.
1.04	12.00	28	0.02	0.	0.02	1.10	49.	1.10	18.00	78	0.	0.	0.	0.
1.04	15.00	29	0.12	0.	0.12	1.10	44.	1.10	21.00	79	0.	0.	0.	0.
1.04	18.00	30	0.24	0.	0.24	1.11	39.	1.11	0.	80	0.	0.	0.	0.
1.04	21.00	31	0.01	0.	0.01	1.11	35.	1.11	3.00	81	0.	0.	0.	0.
1.05	0.	32	0.01	0.	0.01	1.11	32.	1.11	6.00	82	0.	0.	0.	0.
1.05	3.00	33	0.	0.	0.	1.11	28.	1.11	9.00	83	0.	0.	0.	0.
1.05	6.00	34	0.	0.	0.	1.11	25.	1.11	12.00	84	0.	0.	0.	0.
1.05	9.00	35	0.	0.	0.	1.11	23.	1.11	15.00	85	0.	0.	0.	0.
1.05	12.00	36	0.	0.	0.	1.11	21.	1.11	18.00	86	0.	0.	0.	0.
1.05	15.00	37	0.	0.	0.	1.11	20.	1.11	21.00	87	0.	0.	0.	0.
1.05	18.00	38	0.	0.	0.	1.12	19.	1.12	0.	88	0.	0.	0.	0.
1.05	21.00	39	0.	0.	0.	1.12	18.	1.12	3.00	89	0.	0.	0.	0.
1.05	0.	40	0.	0.	0.	1.12	17.	1.12	6.00	90	0.	0.	0.	0.

COMBINE HYDROGRAPHS

COMBINED HYDROGRAPHS AT DAM

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPR1	INAME	ISTAGE	IAUTO
730.94	2	0	0	0	0	1	0	0

202.	490.	743.	1173.	1208.	1361.	1413.	1435.	1436.
1422.	1396.	1362.	1337.	1460.	1774.	2255.	2772.	3093.
4172.	7445.	13304.	39623.	56499.	66791.	68571.	65432.	60354.
53062.	50266.	45571.	43756.	40593.	39632.	38810.	37980.	37088.
36114.	35057.	27824.	18243.	12924.	9601.	7698.	5192.	4407.
2945.	1814.	1203.	847.	622.	483.	292.	227.	200.
172.	158.	141.	125.	111.	96.	78.	70.	62.
55.	49.	43.	39.	34.	31.	27.	21.	19.
17.	15.	13.	11.	9.	8.	7.	7.	6.
5.	5.	4.	4.	3.	3.	2.	2.	2.

TOTAL VOLUME

CFS	66571.	67341.	58259.	40184.	1039803.
CMS	1942.	1907.	1650.	1138.	29444.
INCHES		0.82	2.83	5.86	6.32
MM		20.79	71.93	148.04	160.47
AC-FT	3392.	3392.	115555.	239110.	257602.
THOUS CU H	41189.	142535.	294938.		317995.

SUM OF 2 HYDROGRAPHS AT 730.94 PLAN 1 RTID 2

544.	1290.	1964.	2435.	2729.	2887.	2961.	2982.	2932.
2376.	2805.	2724.	2645.	2866.	2957.	3706.	4387.	5152.
6706.	13413.	28369.	56370.	96391.	132230.	147870.	144394.	119317.
107153.	97326.	89836.	84821.	81766.	79706.	78087.	76572.	74965.
71297.	69152.	51607.	29794.	19341.	13548.	9943.	7974.	73233.
4524.	3209.	1949.	1278.	900.	651.	506.	394.	5329.
206.	183.	145.	129.	114.	102.	90.	80.	239.
64.	57.	50.	45.	40.	35.	31.	28.	71.
20.	17.	16.	14.	12.	11.	10.	9.	22.
6.	5.	4.	4.	4.	3.	3.	3.	7.
								2.

HYDROGRAPH ROUTING

COMBINED HYDROGRAPH ROUTED OVER DAM - RECTANGULAR BREACH

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPR1	INAME	ISTAGE	IAUTO
730.94	1	0	0	0	0	1	0	0

QLOSS	CLSS	AVG	IPES	ISAME	IOPT	IPMP	LSTR
0.	0.	0.	1	1	0	0	0

OVII

STATION 730.94, PLAN 1, RATIO 2

BEGIN DAM FAILURE AT 72.00 HOURS

END-OF-PERIOD HYDROGRAPH ORDINATES

TIME	OUTFLOW	STORAGE	STAGE	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
545.	1012.	1340.	2345.	2604.	2843.	2950.	2941.
2883.	2820.	2740.	2660.	2654.	2881.	3539.	4742.
6375.	11384.	23924.	50370.	92128.	127373.	147873.	134618.
108673.	98461.	90756.	85373.	82123.	79961.	78305.	75205.
71597.	69481.	55777.	33519.	20371.	14917.	10385.	73492.
4669.	3488.	2236.	1382.	927.	448.	266.	5430.
175.	213.	143.	162.	116.	76.	48.	280.
61.	57.	45.	37.	31.	23.	17.	75.
20.	18.	13.	10.	8.	7.	6.	23.
6.	6.	4.	4.	4.	3.	3.	2.
159.	194.	244.	270.	287.	296.	300.	301.
297.	293.	290.	286.	285.	296.	306.	299.
437.	1334.	2829.	3975.	5093.	5694.	5694.	377.
4315.	4186.	3930.	3745.	3557.	3499.	3445.	3309.
3257.	3180.	2647.	1693.	1041.	682.	457.	3388.
261.	209.	139.	85.	81.	83.	81.	337.
80.	79.	79.	79.	78.	78.	78.	81.
78.	78.	77.	77.	77.	77.	77.	78.
77.	77.	77.	77.	77.	77.	77.	77.
77.	77.	77.	76.	76.	76.	76.	76.
169.5	169.8	170.3	170.5	170.6	170.7	170.7	170.7
170.7	170.7	170.6	170.6	170.6	170.7	170.7	170.7
171.9	173.2	175.9	180.2	184.0	187.8	189.5	171.2
181.6	184.7	183.9	183.3	182.9	182.6	182.4	181.2
181.6	181.4	179.6	176.4	174.3	173.1	172.0	181.9
170.4	170.0	169.4	168.3	167.1	166.8	166.0	171.0
165.1	165.2	164.9	165.0	164.8	164.9	164.7	165.5
164.5	164.5	164.5	164.4	164.4	164.3	164.3	164.6
164.3	164.2	164.2	164.2	164.2	164.2	164.2	164.3
164.1	164.1	164.1	164.1	164.1	164.1	164.1	164.1
164.1	164.1	164.1	164.1	164.1	164.1	164.1	164.1

PEAK OUTFLOW IS 147973. AT TIME 81.00 HOURS

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
147873.	143146.	121794.	61481.	2079433.
4187.	4053.	3449.	2307.	58883.
	1.74	5.92	11.88	12.03
	44.18	150.37	301.80	320.92
	70982.	241576.	484844.	515562.
	87554.	297979.	592047.	635936.

CFS
 INCHES
 AC-FT
 THOUS CU M

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FORMULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	1/2 PMF		PMF		RATIOS APPLIED TO FLOWS	
			PLAN	RATIO	PLAN	RATIO	1	2
HYDROGRAPH AT	722.27	741.20 (0.00)	1	79948. (2253.88)	159896. (4527.75)	1.00	2.00	
ROUTED TO	730.94	741.20 (0.00)	1	67901. (1922.75)	143055. (4050.86)			
HYDROGRAPH AT	730.94	24.30 (0.00)	1	7137. (202.10)	14274. (404.19)			
2 COMBINED	730.94	765.50 (0.00)	1	68571. (1941.72)	147070. (4187.21)			
ROUTED TO	730.94	765.50 (0.00)	1	68259. (1932.87)	147873. (4187.28)			
ROUTED TO	731.9	765.50 (0.00)	1	68103. (1928.47)	148400. (4202.22)			
ROUTED TO	771.9	765.50 (0.00)	1	68378. (1936.26)	147455. (4175.47)			
ROUTED TO	800.9	765.50 (0.00)	1	68726. (1946.10)	146799. (4156.87)			

PLAN 1 STATION 730.94

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
1.00	67901.	192.6	84.00
2.00	143055.	201.0	84.00

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	RATIOS APPLIED TO FLOWS		NO	BREACH
			1/2 PMF	PMF		
			PLAN RATIO 1	RATIO 2		
HYDROGRAPH AT	722.27	741.20 (0.00)	1.00	2.00		
			1	79948. 159396. (2263.88)(4527.75)(
ROUTED TO	730.94	741.20 (0.00)				
			1	67901. 143055. (1922.75)(4050.86)(
HYDROGRAPH AT	730.94	24.30 (0.00)				
			1	7137. 14274. (202.10)(404.19)(
2 COMBINED	730.94	765.50 (0.00)				
			1	68571. 147870. (1941.72)(4187.21)(
ROUTED TO	730.94	765.50 (0.00)				
			1	68735. 147096. (1946.35)(4165.34)(

PLAN 1 STATION 730.94


RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
1.00	67901.	192.6	84.00
2.00	143055.	201.0	84.00

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1

ELEVATION
STORAGE
OUTFLOW

INITIAL VALUE SPILLWAY CREST TDP OF DAM
169.00 169.00 174.00
92. 92. 966.
0. 0. 14685.



MAXIMUM
RESERVOIR
H.S. ELEV
181.23
189.76

MAXIMUM
DEPTH
OVER DAM
7.23
15.76

MAXIMUM
STORAGE
AC-FT
3134.
5694.

MAXIMUM
OUTFLOW
CFS
68259.
147873.

DURATION
OVER TDP
HOURS
63.00
69.00

TIME OF
MAX OUTFLOW
HOURS
84.00
81.00

TIME OF
FAILURE
HOURS
78.00
72.00

PLAN 1 STATION 731.9

MAXIMUM
FLOW,CFS
68103.
148400.

MAXIMUM
STAGE,FT
140.9
143.3

TIME
HOURS
84.00
81.00

PLAN 1 STATION 771.9

MAXIMUM
FLOW,CFS
68376.
147455.

MAXIMUM
STAGE,FT
159.9
173.6

TIME
HOURS
64.00
81.00

PLAN 1 STATION 800.9

MAXIMUM
FLOW,CFS
68726.
146799.

MAXIMUM
STAGE,FT
163.7
179.1

TIME
HOURS
64.00
64.00

1A

NO BREACH

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1

ELEVATION STORAGE OUTFLOW

INITIAL VALUE 169.00
SPILLWAY CREST 169.00
TOP OF DAM 174.00

RATIO OF PAF 1.00
PAF 2.00

MAXIMUM RESERVOIR W.S. ELEV 182.79
191.79

MAXIMUM DEPTH OVER DAM 8.79
17.79



MAXIMUM STORAGE AC-FT 3604.
6304.


MAXIMUM OUTFLOW CFS 68735.
147098.

DURATION OVER TOP 63.00
72.00

TIME OF MAX OUTFLOW 84.00
81.00

TIME OF FAILURE 0.
0.





INSERT A



DRAINAGE AREA
DASHVILLE DAM
NY - 76

WSP # 1700

#

WALKILL RIVER/SPILLWAY FLOODS

Results of previous analyses:

- 1) Original Design (1919): 10 feet of overtopping @ 50,000 cfs
- 2) C.T. Main report (1973):
SPF inflow - 62,000 cfs
SPF routed outflow - 38,000 cfs

Unit hydrograph derived from a September, 1960 storm

- 3) Corps of Engineers report (1977):
(computer simulation @ New Paltz) SPF - 79948 cfs

Comparison of known recorded floods vs. simulated floods:

@ Gardiner:

August 1955	30,300 cfs	30,255 cfs
October 1955	30,800 cfs	30,620 cfs

- 4) Phase I inspection report (1978) for Sturgeon Pool Dam:
SPF inflow - 85,800 cfs

HUDSON RIVER BASIN

Yearly discharge, in cubic feet per second, of Shawangunk Kill at Pine Bush, N. Y.

Year	W.S.F. no.	Water year ending Sept. 30					Calendar year		
		Momentary maximum		Minimum day	Per square mile	Runoff in inches	Mean	Runoff in inches	
		Discharge	Date						
1925	601	*2,240	Mar. 28, 1925	10	94.7	0.920	12.60	119	15.85
1926	671	*2,070	Nov. 16, 1925	8	140	1.37	18.85	143	18.99
1927	641, 1502	*3,350	Sept. 1, 1927	16	*227	*2.18	*29.51	*297	*59.56
1928	661, 1502	*4,100	Nov. 3, 1927*	34	*207	*3.01	*40.94	*204	*27.70
1929	661, 1502	*3,600	Mar. 5, 1929	9.2	*155	*1.50	*17.71	*152	*20.74
1930	696	*3,910	Mar. 8, 1930	3.5	115	1.11	15.08	96.1	12.80
1931	711	*2,740	Mar. 29, 1931	14	129	1.26	17.11	125	16.67
1932	726	1,210	Apr. 1, 1932	7.6	92.0	1.02	12.78	-	-

* Revised.

122. Wallkill River at Gardiner, N. Y.

Location.--lat 41°41'10", long 74°09'55", on left bank 400 ft upstream from highway bridge, 500 ft downstream from Shawangunk Mill, and three-quarters of a mile northwest of Gardiner, Ulster County.

Drainage area.--711 sq mi.

Gage.--Water-stage recorder. Datum of gage is 185.70 ft above mean sea level, adjustment of 1912.

Average discharge.--26 years (1924-50), 1,028 cfs.

Extremes.--1924-50: Maximum discharge, 21,000 cfs Dec. 31, 1948 (gage height, 14.81 ft); maximum gage height, 16.83 ft Mar. 7, 1945 (ice jam); minimum discharge, 20 cfs Sept. 17, 1932; minimum gage height, 1.94 ft Sept. 11, 1944.

Remarks.--Large diurnal fluctuation during low and medium flow caused by powerplant above station.

Monthly and yearly mean discharge, in cubic feet per second

Water year	Oct.	Nov.	Dec.	Jan.	Feb.	Mar.	Apr.	May	June	July	Aug.	Sept.	The year
1925	352	138	544	102	2,490	2,290	856	565	255	375	558	293	687
1926	289	1,120	1,160	738	1,380	2,810	1,270	311	783	176	685	576	872
1927	574	1,350	719	836	2,090	2,980	784	1,580	440	717	997	2,180	1,210
1928	920	3,430	2,440	1,650	1,970	1,590	2,150	1,210	1,760	2,740	1,730	966	1,900
1929	227	256	516	601	1,140	2,850	2,440	1,100	560	170	96.5	125	612
1930	496	757	1,050	951	1,040	1,890	925	428	486	274	156	365	728
1931	107	652	203	674	1,240	2,370	1,690	1,200	1,480	925	262	210	916
1932	108	122	978	1,140	1,350	1,050	1,970	682	519	178	103	51.4	631
1933	579	3,010	764	1,050	1,180	1,510	2,870	621	323	218	1,180	2,290	1,360
1934	505	589	731	1,734	404	1,963	2,766	1,162	487	291	144	1,082	1,032
1935	1,045	904	1,521	1,120	1,211	2,195	1,128	497	334	505	126	189	885
1936	157	1,496	891	1,510	483	5,447	2,261	611	527	337	146	110	1,184
1937	598	591	1,704	2,070	1,855	1,411	1,674	1,511	646	450	311	441	1,120
1938	330	1,367	1,247	1,731	1,608	1,743	1,792	625	756	2,306	1,177	7,664	1,564
1939	886	675	1,715	1,179	2,548	2,735	2,878	598	190	111	105	92.2	1,235
1940	262	787	548	970	414	2,982	4,302	1,378	1,331	584	181	767	1,085
1941	251	1,442	1,610	928	1,416	1,614	1,711	259	343	383	168	54.8	800
1942	62.4	262	589	712	1,060	2,541	919	556	483	518	1,547	680	853
1943	1,318	1,984	2,064	1,477	1,978	2,150	961	1,504	716	215	94.8	72.1	1,209
1944	451	1,530	288	598	913	2,089	2,230	697	320	110	60.5	126	763
1945	81.5	462	1,102	922	966	3,593	1,154	1,938	1,324	2,430	1,431	1,458	1,427
1946	775	1,355	2,034	1,976	548	1,890	465	1,155	1,095	380	197	155	1,000
1947	186	146	157	809	578	1,898	1,898	2,550	787	635	447	181	857
1948	90.8	1,477	536	418	1,321	5,716	2,102	1,644	1,073	609	233	68.1	1,106
1949	85.0	351	1,211	3,479	1,927	870	964	956	191	144	92.9	76.8	863
1950	94.7	154	487	893	1,120	2,603	1,295	1,258	1,140	474	222	226	861

Monthly and yearly runoff, in inches

Water year	Oct.	Nov.	Dec.	Jan.	Feb.	Mar.	Apr.	May	June	July	Aug.	Sept.	The year
1925	0.57	0.22	0.56	0.17	3.65	3.71	1.34	0.92	0.37	0.61	0.55	0.46	13.13
1926	.47	1.75	1.89	1.28	1.73	4.71	2.00	.50	.44	.79	1.11	.59	16.64
1927	.83	2.08	1.16	1.44	3.07	4.83	1.23	2.24	.69	.35	1.62	3.42	23.06
1928	3.11	5.55	4.31	1.67	2.89	2.26	2.27	1.81	2.76	4.44	2.80	1.52	36.39
1929	.37	.40	.50	.97	1.68	4.78	2.83	1.78	.57	.79	.16	.70	15.53
1930	.80	1.19	1.71	1.94	1.57	3.07	1.45	.69	.76	.56	.72	.57	13.88
1931	.17	.99	.50	1.03	1.82	3.76	2.66	1.95	2.35	1.80	.46	.35	17.50
1932	.17	.19	.61	1.89	2.00	1.71	3.09	1.11	.81	.79	.17	.08	12.08
1933	.94	4.72	1.24	1.66	1.75	4.07	4.51	1.02	.51	.19	1.06	3.39	26.04
1934	.95	.63	1.19	2.81	.59	3.18	4.34	1.88	.78	.47	.23	2.64	19.69
1935	1.70	1.42	2.14	1.62	1.77	3.86	1.76	.81	.52	.90	.20	.30	16.90
1936	.25	2.34	1.60	2.46	.75	9.64	5.55	.99	.51	.18	.24	.17	22.66
1937	.63	.61	2.77	4.34	2.72	2.28	2.02	2.46	1.01	.73	.50	.69	21.38
1938	.63	2.14	2.02	2.80	2.30	2.02	2.03	1.18	3.74	1.91	4.18	4.18	26.03
1939	1.44	1.37	4.83	1.91	3.73	4.44	4.52	.93	.50	.18	.17	.14	23.57
1940	.42	1.24	.87	.44	.65	4.85	6.70	1.91	1.77	.62	.29	1.70	20.72

Monthly and yearly runoff, in inches

Water year	Oct.	Nov.	Dec.	Jan.	Feb.
1941	0.41	2.26	2.61	1.57	2.27
1942	.10	.25	.82	1.25	2.27
1943	2.13	5.11	3.58	2.45	2.27
1944	.75	2.40	.47	.65	2.27
1945	.13	.72	1.60	1.48	1.44
1946	1.76	2.13	5.27	5.27	2.27
1947	.30	.25	.26	1.44	2.27
1948	.15	2.32	.67	.67	2.27
1949	.15	.55	1.96	5.86	2.27
1950	.15	.21	.81	1.44	2.27

Yearly discharge

Year	W.S.F. no.	Momentary maximum	
		Discharge	Date
1925	601	48,500	Feb. 17, 1925
1926	671	45,500	Mar. 3, 1926
1927	641	11,900	Sept. 7, 1927
1928	661	11,400	Nov. 2, 1928
1929	681	9,450	Mar. 6, 1929
1930	696	5,970	Sept. 17, 1930
1931	711	6,890	June 17, 1931
1932	726	7,530	Apr. 3, 1932
1933	741	10,600	Nov. 22, 1933
1934	756	6,840	Sept. 27, 1934
1935	781	6,550	Dec. 1, 1935
1936	801	18,000	Mar. 12, 1936
1937	821	6,300	May 15, 1937
1938	851	17,500	Sept. 22, 1938
1939	871	11,700	Dec. 8, 1939
1940	891	13,700	Mar. 31, 1940
1941	921	4,600	Dec. 29, 1941
1942	951	4,380	Mar. 9, 1942
1943	971	15,000	Dec. 30, 1943
1944	1001	9,300	Nov. 9, 1944
1945	1031	12,900	July 23, 1945
1946	1051	7,350	May 26, 1946
1947	1081	6,100	Apr. 6, 1947
1948	1111	15,700	Mar. 17, 1948
1949	1141	21,100	Dec. 8, 1949
1950	1171	1,690	Mar. 9, 1950

* Not previously published.

123. Wallkill

Location.--lat 41°44'50", long 74°01' Falluz, Ulster County.

Drainage area.--739 sq mi (revised).

Gage.--Chain gage. Altitude of gage

Monthly and yearly

Water year	Oct.	Nov.	Dec.	Jan.	Feb.
1901	578	517	3,328	2,128	229
1902	2,076	704	2,611	1,729	2,911
1904	4,286	-	-	-	-

* Corrected.
* Not previously published; partly corrected.

Monthly

Water year	Oct.	Nov.	Dec.	Jan.	Feb.
1901	0.82	0.78	5.18	3.34	1.24
1902	3.24	1.00	4.07	2.72	4.12
1904	6.09	-	-	-	-

* Corrected.
* Not previously published; partly corrected.

Yearly discharge

Year	W.S.F. no.	Momentary maximum	
		Discharge	Date
1902	97	-	-
1903	97	-	-

* Not previously published.
853550 O - 60 - 10

at Pine Bush, N. Y.

Water year	Calendar year	
	Runoff in inches	Mean
1926	12.60	119
1927	18.65	143
1928	29.51	297
1929	40.94	204
1930	27.71	212
1931	15.05	96.1
1932	17.11	125
1933	12.76	-

Monthly and yearly runoff, in inches, of Walkill River at Gardiner, N. Y.--Continued

Water year	Calendar year												The year
	Oct.	Nov.	Dec.	Jan.	Feb.	Mar.	Apr.	May	June	July	Aug.	Sept.	
1941	0.41	2.26	2.61	1.51	2.07	2.62	1.90	0.39	0.54	0.62	0.27	0.09	15.29
1942	1.10	.75	.92	1.12	1.53	4.12	1.44	.87	.76	.84	2.50	1.56	13.66
1943	2.13	2.11	3.55	2.43	2.80	3.49	1.51	2.44	1.12	.35	.15	.11	23.09
1944	.75	2.40	.47	.65	1.39	3.24	3.53	1.13	.50	.16	.10	.70	14.62
1945	.13	.72	1.68	1.48	1.44	6.31	1.81	3.14	1.76	3.94	2.37	2.29	27.22
1946	1.76	2.15	3.27	3.12	.80	3.06	.73	1.87	1.72	.62	.57	.21	19.11
1947	.50	.25	.74	1.44	.65	3.08	3.12	3.81	1.23	1.03	.73	.28	16.36
1948	.15	2.37	.87	.68	2.00	6.04	3.30	2.67	1.68	.99	.36	.11	21.19
1949	.13	.55	1.90	5.56	2.82	1.57	1.54	1.52	.30	.23	.15	.12	16.45
1950	.15	.21	.81	1.44	1.64	4.84	2.02	2.04	1.79	.77	.36	.22	17.42

S. Y.

ft upstream from highway bridge, less of a mile northwest of Gard-

above mean sea level, adjustment

1948 (gage height, 14.81 ft); minimum discharge, 20 cfs Sept.

flow caused by powerplant above

Date	feet per second				The year
	July	Aug.	Sept.		
1926	375	338	293		667
1927	776	685	376		872
1928	997	2,180			1,210
1929	1,750	966			1,800
1930	16	96	125		612
1931	224	136	365		728
1932	975	282	210		914
1933	176	103	51		431
1934	118	1,150	209		1,300
1935	291	144	1,662		1,052
1936	555	126	189		835
1937	112	146	110		1,194
1938	450	311	441		1,120
1939	2,306	1,177	2,664		1,364
1940	111	105	92		1,235
1941	364	161	767		1,093
1942	385	168	54		800
1943	516	542	880		833
1944	213	94	72		1,209
1945	110	60	126		763
1946	2,430	2,431	1,458		1,427
1947	360	197	133		1,000
1948	635	447	181		857
1949	609	233	68		1,106
1950	144	92	76		863
1951	474	222	226		602

Date	inches				The year
	July	Aug.	Sept.		
1926	0.61	0.55	0.46		13.13
1927	.29	1.11	.59		16.64
1928	.35	1.62	3.62		23.06
1929	4.44	2.80	1.52		36.39
1930	.29	.16	.20		15.53
1931	.36	.22	.57		13.88
1932	1.50	.46	.33		17.50
1933	.29	.17	.08		12.08
1934	.19	1.86	3.59		26.04
1935	.47	.73	2.84		19.69
1936	.90	.70	.30		16.90
1937	.18	.74	.17		22.66
1938	.73	.50	.69		21.38
1939	3.74	1.91	4.18		26.23
1940	.16	.17	.14		23.87
1941	.62	.29	1.70		20.72

Yearly discharge, in cubic feet per second

Year	W.S.F. no.	Water year ending Sept. 30						Calendar year	
		Momentary maximum		Minimum day	Mean	Per square mile	Runoff in inches	Mean	Runoff in inches
		Discharge	Date						
1925	601	68,500	Feb. 12, 1925	52	687	0.966	13.13	832	15.89
1926	621	45,500	Mar. 3, 1926	50	672	1.23	16.64	875	16.70
1927	641	12,900	Sept. 2, 1927	135	1,210	1.70	23.06	1,660	31.66
1928	661	11,400	Nov. 3, 1927	274	1,800	2.67	36.39	1,300	24.68
1929	681	9,450	Mar. 6, 1929	36	812	1.14	15.53	940	17.96
1930	690	5,970	Sept. 17, 1930	36	728	1.02	13.88	621	11.64
1931	711	6,990	June 17, 1931	70	916	1.29	17.50	881	16.81
1932	726	7,300	Apr. 1, 1932	73	631	.867	12.08	940	18.01
1933	741	10,600	Nov. 20, 1932	29	1,360	1.91	26.04	1,148	21.91
1934	756	6,840	Sept. 17, 1934	55	1,032	1.45	19.69	1,162	22.18
1935	781	6,530	Dec. 1, 1934	67	885	1.74	16.90	830	15.83
1936	801	16,000	Mar. 12, 1936	55	1,184	1.67	22.66	1,175	22.50
1937	821	8,500	May 15, 1937	54	1,120	1.58	21.38	1,160	22.14
1938	851	17,500	Sept. 22, 1938	99	1,364	1.92	26.03	1,491	28.45
1939	871	11,200	Dec. 6, 1938	41	1,235	1.74	23.87	975	18.58
1940	891	13,700	Mar. 21, 1940	62	1,083	1.52	20.72	1,243	23.77
1941	921	6,600	Dec. 29, 1940	33	800	1.13	15.29	591	11.26
1942	951	6,380	Mar. 9, 1942	34	833	1.17	15.88	1,216	23.20
1943	971	13,000	Dec. 30, 1942	44	1,209	1.70	23.09	948	18.10
1944	1001	9,320	Nov. 9, 1943	26	763	1.07	14.62	718	13.75
1945	1031	13,900	July 25, 1945	38	1,427	2.01	27.22	1,637	31.25
1946	1051	7,530	May 28, 1946	86	1,000	1.41	19.11	693	13.24
1947	1081	8,100	Apr. 6, 1947	72	857	1.22	16.56	990	18.91
1948	1111	13,700	Mar. 17, 1948	38	1,106	1.56	21.19	1,071	20.49
1949	1141	21,000	Dec. 31, 1948	36	863	1.71	16.45	785	14.98
1950	1171	7,690	Mar. 9, 1950	46	861	1.72	16.43	-	-

* Not previously published.

123. Walkill River at New Paltz, N. Y.

Location.--Lat 41°44'50", long 74°05'25", on downstream side of highway bridge in New Paltz, Ulster County.

Drainage area.--739 sq mi (revised).

Gage.--Chain gage. Altitude of gage is 180 ft (from topographic map).

Water year	Monthly and yearly mean discharge, in cubic feet per second												The year	
	Oct.	Nov.	Dec.	Jan.	Feb.	Mar.	Apr.	May	June	July	Aug.	Sept.		
1901	-	-	-	-	-	-	-	-	-	-	-	-	2,043	981
1902	528	517	3,325	2,139	739	7,188	1,878	913	394	918	742	820	1,691	1,691
1903	2,076	704	2,611	1,709	2,910	23,558	2,340	312	23,192	1,386	12,154	1994	11,897	11,897
1904	4,286	-	-	-	-	-	-	-	-	-	-	-	-	-

† Corrected. * Not previously published; partly estimated on basis of corrected gage readings.

Water year	Monthly and yearly runoff, in inches												The year	
	Oct.	Nov.	Dec.	Jan.	Feb.	Mar.	Apr.	May	June	July	Aug.	Sept.		
1901	-	-	-	-	-	-	-	-	-	-	-	-	3.19	1.48
1902	0.80	0.78	5.18	3.34	1.04	11.21	2.84	1.42	0.59	1.43	1.16	1.24	31.05	31.05
1903	3.74	1.06	4.07	2.70	4.10	45.55	3.53	.49	44.82	2.16	23.36	11.50	236.58	236.58
1904	6.69	-	-	-	-	-	-	-	-	-	-	-	-	-

† Corrected. * Not previously published; partly estimated on basis of corrected gage readings.

Year	W.S.F. no.	Water year ending Sept. 30						Calendar year		
		Momentary maximum		Minimum day	Mean	Per square mile	Runoff in inches	Mean	Runoff in inches	
		Discharge	Date							
1902	97	-	-	-	70	1,691	2.29	31.05	1,760	32.64
1903	97	-	-	-	121	27,892	22.70	236.58	-	-

* Not previously published.

Mill at Pine Bush, N. Y.

3715. Wallkill River at Gardiner, N. Y.

74°17'40", on left bank 50 ft downstream from top of Pine Bush, Orange County, 2 1/2 miles downstream above mouth at Ganahgote.

Location.--Lat 41°41'10", long 74°09'55", on left bank 400 ft upstream from highway bridge, 500 ft downstream from Shawangunk Kill, and three-quarters of a mile northwest of Gardiner, Ulster County.

Drainage.--711 sq mi.

Water 1932, June 1957 to September 1960.

Records available.--September 1924 to September 1960.

Site is 305 ft. revised (from topographic map). See site and datum.

Gage.--Water-stage recorder. Datum of gage is 185.70 ft above mean sea level, adjustment of 1912.

57-55), 158 cfs.

Average discharge.--36 years (1924-60), 1,074 cfs.

Stage, 7,350 cfs Sept. 1, 1927 (gage height, 19.9 ft), from rating curve extended above 2,300 cfs and height 8.07 ft, an estimated discharge in 1927. Direct measurements on Shawangunk Kill at Ganahgote; discharge in 1955 based on a floodmark at Ganahgote; minimum, 2.3 cfs July 21, 22, 1957; 1958.

Extremes.--1924-60: Maximum discharge, 30,800 cfs Oct. 16, 1955 (gage height, 19.81 ft); minimum, 19 cfs Aug. 9, 1955; minimum gage height, 1.83 ft Aug. 26, 1957.

Recorded a stage of about 12.5 ft, from floodmark at Ganahgote for each flood. Flood of 1955, 11.0 ft, from floodmarks (discharge, 7,200 cfs at Ganahgote).

Remarks.--Large diurnal fluctuations during low and medium flow caused by hydroelectric plant above station. Records of chemical analyses and water temperatures for the period October 1957 to September 1958 are published in report of the Geological Survey.

200 ft above station.

Monthly and yearly mean discharge, in cubic feet per second

Water year	Oct.	Nov.	Dec.	Jan.	Feb.	Mar.	Apr.	May	June	July	Aug.	Sept.	The year
1951	167	935	1,945	2,047	3,027	2,323	2,426	474	431	365	605	194	1,235
1952	361	2,027	1,776	2,673	1,675	2,689	3,780	2,101	2,516	617	501	1,382	1,834
1953	231	1,349	1,895	2,519	1,622	2,735	2,733	1,546	321	152	111	76.9	1,272
1954	113	365	1,841	622	1,160	1,554	975	1,869	228	85.4	63.0	260	761
1955	132	1,571	1,488	867	1,136	2,244	948	371	232	81.2	3,353	377	1,066
1956	4,217	2,595	493	740	1,955	1,886	3,332	1,601	463	627	184	331	1,531
1957	232	548	1,691	734	1,231	1,271	2,242	455	147	95.9	47.0	72.5	726
1958	122	226	1,724	1,809	999	3,565	3,163	1,925	374	222	136	211	1,212
1959	950	1,048	1,688	841	1,087	1,859	2,014	569	412	452	289	160	867
1960	1,133	1,295	1,780	1,585	2,017	1,078	2,793	529	500	389	1,620	2,447	1,424

Stage, in cubic feet per second

Apr.	May	June	July	Aug.	Sept.	The year
-	19.9	10.6	8.04	12.5	-	-
442	253	41.4	35.2	24.0	32.5	174
192	70.0	56.1	26.3	27.7	23.6	114
154	102	112	66.6	169	285	215

Daily runoff, in inches

Apr.	May	June	July	Aug.	Sept.	The year
-	0.22	0.12	0.09	0.14	-	-
4.58	.45	.40	.27	.36	23.22	-
3.12	.61	.30	.31	.26	15.19	-
4.22	1.15	1.23	.75	1.91	3.12	28.74

in cubic feet per second

By Sept. 30			Calendar year		
Mean	Per square mile	Runoff in inches	Mean	Runoff in inches	
174	1.71	23.22	176	23.47	
114	1.12	15.19	139	18.50	
215	2.11	28.74	-	-	

Monthly and yearly runoff, in inches

Water year	Oct.	Nov.	Dec.	Jan.	Feb.	Mar.	Apr.	May	June	July	Aug.	Sept.	The year
1951	0.27	1.47	3.15	3.32	4.43	3.77	3.61	0.77	0.68	0.62	0.98	0.30	23.57
1952	.58	3.16	2.88	4.33	2.54	4.36	5.93	3.41	3.95	1.00	.81	2.14	35.11
1953	.37	2.12	3.07	4.08	2.38	4.44	4.29	2.51	.50	.21	.18	.12	24.27
1954	.16	.57	2.99	1.01	1.70	2.52	1.53	3.03	.36	.14	.10	.41	14.54
1955	.21	2.47	2.41	1.41	1.67	3.64	1.49	.60	.36	.13	5.41	.59	20.39
1956	6.84	4.06	.80	1.20	2.97	3.06	5.25	2.60	.73	1.02	.30	.52	29.33
1957	.38	.86	2.74	1.19	1.80	2.06	3.52	.74	.23	.16	.08	.11	13.87
1958	.20	.35	2.80	3.03	1.46	5.78	4.96	3.12	.51	.36	.22	.35	23.12
1959	1.59	1.64	1.18	1.36	1.59	3.01	3.16	.92	.65	.75	.47	.25	16.55
1960	1.84	2.03	2.89	2.57	3.06	1.75	4.36	.86	.78	.63	2.63	3.84	27.26

Yearly discharge, in cubic feet per second

Year	WSP	Water year ending Sept. 30					Calendar year		
		Momentary maximum		Minimum day	Mean	Per square mile	Runoff in inches	Mean	Runoff in inches
		Discharge	Date						
1950	-	-	-	-	-	-	-	1,056	20.13
1951	1202	12,600	Mar. 31, 1951	65	1,235	1.74	23.57	1,326	25.32
1952	1232	21,200	June 1, 1952	106	1,834	2.58	35.11	1,778	34.23
1953	1272	13,000	Jan. 24, 1953	34	1,272	1.79	24.27	1,176	22.45
1954	1322	8,610	Dec. 7, 1953	32	761	1.07	14.54	632	15.89
1955	1382	30,600	Aug. 19, 1955	21	1,068	1.50	20.39	1,414	27.00
1956	1432	30,800	Oct. 16, 1955	125	1,531	2.15	29.33	1,198	21.61
1957	1502	7,160	Apr. 6, 1957	22	726	1.02	13.87	635	13.24
1958	1572	9,270	Dec. 21, 1957	38	1,212	1.70	23.12	1,267	24.18
1959	1622	7,500	Jan. 22, 1959	65	867	1.22	16.55	890	18.90
1960	1702	10,200	Sept. 13, 1959	130	1,424	2.00	27.26	-	-

CENTRAL HUDSON GAS
AND
ELECTRIC CORPORATION
DASHVILLE HYDRO GENERATING PLANT
REPORT
ON
PROPOSED PLANT
RETIREMENT CONSIDERATIONS

MAIN
Chas. T. Main of New York, Inc.

March, 1973

1050-31

HYDROLOGY & FLOOD STUDY

The Dashville Hydro Generating Plant, located on the Walkill River, commands an area of about 789 square miles and has been subject to many flood situations.

The closest U.S. stream gaging station is at Gardiner and commands an area of 711 square miles and has a period of record extending from 1924. A return period analysis of the annual peak flows was made and the results of this analysis are presented in Table I.

TABLE I
FLOOD FREQUENCY

<u>Return Period - Years</u>	<u>Annual Peaks - cfs</u>
2	9,100
5	14,300
10	18,000
20	21,800
50	27,000
100	31,300
500	41,900
1000	47,200

The flood of September 1960 was analyzed and adopted for use in the derivation of a unit hydrograph for the Walkill River at the Gardiner gaging site. To this unit hydrograph were applied the appropriate 12-hour rainfall excess values for the Probable Maximum Precipitation (PMP), as taken from the Joint U.S. Weather Bureau - Corps of Engineers Hydrometeorological Report No. 33, and corrected for infiltration losses to obtain a Probable Maximum Flood (PMF) at Gardiner.

A comparison of several major flood peaks showed a significant reduction in these peaks from the Gardiner gage to the Dashville Project. This observation led to the conclusion that valley storage, a very common phenomenon in northerly or northeasterly flowing streams in this area, was the cause for this reduction and so it was investigated further. Profiles of the 1955 storms showed that this storage probably occurred upstream of Perrines' Bridge and

the U.S.C. & G.S. maps confirmed this hypothesis. The hydrograph comparison between Gardiner and the project for the two floods of 1955 served to establish the intervening valley storage quantitatively so that a storage curve was derived.

It is current practice to reduce the Probable Maximum Flood by 40 percent to 50 percent to give a Standard Project Flood (SPF) for use in assessing spillway adequacy.

Therefore, the PMF discharge ordinates were reduced 40 percent to obtain the SPF inflow hydrographs which were in turn increased by a factor of 1.1 to compensate for the increase in drainage area between the Gardiner gage and assumed point of valley storage. This SPF hydrograph was routed through the valley storage and over the Dashville Project spillway.

The peak SPF inflow into the natural storage was 62,000 cfs which was reduced by this storage to a peak outflow of 38,000 cfs. This outflow hydrograph was then routed over the project spillway with a peak discharge of 38,000 cfs and a maximum headwater surface elevation of 179.0 and a maximum tailwater elevation of 142.0. Predicated upon the foregoing data, the SPF has a theoretical return period as an annual flood of about 500 years.

#DIVIDE

BEGIN

PEAK U

APPENDIX E
STRUCTURAL STABILITY ANALYSES

PROJECT GRID

JOB	DASHVILLE DAM	SHEET NO.	1	CHECKED BY		DATE	
SUBJECT	STRUCTURAL STABILITY ANALYSIS			COMPUTED BY	RLW	DATE	4/30/79
MAXIMUM SECTION OF THE DAM							
REVISION OF STABILITY PROGRAM RESULTS							
SINCE INTERFACE OF ROCK & DAM IS NOT SMOOTH							
THEN CONCRETE WOULD HAVE TO SHEAR FOR A SLIDING							
FAILURE TO OCCUR.							
∴ USE THE FOLLOWING FORMULA							
$F.S._{\text{SLIDING}} = \frac{\text{RESISTING FORCE} + (S_A)(A)}{\text{DRIVING FORCE}}$							
$S_A = \text{SHEARING STRENGTH OF CONCRETE}$							
$A = \text{AREA OF BASE}$							
NORMAL CONDITIONS - USING RESULTS FROM STABILITY PROGRAM							
$F.S._{\text{SLIDING}} = \frac{66.69 + 0.15 \left[\frac{42(1)(14)}{11.5} \right]}{61.33} = 15.88$							
ICE LOADING							
$F.S._{\text{SLIDING}} = \frac{66.69 + 0.15 \left[\frac{42(1)(14)}{11.5} \right]}{66.33} = 14.68$							
1/2 PMF - (WATER LEVEL 13.8' ABOVE CREST)							
$F.S._{\text{SLIDING}} = \frac{62.29 + 0.15 \left[\frac{42(1)(14)}{11.5} \right]}{94.06} = 10.31$							
PMF - (WATER LEVEL 22.8' ABOVE CREST)							
$F.S._{\text{SLIDING}} = \frac{62.29 + 0.15 \left[\frac{42(1)(14)}{11.5} \right]}{115.40} = 8.40$							

OPE HYD ROUT HYDR Z C ROUT


00-15-1 (3/78)
Formerly GA-17

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

PROJECT GRID


JOB	SHEET NO.	CHECKED BY	DATE
DASHVILLE DAM	2		
SUBJECT	COMPUTED BY		DATE
STRUCTURAL STABILITY ANALYSIS	RLW		5/28/79
MINIMUM SECTION OF THE DAM			
REVISION OF STABILITY PROGRAM RESULTS TO ACCOUNT FOR			
ROUGH SURFACE.			
NORMAL CONDITIONS			
$F.S._{SLIDING} = \frac{2.11 + .15 \left[\frac{2.11 + .15}{1.06} \right]}{1.06} = 266.9$			
ICE LOADING			
$F.S._{SLIDING} = \frac{2.11 + .15 \left[\frac{2.11 + .15}{6.06} \right]}{6.06} = 46.68$			
1/2 PMF			
$F.S._{SLIDING} = \frac{2.11 + .15 \left[\frac{2.11 + .15}{5.36} \right]}{5.36} = 52.78$			
PMF			
$F.S._{SLIDING} = \frac{2.11 + .15 \left[\frac{2.11 + .15}{8.17} \right]}{8.17} = 34.62$			

DASHVILLE DAM N.Y. 76 - MAXIMUM SECTION



SECTION No.	AREA (sq ft)	DISTANCE FROM TOE (ft)
①	$(30)(6) = 228$	$18 + 2 \times 3 = 33$
②	$(33.5)(12) = 402$	$18 + 6 = 24$
③	$\frac{1}{2}(27)(18) = 243$	12
④	$\frac{1}{2}(6)(9) = 27$	$18 + 12 + 5 + 2 = 37$

DASHVILLE DAM - N.Y. 76 - MINIMUM SECTION



170

160

INPUT TO STABILITY ANALYSIS PROGRAM

<u>INPUT ENTRY</u>	<u>PROGRAM No.</u>
Unit Weight of Dam (K/ft^3)	0
Area of Segment No. 1 (ft^2)	1
Distance from Center of Gravity of Segment No. 1 to Downstream Toe (ft)	2
Area of Segment No. 2 (ft^2)	3
Distance from Center of Gravity of Segment No. 2 to Downstream Toe (ft)	4
Area of Segment No. 3 (ft^2)	5
Distance from Center of Gravity of Segment No. 3 to Downstream Toe (ft)	6
Base Width of Dam (Total) (ft)	7
Height of Dam (ft)	8
Ice Loading (K/L ft.)	9
Coefficient of Sliding	10
Unit Weight of Soil (K/ft^3)	11
Active Soil Coefficient - K_a	12
Passive Soil Coefficient - K_p	13
Height of Water over Top of Dam or Spillway (ft)	14
Height of Soil for Active Pressure (ft)	15
Height of Soil for Passive Pressure (ft)	16
Height of Water in Tailrace Channel (ft)	17
Weight of Water (K/ft^3)	18
Area of Segment No. 4 (ft^2)	19
Distance from Center of Gravity of Segment No. 4 to Downstream Toe (ft)	20
Height of Ice Load or Active Water (ft)	46

MAXIMUM SECTION

NORMAL CONDITIONS

ICE LOAD

5 KSF

0.15	RCL 1	0.15	RCL 1
238.		238.	
238.	RCL 2	238.	RCL 2
38.		38.	
38.	RCL 3	38.	RCL 3
402.		402.	
402.	RCL 4	402.	RCL 4
24.		24.	
24.	RCL 5	24.	RCL 5
243.		243.	
243.	RCL 6	243.	RCL 6
12.		12.	
12.	RCL 7	12.	RCL 7
42.		42.	
42.	RCL 8	42.	RCL 8
38.		38.	
38.	RCL 9	38.	RCL 9
0.		5.	
0.	RCL 10	5.	RCL 10
0.6		0.6	
0.6	RCL 11	0.6	RCL 11
0.055		0.055	
0.055	RCL 12	0.055	RCL 12
0.41		0.41	
0.41	RCL 13	0.41	RCL 13
5.8		5.8	
5.8	RCL 14	5.8	RCL 14
0.		0.	
0.	RCL 15	0.	RCL 15
38.		38.	
38.	RCL 16	38.	RCL 16
10.		10.	
10.	RCL 17	10.	RCL 17
0.5		0.5	
0.5	RCL 18	0.5	RCL 18
0.0624		0.0624	
0.0624	RCL 19	0.0624	RCL 19
27.		27.	
27.	RCL 20	27.	RCL 20
38.		38.	
38.	RCL 46	38.	RCL 46
38.		38.	

F. of S.

OVERTURNING

SLIDING

1.476960508
12.29460563
1.087287128

1.358971127
10.05248399
1.005331512

MAXIMUM SECTION

1/2 PMF

0.15	RCL	1
338.	RCL	2
338.	RCL	2
33.	RCL	3
33.	RCL	3
402.	RCL	4
402.	RCL	4
24.	RCL	5
24.	RCL	5
243.	RCL	6
243.	RCL	6
12.	RCL	7
12.	RCL	7
42.	RCL	8
42.	RCL	8
38.	RCL	9
38.	RCL	9
0.	RCL	10
0.	RCL	10
0.6	RCL	11
0.6	RCL	11
0.055	RCL	12
0.055	RCL	12
0.41	RCL	13
0.41	RCL	13
5.8	RCL	14
5.8	RCL	14
13.8	RCL	15
13.8	RCL	15
38.	RCL	16
38.	RCL	16
10.	RCL	17
10.	RCL	17
9.	RCL	18
9.	RCL	18
0.0624	RCL	19
0.0624	RCL	19
27.	RCL	20
27.	RCL	20
38.	RCL	46
38.	RCL	46
38.	RCL	46

PMF

0.15	RCL	1
338.	RCL	2
338.	RCL	2
33.	RCL	3
33.	RCL	3
402.	RCL	4
402.	RCL	4
24.	RCL	5
24.	RCL	5
243.	RCL	6
243.	RCL	6
12.	RCL	7
12.	RCL	7
42.	RCL	8
0.	RCL	8
38.	RCL	9
38.	RCL	9
0.	RCL	10
0.	RCL	10
0.6	RCL	11
0.6	RCL	11
0.055	RCL	12
0.055	RCL	12
0.41	RCL	13
0.41	RCL	13
5.8	RCL	14
5.8	RCL	14
22.8	RCL	15
22.8	RCL	15
38.	RCL	16
38.	RCL	16
10.	RCL	17
10.	RCL	17
15.	RCL	18
15.	RCL	18
0.0624	RCL	19
0.0624	RCL	19
27.	RCL	20
27.	RCL	20
38.	RCL	46
38.	RCL	46
38.	RCL	46

1.00 049575
2.897296549

F. of S.
OVERTURNING
SLIDING

.937 873537
-3.30155864
0.5

MINIMUM SECTION

NORMAL CONDITIONS

ICE LOAD 5 ksf

0.15	RCL	0.15	RCL
	1		1
17.5		17.5	
17.5	RCL	17.5	RCL
	2		2
8.8		8.8	
8.8	RCL	8.8	RCL
	3		3
7.5		7.5	
7.5	RCL	7.5	RCL
	4		4
5.7		5.7	
5.7	RCL	5.7	RCL
	5		5
12.5		12.5	
12.5	RCL	12.5	RCL
	6		6
3.3		3.3	
3.3	RCL	3.3	RCL
	7		7
13.5		13.5	
13.5	RCL	13.5	RCL
	8		8
5.		5.	
5.	RCL	5.	RCL
	9		9
0.		5.	
0.	RCL	5.	RCL
	10		10
0.6		0.6	
0.6	RCL	0.6	RCL
	11		11
0.055		0.055	
0.055	RCL	0.055	RCL
	12		12
0.41		0.41	
0.41	RCL	0.41	RCL
	13		13
5.8		5.8	
5.8	RCL	5.8	RCL
	14		14
0.		0.	
0.	RCL	0.	RCL
	15		15
5.		5.	
5.	RCL	5.	RCL
	16		16
0.		0.	
0.	RCL	0.	RCL
	17		17
0.		0.	
0.	RCL	0.	RCL
	18		18
0.0624		0.0624	
0.0624	RCL	0.0624	RCL
	19		19
0.		0.	
0.	RCL	0.	RCL
	20		20
0.		0.	
0.	RCL	0.	RCL
	46		46
5.		5.	

1. 722457734
4. 255013678
1. 988067629

F. of S.
OVERTURNING
SLIDING

. 7807751435
-2. 848477314
0. 348000073

MINIMUM SECTION

$\frac{1}{2}$ PMF		PMF	
0.15	RCL 1	0.15	RCL 1
17.5		17.5	
17.5	RCL 2	17.5	RCL 2
8.8		8.8	
8.8	RCL 3	8.8	RCL 3
7.5		7.5	
7.5	RCL 4	7.5	RCL 4
5.7		5.7	
5.7	RCL 5	5.7	RCL 5
12.5		12.5	
12.5	RCL 6	12.5	RCL 6
3.3		3.3	
3.3	RCL 7	3.3	RCL 7
13.5		13.5	
13.5	RCL 8	13.5	RCL 8
5.		5.	
5.	RCL 9	5.	RCL 9
0.		0.	
0.	RCL 10	0.	RCL 10
0.6		0.6	
0.6	RCL 11	0.6	RCL 11
0.055		0.055	
0.055	RCL 12	0.055	RCL 12
0.41		0.41	
0.41	RCL 13	0.41	RCL 13
5.8		5.8	
5.8	RCL 14	5.8	RCL 14
13.8		22.8	
13.8	RCL 15	22.8	RCL 15
5.		5.	
5.	RCL 16	5.	RCL 16
0.		0.	
0.	RCL 17	0.	RCL 17
0.		0.	
0.	RCL 18	0.	RCL 18
0.0624		0.0624	
0.0624	RCL 19	0.0624	RCL 19
0.		0.	
0.	RCL 20	0.	RCL 20
0.		0.	
0.	RCL 46	0.	RCL 46
5.		5.	

1.193072745
 1.196990149
 .3903693217

F. of S.
 OVERTURNING
 SLIDING

.9270851029
 .7970847618
 .2582602284

CENTRAL HUDSON GAS
AND
ELECTRIC CORPORATION
DASHVILLE HYDRO GENERATING PLANT
REPORT
ON
PROPOSED PLANT
RETIREMENT CONSIDERATIONS

MAIN
Chas. T. Main of New York, Inc.

March, 1973

1050-31

STRUCTURAL STABILITY ANALYSIS

A structural stability analysis of all water retaining structures in their final altered condition was performed to verify that the structures would be stable under the assumed loadings as presented in Table II. The results of the analysis, as presented in Table IV, indicate that the structures are stable under the loadings as assumed. Tables II and III list the loading cases checked and values and assumptions used in the above analysis.

The safety factors of the structures were checked with respect to overturning and sliding at their bases, and computations were made to check the foundation pressures at this elevation.

The safety factor with respect to overturning is the ratio of the forces (the weight of structure) times their lever arms (moments) tending to prevent the structure from tipping to the forces (moments) tending to tip the structure (the water pressure exerted on the upstream face and beneath the structure). Any safety factor that is equal to 1.0 would theoretically indicate that the structure is stable, with any lesser value placing it at the verge of being unstable. By referring to Table IV, under the column headed $\Sigma Mr / \Sigma Mo$, for all cases considered, the structures are stable with respect to overturning.

The safety factor with respect to sliding including shear-friction resistance is the ratio of the forces tending to resist sliding; namely, the frictional resistance due to the net weight of the structure sliding along its base and the resistance due to the shearing strength developed between the structure and its rock foundation, and the forces tending to promote sliding; namely, the water pressure at the upstream face. It is normally accepted that this ratio be as a minimum 5.0. By referring to Table IV, under the column headed S_{s-f} for all cases considered, the structures are stable with respect to sliding.

During the last field inspection it was noted that silt had accumulated to within 1-1/2 feet from the top of the flashboards at the left abutment and was impeding their removal. It was decided that the additional pressure resulting from the silt should be incorporated into the stability analysis to reflect this observed condition.

TABLE II
CASES USED
STABILITY ANALYSIS

Case I	Normal Levels (proposed) H.W.L. = 170.0 T.W.L. = 133.75 Uplift Included
Case II	Standard Project Flood Water Levels H.W.L. = 179.0 T.W.L. = 142.0 Uplift Included

**TABLE III
VALUES AND ASSUMPTIONS
STABILITY ANALYSIS
CONCRETE SECTIONS**

1. Nomenclature

ΣH = Summation of Horizontal Forces

ΣV = Summation of Vertical Forces

ΣM_R = Summation of Resisting Moments

ΣM_O = Summation of Overturning Moments

$\frac{\Sigma M_R}{\Sigma M_O}$ = Factor of Safety Against Overturning

$\frac{\Sigma H}{\Sigma V}$ = Coefficient of Sliding

2. Unit weight of concrete - 150 lbs/cu. ft.
3. Unit weight of water - 62.4 lbs/cu. ft.
4. Silt pressure: The horizontal silt pressure was assumed to be equal to $14(h_s)^2$ lbs, where h_s = height of silt. Unit weight of silt -90 lbs/cu. ft.
5. Uplift Pressure: The pressure was assumed to vary linearly from full headwater pressure at the upstream side to full tailwater pressure at the downstream side taken over 100% of the base area.
6. Sliding (Shear Included) For a discussion and explanation of terms, see Hydroelectric Handbook by Creager and Justin, John Wiley & Sons, Inc., Second Edition - Page 341.

$$S_{s-f} = \frac{f \Sigma V + r S_a A}{\Sigma H}$$

Where:

S_{s-f} = Shear Friction Factor of Safety
 $f = 0.75$; $r=0.5$; $S_a=380$ psi; A =Area of base

TABLE IV

STABILITY SUMMARY

SECTION	CONDITION	BASE ELEV.		BASE LENGTH	Σ H (KIPS)	Σ V (KIPS)	Σ H / Σ V	S _{s-1}	RESULTANT FROM DOWNSTREAM	Σ M _R (K-FT)	Σ M ₀ (K-FT)	Σ M _R / Σ M ₀	BASE STRESS (PSI)	
		I	II										UPSTREAM	DOWNSTREAM
POWERHOUSE INTAKE STRUCTURE	I - NORMAL	115.0	115.0	59.92	2739	7359	0.37	35.7	16.0	364,842	247,030	1.48	- 4.6	38.5
	II - FLOOD	115.0	115.0	59.92	3927	7105	0.55	24.8	11.3	444,864	364,705	1.22	-11.3	44.4
OGEE SPILLWAY	I - NORMAL	133.3	133.3	39.0	53.8	90.4	0.60	21.1	15.6	3,169	1,756	1.80	9	23
	II - FLOOD	133.3	133.3	39.0	71.5	76.7	0.93	15.7	10.3	3,357	2,568	1.31	- 5.7	33

NOTE:

1. NEGATIVE BASE STRESS INDICATES TENSION.
2. THE SILT LOADING FOR THE POWERHOUSE INTAKE STRUCTURE WAS NOT CONSIDERED SINCE THE OMISSION OF THE LOADING WAS FOUND TO BE A MORE CRITICAL CONDITION.

March 1973

CENTRAL HUDSON GAS & ELECTRIC CORP.
POUGHKEEPSIE, NEW YORK
DASHVILLE HYDRO

CONCRETE SECTIONS ANALYZED FOR STABILITY

MAIN

CHAS. T. MAIN OF NEW YORK, INC.

APPENDIX F

REFERENCES

REFERENCES

- 1) Conservation Commission - New York State; Dashville Dam;
 - a) Computation sheets - October 23-25, 1919
 - b) Memorandum - November 3, 1919

- 2) US Department of the Interior, Bureau of Reclamation;
Design of Small Dams, 2nd edition (Rev. reprint), 1977

- 3) US Geological Survey; Compilation of Records of Surface Waters of the United States, Part 1-B North Atlantic Slope Basins;
Water Supply Paper 1302 (Through September 1950), 1960
Water Supply Paper 1722 (October 1950 to September 1960), 1964

- 4) George, Thomas S. and Taylor, Robert S.; Lower Hudson River Basin Hydrologic Flood Routing Model, for the Department of the Army, New York District, Corps of Engineers, Water Resources Engineers Inc, January 1977

- 5) L.R. Kimball and Associates; Phase 1 Inspection Report - Sturgeon Pool Dam NY-75, for the Department of the Army, New York District, Corps of Engineers, September 1978

- 6) H.W. King and E.F. Brater; Handbook of Hydraulics, 5th edition, McGraw-Hill, 1963

- 7) C.T. Main of New York, Inc.; Dashville Hydro Generating Plant- Report on Proposed Plant Retirement Considerations, for Central Hudson Gas and Electric Corporation, March 1973

- 8) University of the State of New York; Geology of New York, Education Leaflet 20, reprinted 1973

APPENDIX G
CORPS OF ENGINEERS
GUIDELINES

Reclamation and Soil Conservation Service. Many other agencies, educational facilities and private consultants can also provide expert advice. Regardless of where such expertise is based, the qualification of those individuals offering to provide it should be carefully examined and evaluated.

4.3.4. Freeboard Allowances. Guidelines on specific minimum freeboard allowances are not considered appropriate because of the many factors involved in such determinations. The investigator will have to assess the critical parameters for each project and develop its minimum requirement. Many projects are reasonably safe without freeboard allowance because they are designed for overtopping, or other factors minimize possible overtopping. Conversely, freeboard allowances of several feet may be necessary to provide a safe condition. Parameters that should be considered include the duration of high water levels in the reservoir during the design flood; the effective wind fetch and reservoir depth available to support wave generation; the probability of high wind speed occurring from a critical direction; the potential wave runup on the dam based on roughness and slope; and the ability of the dam to resist erosion from overtopping waves.

4.4. Stability Investigations. The Phase II stability investigations should be compatible with the guidelines of this paragraph.

4.4.1. Foundation and Material Investigations. The scope of the foundation and materials investigation should be limited to obtaining the information required to analyze the structural stability and to investigate any suspected condition which would adversely affect the safety of the dam. Such investigations may include borings to obtain concrete, embankment, soil foundation, and bedrock samples; testing specimens from these samples to determine the strength and elastic parameters of the materials, including the soft seams, joints, fault gouge and expansive clays or other critical materials in the foundation; determining the character of the bedrock including joints, bedding planes, fractures, faults, voids and caverns, and other geological irregularities; and installing instruments for determining movements, strains, suspected excessive internal seepage pressures, seepage gradients and uplift forces. Special investigations may be necessary where suspect rock types such as limestone, gypsum, salt, basalt, claystone, shales or others are involved in foundations or abutments in order to determine the extent of cavities, piping or other deficiencies in the rock foundation. A concrete core drilling program should be undertaken only when the existence of significant structural cracks is suspected or the general qualitative condition of the concrete is in doubt. The tests of materials will be necessary only where such data are lacking or are outdated.

4.4.2. Stability Assessment. Stability assessments should utilize in situ properties of the structure and its foundation and pertinent geologic

information. Geologic information that should be considered includes groundwater and seepage conditions; lithology, stratigraphy, and geologic details disclosed by borings, "as-built" records, and geologic interpretation; maximum past overburden at site as deduced from geologic evidence; bedding, folding and faulting; joints and joint systems; weathering; slickensides, and field evidence relating to slides, faults, movements and earthquake activity. Foundations may present problems where they contain adversely oriented joints, slickensides or fissured material, faults, seams of soft materials, or weak layers. Such defects and excess pore water pressures may contribute to instability. Special tests may be necessary to determine physical properties of particular materials. The results of stability analyses afford a means of evaluating the structure's existing resistance to failure and also the effects of any proposed modifications. Results of stability analyses should be reviewed for compatibility with performance experience when possible.

4.4.2.1. Seismic Stability. The inertial forces for use in the conventional equivalent static force method of analysis should be obtained by multiplying the weight by the seismic coefficient and should be applied as a horizontal force at the center of gravity of the section or element. The seismic coefficients suggested for use with such analyses are listed in Figures 1 through 4. Seismic stability investigations for all high hazard category dams located in Seismic Zone 4 and high hazard dams of the hydraulic fill type in Zone 3 should include suitable dynamic procedures and analyses. Dynamic analyses for other dams and higher seismic coefficients are appropriate if in the judgment of the investigating engineer they are warranted because of proximity to active faults or other reasons. Seismic stability investigations should utilize "state-of-the-art" procedures involving seismological and geological studies to establish earthquake parameters for use in dynamic stability analyses and, where appropriate, the dynamic testing of materials. Stability analyses may be based upon either time-history or response spectra techniques. The results of dynamic analyses should be assessed on the basis of whether or not the dam would have sufficient residual integrity to retain the reservoir during and after the greatest or most adverse earthquake which might occur near the project location.

4.4.2.2. Clay Shale Foundation. Clay shale is a highly overconsolidated sedimentary rock comprised predominantly of clay minerals, with little or no cementation. Foundations of clay shales require special measures in stability investigations. Clay shales, particularly those containing montmorillonite, may be highly susceptible to expansion and consequent loss of strength upon unloading. The shear strength and the resistance to deformation of clay shales may be quite low and high pore water pressures may develop under increase in load. The presence of slickensides in clay shales is usually an indication of low shear strength. Prediction

AD-A075 891

NEW YORK STATE DEPT OF ENVIRONMENTAL CONSERVATION ALBANY F/G 13/2
NATIONAL DAM SAFETY PROGRAM DASHVILLE DAM, INVENTORY NUMBER (NY--ETC(U)
SEP 79 G KOCH DACW51-79-C-0001

UNCLASSIFIED


NL

2 OF 2

AD
A075 891



END
DATE
FILMED
12-79
DDC



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

of field behavior of clay shales should not be based solely on results of conventional laboratory tests since they may be misleading. The use of peak shear strengths for clay shales in stability analyses may be unconservative because of nonuniform stress distribution and possible progressive failures. Thus the available shear resistance may be less than if the peak shear strength were mobilized simultaneously along the entire failure surface. In such cases, either greater safety factors or residual shear strength should be used.

4.4.3. Embankment Dams.

4.4.3.1. Liquefaction. The phenomenon of liquefaction of loose, saturated sands and silts may occur when such materials are subjected to shear deformation or earthquake shocks. The possibility of liquefaction must presently be evaluated on the basis of empirical knowledge supplemented by special laboratory tests and engineering judgment. The possibility of liquefaction in sands diminishes as the relative density increases above approximately 70 percent. Hydraulic fill dams in Seismic Zones 3 and 4 should receive particular attention since such dams are susceptible to liquefaction under earthquake shocks.

4.4.3.2. Shear Failure. Shear failure is one in which a portion of an embankment or of an embankment and foundation moves by sliding or rotating relative to the remainder of the mass. It is conventionally represented as occurring along a surface and is so assumed in stability analyses, although shearing may occur in a zone of substantial thickness. The circular arc or the sliding wedge method of analyzing stability, as pertinent, should be used. The circular arc method is generally applicable to essentially homogeneous embankments and to soil foundations consisting of thick deposits of fine-grained soil containing no layers significantly weaker than other strata in the foundation. The wedge method is generally applicable to rockfill dams and to earth dams on foundations containing weak layers. Other methods of analysis such as those employing complex shear surfaces may be appropriate depending on the soil and rock in the dam and foundation. Such methods should be in reputable usage in the engineering profession.

4.4.3.3. Loading Conditions. The loading conditions for which the embankment structures should be investigated are (I) Sudden drawdown from spillway crest elevation or top of gates, (II) Partial pool, (III) Steady state seepage from spillway crest elevation or top of gate elevation, and (IV) Earthquake. Cases I and II apply to upstream slopes only; Case III applies to downstream slopes; and Case IV applies to both upstream and downstream slopes. A summary of suggested strengths and safety factors are shown in Table 4.

4.4.3.6. Seepage Analyses. Review and modifications to original seepage design analyses should consider conditions observed in the field inspection and piezometer instrumentation. A seepage analysis should consider the permeability ratios resulting from natural deposition and from compaction placement of materials with appropriate variation between horizontal and vertical permeability. An underseepage analysis of the embankment should provide a critical gradient factor of safety for the maximum head condition of not less than 1.5 in the area downstream of the embankment.

$$F.S = i_c/i = \frac{H_c/D_b}{H/D_b} = D_b \frac{(\gamma_m - \gamma_w)}{H \gamma_w} \quad (2)$$

i_c = Critical gradient

i = Design gradient

H = Uplift head at downstream toe of dam measured above tailwater

H_c = The critical uplift

D_b = The thickness of the top impervious blanket at the downstream toe of the dam

γ_m = The estimated saturated unit weight of the material in the top impervious blanket

γ_w = The unit weight of water

Where a factor of safety less than 1.5 is obtained the provision of an underseepage control system is indicated. The factor of safety of 1.5 is a recommended minimum and may be adjusted by the responsible engineer based on the competence of the engineering data.

4.4.4. Concrete Dams and Appurtenant Structures.

4.4.4.1. Requirements for Stability. Concrete dams and structures appurtenant to embankment dams should be capable of resisting overturning, sliding and overstressing with adequate factors of safety for normal and maximum loading conditions.

4.4.4.2. Loads. Loadings to be considered in stability analyses include the water load on the upstream face of the dam; the weight of the structure; internal hydrostatic pressures (uplift) within the body of the dam, at the base of the dam and within the foundation; earth and silt loads; ice pressure, seismic and thermal loads, and other loads as applicable. Where tailwater or backwater exists on the downstream side of the structure it should be considered, and assumed uplift pressures should be compatible with drainage provisions and uplift measurements if available. Where applicable, ice pressure should be applied to the contact surface of the structure at normal pool elevation. A unit pressure of not more than 5,000 pounds per square foot should be used. Normally, ice thickness should not be assumed greater than two feet. Earthquake forces should consist of the inertial forces due to the horizontal acceleration of the dam itself and hydrodynamic forces resulting from the reaction of the reservoir water against the structure. Dynamic water pressures for use in conventional methods of analysis may be computed by means of the "Westergaard Formula" using the parabolic approximation (H.M. Westergaard, "Water Pressures on Dams During Earthquakes," Trans., ASCE, Vol 98, 1933, pages 418-433), or similar method.

4.4.4.3. Stresses. The analysis of concrete stresses should be based on in situ properties of the concrete and foundation. Computed maximum compressive stresses for normal operating conditions in the order of 1/3 or less of in situ strengths should be satisfactory. Tensile stresses in unreinforced concrete should be acceptable only in locations where cracks will not adversely affect the overall performance and stability of the structure. Foundation stresses should be such as to provide adequate safety against failure of the foundation material under all loading conditions.

4.4.4.4. Overturning. A gravity structure should be capable of resisting all overturning forces. It can be considered safe against overturning if the resultant of all combinations of horizontal and vertical forces, excluding earthquake forces, acting above any horizontal plane through the structure or at its base is located within the middle third of the section. When earthquake is included the resultant should fall within the limits of the plane or base, and foundation pressures must be acceptable. When these requirements for location of the resultant are not satisfied the investigating engineer should assess the importance to stability of the deviations.

4.4.4.5. Sliding. Sliding of concrete gravity structures and of abutment and foundation rock masses for all types of concrete dams should be evaluated by the shear-friction resistance concept. The available sliding resistance is compared with the driving force which tends to induce sliding to arrive at a sliding stability safety factor. The investigation should be made along all potential sliding paths. The critical path is that plane or combination of planes which offers the least resistance.

4.4.4.5.1. Sliding Resistance. Sliding resistance is a function of the unit shearing strength at no normal load (cohesion) and the angle of friction on a potential failure surface. It is determined by computing the maximum horizontal driving force which could be resisted along the sliding path under investigation. The following general formula is obtained from the principles of statics and may be derived by resolving forces parallel and perpendicular to the sliding plane:

$$R_R = V \tan (\phi + \alpha) + \frac{cA}{\cos \alpha (1 - \tan \phi \tan \alpha)} \quad (3)$$

where

- R_R = Sliding Resistance (maximum horizontal driving force which can be resisted by the critical path)
- ϕ = Angle of internal friction of foundation material or, where applicable, angle of sliding friction
- V = Summation of vertical forces (including uplift)
- c = Unit shearing strength at zero normal loading along potential failure plane
- A = Area of potential failure plane developing unit shear strength "c"
- α = Angle between inclined plane and horizontal (positive for uphill sliding)

For sliding downhill the angle α is negative and Equation (1) becomes:

$$R_R = V \tan (\phi - \alpha) + \frac{cA}{\cos \alpha (1 + \tan \phi \tan \alpha)} \quad (4)$$

When the plane of investigation is horizontal, and the angle α is zero and Equation (1) reduced to the following:

$$R_R = V \tan \phi + cA \quad (5)$$

4.4.4.5.2. Downstream Resistance. When the base of a concrete structure is embedded in rock or the potential failure plane lies below the base, the passive resistance of the downstream layer of rock may sometimes be utilized for sliding resistance. Rock that may be subjected to high velocity water scouring should not be used. The magnitude of the downstream resistance is the lesser of (a) the shearing resistance along the continuation of the potential sliding plane until it daylights or (b) the resistance available from the downstream rock wedge along an inclined plane. The theoretical resistance offered by the passive wedge can be computed by a formula equivalent to formula (3):

$$P_p = W \tan (\phi + \alpha) + \frac{cA}{\cos \alpha (1 - \tan \phi \tan \alpha)} \quad (6)$$

P_p = passive resistance of rock wedge

W = weight (buoyant weight if applicable) of downstream rock wedge above inclined plane of resistance, plus any superimposed loads

ϕ = angle of internal friction or, if applicable, angle of sliding friction

α = angle between inclined failure plane and horizontal

c = unit shearing strength at zero normal load along failure plane

A = area of inclined plane of resistance

When considering cross-bed shear through a relatively shallow, competent rock strut, without adverse jointing or faulting, W and α may be taken at zero and 45° , respectively, and an estimate of passive wedge resistance per unit width obtained by the following equation:

$$P_p = 2 cD \quad (7)$$

where

D = Thickness of the rock strut

4.4.4.5.3. Safety Factor. The shear-friction safety factor is obtained by dividing the resistance R_R by H , the summation of horizontal service

loads to be applied to the structure:

$$S_{s-f} = \frac{R_R}{H} \quad (8)$$

When the downstream passive wedge contributes to the sliding resistance, the shear friction safety factor formula becomes:

$$S_{s-f} = \frac{R_R + P_p}{H} \quad (9)$$

The above direct superimposition of passive wedge resistance is valid only if shearing rigidities of the foundation components are similar. Also, the compressive strength and buckling resistance of the downstream rock layer must be sufficient to develop the wedge resistance. For example, a foundation with closely spaced, near horizontal, relatively weak seams might not contain sufficient buckling strength to develop the magnitude of wedge resistance computed from the cross-bed shear strength. In this case wedge resistance should not be assumed without resorting to special treatment (such as installing foundation anchors). Computed sliding safety factors approximating 3 or more for all loading conditions without earthquake, and 1.5 including earthquake, should indicate satisfactory stability, depending upon the reliability of the strength parameters used in the analyses. In some cases when the results of comprehensive foundation studies are available, smaller safety factors may be acceptable. The selection of shear strength parameters should be fully substantiated. The bases for any assumptions; the results of applicable testing, studies and investigations; and all pre-existing, pertinent data should be reported and evaluated.

APPENDIX G

DRAWINGS



DAM SITE

VICINITY MAP

DASHVILLE DAM

1

500 B-1000000 1400 1000

250 500

300

LINE 1000

2

EL 172.00

EL 189.00

SECTION OF SPILL

Scale

1:100

3

62° Rod 7-6' 1/2

2' 0" to Long
3-4 Chs

E1162


at or about the
mouth of the
river

E1160 29'


E1164 22'

RAILWAY ABOVE FALLS

E1161 18'



4



(Not furnished under this contract)


FLASHBOARDS AT SOUTH END OF

Make 30 panels of 3' x 10' each

(Not furnished under this contract)

*Use 14x16 studs or 12x16 studs
and 2x4s for framing to timber
with screws*

*Use 2" x 4" lumber for
bracing*



TO OF DAM


11.3

(m)

MAXIMUM SECTION OF SPILLWAY

(Designed for Extreme High Water of 1918)

Scale 1" = 10'




EL. 171.00

EL. 172.00


EL. 169.00

7






PLAN OF GALLERY




2



CROSS SECTION 'B-B'

Elev 1420'
Elev 140'



5/22/2015

3

Elev 1720'

Flashboards

Flashboard Society

1840' Radius


Bucket if required

1820'


100'


70'


210'





4











Alroy

STY (180)


5
Elev 157.0


N

L.M. Elev 172.0

Elev 150







SECTION OF POWER HOUSE

UNITED HUDSON ELECTRIC CORPORATION
 CLARKVILLE TREATMENT

PLAN AND SECTIONS OF POWER HOUSE AND DAM


THE J.G. WHITE ENGINEERING CORPORATION

ENGINEERS AND CONTRACTORS

APPROVED *[Signature]*

DATE **August 7, 1908**

[Handwritten Signature]



230

220

210

200

R O A D

190

SUB-S

190

S T A T E

180

170

160

150

Rock Ledge

Boom

2

168

STATION


190


To Transmission Line

WALL

RIVER

Crest Elev. 90






170 180 190 200

3

RIVER

FALLS



Roadway

4

All River

RACE

TAIL

140


130

River Bed Solid Rock



S

130



DASHVILLE



160

150

150

170
180
190

200

140

150

160

170

180

UNITED HUDSON ELECTRIC CORPORATION
DASHVILLE TELEPHONE

CONTOUR MAP AND GENERAL LOCATION PLAN
THE J.S. WHITE ENGINEERING CORPORATION

ENGINEERS AND CONTRACTORS

APPROVED *R. H. White* ENGINEER DATE MAY 29, 1919

MAIN OFFICE - 46 EXCHANGE PLACE N.Y.

AUTHORIZATION NO. 5302

SCALE 1" = 20' 0"

190

200

7

H-1402

130

Note: Site located in Rosendale and Esopus Twp,
Ulster Co. N.Y., about 1 mile above Rifton.

8