

AD-A078 911


KIMBALL (L ROBERT) AND ASSOCIATES EBENSBURG PA  
NATIONAL DAM INSPECTION PROGRAM. LYMAN RUN DAM,  
SEP 79

F/G 13/13  
NDS I.D. NUMBER--ETC(U)  
DACW51-79-C-009

NL

UNCLASSIFIED

| OF |  
AD-  
A078911





NATIONAL BUREAU OF STANDARDS  
MICROCOPY RESOLUTION TEST CHART

SUSQUEHANNA RIVER BASIN  
LYMAN RUN, POTTER COUNTY



AD A 078911

PENNSYLVANIA


**LYMAN RUN DAM**

LEVEL

NDS ID NO. PA-29  
DER ID NO. 53-49

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM



Distribution Unlimited  
Approved for Public Release  
Contract No. DACW31-79-C-0009

DDC FILE COPY

Prepared By  
**L. ROBERT KIMBALL & ASSOCIATES**  
CONSULTING ENGINEERS & ARCHITECTS  
EBENSBURG, PENNSYLVANIA  
15931

DDC  
RECEIVED  
JAN 8 1980  
A

ORIGINAL CONTAINS COLOR PLATES: ALL DDC  
REPRODUCTION IS IN BLACK AND WHITE

FOR  
DEPARTMENT OF THE ARMY  
BALTIMORE DISTRICT CORPS OF ENGINEERS  
BALTIMORE, MARYLAND  
21203

SEPTEMBER, 1979

80-7-1029

197-1-1

## **DISCLAIMER NOTICE**

1

**THIS DOCUMENT IS BEST QUALITY  
PRACTICABLE. THE COPY FURNISHED  
TO DDC CONTAINED A SIGNIFICANT  
NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.**

SUSQUEHANNA RIVER BASIN,  
LYMAN RUN POTTER COUNTY

PENNSYLVANIA.

*National Dam Inspection Program*

# LYMAN RUN DAM

*J.D. number*  
NDS NO. PA-29

*J.D. number*  
DER ID NO. 53-49

*J.D.*

COMMONWEALTH OF PENNSYLVANIA,  
DEPARTMENT OF ENVIRONMENTAL RESOURCES,

PHASE I INSPECTION REPORT,  
NATIONAL DAM INSPECTION PROGRAM



15 DACW31-79-C-0009

Prepared By

**L. ROBERT KIMBALL & ASSOCIATES**  
CONSULTING ENGINEERS & ARCHITECTS  
EBENSBURG, PENNSYLVANIA  
15931

ORIGINAL CONTAINS COLOR PLATES: ALL DDC  
REPRODUCTIONS WILL BE IN BLACK AND WHITE

FOR

DEPARTMENT OF THE ARMY  
BALTIMORE DISTRICT CORPS OF ENGINEERS  
BALTIMORE, MARYLAND  
21203

11 SEPTEMBER 1979

12 85

411 059

mit

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

Approved For	
THIS DAM	
DOC TAB	
Announced	
Justification	
By	
Distribution	
Availability Code	
Analyst/Author	
Disposal	
A 23 CP	

PHASE I REPORT  
NATIONAL DAM INSPECTION REPORT

NAME OF DAM: Lyman Run Dam  
STATE LOCATED: Pennsylvania  
COUNTY LOCATED: Potter  
STREAM: Lyman Run  
DATE OF INSPECTION: June 27 and 28, 1979

[cont'd from p. 1]

ASSESSMENT

The assessment of Lyman Run Dam is based upon visual observations made at the time of inspection, review of available records and data, hydrologic and hydraulic computations, and past operational performance.

The inspection and review of data of Lyman Run Dam did not reveal any problems which require emergency action. The dam appears to be in good condition with the exception of the seepage, well maintained and safely operated.


Lyman Run Dam is a high hazard-intermediate size dam. The Spillway Design Flood is the PMF (Probable Maximum Flood). The spillway and reservoir are capable of controlling the PMF. Based on criteria established by the Corps of Engineers, the spillway is termed adequate.

The long term effect of the seepage exiting from the downstream toe area and right abutment should be evaluated. In addition, the seepage conditions occurring under prolonged high reservoir levels is unknown.


The following recommendations and remedial measures should be instituted immediately.

1. Measuring weirs should be installed at all seepage areas and monitored at frequent intervals and during periods of heavy rainfall or high reservoir level for quantity of seepage and turbidity. The effectiveness of the grouting program should be evaluated by a registered professional engineer knowledgeable in earth dams and grouting.
2. Regular maintenance should be made on the upstream paving blocks.
3. The cracks in the bottom of the spillway exit channel should be repaired and sealed.
4. The slide gate on the 5' x 5' box should be operated and lubricated at regular intervals.
5. A safety inspection program should be conducted at regular intervals.





Overview of upstream slope - Note drain line  
control structure in reservoir.



Overview of downstream slope.

## TABLE OF CONTENTS

	PAGE
SECTION 1 - PROJECT INFORMATION	1
1.1 General	1
1.2 Description of Project	1
1.3 Pertinent Data	2
SECTION 2 - ENGINEERING DATA	5
2.1 Design	5
2.2 Construction	5
2.3 Operation	5
2.4 Evaluation	5
SECTION 3 - VISUAL INSPECTION	6
3.1 Findings	6
3.2 Evaluation	7
SECTION 4 - OPERATIONAL PROCEDURES	8
4.1 Procedures	8
4.2 Maintenance of Dam	8
4.3 Maintenance of Operating Facilities	8
4.4 Warning System in Effect	8
4.5 Evaluation	8
SECTION 5 - HYDRAULICS AND HYDROLOGY	9
5.1 Evaluation of Features	9
5.2 Evaluation Assumptions	9
5.3 Summary of Overtopping Analysis	9
SECTION 6 - STRUCTURAL STABILITY	11
6.1 Evaluation of Structural Stability	11
SECTION 7 - ASSESSMENT AND RECOMMENDATIONS/REMEDIAL MEASURES	12
7.1 Dam Assessment	12
7.2 Recommendations/Remedial Measures	12

APPENDICES

- APPENDIX A - CHECKLIST, VISUAL INSPECTION, PHASE I
- APPENDIX B - CHECKLIST, ENGINEERING DATA, CONSTRUCTION,  
OPERATION, PHASE I
- APPENDIX C - PHOTOGRAPHS
- APPENDIX D - HYDROLOGY AND HYDRAULICS
- APPENDIX E - DRAWINGS
- APPENDIX F - GEOLOGY

PHASE I  
NATIONAL DAM INSPECTION PROGRAM  
LYMAN RUN DAM  
NDI I.D. NO. PA 29  
DER I.D. NO. 53-49

SECTION 1  
PROJECT INFORMATION

1.1 General.

a. Authority. The National Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.

b. Purpose. The purpose of the inspection is to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project.

a. Dam and Appurtenances. Lyman Run Dam is an earthfill dam 920 feet long and 50 feet high. The top width of the dam is 14 feet. The upstream slope is 3H:1V and the downstream slope is 2.5H:1V. The upstream slope is protected against wave action with an 8" layer on concrete block riprap between elevation 1645.0 and 1632.0. The embankment consists of two classes of material. A central core consists of selected impervious material. The upstream and downstream portions of the embankment are constructed using pervious material. A core trench 5 feet deep and 16 feet wide is constructed under the axis of the dam. A line of steel sheet piling is driven along the centerline of the trench to bedrock.

The outlet conduit consists of a 5' by 5' reinforced concrete box culvert under the earth embankment. Three cutoff collars are located along the culvert. A 3' by 3' sluice gate is operated from on top of a twelve foot square reinforced concrete tower, located 148 feet upstream of the axis of the dam. At the discharge end of the box culvert is a scour hole with large hand placed riprap. The discharge channel out of the scour hole is 200 feet long with a bottom width of 8 feet to the natural stream channel of Lyman Run.

The spillway is located at the left abutment of the dam and consists of a concrete lined chute. The weir consists of a 125 foot long concrete ogee. A three foot thick curtain wall extends 6 feet beneath the bottom of the weir base. The spillway exit channel is a concrete chute consisting of a reinforced concrete slab with reinforced concrete retaining walls. The exit channel is 375 feet long and ranges in grade from 5% to 20% ending in a concrete stilling basin.

b. Location. The dam is located on Lyman Run approximately 6 miles west of Galeton, Potter County, Pennsylvania. Lyman Run Dam can be located on the Cherry Springs, U.S.G.S. 7.5 minute quadrangle.

c. Size Classification. Lyman Run Dam is an intermediate size structure (50 feet high, 1428 acre-feet).

d. Hazard Classification. Lyman Run Dam is a high hazard dam. Downstream conditions indicate that loss of more than a few lives is probable should the structure fail (See Section 3.1e).

e. Ownership. Lyman Run Dam is owned by the Commonwealth of Pennsylvania, Department of Environmental Resources. Correspondence should be addressed to:

Bureau of Operation Resources Management  
Department of Environmental Resources  
P.O. Box 1467  
Harrisburg, PA 17120

f. Purpose of Dam. Lyman Run Dam is used for recreation.

g. Design and Construction History. The dam was designed by the Chester Engineers for the General State Authority and Department of Environmental Resources. The dam was constructed by Elmhurst Construction Company and completed in 1951. In 1972, construction began on protective measures for scour and seepage and for grouting the right abutment and dam foundation.

h. Normal Operating Procedures. The reservoir level is maintained at the spillway crest elevation (elevation 1635.0). Excess inflow is discharged over the spillway crest. The drain line gate is operated twice each year.

### 1.3 Pertinent Data.

a. Drainage Area. 17.9 square miles

b. Discharge at Dam Site (cfs).

Maximum known flood at dam site	Unknown
5' x 5' box culvert capacity	Unknown
Emergency spillway capacity at top of dam	28,257

c. Elevation (U.S.G.S. Datum) (feet) - Elevations worked from spillway crest elevation shown on construction drawings.

Top of dam - low point	1651.2
Top of dam - design	1652.5
Maximum pool - design surcharge	1652.5

Full flood control pool	N/A
Normal	1635.0
Spillway crest	1635.0
Upstream portal 5' x 5' box culvert	1600.2
Downstream portal 5' x 5' box culvert	1599.8
Streambed at centerline of dam	1601.0
Maximum tailwater	None
Toe of dam	1599.8
d. <u>Reservoir (feet).</u>	
Length of maximum pool	5000
Length of normal pool	3500
Length of flood control pool	N/A
e. <u>Storage (acre-feet).</u>	
Normal pool	680
Flood control pool	N/A
Top of dam	1428
f. <u>Reservoir Surface (acres).</u>	
Top of dam	53
Maximum pool	53
Flood control pool	N/A
Normal pool	40
Spillway crest	40
g. <u>Dam.</u>	
Type	Earthfill
Length	920 feet
Height	50 feet
Top width	14 feet
Side slopes - upstream	3H:1V
- downstream	2.5H:1V
Zoning	Yes
Impervious core	Yes
Cutoff	Sheet pile cutoff
Grout curtain	Partial, on right abutment
h. <u>Reservoir Drain.</u>	
Type	5' x 5' concrete box culvert
Length	300 feet
Closure	3' x 3' sluice gate on control tower
Access	By boat to control tower
Regulating facilities	Sluice gate on control tower
i. <u>Spillway.</u>	
Type	Concrete lined chute
Length	125 feet
Crest elevation	1635.0

Gates  
Upstream channel  
Downstream channel

None  
Lake  
375 foot long concrete lined chute  
to stilling basin

SECTION 2  
ENGINEERING DATA

2.1 Design. Review of information in the files of the Commonwealth of Pennsylvania, Department of Environmental Resources revealed that construction drawings, inspection reports, permits, photographs and correspondence were available for review. All this data was reviewed for this study.

2.2 Construction. Construction progress reports and concrete and compaction tests were reviewed for this study.

2.3 Operation. No operating records are maintained.

2.4 Evaluation.

a. Availability. Engineering data were provided by PennDER Bureau of Dams and Waterways Management. The state part superintendent accompanied the inspection team to answer questions on operation and maintenance of the dam.

b. Adequacy. The type and amount of design data and other engineering information is substantial. The information is sufficient to complete a Phase I Report.

SECTION 3  
VISUAL INSPECTION

3.1 Findings.

a. General. The onsite inspection of Lyman Run Dam was conducted by personnel of L. Robert Kimball and Associates accompanied by the state park superintendent on June 27 and 28, 1979. The inspection consisted of:

1. Visual inspection of the retaining structure, abutments and toe.
2. Examination of the spillway facilities, portions of any outlet works, and other appurtenant works.
3. Observations affecting the runoff potential of the drainage basin.
4. Evaluation of the downstream area hazard potential.

b. Dam. The dam appears to be in good condition with the exception of the extensive seepage areas. The dam appears to conform closely to the construction drawings. From a brief survey conducted during the inspection, it was noted that the crest of the dam is approximately 1.1 feet lower than the design height. The upstream slope is 3H:1V and the downstream slope is 2.5H:1V. The crest width is 14 feet. On the upstream slope between elevations 1632.0 and 1645.0 is a concrete block slope paving. This paving is in fair condition. Some of the paving blocks show settlement and cracking. In addition, grass is growing between some of the blocks. The remainder of the upstream slope, downstream slope and crest are covered with grass. Along the downstream toe to the left of the principal spillway discharge channel, is a recently placed rock drain. The exposed portion of this drain shows a coarse gravel fill with a corrugated metal pipe draining to the principal spillway discharge channel. Seepage from this drain during the inspection was measured to be 9 gallons per minute. An extensive seepage zone was located at the toe of the dam at the right abutment. The seepage during the inspection was measured at 112 gallons per minute. This area has been the subject of studies immediately after filling. A weir was installed after construction but has subsequently been washed out. In 1974, a grouting program was conducted to cut off some of the seepage. After construction, seepage readings were as high as 400 gallons per minute. A small seepage zone was noted to the immediate right of the reservoir drain (5' x 5' box) on the downstream slope of the dam. This seepage was estimated at 4 gallons per minute. The park superintendent indicated that this seepage zone has just recently been noticed. A large wet area is present beyond the toe of the dam and covers most of the valley floor.

c. Appurtenant Structures. The reservoir level at the time of inspection was 1635.1. The emergency spillway and facilities appeared to be in good condition. The concrete weir appeared to be in good condition. In addition, the spillway exit channel retaining walls appeared to be in good condition and stable. Some cracks have developed in the bottom slab of the spillway exit channel.

The slide gate on the 5' x 5' concrete box was not operated during the inspection. In addition, examination of the 5' x 5' box was not conducted except examination of the exposed portion at the downstream toe of the dam. A minimal amount of flow was exiting from the 5' x 5' box. Operation of the slide gate in the control structure can only be made by gaining access to the intake structure by means of a boat. At the discharge end of the drain line is a riprapped scour hole. Beyond this scour hole is a riprapped trapezoidal channel to the natural streambed of Lyman Run.

d. Reservoir Area. The watershed is covered mostly with woodland. The reservoir slopes are moderate to steep but are not susceptible to massive landslides which would affect the storage volume of the reservoir or overtopping of the dam by displacing water.

e. Downstream Channel. The downstream channel of Lyman Run is moderately wide and gentle. Homes are scattered throughout the valley bottom to the town of Galeton.

3.2 Evaluation. In general, the embankment and appurtenant structures appeared to be in good condition and adequately maintained. The seepage areas at the toe of the dam are of concern and should be monitored at regular intervals.

SECTION 4  
OPERATIONAL PROCEDURES

4.1 Procedures. The reservoir is maintained at the spillway crest elevation 1635.0. The excess inflow discharges over the spillway crest. The drain line is operated twice each year.

4.2 Maintenance of the Dam. No planned maintenance schedule is utilized. Maintenance of the dam is performed by the Department of Environmental Resources, Park Staff. Maintenance of the dam is considered good.

4.3 Maintenance of Operating Facilities. The slide gate on the 5' x 5' concrete box is reportedly operated twice each year. Maintenance of the operating facilities is considered good.

4.4 Warning System in Effect. There is no warning system in effect to warn downstream residents of large spillway discharges or failure of the dam.

4.5 Evaluation. Maintenance of the dam and operating facilities is considered good. There is no warning system in effect to warn downstream residents. The dam is not accessible during flooding which should be corrected.

SECTION 5  
HYDRAULICS AND HYDROLOGY

5.1 Evaluation of Features.

a. Design Data. No hydrologic information is available. The only hydraulic information available were memorandums on hydraulic model studies for the spillway which indicate the spillway can function up to 25,000 cfs. Studies beyond 25,000 cfs were not performed.

b. Experience Data. The maximum flood to date is unknown. It is reported that the spillway has performed adequately in the past.

c. Visual Observations. The spillway and spillway discharge channel appeared to be in good condition.

d. Overtopping Potential. Overtopping potential was investigated through the development of the Probable Maximum Flood (PMF) for the watershed and the subsequent routing of the PMF and fractions of the PMF through the reservoir and spillway.

The Corps of Engineers, Baltimore District, has directed that the HEC-1 Dam Safety Version systemized computer program be utilized. The program was prepared by the Hydrologic Engineering Center (HEC), U.S. Army Corps of Engineers, Davis, California, July, 1978. The major methodologies or key input data for this program are discussed briefly in Appendix D.

5.2 Evaluation Assumptions. To enable us to complete the hydraulic and hydrologic analysis for this structure, it was necessary to make the following assumptions.

1. Water level prior to flood was at the spillway crest elevation 1635.0.
2. No flow through the 5' x 5' box was considered.

5.3 Summary of Overtopping Analysis. Complete summary sheets for the computer output are presented in Appendix D.

Peak Inflow (PMF)	28,821 cfs
Spillway Capacity	28,527 cfs

a. Spillway Adequacy Rating. The Spillway Design Flood (SDF) for this dam is the PMF. The SDF is based on the hazard and size classification of the dam. Based on the following definition provided by the Corps of Engineers, this spillway is rated as adequate as a result of our hydrologic analysis.

Adequate - For intermediate size dams which pass the PMF.

The spillway and reservoir are capable of controlling 99% of the PMF without overtopping the embankment. The spillway can be considered to pass the PMF.

SECTION 6  
STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability.

a. Visual Observations. No signs of slumping or erosion were noted during the inspection. However, the excessive seepage exiting from the downstream toe of the dam and right abutment are of concern (See section 3.1b). The long term effect of this seepage is unknown.

b. Design and Construction Data. No stability analyses were conducted during the design of this dam.

c. Operating Records. No operating records are maintained.

d. Post Construction Changes. In 1974, a grouting program was conducted to cutoff some of the seepage exiting from the right abutment toe. No seepage readings are available from just before grouting and after grouting to determine the effectiveness of the grouting program.

e. Seismic Stability. The dam is located in seismic zone 1. No seismic stability analysis has been performed. Normally, it can be considered that if a dam in this zone is stable under static loading conditions, it can be assumed safe for any expected earthquake loading.

SECTION 7  
ASSESSMENT AND RECOMMENDATIONS/REMEDIAL MEASURES

7.1 Dam Assessment.

a. Safety. The dam appears to be in good condition with the exception of the extensive seepage exiting from the downstream toe area and the right abutment area. The visual observations, review of available information, hydrologic and hydraulic calculations and past operational performance indicate that Lyman Run Dam's spillway is adequate. The spillway is capable of controlling the PMF without overtopping. No adequate stability analyses have been performed for the structure. The long term effect of the seepage is unknown.

b. Adequacy of Information. Sufficient information is available to complete a Phase I Report.

c. Urgency. The recommendations suggested below should be implemented immediately.

d. Necessity for Further Investigations. To complete some of the recommendations/remedial measures outlined below, additional investigations are required.

7.2 Recommendations/Remedial Measures

1. Measuring weirs should be installed at all seepage areas and monitored at frequent intervals and during periods of heavy rainfall or high reservoir levels for quantity of seepage and turbidity. The effectiveness of the grouting program should be evaluated by a registered professional engineer knowledgeable in earth dams and grouting.

2. Regular maintenance should be made on the upstream paving blocks.

3. The cracks in the bottom of the spillway exit channel should be repaired and sealed.

4. The slide gate on the 5' x 5' box should be operated and lubricated at regular intervals.

5. A safety inspection program should be conducted at regular intervals.

6. Access to the dam should be improved so that the dam is accessible during flooding.

7. A warning system should be developed to warn downstream residents of large spillway discharges or failure of the dam.

APPENDIX A

CHECKLIST, VISUAL INSPECTION, PHASE I

CHECK LIST  
VISUAL INSPECTION  
PHASE I

NAME OF DAM Lyman Run Dam COUNTY Potter STATE Pennsylvania ID# PA 29  
TYPE OF DAM Earthfill HAZARD CATEGORY High  
DATE(S) INSPECTION June 27, 28, 1979 WEATHER Clear, warm TEMPERATURE 75°

POOL ELEVATION AT TIME OF INSPECTION 1635.1 M.S.L. TAILWATER AT TIME OF INSPECTION 1597.4 M.S.L.

INSPECTION PERSONNEL:

R. Jeffrey Kimball, L. Robert Kimball and Associates

James T. Hockensmith, L. Robert Kimball and Associates

Kuang-hwei Chuang, L. Robert Kimball and Associates

Richard A. Linn, Regional Park Superintendent, DER

\_\_\_\_\_  
James T. Hockensmith RECORDER

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	None in embankment, some cracks in upstream slope paving.	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None.	
SLOUCHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	None.	
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Horizontal alignment appears to be good. Vertical alignment - ranges from 1651.4 to 1652.0	
RIPRAP FAILURES	None.	

**EMBANKMENT**

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
<b>VEGETATION</b>	Upper part of upstream slope, crest and downstream slope grassed - mowed.	
<b>JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM</b>	Appear to be good, with the exception of the seepage occurring on the downstream slope of the right abutment.	
<b>ANY NOTICEABLE SEEPAGE</b>	Junction of toe and right abutment - 112 gpm, seepage to the right of the 5' x 5' box - 4 gpm, seepage from downstream toe area to the left of the principal spillway discharge channel - 9 gpm.	
<b>STAFF GAUGE AND RECORDER</b>	None,	
<b>DRAINS</b>	Toe area drained by rock drain with corrugated metal pipe.	

CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
ANY NOTICEABLE SEEPAGE	N/A	
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS	N/A	
DRAINS	N/A	
WATER PASSAGES	N/A	
FOUNDATION	N/A	

CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES	N/A	
STRUCTURAL CRACKING	N/A	
VERTICAL AND HORIZONTAL ALIGNMENT	N/A	
MONOLITH JOINTS	N/A	
CONSTRUCTION JOINTS	N/A	
STAFF GAUGE OR RECORDER	N/A	

OUTLET WORKS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	Only the downstream end of the 5' x 5' box culvert exposed. Condition appears to be good.	
INTAKE STRUCTURE	Intake structure in reservoir area, not observed.	
OUTLET STRUCTURE	None.	
OUTLET CHANNEL	Riprapped and in good condition.	
EMERGENCY GATE	Unobserved during inspection.	

UNGATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	In good condition.	
APPROACH CHANNEL	Lake.	
DISCHARGE CHANNEL	Some cracks in bottom of channel.	
BRIDGE AND PIERS	None.	

**GATED SPILLWAY**

<b>VISUAL EXAMINATION OF</b>	<b>OBSERVATIONS</b>	<b>REMARKS OR RECOMMENDATIONS</b>
<b>CONCRETE SILL</b>	N/A	
<b>APPROACH CHANNEL</b>	N/A	
<b>DISCHARGE CHANNEL</b>	N/A	
<b>BRIDGE AND PIERS</b>	N/A	
<b>GATES AND OPERATION EQUIPMENT</b>	N/A	

DOWNSTREAM CHANNEL


VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	Wide and relatively flat. No obstructions.	
SLOPES	Stable.	
APPROXIMATE NO. OF HOMES AND POPULATION	Approximately 400 homes (1500 people).	

RESERVOIR

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	Moderate, stable.	
SEDIMENTATION	Does not appear to be excessive.	

**INSTRUMENTATION**

<b>VISUAL EXAMINATION OF</b>	<b>OBSERVATIONS</b>	<b>REMARKS OR RECOMMENDATIONS</b>
<b>MONUMENTATION/SURVEYS</b>	None.	
<b>OBSERVATION WELLS</b>	Several on downstream slope but may not be functional.	
<b>WEIRS</b>	None.	
<b>PIEZOMETERS</b>	None.	
<b>OTHER</b>	None.	



LYMAN RUN DAM  
Scale: 1" = 200'

APPENDIX B

CHECKLIST, ENGINEERING DATA, DESIGN, CONSTRUCTION, OPERATION, PHASE I

**CHECK LIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION  
PHASE I**

**NAME OF DAM** Lyman Run Dam

**ID#** PA 29


<b>ITEM</b>	<b>REMARKS</b>
<b>AS-BUILT DRAWINGS</b>	None.
<b>REGIONAL VICINITY MAP</b>	U.S.G.S. Quadrangle.
<b>CONSTRUCTION HISTORY</b>	DER files.
<b>TYPICAL SECTIONS OF DAM</b>	Construction drawings.
<b>OUTLETS - PLAN</b> - DETAILS - CONSTRAINTS - DISCHARGE RATINGS <b>RAINFALL/RESERVOIR RECORDS</b>	Construction drawings. Construction drawings. None. None. None.

ITEM	REMARKS
DESIGN REPORTS	None.
GEOLOGY REPORTS	None.
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	None.
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	Construction drawings and DER files.
POST-CONSTRUCTION SURVEYS OF DAM	Yes, all contained in DER files.
BORROW SOURCES	Construction drawings.

ITEM	REMARKS
MONITORING SYSTEMS	None.
MODIFICATIONS	Grouting program conducted in 1974.
HIGH POOL RECORDS	None.
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	None.
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	None.
MAINTENANCE OPERATION RECORDS	None.

ITEM	REMARKS
SPILLWAY PLAN SECTIONS DETAILS	Construction drawings.
OPERATING EQUIPMENT PLANS & DETAILS	Construction drawings.


APPENDIX C  
PHOTOGRAPHS



Crest of dam looking toward spillway (left abutment).



Tailwater at toe of dam.




Rock underdrain beyond toe of dam.



Outlet end of rock underdrain.




Monitors on downstream slope near right abutment.



Major seepage area at right abutment.




Discharge end of outlet works.



Seepage at end of rod adjacent to outlet works discharge.




Large wet area beyond toe of dam.



Spillway weir.



Emergency spillway.



Emergency spillway and stilling basin.

APPENDIX D  
HYDROLOGY AND HYDRAULICS

APPENDIX D  
HYDROLOGY AND HYDRAULICS

Methodology. The dam overtopping and breach analyses were accomplished using the systemized computer program HEC-1 (Dam Safety Investigation), September, 1978, prepared by the Hydrologic Engineering Center, U.S. Army Corps of Engineers, Davis, California. A brief description of the methodology used in the analysis is presented below.

1. Precipitation. The Probable Maximum Precipitation (PMP) is derived and determined from regional charts prepared from past rainfall records including "Hydrometeorological Reports No. 40 prepared by the National Weather Service.

The index rainfall is reduced from 10% to 20% depending on watershed size by utilization of what is termed the HOP Brook adjustment factor. Distribution of the total rainfall is made by the computer program using distribution methods developed by the Corps.

2. Inflow Hydrograph. The hydrologic analysis used in development of the overtopping potential is based on applying a hypothetical storm to a unit hydrograph to obtain the inflow hydrograph for reservoir routing.

The unit hydrograph is developed using the Snyder method. This method requires calculation of several key parameters. The following list gives these parameters their definition and how they were obtained for these analysis.

Parameter	Definition	Where Obtained
$C_t$	Coefficient representing variations of watershed slope and storage	From Corps of Engineers*
L	Length of main stream channel miles	From U.S.G.S. 7.5 minute topographic
$L_{ca}$	Length on main stream to centroid of watershed	From U.S.G.S. 7.5 minute topographic
$C_p$	Peaking coefficient	From Corps of Engineers*
A	Watershed size	From U.S.G.S. 7.5 minute topographic

\*Developed by the Corps of Engineers on a regional basis for Pennsylvania.


3. Routing. Reservoir routing is accomplished by using Modified Plus routing techniques where the flood hydrograph is routed through reservoir storage. Hydraulic capacities of the outlet works, spillways and the crest of the dam are used as outlet controls in the routing.

The hydraulic capacity of the outlet works can either be calculated and input or sufficient dimensions input and the program will calculate an elevation discharge relationship.

Storage in the pool area is defined by an area - elevation relationship from which the computer calculates storage. Surface areas are either planimetered from available mapping or U.S.G.S. 7.5 minute series topographic maps or taken from reasonably accurate design data.

4. Dam Overtopping. Using given percentages of the PMF the computer program will calculate the percentage of the PMF which can be controlled by the reservoir and spillway without the dam overtopping.

5. Dam Breach and Downstream Routing. The computer program is equipped to determine the increase in downstream flooding due to failure of the dam caused by overtopping. This is accomplished by routing both the pre failure peak flow and the peak flow through the breach (calculated by the computer with given input assumptions) at a given point in time and determining the water depth in the downstream channel. Channel cross-sections taken from U.S.G.S. 7.5 minute topographic maps were used in the downstream flood wave routing. Pre and post failure water depths are calculated at locations where cross-sections are input.



L. ROBERT KIMBALL & ASSOCIATES  
CONSULTING ENGINEERS & ARCHITECTS  
EBENSBURG PENNSYLVANIA

DAM NAME LYMAN RUN DAM

I.D. NUMBER PA. 53-49

SHEET NO. 1 OF 2

BY OTM DATE 9-10-79

### LYMAN RUN DAM

#### DRAINAGE AREA

AREA = 17.9 mi<sup>2</sup> (PL. DER. AND USGS 7.5-MIN. QUAD)

#### UNIT HYDROGRAPH PARAMETERS

DAM SITE LOCATED IN ZONE #17, SUSQUEHANNA RIVER BASIN. FROM CORPS OF ENGINEERS, BALTIMORE DISTRICT REGIONAL STUDY.

C<sub>p</sub> = 0.45 , C<sub>t</sub> = 1.13

L = 8.2 mi , L<sub>02</sub> = 3.2 mi (FROM USGS 7.5-MIN. QUAD)

t<sub>p</sub> = C<sub>t</sub>(L × L<sub>02</sub>)<sup>0.3</sup> = 1.13 (8.2 × 3.2)<sup>0.3</sup>

t<sub>p</sub> = 3.0 HRS. (SNYDERS LAG (t<sub>p</sub>) IN HRS.)

#### LOSS RATE AND BASE FLOW PARAMETERS

AS RECOMMENDED BY CORPS OF ENGINEERS, BALTIMORE DISTRICT.

STR TL = 1 INCH

CNSTL = 0.05 IN./HR.

STR Q = 1.5 CFS/MI<sup>2</sup>

QRCSN = 0.05 (5% OF PEAK FLOW)


RT/OR = 2.0

#### PROBABLE MAXIMUM STORM

FROM NR. N<sub>0</sub> 40

PMP INDEX RAINFALL = 22.2 (1.01) = 22.4 IN.

R<sub>6</sub> = 111% , R<sub>12</sub> = 121% , R<sub>24</sub> = 130% , R<sub>48</sub> = 137% , R<sub>72</sub> = 140%



L. ROBERT KIMBALL & ASSOCIATES  
CONSULTING ENGINEERS & ARCHITECTS  
EBENSBURG PENNSYLVANIA

DAM NAME LYMAN RUN DAM

I.D. NUMBER PL. 53-49

SHEET NO. 2 OF 2

BY OTM DATE 8-10-79

ELEVATION - AREA - CAPACITY RELATIONSHIP

FROM U.S.G.S. 7.5-MIN. QUADS, P.A. DER. FILES AND  
FIELD INSPECTION DATA.

AT SPILLWAY CREST ELEV. 1635', AREA 40 ACRES  
INITIAL STORAGE = 680 AC.FT

AT ELEV. 1660, AREA = 60 ACRES

AT ELEV. 1680, AREA = 94 ACRES

FROM CONIC METHOD FOR RESERVOIR VOLUME.  
FLOOD HYDROGRAPH PACKAGE (HEC-1), DAM  
SAFETY VERSION (USERS MANUAL).

$$H = 3V/A = 3(680)/40 = 51'$$

ELEV. AT CAPACITY EQUALS ZERO;  
 $1635' - 51' = 1584$

AREA (AC)	0	40	50	60	78	94
ELEV. (FT)	1584	1635	1648	1660	1672	1680

SPILLWAY DISCHARGE

DETERMINED BY (HEC-1)

SPILLWAY CREST = 1635'

SPILLWAY LENGTH = 125'

COEFFICIENT OF DISCHARGE (C) = 3.5 (OGEE)

OVERTOP PARAMETERS

TOP OF DAM (LOW SPOT) = 1651.2

LENGTH OF DAM = 920'

COEFFICIENT OF DISCHARGE (C) = 3.0 (BROAD CREST)

CHECK LIST  
HYDROLOGIC AND HYDRAULIC  
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: 17.9 square miles, woodland, steep slopes

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 1635.0 ( 680 acre-feet)

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): N/A

ELEVATION MAXIMUM DESIGN POOL: 1652.5

ELEVATION TOP DAM: 1651.2

SPILLWAY CREST:

- a. Elevation 1635.0
- b. Type Concrete ogee weir
- c. Width -
- d. Length 125 feet
- e. Location Spillover Left abutment
- f. Number and Type of Gates None.

OUTLET WORKS:

- a. Type 5' x 5' concrete box culvert
- b. Location Through dam
- c. Entrance inverts 1600.2
- d. Exit inverts 1599.8
- e. Emergency draindown facilities Sluice gate on control tower.

HYDROMETEOROLOGICAL GAUGES:

- a. Type None.
- b. Location \_\_\_\_\_
- c. Records \_\_\_\_\_

MAXIMUM NON-DAMAGING DISCHARGE: Unknown.

4/5

.....  
FLOOD HYDROGRAPH PACKAGE (HEC-1)  
DAM SAFETY VERSION JULY 1978  
LAST MODIFICATION 26 FEB 79  
.....

A1 ANALYSIS OF DAM OVERTOPPING USING RATIOS OF PMF  
A2 HYDROLOGIC-HYDRAULIC ANALYSIS OF DAM SAFETY OF LYMAN RUN DAM  
A3 RATIOS OF PMF ROUTED THROUGH THE RESERVOIR (PA 93-99)

1	280	0	15	0	0	0	0	0	0
2	5	0	0	0	0	0	0	0	0
3	1	0	0	0	0	0	0	0	0
4	0.2	0.3	0.4	0.5	0.6	0.7	0.8	0.9	1.0
5	0	0	0	0	0	0	0	0	0
6	0	0	0	0	0	0	0	0	0
7	0	0	0	0	0	0	0	0	0
8	0	0	0	0	0	0	0	0	0
9	0	0	0	0	0	0	0	0	0
10	1	1	1	1	1	1	1	1	1
11	1	1	1	1	1	1	1	1	1
12	1	1	1	1	1	1	1	1	1
13	3.0	0.45	0.6	0.8	1.0	1.2	1.4	1.6	1.8
14	119	903	240	17.9	130	137	140	140	0.05
15	1	1	1	1	1	1	1	1	1
16	1	1	1	1	1	1	1	1	1
17	1	1	1	1	1	1	1	1	1
18	1	1	1	1	1	1	1	1	1
19	1	1	1	1	1	1	1	1	1
20	1504	1838	50	60	78	94	100	100	-1435
21	1430	128	3.5	1.8	1.5	1.5	1.5	1.5	1.5
22	1430	128	3.5	1.5	1.5	1.5	1.5	1.5	1.5
23	1430	128	3.5	1.5	1.5	1.5	1.5	1.5	1.5

D  
6

.....  
 FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 26 FEB 79  
 .....

RUN DATE 79/08/13  
 TIME 10:59:34

ANALYSIS OF DAM OVERTOPPING USING RATIOS OF PMF  
 HYDROLOGIC-HYDRAULIC ANALYSIS OF DAM SAFETY OF LYMAN RUN DAM  
 RATIOS OF PMF ROUTED THROUGH THE RESERVOIR (PA: 93-99)

JOB SPECIFICATION

NO	NHR	NMIN	IDAY	IHR	IMIN	METRC	IPLT	IPRT	NSTAN
288	0	15	0	0	0	0	0	0	0
JOBER 5 NWT 0 LROPT 0 TRACE 0									

MULTI-PLAN ANALYSES TO BE PERFORMED  
 NPLAN= 1 NRTIO= 4 LRTIO= 1

RTIO= 20 30 40 100

.....

SUBAREA RUNOFF COMPUTATION

INFLOW TO RESERVOIR

ISTAD	ICOMP	IELCON	ITAPE	JPLT	JPRI	INAME	ISTAGE	IAUTO
1	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

3/15

IMYDQ 1 17.90 IAREA 17.90 SNAP 0.00 IRMSDA 17.90 TRSPC 0.00 RATIO 0.000 15HOW 0 ISAME 1 LOCAL 0  
 SPFE 1 0.00 IUMG 1 17.90 IAREA 17.90 SNAP 0.00 IRMSDA 17.90 TRSPC 0.00 RATIO 0.000 15HOW 0 ISAME 1 LOCAL 0  
 PRECIP DATA  
 M12 M24 M48 M72 M96  
 0.00 22.00 111.00 121.00 130.00 137.00 140.00 0.00

TRSPC COMPUTED BY THE PROGRAM IS 1820  
 LOSS DATA  
 LROPI 0 0.00 DLTFR 0.00 RTIOL 1.00 ERAIN 0.00 SIKES 0.00 RTIOK 1.00 STIIL 1.00 CNSIL .05 ALSMR 0.00 RTIMP 0.00

UNIT HYDROGRAPH DATA  
 IFO 3.00 CP 0.5 NTA 0

RECESSIION DATA  
 STRIQ -1.50 ORCSN -.05 RTIOR 2.00

APPROXIMATE CLARK COEFFICIENTS FROM GIVEN HYDRO CP AND TP ARE 70.12.00 AND 19.21.00 INTERVALS  
 UNIT-HYDROGRAPH100 END-OF-PERIOD ORDINATES: LAG= 3.02 HOURS: CP= 145 VOL= .99  
 187. 293. 572. 871. 1116. 1222. 1494. 1628.  
 1723. 1771. 1750. 1674. 1589. 1431. 1358. 1223.  
 1161. 1102. 1046. 993. 942. 894. 848. 805. 764. 725.  
 688. 653. 620. 588. 558. 530. 503. 477. 453. 430.  
 408. 387. 368. 349. 331. 314. 298. 283. 269. 255.  
 242. 230. 218. 207. 196. 186. 177. 168. 159. 151.  
 143. 129. 123. 118. 110. 105. 99. 94. 90.  
 85. 81. 77. 73. 69. 65. 62. 59. 56. 53.  
 50. 48. 45. 43. 39. 37. 35. 33. 32.  
 30. 28. 27. 26. 25. 23. 22. 20. 19.

END-OF-PERIOD FLOW  
 MO.DA HR.MN PERIOD RAIN EXCS LUSS COMP.U MO.DA HR.MN PERIOD RAIN EXCS LUSS COMP.U  
 1.01 015 1 0.00 0.00 0.00 25. 1.02 12.15 145 0.51 0.90 2046.  
 1.01 030 2 0.00 0.00 0.00 23. 1.02 12.30 186 0.91 0.90 2198.

1.01	6.45	3	6.00	0.00	0.00	0.00	0.00	0.00	224	1.02	12.445	147	431	.50	.01	2326.
1.01	1.00	4	6.00	0.00	0.00	0.00	0.00	0.00	206	1.02	13.500	148	51	.50	.01	2573.
1.01	1.15	5	6.00	0.00	0.00	0.00	0.00	0.00	196	1.02	13.15	149	61	.60	.01	2909.
1.01	1.30	6	6.00	0.00	0.00	0.00	0.00	0.00	186	1.02	13.30	150	61	.60	.01	3347.
1.01	1.45	7	6.00	0.00	0.00	0.00	0.00	0.00	176	1.02	13.45	151	61	.60	.01	3897.
1.01	2.00	8	6.00	0.00	0.00	0.00	0.00	0.00	166	1.02	14.00	152	61	.60	.01	4552.
1.01	2.15	9	6.00	0.00	0.00	0.00	0.00	0.00	156	1.02	14.15	153	76	.75	.01	5306.
1.01	2.30	10	6.00	0.00	0.00	0.00	0.00	0.00	146	1.02	14.30	154	76	.75	.01	6154.
1.01	2.45	11	6.00	0.00	0.00	0.00	0.00	0.00	136	1.02	14.45	155	76	.75	.01	7088.
1.01	3.00	12	6.00	0.00	0.00	0.00	0.00	0.00	126	1.02	15.00	156	76	.75	.01	8090.
1.01	3.15	13	6.00	0.00	0.00	0.00	0.00	0.00	116	1.02	15.15	157	77	.76	.01	9129.
1.01	3.30	14	6.00	0.00	0.00	0.00	0.00	0.00	106	1.02	15.30	158	77	.76	.01	10212.
1.01	3.45	15	6.00	0.00	0.00	0.00	0.00	0.00	96	1.02	15.45	159	86	4.32	.01	11408.
1.01	4.00	16	6.00	0.00	0.00	0.00	0.00	0.00	86	1.02	16.00	160	86	4.07	.01	13031.
1.01	4.15	17	6.00	0.00	0.00	0.00	0.00	0.00	76	1.02	16.15	161	77	.70	.01	14811.
1.01	4.30	18	6.00	0.00	0.00	0.00	0.00	0.00	66	1.02	16.30	162	71	.70	.01	16682.
1.01	4.45	19	6.00	0.00	0.00	0.00	0.00	0.00	56	1.02	16.45	163	71	.70	.01	18616.
1.01	5.00	20	6.00	0.00	0.00	0.00	0.00	0.00	46	1.02	17.00	164	77	.70	.01	20587.
1.01	5.15	21	6.00	0.00	0.00	0.00	0.00	0.00	36	1.02	17.15	165	86	.85	.01	22515.
1.01	5.30	22	6.00	0.00	0.00	0.00	0.00	0.00	26	1.02	17.30	166	86	.85	.01	24283.
1.01	5.45	23	6.00	0.00	0.00	0.00	0.00	0.00	16	1.02	17.45	167	86	.85	.01	25809.
1.01	6.00	24	6.00	0.00	0.00	0.00	0.00	0.00	6	1.02	18.00	168	86	.85	.01	27078.
1.01	6.15	25	6.00	0.00	0.00	0.00	0.00	0.00	5	1.02	18.15	169	86	.85	.01	28056.
1.01	6.30	26	6.00	0.00	0.00	0.00	0.00	0.00	4	1.02	18.30	170	86	.85	.01	28657.
1.01	6.45	27	6.00	0.00	0.00	0.00	0.00	0.00	3	1.02	18.45	171	86	.85	.01	28821.
1.01	7.00	28	6.00	0.00	0.00	0.00	0.00	0.00	2	1.02	19.00	172	86	.85	.01	28587.
1.01	7.15	29	6.00	0.00	0.00	0.00	0.00	0.00	1	1.02	19.15	173	86	.85	.01	28143.
1.01	7.30	30	6.00	0.00	0.00	0.00	0.00	0.00	0	1.02	19.30	174	86	.85	.01	27553.
1.01	7.45	31	6.00	0.00	0.00	0.00	0.00	0.00	0	1.02	19.45	175	86	.85	.01	26827.
1.01	8.00	32	6.00	0.00	0.00	0.00	0.00	0.00	0	1.02	20.00	176	86	.85	.01	25979.
1.01	8.15	33	6.00	0.00	0.00	0.00	0.00	0.00	0	1.02	20.15	177	86	.85	.01	25041.
1.01	8.30	34	6.00	0.00	0.00	0.00	0.00	0.00	0	1.02	20.30	178	86	.85	.01	24038.
1.01	8.45	35	6.00	0.00	0.00	0.00	0.00	0.00	0	1.02	20.45	179	86	.85	.01	22995.
1.01	9.00	36	6.00	0.00	0.00	0.00	0.00	0.00	0	1.02	21.00	180	86	.85	.01	21935.
1.01	9.15	37	6.00	0.00	0.00	0.00	0.00	0.00	0	1.02	21.15	181	86	.85	.01	20892.
1.01	9.30	38	6.00	0.00	0.00	0.00	0.00	0.00	0	1.02	21.30	182	86	.85	.01	19896.



1.01	10.48	79	.00	0.00	.00	168.	1.03	6.45	219	.00	0.00	.00	3139.
1.01	19.00	76	.00	0.00	.00	192.	1.03	7.00	220	.00	0.00	.00	2975.
1.01	18.15	77	.00	0.00	.00	218.	1.03	7.15	221	.00	0.00	.00	2823.
1.01	19.30	78	.00	0.00	.00	229.	1.03	7.30	222	.00	0.00	.00	2678.
1.01	19.45	79	.00	0.00	.00	239.	1.03	7.45	223	.00	0.00	.00	2540.
1.01	20.00	80	.00	0.00	.00	247.	1.03	8.00	224	.00	0.00	.00	2409.
1.01	20.15	81	.00	0.00	.00	241.	1.03	8.15	225	.00	0.00	.00	2286.
1.01	20.30	82	.00	0.00	.00	236.	1.03	8.30	226	.00	0.00	.00	2168.
1.01	20.45	83	.00	0.00	.00	227.	1.03	8.45	227	.00	0.00	.00	2057.
1.01	21.00	84	.00	0.00	.00	217.	1.03	9.00	228	.00	0.00	.00	1951.
1.01	21.15	85	.00	0.00	.00	206.	1.03	9.15	229	.00	0.00	.00	1850.
1.01	21.30	86	.00	0.00	.00	199.	1.03	9.30	230	.00	0.00	.00	1759.
1.01	21.45	87	.00	0.00	.00	186.	1.03	9.45	231	.00	0.00	.00	1669.
1.01	22.00	88	.00	0.00	.00	177.	1.03	10.00	232	.00	0.00	.00	1579.
1.01	22.15	89	.00	0.00	.00	165.	1.03	10.15	233	.00	0.00	.00	1497.
1.01	22.30	90	.00	0.00	.00	159.	1.03	10.30	234	.00	0.00	.00	1420.
1.01	22.45	91	.00	0.00	.00	151.	1.03	10.45	235	.00	0.00	.00	1346.
1.01	23.00	92	.00	0.00	.00	141.	1.03	11.00	236	.00	0.00	.00	1276.
1.01	23.15	93	.00	0.00	.00	136.	1.03	11.15	237	.00	0.00	.00	1210.
1.01	23.30	94	.00	0.00	.00	129.	1.03	11.30	238	.00	0.00	.00	1148.
1.01	23.45	95	.00	0.00	.00	122.	1.03	11.45	239	.00	0.00	.00	1088.
1.02	0.00	96	.00	0.00	.00	116.	1.03	12.00	240	.00	0.00	.00	1031.
1.02	.15	97	.03	.02	.01	111.	1.03	12.15	241	.01	0.00	.01	978.
1.02	.30	98	.03	.02	.01	107.	1.03	12.30	242	.01	0.00	.01	927.
1.02	.45	99	.03	.02	.01	104.	1.03	12.45	243	.01	0.00	.01	878.
1.02	1.00	100	.03	.02	.01	101.	1.03	13.00	244	.01	0.00	.01	833.
1.02	1.15	101	.03	.02	.01	114.	1.03	13.15	245	.01	0.00	.01	781.
1.02	1.30	102	.03	.02	.01	123.	1.03	13.30	246	.01	0.00	.01	733.
1.02	1.45	103	.03	.02	.01	135.	1.03	13.45	247	.01	0.00	.01	687.
1.02	2.00	104	.03	.02	.01	151.	1.03	14.00	248	.01	0.00	.01	644.
1.02	2.15	105	.03	.02	.01	169.	1.03	14.15	249	.01	0.00	.01	602.
1.02	2.30	106	.03	.02	.01	190.	1.03	14.30	250	.01	0.00	.01	563.
1.02	2.45	107	.03	.02	.01	213.	1.03	14.45	251	.02	0.00	.01	527.
1.02	3.00	108	.03	.02	.01	236.	1.03	15.00	252	.02	0.00	.01	494.
1.02	3.15	109	.03	.02	.01	259.	1.03	15.15	253	.02	0.00	.01	460.
1.02	3.30	110	.03	.02	.01	281.	1.03	15.30	254	.02	0.00	.01	427.

1.02	9.45	111	.03	.02	.01	304	1.03	15.45	259	.10	.09	.01	409
1.02	8.00	112	.03	.02	.01	322	1.03	16.00	256	.09	.01	.01	398
1.02	8.15	113	.03	.02	.01	341	1.03	16.15	257	.02	.00	.01	389
1.02	8.30	114	.03	.02	.01	359	1.03	16.30	259	.02	.00	.01	374
1.02	8.45	115	.03	.02	.01	376	1.03	16.45	259	.02	.00	.01	349
1.02	8.60	116	.03	.02	.01	393	1.03	17.00	260	.09	.09	.01	329
1.02	8.75	117	.03	.02	.01	408	1.03	17.15	261	.09	.00	.01	329
1.02	8.90	118	.03	.02	.01	422	1.03	17.30	262	.09	.00	.01	338
1.02	9.05	119	.03	.02	.01	436	1.03	17.45	263	.09	.00	.01	343
1.02	9.20	120	.03	.02	.01	449	1.03	18.00	264	.09	.00	.01	344
1.02	9.35	121	.03	.06	.01	464	1.03	18.15	265	.00	.00	.00	343
1.02	9.50	122	.03	.06	.01	479	1.03	18.30	265	.09	.09	.09	336
1.02	9.65	123	.03	.06	.01	494	1.03	18.45	267	.00	.00	.00	321
1.02	9.80	124	.03	.06	.01	508	1.03	19.00	268	.00	.00	.00	301
1.02	9.95	125	.03	.06	.01	522	1.03	19.15	269	.00	.00	.00	289
1.02	10.10	126	.03	.06	.01	536	1.03	19.30	270	.00	.00	.00	275
1.02	10.25	127	.03	.06	.01	550	1.03	19.45	271	.00	.00	.00	261
1.02	10.40	128	.03	.06	.01	564	1.03	20.00	272	.00	.00	.00	249
1.02	10.55	129	.03	.06	.01	578	1.03	20.15	273	.00	.00	.00	235
1.02	10.70	130	.03	.06	.01	592	1.03	20.30	274	.00	.00	.00	223
1.02	10.85	131	.03	.06	.01	606	1.03	20.45	275	.00	.00	.00	211
1.02	11.00	132	.03	.06	.01	620	1.03	21.00	276	.00	.00	.00	200
1.02	11.15	133	.03	.06	.01	634	1.03	21.15	277	.00	.00	.00	189
1.02	11.30	134	.03	.06	.01	648	1.03	21.30	278	.00	.00	.00	179
1.02	11.45	135	.03	.06	.01	662	1.03	21.45	279	.00	.00	.00	170
1.02	11.60	136	.03	.06	.01	676	1.03	22.00	280	.00	.00	.00	160
1.02	11.75	137	.03	.06	.01	690	1.03	22.15	281	.00	.00	.00	152
1.02	11.90	138	.03	.06	.01	704	1.03	22.30	282	.00	.00	.00	144
1.02	12.05	139	.03	.06	.01	718	1.03	22.45	283	.00	.00	.00	136
1.02	12.20	140	.03	.06	.01	732	1.03	23.00	284	.00	.00	.00	129
1.02	12.35	141	.03	.06	.01	746	1.03	23.15	285	.00	.00	.00	121
1.02	12.50	142	.03	.06	.01	760	1.03	23.30	286	.00	.00	.00	116
1.02	12.65	143	.03	.06	.01	774	1.03	23.45	287	.00	.00	.00	108
1.02	12.80	144	.03	.06	.01	788	1.04	0.00	288	.00	.00	.00	102

1.02	12.95	145	.03	.06	.01	802	1.04	0.00	289	.00	.00	.00	96
1.02	13.10	146	.03	.06	.01	816	1.04	0.00	290	.00	.00	.00	90
1.02	13.25	147	.03	.06	.01	830	1.04	0.00	291	.00	.00	.00	84
1.02	13.40	148	.03	.06	.01	844	1.04	0.00	292	.00	.00	.00	78
1.02	13.55	149	.03	.06	.01	858	1.04	0.00	293	.00	.00	.00	72
1.02	13.70	150	.03	.06	.01	872	1.04	0.00	294	.00	.00	.00	66
1.02	13.85	151	.03	.06	.01	886	1.04	0.00	295	.00	.00	.00	60
1.02	14.00	152	.03	.06	.01	900	1.04	0.00	296	.00	.00	.00	54
1.02	14.15	153	.03	.06	.01	914	1.04	0.00	297	.00	.00	.00	48
1.02	14.30	154	.03	.06	.01	928	1.04	0.00	298	.00	.00	.00	42
1.02	14.45	155	.03	.06	.01	942	1.04	0.00	299	.00	.00	.00	36
1.02	14.60	156	.03	.06	.01	956	1.04	0.00	300	.00	.00	.00	30

8/5

	PEAK	8-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	28021.	23628.	10409.	3653.	1052036.
CMS	816.	669.	295.	103.	29790.
INCHES	12038	2163	2278		
MM	31100	64987	57863		
AC-FT	11716	80638	21726		
THOUS CU M	14252	25256	26811		

1 002611 00411 091120792090

HYDROGRAPH AT STA 1 FOR PLAN 11 1110 1

TIME	PEAK	8-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
10	30	0	0	0	0
20	20	0	0	0	0
30	10	0	0	0	0
40	10	0	0	0	0
50	10	0	0	0	0
60	10	0	0	0	0
70	10	0	0	0	0
80	10	0	0	0	0
90	10	0	0	0	0
100	10	0	0	0	0
110	10	0	0	0	0
120	10	0	0	0	0
130	10	0	0	0	0
140	10	0	0	0	0
150	10	0	0	0	0
160	10	0	0	0	0
170	10	0	0	0	0
180	10	0	0	0	0
190	10	0	0	0	0
200	10	0	0	0	0
210	10	0	0	0	0
220	10	0	0	0	0
230	10	0	0	0	0
240	10	0	0	0	0
250	10	0	0	0	0
260	10	0	0	0	0
270	10	0	0	0	0
280	10	0	0	0	0
290	10	0	0	0	0
300	10	0	0	0	0
310	10	0	0	0	0
320	10	0	0	0	0
330	10	0	0	0	0
340	10	0	0	0	0
350	10	0	0	0	0
360	10	0	0	0	0
370	10	0	0	0	0
380	10	0	0	0	0
390	10	0	0	0	0
400	10	0	0	0	0
410	10	0	0	0	0
420	10	0	0	0	0
430	10	0	0	0	0
440	10	0	0	0	0
450	10	0	0	0	0
460	10	0	0	0	0
470	10	0	0	0	0
480	10	0	0	0	0
490	10	0	0	0	0
500	10	0	0	0	0
510	10	0	0	0	0
520	10	0	0	0	0
530	10	0	0	0	0
540	10	0	0	0	0
550	10	0	0	0	0
560	10	0	0	0	0
570	10	0	0	0	0
580	10	0	0	0	0
590	10	0	0	0	0
600	10	0	0	0	0
610	10	0	0	0	0
620	10	0	0	0	0
630	10	0	0	0	0
640	10	0	0	0	0
650	10	0	0	0	0
660	10	0	0	0	0
670	10	0	0	0	0
680	10	0	0	0	0
690	10	0	0	0	0
700	10	0	0	0	0
710	10	0	0	0	0
720	10	0	0	0	0
730	10	0	0	0	0
740	10	0	0	0	0
750	10	0	0	0	0
760	10	0	0	0	0
770	10	0	0	0	0
780	10	0	0	0	0
790	10	0	0	0	0
800	10	0	0	0	0
810	10	0	0	0	0
820	10	0	0	0	0
830	10	0	0	0	0
840	10	0	0	0	0
850	10	0	0	0	0
860	10	0	0	0	0
870	10	0	0	0	0
880	10	0	0	0	0
890	10	0	0	0	0
900	10	0	0	0	0
910	10	0	0	0	0
920	10	0	0	0	0
930	10	0	0	0	0
940	10	0	0	0	0
950	10	0	0	0	0
960	10	0	0	0	0
970	10	0	0	0	0
980	10	0	0	0	0
990	10	0	0	0	0
1000	10	0	0	0	0

D-13

9/5

ROUTE THROUGH RESERVOIR

ISTAQ	ICOMP	IECOM	ITAPE	JPLT	JPRI	INAME	ISTAGE	IAUTO
2	1	0	U	0	0	1	0	0

AVG. LOSS	CLOSS	AVG.	IBRS	ISAME	ICPT	IPMP	ISTB
0.0	0.000	0.000	1	1	0	0	0

ROUTING DATA

NSTPS	NSTD	LAG	AMSEK	X	TSK	STORA	ISPRAT
1	0	U	0.000	0.000	0.000	-1635.	0

SURFACE AREA

CAPACITY	0.	880.	1765.	1923.	2749.	3636.
----------	----	------	-------	-------	-------	-------

ELEVATIONS

1584.	1635.	1668.	1660.	1672.	1680.
-------	-------	-------	-------	-------	-------

DAM DATA

TOPEL	COOD	EXPD	DAMWID
19377	978	155	7201

STATION

80 PLAD 11 RALIA

END-OF-PERIOD HYDROGRAPH ORDINATES

0.	1.	2.	3.	4.	5.	6.	7.	8.	9.	10.
0.	1.	1.	1.	1.	1.	1.	1.	1.	1.	1.









14/5

PEAR FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION STATION AREA PLAN RATIO 1 RATIO 2 RATIO 3 RATIO 4  
.20 .30 .40 .50 1.00

HYDROGRAPH 1 17.90 1 87691 80566 11978 208211  
39381 100221 200221 320451 819011  
ROUTED TO 2 17.90 1 26866 85510 11420 28647  
1 462361 1 160941 242151 323381 811181

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 ..... INITIAL VALUE ..... SPILLWAY CREST ..... TOP OF DAM

ELEVATION STORAGE	1635.00	1635.00	1651.20
OUTFLOW	680.	680.	1428.
	0.	0.	10000

RATIO OF PMF	MAXIMUM RESERVOIR W.S. LEV		MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS		TIME OF FAILURE HOURS	
	0.00	0.00			0.00	0.00	0.00	0.00
1.00	1640.53	1643.26	9121	9996.	0.00	0.00	0.00	0.00
0.90	1643.80	1646.53	1061.	11520.	0.00	0.00	0.00	0.00
0.80	1651.24		1430.	28647.	0.25	93.00	0.00	0.00

APPENDIX E

DRAWINGS







Figure 1




3-A  
PROFILE ON AXIS OF DAM  
Scale: 1/4" = 10' Vert. 1" = 100' Hor.



DETAIL 3-D  
FRONT UPTHEAM BREATHER OF DAM  
Scale: 1/4" = 1' Hor.




SECTION 3-E  
Scale: 1/4" = 1' Hor.




TYPICAL SECTION 3B  
Scale: 1/4" = 1' Hor.

2



3-A  
PROFILE ON AXIS OF DAM  
Scale: Horiz. 1" = 100' Vert. 1" = 20'

SECTION THRU CULVERT & GATE TOWER  
Scale: Horiz. 1" = 20' Vert. 1" = 20'



TYPICAL SECTION THRU DAM  
SECTION 3B  
Scale: 1" = 20'





DETAIL OF  
CUTOFF WALL DETAILS  
Scale: 1" = 20'

SUPPLEMENTARY DRAWING  
THIS DRAWING SUPPLEMENTS AND SUPERSEDES THE ORIGINAL CONTRACT DRAWINGS


<b>REVISED</b> DATE: _____ BY: _____ REASON: _____	<b>THE GENERAL STATE AUTHORITY</b>		<b>PROJECT NO GSA-170-5</b>	
	APPROVED: _____ APPROVED: _____ SUBMITTED: _____ APPROVED: _____ APPROVED: _____ APPROVED: _____ APPROVED: _____ APPROVED: _____ APPROVED: _____	EXECUTIVE DIRECTOR ASSISTANT ENGINEER THE CHESTER ENGINEERS WEST DEPT. OF FORESTRY & WATER CHIEF FOREST DEPT. OF FORESTRY & WATER DEPT. OF FORESTRY & UTILITIES CONTRACTOR BY _____ CONTRACTOR BY _____ CONTRACTOR BY _____	<b>THE LYMAN RUN LAKE &amp; DAM</b> HUNTERDON COUNTY, NEW JERSEY <b>EARTH DAM - SECTIONS</b>	
				<b>SHEET NO. 43</b>

FIGURE 2

L. ROBERT KIMBALL & ASSOCIATES  
CONSULTING ENGINEERS & ARCHITECTS



2



SUPPLEMENTARY DRAWING





DO NOT USE THIS DRAWING SUPPLEMENTS AND SUPERSEDES THE ORIGINAL CONTRACT DRAWINGS

REVISED	THE GENERAL STATE AUTHORITY		PROJECT NO GSA-170-5	
APPROVED	ENGINEER		THE LYMAN RUN LAKE # DAM	
APPROVED	INSPECTOR		SUSQUEHANNA STATE FOREST - PUTTER, PENNSYLVANIA	
APPROVED	THE TRUSTEES ENGINEER		PLAN OF DAM	
APPROVED	NEW YORK STATE FOREST & WATER		DESIGNED ENGINEER	REGISTERED ENGINEER
APPROVED	NEW YORK STATE DEPT OF FOREST & WATERS		1949	THE GENERAL STATE AUTHORITY
APPROVED	NEW YORK STATE DEPT OF FOREST & WATERS		DATE	ISSUED IN COPY
ACCEPTED	NEW YORK STATE DEPT OF FOREST & WATERS		JULY 1949	38
ACCEPTED	NEW YORK STATE DEPT OF FOREST & WATERS		SCALE	ENGINEER
ACCEPTED	NEW YORK STATE DEPT OF FOREST & WATERS		1/2" = 1'	BY
ACCEPTED	NEW YORK STATE DEPT OF FOREST & WATERS		DATE	BY



FIGURE 8

L. ROBERT KIMBALL & ASSOCIATES  
CONSULTING ENGINEERS & ARCHITECTS

1 2



PLAN OF SPILLWAY DOWNSTREAM



PLAN OF SPILLWAY  
Scale 1/2"=1'-0"




SUPPLEMENTARY DRAWING  
THIS DRAWING SUPPLEMENTS AND SUPERSEDES THE ORIGINAL CONTRACT DRAWINGS

REVISED		THE GENERAL STATE AUTHORITY		PROJECT NO 65A-170-5	
NO.	DATE	APPROVED	TITLE	THE LYMAN RUN LAKE & DAM	
		APPROVED	TITLE	SUBDIVISION OF STATE FOREST - POTTER COUNTY, PA.	
		SUBMITTED	<i>John J. Kimball</i>	SPILLWAY	
		APPROVED	TITLE	REGISTERED ENGINEER	REGISTERED ENGINEER
		APPROVED	TITLE	PHILADELPHIA, PENN.	PITTSBURGH, PENN.
		APPROVED	TITLE	15 00	THE GENERAL STATE AUTHORITY
		APPROVED	TITLE	DATE	DATE
		ACCEPTED	TITLE	NO. 65A-170-5	SHEET OF 65
		ACCEPTED	TITLE	DATE	DATE
		ACCEPTED	TITLE	DATE	DATE
		ACCEPTED	TITLE	DATE	DATE

FIGURE 4

12

L. ROBERT KIMBALL & ASSOCIATES  
CONSULTING ENGINEERS & ARCHITECTS









FIGURE 5

2 L. ROBERT KIMBALL & ASSOCIATES  
CONSULTING ENGINEERS & ARCHITECTS




**GENERAL PLAN**  
10-10-54

1



**LOCATION MAP**  
Scale 1:100,000



**SITE PLAN**  
Scale 1:50,000

PROJECT NO. R53-6-102.1 PROJECT TITLE DATE DRAWN BY CHECKED BY	
PROJECT NO. R53-6-102.1 PROTECTIVE MEASURES FOR SCOUR AND SEEPAGE LYBAN RUN STATE PARK DAM POTTER CO. PENNSYLVANIA	
GENERAL PLAN	
SHEET NO. OF SHEETS	2 of 4

**LEGEND**

1. The concrete spillway is shown on 1, 2 and 3.
2. Details of bridge pier and other structures are on sheet 3.
3. Details of concrete retaining structure and details of wing protection are shown on sheet 3.
4. Details of dam structure are shown on sheet 1.
5. Details of dam structure are shown on sheet 2.
6. Details of dam structure are shown on sheet 3.


PLAN

1





2






**FIGURE 6**

**L. ROBERT KIMBALL & ASSOCIATES  
CONSULTING ENGINEERS & ARCHITECTS**




PLAN  
Scale 1/4" = 20' 0"






PROJECT NO R53 6-102 1	
PROTECTIVE MEASURES FOR SCOUR AND SEEPAGE LYMAN RUN STATE PARK DAM POTTER CO PENNSYLVANIA	
DETAILS AND SECTIONS SITE 1	
3 of 4	

FIGURE 7



**PROFILE**

Scale: Hor. 1" = 500', Vert. 1" = 10'



**TYPICAL SECTION**

Scale: 1" = 10'

1




APPENDIX F  
GENERAL GEOLOGY

General Geology.

Lyman Run Dam lies within the Allegheny Mountain Section of the Appalachian Plateau Physiographic Province as described by Fennemann (1938). This section is typified by broad, gentle folding. The surface of this area has been reworked by glaciation. The strata underlying the dam are essentially flat lying.

The dam is underlain by the Catskill Formation of Upper Devonian age. This formation is approximately 2000 feet thick in the area. This formation thickens to the southeast and thins to the northwest. The formation consists of red to brownish shales and sandstone tongues named Elk Mountain, Homesdale, and Shohola.



GEOLOGIC MAP OF LYMAN RUN DAM AREA

Dea

**Catskill Formation**

*Chiefly red to brownish shales and sandstones, including gray and greenish mudstone, tuffaceous sandstone, etc. Mountain House, Skokholm, and Delaware River in the east.*

Scale: 1:250,000