

MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

Name Of Dam:

Location:

Inventory Number:

TENNESSEE RIVER BASIN

MIDDLE FORK SLURRY IMPOUNDMENT

RUSSELL COUNTY, VIRGINIA


VA. NO. 16708

①

LEVEL II

# PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM

ADA 084370



DTIC  
ELECTE  
MAY 21 1980  
S C D

THIS DOCUMENT IS BEST QUALITY PRACTICABLE.  
THE COPY FURNISHED TO DDC CONTAINED A  
SIGNIFICANT NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.

PREPARED FOR

NORFOLK DISTRICT CORPS OF ENGINEERS  
803 FRONT STREET  
NORFOLK, VIRGINIA 23510

BY

SCHNABEL ENGINEERING ASSOCIATES, P.C./  
J. K. TIMMONS AND ASSOCIATES, INC.

This document has been approved  
for public release and sale; its  
distribution is unlimited.

MARCH 1980 80 5 19 027

DDC FILE COPY

## **DISCLAIMER NOTICE**

**THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.**

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER VA 16708	2. GOVT ACCESSION NO. AD-A084370	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program MIDDLE FORK SLURRY IMPOUNDMENT RUSSELL COUNTY, VA		5. TYPE OF REPORT & PERIOD COVERED Final Rept.
7. AUTHOR(s) Ray E. Martin Schnabel Engineering Associates 1 Cary Street Richmond, VA 23220		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS 12 756		8. CONTRACT OR GRANT NUMBER(s) 15) DACW65-79-D-0004
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineering District, Norfolk 803 Front Street Norfolk, VA 23510		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE Mar 80
		13. NUMBER OF PAGES
		15. SECURITY CLASS. (of this report) Unclassified
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia 22151		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dams - VA National Dam Safety Program Phase I Dam Safety Dam Inspection		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) (See reverse side) National Dam Safety Program Middle Fork Slurry Impoundment (ID VA-16708) Tennessee River Basin, Middle Fork of Dumps Creek, Russell County, Virginia, Phase I Inspection Report.		

20. Abstract

Pursuant to Public Law 92-367, Phase I Inspection Reports are prepared under guidance contained in the recommended guidelines for safety inspection of dams, published by the Office of Chief of Engineers, Washington, D. C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general conditions of the dam is based upon available data and visual inspections. Detailed investigations and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

Based upon the field conditions at the time of the field inspection and all available engineering data, the Phase I report addresses the hydraulic, hydrologic, geologic, geotechnic, and structural aspects of the dam. The engineering techniques employed give a reasonably accurate assessment of the conditions of the dam. It should be realized that certain engineering aspects cannot be fully analyzed during a Phase I inspection. Assessment and remedial measures in the report include the requirements of additional indepth study when necessary.

Phase I reports include project information of the dam and appurtenances, all existing engineering data, operational procedures, hydraulic/hydrologic data of the watershed, dam stability, visual inspection report and an assessment including required remedial measures.

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D. C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

TABLE OF CONTENTS

Preface . . . . . 1

Brief Assessment of Dam . . . . . 1

Overview Photo . . . . . 3

Section 1: PROJECT INFORMATION . . . . . 4

Section 2: ENGINEERING DATA . . . . . 8

Section 3: VISUAL INSPECTION . . . . . 12

Section 4: OPERATIONAL PROCEDURES . . . . . 15

Section 5: HYDRAULIC/HYDROLOGIC DATA . . . . . 16

Section 6: DAM STABILITY . . . . . 18

Section 7: ASSESSMENT/REMEDIAL MEASURES . . . . . 22

Appendices

- I - Maps and Drawings
- II - Photographs
- III - Field Observations
- IV - Current Plan for Upgrading the Impoundment
- V - Preliminary Test Boring Logs
- VI - Stability Analysis Summary by  
L. Robert Kimball & Associates
- VII - Stability Analysis Summary by  
Orbital Engineering, Inc.
- VIII - References

Accession For	
NTIS GSA&I	<input checked="" type="checkbox"/>
DEC TAB	
Unannounced Justification	
By _____	
Dist. Number/ _____	
App. # _____	
Author/Editor/ _____	
Dist. Special _____	
AG	

Name: Middle Fork Slurry Impoundment Va. No. 16708  
State: Virginia  
County: Russell  
USGS Quad Sheet: Carbo  
Coordinates: Lat 36° 57.7' Long 82° 12.1'  
Stream: Middle Fork of Dumps Creek  
Date of Inspection: December 11, 1979

BRIEF ASSESSMENT OF DAM

Middle Fork Slurry Impoundment Dam is a mine waste structure, constructed with fine to coarse coal refuse materials. It is approximately 1100 ft long and 300 ft high at its lowest point. This impoundment is a cross valley type structure which is located on the Middle Fork of Dumps Creek approximately 2 miles north of Carbo, Virginia. The dam is owned by Clinchfield Coal Company. The impoundment is used to contain coal refuse pumped from the Moss Mine No. 3 coal preparation plant. Water from the slurry is decanted into a 60 inch diameter diversion pipe at the upstream end of the impoundment. The 60 inch pipe also serves to divert runoff around the impoundment.

This dam is ultimately scheduled for abandonment by filling with refuse, and plans are being prepared for the abandonment procedure.

The dam is an "intermediate" size, "significant" hazard structure. The appropriate spillway design is the PMF. The dam will contain 100 percent of the PMF without overtopping. Based on criteria established by the Department of the Army, Office of the Chief of Engineers (OCE), the dam is rated adequate.


The actual embankment structure is presently being graded to conform with current design drawings for future use and abandonment

of the dam. The stability analysis for the original dam prior to the modifications presently in progress indicates a factor of safety of 1.22 with respect to steady seepage. This is less than the 1.5 requirement included in Reference 1, Appendix VIII. The present modifications will improve the stability of the structure and additional studies are not recommended.

The visual inspection revealed no apparent problems with the embankment and there are no immediate needs for remedial or maintenance measures.

Prepared by:

SCHNABEL ENGINEERING ASSOCIATES, P.C./  
J. K. TIMMONS AND ASSOCIATES, INC.

  
\_\_\_\_\_  
Ray E. Martin, Ph.D., P.E.  
Commonwealth of Virginia

Submitted By:

Original signed by  
JAMES A. WALSH

\_\_\_\_\_  
James A. Walsh, P.E.  
Chief, Design Branch

Approved:

Original signed by:  
Douglas L. Haller

\_\_\_\_\_  
Douglas L. Haller  
Colonel, Corps of Engineers  
District Engineer

Recommended By:

Original signed by  
JACK G. STARR

\_\_\_\_\_  
Jack G. Starr, R.A., P.E.  
Chief, Engineering Division

Date: \_\_\_\_\_

MAR 8 1960



Overview Photo  
Upstream is to the left  
Fall 1970

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
MIDDLE FORK SLURRY IMPOUNDMENT  
VA. NO. 16708

SECTION 1 - PROJECT INFORMATION

1.1 General:

1.1.1 Authority: Public Law 92-367, 8 August 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a national program of safety inspections of dams throughout the United States. The Norfolk District has been assigned the responsibility of supervising the inspection of dams in the Commonwealth of Virginia.

1.1.2 Purpose of Inspection: The purpose is to conduct a Phase I inspection according to the Recommended Guidelines for Safety Inspection of Dams (See Reference 1, Appendix VIII). The main responsibility is to expeditiously identify those dams which may be a potential threat to human life or property.

1.2 Project Description:

1.2.1 Dam and Appurtenances: The Middle Fork Slurry Impoundment Dam is a cross valley mine waste structure constructed with coarse to fine coal refuse materials. It is approximately 1100 ft long and 300 ft high at its lowest point (measured from the toe of the downstream face). The dam is approximately 36 ft high measured from the upstream sediment elevation to the low point in the dam crest. The top of the dam varies in elevation from 1950<sup>±</sup> msl to 2000<sup>±</sup> msl, and the width of the dam crest varies from 100 ft to 400 ft.

Upstream slopes are at the angle of repose (less than one horizontal to one vertical, 1:1) and the downstream slopes vary from 1:1 to 3:1 (See Sheet 9, Appendix III).

Within the impoundment, two additional embankments exist (See Plate No. 2, Appendix I). The middle embankment was previously used for slurry containment upstream, but has been abandoned and replaced with embankment "D" located an additional 1500 ft upstream.

The spillway consists of a 60 inch diameter corrugated metal pipe (CMP) used as a diversion channel. The pipe inlet is located upstream of the impoundment at embankment "D", and extends under the impoundment to the toe of the main embankment (See Plate No. 3, Appendix I). The 60 inch pipe discharges into the natural valley stream below the toe of the dam.

1.2.2 Location: Middle Fork Slurry Impoundment is located on the Middle Fork of Dumps Creek approximately two miles north of Carbo, Virginia (See Plate 1, Appendix I).

1.2.3 Size Classification: The dam is classified as an "intermediate" size structure because of the impoundment potential at the dam crest of 3300 acre ft.

1.2.4 Hazard Classification: The dam is located in a rural area; however, based upon the downstream proximity of the Clinch River Power Plant and the Town of Carbo, the dam is assigned a "significant" hazard classification. The hazard classification used to categorize a dam is a function of location only and has nothing to do with its stability or probability of failure.

1.2.5 Ownership: The dam is owned by the Clinchfield Coal Company, a member of the Pittston Coal Group.

1.2.6 Purpose: The impoundment is used to contain coal sediment from the slurry pumped out of Moss No. 3 Preparation Plant, and to decant the water after the solids have settled out.

1.2.7 Design and Construction History: There was no original design data available; however, the dam was reportedly constructed under the supervision of the Clinchfield Coal Company. Future use and abandonment plans are currently being prepared by the Owner's engineering consultant. An abandonment plan is the filling of the impoundment with refuse and diversion of runoff away from the impoundment. Preliminary engineering studies were performed by L. Robert Kimball and Associates, in 1978; however, Orbital Engineering Inc., Carnegie, Pennsylvania, has since been retained by the Owner to complete the plans. Reports and plans are submitted on an interim basis and the study was not complete at the time of the investigation. Appendix IV includes a brief description of the plan approved in 1978 for upgrading the impoundment. Plate No. 2 of Appendix I includes grading plans for the structure with the present pool level sketched in.

1.2.8 Normal Operational Procedures: The diversion pipe inlet, which acts as a spillway, is ungated; therefore, water rising above the invert of the outlet pipe automatically is discharged downstream in quantities based on the pipe capacity. Normal pool (elev 1916 msl) is maintained by the overflow weir located on

embankment "D" immediately upstream of the pipe inlet. The diversion pipe also intercepts upstream runoff and diverts the runoff away from the impoundment.

1.3 Pertinent Data:

1.3.1 Drainage Areas: The drainage area is 1.00 square miles.

1.3.2 Discharge at Dam Site: Maximum known flood at the dam site occurred in April 1977; however, the pool elevation was not observed. Water has reportedly never overtopped the dam.

Spillway Discharge:

Pool Elevation at Crest of Dam            215 CFS  
(elev 1950 msl)

1.3.3 Dam and Reservoir Data: See Table 1.1, below:

TABLE 1.1 DAM AND RESERVOIR DATA

Item	Elevation Feet msl	Reservoir			
		Area Acres	Acres <sup>**</sup> Feet	Watershed Inches	Length Miles
Crest of Dam	1950*	53	3300	31.9	1.1
Spillway Invert	1875	27	750	1.2	0.5
Downstream Toe of Dam	1650±	-	-	-	-

\* Low Point In Embankment

\*\* Includes refuse storage accumulation

## SECTION 2 - ENGINEERING DATA

2.1 Design: There are no design data for the original construction. All phases of mining operations are controlled and regulated by the U. S. Department of Labor, Mine Safety and Health Administration (MSHA); the Virginia Division of Mines and Quarries (VDMQ); and the Virginia Division of Mined Land Reclamation (DMLR). The impoundment has been used and maintained in compliance with standards required by the above governmental agencies. Although design and "As Built" data were not available, the Owner is presently completing an engineering study for future use and eventual abandonment (for explanation of abandonment, see Section 1) of the entire Moss No. 3 refuse area, which includes the Middle Fork Slurry Impoundment. A preliminary abandonment report was completed in 1978 by L. Robert Kimball and Associates, which included a hydrologic and stability study. The Owner has since retained Orbital Engineering for completion of the future use and abandonment plan. This dam is scheduled for abandonment as an impoundment, and all impoundment capabilities will be eliminated by filling the reservoir with refuse.

The dam site is located with the southeast edge of the Appalachian Plateau (locally Cumberland Plateau) Physiographic Province of Virginia. The Cumberland Plateau is a stream-dissected plateau which is underlain by sedimentary rocks up to upper Pennsylvania in age (See Reference 3, Appendix VIII). The structure crosses the contact between the Lee and Norton Formations. Both formations consist basically of alternating beds of sandstone and shale with interbeds of coal. Coal beds in the Norton, however, are generally thicker and of

greater commercial value. Local geologic structure is controlled by the Hunter Valley Fault which extends in a northeastward direction approximately  $\frac{1}{2}$  mile south of the site. Presence of the fault causes bedding dips to increase from horizontal to vertical over the one-half mile<sup>+</sup> distance.

At the Owner's request, two engineering studies were conducted between 1976 and 1978 by L. Robert Kimball and Associates in order to evaluate the stability of the dam embankment and prepare plans to modify the embankment to meet MSHA requirements. A summary of stability analyses and pertinent laboratory test data are included as Appendix VI. Analyses completed in 1978 resulted in the proposed addition of an embankment berm at the downstream toe of the originally proposed (1976) embankment design configuration. It was believed that the 1978 report was prepared without conclusive documentation of existing seepage conditions within the existing embankment. Consequently, the proposed design configuration with berm added did not resolve the issue of long-term embankment stability to the complete satisfaction of MSHA.

The Owner later engaged Orbital Engineering, Inc. to perform a geotechnical engineering study which would evaluate conditions within the existing embankment, determine the engineering properties of fill materials to be used in constructing the remainder of the embankment, and evaluate the stability of the minimum (no berm) embankment design section described in the 1978 Kimball report. Test borings were drilled and test pits excavated to obtain soil samples for laboratory testing and engineering evaluation of material properties. A

pneumatic piezometer was installed in each test boring upon completion. A plan of the embankment area showing locations of the piezometers, test pits, and embankment section used in the stability analysis is presented as Plate 1 of Appendix VII. Boring logs are included as Appendix V.

At the time of the inspection, water levels in the piezometers had not stabilized; however, readings are now taken weekly and recorded by the Owner. The following readings were taken by Orbital Engineering on December 17, 1979:

<u>PIEZOMETER NO.</u>	<u>GROUND EL @ INSTALLATION</u>	<u>TIP EL (MSL)</u>	<u>WATER LEVEL (MSL)</u>
P-1	1772.4	1683.4	1699.8
P-2	1779.2	1685.1	DRY
P-3	1977.4	1777.4	DRY

The preliminary engineering report and supplementary data developed by Orbital Engineering, Inc. includes laboratory test data describing the physical properties of the materials used to construct the embankment. Soil parameters developed in previous studies by L. Robert Kimball and Associates were also considered. Stability calculations were developed using the ICES (Bishop slip circle) slope and embankment stability program, SLOPE. Stability analysis data developed by Orbital Engineering, Inc. are presented in Appendix VII.

2.2 Construction: Construction records were not available. The dam has been constructed with equipment owned by Clinchfield Coal Company.

2.3 Operation: Present grading and filling procedures are intended to increase the stability of the structure. Piezometers were installed in 1979 to monitor the phreatic water level below the downstream slope. Plans are presently being developed to modify the embankment in compliance with MSHA requirements. More detailed information will be available from the Owner upon completion of current and future studies.

2.4 Evaluation: Original engineering calculations and drawings are not available, but the drawings for the proposed embankment modification are representative of the dam, and hydrologic and hydraulic calculations are adequate. There are no other records available, except the records of the recently installed piezometers.

### SECTION 3 - VISUAL INSPECTION

3.1 Findings: The impoundment was generally in good condition at the time of inspection. Field observations are outlined in Appendix III.

3.1.1 General: An inspection was made 11 December 1979, and the weather was fair with the temperature 35°F. The pool at the time of inspection was at elevation 1916 msl and no tailwater was observed. At the time of inspection, ground conditions were dry. No previous inspection reports were available.

3.1.2 Dam and Spillway: The embankment has been constructed with fine to coarse coal refuse and was essentially free of vegetation. The downstream slope included three benched surfaces at the time of the inspection. Except for the upper most slope, all benches and slopes appeared to be recently constructed and relatively free of erosion. The steep slope (1:1<sup>±</sup>) existing between the crest of the impoundment and the first bench (100 ft<sup>±</sup> difference in elevation) was severely eroded and included gullies 1.5 ft<sup>±</sup> deep and 10 ft<sup>±</sup> wide. The only seepage observed was located near the right abutment on the uppermost bench. The Owner was aware of these wet areas and stated that recent studies by their engineer concluded that the wet spots represent surface water seepage along a buried impervious haul road surface and not seepage through the dam.

Bedrock is exposed only in the right abutment and consists of thin to massively bedded sandstone with weathered shale interbeds. Bedding dips at 45 degrees<sup>±</sup> to the southeast. No faults were observed in the field during this investigation and geologic maps of the area do not show the presence of faults in the immediate vicinity.

The spillway consists of an ungated 60" CMP located at the upstream end of the impoundment. The pipe is in good condition and was recently extended to its current location.

3.1.3 Reservoir Area: The reservoir is in rock cuts, from construction operations, and natural terrain with slopes ranging from vertical to 2:1. These slopes range from bare to densely wooded. Sedimentation was observed throughout the majority of the reservoir area. Pool depth ranged from zero at the main embankment to  $\pm$  20 ft at embankment "D".

3.1.4 Downstream Area: The Middle Fork of Dumps Creek and Dumps Creek converge with the Clinch River approximately two miles downstream of the embankment. The Town of Carbo and the Clinch River Power Plant are located at the Dumps Creek intersection with the Clinch River. The Power Plant and several dwellings in Carbo are located in the flood plain of the Clinch River.

3.1.5 Instrumentation: Three air-activated piezometers were recently installed. Two occur along the downstream toe and one on the crest of the embankment.

### 3.2 Evaluation:

3.2.1 Dam and Spillway: Overall, the dam was in good condition at the time of inspection. The wet spots observed on the uppermost bench are believed to represent surface runoff/seepage following along the path of a covered haul road. The December 17, 1979 piezometer reading from P-1 indicates a piezometric level greater than 100 ft below these wet spots.

The erosion observed on the uppermost portion of the downstream slope is not considered serious because of the massive width of the

embankment. As the future use and abandonment plan is initiated, future grading operations will reshape this slope and provide a more stable and erosion-resistant surface.

The 60" CMP (spillway) appears to be in good condition and appears to be functioning properly.

3.2.2 Downstream Area: The location of the Clinch River Power Plant and the Town of Carbo downstream of the dam (two miles), provides potential for damage and loss of life.

## SECTION 4 - OPERATIONAL PROCEDURES

4.1 Procedures: Coal refuse slurry is pumped into the impoundment through an eight inch pipe located at the upstream end of the impoundment. After the solids settle out, the water is decanted from the upstream end of the impoundment into the 60 inch diameter diversion pipe. Runoff from the upstream valley and the impoundment is diverted into the diversion structure. If the runoff exceeds the diversion structure capacity, excess runoff is stored in the impoundment until it can be removed through the diversion pipe.

4.2 Maintenance of Dam and Appurtenances: Maintenance of the dam and appurtenances is the responsibility of the Clinchfield Coal Company. The embankment is maintained to prevent erosion and the diversion pipe inlet is kept clean of debris. There are no other maintenance requirements.

4.3 Warning System: None exists.

4.4 Evaluation: The maintenance of the dam and appurtenances is adequate. An early warning system should be implemented and an emergency action plan should be prepared.

## SECTION 5 - HYDRAULICS/HYDROLOGIC DATA

5.1 Design: No data is available.

5.2 Hydrologic Records: There are no hydrologic records available for this drainage area.

5.3 Flood Experience: The maximum pool elevation observed was in April 1977; however, the pool elevation is not known.

5.4 Flood Potential: In accordance with the established guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (flood discharges that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible), or fractions thereof. Precipitation amounts for the PMF and  $\frac{1}{2}$  PMF are taken from U. S. Weather Bureau Information (Reference 4, Appendix VIII). Appropriate adjustments for basin size and shape were accounted for and inflow volumes were determined by procedures as outlined in Reference 4, Appendix VIII. The maximum pool elevation was determined by the reservoir storage curve at the volume of inflow predicted.

5.5 Reservoir Regulation: The pool at the beginning of the inflow was assumed to be at elevation 1916 msl (normal pool). Reservoir stage-storage data was determined from the available plans, reports, field measurements, and USGS quadrangle sheets. The diversion pipe was assumed to be blocked and not functioning.

5.6 Overtopping Potential: The predicted rise of the reservoir pool and other pertinent data were determined by storing the volume of inflow in the reservoir as previously described. The results for

the flood conditions (PMF,  $\frac{1}{2}$  PMF) are shown in the following

Table 5.1:

TABLE 5.1 RESERVOIR PERFORMANCE

	Normal Flow	Flood	
		$\frac{1}{2}$ PMF	PMF
Total Inflow,			
Ac-Ft	-	665	1330
Maximum Storage*			
(Ac-Ft)	1900	2565	3230
Maximum Pool Elev.,			
ft., MSL	1916	1930	1944

\* Includes refuse storage accumulation

5.7 Reservoir Emptying Potential: There is no method of lowering the reservoir below the spillway except by seepage and pumping.

5.8 Evaluation: Department of the Army, COE, guidelines indicate the appropriate spillway design flood (SDF) for an intermediate size significant hazard dam is the  $\frac{1}{2}$  PMF to PMF. Because of the risk involved, the PMF has been selected as the SDF. The reservoir will store 100 percent of the PMF with six feet of freeboard.

Hydrologic data used in the evaluation pertains to present day conditions with no consideration given to future development.

## SECTION 6 - DAM STABILITY

6.1 Foundation and Abutments: The dam is believed to be founded on alluvial and/or residual soils, all of which are underlain by the Lee and Norton Formations. Three test borings drilled at the site (See Appendix V) encountered from 89 to 215 ft of coarse coal refuse. Boring P-3, drilled to a depth of 215 ft did not fully penetrate the fill. The test boring logs only describe the coarse coal refuse and bedrock; therefore, it is not known where alluvial and/or residual soils exist and what their physical character and thicknesses are. Top of bedrock was encountered between elevation 1690 and 1680 in the two borings in which bedrock was cored. The bedrock included brown to gray weathered to slightly weathered sandstone, gray clay and weathered shale. Core recoveries (Bx-size or 1-5/8 inch diameter) ranged from 50 to 100% for the sandstone while blow counts recorded during Standard Penetration Tests ranged from 41 per ft to 50/0.3 ft in the clay and weathered shale. Bedrock exposed in the right abutment consisted of similar rock; however, their surface exposure has resulted in a more weathered and fractured physical appearance.

6.2 Embankment: The upstream slope is very steep, ranging from 2 horizontal to 1 vertical to near vertical. The downstream slope includes three benched areas with intervening slopes ranging from approximately 1 horizontal to 1 vertical, to 3 horizontal to 1 vertical (See Sheet 9, Appendix III). The crest of the embankment ranges from elevation 1950± to 2000± msl while the downstream toe is at elevation 1650±.

Normal pool for the impoundment is elevation 1916±. Recently developed laboratory test data concludes that the embankment fill or coal refuse is non-plastic and granular; ranging from fine sand to coarse gravel in size. Placement of this material is by bulldozer and compaction is accomplished by the weight of the machinery during grading operations.

Three piezometers have been recently installed at the locations shown on Plate 2, Appendix I in order to monitor the phreatic level within or beneath the embankment. Readings taken in December 1979 indicate water at elevation 1700± in P-1, which corresponds to the basal portion of the fill. No water was encountered in the other piezometers. Seepage or wet spots described in Section 3 on the downstream slope occur well above elevation 1700± and apparently are caused by surface water seepage along impervious buried surfaces.

Steep to moderately steep slopes form the right abutment; however, the left abutment was covered with coarse coal refuse and was not visible. Weathered and fractured sandstone and shale are exposed in the right abutment and slopes in this area were considered safe and stable at the time of inspection.

### 6.3 Evaluation:

6.3.1 Foundation and Abutments: Dam foundations must be evaluated on the basis of potential settlement, sliding and seepage. Excessive settlement of the dam is not believed to be a problem since test boring data indicates the structure rests upon fairly competent bedrock and hard residual clay. The contact between the embankment fill and overburden soils was not defined in the test boring logs.

Based upon the size of the embankment and the type of soils encountered, it is assumed that settlement related to compression of native overburden soils has been essentially completed under the existing loading condition.

Subsurface mining has been performed within the Jawbone coal bed of Norton Formation. This bed is approximately 4 ft thick and is present just below elevation 1700. The Jawbone seam has been mined beneath the back of the impoundment. A mining plan developed by the Owner considered the possibility of subsidence and its effects on the impoundment. The plan provided an adequate factor of safety against subsidence, and consequently the plan was approved by MSHA in April, 1979. No mining has reportedly taken place beneath the embankment.

A review of the geologic and test boring data indicates that some of the thin clay seams present near the top of the underlying formations could possibly act as potential sliding surfaces. However, the relatively stiff condition of these soils and high ratio of base width to height of this dam reduces the possibility of sliding of the dam along the interface between the embankment and the foundation soils or rock. Consequently, sliding within the foundation bedrock is not believed to be a problem.

Examination of bedrock exposed in the right abutment and the test boring data indicate that much of the underlying near-surface shale and sandstone could be jointed or fractured enough to allow

some seepage beneath the dam. Based upon the physical character of the bedrock, this seepage would probably not be detrimental to the satisfactory performance of the structure.

6.3.2 Embankment: No undue settlement, cracking or seepage was noted at the time of inspection; thus it appears that the embankment is adequate for normal pool level with water at elevation 1916± msl. The stability analysis performed for the original embankment (Appendix VI) indicated a factor of safety of 1.22 for the steady seepage case which is less than the factor of safety of 1.5 required by the guidelines included in Reference 1, Appendix VIII. The rapid drawdown case was not considered since it is not possible for this type of loading condition to occur. Since the dam is presently being modified and stability analyses have been performed for this modification, no additional studies are recommended.

## SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

7.1 Dam Assessment: The Middle Fork Slurry Impoundment at the time of inspection appeared sound and in good condition. The reservoir will store 100 percent of the PMF without overtopping. The SDF is the PMF, and the dam will have six feet of freeboard during the SDF.


The actual embankment structure is presently being graded to conform to the most recent abandonment drawings (See Plate No. 2, Appendix I). The stability analysis performed for the steady seepage case for the existing embankment indicates a factor of safety of 1.22 which is less than the 1.5 requirement of Reference 1, Appendix VIII. Modifications presently in progress will increase the factor of safety of the embankment and no further studies are recommended.

The dam is considered adequate.


7.2 Remedial Measures: Based on the visual inspection and review of existing records, there is no serious problem that would require immediate action for the normal pool conditions.

7.3 Maintenance Measures: Based on the visual inspection, there is no problem that would require immediate action for the normal pool conditions.

APPENDIX I  
MAPS AND DRAWINGS




CARBO, VA.  
 N3652.5-9207.5/7.5



**LEGEND**

- FUTURE REFUSE CONTOURS
- EROSION CONTROL TERRACE
- ▲ APPROX. ELEVATION
- DIRECTION OF FLOW (TERRACE SLOPE)


BARLINE "A" STA. 15+00 TO STA. 2+00 SEE SHEET 8 FOR PROFILE  
 BARLINE "B" STA. 9+00 TO STA. 17+00 SEE SHEET 9 FOR PROFILE  
 BARLINE "C" STA. 100+00 TO STA. 108+00 SEE SHEET 10 FOR PROFILE




REVISED SEA/JKT 30 JAN 1968

PLATE NO. 2 STAGE 1

CLINGFIELD COAL COMPANY		CLINGFIELD NO. 3 MINE		VIRGINIA	
SOUTH CLINGFIELD		DOWNSTREAM GRADING PLAN		L. ROBERT KIMBALL	
CONSULTING ENGINEER		HYDROLOGIST		APPROVALS	
DESIGNED BY	DATE	CHECKED BY	DATE	SCALE	SHEET NO.
BY	3-10-78	BY	3-18-78	1" = 200'	2
BY	3-17-78	BY	3-18-78		
BY	3-18-78	BY			



PLAN




PROFILE


MIDDLE FORK SLURRY IMPOUNDMENT  
OVERALL SCHEMATIC PLATE N°3

APPENDIX II

PHOTOGRAPHS



PHOTOGRAPH OF A LARGE ROCK FOUND IN THE MOUNTAIN TRAP AND 60"  
IN DIAMETER




VIEW OF DEBRIS TRAP AT THE PRINCIPAL SPILLWAY OUTLET PIPE  
(SUMMER 1979) (PRINCIPAL SPILLWAY OUTLET PIPE IS 60"  
IN DIAMETER)

PHOTOGRAPH NO. 2




VIEW OF EMBANKMENT LOOKING UPSTREAM. (ARROW DENOTES  
APPROXIMATE LOCATION OF EMBANKMENT) (SUMMER 1979)

PHOTOGRAPH NO. 3



VIIW OF IMPOUNDED SLURRY POND LOOKING UPSTREAM. (NOTE, HOLLOW ARROWS DENOTE ORIGINAL BEPM) (NOTE, SOLID ARROW SHOWS APPROXIMATE LOCATION OF PRINCIPAL SPILLWAY AND DEBRIS RACK AND SECOND RETAINING BERM). (SUMMER 1979)

PHOTOGRAPH NO. 4



View of Upstream Retaining Structure, 1971  
(1/11/71)

PHOTOGRAPH NO. 5

II-5



View of Downstream Face of Island  
Looking from Top of Island

1-11-1970

PHOTOGRAPH NO. 6

11-6



View of Upstream Face of Main Dam at Point  
Fall, 1936.

PHOTOGRAPH NO. 1

11-7

APPENDIX III

FIELD OBSERVATIONS

Check List  
Visual Inspection  
Phase I

Name Dam Middle Fork Slurry Impoundment County Russell State Virginia Coordinators Lat. 36° 57.7'  
Long. 82° 12.1'

Date(s) Inspection 12/11/79 Weather Fair Temperature 35° F

Pool Elevation at Time of Inspection 1916 msl Tailwater at Time of Inspection 1875 msl

Inspection Personnel:

Schnabel Engineering Associates  
Ray E. Martin, P.E.  
Stephen G. Werner (Recorder)  
  
J. K. Timmons & Associates  
Robert G. Roop, P.E.  
Donald Balzer (Recorder)

Clinchfield Coal Company  
Michael Holbrook  
  
Orbital Engineering, Inc.  
Jim Shellhammer  
  
Virginia State Water Control Board  
Ed Constantine  
Leon Musselwhite

EMBANKMENT

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

SURFACE CRACKS

None observed. The embankment is being constructed with coarse coal refuse and was free of vegetation.

UNUSUAL MOVEMENT OR  
CRACKING AT OR BEYOND  
THE TOE

No unusual movements or cracking were noted on the dam or downstream beyond the embankment toe.

SLOUGHING OR EROSION OF  
EMBANKMENT AND ABUTMENT  
SLOPES

Scattered surface erosion is present along the upper half of the downstream slope. This area has not yet been benched and slopes steeply at about 1H:1V. The surface erosion includes gullies up to 15 ft- deep and 10 ft<sup>±</sup> wide. Except of the upper most slope, all other benches and slopes appeared to be recently constructed and relatively free of erosion. A diversion ditch has been excavated near the crest - right abutment area which can divert runoff into the adjacent hollow.

VERTICAL AND HORIZONTAL  
ALIGNMENT OF THE CREST

The massive size of this embankment makes it difficult to accurately assess the vertical and horizontal alignment. The embankment crest is roughly 1100 ft long and 400 ft<sup>±</sup> wide.

RIPRAP FAILURES

No riprap was observed. It is not required due to the lack of water in the impoundment.

**EMBANKMENT**

**VISUAL EXAMINATION OF**

**JUNCTION OF EMBANKMENT  
AND ABUTMENT, SPILLWAY  
AND DAM**

**OBSERVATIONS**

Conditions at the junction of the embankment and the abutments appear to be good. The right abutment includes thin to massively bedded sandstone outcrops with weathered shale interbeds. The bedrock dips to the southeast at about 45°. The left abutment consists of a very massive pile of coarse coal refuse. Two small areas of original ground are exposed within this waste pile; however, present grading operations will eventually bury these areas. No emergency spillway exists. No faults were observed in the field and geologic maps of the area do not show the presence of faults in the immediate vicinity.

**ANY NOTICEABLE SEEPAGE**

Scattered wet spots or seepage at less than 1 gpm were encountered about halfway down the slope at the junction with the first bench about 50 ft east of the right abutment (see field sketch). The Owner was aware of these wet areas and stated that recent studies by their engineer concluded that the wet spots represent surface water seepage along a buried impervious haul road surface and not seepage through the dam.

**STAFF GAGE AND RECORDER**

None observed.

**DRAINS**

A stone drain which is now covered with coarse coal refuse extends along the left abutment (see field sketch). An estimated 20 gpm of water was flowing from the drain at its surfacing point, following a drainage ditch toward the lower pond. The drain appeared to be functioning properly and water was clear.

EMERGENCY SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	None	Not applicable
APPROACH CHANNEL	None	Not applicable
DISCHARGE CHANNEL	None	Not applicable
BRIDGE AND PIERS	None	Not applicable

OUTLET WORKS

VISUAL EXAMINATION OF CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
	None observed.	Corrugated metal pipe
INTAKE STRUCTURE	60" C.M.P. with debris cage. The pipe extends beneath the embankment and exits below the downstream toe.	Constructed less than one year ago. Good condition
OUTLET STRUCTURE	60" C.M.P.	Good condition
DIVERSION CHANNEL	25' wide with rock base. No erosion	Good condition
EMERGENCY GATE	None	Not applicable

RESERVOIR

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

SLOPES

Very steep (vertical to 2:1) cut and natural slopes with southeastwardly dipping bedrock and thin soil cover bound the reservoir. The slopes range from bare to densely wooded. The cut slopes were created during construction of the impoundment.

SEDIMENTATION

Reservoir is continuously filled with coal refuse slurry. Water depths ranged from 0 ft in the front area to 20 ft in rear (Dam "D").

DOWNSTREAM CHANNEL

VISUAL EXAMINATION OF

REMARKS OR RECOMMENDATIONS

OBSERVATIONS

CONDITION  
(OBSTRUCTIONS,  
DEBRIS, ETC.)

Good condition, no erosion.

SLOPES


Range from shallow to very steep.  
Generally densely vegetated.

APPROXIMATE NO.  
OF HOMES AND  
POPULATION

The Clinch River Power Plant (Appalachian Power) and Town of Carbo are located in Flood Plain of Clinch River at the convergence with Dumps Creek, approximately two miles downstream. Dam breach during peak flooding could cause significant rise in Clinch River.

INSTRUMENTATION

VISUAL EXAMINATION MONUMENTATION/SURVEYS	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
	None	Not applicable
OBSERVATION WELLS	None	Not applicable
WELLS	None	Not applicable
PIEZOMETERS	<p>Three air-activated piezometers have been recently installed, one on the crest and two along the downstream toe. Water levels have not reportedly stabilized; therefore, no readings were taken. Water level readings will be available in the future from the owner.</p>	
OTHER	None	Not applicable



NO SCALE



APPENDIX IV  
CURRENT PLAN FOR UPGRADING IMPOUNDMENT

CURRENT PLAN

The plan for upgrading the Middle Fork Impoundment which was approved by the District Manager of the Coal Mine Safety and Health District 5 on June 13, 1978 consists of:

1. Trench drains and abutments drains will be constructed with selected coarse refuse to carry any seepage which may possibly come from the wet spots on the slope past the toe of the proposed embankment. Filter cloth will be placed directly over the areas of suspected seepage.
2. The embankment will be constructed as shown on Sheet 8 of the "Construction Drawings" up to elevation 1850. The specifications for the construction of this embankment can be found in Appendix G.
3. When construction reaches about elevation 1850, the embankment will be drilled and piezometers will be installed to determine the internal water level.
4. The information obtained from the drilling program will be used to determine the need for drains, buttress, or other remedial work which may be necessary to acquire the required factor of safety.

The work as outlined above has already been initiated. From an economic and engineering standpoint, we feel that the proposed plan is the most logical way to approach the problem. This plan allows for a constant increase in the stability of the embankment while allowing for the acquisition of necessary information to adequately assess the stability of the embankment.

---

R. Michael Holbrook  
Civil Engineer

APPENDIX V  
PRELIMINARY TEST BORING LOGS


STARTED: 9/14/79  
 COMPLETED: 9/28/79  
 CONTRACTOR: Law Engineering  
 EQUIPMENT: CME-55  
 WEATHER:

S 50855.7 E 53663.2  
 OFFSET: N/A  
 GROUND SURFACE EL.: 1772.4

PROJECT NO.: L-702L  
 CLIENT: Clinchfield Coal Co.  
 LOCATION: Dante, Virginia  
 FIELD ENGINEER: M. Lucas


ELEV. (FEET)	DEPTH (FEET)	SAMPLE TYPE	PROFILE	DESCRIPTION	U.S.C.S.	PENETRATION RESISTANCE (BLOWS PER FOOT)			WATER CONTENT (PERCENT)		
						10	30	50	20	40	
1770.0		S/11		COARSE COAL REFUSE							
	5.0	S/12									
		S/22									
		S/8									
		S/7									
	10.0	S/9									
		S/11									
1760.0		S/11									
	15.0	S/10									
		S/11									
		S/10									
		S/9									
	20.0	S/6									
		S/11									
1750.0		S/11									
	25.0	S/10									
		S/11									
	30.0	S/11									
1740.0		S/22									
	35.0	S/22									
		S/27									
1730.0		S/17									
	45.0	S/17									

— 101 WEST MALL PLAZA —  
 — CARNEGIE, PENNSYLVANIA 15106 —  
 — (412) 276-4500 —



ELEV. (FEET)	DEPTH (FEET)	SAMPLE TYPE	PROFILE	DESCRIPTION	U.S.C.S.	PENETRATION RESISTANCE (BLOWS PER FOOT)			WATER CONTENT (PERCENT)	
						10	30	50	20	40
				COARSE COAL REFUSE						
	50.0	S/19								
1720.0										
	55.0	S/56								
	60.0	S/54								
1710.0										
	65.0	S/60								
	70.0	S/50								
1700.0										
	75.0	S/73								
	80.0	S/76								
1690.0										
	85.0	S/15								
	90.0	S/100		COAL REFUSE AND BROWN SILTY CLAY						
1680.0										
	95.0	BX 60%		LIGHT BROWN BROKEN AND WEATHERED SANDSTONE WITH ZONES OF GREY WEATHERED SHALE						

— 101 WEST MALL PLAZA —  
 — CARNEGIE, PENNSYLVANIA 15106 —  
 — (412) 276-4500 —



ELEV. (FEET)	DEPTH (FEET)	SAMPLE TYPE	PROFILE	DESCRIPTION	U.S.S.	PENETRATION RESISTANCE (BLOWS PER FOOT)			WATER CONTENT (PERCENT)	
						10	30	50	20	40
		BX 60%		LIGHT BROWN BROKEN AND WEATHERED SANDSTONE WITH ZONES OF GREY WEATHERED SHALE						
1670.0	100.0	BX 50%								
	105.0			LIGHT GREY SANDSTONE, FINE TO MEDIUM GRAINED, FRAGMENTED, MEDIUM HARD						
1661.3	110.0	BX 83%								
	111.1			BOTTOM OF HOLE						

— 101 WEST MALL PLAZA —  
 — CARNEGIE, PENNSYLVANIA 15106 —  
 — (412) 276-4500 —



STARTED: 10/3/79  
 COMPLETED: 10/9/79  
 CONTRACTOR: Law Engineering  
 EQUIPMENT: CME-55  
 WEATHER:

COORDINATES

S 51045.7 E 53691.9

OFFSET: N/A


GROUND SURFACE EL.: 1779.2

PROJECT NO.: E-782E  
 CLIENT: Clinchfield Coal Co.  
 LOCATION: Dante, Virginia

FIELD ENGINEER: A. Baldrige

ELEV. (FEET)	DEPTH (FEET)	SAMPLE TYPE	PROFILE	DESCRIPTION	U.S.C.S.	PENETRATION RESISTANCE (BLOWS PER FOOT)			WATER CONTENT (PERCENT)		
						10	30	50	20	40	
		S/9		COARSE COAL REFUSE							
		S/8									
	5.0	S/6									
		S/7									
		S/20									
1770.0	10.0	S/15									
		S/10									
		S/14									
		S/12									
	15.0	S/14									
		S/10									
1760.0		S/12									
	20.0	S/23									
		S/37									
	25.0	S/29									
1750.0	30.0	S/25									
	35.0	S/16									
1740.0	40.0	S/34									
	45.0	S/28									

— 101 WEST MALL PLAZA —  
 — CARNEGIE, PENNSYLVANIA 15106 —  
 — (412) 276-4500 —

 ORBITAL ENGINEERING

# TEST BORING LOG

TEST BORING NO. P-2

2 OF 2

ELEV. (FEET)	DEPTH (FEET)	SAMPLE TYPE	PROFILE	DESCRIPTION	U.S.C.S.	PENETRATION RESISTANCE (BLOWS PER FOOT)			WATER CONTENT (PERCENT)	
						10	30	50	20	40
				COARSE COAL REFUSE						
1730.0	50.0	S/19								
	55.0	S/24								
1720.0	60.0	S/21								
	65.0	S/19								
1710.0	70.0	S/18								
	75.0	S/22								
1700.0	80.0	S/22								
	85.0	S/75								
1690.0	90.0	S/53		GREY CLAY AND WEATHERED SHALE						
	95.0	S/41		GREY CLAY AND WEATHERED SHALE						

— 101 WEST MALL PLAZA —  
 — CARNEGIE, PENNSYLVANIA 15106 —  
 — (412) 276-4500 —

 ORBITAL ENGINEERING

TEST DURING LOG

TEST BORING NO. 8-2

3 OF 3

ELEV. (FEET)	DEPTH (FEET)	SAMPLE TYPE	PROFILE	DESCRIPTION	U.S.C.S.	PENETRATION RESISTANCE (BLOWS PER FOOT)			WATER CONTENT (PERCENT)	
						10	30	50	20	40
1680.0	98.5 98.8 100.0	S/ 50 0.3		GREY CLAY AND WEATHERED SHALE						
	105.0	BX 100%		LIGHT GREY SANDSTONE, HARD, FINE TO MEDIUM GRAINED, SLIGHTLY WEATHERED						
1670.4	108.8			BOTTOM OF HOLE						

— 101 WEST MALL PLAZA —  
 — CARNEGIE, PENNSYLVANIA 15106 —  
 — (412) 276-4500 —



ORBITAL ENGINEERING

STARTED: 11/13/79  
 COMPLETED: 11/20/79  
 CONTRACTOR: Law Engineering  
 EQUIPMENT: CME-55  
 WEATHER:

**COORDINATES**

S 50449.5 E 53625.1

OFFSET: N/A


GROUND SURFACE EL: 1977.4

PROJECT NO.: E-782E  
 CLIENT Clinchfield Coal Co  
 LOCATION: Dante, Virginia

FIELD ENGINEER: A. Baldrige

ELEV. (FEET)	DEPTH (FEET)	SAMPLE TYPE	PROFILE	DESCRIPTION	U.S.C.S.	PENETRATION RESISTANCE (BLOWS PER FOOT)			WATER CONTENT (PERCENT)		
						10	30	50	20	40	
1975.0		S/36		COARSE COAL REFUSE							
		S/35									
	5.0	S/42									
1970.0		S/53									
	10.0	S/21									
		S/15									
1965.0		S/19									
		S/17									
	15.0	S/11									
		S/13									
1960.0		S/13									
	20.0	S/17									
		S/32									
1955.0		S/19									
	25.0	S/27									
1950.0											
	30.0	S/14									
1945.0											
	35.0	S/15									
1940.0											
	40.0	S/19									
1935.0											
	45.0										

— 101 WEST MALL PLAZA —  
 — CARNEGIE, PENNSYLVANIA 15106 —  
 — (412) 276-4500 —

 ORBITAL ENGINEERING

# TEST DURING LOG

ELEV. (FEET)	DEPTH (FEET)	SAMPLE TYPE	PROFILE	DESCRIPTION	U.S.G.S.	PENETRATION RESISTANCE (BLOWS PER FOOT)			WATER CONTENT (PERCENT)	
						10	30	50	20	40
1930.0		S/17		COARSE COAL REFUSE						
	50.0	S/14								
1925.0										
	55.0	S/22								
1920.0										
	60.0	S/18								
1915.0										
	65.0	S/23								
1910.0										
	70.0	S/28								
1905.0										
	75.0	S/29								
1900.0										
	80.0	S/24								
1895.0										
	85.0	S/33								
1890.0										
	90.0	S/45								
1885.0										
	95.0									

— 101 WEST MALL PLAZA —  
 — CARNEGIE, PENNSYLVANIA 15106 —  
 — (412) 276-4500 —



ORBITAL ENGINEERING

# TEST BORING LOG

TEST BORING NO. P-3

3 SHEET / 5 OF

ELEV. (FEET)	DEPTH (FEET)	SAMPLE TYPE	PROFILE	DESCRIPTION	U.S.G.S.	PENETRATION RESISTANCE (BLOWS PER FOOT)			WATER CONTENT (PERCENT)	
						10	30	50	20	40
1880.0		S/56		COARSE COAL REFUSE						
	100.0	S/48								
1875.0										
	105.0	S/44								
1870.0										
	110.0	S/42								
1865.0										
	115.0	S/47								
1860.0										
	120.0	S/50								
1855.0		0.4'								
	125.0	S/57								
1850.0										
	130.0	S/62								
1845.0										
	135.0	S/58								
1840.0										
	140.0	S/63								
1835.0										
145.0										

— 101 WEST MALL PLAZA —  
 — CARNEGIE, PENNSYLVANIA 15106 —  
 — (412) 276-4500 —



# TEST DURING LOG

TEST BORING NO. \_\_\_\_\_

4 OF 5

ELEV. (FEET)	DEPTH (FEET)	SAMPLE TYPE	PROFILE	DESCRIPTION	USCS:	PENETRATION RESISTANCE (BLOWS PER FOOT)			WATER CONTENT (PERCENT)		
						10	30	50	20	40	
1830.0		S/79		COARSE COAL REFUSE							
	150.0	S/75									
1825.0											
	155.0	S/58									
1820.0											
	160.0	S/92									
1815.0											
	165.0	S/44									
1810.0											
	170.0	S/50									
1805.0											
	175.0	S/50 0.4'									
1800.0											
	180.0	S/59									
1795.0											
	185.0	S/50 0.3'									
1790.0											
	190.0	S/85									
1785.0											
	195.0										

— 101 WEST MALL PLAZA —  
 — CARNEGIE, PENNSYLVANIA 15106 —  
 — (412) 276-4500 —



# TEST BORING LOG

TEST BORING NO. P-3

SHEET 5  
OF 5

ELEV. (FEET)	DEPTH (FEET)	SAMPLE TYPE	PROFILE	DESCRIPTION	USCS	PENETRATION RESISTANCE (BLOWS PER FOOT)			WATER CONTENT (PERCENT)	
						10	30	50	20	40
1780.0		S/51		COARSE COAL REFUSE						
	200.0	S/35								
1775.0										
	205.0	S/17								
1770.0										
	210.0	S/16								
1765.0										
1762.4	215.0			BOTTOM OF HOLE						

— 101 WEST MALL PLAZA —  
 — CARNEGIE, PENNSYLVANIA 15106 —  
 — (412) 276-4500 —



ORBITAL ENGINEERING

APPENDIX VI

STABILITY ANALYSIS SUMMARY

by

L. ROBERT KIMBALL & ASSOCIATES

The following stability analyses data were developed by L. Robert Kimball & Associates and presented in Reference 6 of Appendix VII:

STABILITY ANALYSIS - 1976 STUDY

The effective stress parameters were used in the stability analysis, because under long term conditions excess pore pressures should not build up in a material as permeable as coarse refuse. The Simplified Bishop Method was used to evaluate the embankment section. The seepage line was estimated for maximum pool conditions. Results of the embankment stability analysis indicated a lowest factor of safety of 1.57, under static loading conditions for the proposed slope configuration. A profile of the proposed slope which was analyzed can be found on Sheet 8 of the "Construction Drawings". The results of this stability analysis and the failure circle corresponding to the lowest factor of safety can be found on Sheet 9 of the "Construction Drawings". The stability analysis backup data can be found in Appendix B.

SUMMARY OF TRIAXIAL (R) TEST RESULTS (1976)

<u>MATERIAL</u>	<u>SAMPLE NO.</u>	<u><math>\phi</math></u> <u>DEGREES</u>	<u>c</u> <u>PSI</u>	<u><math>\bar{\phi}</math></u> <u>DEGREES</u>	<u><math>\bar{c}</math></u> <u>PSI</u>
SLURRY		6.3	7.1	13.5	5.5
NEW REFUSE	A-1	14.3	6.1	23.9	5.0
OLD REFUSE	A-2	10.4	5.8	38.3	0.5
SOIL	A-3	12.0	1.0	29.5	0.5

STABILITY ANALYSES - 1977 - 1978 STUDY

Several stability analyses were performed utilizing various parameters and assumptions. The results of these analyses are summarized below. The computer back-up data for these analyses can be found in Appendix F.

1. A stability analysis was performed on the existing conditions, assuming a high phreatic surface and lower soil parameters than those used in the 1976 stability analysis. The lowest factor of safety was calculated to be 1.22. The results of this stability analysis can be found on Sheet 10 of the "Construction Drawings".
2. A stability analysis was performed on the slope configuration proposed in 1976, assuming a high phreatic surface and soil parameters lower than the two previous stability analyses. The lowest factor of safety was calculated to be 1.36. The results of this stability analysis can be found on Sheet 11 of the "Construction Drawings".

3. A stability analysis was performed on a proposed slope configuration utilizing a downstream berm and drainage blanket, assuming a high phreatic surface and the same soil parameters as in analysis 2 above. The lowest factor of safety was calculated to be 1.65. The results of this stability analysis can be found on Sheet 12 of the "Construction Drawings".
  
4. A dynamic stability analysis was performed utilizing the same slope configuration and parameters as in analysis 3 above. This analysis was performed using the Fellenius Method. The lowest factor of safety was calculated to be 1.27. The results of this stability analysis can be found on Sheet 13 of the "Construction Drawings".

SUMMARY OF TRIAXIAL (S) TEST RESULTS ( 1977 - 1978)

<u>MATERIAL</u>	<u>SAMPLE</u>	<u><math>\bar{\phi}</math></u> <u>DEGREES</u>	<u><math>\bar{c}</math></u> <u>PSI</u>
COARSE REFUSE	REMOLDED $\gamma=90$	31.8	3.2
COARSE REFUSE	REMOLDED $\gamma=95$	34.0	1.6
COARSE REFUSE	REMOLDED $\gamma=100$	33.3	3.3
COARSE REFUSE	REMOLDED $\gamma=110$	34.5	7.4

APPENDIX VII  
STABILITY ANALYSIS SUMMARY  
by  
ORBITAL ENGINEERING, INC.

## STABILITY ANALYSIS

Computerized stability calculations were performed on the minimum (no berm) embankment configuration to evaluate the downstream stability of the proposed design profile. This profile is as described in L. Robert Kimball's 1976 and 1978 reports. The location of this particular embankment section is shown on Drawing E-782E-SK1. The geometry of the embankment section analyzed by OEI and the soil properties used to describe the various material layers are presented on Drawings E-782E-SK3 and E-782E-SK4. The stability during a maximum probable seismic event was evaluated using an equivalent static horizontal load factor of  $0.1g$ , an appropriate value for Seismic Risk Zone 2.

The ground water level used in this analysis was based on our engineering evaluation of the existing ground water conditions obtained from the most recent piezometer readings available (see Table 4). A plot of the water versus date based on the piezometer readings is presented in Figure 5. From this data, and from our engineering evaluation of expected steady state seepage conditions, of the configuration of the phreatic surface used in this analysis was conservatively estimated to be as presented on Drawings E-782E-SK3 and E-782E-SK4.

The stability calculations were carried out using McDonnell Douglas Automation Company (MCAUTO) computer facilities and the ICES slope and embankment stability program, SLOPE. Appendix C contains a description of this program.

An abbreviated summary of the results of these calculations is presented in Table 5 and on Drawings E-782E-SK3 and E-782E-SK4. As these results suggest, the analysis indicates that the minimum factor of safety for static conditions is about 1.58, and corresponds to a localized, surficial, circular arc type failure along the downstream slope. For the more critical type of failure condition involving a relatively deep-seated, circular arc type failure mode encompassing all, or a substantial portion, of the embankment downstream slope, the minimum factor of safety for static conditions is 1.69.

For seismic conditions, the minimum factor of safety is about 1.22; for a localized, surficial failure mode, and about 1.29 for the more critical deep-seated failure mode.

Consideration was given to analyzing the proposed embankment profile for a wedge type failure mode, but such an analysis was discounted because the rock profile is not conducive to this type of failure.








PLATE No. 3

MATERIAL PARAMETERS

NO.	DESCRIPTION	UNIT WEIGHT (pcf)	MODULUS OF ELASTICITY (psi)	POISSON'S RATIO	COMPRESSION PERCENT
1	Common Coal Bedrock	130	10,000,000	0.25	10%
2	Common Coal Bedrock	130	10,000,000	0.25	10%
3	Shale	130	10,000,000	0.25	10%
4	Shale	130	10,000,000	0.25	10%

NOTES:  
 FOR LOCATION, SEE PLAN, SECTION 9-9.  
 FOR SECTION LOCATION, SEE PLAN, SECTION 9-9.

DISTANCE, FEET  
 SECTION 9-9


CLIMCHFIELD COAL COMPANY  
 DANTE, VIRGINIA

DATE: 10/15/57  
 DRAWN BY: [Name]  
 CHECKED BY: [Name]  
 APPROVED BY: [Name]

SCALE: 1" = 100' (VERTICAL)  
 1" = 200' (HORIZONTAL)

PROJECT: [Name]  
 SHEET: [Name]

CLIMCHFIELD COAL COMPANY  
 DANTE, VIRGINIA



**MATERIAL PARAMETERS**

MATERIAL	UNIT WEIGHT (pcf)	ANGLE OF INTERNAL FRICTION (°)	COEFFICIENT OF FRICTION	ADHESION (psi)
①	110	30	0.60	100
②	110	30	0.60	100
③	110	30	0.60	100
④	110	30	0.60	100
⑤	110	30	0.60	100

**NOTES**

- 1. FROM LOCATION, ALL DATA IS FROM 1952.
- 2. THIS SECTION IS A RECONSTRUCTION OF THE ORIGINAL DESIGN.

**PLATE No. 4**

DISTANCE, FEET  
SECTION A-B

CLARKFIELD COAL COMPANY  
DANTE, VIRGINIA

DATE: 11/19/73  
DRAWN BY: J. B. BROWN  
CHECKED BY: J. B. BROWN  
APPROVED BY: J. B. BROWN

ENGINEERING, INC.  
1000 W. 10th St., Tulsa, Okla. 74103  
TELEPHONE: 335-1111

#### APPENDIX VIII-REFERENCES

1. Recommended Guidelines for Safety Inspection of Dams, Department of Army, Office of the Chief of Engineers, 46 pp.
2. Design of Small Dams, U. S. Department of Interior, Bureau of Reclamation, 1974, 816 pp.
3. The Geology and Coal Resources of Russell County, Virginia, Bulletin No. 22, C. K. Wentworth, Virginia Division of Mineral Resources, 1922, 179 pp.
4. Hydrometeorologic Report No. 33, U. S. Department of Commerce, Weather Bureau, U. S. Department of Army, Corps of Engineers, Washington, D.C., April 1956.
5. Engineering Report for Remedial Modification to the Existing Slurry Pond for Moss #3 Coal Refuse Disposal Area on Middle Fork of Dumps Creek; Clinchfield, Russell County, Virginia, Clinchfield Coal Company, Dante, Virginia; November, 1978
6. \*Slope Stability Evaluation at Area 1, Moss #3 Coal Preparation Plant for Clinchfield Coal Company, Dante, Virginia, Orbital Engineering, Inc., Carnegie, Pennsylvania, December, 1979.
7. Calculation Brief, Proposed Upstream Slurry Retention Dam, Middle Fork of Dumps Creek, Russell County, Virginia, Orbital Engineering, Inc., Carnegie, Pennsylvania, November, 1978.

\* Preliminary