


AD-A086 035


GENERAL MOTORS CORP INDIANAPOLIS IN DETROIT DIESEL A--ETC F/8 10/2
ENVIRONMENTAL AND COLD TESTS ON MODEL 04045803 GENERATOR SET SE--ETC(U)
NOV 79 H E GASTON
DDA-79087
NL

UNCLASSIFIED

1-2

AD-A086 035





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A



LEVEL
Detroit Diesel Allison
 Division of General Motors Corporation
 Indianapolis, Indiana

REPORT NO. **DDA-79D871**

DATE **11-9-79**

ENGINEERING TEST REPORT

**ENVIRONMENTAL AND COLD TESTS ON
 MODEL 04045B03 GENERATOR SET SERIAL NUMBER
 0000003 WITH IGT 404-4 ENGINE SERIAL NUMBER 1000003,
 TEST UNIT**

**DTIC
 ELECTED
 JUN 30 1980**

ADA 086035

119 Nov 79

12101

Engine - IGT404-4
 MODEL Generator Set 04045B03 DATE November 13, 1979

P580-01
 PROJECT *P568-06 PREPARED BY *Harris E. Gaston*

15 DAAK70-78-C-0124
 CONTRACT DAAK70-78-0056 **10** HARRIS E. Gaston

AD0097
 FILE CLASS *AD5210 APPROVED *D. M. Hall*
 D. M. Hall, Supv.

GROUP IGT Test Projects

AD0097-02-(EDO-Open)
 TEST REQUEST *AD5210-01-501A DEPARTMENT Industrial Engine Test

CLOSED *X OPEN

TEST STARTED 6-28-79 TEST COMPLETED 9-24-79

DISTRIBUTION:

DESCRIPTORS:

LIBRARY

AUTHOR

H. E. Barrett
 E. E. Flanigan
 D. N. Nigro/S. C. Laux/G. M. Hurt, Jr.
 E. S. Barc/D. M. Hall
 B. C. Hall, Jr./R. G. Larkin
 R. M. Swick/D. E. Morrison
 V. E. Ajango

IGT Generator Set
 208 Volts, 400 Hertz, 150 Kilowatts
 +125°F, 5,000 Ft. Alt. & 107°F,
 8,000 Ft. Alt. & 95°F, -25°F, -50°F
 Power Turb Brg Failure

This document has been approved
 for public release and sale; its
 distribution is unlimited.

/lae

THIS DOCUMENT IS BEST QUALITY PRACTICALLY.
 THE COPY FURNISHED TO DDC CONTAINED A
 SIGNIFICANT NUMBER OF PAGES WHICH DO NOT
 REPRODUCE LEGIBLY.

80 4 9 086

019200

DDC FILE COPY

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DTIC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

CONTENTS AND ENCLOSURES

Page

11 Abbreviations and Special Words

1 Foreword

1 Summary

Discussion:

5 Factual Data

5 Test History

22 Test Results

Addendum A - Ambient Tests (2 Pages)

Addendum B - +125°F Tests (8 Pages)

Addendum C - 5,000 Ft., 107° Tests (5 Pages)

Addendum D - 8,000 Ft., 95°F Tests (5 Pages)

Addendum E - -25°F Cold Tests (5 Pages)

Addendum F - List of Instrumentation (4 Pages)

Enclosures:

AD5210-00006-00008 Vibration Signatures

AD5210-00009-00011 Battery Charging Tests

AD5210-00012 & 00013 60° ΔT Test Results

AD5210-00014 Engine Performance

Photographs:

350363-350369 Installation

348568-Reverse Polarity Diode

350444-Gasifier Pinion Bearing Failure

351421- 351439 Power Turbine Bearing Failure &

Secondary Damage

351525-Control Oil Pressure Tube

Accession For	
NTIS GMA&I	☒
DDC TAB	☐
Unannounced	☐
Justification	☐
By	<i>on file per [signature]</i>
Date	<i>10/1/77</i>
Approved by	<i>[signature]</i>
Approved for	<i>[signature]</i>
Dist	<i>23</i>
<i>A</i>	<i>Q</i>

ABBREVIATIONS AND SPECIAL WORDS

A, amps	Amperes
accel	Acceleration
Avg	Average
CB	Circuit breaker or interrupter
cc	Cubic centimeters - measure of start fuel flow
DC	Direct current
° or °F	Degrees fahrenheit
ΔT	Differential temperature
DFA	Arctic diesel fuel for cold testing
DF2	ASTMD-975 #2 diesel fuel
ECA	Electronic Control Assembly
ETR	Engineering Test Report
ft	Feet (altitude in most applications herein)
F.U.	Fire-up or start
Fuzz	Minor metallic particles as contrasted to "chips"
Gen Set	Generator set model number 04045B03, Serial 0000003
Hz	Hertz--measure of output frequency and a direct indication of generator set speed
IF	D.C. current to operate the fuel valve
K(5)	K number represents a control relay
KW	Kilowatts - electrical load applied
lab	Fuels laboratory at Plant 5
ma	Milliamperes - measure of fuel valve current
Mil-Std 705B	The Military Specification applied to the test
min	Minimum or minutes
MOP	Main oil pressure
N1	Gasifier speed recorded from the ECA test connector
N2	Output speed recorded from the ECA test connector
NEG	Negligible - used in connection with measurements where the width of the printed line is as wide as the variation of the line level.
No., #	Number
O.T.	Overtemperature
O.V.	Overvoltage
PD	Purchase Description document
%	Percent
<, >	Less than, greater than
pf	Power factor, lagging
P/N	Part number
pt	Point (Cloud pt, pour pt, etc.,)
psig	Pounds per square inch - gage, pressure
QC	Quality Conformance, Quality Control as applicable to instrumentation
qts	Quarts
RDG	Reading - hand data
rpm	Revolutions per minute - speed
SEC	Second (time)
S/N	Serial number
STD	Standard
Standard Instrument	The special calibrated generator monitor for reading accurate electrical data.
T ₁	Temperature at engine air inlet

Abbreviations & Special Words (Continued)

T ₄	Burner outlet or gasifier turbine inlet temperature read from a pair of commercial control thermocouples
T ₆	Power turbine outlet temperature
TI	Texas Instruments, 2 channel recorder
UV	Undervoltage
V	Volts

FOREWORD

The purpose of this test was to conduct environmental tests at +125°F, 5,000 Ft. altitude and 107°F, 8,000 Ft. altitude and 95°F and with 60° AT (from about 80°F to 20°F). These tests were to be completed per Test Request AD5210-01-501A, Purchase Description and Military Specification Mil Std 705B. In addition, the testing was to include cold testing at -25°F and -50°F to meet the requirements of the Purchase Description and Mil-Std 705B. The Environmental tests were to be completed on Contract No. DAAK70-78-0056 while the cold tests were to be covered on Contract No. DAAK70-78-C-0124.

SUMMARY

Model 04045B03 Generator Set S/N 0000003 (with IGT 404-4 Engine S/N T000003) was installed in Test Cell 873 for environmental tests and Cold tests on June 28, 1979. Initial ambient checkout tests were completed June 9 after correcting various test equipment problems. Engine-gen set problems involved failure of two reverse polarity diodes and several "undervoltage load dump" incidents.

The test results at +125°F, ambient pressure conditions were as follows: (Addendum B)

1. The unit was running with a blinking overtemperature (OT) light at rated power; and underspeed tests could not be accomplished without T6 overtemperature shutdowns.
2. During the Regulator Range test, and all subsequent testing, the Texas Instruments (T.I.) recorder indicated high voltage regulation values while the "standard instrument" indicated values well within limits. This was probably due to hysteresis in the T.I. recorder.
3. Undervoltage load dumps were due to a broken wire causing a ground on relay K7. This was corrected.
4. Only one of one hundred five parameters was out of limits on the indicating instrument test (panel comparison).
5. Transient conditions were out of limits on 12 of 70 parameter conditions on the Frequency and Voltage Regulation, Stability and Transient Response test. Four (4) of these twelve (12) parameters were voltage regulation as measured by the T.I. recorder which is suspected of hysteresis.

6. The overload relay could not be set properly.
7. Long term stability was within prescribed limits.
8. After installation of parallel reverse polarity diodes, the DC control tests were successful.
9. Battery charging tests successfully demonstrated the necessary capability.
10. The Run, Shutdown, and Restart test was successful.
11. Overvoltage relay operation was up to 5.8 percent faster than the .180 second minimum limit.
12. Voltage Dip and Rise tests were satisfactory.

During the 60°Δ T test (Drift) the regulated voltage and frequency remained within prescribed limits.

Engine and exciter parameters performed as expected with characteristic reductions as the ambient temperature was reduced (Enclosures AD5210-00012 and 00013).

All testing at 5,000 feet altitude and 107°F was accomplished with the O.T. light blinking at 148.2 KW (1.21 percent below the 150 KW rating). At one point the power was raised to 150 KW and the OT light was still not on all the time. The tests at 5,000 feet altitude and 107°F had the following results: (Addendum C)

1. On the Regulator Range test, all parameters were within limits (based on the standard instrument digital data).
2. The results of the Frequency and Voltage Regulation, Stability and Transient Response test indicated nine (9) frequency transient parameters plus five voltage regulation (from TI recorder) were out of limits.
3. On the indicating instrument test at 5,000 feet and 107°F, eight (8) voltage readings (at 75 and 100 percent load) were erroneous beyond allowable limits.
4. Testing could not be done at rated load, underspeed conditions.

The testing at 8,000 feet altitude (Addendum D) with rated power at 138 KW provided the following results:

1. The errors in voltage readings, on the indicating instrument test, were on seven (7) of the same eight (8) that were erroneous at 5,000 feet and 107°F.
2. The Regulator Range test results were good, based on the standard instrument data.
3. Testing could not be accomplished at underspeed, rated load conditions.
4. During the Frequency and Voltage Regulation, Stability and Transient Response test, seven (7) frequency transient parameters and three (3) voltage regulation values (based on T.I. recorder) were out of limits.

An overtemperature shutdown was demonstrated with 125°F conditions in the test chamber. The engine reached the acceleration temperature limit and the O.T. shutdown limit at about the same time. But, due to the OT shutdown delay, the engine decelerated to an underfrequency trip condition, then shut down at the same time it was unloaded.

During the preparations for -25°F Cold testing a starter solenoid failure caused extended motoring. This motoring, in turn, appeared to have caused, due to inadequate lubrication, a gasifier pinion gear bearing failure.

After the unit was repaired, three tests were attempted unsuccessfully after 24 hour soak (each) at -25°F. Testing on a field engine indicated that reduction in the clutch cooling oil flow allowed successful starts at extreme cold conditions. With the installation of a plug to reduce clutch cooling oil flow, the -25°F start and operation were successful. The following results were obtained at -25°F: (Addendum E)

1. The Regulator Range test results based on the standard instrument were within limits.
2. The only values out of limits on the Frequency and Voltage Regulation, Stability and Transient Response Test were voltage regulation values (4 places) based on TI recorder data.

3. The instruments on the gen set were out of limits on 20 of 45 voltage values (error as high as 3.8 volts at 208 volts) on the Indicating Instrument test.

After the normal preparations, the -50°F testing was initiated with a successful start and loading within one minute. However, soon after the loading occurred, the unit emitted two howls and a loud "pop." The pop was apparently due to the quill shaft failing as secondary damage when the power turbine roller bearing failed (lack of lubrication - cooling).

The engine was repaired, check run and shipped to MERADCOM, Ft. Belvoir, VA. Further design analysis is being accomplished to prepare future engines for extreme cold operation. No corrections were made for this problem in engine S/N 0000003.

RECOMMENDATIONS

1. Since the P.D. dated August 3, 1979, still contains the requirement to load to rated load in one minute, further cold tests should be conducted (prior to production units) to insure that the changes for extreme cold operation are satisfactory. A Purchase Description change should be considered.
2. The average engine must be improved to insure satisfactory performance at altitude or hot day and underspeed (388 Hz) conditions.
3. Improvements in the overload relay and main circuit interrupter should be proven before production (first Article) test are initiated.
4. The frequency adjustment range should be extended so the adjustment is not marginal for the tests requiring ± 3 percent adjustment.
5. Serious consideration should be given to the possible problem of icing or blockage of the air inlet particle separators (filters). One possibility might be to increase the compressor discharge bleed flow, at an unloaded condition, to warm up and defrost the filters.

6. Since the PD (August 3, 1979) has not changed relative to the frequency transients, significant changes are required to meet the limits. Additional testing should be accomplished to prove those fixes. This also may require a P.D. change.

DISCUSSION

Factual Data

Generator Set Model No.	04045B03
Generator Set Serial No.	0000003
Generator Set Builds	4-6
Engine Model No.	GT404-4
Engine Serial No.	T000003
Engine Builds	6-8
Test Stand No.	873
Fuel	DF2/DFA
Lube Oil	MIL-L-7808
Test Started - Date	6-28-79
- Clock Time	29.6 Hrs.
- Gen Set Time	29.6 Hrs.
- Engine Time	76.0 Hrs.
Test Ended - Date	9/24/79
- Clock	150.9 Hrs.
- Gen Set Time	142.9 Hrs.
- Engine Time	196.1 Hrs.

Test History

Generator Set Model NO. 04045B03, Serial No. 0000003 was installed (beginning June 28, 1979) in Test Cell 873 following Quality Conformance Tests (ETR 79D63) and subsequent "purchase" by the Army. The instrumentation list (Addendum F) includes a list of parameters, types of instrumentation, readout equipment, etc. All instrumentation was maintained in proper Quality Control throughout the test.

Photographs 350363 through 350369 show, respectively, the control room, TV monitor, load banks (see 7/5/79 below) generator set installation, battery cart and fuel system. The installation was completed July 3, and the initial check out, at ambient conditions, was started. The following chronology provides the pertinent events during this initial checkout:

<u>Date</u>	<u>Gen Set Hrs.</u>	<u>Event</u>
7/3/79	29.6	Initial fire-up.
	30.1	Had a "low fuel" shutdown. Found the test equipment fuel valve wired wrong and the CB-2 circuit breaker open. Corrected the wiring.
7/5/79	30.2	Replaced a shorted K-5 relay which was allowing the set fuel pump to run continuously.
	30.6	Had low T4 on fire-up--found the T1 temperature sensor failed. Replaced the sensor with new part (Same P/N).
7/5/79	33.5	Had T1 and T4 fluctuations and fluctuations on generator set voltage. Found the DC control relays in the load bank "chattering." Repaired the chattering by supplying separate 28V supply to the relays. Also added a grounded shield to the external voltage adjusting potentiometer.
	34.3-34.5	On five (5) occasions, the undervoltage (U.V.) relay operated to open the main contactor (CB5) and drop the load. In addition, the load bank was not supplying sufficient load (150 KW) because of the voltage drop due to the long load lines.
	34.5	Connected a second load bank to provide a complete 150 KW 0.8 power factor (pf) load.
7/6/79	34.5-34.6	Had 2 more U.V. relay "dumps" while instrumentation was indicating 208 volts on all phases.
	34.7	Found and corrected a "short" at the K-7 relay. Did not correct the U.V. light problem.
	35.2	Overload relay dropped the load--increased the setting by 1/4 turn clockwise.

<u>Date</u>	<u>Gen Set Hrs.</u>	<u>Event</u>
	35.5	Experienced fluctuations in T4--appear to have exhaust recirculation. Wrapped exhaust stacks. Had to add a fan to assist the exhaust up the stack.
	36.3	Test equipment emergency stop switch did not shut the unit down when checked. Found the cable connector only partially plugged in.
	37.4-40.2	Completed indicating instrument test (PD27 - MIL-STD-705, Method 513.1) at ambient conditions (See Test Results).
7/7/79	40.2	Battery charging alternator would not charge (hooked up to a load bank only) until excited from battery (+) terminal.
	42.5	Completed battery charging test. Started D.C. Control test per MIL-STD 705B method 655). Batteries upstairs would not crank the unit, apparently due to low charge and extremely long (and small) battery leads. Used the auxilliary set in the special battery cart (See Photo 350368).
	42.6	During the reverse polarity check (in the D.C. Control test) the reverse connection resulted in failure of the special diode. (See Photo 348568 for a typical reverse polarity system). A battery post was damaged also, during an attempted battery hookup before the diode was replaced.
7/9/79	43.0	Installed a new diode (Rev. polarity) and replaced the damaged battery. Attempted a reverse polarity connection and again failed the system diode. Replaced the diode again.
	43.3	Successfully completed DC Control test (MIL STD 705B, method 655.1), except the reverse polarity test.
	44.9	Completed rerunning the Battery Charging test per PD paragraph 4.4.1 (See test results).

<u>Date</u>	<u>Gen Set Hrs.</u>	<u>Event</u>
7/10/79	44.9	<u>Start of 125°F Testing</u> NOTE: The test chamber open tip and oil bath thermocouples plus the engine oil temperature were raised to 125 ⁰ +5 ⁰ ₋₀ °F before starting each day's testing. All testing then was conducted at 125-130°F chamber temperature.
	47.5	The frequency adjust test at 125°F (MIL-STD 705B, Method 511.2) was completed through the stabilization and max speed adjustment. However, when an attempt was made to reduce frequency to the 388 Hz setting, the unit shut down due to T6 (turbine outlet) overtemperature when frequency was reduced to 395 Hz. (See "Test Results"). Had a high T4 spike on the next fire-up.
7/11/79	51.4	The Regulator Range test (Method 511.1) was started but U.V. relay load "dumps" occurred 5 times and the test was aborted.
	51.6	One (1) additional U.V. relay load dump occurrence preceded the discovery of a broken wire which was intermittently grounding the relay (K7). This broken wire was repaired.
	54.4	The Regulator Range Test (PD#29, MIL-STD 705B, Method 511.1) was completed. (See "Test Results")
	57.3	The Indicating Instrument test (PD#27, MIL-STD 705B, Method 513.2) was completed except the 150 KW, 0.8 pf load point at 388 Hz (underspeed). This point could not be run because of high turbine outlet temperatures. (See "Test Results")
7/12/79	60.5	Completed the Frequency and Voltage Regulation, Stability (short term) and transit Response Test at 125°F (PD#17, MIL-STD 705B, Method 511.2) See "Test Results".

<u>Date</u>	<u>Gen Set Hrs.</u>	<u>Event</u>
7/12/79	64.0	Completed overload relay test at 125°F (PD paragraph 3.10.3.3 and relay print). See "Test Results."
7/13/79	75.2	Completed Long Term Frequency and Voltage Stability Test at 125°F per PD#20 and MIL STD 705B, method 608.2; See "Test Results."
7/16/79	75.2	Installed a second diode in parallel with the first reverse polarity diode.
	75.8	Had a shutdown, during the D.C. Control test, when batteries were disconnected. Found a loose connection at the new diode installation. Shorted the alternator diode trio during alternator adjustment. Replaced the diode trio assembly.
	77.1	Completed DC Control test at 125°F, per PD#37 and MIL STD 705B, method 655.1, including the reverse polarity battery hookup. See "Test Results."
	78.4	Completed Run, Shutdown, and Restart test at 125°F (per MIL STD 705B, Method 710.1). See "Test Results."
	78.6	While setting up for overvoltage (OV) and undervoltage (UV) tests, the external resets appeared not to work properly.
7/17/79	80.3	Completed the "Circuit Interrupter - Over-voltage and Undervoltage Test" at 125°F per PD#26, MIL STD 705B, Method 512.3. See "Test Results."
	81.1	During the process of adjusting the alternator regulator, while running the Battery Charging Test at 125°F, the adjustment was overtorqued, failing the regulator. The alternator was replaced.
	83.4	Completed Battery Charging Test at 125°F per PD paragraph 4.4.1. See "Test Results."

<u>Date</u>	<u>Gen Set Hrs.</u>	<u>Event</u>
	86.5	Completed voltage dip and rise test at 125°F per PD #24, MIL STD 705B, method 619.2. See "Test Results."
7/18/79	86.5	<u>Start of 60° ΔT Test</u>
	96.3	Completed 60° ΔT test from 81° (stabilized) to 21°F with stabilization per PD 19, paragraph 4.4.5. See "Test Results." Found left rear T4 thermocouple was not connected onto the junction block. (Added one (1) quart of MIL-L-7808 oil)
7/19/79	96.3	<u>Start of Test at 5000 Feet Altitude & 107°F</u> At 107°F and 5,000 ft. altitude, over-temperature light is blinking at 148.2 KW.
	100.4	Completed Regulator Range test at 5,000 ft. and 107°F per PD#29 MIL STD 705B, method 511.1. Power was limited to about 148 KW because of overtemperature light blinking. See "Test Results."
	103.5	Completed Frequency and Voltage Regulation, Stability (short term) and Transient Response test at 5,000 ft. altitude and 107°F per PD#17, MIL STD 705B, method 608.1. See "Test Results."
7/20/79	104.8	While conducting the Indicating Instrument test, lost the magnetic drain plug "continuity" (yellow) light.
	106.0	Completed Indicating Instrument test at 5,000 Ft. altitude and 107°F per PD#27 MIL-STD-705B, method 513.1. See "Test Results." Note: Could not run 388 Hz with 148.2 KW load.
	106.7	Extended power to 150 KW and obtained data at 400 Hz. O.T. light still blinking with observed T4 at 1944°F.

<u>Date</u>	<u>Gen Set Hrs.</u>	<u>Event</u>
	106.7	<u>Start of Test at 8,000 Feet Altitude and 95°F (138 KW)</u>
	108.7	Completed Indicating Instrument test at 8,000 ft. altitude and 95°F per PD#27, MIL STD 705B, Method 513.1 with 138 KW rated load. Unable to complete 388 Hz, rated load point. See "Test Results."
7/21/79	108.9	On the first load application of the day, to 138 KW (8,000 ft. and 95°F), the O.T. light stayed on steady with 1950°F on the chart (T4 signal from box). The load was cycled a few times and the T4 temperature reduced to 1935 with the O.T. light blinking.
	113.1	Completed Regulator Range test, at 8,000 ft. altitude and 95°F, per PD #29, MIL-STD-705B, method 511.1. The overtemperature light blinked off and on during the test at 138 KW (rated power). See "Test Results."
	116.6	Completed Frequency and Voltage Regulation, Stability and Transient Response test, at 8,000 feet altitude and 95°F, per PD#17, MIL-STD 705B method 608.1. See "Test Results."
	117.2	<u>Returned to Ambient Pressure, 125°F Conditions.</u> Completed overtemperature safety device test at 125° per PD#40, MIL-STD-705B, method 515.2a. After the OT shutdown, the underfrequency lamp stayed lighted, even when the main switch was turned off. Checked over external wiring and underfrequency lamp went out--did not take positive corrective action.
	117.2	<u>Start of -25°F Preparation and Testing.</u> Cleaned the magnetic drain plug of small amount of "fuzz."

<u>Date</u>	<u>Gen Set Hrs.</u>	<u>Event</u>
7/23/79	118.0	Attempted start with batteries from upstairs--no fire-up attained and voltage dropped to 17.3 volts. About 5-10 minutes later the unit was found motoring. Removed the battery connector to stop the unit. Closed the manual fuel shutoff valve, hooked up the set internal batteries and motored to clear the unit of fuel (if any). Again the unit did not quit cranking and battery cables had to be removed. Found the starter solenoid contacts stuck closed. Replaced the starter assembly.
	119.1	Experienced a magnetic drain plug indication (light and alarm) while conducting a battery charging run.
	119.4	Checked magnetic drain plug. Found significant accumulation of larger chips on magnetic drain plug and removed the unit for disassembly.
7/24/79	119.4	<u>Teardown 4, BU5 on Gen Set</u> <u>Teardown 6, BU7 on Engine</u> Disassembly of the generator set and the engine gearbox revealed that the rear bearing on the gasifier pinion gear had failed. (See Photo 350444), allowing the pinion to move rearward and contact the rear pinion bearing support. The long motoring period at 118.0 hours, probably with inadequate oil flow to this bearing, appeared to be the cause of the failure.
7/25/79	119.4	Completed the rebuild of the engine and generator set and started installation in Test Cell 873. Replaced the auxilliary battery power receptacle because it was burned during the problems of 7/23/79 at 118.0 hours.
7/26/79	119.5	Shut down two times to clean "fuzz" from the magnetic drain plug.

<u>Date</u>	<u>Gen Set Hrs.</u>	<u>Event</u>
	120.4	Rejordings indicated significant T4 and If spikes during 50 percent load transients. With the droop switch on, no spikes occurred. Ran a bench test on the ECA and could find no difficulty. Subsequently, adjustments on load pulse during the ensuing run appeared to correct the problem.
	121.3	Completed the engine-generator set checkout.
	121.9	Completed preparations for -25°F start and run. All DFA fuel in the system was processed through Army H2O separator.
7/27/79	121.9	<u>-25° Cold Test.</u> Started the 24 hour cold soak at 00:00 o'clock 7/28/79.

After 16.8 hours soak at -25 to -30°F a formation of white material appeared in the fuel sample which was visible in the test chamber window. The fuel in various supply drums and in the test chamber drums was sampled with the following results:

<u>Drum No.</u>	<u>API</u>	<u>Pour Pt</u>	<u>Cloud Pt</u>
1B	39.7	<-70	-70
2B	39.7	<-70	-72
3B	39.9	<-70	-68
4B	39.9	-80	-68
5B	39.8	-80	-68
6B	39.8	<-65	-68
7B	39.7	-70	-68
8B	39.8	-70	-68
9B	39.9	-70	---
10B	39.7	-75	---
*12B	37.5	-50/-30	-4
*Test System	38.0	-45	-8

*The lab reported that the sample from 12B and from the test cell systems were contaminated with some foreign material. When cooled, the samples would form a "frozen" network throughout. But if these samples were stirred, the network broke up and dissolved immediately.

<u>Date</u>	<u>Gen Set Hrs.</u>	<u>Event</u>
		The -25° cold test was aborted, the fuel system cleaned out and rinsed and refilled with fuel from good drums. The gen set day tank was drained and refilled with good fuel; fuel was pumped through the engine system as in fuel priming and both fuel filters were replaced with new clean filters.
7/28/79	122.2	Completed a battery charging, engine drying run during cool down. <u>Started -25°F Cold Soak at 0600</u> Following the two (2) mandatory 15 second motorings, three cold start (-25°F) attempts were unsuccessful because light-off which occurred during quick fill were not recognized. The quick fill (fuel valve) current was increased from 85 milliamps (nominal) to 195 ma. Four (4) additional start attempts were shutdown with "no light-off" or "failed sensor" shutdowns. The cold auxilliary batteries were connected and two additional start attempts were also unsuccessful (The two mandatory, 15 second, motorings were made before these start attempts). The unit was motored to blow out any excess fuel and the start flow (fuel) adjustment was turned to "max." The auxilliary batteries were disconnected and more start attempts were made with the set batteries. During these the diverter valve was pecked on, the fuel system return hose was capped off, and start flow checks were made (100 cc). The auxilliary batteries were reconnected for one start attempt (also unsuccessful) and the warm auxilliary batteries were then moved into the chamber and connected to the unit. On the fourth attempt, 1320°F T4 was reached but the unit shut down with an overcrank. The fifth attempt with warm batteries (the 28th attempt in 3 hours, 42 minutes) was successful.

<u>Date</u>	<u>Gen Set Hrs.</u>	<u>Event</u>
	123.0	After a battery charging run, the 24 hour soak was restarted for another cold start attempt. The chamber temperatures were held at -25°F.
7/20/79	123.0	Following the two (2) fifteen second motorings, eleven (11) start attempts were unsuccessful. Had fuel on cc checks and could hear ignition. Facilities went down due to surged unit. Found the fuel nozzle had a plugged pilot orifice--blew it out with dry nitrogen. Two additional attempts with warm batteries reached higher temperatures but the 2nd of these was manually aborted because facilities were not flowing air and recirculation was occurring. The -25°F test was again aborted.
7/31/79	123.0	The fuel system components were bench tested with the following results: Control Box - - o Cold test--no affect. - o Changed sensing to recognize light-off during quick fill. - o Lowered failed sensor shut-down from 200° to 100°F. - o Changed quick fill dropout from 8 percent to 12 percent speed. - o Reset quick fill to 120 ma. - o Reset start flow to standard. - o Added 100 ohm buffer in If circuit of test connector. Fuel Nozzle - Flow satisfactory Fuel Valve - Increased pressure relief valve setting. Spin samples and cold samples of fuel did not show any indication of water. Fuel samples from the primary fuel filter, the day tank, and the secondary fuel filter were analyzed for water content and, respectively, showed .006, .005, and .006 percent H₂O by volume. The fuel specific gravity was .8276 at 60/60°F.

<u>Date</u>	<u>Gen Set Hrs.</u>	<u>Event</u>
8/1/79	123.0	Started the following action to achieve starts on next cold test: 1. Circulating fuel through a chilling/filtering system to try to remove H ₂ O from system. 2. Recharging batteries.
8/2/79	123.0	Found Army supplied water separator had come apart inside. Sent to the Instrument Lab for repair (This unit may not have been working at any time!). Continued circulating fuel. Reinstalled the fuel system parts. Added "Prist" fuel drying compound to remove any moisture from the engine system.
8/3/79	123.2	Completed a run to "low fuel level" shutdown to run "Prist" dried fuel through the engine. Drained the remainder of this fuel from the day tank and replaced both fuel filters. All fuel in fuel system chilled/filtered and covered with a dry nitrogen purge. A fuel sample from system checked 39.8 API and .004 percent H ₂ O by volume.
8/3/79	124.1	Completed a battery charging run which should also have purged the remaining "Prist" from the engine system. Starting to cool down for -25°F cold test. Started 24 hour soak at 17:20 o'clock.
8/4/79	124.1	Checked system - Gen set doors operated satisfactorily. Fuel and oil samples were clear. Completed 2 mandatory 15 second motorings. Attempted seven (7) unsuccessful starts. All were shut down on overcrank with a maximum temperature of 1550°F. The quick fill resistor was clipped to raise the quick fill flow level but the board collected frost (apparently) and three (3) subsequent attempts displayed odd quick fill current levels. Aborted -25°F Test.
8/6/79	124.1	Removed ECA and T6 control box for bench test. Also removed fuel pump and fuel valve for bench tests.

<u>Date</u>	<u>Gen Set Hrs.</u>	<u>Event</u>
8/7/79	124.1	Removed fuel nozzle, 3-way valve, 2-way valve and diverter valve (plus lines and bracket) for a "system" cold bench test. (See ETR 79D30 for the results of the system cold test.
8/13/79	124.1	Discovered a wire in the Control Console which had the insulation worn off.
8/27/79	124.1	NOTE: Cold tests have been conducted, by the Army, at Ft. Belvoir, VA; and design engineering has determined the probable cause of the start failures to be the excess cold oil in the clutch because of the mandatory cranks. Removed the two paralleled reverse polarity diodes and installed a single large diode.
8/29/79	124.1	Circulating fuel through the repaired Army separator and it is now removing some water and other foreign material. Conducted a shaker test on the control console and found the entire wiring panel exhibited significant resonant vibration at 50 Hz (generator rotational frequency). Repaired three shorted or broken wires and provided improved protection for others in the control console.
8/30/79	124.1	Reinstalled 3-way and 2-way fuel valves. Chilling and filtering fuel in fuel system.
9/4/79	124.1	Installed a plug in the clutch cooling oil passage to reduce clutch cooling oil flow. Reinstalled a new fuel nozzle, a replacement fuel pump and fuel valve and a new diverter valve.
9/5/79	125.3	Completed check runs to correct fuel leaks and to check operation with replacement parts.
	125.5	Completed battery charging and engine drying run during start of cooling cycle.

<u>Date</u>	<u>Gen Set Hrs.</u>	<u>Event</u>
9/6/79	125.5	Started on 24 hour soak at 00:00 o'clock. Added 2 quarts of oil to raise level in engine 2 qts. above full per new level requirements.
9/7/79	127.0	<u>-25°F Cold Test</u> The unit fired successfully (after the two motorings) and the first portion of the cold test (through the no-load engine oil stabilization run) was completed. While running with rated load, following the engine oil stabilization, the unit decelerated and "dumped" the load on an "under-frequency trip," then recovered to max speed. An inspection of the engine revealed that the inlet air filters were clogged with frost. Attempted to brush off the screens and blow out the frost with dry nitrogen.
	129.5	Maintaining -25°F chamber temperatures. Made three additional runs, attempting (unsuccessfully) to keep the inlet filter clear. Finally removed the inlet filters and installed filter shells only. NOTE: Facilities had a heat exchange leak allowing moisture into the cold system. This was the cause the icing and frost formation.
	134.5	Completed Regulator Range test at -25°F per PD#29, MIL STD 705B, method 511.1. During the testing at 150 KW and 197 volts, the overload relay dumped the load. The test was completed without further problems (See "Test Results").
	137.9	Completed frequency and voltage regulation, stability (short term) and transient response test at -25°F, per PD#17, MIL STD 705B, method 608.1 (See "Test Results"). NOTE: It was necessary to brush frost from the engine and generator air inlet screens on occasion during the tests.
	138.0	Unit shut down with "low fuel." Added DFA (dried) fuel to system.

<u>Date</u>	<u>Gen Set Hrs.</u>	<u>Event</u>																												
9/8/79	139.0	While conducting the indicating instrument test, the unit shut down for no know cause.																												
	140.5	Completed the indicating instrument test at -25°F per PD#27, MIL STD 705B, method 513.1. See "Test Results." Started warming the test chamber and started setting up for -50°F Cold Test.																												
9/10/79	140.5	Completed setup for -50°F cold test with the following items: 1. Set up to add JP4 fuel to the system when the DFA fuel is used up. 2. Obtained new fuel and oil samples. 3. Set up for maintaining auxilliary batteries at -25 with heaters built in.																												
	140.6	Completed run to dry the engine while cooling.																												
	140.6	<u>Start of -50° Cold Test.</u> Started 24 hour cold soak at 0920 o'clock.																												
9/11/79	140.6	Cold start was completed at -50° and the unit was loaded, within 1 minute to rated load (150 KW). The following chronological sequence ended in engine failure: <table border="1"> <thead> <tr> <th><u>Time(Sec)</u></th> <th><u>Event</u></th> </tr> </thead> <tbody> <tr> <td>0</td> <td>Selected start.</td> </tr> <tr> <td>.35</td> <td>Quick fill @ 180 ma.</td> </tr> <tr> <td>1</td> <td>Start of N1 increase.</td> </tr> <tr> <td>2</td> <td>Light-off to 400°F T4.</td> </tr> <tr> <td>2.4</td> <td>Off the quick fill to about 60 ma.</td> </tr> <tr> <td>7.6</td> <td>Start of rapid T4 rise from 450°F.</td> </tr> <tr> <td>14</td> <td>Start of MOP rise. If at 80 ma and starting to cut back—T4 at 1680°F.</td> </tr> <tr> <td>18.3</td> <td>Control oil press "pegged" at 500 psig +, MOP = 10 psig, If = 68 ma, N1 = 10,500 rpm, T4 = 1800°F.</td> </tr> <tr> <td>20.7</td> <td>Control oil press below 500 psig.</td> </tr> <tr> <td>21.4</td> <td>Start of increase in N2.</td> </tr> <tr> <td>38.1</td> <td>Main oil press (MOP) = 130 psig at maximum point.</td> </tr> <tr> <td>40.0</td> <td>If cut back to zero--awaiting synchronous speeds.</td> </tr> <tr> <td>41.0</td> <td>Start of accel - N1 = 26,000 rpm, N2 = 2350 rpm.</td> </tr> </tbody> </table>	<u>Time(Sec)</u>	<u>Event</u>	0	Selected start.	.35	Quick fill @ 180 ma.	1	Start of N1 increase.	2	Light-off to 400°F T4.	2.4	Off the quick fill to about 60 ma.	7.6	Start of rapid T4 rise from 450°F.	14	Start of MOP rise. If at 80 ma and starting to cut back—T4 at 1680°F.	18.3	Control oil press "pegged" at 500 psig +, MOP = 10 psig, If = 68 ma, N1 = 10,500 rpm, T4 = 1800°F.	20.7	Control oil press below 500 psig.	21.4	Start of increase in N2.	38.1	Main oil press (MOP) = 130 psig at maximum point.	40.0	If cut back to zero--awaiting synchronous speeds.	41.0	Start of accel - N1 = 26,000 rpm, N2 = 2350 rpm.
<u>Time(Sec)</u>	<u>Event</u>																													
0	Selected start.																													
.35	Quick fill @ 180 ma.																													
1	Start of N1 increase.																													
2	Light-off to 400°F T4.																													
2.4	Off the quick fill to about 60 ma.																													
7.6	Start of rapid T4 rise from 450°F.																													
14	Start of MOP rise. If at 80 ma and starting to cut back—T4 at 1680°F.																													
18.3	Control oil press "pegged" at 500 psig +, MOP = 10 psig, If = 68 ma, N1 = 10,500 rpm, T4 = 1800°F.																													
20.7	Control oil press below 500 psig.																													
21.4	Start of increase in N2.																													
38.1	Main oil press (MOP) = 130 psig at maximum point.																													
40.0	If cut back to zero--awaiting synchronous speeds.																													
41.0	Start of accel - N1 = 26,000 rpm, N2 = 2350 rpm.																													

<u>Date</u>	<u>Gen Set Hrs.</u>	<u>Event</u>
	<u>Time(Sec)</u>	<u>Event</u>
	43.0	N2 = 3500, N1 = 40, 500, I _f cut to zero. T4 decreasing, frequency = 449 Hz.
	46	N1 back to 35,000 rpm, N2 back to 2650 rpm, start of clutch lock-up and increase in I _f .
	48.4	400 Hz steady, T4 = 970°F, clutch pressure = 130 psig, MOP = 100 psig, control oil press = 215 psig.
	60	Load to 150 KW, .8 PF., Max T4 = 1550°F, 2 Hz dip in frequency, recovery to 403 Hz.
	70	Temperature increase from 1400° to 1590° with slow speed decrease to 386 Hz - <u>Howl from Unit.</u>
	71.6	386 Hz starting to recover.
	74.4	Recovered to 406 Hz, T4 dropped to 1400°F.
	76.2	T4 increase to 1550°F <u>with howl.</u> Speed decreased to 398 Hz.
	78.7	T4 dropped to 1450°F and speed recovered to 406 Hz.
	86	Unit emitted a loud "pop." T4 went to 1920°F and unit was manually shut down.

The generator set and engine were disassembled to assess the failure damage. The failure and secondary damage are shown on Photos 351421 through 351439 and 351525.

Photographs 351430 and 351432 picture the failed power turbine roller bearing which was apparently the primary failure due to lack of lubrication. The other photographs depict secondary damage but special interest should be taken in the gasifier front (Photo 351429) and rear (Photo 351427) ball bearings which had extreme distress on one side due to the heavy activity at the quill shaft which finally failed at the seal (Photo 351424) which runs in the bushing located in the aft end of the power turbine (Photo 351426).

Following the replacement of parts, the engine was repaired and was check run on test stand 887. Several problems and significant events ensued as follows:

<u>Date</u>	<u>Engine Hours</u>	<u>Event</u>
9/17/79	185.6	Had to rework compressor cover pilot (.006 inch too small) to install the inlet adapter. Start flow checks--40 and 66 cc's.
	185.8	Obtained vibration signatures which showed predominantly 50 Hz (output rotational) and 2500-3150 Hz (output gear tooth mesh frequency). All levels were within limits (AD5210-00006 thru 00008).
	185.9/186.5	Had two magnetic drain plug indications. Plugs were cleaned of fuzz.
9/18/79	190.0	Replaced the P/N 23000974 gasifier oil transfer cap to stop an air leak at the flange. Flange was on the old one.
	191.7	Discovered T4 thermocouple guide tubes were not in the proper positions. Reinstalled them properly.
	193.7	Completed engine check out. See "Test Results."

During the engine repair and test period, this buildup, stiffeners were installed in the generator set control console. The engine was reinstalled in the generator set, and on September 20, 1979, the generator set (S/N 0000003, Buildup #6) was reinstalled on Test Stand 873 for a final checkout prior to shipment to the Army. The unit was checked out through the speed and power range, paralleling systems were checked, load sensing was checked at 3.0 volts and the Delco monitor was checked (minor adjustments) for agreement with the standard instrument. The exhaust covers were installed and functionally checked. Following the generator set final check-out, a shaker test was conducted indicating that the added stiffeners had significantly reduced the 50 Hz vibration in the wiring panel and adjacent control console components. (See ETR 79D65.)

The generator set S/N 0000003 was prepared for shipment (including repainting) and, on September 24, the unit was shipped to MERADCOM Ft. Belfoir, VA. The following additional items were included in the shipment: (The unit oil and fuel systems were full, the batteries disconnected and circuit breaker open)

1. One box of extraneous load bank instrumentation parts.
2. Exhaust (engine and generator) ducts and supporting structure.
3. Load bank that had been used for extra loading on this test and for all QC tests.

Test Results

Prior to the start of the environmental tests, several of the required tests were run to check the unit and test techniques at ambient conditions.

The Indicating Instrument test—PD#27 (513.1) data, tabulated on Addendum A, pages 1 and 2 indicated phase to phase voltages were out of limits at the following conditions:

1. Phase 2-3 with 75 percent load at 388 Hz and 400 Hz frequency.
2. Phase 3-1 with 75 percent load at 388 Hz, 400 Hz, and 412 Hz.
3. Phase 2-3 with 100 percent load at 388 Hz.
4. Phase 3-1 with 50 percent load at 388 Hz.
5. At 100 percent load and 412 Hz frequency, gen set data were not taken.

The Battery Charging test at ambient conditions per paragraph 4.4.1 was completed and the results are plotted on Enclosure AD5210-00009. These curves indicate good regulation from minimum current to over 60 amps with about 0.2 volts drop at the higher loads. (See results of test after D.C. control test).

The D.C. control test was attempted three times. On the first two tests, the reverse polarity test resulted in a failed reverse polarity system diode. On the third test, the reverse polarity test was deleted and the remaining results were as follows:

1. There were no apparent operational problems resulting from disconnecting the batteries.

2. There were no voltage spikes (on the oscillograph voltage records) at any time.
3. With 28.4 initial DC volts, the following changes occurred when the batteries were disconnected:
 - 3.1 T4 temperature decreased from 1690°F to 1659°F apparently due to dropping the battery charging load.
 - 3.2 DC voltage increased from 28.4 volts to 31.6 volts for the same reason (See Battery Charging Test below.)
 - 3.3 Exciter current increased from 2.287 amps to 2.322 while exciter voltage increased from 7.047 to 7.212 volts.
 - 3.4 Frequency, load, AC voltages, AC currents and other parameters did not change significantly.
 - 3.5 Voltage and frequency bandwidths remained well below limits at 0.2 and 0.1 percent respectively.
4. With 25.9 initial voltage setting, the following changes resulted from disconnecting batteries:
 - 4.1 T4 temperature dropped from 1652°F to 1640°F.
 - 4.2 DC control voltage increased from 25.9 to 28.0 volts.
 - 4.3 DC current dropped from 4.4 amps to 4.0 amps--reason unknown.
 - 4.4 Exciter current increased (2.263 to 2.318 amps) while exciter voltage increased (7.120 to 7.429 volts).
 - 4.5 No other parameters showed significant change.
 - 4.6 Bandwidths remained at about 0.2 and 0.1 percent for voltage and frequency respectively.
5. The test was not run at max voltage because of the concern that the reverse polarity system diode would be affected.

Because of discrepancies in load, no-load voltage during the battery charging and DC Control tests above, the Battery Charging test was rerun and plotted on Enclosure AD5210-00010. These results indicate about 1.5 volts drop from no load to loaded (60 amp) condition. The reason for the discrepancy is unexplained unless the reverse polarity diode failures affected the alternator or its regulator.

The data for the Frequency Adjust testing at ambient pressure and +125°F temperature per MIL STD 705B, method 511.2 are tabulated on Addendum B, page 1. These data indicate that the +3 percent limit could not be reached (411 Hz max) and the unit shut down with a T6 overtemperature shutdown when frequency was reduced to 396 Hz with 150 KW load. The no load testing was acceptable except 411 Hz was maximum frequency attainable.

The test results of the Regulator Range test, at +125°F, per PD#29 (511.1), are tabulated on Addendum B page 2. The data from the Standard Instrument indicated regulation was well within the one (1) percent limit. The Texas Instruments (T.I.) recorder appeared to have some hysteresis; and thusly, results from it indicated regulation in the 1.91 to 2.72 percent range. This discrepancy was not resolved.

The test data from the Indicating Instrument test at +125°F temperature per PD#27 (513.1) are shown on pages 3 and 4 of Addendum B. These data indicate good agreement between the generator set instruments and the "standard" with only one voltage (3-1 phase at 400 Hz) out of limits. The 100 percent load at 388 Hz could not be run.

The data from the Frequency and Voltage Regulation, Stability, and Transient Response Test at +125°F per PD17 (608.1) are shown on pages 5 and 6 of Addendum B. These data indicate that the frequency overshoots and recovery times were out of limits at 75 and 100 percent load. This is as expected, and the prototype units are not required to meet these limits. In addition, the voltage regulation was out of limits at all load changes except 25 percent. These data were transient, taken from the T.I. recorder. (See the discussion on Regulator Range test, above, for further information on regulation.)

Though eliminated in the Test Request, the overload relay test per PD paragraph 3.10.3.3 was requested at 125°F; and this relay, as expected, failed to meet the Purchase Description (PD) paragraph 3.10.3.3 requirements. The time results were as follows:

<u>Phase</u>	<u>*Load</u>	<u>Operating Time</u>
3(C)	200%	1:12, 1:27, 1:27 (Min:Sec)
	130%	> 10 minutes
2(B)	200%	1:27, 1:14, 1:14 (Min:Sec)
	130%	>10 Minutes
1(A)	200%	1:14, 1:12, 1:13 (Min:Sec)
	130%	>10 Minutes

<u>Phase</u>	<u>*Load</u>	<u>Operating Time</u>
1,2&3	110%	No load release in 2 hours.

*The overload was simulated to the relay by using special current transformers on the load lines.

When the relay is set to operate in the 8+2 minutes at 130 percent load, it will release the load when running for long periods at 100% load (150 KW).

The data from the long term frequency and voltage stability test, at 125°F, per PD#20 (608.2), tabulated on Addendum B, page 7, indicate a maximum long term bandwidth of .56 volts or .47 percent of rated phase-to-neutral voltage (120V). This is within the required limits.

The data from the DC control test at 125°F per PD#37, MIL-STD-705B, method 655.1, did not indicate any operating difficulties (except those described in Test History due to diode problems) or any voltage spikes during operation with, or without batteries connected. Incomplete hand data prevented analysis of the DC current and voltage relationships during this test.

On the run, shutdown, and restart test per MIL STD 705B, method 710.1, the unit completed the test without any difficulties. As expected, the shutdown, from rated load condition, caused more severe overspeed due to the high residual temperature in the regenerators. This overspeed reached about (off the chart scale) 460 Hz or 115 percent speed. The restart required about 23.7 seconds to reach 100 percent speed.

The circuits interrupter-overvoltage and undervoltage test, at 125°F, per PD#26 (512.3), provided the following operating times:

1. Overvoltage step applications from 208 volts to 271-272 volts resulted in the overvoltage relay opening at .170, .182 and .171 seconds on three tests. Two of these are slightly faster than the .20+.02 second limits.
2. Undervoltage steps from 208 volts to 161 volts resulted in the main circuit interrupter (CB5) opening after 2.840, 2.840 and 2.843 seconds on three (3) tests. These values were within the 3+1 second limit.

Enclosure AD5210-00011 contains the data from the battery charging test at 125°F per PD paragraph 4.4.1. The battery charging alternator was damaged during the test and was replaced before the minimum voltage portion of the test. As may be seen from the enclosure, the minimum voltage adjustable was 27.9 volts at 3 amps. The curve for the minimum voltage setting on the replacement alternator did not have the same characteristics as the unit that had been damaged. A short time short circuit was applied across the alternator without damage. Current limiting was not checked.

Page 8 of Addendum B contains the data from the voltage dip and rise test at 125°F per PD#24 (619.2). These data show that all voltage dips and rises were within the 15 percent limit, but the percent rise values, during load dump, were as high as 14.9 percent, which is very marginal. Recovery times were very fast with a maximum time of .0925 seconds which is .26 percent of the .35 second limit.

Enclosures AD5210-00012 and AD5210-00013 contain the basic engine and gen set parameters during the voltage and frequency drift test per PD#19 and paragraph 4.4.5. This test was run with end points at 81°F and 21°F. The data from the above referenced enclosures show the following:

1. Power, regulated voltage, oil temperature, generator cooling air differential temperature (ΔT) and generator set cooling air differential temperature experienced only minor changes.
2. T4 dropped from about 1670°F to about 1440°F or 3.83 degrees for each degree reduction in inlet temperature.
3. Frequency increased about 1.7 Hz (.43%) while the generator set instrument indicated a decrease of 2 Hz (0.5%). The allowable limit for drift was 3.0 percent.
4. Engine exhaust temperature decreased from 545°F to 470°F or 1.25°F per degree of inlet temperature change.
5. Exciter voltage decreased 1.16 volts (15.83%).
6. Exciter current decreased .10 amps (4.35%).

Page one (1) of Addendum C comprises the test results of the regulator range test at 5,000 ft. altitude and 107°F per PD#29 (511.1). These data again show the regulation, based on data from the Standard Instrument, is well below limits with a maximum value (at 219 volts) of 0.71 percent. The T.I. recorder indicates a maximum regulation error of 2.40 percent at 197 volts.

The test results from the frequency and voltage regulation, stability and transient response test at 5,000 ft. altitude and 107°F per PD#17 (608.1) are tabulated on pages 2 and 3 of Addendum C. These data indicate the following parameters were out of limits:

1. Unload overshoot on frequency at 75 and 100 percent load dumps.
2. Unload recovery time on frequency at all loads but 25 percent.
3. Load recovery time on frequency at 100 percent load.
4. Voltage regulation during all load changes except 25 percent load. Note the differences in instruments reported in discussion of voltage regulator range test above.
5. Unload recovery time on voltage from 100 percent load.

Addendum C (pages 4 and 5) contains the results of the Indicating Instrument test, at 5,000 ft. and 107°F per PD#27 (513.1). The instruments in the generator set were within limits compared with the Standard Instrument except for readout of voltage as follows:

1. Phase 3-1 voltage at all tested speeds with 75 and 100 percent load were out of limits.
2. Phase 1-2 voltage was out of limits at 75 percent load and 388 Hz.
3. Phase 2-3 voltage was out of limits at 100 percent load with 400 and 412 Hz speeds.

In addition, the rated load, 288 Hz condition could not be run because of high operating temperatures.

Testing at 8,000 feet altitude and 95°F was initiated 7/20/79 and completed 7/21/79. The test results from the Indicating Instrument test at 8,000 Ft. and 95°F per PD#27 (513.1) are tabulated on pages 1 and 2 of Addendum D. Again, the rated power (138 KW) could not be run at 388 Hz due to high T6 temperatures. The remaining data indicate that the gen set instruments agreed with the Standard Instrument except on voltage phase 3-1 at all speeds with 75 percent and rated load and phase 2-3 voltage at both speeds with rated load.

NOTE: In all tests at 8,000 ft. and 95°F, where rated load is 137.5 KW, the part power points were run at 25, 50 or 75 percent of 150 KW.

The test results of the regulator range test at 8,000 ft. altitude and 95°F per PD#29 (511.1) are displayed on page 3 of Addendum D. As in the tests at other conditions, the data from the Standard Instrument indicate all regulation is well within the 1 percent limit (.35 percent max at 197 volts) while the T.I. recorder indicates values as high as 2.18 percent.

The attached pages 4 and 5 of Addendum D contain the test results of the frequency and voltage regulation, stability and transient response test at 8,000 ft. and 95°F per PD#17 (608.1). The following conditions were out of limits (this prototype unit is not contractually required to meet frequency overshoot, undershoot and recovery times):

1. Frequency overshoot was out of limits when unloading from 75 percent or rated load (138 KW).
2. Frequency recovery time was out of limits for 50 and 75 percent loads and for rated load (138 KW).
3. Voltage regulation, based on the T.I. recorder data, was out of limits at 75 percent and rated (138 KW) load.

The overtemperature safety device test at 125°F per PD#40 (515.2A) resulted in 174 KW and 2020°F T4 at the time of the overtemperature shutdown. The engine actually decelerated along an acceleration fuel schedule until an underfrequency relay trip dropped the load. At about this same time, the O.T. shutdown occurred.

The gasifier pinion bearing failure and the various problems during the early start attempts at -25°F chamber soak temperatures are documented in the Test History. The special tests resumed 9/7/79 on the -25°F cold test.

The fire-up and loading to 150 KW within one minute with -25°F temperatures did not present any problem following the installation of the clutch cooling oil reduction plug.

The first special test at -25°F was the regulator range test per PD#29. Addendum E, page 1 contains the results of this test at -25°F per PD#29 (511.1). As in the other regulator range tests, the data from the Standard Instrument and the T.I. recorder disagree. The unit meets all requirements based on data from the "Standard Instrument" which measured a maximum regulation of .260 percent at 197 volts.

Addendum E pages 2 and 3 show the results of the frequency and voltage regulation, stability and transient response test at -25°F per PD#17 (608.1). These data indicate that the only parameter out of limits was voltage regulation, based on the T.I. recorder results.

On the Indicating Instrument test, at -25°F, per PD#27 (513.1), the phase 3-1 voltage was out of limits at all conditions except 388 and 412 Hz with zero load. All voltage readings were out of limits at 100 percent load and phase 2-3 voltage was out of limits at zero load. These data are tabulated on pages 4 and 5 of Addendum E.

The remaining environmental testing through the engine failure on the -50° cold test are reported in Test History. The engine performance, during the check run, is plotted on Enclosure AD5210-00014.

All line recordings and hand data are filed with the test folders under EDO5210-01, P568-06.

ADDENDUM E
-25°F COLD TEST
511.1 REGULATOR RANGE TEST @ -25°F

Page 1

$$\underline{208V} \quad \text{STANDARD} = \frac{121.8 - 121.5}{1.215} = 0.247\%$$

$$\text{TI RECORDER} = \frac{122.0 - 119}{1.215} = 2.52\%$$

$$\underline{219V} \quad \text{STANDARD} = \frac{127.5 - 127.2}{1.272} = 0.236\%$$

$$\text{TI RECORDER} = \frac{128 - 125.2}{1.252} = 2.24\%$$

$$242V \quad \text{STANDARD} = \frac{141.1 - 140.8}{1.408} = 0.213\%$$

$$\text{TI RECORDER} = \frac{141.139}{1.39} = 1.44\%$$

$$197V \quad \text{STANDARD} = \frac{115.5 - 115.2}{1.152} = 0.260\%$$

$$\text{TI RECORDER} = \frac{115.7 - 113}{1.13} = 2.39\%$$

MIN VOLTAGE

106.4 V.

ADDENDUM E

- 25° COLD TEST

Page 2

17

608.1

FREQUENCY AND VOLTAGE REGULATION STABILITY

(SHORT TERM) AND TRANSIENT RESPONSE (MAX VALUES)

		<u>FREQUENCY</u>	<u>VOLTAGE</u>
LIMITS	BAND WIDTH @ LOAD	<u>.5%</u>	<u>1%</u>
	NO LOAD	<u>.5%</u>	<u>1%</u>
* NEGLIGIBLE	REGULATION	<u>.5%</u>	<u>1%</u>
	UNLOAD OVERSHOOT	<u>1.5%</u>	<u>15%</u>
	RECOVERY TIME	<u>1 SEC</u>	<u>.35 SEC</u>
	LOAD UNDERSHOOT	<u>1.5%</u>	<u>15%</u>
	RECOVERY TIME	<u>1 SEC</u>	<u>.35 SEC</u>
FULL LOAD RDGS			
	BAND WIDTH @ LOAD	<u>* NEG</u>	<u>NEG</u>
	NO LOAD	<u>NEG</u>	<u>NEG</u>
	REGULATION	<u>.038%</u>	<u>(1.83%)</u>
	UNLOAD OVERSHOOT	<u>.75%</u>	<u>3.50%</u>
	RECOVERY TIME	<u>.51 SEC</u>	<u>.24 SEC</u>
	LOAD UNDERSHOOT	<u>.475%</u>	<u>1.17%</u>
	RECOVERY TIME	<u>.69 SEC</u>	<u>.24 SEC</u>
3/4 LOAD READINGS			
	BAND WIDTH @ LOAD	<u>NEG</u>	<u>NEG</u>
	NO LOAD	<u>NEG</u>	<u>NEG</u>
	REGULATION	<u>.025%</u>	<u>(1.75%)</u>
	UNLOAD OVERSHOOT	<u>.31%</u>	<u>2.50%</u>
	RECOVERY TIME	<u>.24 SEC</u>	<u>.27 SEC</u>
	LOAD UNDERSHOOT	<u>.24%</u>	<u>NEG</u>
	RECOVERY TIME	<u>.18 SEC</u>	<u>NEG</u>
1/2 LOAD READINGS			
	BAND WIDTH @ LOAD	<u>NEG</u>	<u>NEG</u>
	NO LOAD	<u>NEG</u>	<u>NEG</u>
	REGULATION	<u>.025%</u>	<u>(1.33%)</u>
	UNLOAD OVERSHOOT	<u>NEG</u>	<u>NEG</u>
	RECOVERY TIME	<u>NEG</u>	<u>NEG</u>
	LOAD UNDERSHOOT	<u>.075%</u>	<u>NEG</u>
	RECOVERY TIME	<u>NEG</u>	<u>NEG</u>

ADDENDUM E

- 25°F COLD TEST

Page 3

17 (CONT) 608.1

FREQUENCY AND VOLTAGE REGULATION, STABILITY
(SHORT TERM) AND TRANSIENT RESPONSE (MAX VALUES)

FREQUENCY VOLTAGE

1/4 LOAD

READINGS _____

BAND WIDTH @ LOAD

NEG

NEG

NO LOAD

NEG

NEG

REGULATION

—

.67%

UNLOAD OVERSHOOT

—

NEG

RECOVERY TIME

—

—

LOAD UNDERSHOOT

—

—

RECOVERY TIME

↓

↓

FULL LOAD

READINGS _____

BAND WIDTH @ LOAD

NEG

NEG

NO LOAD

NEG

NEG

REGULATION

.025%

2.33%

UNLOAD OVERSHOOT

.65%

3.0%

RECOVERY TIME

.45 SEC

.24 SEC

LOAD UNDERSHOOT

.475%

1.0%

RECOVERY TIME

.69 SEC

.21 SEC

ADDENDUM E

- 25 °F COLD TEST

Page 4

27 513.1

PANEL INSTRUMENTATION

		INSTRUMENT ERROR			
		<u>258 Hz</u>	<u>400 Hz</u>	<u>242 Hz</u>	<u>LIMIT</u>
ZERO LOAD -	KW	<u>+2.</u>	<u>+2.</u>	<u>+1.</u>	<u>—</u>
	FREQUENCY	<u>+ .6</u>	<u>+ .7</u>	<u>- .1</u>	<u>± 3 Hz</u>
	VOLTAGE 1-2	<u>-1.3</u>	<u>-1.6</u>	<u>-1.3</u>	<u>± 1.56V</u>
	2-3	<u>- .8</u>	<u>(-1.7)</u>	<u>-1.2</u>	<u>± 1.56V</u>
	3-1	<u>-1.4</u>	<u>(-1.8)</u>	<u>-1.4</u>	<u>± 1.56V</u>
	CURRENT 1	<u>+1.</u>	<u>0</u>	<u>+1.</u>	<u>± 10.4A</u>
	2	<u>+1.</u>	<u>0</u>	<u>0</u>	<u>± 10.4A</u>
	3	<u>+1.</u>	<u>0</u>	<u>+1.</u>	<u>± 10.4A</u>
25% LOAD - KW		<u>+2.3</u>	<u>+2.3</u>	<u>+0.1</u>	<u>—</u>
	FREQUENCY	<u>+1.7</u>	<u>+ .9</u>	<u>+2.4</u>	<u>± 3 Hz</u>
	VOLTAGE 1-2	<u>-1.5</u>	<u>-1.4</u>	<u>-1.5</u>	<u>± 1.56V</u>
	2-3	<u>- .6</u>	<u>- .6</u>	<u>- .6</u>	<u>± 1.56V</u>
	3-1	<u>(-1.8)</u>	<u>(-1.8)</u>	<u>(-1.8)</u>	<u>± 1.56V</u>
	CURRENT 1	<u>-1.2</u>	<u>-2.4</u>	<u>-1.6</u>	<u>± 10.4A</u>
	2	<u>+ .5</u>	<u>+ .6</u>	<u>+ .4</u>	<u>± 10.4A</u>
	3	<u>- .3</u>	<u>- .7</u>	<u>- .2</u>	<u>± 10.4A</u>
50% LOAD - KW		<u>+3.3</u>	<u>+3.4</u>	<u>+3.6</u>	<u>—</u>
	FREQUENCY	<u>+1.2</u>	<u>+ .8</u>	<u>- .1</u>	<u>± 3 Hz</u>
	VOLTAGE 1-2	<u>-1.5</u>	<u>-1.4</u>	<u>-1.4</u>	<u>± 1.56V</u>
	2-3	<u>+ .1</u>	<u>- .8</u>	<u>+ .2</u>	<u>± 1.56V</u>
	3-1	<u>(-2.1)</u>	<u>(-3.0)</u>	<u>(-2.0)</u>	<u>± 1.56V</u>
	CURRENT 1	<u>-1.7</u>	<u>-1.2</u>	<u>-1.2</u>	<u>± 10.4A</u>
	2	<u>+2.5</u>	<u>+2.8</u>	<u>+3.4</u>	<u>± 10.4A</u>
	3	<u>-1.6</u>	<u>- .8</u>	<u>- .3</u>	<u>± 10.4A</u>

ADDENDUM E -25°F COLD TEST

Page 5

		<u>INSTRUMENT ERROR</u>			<u>LIMIT</u>
		<u>@388 Hz</u>	<u>@400 Hz</u>	<u>@412 Hz</u>	
75% LOAD-KW		<u>+1.8</u>	<u>+1.7</u>	<u>+1.8</u>	<u>—</u>
FREQUENCY		<u>+1.2</u>	<u>0</u>	<u>-1.3</u>	<u>±3 Hz</u>
VOLTAGE	1-2	<u>-1.3</u>	<u>-1.2</u>	<u>-1.1</u>	<u>±1.56V</u>
	2-3	<u>-1.8</u>	<u>-1.7</u>	<u>-1.6</u>	<u>±1.56V</u>
	3-1	<u>(-3.0)</u>	<u>(-2.9)</u>	<u>(-2.8)</u>	<u>±1.56V</u>
CURRENT	1	<u>-2.6</u>	<u>-3.1</u>	<u>-3.2</u>	<u>±10.4A</u>
	2	<u>+3.4</u>	<u>+3.6</u>	<u>+3.9</u>	<u>±10.4A</u>
	3	<u>-1.9</u>	<u>-1.2</u>	<u>-1.0</u>	<u>±10.4A</u>
100% LOAD-KW		<u>+3.8</u>	<u>+3.2</u>	<u>+3.7</u>	<u>—</u>
FREQUENCY		<u>-.4</u>	<u>-.9</u>	<u>-.1</u>	<u>±3 Hz</u>
VOLTAGE	1-2	<u>(-1.9)</u>	<u>(-1.9)</u>	<u>(-1.8)</u>	<u>±1.56V</u>
	2-3	<u>(-3.8)</u>	<u>(-1.7)</u>	<u>(-1.6)</u>	<u>±1.56V</u>
	3-1	<u>(-2.8)</u>	<u>(-1.9)</u>	<u>(-2.6)</u>	<u>±1.56V</u>
CURRENT	1	<u>-4.8</u>	<u>-5.</u>	<u>-4.</u>	<u>±10.4A</u>
	2	<u>+4.2</u>	<u>+4.3</u>	<u>+3.7</u>	<u>±10.4A</u>
	3	<u>-1.9</u>	<u>-2.</u>	<u>-2.1</u>	<u>±10.4A</u>

ADDENDUM F

Page 1
PREPARED BY H-GASTON

DATE 11/6/79 DEPT NO. 5870

INSTRUMENTATION LIST

PARAMETER	NAME	TYPE	MODEL	SERIAL	LAST CAL	CAL REQD
WATTS	ROCKWELL ENRIG GENERATOR MONITOR	DIGITAL	034027	78041	3/18/79	3/18/80
KILOVARS	"	"	"	"	"	"
A.C. VOLTS (L)	"	"	"	"	"	"
A.C. CURRENT	"	"	"	"	"	"
D.C. CURRENT	"	"	"	"	"	"
D.C. VOLTAGE	"	"	"	"	"	"
FREQUENCY	ATEC COUNTER	"	2300	628715	5/10/79	11/10/79
TEMP	TRENDICATOR	DIGITAL	400 A	55475	6/29/79	12/29/79
VIBRATION	C.E.C.	METER	117	4009	3/21/79	7/21/79
2	C.E.C.	"	117	"	7/19/79	11/22/79
3	C.E.C.	"	117	"	"	"
ALTERNATE	FLUKK	DIGITAL	8000A	4129	6/24/79	10/26/79
CURRENT	"	"	"	000171	3/10/79	9/10/79
VOLTAGE	"	"	"	000171	"	"
TEST CELL	DORIC	GA	DS300	62089	6/29/79	12/29/79
AIR TEMP #1	"	"	"	"	"	"
#2	"	"	"	"	"	"
#3	"	"	"	"	"	"
#4	"	"	"	"	"	"
TEST CELL	"	"	"	"	"	"
ON BATH #1	"	"	"	"	"	"
TEMP #2	"	"	"	"	"	"

PCWP V118
OF. 944, 5/29/79
P.U. H268, OF. 917
6/6/79
P.U. H317, OF. 897
6/6/79

ADDENDUM F

SUBJECT

PREPARED BY H. GASTON

DATE 11/6/79

DEPT NO. 5870

INSTRUMENTATION LIST

PARAMETER	NAME	TYPE	MODEL	SERIAL	LAST CAL		CAL REQ'D
					CAL	RECD	
TEST CELL OIL BATH #3	DORIC	DIGITAL	DS300	62089	6/29/79	6/29/79	
#4	"	CA "	"	"	"	"	"
OIL IN TEMP	"	"	"	"	"	"	"
OIL SUMP TEMP	"	"	"	"	"	"	"
BATTERY	"	"	"	"	"	"	"
ELECTROLYTE (1)	"	"	"	"	"	"	"
(2)	"	"	"	"	"	"	"
(3)	"	"	"	"	"	"	"
(4)	"	"	"	"	"	"	"
ENGINE LH EXH. TEMP	"	"	"	"	"	"	"
RH	"	"	"	"	"	"	"
GEN COOLING	"	"	"	"	"	"	"
AIR IN	"	"	"	"	"	"	"
GEN COOLING	"	"	"	"	"	"	"
AIR OUT	"	"	"	"	"	"	"
CONTROL	"	"	"	"	"	"	"
CABINET TEMP	"	"	"	"	"	"	"
GEN STATOR	"	"	"	"	"	"	"
TOP TEMP	"	"	"	"	"	"	"
GEN STATOR	"	"	"	"	"	"	"
BOTTOM TEMP	"	"	"	"	"	"	"
ENCLOSURE	"	"	"	"	"	"	"
IN TEMP	"	"	"	"	"	"	"
ENCLOSURE	"	"	"	"	"	"	"
OUT TEMP	"	"	"	"	"	"	"
DAY TANK	"	"	"	"	"	"	"
FUEL TEMP	"	"	"	"	"	"	"
EXCITER	"	"	"	"	"	"	"
STATOR TEMP	"	"	"	"	"	"	"

ADDENDUM F

Page 3

SUBJECT

PREPARED BY H. GASTON

DATE 11/6/79

DEPT NO.

5870

INSTRUMENTATION LIST

PARAMETER	INSTRUMENT					
	NAME	TYPE	MODEL	SERIAL	LAST CAL	RECAL DATE
ENGINE AIR	DORIC	CA DIGITAL	DS 300	62089	6/29/79	12/29/79
IN TEMP LH	"	"	"	"		
ENGINE AIR	"	"	"	"		
IN TEMP RH	"	"	"	"		
WOODWARD	"	"	"	"		
CONTROL TEMP	"	"	"	"		
FUEL SUPPLY	HONEYWELL	IC POTENTIOMETER	—	944446	6/29/79	10/29/79
TEMP	BROWN					
THE FOLLOWING PARAMETERS WERE RECORDED FOR DDAD						
INFORMATION: (NOT ALL RECORDED SIMULTANEOUSLY)						
Gasifier	Ground Bourn	LINE	156617	Y10026	3/15/79	9/15/79
Speed	"	Recorder	"	Y10025	9/15/79	9/15/79
Output	"	"	"	"	"	"
SAND	"	"	"	"	"	"
TY TEMP	"	"	"	"	"	"
MAIN OIL	"	"	"	"	"	"
PRESSURE	"	"	"	"	"	"
CLUTCH OIL	"	"	"	"	"	"
PRESSURE	"	"	"	"	"	"
CONTROL OIL	"	"	"	"	"	"
PRESSURE	"	"	"	"	"	"
CLUTCH VALVE	"	"	"	"	"	"
CURRENT	"	"	"	"	"	"
FUEL VALVE	"	"	"	"	"	"
CURRENT	"	"	"	"	"	"
FREQUENCY	"	"	"	"	"	"
MAIN OIL	DYNASCO	STEAM GAGE	PT310	028701	6/24/79	12/24/79
PRESSURE	"	TRANSDUCER				
CLUTCH OIL	"	"	BLN-DNF	028752	6/24/79	12/24/79
PRESSURE	"	"				
CONTROL OIL	"	"	BLN-DNF	028729	6/24/79	12/24/79
PRESSURE	"	"				

SEE TRANSDUCER

SEE TRANSDUCER

SEE TRANSDUCER

ADDENDUM F

Page 4

SUBJECT

PREPARED BY H. GASTON

DATE 11/6/79

DEPT NO. 5870

INSTRUMENTATION LIST

PARAMETER	NAME	TYPE	MODEL	SERIAL	LAST CAL	RECAL	
FREQUENCY PARKS 3-A	TEXAS INSTRUMENTS	2 CHANNEL REORDER	PDR HYF-MVA -A16-KT	3521	5/21/79	11/21/79	
AC VOLTAGE VOLTAGE 1-2	"	"	"	"	"	"	
" 2-3	HONEYWELL VISICORDER	OSCILLOGRAPH	1558	X-10027	5/29/79	11/29/79	USED FOR O.V., U.V., VOLTAGE D.P.S.
" 3-1	"	"	"	"	"	"	U.V. TESTS
AC CURRENT 3-1	"	"	"	"	"	"	
INNOV AIR PRESS	TRANSDUCER	INNOV MEXURY	M 155	C 153112	6/28/79		13 NOV 1975 TESTS FOR TESTED 6/28/79 BARTONGATE SUBT UPCM MONITOR
EXNGOS PRESS LN	"	"	"	153114	"	"	
" RH	"	"	"	153118	"	"	

ADDENDUM A

Ambient Inlet Conditions

Page 1

27

513.1

PANEL INSTRUMENTATION

		INSTRUMENT ERROR			
		6088Hz	5702Hz	5712Hz	LIMIT
ZERO LOAD -	KW	+1.9	+1.9	+1.9	—
	FREQUENCY	+2	+2	+2	±3 Hz
	VOLTAGE 1-2	-0.6	-0.6	-0.6	±1.56V
	2-3	-0.6	-0.6	-0.5	±1.56V
	3-1	+0.3	+0.3	+0.2	±1.56V
	CURRENT 1	+2	+2	+1	±10.4A
	2	+2	+2	+1	±10.4A
	3	+2	+2	+1	±10.4A
25% LOAD - KW		+3	+3	+3.1	—
	FREQUENCY	+2	+1	+1	±3 Hz
	VOLTAGE 1-2	-0.3	-0.7	-0.3	±1.56V
	2-3	-0.4	-0.3	-0.4	±1.56V
	3-1	-0.7	-0.6	-0.7	±1.56V
	CURRENT 1	-0.5	-0.8	-1	±10.4A
	2	+1.2	+2.1	+2.1	±10.4A
	3	+0.2	-0.2	-0.4	±10.4A
50% LOAD - KW		+3.7	+3.8	+3.9	—
	FREQUENCY	+2	0	+1	±3 Hz
	VOLTAGE 1-2	-0.4	-0.4	-0.3	±1.56V
	2-3	+1.2	+0.2	-0.2	±1.56V
	3-1	-1.8	-0.8	+0.3	±1.56V
	CURRENT 1	-1.1	-1.2	-0.6	±10.4A
	2	+4.1	+3	+3.9	±10.4A
	3	-0.1	-0.8	-0.2	±10.4A

ADDENDUM A

Ambient Inlet Conditions

Page 2

		INSTRUMENT ERROR			LIMIT
		@388 Hz	@400 Hz	@412 Hz	
75% LOAD-KW		+2.8	+3	+3.3	—
FREQUENCY		+2	+2	+1	±3 Hz
VOLTAGE	1-2	-0.6	-0.5	-0.4	±1.56V
	2-3	+1.7	+1.7	+0.9	±1.56V
	3-1	-1.7	-1.8	-1.6	±1.56V
CURRENT	1	-2.6	-2.2	-2.7	±10.4A
	2	+4.8	+4.7	+5	±10.4A
	3	-0.6	+0.1	-0.3	±10.4A
100% LOAD-KW		+1.5	+2.9	—	—
FREQUENCY		+2	+2	—	±3 Hz
VOLTAGE	1-2	-0.2	-0.1	—	±1.56V
	2-3	-4.2	+1.1	—	±1.56V
	3-1	-0.9	-0.8	—	±1.56V
CURRENT	1	-3.7	-2.8	—	±10.4A
	2	+5.6	+6	—	±10.4A
	3	-1.2	-0.9	—	±10.4A

ADDENDUM E

Page 1

+125°F OFFICIAL TEST.
 1. FREQUENCY ADJUST TEST. RESULTS. (511.2)-150 KW
BRUSH - STABILIZED 399 Hz, 1900-1950° T4 IND
 MAX SPEED 409 Hz, ~1850° T4.
 MIN SPEED 394 Hz, 2000° MAX T4.
T6 SHUT DOWN
 T.I - STABILIZED 400.2 Hz, ~122 V C-N.
 MAX SPEED 411.3 Hz, ~122 V C-N
 MIN SPEED 396 Hz - ~122 V C-N.
T6 SHUT DOWN.
 MASTER INSTRUMENT SET
 MANUAL DATA. 400 Hz - RDG 148. 402 Hz
 411 Hz - RDG 149, 412 Hz
 MIN - DATA NOT OBTAINED.

BECAUSE OF OVERTEMPERATURE INDICATIONS
 THE MINIMUM FREQUENCY PORTION COULD
 NOT BE COMPLETED AT 128°F CIT AND 150 KW
 0.8 PF. ALSO - MAX ADJUSTMENT WAS
 411 Hz INSTEAD OF DESIRED 412 Hz (+3%)
 PER P.D. 3.5.11.6. SEE INDICATING
 INSTRUMENT TEST, (METHOD 513.2) FOR ADDI-
 TIONAL FREQUENCY ADJUSTMENT TESTS AT
 ALL LOADS.

NO LOAD RESULTS.

BRUSH STABILIZED - 398 Hz
 MAX SPEED - 409 Hz
 MIN SPEED - 378 Hz
 T.I STABILIZED - 401 Hz
 MAX SPEED - 411.4 Hz
 MIN SPEED - 382.2 Hz
 MASTER INSTRUMENT INSTR SET
 MANUAL DATA STABILIZED RDG 154 400 Hz, 402 Hz
 MAX SPEED - RDG 155 411 Hz, 412 Hz
 MIN SPEED - RDG 156 380 Hz, 382 Hz

H. Guston

ADDENDUM E

REGULATOR RANGE TEST AT 125°F CIT (511.1).

1ST TEST ABORTED DUE TO BROKEN GROUND
WIRE CAUSING UNDER VOLTAGE "DUMP".

LIMIT - 1% (P.D. 3.5.5)

208 V.

T.I RESULTS. $\frac{124.5 - 121.2}{121.2} = 2.72\%$

MASTER. (RDG 168-169) $\frac{122.0 - 121.5}{121.5} = .41\%$

219 V.

T.I $\frac{131.3 - 128.8}{128.8} = 1.94\%$

MASTER (RDG 170-171) $\frac{128.2 - 127.8}{127.8} = .31\%$

242 V

T.I. $\frac{144 - 141.3}{141.3} = 1.91\%$

MASTER (RDG 172-173) $\frac{140.7 - 140.3}{140.3} = 0.29\%$

219 V

T.I $\frac{118 - 115}{115} = 2.61\%$

MASTER (RDG 174-175) $\frac{115.7 - 115.3}{115.3} = 0.35\%$

MIN VOLTAGE - RDG 176.

T.I 108 V C-N,
MASTER NO READING.

ADDENDUM B

+125°F CONDITIONS

Page 3

27 513.1

PANEL INSTRUMENTATION

		INSTRUMENT ERROR			
		<u>300Hz</u>	<u>400Hz</u>	<u>412Hz</u>	<u>LIMIT</u>
ZERO LOAD -	KW	<u>+2</u>	<u>+2</u>	<u>+2</u>	<u>—</u>
FREQUENCY		<u>+2</u>	<u>+2</u>	<u>+1</u>	<u>±3 Hz</u>
VOLTAGE 1-2		<u>-.3</u>	<u>-.3</u>	<u>-.3</u>	<u>±1.56V</u>
2-3		<u>-.2</u>	<u>-.3</u>	<u>-.2</u>	<u>±1.56V</u>
3-1		<u>-.4</u>	<u>-.5</u>	<u>-.5</u>	<u>±1.56V</u>
CURRENT 1		<u>+1</u>	<u>+1</u>	<u>+1</u>	<u>±10.4A</u>
2		<u>+1</u>	<u>+1</u>	<u>+1</u>	<u>±10.4A</u>
3		<u>+1</u>	<u>+1</u>	<u>+1</u>	<u>±10.4A</u>
25% LOAD - KW		<u>+2.8</u>	<u>+2.8</u>	<u>+2.3</u>	<u>—</u>
FREQUENCY		<u>+2.</u>	<u>+1.5</u>	<u>+1.0</u>	<u>±3 Hz</u>
VOLTAGE 1-2		<u>+1</u>	<u>+2</u>	<u>0</u>	<u>±1.56V</u>
2-3		<u>-.1</u>	<u>0</u>	<u>0</u>	<u>±1.56V</u>
3-1		<u>-.3</u>	<u>-.3</u>	<u>-.3</u>	<u>±1.56V</u>
CURRENT 1		<u>-1.2</u>	<u>-1.7</u>	<u>-1.2</u>	<u>±10.4A</u>
2		<u>+1.1</u>	<u>+1.0</u>	<u>+1.8</u>	<u>±10.4A</u>
3		<u>-.6</u>	<u>-.8</u>	<u>-1.3</u>	<u>±10.4A</u>
50% LOAD - KW		<u>+3.2</u>	<u>+3.3</u>	<u>+3.3</u>	<u>—</u>
FREQUENCY		<u>+2.</u>	<u>+1.</u>	<u>+1.5</u>	<u>±3 Hz</u>
VOLTAGE 1-2		<u>+1</u>	<u>+2</u>	<u>+2</u>	<u>±1.56V</u>
2-3		<u>+6</u>	<u>+6</u>	<u>+6</u>	<u>±1.56V</u>
3-1		<u>-1.5</u>	<u>-1.4</u>	<u>-1.4</u>	<u>±1.56V</u>
CURRENT 1		<u>-2.5</u>	<u>-1.5</u>	<u>-1.2</u>	<u>±10.4A</u>
2		<u>+3.</u>	<u>+2.9</u>	<u>+3.0</u>	<u>±10.4A</u>
3		<u>-1.0</u>	<u>-1.9</u>	<u>-.2</u>	<u>±10.4A</u>

ADDENDUM B

Page 4

27 513.1 PANEL INSTRUMENTATION @ +125°F

INSTRUMENT ERROR

	@386 Hz	@400 Hz	@412 Hz	LIMIT
75% LOAD-KW	+2.2	+2.4	+2.7	—
FREQUENCY	+1.0	0	+1.	± 3 Hz
VOLTAGE 1-2	-0.6	-0.2	-0.2	± 1.56 V
2-3	+1.1	+1.1	+1.2	± 1.56 V
3-1	-1.4	-2.4	-1.4	± 1.56 V
CURRENT 1	+0.4	-3.	-3.2	± 10.4 A
2	+3.5	+4.1	+4.0	± 10.4 A
3	-1.2	-1.2	-0.9	± 10.4 A
100% LOAD-KW	—	-4.3	-4.	—
FREQUENCY	—	+1.	+1.	± 3 Hz
VOLTAGE 1-2	—	-0.3	-0.2	± 1.56 V
2-3	TESTED	+1.2	+1.2	± 1.56 V
3-1	—	-1.4	-1.4	± 1.56 V
CURRENT 1	TESTED	-4.2	-4.6	± 10.4 A
2	NO	+5.3	+4.7	± 10.4 A
3	—	-2.9	-2.4	± 10.4 A

ADDENDUM B

+125°F CONDITIONS.

Page 5

17

608.1

FREQUENCY AND VOLTAGE REGULATION, STABILITY

(SHORT TERM) AND TRANSIENT RESPONSE (MAX VALUES)

LIMITS	BAND WIDTH @ LOAD	FREQUENCY	VOLTAGE
		<u>.5%</u>	<u>1%</u>
	NO LOAD	<u>.5%</u>	<u>1%</u>
NEG = NEGLIGIBLE.	REGULATION	<u>.5%</u>	<u>1%</u>
	UNLOAD OVERSHOOT	<u>1.5%</u>	<u>15%</u>
	RECOVERY TIME	<u>1 SEC</u>	<u>.35 SEC</u>
	LOAD UNDERSHOOT	<u>1.5%</u>	<u>15%</u>
	RECOVERY TIME	<u>1 SEC</u>	<u>.35 SEC</u>
	FULL LOAD RDGS		
	BAND WIDTH @ LOAD	<u>.06%</u>	<u>NEG</u>
	NO LOAD	<u>.08%</u>	<u>NEG.</u>
	REGULATION	<u>.10%</u>	<u>(2.50%)</u>
	UNLOAD OVERSHOOT	<u>(6.93%)</u>	<u>2.16%</u>
	RECOVERY TIME	<u>(6.18 SEC)</u>	<u>.30 SEC</u>
	LOAD UNDERSHOOT	<u>1.14%</u>	<u>2.0%</u>
	RECOVERY TIME	<u>(2.82 SEC)</u>	<u>.15 SEC.</u>
	3/4 LOAD READINGS		
	BAND WIDTH @ LOAD	<u>NEG</u>	<u>NEG</u>
	NO LOAD	<u>NEG</u>	<u>NEG</u>
	REGULATION	<u>.10%</u>	<u>(1.72%)</u>
	UNLOAD OVERSHOOT	<u>(2.28%)</u>	<u>1.42%</u>
	RECOVERY TIME	<u>(3.24 SEC)</u>	<u>.18 SEC</u>
	LOAD UNDERSHOOT	<u>.43%</u>	<u>.92%</u>
	RECOVERY TIME	<u>.72 SEC.</u>	<u>.18 SEC.</u>
	1/2 LOAD READINGS		
	BAND WIDTH @ LOAD	<u>NEG</u>	<u>NEG</u>
	NO LOAD	<u>NEG</u>	<u>NEG</u>
	REGULATION	<u>.04%</u>	<u>(1.67%)</u>
	UNLOAD OVERSHOOT	<u>.10%</u>	<u>0</u>
	RECOVERY TIME	<u>.15 SEC</u>	<u>.09 SEC.</u>
	LOAD UNDERSHOOT	<u>.075%</u>	<u>0</u>
	RECOVERY TIME	<u>.15 SEC</u>	<u>.06 SEC</u>

ADDENDUM E + 25°F CONDITIONS

Page 6

17 608.1 FREQUENCY AND VOLTAGE REGULATION,
STABILITY AND TRANS. RESPONSE (MAX VALUES)

1/4 LOAD	READINGS		
	BAND WIDTH @ LOAD	<u>NEG</u>	<u>NEG</u>
	NO LOAD	<u>NEG</u>	<u>NEG</u>
	REGULATION	<u>0.</u>	<u>.83%</u>
	UNLOAD OVERSHOOT	<u>0</u>	<u>0</u>
	RECOVERY TIME	<u>0</u>	<u>0</u>
	LOAD UNDERSHOOT	<u>0</u>	<u>0</u>
FULL LOAD	RECOVERY TIME	<u>0</u>	<u>0</u>
	READINGS		
	BAND WIDTH @ LOAD	<u>NEG.</u>	<u>NEG.</u>
	NO LOAD	<u>.10%</u>	<u>NEG.</u>
	REGULATION	<u>.15%</u>	<u>(2.58%)</u>
	UNLOAD OVERSHOOT	<u>(6.80%)</u>	<u>3.33%</u>
	RECOVERY TIME	<u>(6.12 SEC)</u>	<u>.30 SEC</u>
	LOAD UNDERSHOOT	<u>1.10%</u>	<u>2.25%</u>
	RECOVERY TIME	<u>(1.98 SEC)</u>	<u>.33 SEC.</u>

ADDENDUM B

125°F CONDITIONS

Page 7

607.2 LONG TERM FREQUENCY AND VOLTAGE STABILITY TEST

SHORT TERM-NO LOAD

$$\text{TRACE WIDTH} \approx .015 \text{ WIDE OR } \frac{.015}{.445} \times 10 = .34 \text{ VOLTS}$$

$$* \text{ MIN SHORT TERM} = 120 \text{ V} + \frac{.220}{.445} \cdot 10 = 124.94 \text{ V}$$

$$** \text{ MAX SHORT TERM} = 120 \text{ V} + \frac{.240}{.445} \cdot 10 = 125.37 \text{ V}$$

$$\text{DIFF} = .45 \text{ V}$$

$$- \text{TRACE WIDTH } .34 \text{ V}$$

$$\boxed{\text{BANDWIDTH} = .12 \text{ V}}$$

$$= .10\%$$

- * AT BOTTOM OF TRACE
- ** AT TOP OF TRACE

LONG TERM-NO LOAD

$$* \text{ MIN LONG TERM} = 120 \text{ V} + \frac{.220}{.445} \cdot 10 = 124.94 \text{ V}$$

$$** \text{ MAX LONG TERM} = 120 \text{ V} + \frac{.260}{.445} \cdot 10 = 125.84 \text{ V}$$

$$\text{DIFF} = .90 \text{ V}$$

$$- \text{TRACE WIDTH } .34 \text{ V}$$

$$\boxed{\text{BANDWIDTH} = .56 \text{ V}}$$

$$= .47\%$$

SHORT TERM-LOADED

$$* \text{ MIN SHORT TERM} = 120 + \frac{.075}{.445} \cdot 10 = 121.69 \text{ V}$$

$$** \text{ MAX SHORT TERM} = 120 + \frac{.100}{.445} \cdot 10 = 122.25 \text{ V}$$

$$\text{DIFF} = .56 \text{ V}$$

$$- \text{TRACE WIDTH } .34 \text{ V}$$

$$\boxed{\text{BANDWIDTH} = .22 \text{ V}}$$

$$= .18\%$$

LONG TERM-LOADED

$$* \text{ MIN LONG TERM} = 120 + \frac{.075}{.445} \cdot 10 = 121.69 \text{ V}$$

$$** \text{ MAX LONG TERM} = 120 + \frac{.105}{.445} \cdot 10 = 122.36 \text{ V}$$

$$\text{DIFF} = 0.67 \text{ V}$$

$$- \text{TRACE WIDTH } .34 \text{ V}$$

$$\boxed{\text{BANDWIDTH} = .33 \text{ V}}$$

$$= .28\%$$

ADDENDUM B

Page 8

125 °F CONDITIONS

VOLTAGE DIP DURING FULL LOAD APPLICATION

V_{NL} - No Load Voltage BEFORE Loading.

V_R - RATED VOLTAGE

V_L - LOADED VOLTAGE AFTER LOADING

D - MIN PEAK-PEAK AMPLITUDE DURING TRANSIENT

L - AMPLITUDE - STABILIZED, LOADED

$V_D = D \cdot V_L / L$

$V_D\% = (V_{NL} - V_D) \cdot 100. / V_R$

MEMO SECTION

	5	7	9	AVG.	LIMITS
V_{NL}	122.3	122.3	122.3	122.3	
V_R	120.	120.	120.	120.0	
V_L	122.0	122.0	122.0	122.0	
D	2.59	2.62	2.62	2.61	
L	2.93	2.95	2.94	2.94	
V_D	107.84	108.35	108.72	108.30	
% V_D	12.05%	11.62%	11.32%	11.66%	15%
RECOVERY TIME	.0675SEC	.0588SEC	.0563SEC	.0609SEC	35SEC

VOLTAGE RISE DURING FULL LOAD DUMP

V_{NL} - No Load Voltage AFTER TRANSIENT

V_R - RATED VOLTAGE

V_L - LOADED VOLTAGE BEFORE TRANSIENT

R - MAX PEAK-PEAK AMPLITUDE DURING TRANSIENT

NL - AMPLITUDE - STABILIZED, NO LOAD.

MEMO SECTNN

	4	6	8	AVG	
V_{NL}	122.3	122.4	122.3	122.33	
V_R	120.	120.	120	120.0	
V_L	122.0	122.0	122.0	122.0	
R	3.37	3.36	3.35	3.36	
NL	2.97	2.94	2.95	2.953	
V_{RISE}	138.77	139.89	139.88	139.18	
% V_{RISE}	+13.98%	14.90%	14.07%	14.32%	15%
RECOVERY TIME	.0915SEC	.0925SEC	.0925SEC	.0920SEC	35SEC

$V_{RISE} = (R \cdot V_{NL}) / NL$

% $V_{RISE} = (V_{RISE} - V_L) \cdot 100 / V_R$

(511.1)

ADDENDUM C

Page 1

REGULATOR RANGE TEST AT 5000 FT, 107°F. LIMIT 1% (PD 3.5.5).

208 V

$$TI \text{ RESULTS} = \frac{122.0 - 119.5}{1195} = 2.09\%$$

$$MASTER \text{ DATA} = \frac{122.6 - 122.0}{1.220} = 0.49\%$$

219 V

$$TI \text{ RESULTS} = \frac{128.0 - 125.8}{1.258} = 1.75\%$$

$$MASTER \text{ DATA} = \frac{127.9 - 127.0}{1.270} = 0.71\%$$

242 V

$$TI \text{ RESULTS} = \frac{141.2 - 139.0}{1.390} = 1.58\%$$

$$MASTER \text{ DATA} = \frac{140.8 - 140.4}{1.404} = 0.28\%$$

197 V

$$TI \text{ RESULTS} = \frac{115.3 - 112.6}{1.126} = 2.40\%$$

$$MASTER \text{ DATA} = \frac{115.9 - 115.6}{1.156} = 0.26\%$$

183 V

MIN VOLTAGE 105.4 VOLTS (TI)

182.6

106.7 VOLTS (MASTER)

ADDENDUM C

5000 FT, 107°F

Page 2

17 608.1 FREQUENCY AND VOLTAGE REGULATION STABILITY

(SHORT TERM) AND TRANSIENT RESPONSE (MAX VALUES)

* NEGLIGIBLE

		<u>FREQUENCY</u>	<u>VOLTAGE</u>
LIMITS	BAND WIDTH @ LOAD	<u>.5%</u>	<u>1%</u>
	NO LOAD	<u>.5%</u>	<u>1%</u>
	REGULATION	<u>.5%</u>	<u>1%</u>
	UNLOAD OVERSHOOT	<u>1.5%</u>	<u>15%</u>
	RECOVERY TIME	<u>1 SEC</u>	<u>.35 SEC</u>
	LOAD UNDERSHOOT	<u>1.5%</u>	<u>15%</u>
	RECOVERY TIME	<u>1 SEC</u>	<u>.35 SEC</u>
<u>FULL LOAD RDGS</u>			
	BAND WIDTH @ LOAD	<u>* NEG</u>	<u>NEG</u>
	NO LOAD	<u>NEG</u>	<u>NEG</u>
	REGULATION	<u>.125%</u>	<u>(2.0%)</u>
	UNLOAD OVERSHOOT	<u>(9.5%)</u>	<u>3.33%</u>
	RECOVERY TIME	<u>(8.64 SEC)</u>	<u>.30 SEC</u>
	LOAD UNDERSHOOT	<u>.87%</u>	<u>2.58%</u>
	RECOVERY TIME	<u>(1.62 SEC)</u>	<u>.15 SEC</u>
<u>3/4 LOAD READINGS</u>			
	BAND WIDTH @ LOAD	<u>NEG</u>	<u>NEG</u>
	NO LOAD	<u>.075%</u>	<u>NEG</u>
	REGULATION	<u>.05%</u>	<u>(1.75%)</u>
	UNLOAD OVERSHOOT	<u>(4.21%)</u>	<u>1.67%</u>
	RECOVERY TIME	<u>(4.95 SEC)</u>	<u>.27 SEC</u>
	LOAD UNDERSHOOT	<u>.35%</u>	<u>.67%</u>
	RECOVERY TIME	<u>.60 SEC</u>	<u>.12 SEC</u>
<u>1/2 LOAD READINGS</u>			
	BAND WIDTH @ LOAD	<u>NEG</u>	<u>NEG</u>
	NO LOAD	<u>NEG</u>	<u>NEG</u>
	REGULATION	<u>NEG</u>	<u>(1.50%)</u>
	UNLOAD OVERSHOOT	<u>.59%</u>	<u>NEG</u>
	RECOVERY TIME	<u>(1.35 SEC)</u>	<u>NEG</u>
	LOAD UNDERSHOOT	<u>.125%</u>	<u>NEG</u>
	RECOVERY TIME	<u>.09 SEC</u>	<u>NEG</u>

ADDENDUM C 5000 FT, 107°F

Page 3

17 (CONT) 608.1

FREQUENCY AND VOLTAGE REGULATION, STABILITY
(SHORT TERM) AND TRANSIENT RESPONSE (MAX VALUES)

FREQUENCY VOLTAGE

1/4 LOAD

READINGS —

BAND WIDTH @ LOAD

NO LOAD

REGULATION

UNLOAD OVERSHOOT

RECOVERY TIME

LOAD UNDERSHOOT

RECOVERY TIME

FULL LOAD

READINGS —

BAND WIDTH @ LOAD

NO LOAD

REGULATION

UNLOAD OVERSHOOT

RECOVERY TIME

LOAD UNDERSHOOT

RECOVERY TIME

* NEG

NEG

NEG

.83%

NEG

—

—

—

NEG

NEG.

.05%

NEG.

.075%

(1.92%)

(8.38%)

3.0%

(8.40 SEC)

(.42 SEC)

.875%

2.5%

(1.65 SEC)

.30 SEC

* NEGLIGIBLE

ADDENDUM C

5000 FT, 107°F

Page 4

27

513.1

PANEL INSTRUMENTATION

		INSTRUMENT ERROR			
		388 Hz	400 Hz	412 Hz	LIMIT
ZERO LOAD -	KW	+7	+7	+7	—
FREQUENCY		0	-3	0	±3 Hz
VOLTAGE 1-2		-0.2	-0.2	-0.2	±1.56V
2-3		-0.2	-0.2	-0.3	±1.56V
3-1		-0.4	-0.3	-0.4	±1.56V
CURRENT 1		+1	+1	+1	±10.4A
2		+1	+2	+1	±10.4A
3		+1	+1	+1	±10.4A
25% LOAD - KW		+8.5	+8	+7.6	—
FREQUENCY		0	0	0	±3 Hz
VOLTAGE 1-2		0	+0.1	+0.1	±1.56V
2-3		-0.1	0	-1.0	±1.56V
3-1		-1.3	-1.3	-1.3	±1.56V
CURRENT 1		-0.9	-1.2	-0.7	±10.4A
2		+1.1	+0.2	+2.1	±10.4A
3		-0.4	-0.7	-1.1	±10.4A
50% LOAD - KW		+3	+3.9	+5	—
FREQUENCY		+1	+1	+1	±3 Hz
VOLTAGE 1-2		+0.4	+0.4	+0.1	±1.56V
2-3		+0.9	+0.7	+0.7	±1.56V
3-1		-1.4	-1.4	-1.4	±1.56V
CURRENT 1		-1.6	-0.5	-0.8	±10.4A
2		+2.7	+3.2	+4.1	±10.4A
3		-0.3	+0.7	+1.2	±10.4A

ADDENDUM C

Page 5

5000 FT 107°F

75% LOAD-KW

INSTRUMENT ERROR			
	@388 Hz	@400 Hz	@412 Hz
LIMIT			
+7.8	+8.2	+9.7	—
FREQUENCY	+1	+1	0
VOLTAGE 1-2	-1.8	+0.1	0
2-3	+1.3	+1.4	+1.4
3-1	-2.4	-2.3	-2.6
CURRENT 1	-2.1	-2.2	-2.1
2	+4.3	+4.7	+3.1
3	-1.6	-1.3	+0.3
100% LOAD-KW		-4.8	+4.1
FREQUENCY		+1	0
VOLTAGE 1-2		-0.8	-0.7
2-3		+1.8	+1.7
3-1		-2.3	-2.1
CURRENT 1		-4.9	-4.2
2		+5.2	+5.3
3		-0.7	-2.0

100% LOAD-KW

FREQUENCY

VOLTAGE 1-2

2-3

3-1

CURRENT 1

2

3

ADDENDUM D 8000 FT, 95°F

Page 1

27

513.1

PANEL INSTRUMENTATION

		INSTRUMENT ERROR			
		@ 388 Hz	@ 400 Hz	@ 412 Hz	LIMIT
ZERO LOAD -	KW	+ 2	+ 1	+ 2	—
FREQUENCY		0	- 1	- 1	± 3 Hz
VOLTAGE 1-2		- 0.5	- 0.5	+ 0.4	± 1.56V
2-3		- 0.6	- 0.5	- 0.5	± 1.56V
3-1		- 0.7	- 0.7	- 0.8	± 1.56V
CURRENT 1		+ 2	+ 1	+ 1	± 10.4A
2		+ 1	+ 1	+ 1	± 10.4A
3		+ 1	+ 1	+ 1	± 10.4A
25% LOAD - KW		+ 5.3	+ 4.4	+ 5.5	—
FREQUENCY		0	0	- 1	± 3 Hz
VOLTAGE 1-2		- 0.2	- 0.2	- 0.2	± 1.56V
2-3		- 0.3	- 0.3	- 0.4	± 1.56V
3-1		- 0.7	- 0.6	- 0.6	± 1.56V
CURRENT 1		- 0.8	- 1.1	- 0.7	± 10.4A
2		+ 1.9	+ 2	+ 1.8	± 10.4A
3		+ 1.2	0	0	± 10.4A
50% LOAD - KW		+ 6.2	+ 4.9	+ 6	—
FREQUENCY		0	0	- 1	± 3 Hz
VOLTAGE 1-2		+ 0.2	+ 0.2	+ 0.3	± 1.56V
2-3		+ 0.8	+ 0.8	+ 0.9	± 1.56V
3-1		- 1.7	- 1.3	- 0.8	± 1.56V
CURRENT 1		- 0.9	- 1	- 1.1	± 10.4A
2		+ 2.6	+ 3	+ 3	± 10.4A
3		- 0.2	- 0.5	- 0.1	± 10.4A

ADDENDUM D

Page 2

8000 Ft. 95°F

		INSTRUMENT ERROR			LIMIT
		@385 Hz	@400 Hz	@412 Hz	
75% LOAD-KW		+7.4	+7.2	+6.9	—
FREQUENCY		0	0	0	±3 Hz
VOLTAGE	1-2	-0.5	+0.1	-0.3	±1.56 V
	2-3	+0.9	+1.1	+1.2	±1.56 V
	3-1	-2.5	-2.3	-2.8	±1.56 V
CURRENT	1	-2.2	-3.3	-2.5	±10.4 A
	2	+3.8	-4.1	+3.8	±10.4 A
	3	-0.8	-0.4	-1.4	±10.4 A
100% LOAD-KW			+6	+6.4	—
FREQUENCY			0	0	±3 Hz
VOLTAGE	1-2		-0.3	-0.2	±1.56 V
	2-3		+2.5	+2.6	±1.56 V
	3-1		-2.7	-3.2	±1.56 V
CURRENT	1		-3.4	-2.8	±10.4 A
	2		+3.6	+3.4	±10.4 A
	3		-2.0	-1.0	±10.4 A

ADDENDUM D

Page 3

(511.1) REGULATOR RANGE TEST AT 8000 FT, 95°F
RDS 390 - 403
LIMIT - 1% (PD. 3.5.5)

208V TI RESULTS = $\frac{123.8 - 121.5}{1.215} = 1.89\%$

MASTER DATA = $\frac{122.3 - 122.0}{1.22} = 0.16\%$

219V TI RESULTS = $\frac{129.7 - 127.4}{1.274} = 1.81\%$

MASTER DATA = $\frac{127.6 - 127.2}{1.272} = 0.31\%$

242V TI RESULTS = $\frac{143.5 - 141.3}{1.413} = 1.56\%$

MASTER DATA = $\frac{141.0 - 140.7}{1.407} = 0.21\%$

197V TI RESULTS = $\frac{117.3 - 114.8}{1.148} = 2.18\%$

MASTER DATA = $\frac{115.7 - 115.3}{1.153} = 0.35\%$

MIN VOLTAGE TI OBSERVED (C-N) = 107.5V
MASTER " (C-N) = 106.7V.

ADDENDUM D 8000 FT ALT, 95°F

Page 4

17

608.1

FREQUENCY AND VOLTAGE REGULATION STABILITY

(SHORT TERM) AND TRANSIENT RESPONSE (MAX VALUES)

LIMITS		FREQUENCY VOLTAGE	
* NEGLIGIBLE	BAND WIDTH @ LOAD	.5%	1%
	NO LOAD	.5%	1%
	REGULATION	.5%	1%
	UNLOAD OVERSHOOT	1.5%	15%
	RECOVERY TIME	1 SEC	.35 SEC
	LOAD UNDERSHOOT	1.5%	15%
	RECOVERY TIME	1 SEC	.35 SEC
	FULL LOAD RDGS		
	(130KW) BAND WIDTH @ LOAD	*NEG	NEG
	NO LOAD	.05%	NEG
	REGULATION	12.5%	3.58%
	UNLOAD OVERSHOOT	11.0%	3.58%
	RECOVERY TIME	11.16 SEC	.275 SEC
	LOAD UNDERSHOOT	.625%	1.92%
	RECOVERY TIME	.90 SEC	.24 SEC
3/4 LOAD READINGS			
	(112KW) BAND WIDTH @ LOAD	NEG	NEG
	NO LOAD	.088%	NEG
	REGULATION	.05%	1.83%
	UNLOAD OVERSHOOT	6.38%	.75%
	RECOVERY TIME	7.50 SEC	.09 SEC
	LOAD UNDERSHOOT	.250%	1.00%
	RECOVERY TIME	.15 SEC	NEG
1/2 LOAD READINGS			
	(75KW) BAND WIDTH @ LOAD	NEG	NEG
	NO LOAD	NEG	NEG
	REGULATION	NEG	.79%
	UNLOAD OVERSHOOT	.93%	NEG
	RECOVERY TIME	2.67 SEC	NEG
	LOAD UNDERSHOOT	NEG	NEG
	RECOVERY TIME	NEG	NEG

ADDENDUM D

8000 FT ALT., 95°F

Page 5

17 (CONT) 608.1

FREQUENCY AND VOLTAGE REGULATION, STABILITY
(SHORT TERM) AND TRANSIENT RESPONSE (MAX VALUES)

FREQUENCY VOLTAGE

1/4 LOAD
(112 KW)

READINGS —

BAND WIDTH @ LOAD

NEG.

NEG.

NO LOAD

NEG.

NEG.

REGULATION

—

.5%

UNLOAD OVERSHOOT

—

NEG.

RECOVERY TIME

—

—

LOAD UNDERSHOOT

—

—

RECOVERY TIME

↓

↓

FULL LOAD
(138 KW)

READINGS —

BAND WIDTH @ LOAD

NEG.

.33%

NO LOAD

.07%

NEG.

REGULATION

.112%

(1.83%)

UNLOAD OVERSHOOT

(10.75%)

3.00%

RECOVERY TIME

(10.50 SEC)

.24 SEC

LOAD UNDERSHOOT

.625%

1.83%

RECOVERY TIME

.84 SEC

.30 SEC



Detroit Diesel Allison
Division of General Motors Corporation

AD5210-00006

TITLE <u>ENG T3 ACCEPT TEST</u>		CURVE NO. _____
<u>100% LOCK-UP</u>		
PREPARED BY _____	DATE _____	TEST DATE _____
DEPARTMENT _____		


VIBRATION SIGNATURE

ENG. S/N T3 BU 8 TEST STAND 887

DATE 9-17-79 TIME _____

VIBRATION METER READING .14 PICKUP LOCATION FRT VERTICAL

N₁ 36830 RPM N₂ 3000 RPM



AD 5210-00006



Detroit Diesel Allison
Division of General Motors Corporation

AD5210-00007

TITLE <u>ENG T3 ACURPT TEST</u>		CURVE NO. _____
<u>100% LOCK-UP</u>		
PREPARED BY _____	DATE _____	TEST DATE _____
DEPARTMENT _____		


VIBRATION SIGNATURE

ENG. S/N T3 BU 8 TEST STAND 887

DATE 9/17/79 TIME _____

VIBRATION METER READING 11-12 PICKUP LOCATION FRT LATERAL

N₁ 36830 RPM N₂ 3000 RPM



AD5210-00007



Detroit Diesel Allison
Division of General Motors Corporation

AD5210-00008

TITLE <u>ENG T3 ACCEPT TEST</u>		CURVE NO _____
<u>100% LOCK-UP</u>		
PREPARED BY _____	DATE _____	TEST DATE _____
DEPARTMENT _____		


VIBRATION SIGNATURE

ENG. S/N T3 BU 8 TEST STAND 887

DATE 9/17/79 TIME 2340

VIBRATION METER READING .27-.29 PICKUP LOCATION REAR LATERAL


N₁ 36830 RPM N₂ 3000 RPM



AD 5210-00008

~~BY AND THEIR ATTENDED CONDITIONS~~

C	39.1 VOLTS	NO LOAD
F	28.1 VOLTS	NO LOAD
A	25.9 VOLTS	NO LOAD




AD5210-00010

BATTERY CHARGING TEST
GENSET MODEL D4045003, SEE HQ ORDER 03
BUILD UP #4, JULY 9, 1979
AT NORMAL AMBIENT CONDITIONS

LEGEND:

- O 30.0 VOLTS - NO LOAD
- 28.0 VOLTS - NO LOAD
- △ 27 VOLTS - NO LOAD



WILLIAMS
 NATIONAL TRACING PAPER
 INDIANAPOLIS, INDIANA

2301 THIS IS 10.0 V, INCH
 LINE IN U.S.A.

AD5210-00010

AD5210-00011

BATTERY CHARGING TEST


MODEL 6403 603 GEN SET 510000007

BUILD UP # 4, JULY 17, 1979

125°F, AMBIENT PRESSURE

WILLIAMS
NATIONAL ENGINEERING
INDIANAPOLIS, INDIANA

2301 THIS TUBE 10.5 INCH
11 INCH IN U.S.A.



AD5210-00011

HD 5210-00012


60°F AT TEST

MODEL Q4045803 GENERATOR SET S/N 00000003

TEST STAND 873 TEST DATE 7/18/79, R065 294-311

WILLOW TRADING PAPER
NATION
INDIANAPOLIS, INDIANA

200 THIS USED 10-INCH
LITHO IN U.S.A.



HD 5210-00012

AD5210-00013


60°F AT TEST

MODEL QUARTZ ROT GENERATOR SET S/N 0000003

TEST STAND 573 TEST DATE 1/15/55, RUGS 194-511

WILLIAMSON
NATIONAL IMAGING PAPER
INDIANAPOLIS, INDIANA


2401 1945 INKED 101. INCH
11110 IN U.S.A.



AD5210-00013


1/15/55

AD 5210-00014




AD 5210-00014






ENVIRONMENTAL TEST GENERATOR SET, SIN 0000003

350363




ENVIRONMENTAL TEST GENERATOR SET, SN 0000003.

350364



ENVIRONMENTAL TEST GENERATOR SET, SN 0000003.

350365




ENVIRONMENTAL TEST GENERATOR SET, SIN 00000003.

350366




ENVIRONMENTAL TEST GENERATOR SET, SN 0000003.

350367




350368

ENVIRONMENTAL TEST GENERATOR SET, SIN 0000003.




ENVIRONMENTAL TEST GENERATOR SET, SIN 0000003.

350369



OF THE A. S. S. C. I.




-50°F COLD TEST BRG. FAILURE, GEN. SET #3, ENG. T3, B.U. 7.


351421




-50°F COLD TEST BRG. FAILURE, GEN. SET #3, ENG. T3, B.U. 7. 351422



-50°F COLD TEST BRG. FAILURE, GEN. SET #3, ENG. T3, B.U. 7. 351423




-50°F COLD TEST BRG. FAILURE, GEN. SET #3, ENG. T3, B.U. 7 351424



-50°F COLD TEST BRG. FAILURE, GEN. SET #3, ENG. T3, B.U. 7. 351425




-50°F COLD TEST BRG. FAILURE, GEN. SET #3, ENG. T3, B.U. 7. 351426




-50°F COLD TEST BRG. FAILURE, GEN. SET #3, ENG. T3, B.U. 7. 351427





-50°F COLD TEST BRG. FAILURE, GEN. SET #3, ENG. T3, B.U. 7 351428



-50°F COLD TEST BRG. FAILURE, GEN. SET #3, ENG. T3, B. U. 7. 351429




-50°F COLD TEST BRG. FAILURE, GEN. SET #3, ENG. T3, B. U. 7. 351430




-50°F COLD TEST BRG. FAILURE. GEN. SET #3, ENG. T3, B.U. 7.

351431



-50°F COLD TEST BRG. FAILURE, GEN. SET #3, ENG. T3, B.U. 7.

351432




-50°F COLD TEST BRG. FAILURE, GEN. SET #3, ENG. T3, B.U. 7.

351433



-50°F COLD TEST BRG. FAILURE, GEN. SET #3, ENG. T3, B.U. 7.

351434



-50°F COLD TEST BRG. FAILURE, GEN. SET #3, ENG. T3, B.U. 7.

351435

AD-A086 035

GENERAL MOTORS CORP INDIANAPOLIS IN DETROIT DIESEL A--ETC F/8 10/2
ENVIRONMENTAL AND COLD TESTS ON MODEL 04045803 GENERATOR SET SE--ETC(U)
NOV 79 H E GASTON
DDA-79087
DAAK70-78-C-0125
NL

UNCLASSIFIED

2 - 2

NOV 79




END

DATE


FILMED

8 80

DTIC





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS 1963 A





-50°F COLD TEST BRG. FAILURE, GEN. SET #3, ENG. T3, B.U. 7.

351436




-50°F COLD TEST BRG. FAILURE, GEN. SET #3, ENG. T3, B.U. 7.

351437



-50°F COLD TEST BRG. FAILURE, GEN. SET #3, ENG. T3, B.U. 7.

351438



-50°F COLD TEST BRG. FAILURE, GEN. SET #3, ENG. T3, B.U. 7.

351439

-50°F COLD TEST BRG FAILURE, GEN SET #3, ENG T3, BU 7



351525

DATA
FILM

8-8