

LEVEL II

ATLANTIC COAST BASIN  
MUDDY RUN, SALEM COUNTY  
NEW JERSEY

ADA 087632

# CENTRETON LAKE DAM NJ 00439

PHASE 1 INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

ORIGINAL CONTAINS COLOR PLATES; ALL DDC  
REPRODUCTIONS WILL BE IN BLACK AND WHITE

DTIC  
ELECTE  
AUG 8 1980



APPROVED FOR PUBLIC RELEASE  
DISTRIBUTION UNLIMITED.

DEPARTMENT OF THE ARMY

Philadelphia District  
Corps of Engineers  
Philadelphia, Pennsylvania

MARCH 1980  
APPROVED FOR PUBLIC RELEASE;

DDC FILE COPY

DISTRIBUTION UNLIMITED

80 8 7 037





DEPARTMENT OF THE ARMY  
 PHILADELPHIA DISTRICT, CORPS OF ENGINEERS  
 CUSTOM HOUSE-2 D & CHESTNUT STREETS  
 PHILADELPHIA, PENNSYLVANIA 19106

IN REPLY REFER TO  
 NAPEN-N

04 AUG 1980

Honorable Brendan T. Byrne  
 Governor of New Jersey  
 Trenton, New Jersey 08621

ACCESSION for	
NTIS	White Section <input checked="" type="checkbox"/>
DDC	Buff Section <input type="checkbox"/>
UNANNOUNCED	<input type="checkbox"/>
JUSTIFICATION	
BY	
DISTRIBUTION/AVAILABILITY CODES	
Dist.	AVAIL. SPC/AL
A	

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for Centreton Lake Dam in Salem County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Centreton Lake Dam, initially listed as a "high" hazard potential structure, but reduced to a "significant" hazard potential structure as a result of this inspection, is judged to be in good overall condition. The dam's spillway is considered inadequate because a flow equivalent to 25 percent of the Spillway Design Flood - SDF - would cause the dam to be overtopped. (The SDF, in this instance, is one half of the Probable Maximum Flood). To ensure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Within six months of the consultant's findings, remedial measures to ensure spillway adequacy should be initiated.

b. Within one year from the date of approval of this report, the following remedial measures should be completed:

(1) The upstream and downstream slopes of the dam embankment in the vicinity of the spillway wingwalls should be regraded, compacted and topped with suitable slope paving or stone riprap.

(2) Dead trees and underbrush should be removed from the backslopes and the disturbed areas regraded, compacted and seeded.

(3) The downstream stilling basin should be filled in with heavy stone at the edge of the timber splash apron to prevent continual scouring and preclude the undermining of the spillway structure.

- NAPEN-N  
Honorable Brendan T. Byrne

(4) Clean up the fallen trees and timber drift in the river channel south of the highway bridge.

(5) Replace the rotted timbers in the spillway superstructure.

c. The owner should develop an emergency action plan and downstream warning system within six months from the date of approval of this report.

d. The owner should develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam within one year from the date of approval of this report.


A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressman Hughes of the Second District. Under the provision of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, five days after the date of this letter.

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.

An important aspect of the Dam Inspection Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely,

1 Incl  
As stated

  
JAMES G. TON  
Colonel, Corps of Engineers  
District Engineer

Copies furnished:  
Mr. Dirk C. Hofman, P.E., Deputy Director  
Division of Water Resources  
N.J. Dept. of Environmental Protection  
P.O. Box CNO29  
Trenton, NJ 08625

Mr. John O'Dowd, Acting Chief  
Bureau of Flood Plain Regulation  
Division of Water Resources  
N.J. Dept. of Environmental Protection  
P.O. Box CNO29  
Trenton, NJ 08625

CENTRETON LAKE DAM (NJ00439)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 4 December 1979 by Louis Berger and Associates, Inc. under contract to the State of New Jersey. The State, under agreement with the U.S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

Centreton Lake Dam, initially listed as a "high" hazard potential structure, but reduced to a "significant" hazard potential structure as a result of this inspection, is judged to be in good overall condition. The dam's spillway is considered inadequate because a flow equivalent to 25 percent of the Spillway Design Flood - SDF - would cause the dam to be overtopped. (The SDF, in this instance, is one half of the Probable Maximum Flood). To ensure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Within six months of the consultant's findings, remedial measures to ensure spillway adequacy should be initiated.

b. Within one year from the date of approval of this report, the following remedial measures should be completed:

(1) The upstream and downstream slopes of the dam embankment in the vicinity of the spillway wingwalls should be regraded, compacted and topped with suitable slope paving or stone riprap.

(2) Dead trees and underbrush should be removed from the backslopes and the disturbed areas regraded, compacted and seeded.

(3) The downstream stilling basin should be filled in with heavy stone at the edge of the timber splash apron to prevent continual scouring and preclude the undermining of the spillway structure.

(4) Clean up the fallen trees and timber drift in the river channel south of the highway bridge.

(5) Replace the rotted timbers in the spillway superstructure.

c. The owner should develop an emergency action plan and downstream warning system within six months from the date of approval of this report.

d. The owner should develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam within one year from the date of approval of this report.

APPROVED:

*James G. Ton*  
JAMES G. TON  
Colonel, Corps of Engineers  
District Engineer

DATE:

*17 July 80*

(6) National Dam Safety Program, Contractor,  
Lake Dam (NJ 88439), Atlantic Coast Basin,  
Muddy Run Tributary of Maurice Rivers  
Salem County, New Jersey  
Phase I Inspection Report.

(11) *Mar 80*

(10) *Rudolph/Wright*

(9) *Final Report*

(12) *57*

(13) *LA W 61-41-3-1044*

710871

*AK*

PHASE I REPORT  
NATIONAL DAM INSPECTION PROGRAM


Name of Dam: Centreton Lake Dam Fed ID# NJ00434,  
NJ ID# 466 (35-3)

State Located New Jersey  
County Located Salem  
Coordinates Lat. 3931.5 - Long. 7510.2  
Stream Muddy Run Tributary of Maurice River  
Date of Inspection 4 December 1979

ASSESSMENT OF  
GENERAL CONDITIONS

Centreton Lake Dam is assessed to be in a fair overall condition and is recommended to be downgraded to a significant hazard category. No detrimental findings were uncovered to jeopardize the structural stability. Remedial actions to be undertaken in the future consist of regrading and protecting the embankment sideslopes from erosion, removing dead trees and underbrush roots, refilling the stilling basin below the splash apron, clearing the downstream channel and replacing the rotted timbers in the spillway.

The dam has an inadequate spillway, being able to accomodate 24% of the 1/2 PMF design storm. Hence, further hydraulic studies are recommended to be undertaken in the future.

  
\_\_\_\_\_  
Rudolph Wrübel  
Vice President  
Louis Berger & Associates, Inc.



OVERVIEW OF CENTRETON LAKE DAM

December, 1979

## TABLE OF CONTENTS

	<u>Page</u>
Assessment of General Conditions	
Overall View of Dam	
Table of Contents	
Preface	
Section 1 - Project Information	1-4
Section 2 - Engineering Data	5-6
Section 3 - Visual Inspection	7-8
Section 4 - Operational Procedures	9
Section 5 - Hydraulic/Hydrologic	10-11
Section 6 - Structural Stability	12-13
Section 7 - Assesment/Recommendations/Remedial Measures	14-15

## FIGURES

- Figure 1 - Regional Vicinity Map
- Figure 2 - General Plan
- Figure 3 - Spillway Details

## APPENDIX

Check List - Visual Inspection	
Check List - Engineering Data	
Photographs	
Check List - Hydrologic and Hydraulic Data Computations	A1-A15

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM  
NAME OF DAM: CENTRETON LAKE DAM FED #NJ00434

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

a. Authority

This report is authorized by the Dam Inspection Act, Public Law 92-367, and has been prepared in accordance with Contract FPM-36 between Louis Berger & Associates, Inc. and the State of New Jersey and its Department of Environmental Protection, Division of Water Resources. The State, in turn, is under agreement with the U.S. Army Engineer District, Philadelphia to have this inspection performed.

b. Purpose of Inspection

The purpose of this inspection is to evaluate the structural and hydraulic condition of the Centreton Lake Dam and appurtenant structures, and to determine if the dam constitutes a hazard to human life or property.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam and Appurtenances

The dam consists of a low irregular earth embankment with a maximum height of twelve feet and length of approximately 1500 feet. A 12-gated timber spillway is located within the 640 foot central portion which actually dikes off the southerly end of the natural flood plain. The timber gates are operable and each is 3'-8" wide. There is an ill-defined auxiliary overflow spillway positioned above the left abutment zone which discharges into a lagoon immediately below the center portion of the embankment. A timber bulkhead extends across most of the upstream face of the dam crest.

b. Location

Centreton Dam is located on the Muddy Run tributary of the Maurice River in Pittsgrove Township, Salem County, N.J. It lies just above the intersection of the Centreton-Bridgeton Road (Route 553) and the Deerfield Station Road (Route 540), west of the Centreton village center. The dam discharges into the headwaters of the Parvin State Park.

c. Size Classification

The maximum height of the dam is 12 feet and the maximum storage is estimated to be 576 acre-feet. Therefore, the dam is classified as small, as defined by the Corps of Engineers criteria (storage less than 1000 acre-feet and height less than 40 feet).

d. Hazard Classification

Based upon Corps of Engineers criteria, the hazard class is recommended to be downgraded to significant as in the event of failure, the only damage would be to the dam itself and possibly the heavily travelled Centreton-Bridgeton Road bridge and embankment which lies immediately downstream. Further, a few lives could be endangered should there be passing traffic. There are no homes in the downstream flood plain as most of the lands are within the Parvin State Park.

e. Ownership

The dam, or major portions thereof, are presently owned by the Centreton Lake Park Association, Inc., RD #1, Centreton, of which Mr. Ted Grouber is President and Mr. Rene Lanusse, the previous owner is a corporate stockholder.

f. Purpose of Dam

The impoundment is used solely for recreation although vestiges of an early millrace exist at the site. Further, the side channel spillway immediately below the center of the dam originally served as a fish breeding pond.

g. Design and Construction History

The original installation date of this structure is unknown as the first recorded documentation uncovered in State Water Policy records are a 1942 inspection. Archeological traces of an earlier millrace exist in the vicinity of the left abutment where an abandoned roadway culvert exists. The dam crest was originally at a lower elevation and was overtopped in September 1940 but did not fail. The timber-gated spillway collapsed in 1952 and was rebuilt in 1953 (under Dam Application No. 466) when the embankment crest was raised three feet and the present spillway installed. Division of Water Resources inspection in 1963 uncovered "bulging" in the timber apron but this problem was apparently remedied although as late as 1971, the Division had not been notified of the completion. However, the dam was inspected that year by the owner's Engineer who found it in satisfactory condition.

The name of the adjacent village is Centerton but the spelling of the dam name is recorded as both Centerton and Centreton and appears to be used interchangeably.

h. Normal Operating Procedures

See Section 4.

1.3 PERTINENT DATA

a. Drainage Area

The dam has a drainage area of 39.4 square miles which consists mainly of farm and woodland with some residential development.

b. Total combined spillway capacity - 1170 cfs.

c. Elevations (ft above MSL)

Top of dam	- 82.5
Recreation pool	- 79.0
Streambed at centerline of dam	- 71 ±

d. Reservoir

Length of maximum design pool	- 4000 ± feet
Length of recreation pool	- 3500 feet

- e. Storage (acre-feet)
  - Top of dam - 576
  - Recreation pool - 132
- f. Reservoir Surface (acres)
  - Top of dam - 216
  - Recreation pool - 37
- g. Dam
  - Type - Earth embankment with timber sluiceway and auxiliary spillway
  - Length - 1500 feet
  - Maximum Height - 12 feet
  - Top Width - Varies (8 - 20 feet)
  - Side Slopes - Varies (2 to 1H:1V) (vertical along bulkhead)
  - Zoning - Unknown
- h. Diversion and Regulating Tunnel - None
- i. Spillway
  - Type - timber narrow crested weir with 12 gates (3'-8"x6')
  - Crest Elevation - 79.0
  - U/S Channel - main lake reservoir
  - D/S Channel Width - 40 ± feet
  
  - Auxiliary spillway: 100 feet x 1.0 ± foot depression in west embankment.
- j. Regulating Outlets - removable stoplogs in main spillway.

## 2.1 DESIGN

The only information available for design review were microfilm drawings of Encroachment Application No. 466 prepared in 1953 by Mr. James S. Sparks, P.E. for the reconstruction of the main timber spillway. The spillway is founded on timber piles and protected from undercutting by wood sheeting on all sides. Work appears to have been carefully detailed.

As previously stated, the 1953 reconstruction replaced an earlier timber spillway at this location. The trapezoidal embankment was already in place. However, additional fill was placed on the sideslopes and crest which raised the crest height approximately three feet. No test boring data was available but this site is located in the southeastern part of Salem County and is within the outer zone of the Coastal Plain physiographic province. The most predominant surficial soils are comprised of alluvial silty and clayey sands and gravel of the Bridgeton Formation. In places these soils have been locally solidified by iron oxide. The solidified areas are generally present as a capping on the higher hills in the area. Stratified alluvial silts, silty sand and sandy silts of the Cape May, Pensauken and Bridgeton formation are also present at the surface near the southwest side of the lake. In the immediate vicinity, the surficial soils consist of recent alluvium that is mixed with and overlies swampy soils. This alluvium is comprised of sand and silt with some clay and gravel and often occurs as discontinuous intermingled layers.

## 2.2 CONSTRUCTION

No information is available regarding construction except that Division of Water Resources engineers monitored the installation and reported on its progress as being satisfactory.

## 2.3 OPERATION

The spillway operates as an uncontrolled weir (see Section 4) and the gates are periodically adjusted by members of the Park Association.

## 2.4 EVALUATION

### a. Availability

In view of the dam assessment and recommendations contained in Section 7, it is believed that sufficient engineering data is available for the following assessment without recourse to obtaining additional design data or the original contract plans.

### b. Adequacy

In view of the dam configuration and recommendations contained in Section 7, it is felt the field inspection provided adequate engineering data upon which to base a reliable evaluation of the dam's condition.

### c. Validity

The validity of the 1953 plans is not challenged.

## SECTION 3 - VISUAL INSPECTION

### 3.1 FINDINGS

#### a. General

The visual inspection was conducted on December 4, 1979 at which time the water level in the lake was producing a moderate flow through the gate at the far left of the spillway (which prevented close inspection of the spillway walls). The overall physical condition of the dam is fair but the embankment slopes appeared to be very irregular and poorly graded.

#### b. Dam

The main portion of the embankment is approximately 660 feet long; the remainder of the length being contiguous perimeter dikes along the low-lying sides of the reservoir. The slopes are very irregular and most of the lakeside crest is protected with an aged timber bulkhead. Judging from its condition, it was installed before the timber spillway. There are numerous live and dead trees on the crest and the embankment surface consists of coarse to fine sand with very little fines or cohesive material. The auxiliary spillway area is located on the dam crest near the left edge of the lake and discharges into an irregular side channel or lagoon which flows westward back into the main downstream channel. The older bridge/culvert (Salem County No. 1257) located immediately south of the auxiliary overflow is almost completely plugged up.

There are numerous sloughed areas and swales along the backslope zones and it appears nothing has been done to maintain the design slopes for many years.

Although the ground was partially frozen at the time of inspection, it appears that there may be a perched water table in the vicinity of the lagoon just below the dam. The exact cause could not be ascertained. Consequently, little evidence of seepage was observed. The average height of most of the embankment is between 6 and 8 feet with the perimeter dike zones being 2.5 to 3 feet high.

c. Appurtenant Structures

The timber spillway structure is in fair condition and well-maintained in view of its age. There are some rotted sections and individual members which should be replaced but all twelve gates appear operable. The head beam over the stop logs is solid as are the access walkway planking and painted railings. The fill behind the parallel downstream wingwalls is eroded away, exposing most of the 15 foot wings. The downstream apron is approximately two feet above the natural streambed but does not appear to be undercut. Three diagonal braces have been expediently installed above the downstream apron, apparently to brace the access walkway bridge.

d. Reservoir

Centreton Lake has stable, wooded natural banks that slope up gradually from the shoreline and are left in a natural state befitting the parkland environment. Heavy debris appears to have been removed as a continuing part of maintenance. However, nothing appears to have been done regarding the lake's siltation. It was noted that the Palatine Dam lies about one mile upstream and that the juncture of Muddy Run and Indian Run occurs at the reservoir headwaters. It appears the seasonal lake level during winter months is maintained about two feet below the normal recreation pool.

e. Downstream Channel

The downstream riverbed is fairly clear and straight after passing under County Bridge No. 1235 which is situated about 150 feet below the spillway. This two span bridge was built in 1944 and it appears that the bridge and roadway to the east are flooded during extreme heavy storms. A considerable stilling basin has been created between the spillway and bridge and eddy currents have contributed to the erosion behind the downstream wingwalls. Immediately below the bridge, Muddy Run flows into the undeveloped woodland environment of Parvin State Park.

## SECTION 4 - OPERATIONAL PROCEDURES

### 4.1 PROCEDURES

Operational procedures were not observed by the inspection team. Maintenance responsibility is undertaken by Mr. Rene Lanusse, the prior owner of record who is obligated under legal agreement with the N.J. Division of Water Policy and Supply to maintain the operation of the gates. As best as can be determined, this agreement, dated March 20, 1953, is still in effect, although part of the property has been sold to the present owner.

### 4.2 MAINTENANCE OF DAM

Except for the operational aspects of the spillway, there has apparently been little or no continual maintenance of the remaining structural aspects of the dam.

### 4.3 MAINTENANCE OF OPERATING FACILITIES

The stoplogs in the 12 gated sections are periodically raised and lowered by Mr. Lanusse or his authorized representatives. Overall maintenance is conducted each spring but appears to consist of a clean-up of drift and freeing the gates as required.

### 4.4 DESCRIPTION OF WARNING SYSTEM IN EFFECT

There is no formalized warning system in effect but because the road just below the spillway is quite heavily travelled, it appears local Municipal and County forces monitor the site during heavy storms.

### 4.5 EVALUATION OF OPERATIONAL ADEQUACY

Present safeguards are deemed to be adequate in view of performance record and the level of hazards relating to the dam. However, it is felt that the ownership responsibility of maintenance should be clarified in the future by state authorities in view of the agreement between the State and the prior owner. See Para. 7.2)

## SECTION 5 - HYDRAULIC/HYDROLOGIC

### 5.1 EVALUATION OF FEATURES

#### a. Design Data

Based on the criteria in the Recommended Guidelines for Safety Inspection of Dams, one-half the probable maximum flood (PMF) was selected as the design storm by the inspecting engineer. Precipitation data was obtained from Hydro-meteorological Report #33. The inflow hydrograph and reservoir routing were calculated utilizing the HEC-1 computer program. The discharge for the SDF was calculated to be 4898 cfs. The spillways have a maximum combined discharge capacity of approximately 1170 cfs before overtopping occurs and can therefore accommodate only 24% of the design flood.

#### b. Experience Data

Nothing was located regarding the past hydrologic history of the dam. It appears the spillway (especially with all flashboards in place) was not designed by any normally accepted engineering procedure to accommodate the design flow of the drainage area. The previous 1952 failure of the spillway occurred mainly due to deterioration and undermining of the foundation support.

#### c. Visual Observations

There are two dams (Lakes Elmer and Palantine) above and two below (Parvin and Rainbow) the study dam which have similar spillway capacities. Further it was estimated that in extreme floods, the roadway below the dam could be overtopped and although not damaged, would be closed to traffic.

#### d. Overtopping Potential

There are no indications that the dam has been recently overtopped and records indicate that the 1940 overtopping did little damage. However, the overtopping potential continues to exist as the appended calculations indicate that the dam would be overtopped by approximately 1 foot during the the design storm. Such a flood would almost certainly overtop the adjacent road and much of the surrounding property.

e. Drawdown Potential

Using all the stoplog gates, the reservoir could theoretically be drawn down the full height of gates in approximately three hours.

## SECTION 6 - STRUCTURAL STABILITY

### 6.1 EVALUATION OF STRUCTURAL STABILITY

#### a. Visual Observations

The timber spillway contains elements which will require replacement within the next few years. All major members, especially those supporting the gates and beams are satisfactory but there is a possibility that there is hidden structural (internal) damage to the access walkway bridge. Also from the uniform high level of tailwater, the trailing edge of the outfall splash apron could not be observed and some concern was expressed (in view of the excess exit energy) that the timber sheeting may be undercut. This 3" T & G sheeting was installed untreated and is over 25 years old.

The timber bulkhead along the front edge of the dam crest is even older and in a more advanced stage of deterioration but its condition is of less concern regarding the overall dam safety, except where it frames into the wingwalls of the spillway. Excessive erosion has occurred here and the embankment should be replaced, especially in the vicinity of the earlier bulkheads around the stilling basin (these are completely demolished). Judging from the large size of trees on the embankment, this portion of the dam structure is exceedingly old and probably served as the river crossing prior to building the highway in the 1920's. Consequently, the lack of an impervious core and proper compaction make the spillway somewhat susceptible to hydrostatic pressures or dangerous piping action around the ends of the wingwalls. The remainder of the embankment is of less concern although there has been no engineering maintenance for many years.

#### b. Design and Construction Data

The review of the 1953 spillway plans reveal the design to be conservatively executed although no computations were available. The construction conforms closely to the design except for the diagonal braces which have been installed at the access bridge pile bents.

c. Operating Records

There are no formal records in existence although the spillway stoplogs are adjusted yearly to facilitate maintenance. It appears the lake is maintained at the normal recreation pool only during the summer months.

d. Post Construction Changes

Except for the braces mentioned previously, there have been no post-construction modifications since the 1953 reconstruction of the spillway.

e. Seismic Stability

The dam appears to have an adequate factor of safety against static loadings and experience indicates that it will therefore have adequate stability against Zone 1 dynamic loadings. The height of the embankment is so low it will have negligible vulnerability due to any type of loading.

SECTION 7 - ASSESSMENTS/RECOMMENDATIONS/  
REMEDIAL MEASURES

7.1 DAM ASSESSMENT

a. Safety

Subject to the inherent limitations of the Phase I visual inspection, the Centerton Lake Dam is classified as being in a sound and overall fair condition insofar as its embankment structure is concerned but the timber spillway is in need of selected repairs. No seriously detrimental findings were revealed in this inspection to render a questionable judgement as to the structural stability. The spillway is inadequate hydraulically, being able to accommodate only 24% of the selected design flood. The overtopping potential is considerable due to the hydraulically substandard spillway width and the ease with which the narrow sluiceway openings under the access bridge can be blocked with debris. There is little that can be done to increase the present spillway capacity without undertaking major reconstruction. It appears that the County Road 540 immediately below the dam can be frequently flooded by heavy storms. However, as there is only moderate downstream hazard to human life or property should the dam collapse, its hazard category is recommended to be downgraded to significant.

b. Adequacy of Information

The information gathered for the Phase I inspection is deemed to be adequate regarding the structural stability of the dam. However, no surveys or inspections have been recorded since 1971 and the dam has undergone deterioration since that time.

c. Urgency

No urgency is attached to implementing further studies in view of the dam hazard assessment. It is recommended that the remedial measures set forth below be taken under advisement in the future except that the backfilling of the spillway wingwalls should be undertaken this coming spring or summer.

d. Necessity for Further Study

Due to the significant hazard classification and the present spillway capacity, further engineering studies, under the purview of the P.L. 92-367, are believed to be necessary to ascertain more precisely the hydraulic conditions.

7.2 RECOMMENDATIONS/REMEDIAL MEASURES

It is recommended that the ownership and responsibility for maintenance be clarified especially regarding the legal agreement between the previous owner and the State of New Jersey.


a. Remedial Measures

- The upstream and downstream slopes of the dam embankment in the vicinity of the spillway wingwalls should be regraded, compacted and topped with suitable slope paving or stone riprap.
- Dead trees, underbrush, and dead roots should be removed from the backslopes and the disturbed areas regraded, compacted and seeded.
- The downstream stilling basin should be filled in with heavy stone at the edge of the timber splash apron to prevent continual scouring and preclude the undermining of the spillway structure.
- Although it is beyond the owner's property, it would be advisable to clean up the fallen trees and timber drift in the river channel south of the highway bridge.
- Replace the rotted timbers in the spillway superstructure.

b. O&M Maintenance and Procedures


In the near future the owner should develop written operating procedures and a periodic maintenance plan to insure the safety of the dam. In addition, an emergency action plan to minimize downstream effects of an emergency together with a warning system should be developed.





LOCATION PLAN  
NOT TO SCALE

FIGURE 2



UPSTREAM SPILLWAY ELEVATION  
 NOT TO SCALE

FIGURE 3

Check List  
Visual Inspection  
Phase 1

Name Dam Centerton Lake County Salem State New Jersey Coordinators NJDEP

Date(s) Inspection 12-4-79  
1-11-80 Weather Sunny Temperature 40° F

Pool Elevation at Time of Inspection 77± M.S.L. Tailwater at Time of Inspection 72<sup>+</sup> M.S.L.

Inspection Personnel:

<u>M. Carter</u>	<u>D. Lang</u>
<u>L. Baines</u>	<u>K. Jolls</u>
<u>J. Voorhees</u>	<u>D. Lang</u> Recorder

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	None	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	Upstream face has timber bulkhead from NE end to spillway, alignment fair, timber in fair to poor condition. Embankment extends around south shore for 300' +, 2 1/2 - 3' high.	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	Erosion evident around right wingwall. Numerous large trees on embankment 12"-20"Ø. Many of them are dead and rotting.	
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Horizontal good, vertical good. Dam appears to have fairly uniform elevation throughout.	
RIPRAP FAILURES	Yes at NE wingwall, riprap not placed, but dumped.	Appears to be a continual problem.

⑬

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAN	Poor, severe erosion problem behind both spillway wingwalls, probably due to surface runoff and pedestrian traffic.	Regrade and protect with slope paving or stone riprap.
ANY NOTICEABLE SEEPAGE	Seepage possible 60' southwest of spillway. Possibly at breeding pond.	
STAFF GAGE AND RECORDER	None	
DRAINS	None	

GATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE SILL	None	
APPROACH CHANNEL	Centerton Lake	Free and clear of debris.
DISCHARGE CHANNEL	50' + wide, through heavily wooded area after county bridge.	
BRIDGE AND PIERS	County Bridge 150' downstream. Abutments from previous bridge still evident.	Bridge constructed in 1944
GATES AND OPERATION EQUIPMENT	12-vertical lift timber gates. All gates appear operable.	Much of the timber in poor condition.



RESERVOIR

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

SLOPES

Mild 1:3 to 1:4. Park facilities on North shore.  
Southwest shore is heavily wooded.  
Marshy area up at head of lake.

SEDIMENTATION

Yes, along upstream face of embankment

DOWNSTREAM CHANNEL

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	County of Salem Bridge 1944, 2-25' spans, 2½' freeboard. Numerous large trees fallen across channel. High pressure gas line. Storm sewer inlet at SE wingwall	Fallen trees could cause backwater.
SLOPES	2' high embankment, then low heavily wooded flood plain on either side.	
APPROXIMATE NO. OF HOMES AND POPULATION	Some stores at north end. Old roadway abutment still evident on both sides of banks.	Appear to be away from any flooding.

CHECK LIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION

ITEM	REMARKS
PLAN OF DAM	Available - NJDEP - Division of Water Resources - Bureau of Flood Plain Management.
REGIONAL VICINITY MAP	Available - U.S. G.S. Quad - Elmer, N.J.
CONSTRUCTION HISTORY	None available
TYPICAL SECTIONS OF DAM	None available
HYDROLOGIC/HYDRAULIC DATA	Some available - NJDEP - 1953 Encroachment Application
OUTLETS - PLAN	Some Available - NJDEP
- DETAILS	None available - NJDEP
-CONSTRAINTS	Unknown
-DISCHARGE RATINGS	Some available - NJDEP 1953 Encroachment Application
RAINFALL/RESERVOIR RECORDS	None available

**ITEM**

**REMARKS**

**SPELLWAY PLAN** Available - NJDEP - 1953 Encroachment Application

**SECTIONS** Available - NJDEP - 1953 Encroachment Application

**DETAILS** Available - NJDEP - 1953 Encroachment Application

**OPERATING EQUIPMENT  
PLANS & DETAILS**

None available

REMARKS

ITEM

DESIGN REPORTS      None available

GEOLOGY REPORTS      None available

DESIGN COMPUTATIONS      Not available  
HYDROLOGY & HYDRAULICS      Not available  
DAM STABILITY      Not available  
SEEPAGE STUDIES      Not available

MATERIALS INVESTIGATIONS      Not available  
BORING RECORDS      Not available  
LABORATORY      Not available  
FIELD      Non available

POST-CONSTRUCTION SURVEYS OF DAM      Not available

BORROW SOURCES      Unknown






View of Spillway

December, 1979



View of Bridge Immediately Downstream of Dam

December, 1979



December, 1979  
View of Crest Looking Northeast



December, 1979  
View of Left Abutment



December, 1979  
View of Timber Bulkhead Along Upstream Face of Dam



December, 1979  
Downstream View of Dam

CHECK LIST  
HYDROLOGIC AND HYDRAULIC DATA  
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: 39.4 square miles

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): +79.0 M.S.L. (132 acre-ft.)

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): Not applicable

ELEVATION MAXIMUM DESIGN POOL: \_\_\_\_\_

ELEVATION TOP DAM: +82.5 M.S.L. (576 acre-feet)

CREST: \_\_\_\_\_

- a. Elevation +82.5 M.S.L.
- b. Type Earth embankment with timber sluiceways
- c. Width varies (8'-20')
- d. Length 1500'±
- e. Location Spillover 1100' ± from left abutment
- f. Number and Type of Gates 12-3'-8"x6' timber gates

OUTLET WORKS: Auxiliary spillway

- a. Type Depressed embankment
- b. Location left abutment
- c. Entrance inverts +81.5 M.S.L.
- d. Exit inverts +71.5 ± M.S.L.
- e. Emergency draindown facilities \_\_\_\_\_

HYDROMETEOROLOGICAL GAGES: None

- a. Type \_\_\_\_\_
- b. Location \_\_\_\_\_
- c. Records \_\_\_\_\_

MAXIMUM NON-DAMAGING DISCHARGE: 1170 cfs

BY RFE DATE 1-22-72

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. A1 OF

CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_

CONTRACT NO. 439

PROJECT 024a

SUBJECT \_\_\_\_\_

### ORITICAL DATA

LENGTH OF LONGEST WATER COURSE  $L = 10.49$   
LENGTH TO CENTER  $L_c = 4.08$

$$LL_c = 10.49 \times 4.08 = 44.40$$

USING CURVE 2 FROM COE PLATE VI FROM  
SPECIAL PROJECT MATH 439:  $f_p = 25.1$

USE DRYING COEFFICIENT FURNISHED BY COE  
 $\alpha = 0.43$

---

### PRECIPITATION

PME FOR 200 SQ. MI.  $\frac{1}{2}$  24 HOUR DURATION = 24"

MAXIMUM 6 HOUR PERCENTAGE = 99%


MAXIMUM 12 HOUR PERCENTAGE = 108%

MAXIMUM 24 HOUR PERCENTAGE = 115%


MAXIMUM 48 HOUR PERCENTAGE = 130%

BY                      DATE 1-22-57 **LOUIS BERGER & ASSOCIATES INC.**  
 CHKD. BY                      DATE                       
 SUBJECT                     

SHEET NO.            OF             
 PROJECT           



ELEV.	M. STALLWAY			E. STALLWAY			EMBANKMENT			TOTAL	
	H	C	Q	H	C	Q	H	C	Q		
79	0	31	44	0	26	100	0	0	0	0	133
80	1			0			0				385
81	0			0			0				540
81.5	25			0			99				910
82	3			.5			0				1170
82.5	3.5			1			0				2660
83	4			1.5			514			1280	2660
84	5			2.5			1107			6654	9285
85	6			3.5			1822			14516	15150
86	7			4.5			2673			23715	25415



BY \_\_\_\_\_ DATE \_\_\_\_\_

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. 114 OF \_\_\_\_\_

CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_

Checked by Louis Berger


PROJECT \_\_\_\_\_

SUBJECT \_\_\_\_\_

Area of Lake @ Elev. 19.0 = 37 Acres

Area of 50 ft Contour = 88.8 Acres


Assume Pool Area Above 80 ft Contour Flooding  
at same rate



$$\Delta Y = \Delta Y (x + \Delta x)$$

Height Above Stillway Crest	Area Acres	$\Delta$ Y/L	Sum of Area
0	27	0	0
1	88.8	62.6	62.6
2	131.6	114.7	177.3
3	157.2	131.2	308.5
4	175.1	144.0	452.5
5	216.4	161.4	613.9
6	241.2	174.7	788.6
7	267.5	187.6	976.2
8	294.1	200.2	1176.4
9	346.1	270.2	1516.6

CENTRETON LAKE DAM  
 STAGE - SURCHARGE  
 CURVE



STAGE IN FEET ABOVE FLOWLINE

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18

SURCHARGE IN FEET AT V. G.

TOP OF DAM, 11171 52.5'

LOUIS BERGER & ASSOCIATES INC.

BY \_\_\_\_\_ DATE 8-12 SHEET NO. A-6 OF  
 CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_ PROJECT C-246  
 SUBJECT \_\_\_\_\_

ASSUME DRAWDOWN OF 10' FOR ALL 12 STOPLOG (30')  
 $L = 12 \times 3.67 = 44'$

ASSUME INFLOW OF 40 CFS

ASSUME DRAWDOWN IN TWO STAGES

STAGE 1

$$H = 6'$$

$$Q = C \cdot L \cdot H^{3/2} \quad C = 3.1 \quad L = 44'$$

$$Q = 2005 \text{ CFS}$$

$$Q = 2005 - 40$$

$$= 1965 \text{ CFS}$$

$$\therefore \text{TIME} = \frac{122 \times 43560}{2 \times 1965 \times 3200}$$

$$= 0.4 \text{ HRS}$$

STAGE 2

$$H = 2'$$

$$Q = C \cdot (44) \cdot (2)^{3/2}$$

$$Q = 352 - 40$$

$$Q = 312 \text{ CFS}$$

$$\therefore \text{TIME} = \frac{132 \times 43560}{2 \times 312 \times 3200}$$

$$= 2.2 \text{ HRS}$$

TOTAL TIME = 0.4 + 2.2 = 2.6 HRS

A CENTRETON LAKE DAM

A CENTRETON LAKE DAM

BY R. F. BERRY

A MAY, 1980

B 150 2

1 3

K 0

1 1

1 INFLOW HYDROGRAPH

M 1 1 39.4 0 39.4 0.5

P 0 24 99 108 119 130 0.5 0.1

1 25.1 0.43

X 0 0 1

K 1 1

1 ROUTING THROUGH RESERVOIR

Y 1 1

2 0 63 177 253 342 444 558 826 1145 1516

3 0 135 385 540 810 1170 2885 9285 18155 28915

K 99

A A A A A A



TIME	RAIN	EXCS	END-OF-PERIOD FLOW	COMP	23.	22.	21.	20.	19.
				G	14.	14.	13.	13.	12.
					9.	9.	8.	8.	7.
1	0.03	0.00	0	0					
2	0.03	0.00	0	0					
3	0.03	0.00	0	0					
4	0.06	0.00	0	0					
5	0.06	0.00	0	0					
6	0.06	0.00	0	0					
7	0.48	0.14	1	1					
8	0.98	0.78	11	11					
9	0.39	0.19	37	37					
10	0.04	0.00	75	75					
11	0.04	0.00	121	121					
12	0.04	0.00	173	173					
13	0.30	0.10	230	230					
14	0.30	0.10	292	292					
15	0.30	0.10	356	356					
16	0.61	0.41	419	419					
17	0.61	0.41	485	485					
18	0.61	0.41	558	558					
19	5.21	5.01	678	678					
20	10.62	10.42	964	964					
21	4.21	4.01	1492	1492					
22	0.45	0.25	2226	2226					
23	0.45	0.25	3105	3105					
24	0.45	0.25	4091	4091					
25	0.00	0.00	5153	5153					
26	0.00	0.00	6241	6241					
27	0.00	0.00	7270	7270					
28	0.00	0.00	8163	8163					
29	0.00	0.00	8882	8882					
30	0.00	0.00	9413	9413					
31	0.00	0.00	9733	9733					
32	0.00	0.00	9796	9796					
33	0.00	0.00	9587	9587					
34	0.00	0.00	9213	9213					
35	0.00	0.00	8806	8806					
36	0.00	0.00	8408	8408					
37	0.00	0.00	8022	8022					
38	0.00	0.00	7651	7651					
39	0.00	0.00	7297	7297					
40	0.00	0.00	6960	6960					
41	0.00	0.00	6638	6638					
42	0.00	0.00	6331	6331					
43	0.00	0.00	6039	6039					
44	0.00	0.00	5760	5760					
45	0.00	0.00	5493	5493					
46	0.00	0.00	5239	5239					
47	0.00	0.00	4997	4997					
48	0.00	0.00	4766	4766					
49	0.00	0.00	4546	4546					

A-10

50	4336	0 00	0 00	0 00
51	4135	0 00	0 00	0 00
52	3744	0 00	0 00	0 00
53	3752	0 00	0 00	0 00
54	3520	0 00	0 00	0 00
55	3452	0 00	0 00	0 00
56	3264	0 00	0 00	0 00
57	3113	0 00	0 00	0 00
58	2969	0 00	0 00	0 00
59	2832	0 00	0 00	0 00
60	2701	0 00	0 00	0 00
61	2576	0 00	0 00	0 00
62	2457	0 00	0 00	0 00
63	2344	0 00	0 00	0 00
64	2235	0 00	0 00	0 00
65	2132	0 00	0 00	0 00
66	2033	0 00	0 00	0 00
67	1939	0 00	0 00	0 00
68	1850	0 00	0 00	0 00
69	1764	0 00	0 00	0 00
70	1683	0 00	0 00	0 00
71	1605	0 00	0 00	0 00
72	1531	0 00	0 00	0 00
73	1460	0 00	0 00	0 00
74	1393	0 00	0 00	0 00
75	1328	0 00	0 00	0 00
76	1267	0 00	0 00	0 00
77	1208	0 00	0 00	0 00
78	1152	0 00	0 00	0 00
79	1099	0 00	0 00	0 00
80	1048	0 00	0 00	0 00
81	1000	0 00	0 00	0 00
82	954	0 00	0 00	0 00
83	910	0 00	0 00	0 00
84	867	0 00	0 00	0 00
85	827	0 00	0 00	0 00
86	789	0 00	0 00	0 00
87	753	0 00	0 00	0 00
88	718	0 00	0 00	0 00
89	685	0 00	0 00	0 00
90	653	0 00	0 00	0 00
91	623	0 00	0 00	0 00
92	594	0 00	0 00	0 00
93	567	0 00	0 00	0 00
94	540	0 00	0 00	0 00
95	515	0 00	0 00	0 00
96	492	0 00	0 00	0 00
97	469	0 00	0 00	0 00
98	447	0 00	0 00	0 00
99	427	0 00	0 00	0 00
100	407	0 00	0 00	0 00
101	388	0 00	0 00	0 00
102	370	0 00	0 00	0 00
103	353	0 00	0 00	0 00
104	337	0 00	0 00	0 00

105	0.00	0.00	0.00	321.
106	0.00	0.00	0.00	306.
107	0.00	0.00	0.00	291.
108	0.00	0.00	0.00	272.
109	0.00	0.00	0.00	298.
110	0.00	0.00	0.00	246.
111	0.00	0.00	0.00	235.
112	0.00	0.00	0.00	224.
113	0.00	0.00	0.00	213.
114	0.00	0.00	0.00	202.
115	0.00	0.00	0.00	192.
116	0.00	0.00	0.00	181.
117	0.00	0.00	0.00	169.
118	0.00	0.00	0.00	159.
119	0.00	0.00	0.00	116.
120	0.00	0.00	0.00	36.
121	0.00	0.00	0.00	6.
122	0.00	0.00	0.00	4.
123	0.00	0.00	0.00	2.
124	0.00	0.00	0.00	0.
125	0.00	0.00	0.00	0.
126	0.00	0.00	0.00	0.
127	0.00	0.00	0.00	0.
128	0.00	0.00	0.00	0.
129	0.00	0.00	0.00	0.
130	0.00	0.00	0.00	0.
131	0.00	0.00	0.00	0.
132	0.00	0.00	0.00	0.
133	0.00	0.00	0.00	0.
134	0.00	0.00	0.00	0.
135	0.00	0.00	0.00	0.
136	0.00	0.00	0.00	0.
137	0.00	0.00	0.00	0.
138	0.00	0.00	0.00	0.
139	0.00	0.00	0.00	0.
140	0.00	0.00	0.00	0.
141	0.00	0.00	0.00	0.
142	0.00	0.00	0.00	0.
143	0.00	0.00	0.00	0.
144	0.00	0.00	0.00	0.
145	0.00	0.00	0.00	0.
146	0.00	0.00	0.00	0.
147	0.00	0.00	0.00	0.
148	0.00	0.00	0.00	0.
149	0.00	0.00	0.00	0.
150	0.00	0.00	0.00	0.

SUM	26.36	22.83	286006.	
PEAK	9796.	8747.	6115.	286007.
6-HOUR	9705.	826	1732	22.51
24-HOUR	229	17359.	36405.	47298.
72-HOUR	4815.			

CFS.  
INCHES  
AC-FT

RUNOFF MULTIPLIED BY 0.50



15	49.	162.	104.
16	61.	194.	131.
17	74.	226.	160.
18	89.	261.	191.
19	105.	309.	227.
20	131.	411.	283.
21	177.	614.	385.
22	254.	929.	543.
23	358.	1333.	866.
24	463.	1799.	1458.
25	526.	2311.	2404.
26	559.	2848.	2899.
27	585.	3378.	3535.
28	603.	3858.	3964.
29	620.	4261.	4358.
30	632.	4574.	4644.
31	640.	4786.	4833.
32	642.	4882.	4898.
33	639.	4846.	4828.
34	632.	4700.	4658.
35	624.	4505.	4454.
36	615.	4303.	4254.
37	607.	4107.	4059.
38	599.	3918.	3872.
39	592.	3737.	3693.
40	585.	3564.	3522.
41	578.	3400.	3359.
42	571.	3242.	3204.
43	565.	3093.	3056.
44	559.	2950.	2915.
45	552.	2813.	2797.
46	544.	2683.	2671.
47	536.	2559.	2547.
48	528.	2441.	2429.
49	520.	2328.	2317.
50	513.	2220.	2210.
51	506.	2118.	2108.
52	500.	2020.	2010.
53	494.	1927.	1917.
54	488.	1838.	1829.
55	482.	1753.	1744.
56	477.	1672.	1664.
57	472.	1594.	1587.
58	467.	1521.	1513.
59	462.	1450.	1443.
60	458.	1383.	1377.
61	454.	1319.	1313.
62	449.	1258.	1252.
63	446.	1200.	1195.
64	440.	1145.	1157.
65	432.	1092.	1128.
66	421.	1041.	1089.
67	409.	993.	1046.
68	396.	947.	1001.
69	384.	904.	957.

70	371.	862.	914.
71	360.	822.	872.
72	348.	784.	832.
73	337.	748.	796.
74	326.	713.	763.
75	316.	660.	730.
76	305.	649.	697.
77	294.	619.	666.
78	284.	590.	635.
79	275.	563.	606.
80	266.	537.	578.
81	257.	512.	552.
82	248.	488.	530.
83	239.	466.	512.
84	230.	444.	492.
85	220.	424.	472.
86	210.	404.	453.
87	201.	385.	433.
88	191.	368.	414.
89	182.	351.	396.
90	174.	334.	378.
91	165.	319.	360.
92	158.	304.	343.
93	150.	290.	327.
94	143.	277.	311.
95	137.	264.	297.
96	130.	252.	283.
97	124.	240.	270.
98	119.	229.	257.
99	113.	218.	245.
100	108.	208.	234.
101	103.	199.	223.
102	99.	190.	213.
103	94.	181.	203.
104	90.	172.	194.
105	86.	164.	185.
106	82.	157.	176.
107	78.	149.	168.
108	74.	141.	160.
109	70.	133.	151.
110	67.	126.	144.
111	64.	120.	136.
112	61.	115.	130.
113	58.	109.	124.
114	55.	104.	118.
115	52.	99.	112.
116	50.	93.	106.
117	47.	87.	101.
118	44.	82.	95.
119	41.	69.	87.
120	34.	38.	72.
121	25.	10.	54.
122	18.	2.	38.
123	13.	1.	27.
124	9.	0.	19.

125	6	0	13
126	4	0	9
127	3	0	7
128	2	0	5
129	1	0	3
130	1	0	2
131	1	0	2
132	1	0	1
133	0	0	1
134	0	0	1
135	0	0	0
136	0	0	0
137	0	0	0
138	0	0	0
139	0	0	0
140	0	0	0
141	0	0	0
142	0	0	0
143	0	0	0
144	0	0	0
145	0	0	0
146	0	0	0
147	0	0	0
148	0	0	0
149	0	0	0
150	0	0	0

SUM 143004

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME  
 4898 4853 4376 3046 143004  
 CFS 1.15 4.13 8.63 11.25  
 INCHES 2408 8685 18134 23649  
 AC-FT

\*\*\*\*\*  
 \*\*\*\*\*  
 \*\*\*\*\*  
 \*\*\*\*\*

RUNOFF SUMMARY, AVERAGE FLOW

HYDROGRAPH AT	1	PEAK	6-HOUR	24-HOUR	72-HOUR	AREA
ROUTED TO	1	4898	4853	4374	3057	39.40
		4898	4853	4376	3046	39.40