

AD-A097 601

BAKER (MICHAEL) JR INC BEAVER PA

NATIONAL DAM INSPECTION PROGRAM. LOWER ALFORD LAKE DAM (NDI NUM--ETC(1))

FEB 81 J A DZIUBEK

DACV31-81-C-0011

ML

UNCLASSIFIED

1 OF 1
AD-A097 601



END
DATE
FILMED
5 81
DTIC

①

SUSQUEHANNA RIVER BASIN
MARTINS CREEK, SUSQUEHANNA COUNTY
PENNSYLVANIA

10/1/81

LOWER ALFORD LAKE DAM


NDI No. PA 00053

PennDER NO-58-47.

Dam Owners: William Deininger, David Deininger
Louis Fortuna, John Fortuna

PHASE I INSPECTION REPORT.
NATIONAL DAM INSPECTION PROGRAM

DACW 31-81-C-0011



prepared for

DEPARTMENT OF THE ARMY
Baltimore District, Corps of Engineers
Baltimore, Maryland 21203

prepared by

MICHAEL BAKER, JR., INC.

Consulting Engineers
4301 Dutch Ridge Road
Beaver, Pennsylvania 15009

February 1981

DISTRIBUTION STATEMENT I
Approved for public release
Distribution unlimited

AD A 097601

DIC FILE COPY

Original contains color
plates. All DIC reproductions
will be in black and white.

81 4 6 074

SUSQUEHANNA RIVER BASIN

12

LOWER ALFORD DAM
SUSQUEHANNA COUNTY, COMMONWEALTH OF PENNSYLVANIA
NDI No. PA 00053
PennDER No. 58-47

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY INSPECTION PROGRAM

DTIC
SELECTED
APR 9 1981

Prepared for: DEPARTMENT OF THE ARMY
Baltimore District, Corps of Engineers
Baltimore, Maryland 21203

Prepared by: MICHAEL BAKER, JR., INC.
Consulting Engineers
4301 Dutch Ridge Road
Beaver, Pennsylvania 15009

February, 1981

DISTRIBUTION STATEMENT A

Approved for public release

with unlimited distribution

PREFACE

This report is prepared under guidance contained in the "Recommended Guidelines for Safety Inspection of Dams," for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I Inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

Accession For
HTIS CB&I
2010 TAB
Unannounced
Distribution for 30m
SC box file

By
Distribution/
Availability/

Dict 30m box

A

PHASE I REPORT
NATIONAL DAM INSPECTION PROGRAM

Lower Alford Dam, Susquehanna County, Pennsylvania
NDI No. PA 00053, PennDER No. 58-47
Martins Creek
Inspected 30 October 1980

ASSESSMENT OF
GENERAL CONDITIONS

Lower Alford Dam is owned by William Deininger, David Deininger, Louis Fortuna, and John Fortuna. Lower Alford Dam is classified as a "High" hazard - "Small" size dam. The dam was found to be in good overall condition at the time of inspection.

Hydraulic/hydrologic evaluations, performed in accordance with procedures established by the Baltimore District, Corps of Engineers, for Phase I Inspection Reports, revealed that the spillway will pass approximately 3.5 percent of the Probable Maximum Flood (PMF) before overtopping will occur. A spillway design flood (SDF) in the range of the 1/2 Probable Maximum Flood (1/2 PMF) to the PMF is required for Lower Alford Dam. The 1/2 PMF was chosen for the SDF as the dam is on the low end of the "Small" size category. Because the total duration and maximum depth of overtopping under the 1/2 PMF (20.50 hours and 4.17 feet, respectively) exceeds the limiting criteria estimated for failure of the dam (5 hours and 4.0 feet), it was determined that dam failure is likely under 1/2 PMF conditions. Further analyses indicated that the downstream damages would increase significantly as a result of failure of the dam. The spillway is therefore considered "Seriously Inadequate." The owners should immediately initiate an engineering study to further evaluate the spillway capacity and to develop recommendations for remedial measures to reduce the overtopping potential of the dam.

In summary, Lower Alford Dam is classified as being in an "Unsafe" - "Non-emergency" condition because of the results of the hydraulic/hydrologic evaluations.

The inspection and review of information revealed certain items of work which should be performed immediately by the owners. Item 1 below should be designed and completed under the guidance of a qualified professional engineer experienced in the design of hydraulic structures for dams.

- 1) Initiate an engineering study to further evaluate the spillway capacity in order to develop recommendations for remedial measures to reduce the overtopping potential of the dam.

LOWER ALFORD DAM

- 2) Cut the brush and trees located on the right downstream face of the dam.
- 3) Remove the debris and cut the vegetation in the downstream channel.
- 4) Provide means to draw down reservoir during an emergency.

In addition, the following operational measures are recommended to be undertaken by the owners:

- 1) Develop a detailed emergency operation and warning system.
- 2) During periods of unusually heavy rain, provide around-the-clock surveillance of the dam.
- 3) When warning of a storm of major proportions is given by the National Weather Service, activate the emergency operation and warning system.

It is further recommended that formal inspection, maintenance, and operation procedures and records be developed and implemented. An emergency drawdown plan should be developed in case emergency drawdown of the reservoir should become necessary. These should be included in a formal maintenance and operations manual for the dam.

Submitted by:

MICHAEL BAKER, JR., INC.

John A. Dziubek

John A. Dziubek, P.E.
Engineering Manager-Geotechnical

Date: 19 February 1981

Approved by:

DEPARTMENT OF THE ARMY
BALTIMORE DISTRICT, CORPS OF ENGINEERS

James W. Peck

JAMES W. PECK
COL, Corps of Engineers
District Engineer
Date: 13 MAR 81

LOWER ALFORD DAM



Overall View of Dam from Left Abutment

TABLE OF CONTENTS

	<u>Page</u>
Section 1 - Project Information	1
Section 2 - Engineering Data	5
Section 3 - Visual Inspection	6
Section 4 - Operational Procedures	7
Section 5 - Hydraulic/Hydrologic	8
Section 6 - Structural Stability	10
Section 7 - Assessment, Recommendations/Remedial Measures	11

APPENDICES

Appendix A - Visual Inspection Check List, Field Sketch, Top of Dam Profile, and Typical Cross-Section
Appendix B - Engineering Data Check List
Appendix C - Photograph Location Plan and Photographs
Appendix D - Hydrologic and Hydraulic Computations
Appendix E - Plates
Appendix F - Regional Geology

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM
LOWER ALFORD DAM
NDI No. PA 00053, PennDER No. 58-47

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

- a. Authority - The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.
- b. Purpose of Inspection - The purpose of the inspection is to determine if the dam constitutes a hazard to human life or property.

1.2 DESCRIPTION OF PROJECT

- a. Description of Dam and Appurtenances - Lower Alford Dam consists of an earthfill embankment with dry stone masonry walls for the upstream and downstream slopes. The dam is approximately 120 feet long and 14.5 feet high, with a crest width of 15 feet.

The spillway consists of a concrete broad crested weir located at the left abutment of the dam. The spillway length is 48.5 feet perpendicular to the direction of flow with stone training walls rising approximately 1 foot above the crest of the spillway. The flow then falls approximately 14 feet into a stone-lined plunge pool.

Two abandoned tailrace structures, 3 ft. by 3 ft. and 7 in. by 10 in. stone conduits, are located to the right of the spillway. They are sealed off at the upstream side.

- b. Location - Lower Alford Dam is located on Martins Creek, 3.4 miles north-northwest of Kingsley, in Harford Township, Susquehanna County, Pennsylvania. The coordinates of the dam are N 41° 48.4', W 75° 46.4'. The dam is located on USGS 7.5 minute topographic quadrangle, Montrose East, Pennsylvania
- c. Size Classification - The height of the dam is 14.5 feet. Storage at the top of the dam [Elevation 1035.6 ft. M.S.L.] is 315 acre-feet. The dam is therefore in the "Small" size category.

d. Hazard Classification - Loss of life could occur from a failure of the dam since two residential structures are located within 1,000 feet downstream. Therefore, Lower Alford Dam is considered in the "High" hazard category.

e. Ownership - The dam is owned jointly by four people. They are:

William Deininger
Box 294
RD 3
Ranson Road
Clarks Summit, PA 18411

David Deininger
101 Billy Lane
Taylor, PA

Louis Fortuna
433 Whales Street
Scranton, PA

John Fortuna
501 Powell Street
Taylor, PA

f. Purpose of Dam - The impoundment created by the dam was originally used for water power but is now used for recreational purposes.

g. Design and Construction History - It could not be determined who the contractor or engineer was or when the dam was constructed. The earliest available records of the dam date back to 1919.

h. Normal Operational Procedures - The reservoir is typically maintained at the spillway crest (Elevation 1034.0 ft. M.S.L.). The owner visits the dam at least once a week and more frequently in the warmer months.

1.3 PERTINENT DATA

a. <u>Drainage Area (square miles)</u> -	5.34
b. <u>Discharge at Dam Site (c.f.s.)</u> -	
Maximum Flood -	Unknown

Spillway Capacity (at Pool El. 1035.6 ft. M.S.L.) -		250
c.	<u>Elevation (feet above Mean Sea Level [M.S.L.])</u> * -	
	Design Top of Dam -	Unknown
	Minimum Top of Dam -	1035.6
	Maximum Design Pool -	Unknown
	Spillway Crest -	1034.0
	Streambed at Toe of Dam -	1021.1
	Maximum Tailwater of Record -	Unknown
d.	<u>Reservoir (feet)</u> -	
	Length of Normal Pool (El. 1034.0 ft. M.S.L.) -	6350
	Length of Maximum Pool (El. 1035.6 ft. M.S.L.) -	6700
e.	<u>Storage (acre-feet)</u> -	
	Top of Dam (El. 1035.6 ft. M.S.L.) -	315
	Normal Pool (El. 1034.0 ft. M.S.L.) -	260
f.	<u>Reservoir Surface (acres)</u> -	
	Normal Pool (El. 1034.0 ft. M.S.L.) -	34
	Maximum Pool (El. 1035.6 ft. M.S.L.) -	38
g.	<u>Dam</u> -	
	Type - Earthfill with dry stone masonry walls	
	Total Length (feet) -	120
	Height (feet) - Design -	Unknown
	Field -	14.5
	Top Width (feet) -	15
	Side Slopes - Upstream -	Vertical
	Downstream -	Vertical
	Zoning -	None
	Impervious Core -	None
	Cut-off -	None
	Drains -	None
h.	<u>Diversion and Regulating Tunnel</u> -	None

*All elevations are referenced to the spillway crest of the dam, El. 1034.0 ft. M.S.L. as estimated from the USGS 7.5 minute topographic quadrangle, Montrose East, Pennsylvania.

i. Spillway -

Type - Concrete broad crested
Location - At left abutment
Length of Crest Perpendicular to
Flow (feet) - 48.5
Width of Crest Parallel to Flow
(feet) - 10
Crest Elevation (ft. M.S.L.) - 1034.0
Gates - None
Downstream Channel - Natural streambed; a stone
pier and remnants of an old
mill are located in the
channel approximately 200 feet
downstream from the dam.

j. Outlet Works - Two abandoned tailrace structures,
3 ft. by 3 ft. and 7 in. by 10 in. stone conduits,
are both sealed off at the upstream side. These
structures apparently supplied water to the aban-
doned mill downstream from the dam. There are no
other outlet works.

SECTION 2 - ENGINEERING DATA

2.1 DESIGN

The information reviewed consisted of File No. 58-47 of the Pennsylvania Department of Environmental Resources (PennDER). This file contained a copy of the following information:

- 1) The first dam inspection report on Lower Alford Dam, dated 28 August 1919.
- 2) The latest dam inspection report on Lower Alford Dam, dated 22 October 1964. The dam was reported to be in good condition at that time. No information is available concerning the design or construction of the dam.
- 3) Other inspection reports performed between the 1919 and 1964 inspections.

2.2 CONSTRUCTION

The information reviewed consisted of File No. 58-47 of the Pennsylvania Department of Environmental Resources (PennDER). The file contained no information concerning construction of the dam.

2.3 OPERATION

The owners of the dam are responsible for all operations and maintenance.

2.4 EVALUATION

- a. Availability - The information used is readily available from PennDER File No. 58-47.
- b. Adequacy - The information available is adequate for Phase I Inspection of this dam.
- c. Validity - There is no reason at the present time to doubt the validity of the available engineering data.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

- a. General - The dam was found to be in good overall condition at the time of inspection on 30 October 1980. No unusual weather conditions were experienced during the inspection. Noteworthy deficiencies observed during the visual inspection of the dam are described briefly in the following paragraphs. The complete visual inspection check list, field sketch, top of dam profile, and typical cross-section are presented in Appendix A.
- b. Dam - Some trees and brush were observed on the right downstream face of the dam. These should be cut.
- c. Appurtenant Structures - The spillway crest is slightly irregular, however, this should not significantly affect the performance of the spillway.
- d. Reservoir Area - The reservoir area has steep slopes which are densely forested. However, the slope of Martins Creek, the main tributary to Lower Alford Dam, is mild to moderate. The creek passes through several marshes before it reaches Lower Alford Dam. There is also a small dam, Upper Alford Dam, and several large masonry culverts under railroad embankments, through which Martins Creek passes in the upper portions of the watershed. Neither the upstream dam nor the masonry culverts is judged to have a significant effect on Lower Alford Dam.
- e. Downstream Channel - The downstream channel is moderately sloped. There are some large trees and debris in the channel. The channel is partially obstructed by an old mill located 200 feet downstream of the dam. There is an average of 4 feet of clearance between the channel invert and the bottom of the mill. Located 500 and 1,000 feet downstream of the dam are a trailer and house, respectively, which may suffer economic damage and possible loss of lives in these structures in the event of failure of the dam.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES

There are no formal procedures for lowering the reservoir or evacuating the downstream area in case of an impending failure of the dam. It is recommended that formal emergency procedures be adopted, prominently displayed, and furnished to all operating personnel.

4.2 MAINTENANCE OF DAM

Generally, the maintenance procedures followed are adequate; however, a more conscientious and formal maintenance program and procedures should be developed.

4.3 MAINTENANCE OF OPERATING FACILITIES

Maintenance is performed on an as-needed basis. It is recommended that a formal operation and preventive maintenance schedule be developed and implemented. An emergency drawdown plan should be developed in case emergency drawdown of the reservoir should become necessary.

4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT

There is no warning system in the event of a dam failure. An emergency warning system should be developed.

4.5 EVALUATION OF OPERATIONAL ADEQUACY

The current operational features are adequate for the purpose they serve. However, it is recommended that a formal maintenance and operations manual be prepared for the dam.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

- a. Design Data - No hydrologic or hydraulic design calculations are available for Lower Alford Dam.
- b. Experience Data - No information concerning the effects of significant floods on the dam is available.
- c. Visual Observation - This is a masonry dam with a concrete cap on the spillway. The minimum top of dam elevation is 1035.6 feet which gives a free-board of 1.6 feet. The spillway crest is irregular, being low (1034.0 feet) in the center and higher on each end with an average crest elevation of 1034.2 feet. During the visual inspection, no problems were observed which would indicate that the dam and appurtenant facilities could not perform satisfactorily during a flood event.
- d. Overtopping Potential - Lower Alford Dam is a "Small" size - "High" hazard dam requiring evaluation for a spillway design flood (SDF) in the range of 1/2 Probable Maximum Flood (1/2 PMF) to the Probable Maximum Flood (PMF). Due to the small size of the impoundment, the 1/2 PMF was chosen as the SDF.

The hydraulic capacity of the dam, reservoir, and spillway was assessed by utilizing the U.S. Army Corps of Engineers' Flood Hydrograph Package, HEC-1 DB. The hydrologic characteristics of the basin, specifically, the Snyder's unit hydrograph parameters, were obtained from a regionalized analysis conducted by the Baltimore District of the U.S. Army Corps of Engineers.

Analysis of the dam and spillway shows that during the SDF, the dam will be overtopped by a maximum depth of 4.17 feet for a duration of 20.50 hours.

The spillway is capable of passing only 3.5 percent of the PMF before overtopping occurs.

- e. Spillway Adequacy - As outlined in the above analyses, the spillway cannot pass the SDF before overtopping occurs. The next criteria for determining spillway adequacy requires an estimate of whether the dam will fail during the 1/2 PMF. The following conditions, as well as the overall state

of the dam, were estimated as the limiting criteria which are likely to cause failure of the dam.

- 1) Depth of overtopping of 4.0 feet or greater.
- 2) Duration of overtopping in excess of 5 hours.

Both of these criteria are exceeded during the 1/2 PMF, indicating the dam is likely to fail. To assess the impact of the dam's failure on the damage centers downstream, the 1/2 PMF was routed through the dam for failure and non-failure cases. This analysis indicated that there would be a significant increase in flow magnitude and depth in the downstream damage centers from the non-failure to the failure case. It is likely that there would be a significant increase in downstream damages accompanying this increase in flow which would place this spillway in the "Seriously Inadequate" category.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

- a. Visual Observations - There were no structural inadequacies noted during the visual inspection that cause concern for the structural stability of the dam.
- b. Design and Construction Data - No design or construction data were available for review. Generally, for this type of dam, if the ratio of the width of the stonewall portion of the dam is greater than 0.5 times the height of the dam (0.5 w/h), then stability of the dam due to overturning or sliding is not a problem. (Reference: "Evaluation and Repair of Stonewall-earth Dams," by Kent A. Healy, Proceedings of "Safety of Small Dams" conference, New England College, Henniker, New Hampshire, August 4-9, 1974, pp. 149-178). The w/h ratio for this dam is approximately one and no signs of instability were observed during the visual inspection, therefore, further assessments of the structural stability are not considered necessary.
- c. Operating Records - No operating records are available.
- d. Post-Construction Changes - No changes adversely affecting the structural stability of the dam have been performed.
- e. Seismic Stability - The dam is located in Seismic Zone 1 of the "Seismic Zone Map of the Contiguous United States," Figure 1, page D-30, "Recommended Guidelines for Safety Inspection of Dams." This is a zone of minor seismic activity. Therefore, further consideration of the seismic stability is not warranted.

SECTION 7 - ASSESSMENT, RECOMMENDATIONS/REMEDIAL MEASURES

7.1 DAM ASSESSMENT

- a. Safety - Lower Alford Dam was found to be in good overall condition at the time of inspection. Lower Alford Dam is a "High" hazard - "Small" size dam requiring evaluation for an SDF in the range of the 1/2 PMF to PMF. Because of the small size of the impoundment, the 1/2 PMF was chosen as the SDF. As presented in Section 5, the spillway and reservoir were determined to have a capacity of only 3.5 percent of the PMF before overtopping of the dam will occur. During the 1/2 PMF, the maximum depth and total duration of overtopping are 4.17 feet and 20.50 hours, respectively. These exceed the limiting criteria for failure of 4.0 feet or greater maximum depth of overtopping and a total duration in excess of 5 hours estimated for this dam. Therefore, it was concluded that failure of the dam is likely to occur during the 1/2 PMF event. Further, the 1/2 PMF was routed downstream for failure and non-failure cases, and it was determined that failure would significantly increase the damages downstream. The spillway is therefore classified as "Seriously Inadequate" and the dam is assessed as being in an "Unsafe" - "Non-emergency" condition.
- b. Adequacy of Information - The information available and the measurements and observations made during the visual inspection are considered sufficient for this Phase I Inspection Report.
- c. Urgency - The owner should immediately initiate the further investigation as discussed in paragraph 7.1.d.
- d. Necessity for Additional Data/Evaluation - The hydraulic/hydrologic analyses performed for this dam has indicated the need for additional spillway capacity. It is recommended that the owners of Lower Alford Dam immediately initiate an engineering study to further evaluate the spillway capacity and to develop recommendations for reducing the overtopping potential of the dam. This study should result in the implementation of the necessary remedial measures.

7.2 RECOMMENDATIONS / REMEDIAL MEASURES

The inspection and review of information revealed certain items of work which should be immediately performed by the owners. Item 1 below should be designed and completed under the guidance of a qualified professional engineer experienced in the design of hydraulic structures for dams.

- 1) Initiate an engineering study to further evaluate the spillway capacity in order to develop recommendations for remedial measures to eliminate the overtopping potential of the dam.
- 2) Cut the brush and trees located on the right downstream face of the dam.
- 3) Remove the debris and cut the vegetation in the downstream channel.
- 4) Provide means to draw down reservoir during an emergency.

In addition, the following operational measures are recommended to be undertaken by the owners:

- 1) Develop a detailed emergency operation and warning system.
- 2) During periods of unusually heavy rain, provide around-the-clock surveillance of the dam.
- 3) When warning of a storm of major proportions is given by the National Weather Service, activate the emergency operation and warning system.

It is further recommended that formal inspection, maintenance, and operation procedures and records be developed and implemented. An emergency drawdown plan should be developed in case an emergency drawdown of the reservoir should become necessary. These should be included in a formal maintenance and operations manual.

APPENDIX A

VISUAL INSPECTION CHECK LIST, FIELD SKETCH,
TOP OF DAM PROFILE, AND TYPICAL CROSS-SECTION

A-1

Check List
Visual Inspection
Phase 1

Name of Dam Lower Alford Dam County Susquehanna State PA Coordinates Lat. N 41°48.4'

NDI # PA 00053
PennDER # 58-47

Long. W 75°46.4'

Date of Inspection 30 October 1980 Weather Overcast Temperature 40° F.

Pool Elevation at Time of Inspection 1034.2 ft.* M.S.L. Tailwater at Time of Inspection 1021.3 ft.* M.S.L.

*All elevations referenced to the spillway crest of the dam, El. 1034.0 ft. M.S.L. as estimated from the USGS 7.5 minute topographic quadrangle, Montrose East, Pennsylvania.

Inspection Personnel:

Michael Baker, Jr., Inc.:

Owner's Representatives:

James G. Ulinski
Wayne D. Lasch
Jeffrey S. Maze

James G. Ulinski Recorder

MASONRY DAMS

Name of Dam: LOWER ALFORD DAMNDI # PA 00053

<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
LEAKAGE	None observed	
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS	Good condition	
DRAINS	None observed	
WATER PASSAGES	Not Applicable	
VEGETATION	There are some trees and brush on the right downstream face of the dam.	The trees and brush should be cut.
FOUNDATION	No problems observed	

MASONRY DAMS

Name of Dam: LOWER ALFORD DAM

NDI # PA 00053

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES	None observed	
STRUCTURAL CRACKING	Not Applicable	
VERTICAL AND HORIZONTAL ALIGNMENT	Good	
MONOLITH JOINTS	Not Applicable	
CONSTRUCTION JOINTS	Not Applicable	

EMBANKMENT - Not Applicable

A-4

Name of Dam LOWER ALFORD DAM

NDI # PA 00053

<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
------------------------------	---------------------	-----------------------------------

SURFACE CRACKS

UNUSUAL MOVEMENT OR
CRACKING AT OR BEYOND
THE TOE

SLOUGHING OR EROSION OF
EMBANKMENT AND ABUTMENT
SLOPES

EMBANKMENT - Not Applicable

A-5

Name of Dam LOWER ALFORD DAM
NDI # PA 00053

<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
------------------------------	---------------------	-----------------------------------

VERTICAL AND HORIZONTAL
ALIGNMENT OF THE CREST

RIPRAP FAILURES

EMBANKMENT - Not Applicable

A-6

Name of Dam LOWER ALFORD DAM

NDI # PA 00053

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

JUNCTION OF EMBANKMENT
AND ABUTMENT, SPILLWAY
AND DAM

ANY NOTICEABLE SEEPAGE

STAFF GAGE AND RECORDER

DRAINS

OUTLET WORKS

A-7

Name of Dam: LOWER ALFORD DAM

NDI # PA 00053

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	Not Applicable	
INTAKE STRUCTURE	Intake structure to both conduits sealed shut by owner.	
OUTLET STRUCTURE	Good condition	
OUTLET CHANNEL	Good condition	
EMERGENCY GATE	None observed	

UNGATED SPILLWAY

Name of Dam: LOWER ALFORD DAM

NDI # PA 00053

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
-----------------------	--------------	----------------------------

CONCRETE WEIR	Good condition	
---------------	----------------	--

APPROACH CHANNEL	Good condition	
------------------	----------------	--

DISCHARGE CHANNEL	Good condition	
-------------------	----------------	--

BRIDGE AND PIERS	None	
------------------	------	--

GATED SPILLWAY - Not Applicable

Name of Dam: LOWER ALFORD DAM

NDI # PA 00053

<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
------------------------------	---------------------	-----------------------------------

CONCRETE SILL		
---------------	--	--

APPROACH CHANNEL		
------------------	--	--

DISCHARGE CHANNEL		
-------------------	--	--

BRIDGE AND PIERS		
------------------	--	--

GATES AND OPERATION EQUIPMENT		
----------------------------------	--	--

INSTRUMENTATION

Name of Dam: LOWER ALFORD DAM

NDI # PA 00053

<u>VISUAL EXAMINATION</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
---------------------------	---------------------	-----------------------------------

MONUMENTATION/SURVEYS	None observed	
-----------------------	---------------	--

OBSERVATION WELLS	None observed	
-------------------	---------------	--

WEIRS	None observed	
-------	---------------	--

PIEZOMETERS	None observed	
-------------	---------------	--

OTHER		
-------	--	--

RESERVOIR

Name of Dam: LOWER ALFORD DAM

NDI # PA 00053


VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	Fairly steep to steep with good growth of ground cover and trees.	
SEDIMENTATION	Upper end of reservoir is mostly marshy. Sedimentation in the reservoir is not believed to have a significant affect on the performance of the dam and reservoir during a flood event.	
UPSTREAM DAM	Upper Alford Dam upstream is considered to have insignificant impact on Lower Alford Dam.	

DOWNSTREAM CHANNEL

Name of Dam: LOWER ALFORD DAM

NDI # PA 00053

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	An old mill is located over the channel approximately 200 ft. downstream of the dam. There is an average of 4 ft. of clearance between the channel invert and the soffit of the mill. Both vegetation and debris are in the channel.	Remove debris and cut the vegetation.
SLOPES	The downstream channel is moderately sloped.	
APPROXIMATE NO. OF HOMES AND POPULATION	One trailer and one house may suffer economic damage downstream of the dam. Loss of life may occur in the trailer if the dam should fail.	



MICHAEL BAKER, JR., INC.

THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009


A-14

LOWER ALFORD DAM


TOP OF DAM PROFILE
TYPICAL CROSS-SECTION

DATE OF INSPECTION: 27 October 1980

TOP OF DAM PROFILE (LOOKING DOWNSTREAM)
LENGTH OF DAM: 120 FEET



TYPICAL CROSS SECTION AT STA. 0+70



APPENDIX B

ENGINEERING DATA CHECK LIST

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION

Name of Dam: LOWER ALFORD DAM

NDI # PA 00053

ITEM	REMARKS
PLAN OF DAM	No information available. See Field Sketch, Plate 3.
REGIONAL VICINITY MAP	A USGS 7.5 minute topographic quadrangle, Montrose East, Pennsylvania, was used to prepare the vicinity map which is enclosed in this report as Plate 1.
CONSTRUCTION HISTORY	No information available
TYPICAL SECTIONS OF DAM	No information available. See typical cross section, Plate 4.
HYDROLOGIC/HYDRAULIC DATA	No information available
OUTLETS - PLAN	No information available
- DETAILS	No information available
- CONSTRAINTS	No information available
- DISCHARGE RATINGS	No information available
RAINFALL/RESERVOIR RECORDS	None

Name of Dam: LOWER ALFORD DAM

B-2

NDI # PA 00053

<u>ITEM</u>	<u>REMARKS</u>
DESIGN REPORTS	No information available
GEOLOGY REPORTS	No information was available. The regional geology is presented as Appendix F of this report.
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	No information available
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	No information available
POST-CONSTRUCTION SURVEYS OF DAM	None
BORROW SOURCES	No information available

Name of Dam: LOWER ALFORD DAM

B-3

NDI # PA 00053

<u>ITEM</u>	<u>REMARKS</u>
MONITORING SYSTEMS	None
MODIFICATIONS	The weir of the dam was replaced with a concrete broadcrested weir in 1980, and the outlet works were plugged by the owner in 1942.
HIGH POOL RECORDS	No information available
POST-CONSTRUCTION ENGINEERING STUDIES AND REPORTS	No detailed engineering reports other than the 28 August 1919 Water Supply Commission Inspection are available. A number of inspection reports are available in the PennDER file, including the latest recorded inspection on 22 October 1964 by PennDER.
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	None reported in the information available.
MAINTENANCE OPERATION RECORDS	None available

Name of Dam: LOWER ALFORD DAM
NDI # PA 00053

B-4

ITEM	REMARKS
SPILLWAY PLAN, SECTIONS, and DETAILS	No information available
OPERATING EQUIPMENT PLANS & DETAILS	None observed

CHECK LIST
HYDROLOGIC AND HYDRAULIC DATA
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: 5.34 sq.mi., moderate to steep
slopes, wooded

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 1034.0 ft. M.S.L.
(260 ac.-ft.)

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): 1035.6 ft. M.S.L.
(315 ac.-ft.)

ELEVATION MAXIMUM DESIGN POOL: Unknown

ELEVATION TOP DAM: 1035.6 ft. M.S.L. (minimum crest elevation)

SPILLWAY: Rectangular channel with concrete cap

- a. Crest Elevation 1034.0 ft. M.S.L.
- b. Type Rectangular channel
- c. Width of Crest Parallel to Flow 10 ft.
- d. Length of Crest Perpendicular to Flow 48.5 ft.
- e. Location Spillover Right side of embankment
- f. Number and Type of Gates None

OUTLET WORKS: None

- a. Type _____
- b. Location _____
- c. Entrance Inverts _____
- d. Exit Inverts _____
- e. Emergency Drawdown Facilities _____

HYDROMETEOROLOGICAL GAGES: None

- a. Type _____
- b. Location _____
- c. Records _____

MAXIMUM NON-DAMAGING DISCHARGE Unknown

APPENDIX C

PHOTOGRAPH LOCATION PLAN AND PHOTOGRAPHS

DETAILED PHOTOGRAPH DESCRIPTIONS

Overall View of Dam from Left Abutment

Photograph Location Plan

Photo 1 - View of Upstream Side of Dam from Right Abutment

Photo 2 - View of Crest of Dam from Right Abutment

Photo 3 - View of Crest of Dam from Left Abutment

Photo 4 - View of Downstream Side of Dam from Right Abutment


Photo 5 - View of Downstream Side of Dam from Left Abutment

Photo 6 - View of Downstream Channel from Crest of Dam

Photo 7 - View of Abandoned Tailrace Structure

Photo 8 - Inside View of Abandoned Tailrace Structure

Note: Photographs were taken on 30 October 1980.



LOWER ALFORD DAM



PHOTO 1. View of Upstream Side of Dam from Right Abutment



PHOTO 2. View of Crest of Dam from Right Abutment

LOWER ALFORD DAM



PHOTO 3. View of Crest of Dam from Left Abutment



PHOTO 4. View of Downstream Side of Dam from Right Abutment

LOWER ALFORD DAM



PHOTO 5. View of Downstream Side of Dam from Left Abutment



PHOTO 6. View of Downstream Channel from Crest of Dam

LOWER ALFORD DAM



PHOTO 7. View of Abandoned Terrace Structure



PHOTO 8. Inside View of Abandoned Terrace Structure

APPENDIX D

HYDROLOGIC AND HYDRAULIC COMPUTATIONS

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject LOWER ALCOID DAM S.O. No. _____
APPENDIX D - HYDROLOGIC AND Sheet No. _____ of _____
HYDRAULIC COMPUTATIONS Drawing No. _____
Computed by _____ Checked by _____ Date _____

<u>SUBJECT</u>	<u>PAGE</u>
PREFACE	i
HYDROLOGY AND HYDRAULIC DATA BASE	1
HYDRAULIC DATA	2
DRAINAGE AREA AND CENTROID MAP	3
TOP OF DAM PROFILE AND CROSS SECTION	4
SPILLWAY PROFILE AND DISCHARGE RATING	5
SPILLWAY CAPACITY ANALYSIS AND FAILURE ASSUMPTIONS	6
HEC-1 SPILLWAY CAPACITY ANALYSIS	7
HEC-1 DOWNSTREAM ROUTING	12

PREFACE

HYDROLOGIC AND HYDRAULIC COMPUTATIONS

The hydrologic determinations presented in this Phase I Inspection Report are based on the use of a Snyder's unit hydrograph developed by the U.S. Army Corps of Engineers. Due to the limited number of gaging stations available in this hydrologic region and the wide variations of watershed slopes, the Snyder's coefficients may yield results of limited accuracy for this watershed. As directed however, a further refinement of these coefficients is beyond the scope of this Phase I Investigation.

In addition, the conclusions presented pertain to present conditions, and the effect of future development on the hydrology has not been considered.

HYDROLOGY AND HYDRAULIC ANALYSIS
DATA BASE

NAME OF DAM: LOWER ALFORD DAM

PROBABLE MAXIMUM PRECIPITATION (PMF) = 21.0 INCHES/24 HOURS⁽¹⁾

STATION	1	2	3	4	5
Station Description	LOWER ALFORD DAM				
Drainage Area (square miles)	5.34				
Cumulative Drainage Area (square miles)	5.34				
Adjustment of PMF for Drainage Area (%) ⁽²⁾	ZONE 1				
6 Hours	111%				
12 Hours	123%				
24 Hours	133%				
48 Hours	142%				
72 Hours	--				
Snyder Hydrograph Parameters					
Zone (3)	11				
C_p/C_t (4)	0.62/1.50				
L (miles) (5)	5.72				
L_{ca} (miles) (5)	2.77				
$t_p = C_t (L \cdot L_{ca})^{0.3}$ (hours)	3.44				
Spillway Data					
Crest Length (ft)	48.5				
Freeboard (ft)	1.6				
Discharge Coefficient Exponent	(DISCHARGE RATING CURVE DEVELOPED ON SHEET 5)				

(1) Hydro-meteorological Report 33 (Figure 1), U.S. Army, Corps of Engineers, 1956.

(2) Hydro-meteorological Report 33 (Figure 2), U.S. Army, Corps of Engineers, 1956.

(3) Hydrological zone defined by Corps of Engineers, Baltimore District, for determining Snyder's coefficients (C_p and C_t).

(4) Snyder's Coefficients.

(5) L = Length of longest water course from outlet to basin divide.

L_{ca} = Length of water course from outlet to point opposite the centroid of drainage area.

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject LOWER BEVER DAM S.O. No. _____
HYDROLOGIC DATA Sheet No. 2 of 17
Drawing No. _____
Computed by GLT Checked by WDL Date 12-10-90

STORAGE CALCULATIONS

AREA VS. ELEVATION DATA : (MEASURED FROM QUAD)

<u>ELEVATION (FT)</u>	<u>SURFACE AREA (ACRES)</u>
1034	33.98
1040	48.67
1060	68.87

NORMAL POOL STORAGE

$$\text{STORAGE VOLUME} = V_{NP} = \frac{h}{3} (A_1 + A_2 + \sqrt{A_1 A_2})$$

h = ESTIMATED FROM FIELD NOTES = 7.8 FT.

A_1 = SURFACE AREA OF NORMAL POOL = 33.98 AC.

A_2 = SURFACE AREA OF RESERVOIR BOTTOM = 32.41 AC.

(ESTIMATED FROM AVERAGE DEPTH AND
RESERVOIR SIDE SLOPES)

$$\text{NORMAL POOL STORAGE} = V_{NP} = \frac{7.8}{3} (33.98 + 32.41 + \sqrt{(33.98)(32.41)})$$

$$V_{NP} = 258.89 \text{ AC.-FT.}$$

TOP OF DAM STORAGE

315 AC.-FT. (FROM HEC-1 ANALYSIS)

SNYDER'S UNIT HYDROGRAPH PARAMETERS


$$L = 5.72 \text{ MI.}, L_{CA} = 2.77 \text{ MI.}$$

WATERSHED IS IN ZONE II

$$C_p = 0.62 \quad C_t = 1.50$$

$$t_p = 1.50 (L \times L_{CA})^{0.3} = 3.44 \text{ HR.}$$

$$\text{DRAINAGE AREA} = 5.34 \text{ SQ. MI.}$$



MICHAEL BAKER, JR., INC.

THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject LOWER ALFORD DAM

S.O. No. 13837-00-ARR-06

TOP OF DAM PROFILE

Sheet No. 4 of 17

TYPICAL CROSS SECTION


Drawing No. _____

Computed by GWT Checked by WDL


Date 11-17-80

TOP OF DAM PROFILE (LOOKING DOWNSTREAM)

LENGTH OF DAM = 120 FEET



TYPICAL CROSS SECTION AT STA. 0+70




MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject LOWER ALFORD DAM S.O. No. 13837-00-ARA-06
SPILLWAY DISCHARGE RATING Sheet No. 5 of 17
AND SPILLWAY PROFILE Drawing No. _____
Computed by GUT Checked by WDL Date 11-21-80

SPILLWAY PROFILE



SPILLWAY DISCHARGE RATING

DEVELOP RATING CURVE BASED UPON CRITICAL FLOW OVER SPILLWAY:

$$V = \sqrt{gD} \quad (\text{CHOW, OPEN CHANNEL HYDRAULICS, P. 43})$$

$$g = 32.2 \text{ FT/SEC}^2$$

$$D = \text{MEAN HYDRAULIC DEPTH} = \frac{\text{FLOW AREA}}{\text{FREE SURFACE TOP WIDTH}} = \frac{A}{T}$$

$$V = \text{MEAN FLOW VELOCITY}$$


$$Q = AV$$

SPILLWAY ELEVATION, FT.	FLOW DEPTH, FT.	AREA, FT ²	TOP WIDTH, FT.	A/T	V, FT/SEC.	Q, CFS	V ² /2g	RESERVOIR SURFACE, FT.
1034.0	0	0	0	0	0	0	0	1034.0
1034.5	0.5	10.0	40.0	0.25	2.84	28.37	0.12	1034.62
1034.8	0.8	23.28	48.5	0.48	3.93	91.52	0.24	1035.04
1035.0	1.0	37.83	48.5	0.78	5.01	189.59	0.39	1035.29
1035.5	1.5	62.08	48.5	1.28	6.42	398.55	0.64	1036.14
1035.6	1.6	66.93	48.5	1.38	6.67	446.16	0.69	1036.29
1036.0	2.0	86.33	48.5	1.78	7.57	653.58	0.89	1036.89
1036.5	2.5	110.58	48.5	2.28	8.57	947.48	1.14	1037.64
1037.0	3.0	134.83	48.5	2.78	9.46	1,275.67	1.39	1038.39
1038.0	4.0	183.33	48.5	3.78	11.03	2,022.59	1.89	1039.89
1039.0	5.0	231.83	48.5	4.78	12.41	2,876.15	2.39	1041.39
1040.0	6.0	280.33	48.5	5.78	13.64	3,824.38	2.88	1042.88
1041.0	7.0	328.83	48.5	6.78	14.77	4,858.63	3.39	1044.39

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject LOWER ALFORD DAM S.O. No. _____
SPILLWAY CAPACITY ANALYSIS Sheet No. 6 of 17
AND FAILURE ASSUMPTIONS Drawing No. _____
Computed by GWT Checked by WDL Date 12/12/80



FAILURE ASSUMPTIONS:

1. FAILURE TAKES PLACE AS THE DEPTH OF OVERTOPPING NEARS ITS MAXIMUM.
2. THE DAM FAILS ALONG ITS ENTIRE CREST LENGTH.
3. BECAUSE THIS IS A MASONRY DAM THE TOTAL DAM IS ASSUMED TO FAIL. FAILURE WILL OCCUR MODERATELY RAPID. (0.5 HRS. DURATION)
4. FAILURE DEPTH WILL BE TO THE RESERVOIR BOTTOM. (ELEV. 1023.0 FT ASSUMED.)

 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DIM SAFETY VERSION JULY 1978
 LAST MODIFICATION 26 FEB 79
 NOJ UPDATE 04 JUN 79

SPURGE CAPACITY ANALYSIS

1 AI NATIONAL PROGRAM FOR INSPECTION OF MIN-FEDERAL DAMS
 2 A2 HYDRAULIC AND HYDRAULIC ANALYSIS OF LOWER ALFORD POND DAM
 3 A3 UNIT HYDROGRAPH BY SNYDER'S METHOD

4 B 30 J 30 0 0 0 0 -4 0

5 B1 5 I 1 5 0.25 0.01 1

6 J 1 J 1.0 0.25 0.01 1

7 J1 1.0 0.25 0.01 1

8 K J 1

9 K1 RUNOFF HYDROGRAPH TO DAM

10 M 1 1 5.34 123 133 142 1.0 0.05

11 P 1 21 111 123 133 142 1.0 0.05

12 I 1 21 111 123 133 142 1.0 0.05

13 W 3.44 0.62

14 X -1.5 -0.05 2.0

15 K 1 2

16 K1 RUNOFF FOR LOWER ALFORD POND DAM

17 V 1 1

18 V1 1

19 V4 1034 1034.6 1035.0 1035.4 1036.1 1036.3 1036.9 1037.6 1038.4 1039.9

20 V41041.4 1042.9 1044.4

21 V5 28.37 91.5 189.6 398.5 446.2 653.6 947.5 1275.7 2022.6

22 V52876.2 3624.4 4898.6

23 SA 32.41 33.98 48.67 68.87

24 SE1026.2 1036.2 1040 1050

25 SA 1014

26 SA1015.6 3.04 1.5 120

27 SC 0 59 90 112 117 124 128 135

28 SV1035.0 1036.0 1037.0 1037.5 1038.0 1038.5 1039.0

29 K 99

 FLOOD HYDROGRAPH PACKAGE (HRC-1)
 DAN SAFETY VERSION JULY 1978
 LAST MODIFICATION 26 FEB 79
 NOJ UPDATE 04 JUL 79

RUN DATE 12/02/80
 TIME 1356

NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
 HYDROLOGIC AND HYDRAULIC ANALYSIS OF LOWER ALFJORD POND DAM
 UNIT HYDROGRAPH BY SNYDER'S METHOD

JOB SPECIFICATION

NO	WTR	NRIN	TDAY	JHR	TRIN	METRC	JPLT	IPRT	NSTAN
300	3	30	0	0	0	0	0	-4	0
			JUPER	NAT	LROPT	TRACE			
			5	0	0	0	0		

MULTI-PLAN ANALYSES TO BE PERFORMED

NPLAN= 1 NRATIO= 5 LRTIU= 1

RTIJS= 1.70 0.50 0.25 0.05 0.01

SUB-AREA RUNOFF COMPUTATION

RUNOFF HYDROGRAPH TO DAM

ISTAQ	ICOMP	TECON	ITAPE	JPLT	JPRY	INAME	ISTAGE	TAUTO
1	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

HYDGR	LIJNG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISHUM	ISAME	LOCAL
1	1	5.34	0.0	5.34	0.0	0.0	0	0	0

PRECIP DATA

SIFE	PMS	R6	R12	R24	R48	R72	R96
0.0	21.00	111.00	123.00	133.00	142.00	0.0	0.0

TRSPC COMPUTED BY THE PROGRAM IS 0.000

LOSS DATA

LROPT	STAKR	DLTKR	RTIDL	ERAIN	STAKS	RTLOK	STIRL	CNSTL	ALSMX	RTIMP
0	0.0	0.0	1.00	0.0	0.0	1.00	1.00	0.05	0.0	0.0

UNIT HYDROGRAPH DATA

IP= 3.44 CP=0.02 NTA= 0

RECESSION DATA

STRTQ= -1.50 JRCNV= -0.05 RTLOK= 2.00

UNIT HYDROGRAPH 19 END-OF-PERIOD ORIGINATES, LAQ=

13.	121.	241.	376.	502.	591.	633.	616.	547.	468.
400.	342.	293.	250.	214.	183.	156.	134.	115.	98.
77.	61.	52.	45.	38.	32.	28.	24.	20.	15.
13.	13.	11.	9.	8.	7.	6.	5.	4.	3.

NO. DA H4.MN PERIOD RAIN EXCS LUSS END-OF-PERIOD FLOW
CUMP Q MU.DA HK.MN PERIOD MAIN EXCS LUSS CUMP Q

SUM 21.86 21.48 2.38 151765.
1 606.71 546.71 60.71 4297.511

HYDROGRAPH ROUTING

ROUTING FOR LOWER ALFORD POND DAM

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPRI	INAME	ISTAGE	IAUTO
2	1	0	0	0	0	1	0	0

ROUTING DATA

LUSS	LUSS	AVG	IRAS	ISAME	IUPT	IPMP	LSTR
0.0	0.0	1	1	0	0	0	0

HSTPS	NSIDL	LAG	AMSKK	X	ISK	STURA	ISPRAT
1	0	0	0.0	0.0	0.0	-1034.	-1

STAGE	1034.00	1034.00	1035.00	1035.40	1036.10	1036.30	1036.90	1037.60	1038.40	1039.90
1041.40	1042.90	1044.40								

FLOW	0.0	28.37	91.50	189.60	398.50	446.20	653.60	947.50	1275.10	2022.60
2876.20	3324.40	4858.60								

SURFACE AREA= 32. 34. 49. 69.

CAPACITY= 0. 266. 504. 1674.

ELEVATION= 1026. 1034. 1040. 1060.

CREL	SPWID	COQM	EXPW	ELEV	COUL	CAREA	EXPL
1034.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

TOPEL	CUQD	EXPJ	UAMWID
1035.6	3.1	1.5	120.

CREST LENGTH AT OR BELOW ELEVATION	0.	69.	90.	112.	117.	124.	128.	135.
1035.0	1035.0	1036.5	1037.0	1037.5	1038.0	1038.5	1039.0	

PEAK OUTFLOW IS 9234. AT TIME 43.50 HOURS

PEAK OUTFLOW IS 4605. AT TIME 43.50 HOURS

PEAK OUTFLOW IS 2289. AT TIME 43.50 HOURS

PEAK OUTFLOW IS 413. AT TIME 44.00 HOURS

PEAK OUTFLOW IS 56. AT TIME 46.00 HOURS

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLJWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE FEET (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIO	RATIOS APPLIED TO FLOWS				
					RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5
					1.00	0.50	0.25	0.05	0.01
HYDROGRAPH AT	1	13.83	1	9332.	4666.	2333.	467.	93.	
				264.25	132.12	66.06	13.21	2.64	
ROUTED TO	2	13.83	1	9234.	4605.	2289.	413.	56.	
				261.49	130.74	64.87	11.59	1.60	

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1									
ELEVATION		INITIAL VALUE		SPILLWAY CREST		TOP OF DAM			
STORAGE		1034.00		1034.00		1035.60			
OUTFLOW		259.		259.		315.			
		0.		0.		249.			
RATIO OF PWF	MAXIMUM RESERVOIR 4.5-LEVEL	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS		TIME OF FAILURE HOURS	
	1.00	1042.19	6.59	613.	9234.	27.50	43.50	0.0	0.0
	0.50	1039.77	4.17	493.	4605.	20.50	43.50	0.0	0.0
	0.25	1038.19	2.59	420.	2289.	15.00	43.50	0.0	0.0
	0.05	1036.05	0.45	333.	413.	6.00	44.00	0.0	0.0
0.01	1034.78	0.0	286.	56.	0.0	46.00	0.0	0.0	
SPILLWAY CAPACITY ANALYSIS									
17									
18									
19									
20									
21									
22									
23									
24									
25									
26									
27									
28									
29									
30									
31									
32									
33									
34									
35									
36									
37									
38									
39									
40									
41									
42									
43									
44									
45									
46									
47									
48									
49									
50									
51									
52									
53									
54									
55									
56									
57									
58									
59									
60									
61									
62									
63									
64									
65									
66									
67									
68									
69									
70									
71									
72									
73									
74									
75									
76									
77									
78									
79									
80									
81									
82									
83									
84									
85									
86									
87									
88									
89									
90									
91									
92									
93									
94									
95									
96									
97									
98									
99									
100									

SHEET 11 OF 17

 FLUID HYDROGRAPH PACKAGE (ALG-LJ)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 26 FEB 79
 NBJ UPDATE 04 JUN 79

ANALYSIS OF PART FAILURE

NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
 HYDRAULIC AND HYDRAULIC ANALYSIS OF LOWER ALFORD POND DAM
 UNIT HYDROGRAPH BY SNTUERS METHOD

PLAN 1 - FAILURE

PLAN 2 - NON-FAILURE

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

ROUTING FOR LOWER ALFORD POND DAM

 FLUJO HYDROGRAPH PACKAGE (JUL-1)
 DAM SAFETY VERSION JULY 1973
 LAST MODIFICATION 26 FEB 79
 MAJ UPDATE 04 JUL 79

RUN DATE 12/11/80
 TIME 11.15

NATIONAL PROGRAM FOR INSPECTION OF NJN-FEDERAL DAMS
 HYDRAULIC AND HYDRAULIC ANALYSIS OF LOWER ALPORD POND DAM
 UNIT HYDROGRAPH BY SNYDERS METHOD

JOB SPECIFICATION

NO	HR	MIN	DAY	JHR	MIN	NETC	IPLT	IPRT	NSTAN
500	0	5	0	0	0	J	0	-4	0
	JOPER	NMI	LROPT	TRAGE					
	5	0	0	0	0				

MULTI-PLAN ANALYSES TO BE PERFORMED
 NPLAN= 2 NRTIO= 1' LRTIO= 1

KILUS= 0.50

SUB-AREA RUNOFF COMPUTATION

RJHOFF HYDROGRAPH TO DAM

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPRI	INATE	ISTAGE	IAUTO
1	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

INVOG	IJNG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
1	1	5.34	0.0	5.34	0.0	0.0	0	1	0

PRECIP DATA

SPEE	PMS	R6	R12	R24	R48	R72	R96
0.0	21.00	111.00	123.00	133.00	142.00	0.0	0.0

TRSPC COMPUTED BY THE PROGRAM IS 0.800

LUSS DATA

LMDPT	STRAX	DLTKR	RTIOL	ERAIN	STAKS	RTIOK	STRTL	UNSTL	ALSNX	RTIMP	ISL	ISL
0	0.0	0.0	1.00	0.0	0.0	1.00	1.00	0.00	0.0	0.0	0.0	0.0

UNIT HYDROGRAPH DATA
 IP= 3.44 CP=0.62 NTA= 0

RECESSION DATA
 STRIQ= -1.50 SRCNS= 0.05 RTIUP= 2.00

UNIT HYDROGRAPH END-OF-PERIOD ORIGINATES, LAG= 3.44 HOURS, CP= 0.62 VUL= 0.86

3.	13.	20.	32.	47.	62.	79.	97.	116.	135.
156.	177.	198.	221.	243.	266.	289.	313.	337.	361.
386.	411.	435.	459.	481.	507.	522.	543.	557.	572.
586.	599.	610.	620.	629.	636.	642.	646.	648.	649.

NOTE: UNIT HYDROGRAPH VOLUME
 IS SLIGHTLY LESS THAN 1.0 DUE
 TO COMPUTER PROGRAM
 LIMITATIONS FOR A RAINFALL DURATION
 OF 5 MIN. HOWEVER THE 5 MIN.
 DURATION IS NECESSARY FOR
 DOWNSTREAM ROUTING DURING
 FAILURE CONDITIONS.

0	HR.MN	PERIOD	RAIN	EXCS	LOSS	CUMP Q	MU.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	CUMP J
649.	600.		641.	634.	622.	607.	591.	576.	562.	547.			
533.	523.		507.	494.	481.	469.	457.	445.	434.	423.			
412.	402.		391.	382.	372.	362.	353.	344.	335.	327.			
319.	313.		303.	295.	287.	280.	273.	266.	259.	253.			
246.	240.		234.	228.	222.	216.	208.	200.	195.	191.			
190.	185.		181.	176.	172.	167.	163.	159.	155.	151.			

END-OF-PERIOD FLOW

MU.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	CUMP Q	MU.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	CUMP J
SUM	23.05	21.47	2.34	735263.									
	1	606.11	545.11	61.1	120792.041								

HYDROGRAPH ROUTING

ROUTING FOR LOWER ALEORD POND DAM

ISTAQ	ICUMP	IECUN	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTU
2	1	0	0	0	0	1	0	0

ALL PLANS HAVE SAME

ROUTING DATA

QJUS	GLUSS	AVG	IRCS	ISAME	IUPT	IPMP	LSTR
0.0	0.0	0.0	1	1	0	0	0

NSTPS	NSTOL	LAG	AMSKK	X	TSK	STURA	ISPRAT
1	0	0	0.0	0.0	0.0	-1034.	-1

STAGE	1034.00	1034.50	1035.00	1035.40	1036.10	1036.30	1036.90	1037.60	1038.40	1039.20
1041.40	1042.90	1044.40								

FLOW	0.0	28.37	91.50	189.60	398.50	446.20	653.60	947.50	1275.70	2022.60
2876.20	3824.40	4858.60								

SURFACE AREA= 32. 34. 49. 69.

CAPACITY= 0. 266. 504. 1674.

ELEVATION= 1026. 1034. 1040. 1060.

UFEL	SPWID	COUW	EXPW	ELEV	COQL	CAREA	EXPL
1034.1	0.0	0.0	0.0	0.0	0.0	0.0	0.0

DAM DATA

TOPEL	CUGD	EXPJ	DAMWID
1035.6	3.1	4.5	120.

CREST LENGTH	0.	69.	90.	112.	117.	124.	128.	135.
AT OR BELOW								

ELEVATION	1035.0	1036.0	1036.5	1037.0	1037.5	1038.0	1038.5	1039.0

DAM BREACH DATA

BRWID	120.	1.00	1023.00	0.50	1034.20	1039.60

WARNING *** TOP OF DAM, BOTTOM OF BREACH, OR LOW-LEVEL OUTLET IS NOT WITHIN RANGE OF GIVEN ELEVATIONS IN STORAGE-ELEVATION DATA
 BOTTOM OF RESERVOIR ASSUMED TO BE AT 1026.20
 STORAGE-ELEVATION DATA WILL BE EXTRAPOLATED ABOVE ELEVATION 1060.00

BEGIN DAM FAILURE AT 42.00 HOUR.

PEAK OUTFLOW IS 13684. AT TIME 43.00 HOURS

DAM BREACH DATA
BRWD 120. Z 1.00 ELUM 1023.00 IFAIL 0.57 MSL 1034.20 FAILL 1045.00

WARNING *** TOP OF DAM, BOTTOM OF BREACH, OR LOW-LEVEL OUTLET IS NOT WITHIN RANGE OF GIVEN ELEVATIONS IN STORAGE-ELEVATION DATA
BOTTOM OF RESERVOIR ASSUMED TO BE AT 1026.20
STORAGE-ELEVATION DATA WILL BE EXTRAPOLATED ABOVE ELEVATION 1060.00

PEAK OUTFLOW IS 4592. AT TIME 43.17 HOURS

HYDROGRAPH ROUTING

ROUTED TO SECTION 1700 FEET DOWNSTREAM OF DAM

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPAT	INAME	ISTAGE	IAUTO
3	1	0	0	0	0	1	0	0

ALL PLANS HAVE SAME

ROUTING DATA

WLUSS	WLUSS	AVG	IRIS	ISAME	IUPT	IPMP	LSIK
0.3	0.0	0.0	1	1	0	0	0

NSTPS	MSIDL	LAG	AMSKK	X	ISK	STORA	ISPRAT
1	0	0.0	0.0	0.0	0.0	0.0	0

NORMAL DEPTH CHANNEL ROUTING

ON(1) ON(2) ON(3) ELAVI ELMAX RLNTH SLL
0.0400 0.0400 0.0400 1013.5 1040.0 1200. 0.00490

CROSS SECTION COORDINATES--STA,ELEV,STA,ELEV--ETC
0.0 1040.00 125.00 1020.00 135.00 1015.00 145.00 1013.50 150.00 1013.50

160.00 1015.00 170.00 1020.00 300.00 1040.00

STORAGE	0.0	0.25	1.78	3.66	6.18	9.34	13.08	17.41	22.31	27.79
	33.84	40.47	47.67	55.45	63.81	72.74	82.25	92.33	102.99	114.22
OUTFLOW	2.0	46.20	251.97	634.36	1216.90	2027.77	3089.69	4415.42	6024.10	7934.51
	10165.00	12733.51	15657.60	18954.41	22640.80	26733.22	31247.84	36200.56	41607.02	47482.56
STAGE	1013.50	1014.39	1016.29	1017.68	1019.08	1020.47	1021.87	1023.26	1024.66	1026.05
	1021.45	1028.14	1030.23	1031.63	1033.32	1034.42	1035.81	1037.21	1038.60	1040.00
FLOW	0.0	46.20	251.97	634.36	1216.90	2027.77	3089.69	4415.42	6024.10	7934.51
	10165.00	12733.51	15657.60	18954.41	22640.80	26733.22	31247.84	36200.56	41607.02	47482.56

MAXIMUM STAGE IS 1029.2

MAXIMUM STAGE IS 1023.4

100

SHEET 16 OF 17

—

—

APPENDIX E

PLATES


CONTENTS

Plate 1 - Location Plan

Plate 2 - Watershed Map


Plate 3 - Field Sketch Plan from Field Inspection


Plate 4 - Top of Dam Profile and Typical Cross Section
from Field Inspection



REFERENCES:
1. U.S.G.S. 7.5' MONTROSE EAST, PA.
QUADRANGLE PHOTOREVISED 1978

PLATE I LOCATION PLAN
LOWER ALFORD DAM






MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS


Box 280
Beaver, Pa. 15009

Subject LOWER FLEED DAM S.O. No. 13837-00-ARR-06
TOP OF DAM PROFILE Sheet No. 4 of 17
TYPICAL CROSS SECTION Drawing No. _____
Computed by GWT Checked by WDX Date 11-17-80

TOP OF DAM PROFILE (LOOKING DOWNSTREAM)
LENGTH OF DAM = 120 FEET



TYPICAL CROSS SECTION AT STA. 0+70



APPENDIX F


REGIONAL GEOLOGY

LOWER ALFORD DAM
NDI No. PA 00053, PennDER No. 58-47

REGIONAL GEOLOGY

Lower Alford Dam is located in the Glaciated Low Plateaus physiographic province. The area has been glaciated at least three times and is presently covered with Wisconsin Stage deposits. The land drains to the south and has a maximum relief of approximately 500 feet. According to the Soil Conservation Service's Soil Survey for Susquehanna County, the surface soils in the vicinity of the dam consist primarily of silt loams on the valley floor and very stoney, silt loams on the valley walls. All soils are of the Mardin-Volusia-Oquaga association. No test boring data were available for review, thus, the thickness of this overburden is difficult to ascertain.

Geologic references indicate that the bedrock in the vicinity of the dam consists of members of the Catskill Formation in the Susquehanna Group. The Catskill Formation contains red and gray shales and sandstones of Upper Devonian age. The formation may also contain scattered, thin, streaks of coal and scattered fish remains. The strata near Lower Alford Pond were deposited in a bay or delta front environment and remain essentially horizontal after the Appalachian Uplift.



GEOLOGY MAP LEGEND

DEVONIAN UPPER

WESTERN PENNSYLVANIA

- Oawayo Formation**
Greenish gray to gray shales, siltstones and sandstones becoming increasingly shaly westward, considered equivalent to type Oawayo, Riceville Formation Or in Erie and Crawford Counties, probably not distinguishable north of Carry.
- Dcr** **Cattaraugus Formation**
Red, gray and brown shale and sandstone with the proportion of red decreasing westward, includes Venango sands of drillers and Salamanca sandstone and conglomerate, some limestone in Crawford and Erie counties.
- Conneaut Group**
Alternating gray, brown, greenish and purplish shales and siltstones, includes "pink rock" of drillers and "Chemung" and "Girard" Formations of northwestern Pennsylvania.
- Canadaway Formation**
Alternating brown shales and sandstones, includes "Portage" Formation of northwestern Pennsylvania.

CENTRAL AND EASTERN PENNSYLVANIA

- Oawayo Formation**
Brownish and greenish gray, fine and medium grained sandstones with some shales and scattered calcareous lenses, includes red shales which become more numerous eastward. Relation to type Oawayo not proved.
- Dck** **Catskill Formation**
Chiefly red to brownish shales and sandstones, includes gray and greenish siltstone tongues named Elk Mountain, Honadale, Shohola, and Delaware River in the east.
- Dm** **Marine beds**
Gray to olive brown shales, graywackes, and sandstones, contains "Chemung" beds and "Portage" beds including Burket, Butler, Hurrell, and Trimmers Rock, Tully Limestone at base.

Ds

Susquehanna Group

Barbed line is "Chemung-Catskill" contact of Second Pennsylvania Survey County reports, barbs on "Chemung" side of line.

MIDDLE AND LOWER

Oh
Hamilton Group

- Mahantango Formation**
Brown to olive shale with interbedded sandstones which are dominant in places (Montebello); highly fossiliferous in upper part; contains "Centerfield coral bed" in eastern Pennsylvania.
- Marcellus Formation**
Black, fissile, carbonaceous shale with thick, brown sandstone (Turkey Ridge) in parts of central Pennsylvania.
- Onondaga Formation**
Greenish blue, thin bedded shale and dark blue to black, medium bedded limestone with shale predominant in most places; includes Selinogora Limestone and Needmore Shale in central Pennsylvania and Butterfield Falls Limestone and Enopus Shale in easternmost Pennsylvania; in Lehigh Gap area includes Palmerton Sandstone and Howmanstown Chert.
- Oriakany Formation**
White to brown, fine to coarse grained, partly calcareous, locally conglomeratic, fossiliferous sandstone (Kidgeley) at the top; dark gray, cherty limestone with some interbedded shales and sandstones below (Shriver).
- Helderberg Formation**
Dark gray, calcareous, thin bedded shale (Mandata) at the top, equivalent to Port Ewen Shale and Hervaft Limestone in the east; dark gray, cherty, thin bedded, fossiliferous limestone (New Scotland) with some local sandstones in the middle; and, at the base dark gray, medium to thick bedded, crystalline limestone (Creminal) sandy and shaly in places with some chert nodules.

Dm

END

DATE
FILMED

5 81

DTIC