


AD-A105 001

KIMBALL (L ROBERT) AND ASSOCIATES EBENSBURG PA
NATIONAL DAM SAFETY PROGRAM. SHEPARD MOUNTAIN DAM (MO 30324), M--ETC(U)
AUG 79 L R KIMBALL DACW43-79-C-0034
NL

UNCLASSIFIED

1 of 1
AD
207-00



END
DATE
FILMED
10-81
DTIC

LEVEL

①
B3

MISSISSIPPI - KASKASKIA - ST. LOUIS BASIN

**SHEPARD MOUNTAIN DAM
IRON COUNTY, MISSOURI
MO 30324**

SELECTED
OCT 6 1981
H

AD A105001

**PHASE 1 INSPECTION REPORT
NATIONAL DAM SAFETY INSPECTION**

DTIC FILE COPY



**United States Army
Corps of Engineers**
... Serving the Army
... Serving the Nation

St. Louis District

"Original contains color plates: All DTIC reproductions will be in black and white"

DISTRIBUTION STATEMENT A
Approved for public release;
Distribution Unlimited

PREPARED BY: U. S. ARMY ENGINEER DISTRICT, ST. LOUIS

FOR: STATE OF MISSOURI

AUGUST 1979

81 10 2 185

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO. AD-A10 5001	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Dam Inspection Report National Dam Safety Program Shepard Mountain Dam (MO 30324) Iron County, Missouri		5. TYPE OF REPORT & PERIOD COVERED Final Report.
7. AUTHOR(s) L. Robert Kimball and Associates (19) L. R. Kimball		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		8. CONTRACT OR GRANT NUMBER(s) 15 DACW43-79-C-0034
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) 6 National Dam Safety Program, Shepard Mountain Dam (MO 30324), Mississippi - Kaskaskia - St. Louis Basin, Iron County, Missouri. Phase I Inspection Report.		12. REPORT DATE 11 August 1979
16. DISTRIBUTION Approved for release; distribution unlimited.		13. NUMBER OF PAGES Approximately 45
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		15. SECURITY CLASS. (of this report) UNCLASSIFIED
18. SUPPLEMENTARY NOTES		5a. DECLASSIFICATION/DOWNGRADING SCHEDULE 12 52
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety, Lake, Dam Inspection, Private Dams		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report was prepared under the National Program of Inspection of Non-Federal Dams. This report assesses the general condition of the dam with respect to safety, based on available data and on visual inspection, to determine if the dam poses hazards to human life or property.		

DD FORM 1 JAN 73 1473

EDITION OF 1 NOV 65 IS OBSOLETE

411059

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

SHEPARD MOUNTAIN DAM
IRON COUNTY, MISSOURI

MISSOURI INVENTORY NO. 30324

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

PREPARED BY

L. ROBERT KIMBALL AND ASSOCIATES
CONSULTING ENGINEERS AND ARCHITECTS
EBENSBURG, PENNSYLVANIA

UNDER DIRECTION OF
ST. LOUIS DISTRICT, CORPS OF ENGINEERS
FOR
GOVERNOR OF MISSOURI

AUGUST 1979



DEPARTMENT OF THE ARMY
 ST. LOUIS DISTRICT, CORPS OF ENGINEERS
 210 NORTH 12TH STREET
 ST. LOUIS, MISSOURI 63101

IN REPLY REFER TO

SUBJECT: Shepard Mountain Dam Phase I Inspection Report

This report presents the results of field inspection and evaluation of the Shepard Mountain Dam. It was prepared under the National Program of Inspection of Non-Federal Dams.

SUBMITTED BY: SIGNED 23 AUG 1979
 Chief, Engineering Division Date

APPROVED BY: SIGNED 23 AUG 1979
 Colonel, CE, District Engineer Date

Accession stamp with a checkmark and the letter 'A' written below it.

Accession stamp
 NTIS
 LDC
 U.S. Army
 Corps of Engineers
 St. Louis District
 By
 Date
 A

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I REPORT

NATIONAL DAM SAFETY PROGRAM

NAME OF DAM	Shepard Mountain Dam
STATE LOCATED	Missouri
COUNTY LOCATED	Iron
STREAM	Unnamed Tributary to Stouts Creek
DATE OF INSPECTION	30 April 1979

Shepard Mountain Dam was inspected using the "Recommended Guidelines for Safety Inspection of Dams". These guidelines were developed by the Chief of Engineers, U.S. Army, Washington, D.C., with the help of federal and state agencies, professional engineering organizations, and private engineers. The resulting guidelines are considered to represent a consensus of the engineering profession.

Based on the criteria in the guidelines, the dam is in the high hazard potential classification, which means that loss of life and appreciable property loss could occur in the event of failure of the dam. The dam is in the small size classification since it is greater than 25 feet high but less than 40 feet high. The downstream affected area includes Highway M located immediately downstream of the dam, a dwelling .15 miles downstream, a dwelling .35 miles downstream, and portions of the towns of Ironton and Acadia 2.5 miles downstream of the dam. Based on this downstream exposure the Spillway Design Flood for this dam is the PMF.

Because of the configuration of the dam with a total overflow spillway section, the dam is capable of controlling the PMF from a hydrologic standpoint. However, spillway capacity is related to the structural adequacy of the dam. If the dam cannot withstand the high loading induced by the PMF then it can be stated that the spillway cannot control the PMF. No structural analyses have been performed on the structure and it is uncertain whether the dam can tolerate the loading.

Deficiencies visually observed for Shepard Mountain Dam were minor spalling of the gunite surface and inoperable valves. It must be noted that the condition of the concrete under the gunite and on the upstream face was unobserved. These deficiencies should be remedied at the direction of a professional engineer knowledgeable in dam design to avoid creating an unsafe condition. Concrete may deteriorate with age and review of the safety of the structure should be made at an on-going basis. The lack of stability, stress and seepage analyses, a warning system, and a formal inspection program should be corrected.

It is recommended that the owner take action to correct or control the deficiencies described.

R Jeffrey Kimball

R. JEFFREY KIMBALL, P.E.
L. Robert Kimball & Associates
Vice President, Earth Sciences

James T. Hockensmith

JAMES T. HOCKENSMITH
L. Robert Kimball & Associates
Geologist

K. Chuang

KUANG HWEI CHUANG, P.E.
L. Robert Kimball & Associates
Hydraulic Engineer



Shepard Mountain Dam - Overview

TABLE OF CONTENTS

	PAGE
SECTION 1 - PROJECT INFORMATION	
1.1 General	1
1.2 Description of Project	1
1.3 Pertinent Data	2
SECTION 2 - ENGINEERING DATA	
2.1 Design	5
2.2 Construction	5
2.3 Operation	5
2.4 Evaluation	5
SECTION 3 - VISUAL INSPECTION	
3.1 Findings	6
3.2 Evaluation	7
SECTION 4 - OPERATIONAL PROCEDURES	
4.1 Procedures	8
4.2 Maintenance of the Dam	8
4.3 Maintenance of Operating Facilities	3
4.4 Description of any Warning System in Effect	8
4.5 Evaluation	8
SECTION 5 - HYDRAULIC/HYDROLOGIC	
5.1 Evaluation of Features	9
SECTION 6 - STRUCTURAL STABILITY	
6.1 Evaluation of Structural Stability	11
SECTION 7 - ASSESSMENT AND RECOMMENDATIONS/REMEDIAL MEASURES	
7.1 Dam Assessment	12
7.2 Recommendations/Remedial Measures	12

LIST OF APPENDICES

APPENDIX A - DRAWINGS

APPENDIX B - HYDROLOGY AND HYDRAULICS

APPENDIX C - PHOTOGRAPHS

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
SHEPARD MOUNTAIN LAKE DAM - ID NO. 30324

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL.

a. Authority. The National Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of safety inspection of dams throughout the United States. Pursuant to the above, the St. Louis District, Corps of Engineers, District Engineer directed that a safety inspection of the Shepard Mountain Lake Dam be made.

b. Purpose of Inspection. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based on available data and visual inspection, in order to determine if the dam poses hazards to human life or property.

c. Evaluation Criteria. Criteria used to evaluate the dam were furnished by the Department of the Army, Office of the Chief of Engineers, in "Recommended Guidelines for Safety Inspection of Dams". These guidelines were developed with the help of several Federal Agencies and many state agencies, professional engineering organizations, and private engineers.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam and Appurtenances.

(1) Shepard Mountain Lake Dam is a concrete arch dam with a concrete section at the right abutment. The arch portion of the dam is 287.4 feet long and approximately 35 feet high. The dam has a felsite foundation. The top width of the dam is 4 feet, the base thickness is unknown. The right abutment is formed by a 90 foot long concrete section. This concrete section is approximately 5 feet high. The top width is 2 feet. The left abutment is formed by a felsite outcrop. Beyond this felsite outcrop is a concrete wingwall approximately 2 feet high.

The outlet works consist of two 8 foot diameter concrete towers. In the concrete towers are pumps which pump water to the water treatment plant. Three drainlines are located through the concrete arch section of the dam. These drainlines are 6", 9" and 12" cast iron pipes. Both the concrete arch and concrete abutment section act as overflow sections and form the spillway.

Upstream of Shepard Mountain Lake is Snow Hollow Dam (drainage area 481 acres). Snow-Hollow Dam is an earth fill dam 530 feet long and 35 feet high. The dam has two spillways cut in rock (one on each abutment).

Immediately downstream of Shepard Mountain Dam is State Road M. Overflow from the spillway flows under State Road M through a box culvert.

b. Location. Shepard Mountain Lake Dam is located approximately 1.5 miles west of Ironton, Missouri on an unnamed tributary to Stouts Creek. The dam can be located (Section 1, Township 33 North, Range 3 East) on the Ironton, Missouri 7.5 minute U.S.G.S. Quadrangle.

c. Size Classification. Shepard Mountain Lake Dam is a small size dam (36 feet high, 168 acre-feet).

d. Hazard Classification. Shepard Mountain Lake Dam is a high hazard dam. Downstream conditions indicate that loss of life is probable should failure of the structure occur.

e. Ownership. Shepard Mountain Lake Dam is owned by the City of Ironton. Correspondence should be addressed to:

City of Ironton
Ironton, Missouri 63650
314-546-3069

f. Purpose of Dam. Shepard Mountain Lake Dam is used for water supply.

g. Design and Construction History. Design and construction history was unavailable for Shepard Mountain Lake Dam. No design drawings, reports or construction history exists.

h. Normal Operating Procedures. No operating records exist. The reservoir is maintained at the spillway crest with the excess inflow discharging over the spillway. Water is drawn off the reservoir on an as-needed basis.

1.3 PERTINENT DATA

- a. Drainage Area. 7.07 square miles
(includes upstream dam)
- b. Discharge at Damsite (cfs).
- | | |
|-------------------------------------|----------------------|
| (1) Maximum known flood at dam site | Approximately 10,000 |
| | in 1974 |
| (2) Ungated spillway capacity | PMF - 52,054 |
| (3) Gated spillway capacity | N/A |
| (4) Drainlines | Unknown |

c. Elevation (feet) - Based on spillway crest shown on U.S.G.S. quadrangle.

(1) Top of dam	977.0
(2) Spillway crest	977.0
(3) Normal pool	977.0
(4) Maximum pool (PMF)	987.0
(5) Invert 6" CIP	953.5
(6) Invert 9" CIP	963.5
(7) Invert 12" CIP	949.5
(8) Tailwater on day of inspection	944.5
(9) Streambed at centerline of dam	941.0

d. Reservoir (feet).

(1) Length of maximum pool	2300
(2) Length of normal pool	2300

e. Storage (acre-feet).

(1) Top of dam	168
(2) Spillway crest	168
(3) Normal pool	168
(4) Maximum pool (PMF)	558

f. Reservoir Surface (acres).

(1) Top of dam	21
(2) Spillway crest	21
(3) Normal pool	21
(4) Maximum pool (PMF)	56

g. Dam.

(1) Type	Concrete arch
(2) Length	377.5 feet
(3) Height	36 feet
(4) Top width	4 feet - concrete arch section 2 feet - concrete abutment section
(5) Side slopes	Upstream - unknown Downstream - near vertical
(6) Zoning	None
(7) Grout Curtain	None
(8) Cutoff	Unknown

h. Diversion and Regulating Tunnel.

(1) Type	6", 9", and 12" Cast Iron Pipes
(2) Elevation (feet)	6" - 953.5 9" - 963.5 12" - 949.5

(3) Length	Each approximately 8 feet long
(4) Closure	Downstream of dam
(5) Access	Downstream of dam

i. Spillway.

(1) Type	Uncontrolled-broad crested weir
(2) Length	377.5 feet
(3) Crest elevation	977.0 feet
(4) Upstream channel	Lake
(5) Downstream channel	Unnamed tributary to Stouts Creek and Stouts Creek
(6) Gates	None

SECTION 2 - ENGINEERING DATA

2.1 DESIGN. No design drawings, reports or data are known to exist.

2.2 CONSTRUCTION. The date of original construction is unknown. The lake was reportedly used for recreation. In 1955, the City of Ironton bought the reservoir. At this time, the dam was raised 5 feet and gunited.

2.3 OPERATION. No operating records exist.

2.4 EVALUATION

a. Availability. No engineering data is available.

b. Adequacy. The field surveys and visual inspections presented herein are considered adequate to support the conclusion of this report. Seepage and structural analyses comparable to the requirements of the guidelines are not on record. This is a deficiency which should be rectified.

c. Validity. Not applicable.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

a. General. The onsite inspection of Shepard Mountain Lake Dam was conducted by personnel of L. Robert Kimball and Associates accompanied by the owner's water superintendent, Ralph Kloess, on April 30, 1979. The inspection team consisted of a hydrologist, structural/soils engineer and a geologist. The inspection consisted of:

1. Visual inspection of the retaining structure, abutments and toe.
2. Examination of the spillway facilities, exposed portions of any outlet works, and other appurtenant works.
3. Observations affecting the runoff potential of the drainage basin.

b. Project Geology. Shepard Mountain Lake Dam is underlain by Precambrian felsites. These are chiefly rhyolite porphyries with some rhyolites and tuffs.

Structural features in the area include the Ironton and Hogan Mountain Faults. The Ironton Fault has not yet been fully substantiated but is believed to extend for over ten miles in a northwest-southeast direction and to pass within two miles northeast of the dam. It is also uncertain as to whether this is a normal or reverse fault and what the displacement is since little work has been done in this area.

The Hogan Mountain Faults lie approximately 1 to 2 miles southwest of the dam. They consist of three faults which strike to the northeast. The down thrown sides are the northwestern sides, but the displacements are unknown. Jointing is probably present in these rocks, but to an unknown degree.

c. Dam and Spillway. Visual inspection of the dam indicated the structure was in good condition. From a brief survey conducted during the inspection it was determined that the spillway elevation is fairly even (977.0). The entire dam is covered with gunite. Close examination of the concrete was impossible because of the gunite surface. One portion of the gunite was missing (see Figure 2 for location). Because of the water discharging over the spillway and running down the face of the dam, examination for any seepage zones was not possible. No cracks or major deteriorated zones were noted. Approximately 3 feet of tailwater was present during the inspection. The right and left abutments are formed by gently sloping grassed areas with occasional felsite outcrops.

d. Appurtenant Structures. The outlet works consist of two 8 foot diameter concrete towers. It is reported that pumps are located in the concrete towers to pump water to the water treatment plant. Examination of the inside of the outlet works was not conducted during the inspection. Three drainlines are located through the dam at different elevations. The drainlines are 6", 9" and 12" cast iron pipes. The 6" and 9" cast iron pipes contain no valves at the discharge end. The 12" cast iron pipe is inoperable because of a cracked valve. It was reported by the water superintendent that the drainlines have not been operated since 1955.

e. Reservoir Area. No pertinent problems were noted in the reservoir area. The watershed is moderately steep, wooded and undeveloped.

f. Downstream Channel. Discharges from the spillway enter the unnamed tributary of Stouts Creek for a distance of approximately 400 feet before flowing into Stouts Creek.

3.2 EVALUATION. The visual inspection did not reveal any immediate signs of instability. The dam appeared to be in good condition. However, the presence of the gunite over the entire concrete surface may obscure deterioration of the concrete. In addition, water flowing over the spillway weir and down the downstream portion of the dam may have obscured any seepage present. Examination of the upstream face was impossible because of the high reservoir level.

Complete evaluation of the structure cannot be made without a detailed stability analysis or stress analysis with test results of the concrete and knowledge on the geometry of the section.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES. The reservoir is maintained at the spillway crest at all times. Water is drawn off the reservoir on an as-needed basis.

4.2 MAINTENANCE OF THE DAM. No major maintenance of the dam has been conducted since the dam was purchased by the City of Ironton in 1955.

4.3 MAINTENANCE OF OPERATING FACILITIES. The outlet works are maintained on an as-needed basis. The drainlines have not been maintained since before 1955.

4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT. There is no warning system in effect.

4.5 EVALUATION. Maintenance of the dam and operating facilities is considered fair. There is no warning system in effect to warn downstream residences of large spillway discharges or failure of the dam.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

a. Design Data. There are no hydraulic and hydrological design data available.

b. Experience Data. The drainage area was developed using the U.S.G.S. quadrangle sheet. The lake surface area was determined by planimetering the quadrangle sheet. Surface area - elevations were determined by planimetering various contour lines within the drainage area on the U.S.G.S. quadrangle sheets. The spillway and dam layout was obtained from surveys conducted during the inspection.

c. Visual Observations. The dam is constructed as a total overflow section. The spillway is 377.5 feet long. During flooding, the right abutment and left abutment will carry flow and act as a portion of the spillway.

d. Overtopping Potential. Overtopping potential was investigated through the development of the probable maximum flood (PMF) for the watershed and the subsequent routing of the PMF and fractions of the PMF through the reservoir and spillway.

The Corps of Engineers, St. Louis District, has directed that the HEC-1 Dam Safety Version systemized computer program be utilized. The program was prepared by the Hydraulic Engineering Center (HEC) U.S. Army Corp of Engineers, Davis California, July, 1978. The major methodologies or key input data for this program are discussed in Appendix B.

To enable us to complete the hydraulic and hydrologic analysis for this structure, it was necessary to make the following assumptions:

1. Water level prior to flood was at the spillway crest or top of dam (elevation 977.0).
2. Flow was allowed over the abutments.

Complete summary sheets of the computer output are presented in Appendix B. To facilitate review, the major results of the overtopping analysis are presented below:

Peak Inflow	53,219 cfs
Maximum Outflow	52,504 cfs

Ratio of PMF	Maximum Reservoir Water Surface El. (ft.)	Maximum Depth over dam (concrete spillway,ft)	Maximum Outflow, (cfs)	Duration of Over- topping, (hours)
.10	979.38	2.38	4649	.67
.20	980.71	3.71	9489	1.92
.30	981.76	4.76	14514	4.75
.40	982.65	5.65	19632	5.75
.50	983.49	6.49	25048	6.08
1.00	986.95	9.95	52054	6.92

The Corps of Engineers Spillway Design Flood for a high hazard-small dam is 1/2 PMF to the PMF. Based on the downstream exposure, the Spillway Design Flood for this dam is the PMF. The spillway is capable of discharging the PMF with flow over the abutments. The abutment sections should be able to withstand some overtopping. Because of the rather shallow soil depth and the nature (felsite) of the bedrock on the abutments, no severe erosion of the abutments is anticipated. The dam is capable of passing the PMF from a hydraulics standpoint, but the dam may not be able to withstand this high overtopping from a structural point. With a high water level the dam could fail from sliding, over-stress of concrete, or shearing.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations. Visual observations did not reveal any signs of immediate instability. No zones of cracking or deterioration of the concrete were noted because the gunited surface obscured most of the concrete. No misalignment or deflection of the structure was noted. The foundation rock appears to be competent but the characteristics of the foundation/concrete contact is unknown.

b. Design and Construction Data. No design or construction data is available on the dam. No dimensions of the dam cross-section are known. No testing of the concrete was performed. No structural analyses of the dam have been conducted. Stability stress or seepage analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency.

c. Operating Records. No operating records are kept on the structure.

d. Post-Construction Changes. The dam was raised 5 feet in 1955. No details or drawings are available for this change or the original construction.

e. Seismic Stability. The dam is located in seismic zone 2, to which the guidelines assign a "moderate" damage potential. No seismic structural analysis has been conducted.

SECTION 7 - ASSESSMENT AND RECOMMENDATIONS/REMEDIAL MEASURES

7.1 DAM ASSESSMENT

a. Safety. The visual observations, review of available data, hydrologic calculations, and past operational performance indicate that Shepard Mountain Lake Dam's spillway is adequate. The spillway is capable of controlling the PMF. This is based on the abutments acting as a portion of the spillway. Since much of the abutments consist of felsite outcrops, it is believed that the abutments can control this flow without any adverse effects. The structural adequacy of the dam is unknown. The structure should be evaluated for critical loading conditions.

The dam appeared to be in good condition. No cracks, seepage zones or deteriorated zones were noted. However, the gunited surface may obscure any deficiencies, if present. No design drawings with data on construction of the dam is available. Stability, stress or seepage analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency.

It must be noted that concrete deteriorates with age. Safety reviews of this structure should be made on an on-going basis. Periodic inspections and reevaluation should be conducted.

b. Adequacy of Information. Complete assessment of the structural adequacy of the structure cannot be made because of the limited design data, construction data, and no past stability or stress analyses comparable to the requirements of "Recommended Guidelines for Safety Inspection of Dams".

c. Urgency. The deficiencies described herein are serious and corrective actions listed below should be initiated promptly.

d. Necessity for Phase II. In order to accomplish some of the recommendations/remedial measures outlined below, further investigations will be required.

7.2 RECOMMENDATIONS/REMEDIAL MEASURES

a. A detailed stability, stress and seepage analysis comparable to the requirements of "Recommended Guidelines for Safety Inspection of Dams" should be conducted by a registered professional engineer knowledgeable in dam design. The analyses should be conducted using the maximum anticipated water levels. Core samples of the concrete should be removed from the dam and the concrete should be tested. The structural adequacy of the Snow Hollow Dam should be periodically checked since failure of this dam would increase overtopping and possible performance of Shepard Mountain Dam.



b. The damaged valve on the 12" cast iron pipe should be repaired.

c. All drainlines should be repaired. The valves should be exercised and lubricated at six month intervals.

d. Institute a formal inspection program to be conducted at regular intervals.

e. Institute a formal warning system to warn downstream residences of high spillway discharges or failure of the dam.

APPENDIX A
DRAWINGS



VICINITY MAP
 SHEPARD MOUNTAIN DAM
 Scale: 1" = 2000'




FIGURE 2

APPENDIX B
HYDROLOGY AND HYDRAULICS

APPENDIX B

HYDROLOGIC AND HYDRAULIC COMPUTATIONS

The hydrologic analysis used in development of the overtopping potential is based on applying a hypothetical storm to a unit hydrograph to obtain the inflow hydrograph for a reservoir routing. The Probable Maximum Precipitation is derived and determined from regional charts prepared by the National Weather Service in "Hydrometeorological Report No. 33." Reduction factors have not been applied. A 24 hour storm duration is assumed with total depth distributed over 6 hour periods in accordance with procedures outlined in EM 1110-2-1411 (SPF Determination). The maximum 6 hour rainfall period is then distributed to hourly increments by the same criteria. Within-the-hour distribution is based upon NOAA Technical Memorandum NWS HYDRO-35. The non-peak 6 hour rainfall periods are distributed uniformly. All distributed values are arranged in a critical sequence by the SPF criteria. The final inflow hydrograph is produced by deduction of infiltration losses appropriate to the soil, land use, and antecedent moisture conditions.

Dam overtopping analysis has been conducted by hydrologic methods for this dam and lake. This computation determines the percentage of the PMF hydrograph that the reservoir can contain without the dam being overtopped. An output summary in the hydrologic appendix displays this information as well as other characteristics of the simulated dam overtopping.

The above analysis has been accomplished for this report using the systemized computer program HEC-1 (Dam Safety Version), July, 1978, prepared by the Hydrologic Engineering Center, U.S. Army Corps of Engineers, Davis, California. The numeric parameters estimated for this site are listed in the computer printout. Definitions of these variables are contained in the "User's Manual" for the computer program.

The inflow hydrograph was routed through the reservoir using HEC-1's Modified Puls option.



L. ROBERT KIMBALL & ASSOCIATES
CONSULTING ENGINEERS & ARCHITECTS
EBENSBURG PENNSYLVANIA

DAM NAME SHEPARD MT. DAM
I.D. NUMBER 30324
SHEET NO. 1 OF 3
BY OTM DATE 6-5-79

SHEPARD MOUNTAIN DAM

DRAINAGE AREA

AREA = 707 SQ. MI (SEE LOGS DATED 10/1/68 AND
11/15/68, 75-M.I. CLASS.)

UNIT HYDROGRAPH PARAMETERS

KRUPICH METHOD:

$t_p = 0.83$ HRS (FROM TIME OF CONCENTRATION ON
NOMOGRAPH, KENTUCKY BUREAU
OF HIGHWAYS)
 $= 0.6 t_r$
 $= 0.5$ HRS

WHERE $L = 20,000'$ $\theta = 39'$

CURVE NUMBER METHOD:

$$L_{10}(L) = \frac{L^{0.8} (S+1)^{0.7}}{1900 Y^{0.5}} = \frac{(20000)^{0.8} (2.47)^{0.7}}{1900 (20)^{0.5}}$$

$$= \frac{(2759)(1.90)}{8497} = \underline{0.6 \text{ HRS.}}$$

WHERE L = GREATEST FLOW LENGTH IN FEET.
 $S = \frac{1000}{CN} - 10$ AND CN = CURVE NUMBER
 Y = SLOPE IN %

LOSS RATE AND BASE FLOW

STRTL = 1 INCH
CN STRL = 87 SCS CURVE NUMBER
STRTRQ = 1.5 CFS/MI²
ORCSN = 0.05 (5% OF PEAK FLOW)
RTIOR = 2.5

UTILIZED ANTECEDENT MOISTURE CONDITION II



L. ROBERT KIMBALL & ASSOCIATES
CONSULTING ENGINEERS & ARCHITECTS
EBENSBURG PENNSYLVANIA

DAM NAME SHEPARD DAM
I.D. NUMBER 70334
SHEET NO. 3 OF 3
BY SW DATE 6-15-79

POSSIBLE MAXIMUM STORM

FROM HR NO. 33

EMP INDEX RAINFALL (ZONE 7) = 26.5 INCHES
 $R_6 = 102\%$, $R_2 = 120\%$, $R_{24} = 130\%$

ELEVATION-AREA-CORRECTED TO RIGHT OF DAM

SPILLWAY CREST ELEV. = 977' AREA = 0 ACRES
TOTAL STORAGE = 163 AC-FEET
(FROM FIELD INSPECTION DATA, ST. LOGS, C&G,
C.O.E. INFO. AND USGS 7.5-MIN. QUA.)

ELEV. 930' AREA = 53 ACRES
ELEV. 1000' AREA = 104 ACRES

FROM CONC METHOD FOR RESERVOIR VOLUME,
FLOOD HYDROGRAPH PACKAGE (HEC-1), DAM
SAFETY VERSION (USERS MANUAL).

$$H = 3/A = 3(163)/2' = 24'$$

∴ ELEV. WHERE CAPACITY EQUALS ZERO;
 $977 - 24' = 953'$

ELEVATION (F+)	953	977	980	985	991	1000
AREA (AC)	0	21	33	50	70	104

SPILLWAY DISCHARGE

DETERMINED BY (HEC-1)

SPILLWAY CREST ELEV. = 977'
LENGTH OF SPILLWAY = 377.5
COEFFICIENT OF DISCHARGE = 3.2



L. ROBERT KIMBALL & ASSOCIATES
CONSULTING ENGINEERS & ARCHITECTS
EBENSBURG PENNSYLVANIA

DAM NAME SHEPARD MT. DAM

I.D. NUMBER 30324

SHEET NO. 3 OF 3

BY SM DATE 6-15-79

OVERTOPPING PARAMETERS


TOP OF DAM ELEV. = 979'

COEFFICIENT OF DISCHARGE = 3.0

LENGTH = 259' (84 MAX = 259', 84 MAX = 284')

UPSTREAM CONDITIONS (SCHEMATIC NETWORK)

SNOW HOLLOW LAKE APPROX. 14,000' UPSTREAM.
EVALUATED EFFECTS ON SHEPARD MOUNTAIN
LAKE DAM.



84	VI	3	12	68	152	286	584
85	VI	0	12	68	152	286	584
86	VI	0	12	68	152	286	584
87	VI	0	12	68	152	286	584
88	VI	0	12	68	152	286	584
89	VI	0	12	68	152	286	584
90	VI	0	12	68	152	286	584
91	VI	0	12	68	152	286	584
92	VI	0	12	68	152	286	584
93	VI	0	12	68	152	286	584
94	VI	0	12	68	152	286	584
95	VI	0	12	68	152	286	584
96	VI	0	12	68	152	286	584
97	VI	0	12	68	152	286	584
98	VI	0	12	68	152	286	584
99	VI	0	12	68	152	286	584
100	VI	0	12	68	152	286	584

 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 26 FEB 79

RUN DATE 79/06/13.
 TIME 15.46.24.

ANALYSIS OF DAM OVERTOPPING USING RATIOS OF PMF
 HYDROLOGIC-HYDRAULIC ANALYSIS OF SAFETY OF SHEPARD MOUNTAIN LAKE
 RATIOS OF PMF ROUTED THROUGH THE RESERVOIR (MISSOURI #30324)

JOB SPECIFICATION

NO	NHR	NMIN	IDAY	IHR	IMIN	METRC	IPLT	IPRT	NSTAN
288	0	5	0	0	0	0	0	0	0

JOPER 5
 NWI 0
 LROPT 0
 TRACE 0

MULTI-PLAN ANALYSES TO BE PERFORMED

RATIOS= .10 .20 .30 .40 .50 1.00
 NPLAN= 1 NRATIO= 6 LRATIO= 1

SUB-AREA RUNOFF COMPUTATION

RUNOFF (SUB-AREA A)

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPRI	INAME	ISTAGE	IAUTO
1	0	0	10	0	0	1	0	0

HYDROGRAPH DATA

HYDROGRAPH ROUTING

ROUTE THROUGH SNOW HOLLOW LAKE

I STAQ ICOMP IRECON I TAPE JPLT JPRY I NAME I STAGE I AUTO

0 2 1 0 0 0 0 1 0 0 0

ROUTING DATA

0 LOSS CLOSS AVG IRES I SAME I OPT I PMP LSTR

0.0 0.000 0.000 1 1 0 0 0

NSTPS NSTDL LAG AMSK X TSK STORA I SPRAY

1 0 0 0.000 0.000 0.000 -1278. -1

STAGF 1278.00 1280.00 1281.00 1282.00 1283.00 1283.40 1284.00 1285.00 1286.00

1287.00

FLOW 0.00 71.00 195.00 460.00 1081.00 1405.00 2350.00 3978.00 7416.00

11539.00

CAPACITY= 0. 68. 501. 1067.

ELEVATION= 1278. 1280. 1290. 1300.

CREL 1278.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

SPWID 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

COQM 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

EXPW 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

ELEVL 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

COOL 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

GAREA 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

EXPL 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

DAM DATA

TOPEL COOD EXPD DAMWID

1283.4 0.0 0.0 0.

STATION 2, PLAN 1, RATIO 1

END-OF-PERIOD HYDROGRAPH ORDINATES

OUTFLOW

STATIONS OF MAX CAPACITY AVAILABLE

STATION 1 STATION 2 STATION 3 STATION 4
 1275.00 1275.00 1275.00 1275.00
 100.00 100.00 100.00 100.00
 100.00 100.00 100.00 100.00
 100.00 100.00 100.00 100.00

GATE NO	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AT GATE	MAXIMUM FLOW OVER TOP OF DAM	MAXIMUM FLOW OVER TOP OF DAM	MAXIMUM FLOW OVER TOP OF DAM	MAXIMUM FLOW OVER TOP OF DAM	TIME OF FLOW OVER TOP OF DAM	TIME OF FLOW OVER TOP OF DAM	TIME OF FLOW OVER TOP OF DAM	TIME OF FLOW OVER TOP OF DAM
10	1250.62	87	125	125	125	125	15.38	15.38	15.38	0.00
20	1281.82	147	213	213	213	213	16.25	16.25	16.25	0.00
30	1282.92	194	277	277	277	277	16.50	16.50	16.50	0.00
40	1284.72	225	311	311	311	311	15.92	15.92	15.92	0.00
50	1294.25	257	361	361	361	361	15.92	15.92	15.92	0.00
100	1296.00	328	460	460	460	460	15.83	15.83	15.83	0.00

PLAN 1 STATION 3

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME, HOURS
0.10	124	1055.1	16.17
0.20	401	1055.5	16.83
0.30	935	1056.1	16.33
0.40	1596	1056.4	16.17
0.50	2393	1057.4	16.09
1.00	6420	1058.4	15.92

PLAN 1 STATION 4

MAXIMUM	MAXIMUM	TIME
MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME, HOURS

DATE	RECEIVED	AMOUNT	BALANCE
1967		157.25	157.25
1967		17.71	173.54
1967		17.71	155.83
1967		17.71	138.12
1967		17.71	120.41
1967		17.71	102.70
1967		17.71	85.00
1967		17.71	67.29
1967		17.71	49.58
1967		17.71	31.87
1967		17.71	14.16
1967		17.71	-3.55
1967		17.71	-21.26
1967		17.71	-38.97
1967		17.71	-56.68
1967		17.71	-74.39
1967		17.71	-92.10
1967		17.71	-109.81
1967		17.71	-127.52
1967		17.71	-145.23
1967		17.71	-162.94
1967		17.71	-180.65
1967		17.71	-198.36
1967		17.71	-216.07
1967		17.71	-233.78
1967		17.71	-251.49
1967		17.71	-269.20
1967		17.71	-286.91
1967		17.71	-304.62
1967		17.71	-322.33
1967		17.71	-340.04
1967		17.71	-357.75
1967		17.71	-375.46
1967		17.71	-393.17
1967		17.71	-410.88
1967		17.71	-428.59
1967		17.71	-446.30
1967		17.71	-464.01
1967		17.71	-481.72
1967		17.71	-499.43
1967		17.71	-517.14
1967		17.71	-534.85
1967		17.71	-552.56
1967		17.71	-570.27
1967		17.71	-587.98
1967		17.71	-605.69
1967		17.71	-623.40
1967		17.71	-641.11
1967		17.71	-658.82
1967		17.71	-676.53
1967		17.71	-694.24
1967		17.71	-711.95
1967		17.71	-729.66
1967		17.71	-747.37
1967		17.71	-765.08
1967		17.71	-782.79
1967		17.71	-800.50
1967		17.71	-818.21
1967		17.71	-835.92
1967		17.71	-853.63
1967		17.71	-871.34
1967		17.71	-889.05
1967		17.71	-906.76
1967		17.71	-924.47
1967		17.71	-942.18
1967		17.71	-959.89
1967		17.71	-977.60
1967		17.71	-995.31
1967		17.71	-1013.02
1967		17.71	-1030.73
1967		17.71	-1048.44
1967		17.71	-1066.15
1967		17.71	-1083.86
1967		17.71	-1101.57
1967		17.71	-1119.28
1967		17.71	-1136.99
1967		17.71	-1154.70
1967		17.71	-1172.41
1967		17.71	-1190.12
1967		17.71	-1207.83
1967		17.71	-1225.54
1967		17.71	-1243.25
1967		17.71	-1260.96
1967		17.71	-1278.67
1967		17.71	-1296.38
1967		17.71	-1314.09
1967		17.71	-1331.80
1967		17.71	-1349.51
1967		17.71	-1367.22
1967		17.71	-1384.93
1967		17.71	-1402.64
1967		17.71	-1420.35
1967		17.71	-1438.06
1967		17.71	-1455.77
1967		17.71	-1473.48
1967		17.71	-1491.19
1967		17.71	-1508.90
1967		17.71	-1526.61
1967		17.71	-1544.32
1967		17.71	-1562.03
1967		17.71	-1579.74
1967		17.71	-1597.45
1967		17.71	-1615.16
1967		17.71	-1632.87
1967		17.71	-1650.58
1967		17.71	-1668.29
1967		17.71	-1686.00
1967		17.71	-1703.71
1967		17.71	-1721.42
1967		17.71	-1739.13
1967		17.71	-1756.84
1967		17.71	-1774.55
1967		17.71	-1792.26
1967		17.71	-1809.97
1967		17.71	-1827.68
1967		17.71	-1845.39
1967		17.71	-1863.10
1967		17.71	-1880.81
1967		17.71	-1898.52
1967		17.71	-1916.23
1967		17.71	-1933.94
1967		17.71	-1951.65
1967		17.71	-1969.36
1967		17.71	-1987.07
1967		17.71	-2004.78
1967		17.71	-2022.49
1967		17.71	-2040.20
1967		17.71	-2057.91
1967		17.71	-2075.62
1967		17.71	-2093.33
1967		17.71	-2111.04
1967		17.71	-2128.75
1967		17.71	-2146.46
1967		17.71	-2164.17
1967		17.71	-2181.88
1967		17.71	-2199.59
1967		17.71	-2217.30
1967		17.71	-2235.01
1967		17.71	-2252.72
1967		17.71	-2270.43
1967		17.71	-2288.14
1967		17.71	-2305.85
1967		17.71	-2323.56
1967		17.71	-2341.27
1967		17.71	-2358.98
1967		17.71	-2376.69
1967		17.71	-2394.40
1967		17.71	-2412.11
1967		17.71	-2429.82
1967		17.71	-2447.53
1967		17.71	-2465.24
1967		17.71	-2482.95
1967		17.71	-2500.66
1967		17.71	-2518.37
1967		17.71	-2536.08
1967		17.71	-2553.79
1967		17.71	-2571.50
1967		17.71	-2589.21
1967		17.71	-2606.92
1967		17.71	-2624.63
1967		17.71	-2642.34
1967		17.71	-2660.05
1967		17.71	-2677.76
1967		17.71	-2695.47
1967		17.71	-2713.18
1967		17.71	-2730.89
1967		17.71	-2748.60
1967		17.71	-2766.31
1967		17.71	-2784.02
1967		17.71	-2801.73
1967		17.71	-2819.44
1967		17.71	-2837.15
1967		17.71	-2854.86
1967		17.71	-2872.57
1967		17.71	-2890.28
1967		17.71	-2907.99
1967		17.71	-2925.70
1967		17.71	-2943.41
1967		17.71	-2961.12
1967		17.71	-2978.83
1967		17.71	-2996.54
1967		17.71	-3014.25
1967		17.71	-3031.96
1967		17.71	-3049.67
1967		17.71	-3067.38
1967		17.71	-3085.09
1967		17.71	-3102.80
1967		17.71	-3120.51
1967		17.71	-3138.22
1967		17.71	-3155.93
1967		17.71	-3173.64
1967		17.71	-3191.35
1967		17.71	-3209.06
1967		17.71	-3226.77
1967		17.71	-3244.48
1967		17.71	-3262.19
1967		17.71	-3279.90
1967		17.71	-3297.61
1967		17.71	-3315.32
1967		17.71	-3333.03
1967		17.71	-3350.74
1967		17.71	-3368.45
1967		17.71	-3386.16
1967		17.71	-3403.87
1967		17.71	-3421.58
1967		17.71	-3439.29
1967		17.71	-3457.00
1967		17.71	-3474.71
1967		17.71	-3492.42
1967		17.71	-3510.13
1967		17.71	-3527.84
1967		17.71	-3545.55
1967		17.71	-3563.26
1967		17.71	-3580.97
1967		17.71	-3598.68
1967		17.71	-3616.39
1967		17.71	-3634.10
1967		17.71	-3651.81
1967		17.71	-3669.52
1967		17.71	-3687.23
1967		17.71	-3704.94
1967		17.71	-3722.65
1967		17.71	-3740.36
1967		17.71	-3758.07
1967		17.71	-3775.78
1967		17.71	-3793.49
1967		17.71	-3811.20
1967		17.71	-3828.91
1967		17.71	-3846.62
1967		17.71	-3864.33
1967		17.71	-3882.04
1967		17.71	-3899.75
1967		17.71	-3917.46
1967		17.71	-3935.17
1967		17.71	-3952.88
1967		17.71	-3970.59
1967		17.71	-3988.30
1967		17.71	-4006.01
1967		17.71	-4023.72
1967		17.71	-4041.43
1967		17.71	-4059.14
1967		17.71	-4076.85
1967		17.71	-4094.56
1967		17.71	-4112.27
1967		17.71	-4129.98
1967		17.71	-4147.69
1967		17.71	-4165.40
1967		17.71	-4183.11
1967		17.71	-4200.82
1967		17.71	-4218.53
1967		17.71	-4236.24
1967		17.71	-4253.95
1967		17.71	-4271.66
1967		17.71	-4289.37
1967		17.71	-4307.08
1967		17.71	-4324.79
1967		17.71	-4342.50
1967		17.71	-4360.21
1967		17.71	-4377.92
1967		17.71	-4395.63
1967		17.71	-4413.34
1967		17.71	-4431.05
1967		17.71	-4448.76
1967		17.71	-4466.47
1967		17.71	-4484.18
1967		17.71	-4501.89
1967		17.71	-4519.60
1967		17.71	-4537.31
1967		17.71	-4555.02

UNIT HYDROGRAPH

SUB-AREA POINTS CONNECTION

STAGE	ICOMP	RECH	HEAD	PHI	ISRT	ISAM	ISAGE	IAUJO
5	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

TIME	TAREA	SEAD	INSPC	RATIO	ISHOW	ISAM	LOCAL
2	6.32	0.00	7.07	0.000	0	1	0

PRECIP DATA

TIME	TC	RT2	RT3	RT4	RT5
2.00	26.50	102.00	130.00	0.00	0.00

LOSS DATA

LOSS	STAKK	DLTKR	RTIOL	LNAIN	STIKS	RTIOK	SIRTL	CNSIC	ALSMX	RTIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	-1.00	-87.00	0.00	0.00

CORRE NO = -87.00 METHOD = -1.00 EFFECT CN = 87.00

UNITY HYDROGRAPH DATA

TC = 0.00 LAG = .50

RECESSION DATA

STRF = -1.50 GRCSIG = -.00 RTIOP = 2.50

UNITY HYDROGRAPH END OF PERIOD ORDINATES, TC = 0.00 HOURS, LAG = .50 VOL = 1.00

49129.	32632.	53219.	51274.	41566.	42827.	37899.	35837.	56428.	27730.
29518.	22735.	22389.	21254.	20303.	19809.	18914.	18237.	17564.	16900.
16787.	15318.	15318.	14946.	14650.	14495.	14132.	13765.	13057.	12683.
10871.	8160.	8160.	6926.	5843.	4864.	4209.	3771.	3394.	3155.
2931.	2727.	2527.	2345.	2176.	2092.	1968.	1896.	1835.	1782.
1735.	1695.	1639.	1627.	1593.	1576.	1554.	1535.	1518.	1503.
1469.	1475.	1463.	1451.	1440.	1429.	1419.	1409.	1400.	1392.
1383.	1379.	1368.	1361.	1353.	1348.	1342.	1336.	1331.	1326.
1325.	1316.	1311.	1307.	1303.	1299.	1295.	1292.	1289.	1286.
1264.	1259.	1249.	1247.	1245.	1243.	1241.	1240.		

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME	
CFS	53219.	19582.	5127.	6127.	1764573.
CMS	1507.	596.	173.	173.	49967.
INCHES		75.85	32.75	32.75	32725
MM		658.76	819.05	819.05	819405
AC-FT		9745.	12153.	12153.	12153.
THOUS CU FT		12820.	14990.	14990.	14990.

HYDROGRAPH ROUTING

ROUTE THROUGH RESERVOIR (SHEPARD MT. LAKE)

INSTAG	ICOMP	TECON	ITAPE	JPLT	JPRT	INARE	ISTAGE	TAUTO
7	1	0	0	0	0	1	0	0
ROUTING DATA								
LOSS	CLASS	AVG	IPES	TEAME	TOPT	IPMP	LSTR	
0.0	0.000	0.00	1	1	0	0		
MSYR	NSYR	LAG	AMSK	X	TSK	STORA	ISPRAT	

1 0 0 0.000 0.000 0.000 -977. 0
 21. 31. 50. 78. 106.

CAPACITY= 0. 166. 248. 499. 913. 1591.
 ELEVATION= 953. 977. 980. 985. 991. 1000.

CURVE SPEED CURVE FLOW CURVE AREA CURVE
 977.0 377.5 3.0 1.0 0.0 0.0 0.0 0.0

DAN DATA
 TOPEL CUOD EXOD DAMWID
 979.0 3.0 1.5 259.
 977.0 975.0 980.0 981.0 982.0 983.0

STATION 7. PLAN 1. RATIO 1

END-OF-PERIOD HYDROGRAPH ORDINATES

	OUTFLOW									
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
1.	1.	1.	1.	2.	2.	3.	4.	4.	5.	5.
6.	7.	9.	10.	11.	12.	13.	14.	15.	15.	15.
18.	19.	20.	21.	22.	23.	24.	24.	25.	25.	25.
26.	27.	28.	29.	30.	31.	32.	32.	32.	32.	32.
33.	34.	35.	37.	40.	46.	53.	63.	76.	76.	76.
90.	106.	171.	137.	151.	165.	177.	188.	193.	193.	193.
215.	225.	229.	235.	240.	245.	249.	253.	257.	257.	260.
263.	266.	269.	271.	273.	276.	278.	280.	282.	282.	284.
285.	287.	288.	290.	291.	292.	294.	295.	295.	295.	297.

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS					
				RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6
				.10	.20	.30	.40	.50	1.00
HYDROGRAPH AT	1	.75 (1.94)	1	1052. (29.78)	2104. (59.57)	3155. (89.35)	4207. (119.13)	5259. (148.91)	10518. (297.83)
ROUTED TO	2	.75 (1.94)	1	125. (3.53)	413. (11.70)	1032. (29.23)	1911. (54.12)	2761. (78.19)	7408. (209.77)
ROUTED TO	3	.75 (1.94)	1	124. (3.50)	403. (11.42)	935. (26.49)	1594. (45.13)	2393. (67.75)	6420. (181.80)
ROUTED TO	4	.75 (1.94)	1	120. (3.40)	380. (10.75)	778. (22.04)	1300. (36.80)	1947. (55.14)	5121. (145.02)
HYDROGRAPH AT	5	6.32 (16.37)	1	4817. (136.41)	9635. (272.82)	14452. (409.24)	19269. (545.65)	24087. (682.06)	48173. (1364.12)
2 COMBINED	6	7.07 (18.31)	1	4872. (137.97)	9820. (278.08)	14907. (422.12)	20106. (569.35)	25624. (725.58)	53219. (1506.98)
ROUTED TO	7	7.07 (18.31)	1	4649. (131.64)	9489. (268.70)	14514. (410.99)	19632. (555.91)	25048. (709.29)	52054. (1474.00)


REPORT OF 24-HR. WATER ANALYSIS

DATE: 10/10/50
 TIME: 10:00 AM
 LOCATION: ...
 ANALYST: ...
 TOTAL VOLUME: 100.00
 ...
 ...
 ...

DATE	TIME	INLET	OUTLET	DIFFERENCE	PERCENT	REMARKS
10/10	10:00
10/10	11:00
10/10	12:00
10/10	13:00
10/10	14:00
10/10	15:00
10/10	16:00
10/10	17:00
10/10	18:00
10/10	19:00
10/10	20:00
10/10	21:00
10/10	22:00
10/10	23:00
10/10	24:00

APPENDIX C
PHOTOGRAPHS

↑ P₁₂
P₁₃ > SNOW HOLLOW DAM UPSTREAM OF SHEPARD MT. DAM




P- INDICATES PHOTO LOCATION

SHEPARD MOUNTAIN DAM
PHOTO INDEX



Photograph No. 1
Dam from right abutment.



Photograph No. 2
Right abutment gravity section.



Photograph No. 3

Downstream face of dam.



Photograph No. 4

Right abutment.



Photograph No. 5

Left abutment.



Photograph No. 6

Left abutment.



Photograph No. 7

Left abutment wall.




Photograph No. 8

Outlet works.



Photograph No. 9
Roadway culvert below dam.
C-6



Photograph No. 10

Outlet works.



Photograph No. 11
Spalled Gunite.

C-7



Photograph No. 12

Snow Hollow Dam.



Photograph No. 13

Spillway of Snow Hollow Dam.

DATE
ILME