



AD A105959

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO. <i>DR-A105 959</i>	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Dam Inspection Report National Dam Safety Program Fairview Lake Dam (MO 10976) Boone County, Missouri		5. TYPE OF REPORT & PERIOD COVERED Final Report
		6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(s) Corps of Engineers, St. Louis District		8. CONTRACT OR GRANT NUMBER(s)  N/A
9. PERFORMING ORGANIZATION NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		12. REPORT DATE September 1978
		13. NUMBER OF PAGES Approximately 30
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		15. SECURITY CLASS. (of this report)  UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)  Approved for release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)  Dam Safety, Lake, Dam Inspection, Private Dams		<b>SECRET</b> OCT 21 1981 <b>D</b> <b>H</b>
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report was prepared under the National Program of Inspection of Non-Federal Dams. This report assesses the general condition of the dam with respect to safety, based on available data and on visual inspection, to determine if the dam poses hazards to human life or property.		

FAIRVIEW LAKE DAM  
BOONE COUNTY, MISSOURI  
MISSOURI INVENTORY NO. 10976

6 PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

Fairview Lake Dam (MO 10976).  
Missouri - Kansas City Basin. Boone County,  
Missouri. Phase I Inspection Report.

9 Final rept.

10 Ken / Alexander Chien (Nancy) / Hsieh

12 36

PREPARED BY: ST. LOUIS DISTRICT CORPS OF ENGINEERS  
FOR: GOVERNOR OF MISSOURI  
AUG 1978

11

4-1525

PHASE I REPORT  
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Fairview Lake Dam  
State Located: Missouri  
County Located: Boone County  
Stream: Tributary to County House Branch  
Date of Inspection: 13 April 1978

Fairview Lake Dam was inspected by a team of engineers from the St. Louis District, U. S. Army Corps of Engineers. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property. The assessment of the dam size and hazard classification was based on "Recommended Guidelines for Safety Inspection of Dams". These guidelines were developed by the Chief of Engineers, U.S. Army, Washington, D.C., with the help of Federal and State agencies, professional engineering organizations, and private engineers.

Based on the guidelines, this dam is classified small size dam with high downstream hazard potential. A sudden failure will significantly increase the potential for loss of life; serious damage to homes; and extensive damage to property downstream of the dam.

Based on hydraulic - hydrologic analysis, the drop inlet spillway does not meet the criteria set forth in the guidelines for a dam of the size and hazard classification designated. The drop inlet spillway will not pass a one percent chance flood (100 year flood) without overtopping. The dam will begin to be overtopped by 15 percent of the Probable Maximum Flood (PMF) which is less than the 50 percent PMF recommended in the guidelines for a dam of this size and hazard potential. Overtopping is likely to cause a sudden failure of the dam. This dam is classified as unsafe for overtopping conditions discussed above. However, no conditions were observed that would pose an emergency at non-overtopping conditions.

Based on a visual inspection and available data, the Fairview Lake Dam has the following additional deficiencies which are considered to have an adverse effect on the safety of the dam:

- a. Extensive erosion and undermining at the exit portals of the corrugated metal pipes.

Accession For	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
NTIS GR&I			
DTIC TAB			
Unannounced			
Justification			
By			
Distribution/			
Availability Codes			
Avail and/or			
Dist Special			
			A

b. Heavy vegetation and trees growing on the downstream slope of the dam.

c. The dam does not have seepage or stability analyses records available. In accordance with the above guidelines, the absence of such records is a deficiency which should be rectified.

It is recommended that the owner take the necessary action in the near future to correct or control the deficiencies reported herein. A detailed discussion of these deficiencies is included in the following report.

Ken Alexander  
KEN ALEXANDER  
Soils Engineer


Chien Hsieh  
CHIEN (NANCY) HSIEH  
Hydraulic Engineer

Submitted By Paul D. Chini  
Chief, Engineering Division

21 Sept 78  
Date

Approved By Leon E. Muthy  
Colonel, CE, District Engineer

22 Sep 78  
Date



OVERVIEW OF FAIRVIEW LAKE DAM

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
FAIRVIEW LAKE DAM - ID NOS. 10976

TABLE OF CONTENTS

<u>Paragraph No.</u>	<u>Title</u>	<u>Page No.</u>
SECTION I - PROJECT INFORMATION		
1.1	General	1
1.2	Description of Project	1
1.3	Pertinent Data	2
SECTION II - ENGINEERING DATA		
2.1	Design	4
2.2	Construction	4
2.3	Operation	4
2.4	Evaluation	4
SECTION III - VISUAL INSPECTION		
3.1	Findings	5
3.2	Evaluation	6
SECTION IV - OPERATIONAL PROCEDURES		
4.1	Procedures	7
4.2	Maintenance of Dam	7
4.3	Maintenance of Operating Facilities	7
4.4	Description of Any Warning System in Effect	7
4.5	Evaluation	7
SECTION V - HYDRAULIC/HYDROLOGIC		
5.1	Evaluation of Features	8
SECTION VI - STRUCTURAL STABILITY		
6.1	Evaluation of Structural Stability	9
SECTION VII - ASSESSMENT/REMEDIAL MEASURES		
7.1	Dam Assessment	10
7.2	Remedial Measures	11

TABLE OF CONTENTS (CONTINUED)

<u>Paragraph No.</u>	<u>Title</u>	<u>Page No.</u>
APPENDIX		
A	Hydrologic and Hydraulic Computations	

LIST OF PLATES

<u>Plate No.</u>	<u>Title</u>
1	Vicinity Topography
2	Location Map
3	Fairview Lake Dam
4	Profile and Cross sections
5	Cross section 1+20

LIST OF PHOTOGRAPHS

<u>Photo No.</u>	<u>Title</u>
1	Curb Opening Drop Inlet Spillway
2	30 inches CMP and Exit Portal
3	Exit Channel
4	Fairview Lake Dam
5	Downstream Slope (1 of 2)
6	Downstream Slope (2 of 2)
7	14 inches CMP Downstream
8	Upstream slope

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
FAIRVIEW LAKE DAM ID NO. 10976

SECTION I - PROJECT INFORMATION

1.1 GENERAL

a. Authority. The National Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of safety inspection of dams throughout the United States. Pursuant to the above, the St. Louis District, Corps of Engineers, District Engineer directed a safety inspection of the Fairview Lake Dam.

b. Purpose of Inspection. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection in order to determine if the dam poses hazards to human life or property.

c. Evaluation Guidelines. The inspection and evaluation were performed in accordance with the investigation procedures as prescribed in "Recommended Guidelines for Safety Inspection of Dams" Appendix D, published by the Department of the Army, Office of the Chief of Engineers.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam and Appurtenance.

The dam is an earth structure north of the Missouri River near Columbia, Missouri. Topography near the dam is gently rolling and is shown on PLATE 1.

The spillway is a 44-foot long curb opening drop inlet, which has eight 5-foot long by 8-inch high openings at the east overbank abutting the dam (see Photo 1). The water enters the openings and drops through a vertical shaft and flows to the downstream river channel through a 30 inch corrugated metal pipe and exit channel (see Photos 2 and 3). The earth embankment of the dam supports an asphalt paved roadway with concrete curb gutter on both sides and a 4-foot wide sidewalk on the south of the road (see Photo 4).

The pertinent physical data are given in paragraph 1.3 below and the general layout of the dam is shown on PLATE 3.

b. Location. The dam is located in the SW 1/4 of Section 15, T48N, R3W at west side of city of Columbia, Missouri, Boone County, as shown on PLATES 1 and 2.

c. Size Classification. The size classification of a dam and impoundment is based on the height of the dam and storage capacity. Fairview Lake Dam is in the small size category (per the guidelines referenced in paragraph 1.1c above).

d. Hazard Classification. The dam is in the high hazard classification.

e. Ownership. Dam is owned by Fairview Lake Association, Dr. Thomas E. Coyle (President of the Association), 601 Eastlake Drive, Columbia, Missouri 65201.

f. Purpose of Dam. The dam impounds water for the purpose of recreation.

g. Design and Construction History. The inspection team was unable to find any design data on the dam. Recent information obtained from Mr. Carl Hulen, the original owner, indicated that the dam was constructed during 1947-1948 by the Bill Goodson Construction Co.

h. Normal Operating Procedure. The lake level is governed by the drop inlet spillway.

### 1.3 PERTINENT DATA

a. Drainage Areas - 46 Acres

b. Discharge at Damsite.

(1) All discharge at the damsite is through curb opening drop inlet with 30 inch CMP.

(2) Ungated spillway capacity at maximum pool elevation is 45 cfs., estimated.

c. Elevation. (feet above MSL)

(1) Top Dam - 711.5 ±

(2) Stream bed at centerline of dam - 677 ± Est.

(3) Maximum tailwater - unknown

d. Reservoir.

(1) Length of Maximum Pool (feet) - 700 ±

e. Storage. Unknown.

f. Reservoir Surface. (Acres) - Top of dam 2± Est.

g. Dam.

(1) Type - earth embankment

(2) Length, (feet) - 230 ±

(3) Height, (feet) - 35 Est.

(4) Top width (feet) - 28 ±

(5) Side Slopes

Upstream IV on 1H

Downstream IV on 3 H

h. Diversion and Regulating Tunnel. None

i. Spillway.

(1) Type and Size - 44 feet (8 - 5-foot x 8-inch) curb opening drop inlet for a 30 inch CMP

(2) Invert elevation, (feet MSL) - 709.9 ±

j. Regulating Outlets. None

## SECTION II - ENGINEERING DATA

### 2.1 DESIGN

Design data for this structure was not available.

### 2.2 CONSTRUCTION

The dam was constructed in 1947 and 1948 by the Bill Goodson Construction Company. The original owner (Mr. Carl Hulen) reported all embankment material was compacted with a sheepsfoot roller.

### 2.3 OPERATION

No operational records were found. The dam has a high level uncontrolled spillway for controlling lake level.

### 2.4 EVALUATION

- a. Availability. None
- b. Adequacy.
- c. Validity. No valid engineering data was found on design or construction of the dam.

## SECTION III - VISUAL INSPECTION

### 3.1 FINDINGS

a. General. A visual inspection of the dam outlet spillway and exit channel was made on 13 April 1978 by Corps of Engineers, St. Louis District personnel.

b. Dam. The location, profile, and section of the dam is shown on PLATES 1 through 5.

The exposed portion of the dam upstream slope above the water level was very steep (estimated 1V on 1H) with heavy growth of trees and brush (see Photo 8). The downstream slope near the left abutment was very steep, irregular, and had a very heavy growth of vegetation (see Photo 6). The slope near the center of the dam became less steep with a berm beginning approximately one-third of the downstream height from the crown of the dam (see Photo 5). The Missouri Geological Survey reported that several years ago a slide had occurred near the right abutment. This slide was reported to contain only waste material that was placed on the downstream slope of the dam. No evidence of this slide is presently visible. The material on the downstream slope near the left abutment appears to be waste material placed after construction of the dam.

c. Appurtenant Structure.

Some deterioration of concrete was noticed at the lower end of the horizontal lip of the curb opening drop inlet spillway (see Photo 1). Two pipes were visible on the downstream slope of the dam. One 30-inch CMP was near the left abutment to release the water from the upstream spillway. One 14 inch CMP was near the center of the dam several feet above the toe to drain the storm water from pavement on top of the embankment of the dam. A significant amount of erosion and undermining at the exit ends of both pipes were noticed (see photos 2 and 7). The collapse of the slab downstream of the 30-inch pipe, as shown in Photo 2, was probably attributed to flow overtopping the sides of slab in sufficient quantity and rate to cause erosion and undermining.

d. Lake Area. No wave wash, excessive erosion or slides were observed along the shore of the lake area.

e. Downstream Channel.

The discharge from the spillway flows through the 30-inch pipe into the exit channel which is protected with broken concrete slabs and dump stones. Erosion has occurred along the exit channel (see Photo 3).

### 3.2 EVALUATION

The deficiencies observed during this inspection and noted herein, if left uncontrolled or uncorrected, could lead to a serious potential for failure.

## SECTION IV - OPERATIONAL PROCEDURE

### 4.1 PROCEDURES

There is no controlled outlet works for the dam; therefore, no regulating procedure exists. The pool is controlled by rainfall, runoff, evaporation, and the capacity of the uncontrolled spillway and outlet.

### 4.2 MAINTENANCE OF DAM

Based on the amount of vegetation on the downstream slope of the dam, no maintenance has been accomplished on the dam for several years.

### 4.3 MAINTENANCE OF OPERATING FACILITIES

No operating facilities exist at the dam.

### 4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT

The inspection team is not aware of any existing warning system for the dam.

### 4.5 EVALUATION

If lack of maintenance is allowed to continue, a serious potential for failure may develop

## SECTION V - HYDRAULIC/HYDROLOGIC

### 5.1 EVALUATION OF FEATURES

a. Design Data. Design data are not available.

b. Experience Data. The drainage area and lake surface area were obtained from the USGS Columbia and Huntsdale Quadrangles. The alignment of the dam, spillway, and outlet was developed from surveys made during the inspection.

c. Visual Observations.

(1) Drawdown facilities necessary to evacuate the pool did not exist at the lake.

(2) The observed condition of the spillway, culvert and exit channel are discussed in Section 3, paragraphs 3.1c and 3.1e.

d. Overtopping Potential. The drop inlet spillway and pipe of the dam is too small to pass one-half of the probable maximum or the one percent chance flood (100 year flood) without overtopping. The probable maximum flood is defined as the flood that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region. The one percent chance flood is a flood that would have a one percent chance of being exceeded in any given year. The drop inlet spillway and pipe has a capacity for passing 15 percent of the PMF without overtopping. Routing the one-half PMF through the lake reveals that the dam would be overtopped for approximately 4.5 hours with a maximum of 1.7 feet water and 440 cfs discharge over the top of the dam. Hydrologic and hydraulic computations are presented in Appendix A. Overtopping of the magnitude described above is likely to cause sudden failure of the dam. The tsunami wave from a sudden failure of this dam will threaten the safety of the people and property downstream of the dam.

## SECTION VI - STRUCTURAL STABILITY

### 6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations. Conditions observed which affect the structural stability of the dam is discussed in Section 3, paragraph 3.1b.

b. Design and Construction Data. No design or construction data relating to the structural stability of the dam were found.

c. Operating Records. No appurtenant structures requiring operation exist at the dam.

d. Seismic Stability. Since the dam is located in Seismic Zone 1, it is not likely that an earthquake would occur of sufficient intensity to cause severe damage or failure of the dam.

## SECTION VII - ASSESSMENT/REMEDIAL MEASURES

### 7.1 DAM ASSESSMENT

a. Safety. The dam inspected did not have seepage or stability analyses records. To assure that conventional safety margins exist, these records should be obtained. Other deficiencies observed which could lead to unsafe conditions are:

- (1) Heavy growth of vegetation and trees on the downstream slope and a few trees on the upstream slope of the dam
- (2) Erosions at exit portals and exit channel of the 30- and 14-inch pipes.
- (3) Inadequate spillway.

b. Adequacy of Information. Due to the lack of engineering design and construction data, the conclusions in this report were based on performance history and visual conditions. Guidelines furnished for inspection of dams requires that seepage and stability analyses be on file for each dam inspection. No such data was available for the dam.

c. Urgency. The stability and seepage data discussed in paragraph 7.1a above should be obtained to assure that conventional safety margins exist. Also, means of controlling the seepage referred to in paragraph 7.1a above should be accomplished. If stability or seepage data indicates an unsafe condition, the condition should be corrected. The remedial measures recommended in paragraph 7.2 should be accomplished in the near future. If the other deficiencies listed in paragraph 7.1a are not corrected they could continue to deteriorate and lead to a serious potential failure. Therefore, these deficiencies should be corrected or controlled in the near future.

d. Necessity for Phase II. Based on the results of the Phase I inspection, no Phase II inspection is recommended.

e. Seismic Stability. The dam is located in Seismic Zone 1. An earthquake of this magnitude is not expected to cause structure failure to the earth dam.

### 7.2 REMEDIAL MEASURES

a. Alternatives.

(1) The outlet size and/or height of the dam should be increased to pass the probable maximum flood without overtopping the dam or to use other positive means for protecting the dam from sudden failure due to overtopping.

(2) If stability analysis of the dam shows an unacceptable factor of safety, methods of stabilizing the dam should be studied.

b. O&M Maintenance and Procedures. The following Operation and maintenance procedures are recommended:

(1) Remove trees and heavy vegetation from the slopes of the dam.

(2) Repair erosion and undermining and provide erosion protection and/or energy dissipators at the exit end of the two pipes on the downstream slope of Fairview Lake Dam.

(3) Keep the culverts and spillway clean.

## HYDROLOGIC AND HYDRAULIC COMPUTATIONS

1. The hydrologic analysis used in development of the overtopping potential is based on applying a hypothetical storm to a unit hydrograph to obtain the inflow hydrograph for a reservoir routing. The Probable Maximum Precipitation is derived and determined from regional charts prepared by the National Weather Service in "Hydrometeorological Report No. 33." Reduction factors have not been applied. A 24-hour storm duration is assumed with total depth distributed over 6-hour periods in accordance with procedures outlined in EM 1110-2-1411 (SPF Determination). The maximum 6-hour rainfall period is then distributed to hourly increments by the same criteria. Within-the-hour distribution is based upon NOAA Technical Memorandum NWS HYDRO-35. The non-peak 6-hour rainfall periods are distributed uniformly. All distributed values are arranged in a critical sequence by the SPF criteria. The final inflow hydrograph is produced by deduction of infiltration losses appropriate to the soil, land use, and antecedent moisture conditions.

2. The reservoir routing is accomplished by using Modified Puls routing techniques wherein the flood hydrograph is routed through lake storage. Hydraulic capacities of the outlet works, spillway, and crest of dam are used as outlet controls in the routing. Storage in the pool area is defined by an elevation-storage capacity curve. The hydraulic capacity of the outlet works, spillway, and top of dam are defined by elevation-discharge curves.

3. Dam overtopping analysis has been conducted by hydrologic methods for this dam and lake. This computation determines the percentage of the PMF hydrograph that the reservoir can contain without the dam being overtopped. An output summary in the hydrologic appendix displays this information as well as other characteristics of the simulated dam overtopping.

4. The above methodology has been accomplished for this report using the systemized computer program HEC-1 (Dam Safety Version), July 1978, prepared by the Hydrologic Engineering Center, U.S. Army Corps of Engineers, Davis, California. The numeric parameters estimated for this site are listed in the attached computer printout. Definitions of these variables are contained in the "User's Manual" for the computer program.

b. A triangular weir formula is used for the dam overtopping analysis.

$$Q = C^1 ZH^{2.5} = CH^{2.5}$$

$$C^1 = 2.4$$

$$Z = \frac{1}{2} \left( \frac{1}{S_1} + \frac{1}{S_2} \right)$$

(S is the slope of the top of the dam ft./ft.) H = Head on the lowest point of the dam.

DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 29 AUG 78

A1	DAM INSPECTION 13 APRIL 1978										
A2	FAIRVIEW LAKE DAME COLUMBIA MO										
A3	SCS HYDROGRAPHS PMP AND IPMP										
R	28A	0	5	0	0	0	0	0	0	-5	0
R1	5										
J	1	4	1								
J1	1.0	.2	.3	.5							
K	0	1	0	0	1	3	1				
K1	CALCULATION OF INFLOW HYDROGRAPH OF FAIRVIEW LAKE DAM										
M	1	2	.07	0	0	1	0	0	0	1	
P	0	25	102	121	130						
T	0	0	0	0	0						
M2	0	.07				0	0	-1		-85	
X	30	40	2								
K	1	2	0	0	0	0	0	1			
K1	ROUTED FLOW THROUGH DROP INLET SPILLWAY AND 30 INCH CMP AND TOP OF DAM										
V	0	0	0	1							
V1	J	0	0	0	0	0	0	-709.9		-1	
V4	709.0	710	711	711.9	713	718					
V5	1	32	40	45	50	70					
SA	0	2.3	2.3	2.4	2.5	2.5	3.0				
SE	677.3	709.9	710	711	711.9	715	716				
SS	709.9										
SD	711.5	120	2.5	1							
M	99										

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

RUNOFF HYDROGRAPH AT	1
ROUTE HYDROGRAPH TO	2
END OF NETWORK	

FLOOD HYDROGRAPH PACKAGE (HEC-1)

DAM SAFETY VERSION JULY 1976  
 LAST MODIFICATION 29 AUG 76  
 \*\*\*\*\*

RUN DATE: 78/09/01,  
 TIME: 09.16.39.

DAM INSPECTION 13 APRIL 1976  
 FAIRVIEW LAKE DAME COLUMBIA MO  
 SCS HYDROGRAPHS PMP AND IPMP

JOB SPECIFICATION  
 NO NHR NMIN IDAY IMR IMIN METRC IPLY IPRT NSTAN  
 200 0 5 0 0 0 0 0 -5 0  
 JOBER NMT LROPT TRACE  
 5 0 0 0

\*\*\*\*\* SUB-AREA RUNOFF COMPUTATION \*\*\*\*\*

CALCULATION OF INFLOW HYDROGRAPH OF FAIRVIEW LAKE DAME  
 ISYAG ICOMP IECON IYAPE JPLT JPRT INAME IYAGE IAUTO  
 1 0 0 0 1 3 1 0 0

HYDROGRAPH DATA  
 INYGC IUNG TAREA SNAP TRSDA TRSPC RATIO ISNOW ISAME LOCAL  
 1 2 .07 0.00 .07 1.00 0.000 0 1 0

PRECIP DATA  
 SPFE PHS R6 R12 R24 R48 R72 R96  
 0.00 25.00 102.00 121.00 130.00 0.00 0.00 0.00

LOSS DATA  
 LROPT STRKR ULTKR RTIOL ERAIN STRKS RTIOK STRTLI CNSTL ALSMX RTIMP  
 0 0.00 0.00 1.00 0.00 0.00 1.00 -1.00 -85.00 0.00 0.00

CURVE NO = -85.00 WETNESS = -1.00 EFFECT CN = 85.00

UNIT HYDROGRAPH DATA  
 TCS 0.00 LAG = .07

RECESSION DATA  
 STRTQ = 30.00 GRCSN = 40.00 RTIOR = 2.00

TIME INCREMENT TOO LARGE--(NMQ IS GT LAG/2)

UNIT HYDROGRAPH 6 END OF PERIOD ORDINATES, TCS 0.00 HOURS, LAG = .07 VOL = 1.00  
 257. 203. 58. 17. 5. 2.

MO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	END-OF-PERIOD FLOW	MO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	COMP 0
1.01	.05	1	.01	0.00	.01	28.	1.01	12.05	145	.21	.20	.01	89.
1.01	.10	2	.01	0.00	.01	26.	1.01	12.10	146	.21	.20	.01	97.
1.01	.15	3	.01	0.00	.01	24.	1.01	12.15	147	.21	.20	.01	105.

1.01	.20	4	.01	0.00	.01	23.	1.01	12.20	148	.21	.20	109.
.01	.25	5	.01	0.00	.01	21.	1.01	12.25	149	.21	.20	110.
1.01	.30	6	.01	0.00	.01	20.	1.01	12.30	150	.21	.20	110.
1.01	.35	7	.01	0.00	.01	18.	1.01	12.35	151	.21	.20	110.
1.01	.40	8	.01	0.00	.01	17.	1.01	12.40	152	.21	.20	110.
1.01	.45	9	.01	0.00	.01	16.	1.01	12.45	153	.21	.20	110.
1.01	.50	10	.01	0.00	.01	15.	1.01	12.50	154	.21	.20	111.
1.01	.55	11	.01	0.00	.01	14.	1.01	12.55	155	.21	.20	111.
1.01	1.00	12	.01	0.00	.01	13.	1.01	13.00	156	.21	.21	111.
1.01	1.05	13	.01	0.00	.01	12.	1.01	13.05	157	.26	.25	122.
1.01	1.10	14	.01	0.00	.01	11.	1.01	13.10	158	.26	.25	130.
1.01	1.15	15	.01	0.00	.01	11.	1.01	13.15	159	.26	.25	133.
1.01	1.20	16	.01	0.00	.01	10.	1.01	13.20	160	.26	.25	134.
1.01	1.25	17	.01	0.00	.01	9.	1.01	13.25	161	.26	.25	134.
1.01	1.30	18	.01	0.00	.01	9.	1.01	13.30	162	.26	.25	134.
1.01	1.35	19	.01	0.00	.01	8.	1.01	13.35	163	.26	.25	135.
1.01	1.40	20	.01	0.00	.01	8.	1.01	13.40	164	.26	.25	135.
1.01	1.45	21	.01	0.00	.01	7.	1.01	13.45	165	.26	.25	135.
1.01	1.50	22	.01	0.00	.01	7.	1.01	13.50	166	.26	.25	135.
1.01	1.55	23	.01	0.00	.01	6.	1.01	13.55	167	.26	.25	135.
1.01	2.00	24	.01	0.00	.01	6.	1.01	14.00	168	.26	.25	135.
1.01	2.05	25	.01	0.00	.01	5.	1.01	14.05	169	.32	.31	152.
1.01	2.10	26	.01	0.00	.01	5.	1.01	14.10	170	.32	.31	164.
1.01	2.15	27	.01	0.00	.01	5.	1.01	14.15	171	.32	.31	168.
1.01	2.20	28	.01	0.00	.01	4.	1.01	14.20	172	.32	.31	169.
1.01	2.25	29	.01	0.00	.01	4.	1.01	14.25	173	.32	.31	170.
1.01	2.30	30	.01	0.00	.01	4.	1.01	14.30	174	.32	.31	170.
1.01	2.35	31	.01	0.00	.01	4.	1.01	14.35	175	.32	.31	170.
1.01	2.40	32	.01	0.00	.01	4.	1.01	14.40	176	.32	.31	170.
1.01	2.45	33	.01	0.00	.01	3.	1.01	14.45	177	.32	.31	170.
1.01	2.50	34	.01	0.00	.01	3.	1.01	14.50	178	.32	.31	170.
1.01	2.55	35	.01	0.00	.01	3.	1.01	14.55	179	.32	.31	171.
1.01	3.00	36	.01	0.00	.01	3.	1.01	15.00	180	.32	.32	171.
1.01	3.05	37	.01	0.00	.01	3.	1.01	15.05	181	.19	.19	139.
1.01	3.10	38	.01	0.00	.01	3.	1.01	15.10	182	.39	.38	163.
1.01	3.15	39	.01	0.00	.01	3.	1.01	15.15	183	.39	.38	195.
1.01	3.20	40	.01	0.00	.01	3.	1.01	15.20	184	.58	.58	254.
1.01	3.25	41	.01	0.00	.01	3.	1.01	15.25	185	.68	.67	320.
1.01	3.30	42	.01	0.00	.01	3.	1.01	15.30	186	1.65	1.63	599.
1.01	3.35	43	.01	0.00	.01	3.	1.01	15.35	187	2.71	2.70	1077.
1.01	3.40	44	.01	0.00	.01	3.	1.01	15.40	188	1.07	1.06	930.
1.01	3.45	45	.01	0.00	.01	3.	1.01	15.45	189	.68	.67	576.
1.01	3.50	46	.01	0.00	.01	3.	1.01	15.50	190	.58	.58	402.
1.01	3.55	47	.01	0.00	.01	3.	1.01	15.55	191	.39	.39	290.
1.01	4.00	48	.01	0.00	.01	3.	1.01	16.00	192	.39	.39	232.
1.01	4.05	49	.01	0.00	.01	3.	1.01	16.05	193	.30	.30	192.
1.01	4.10	50	.01	0.00	.01	3.	1.01	16.10	194	.30	.30	169.
1.01	4.15	51	.01	0.00	.01	3.	1.01	16.15	195	.30	.30	163.
1.01	4.20	52	.01	0.00	.01	3.	1.01	16.20	196	.30	.30	161.
1.01	4.25	53	.01	0.00	.01	3.	1.01	16.25	197	.30	.30	161.
1.01	4.30	54	.01	0.00	.01	3.	1.01	16.30	198	.30	.30	161.
1.01	4.35	55	.01	0.00	.01	3.	1.01	16.35	199	.30	.30	161.
1.01	4.40	56	.01	0.00	.01	3.	1.01	16.40	200	.30	.30	161.
1.01	4.45	57	.01	0.00	.01	3.	1.01	16.45	201	.30	.30	161.
1.01	4.50	58	.01	0.00	.01	3.	1.01	16.50	202	.30	.30	161.
1.01	4.55	59	.01	0.00	.01	3.	1.01	16.55	203	.30	.30	161.
1.01	5.00	60	.01	0.00	.01	3.	1.01	17.00	204	.30	.30	161.
1.01	5.10	61	.01	0.00	.01	3.	1.01	17.05	205	.23	.23	144.
1.01	5.15	62	.01	0.00	.01	3.	1.01	17.10	206	.23	.23	131.
1.01	5.15	63	.01	0.00	.01	3.	1.01	17.15	207	.23	.23	128.

1.01	5.20	64	.01	.00	.01	3.	1.01	17.20	206	.23	.23	.00	127.
1.01	5.25	65	.01	.00	.01	3.	1.01	17.25	209	.23	.23	.00	126.
1.01	5.30	66	.01	.00	.01	3.	1.01	17.30	210	.23	.23	.00	126.
1.01	5.35	67	.01	.00	.01	3.	1.01	17.35	211	.23	.23	.00	126.
1.01	5.40	68	.01	.00	.01	3.	1.01	17.40	212	.23	.23	.00	126.
1.01	5.45	69	.01	.00	.01	3.	1.01	17.45	213	.23	.23	.00	126.
1.01	5.50	70	.01	.01	.01	3.	1.01	17.50	214	.23	.23	.00	126.
1.01	5.55	71	.01	.01	.01	3.	1.01	17.55	215	.23	.23	.00	126.
1.01	6.00	72	.01	.01	.01	3.	1.01	18.00	216	.23	.23	.00	126.
1.01	6.05	73	.07	.03	.04	9.	1.01	18.05	217	.02	.02	.00	71.
1.01	6.10	74	.07	.03	.04	14.	1.01	18.10	218	.02	.02	.00	39.
1.01	6.15	75	.07	.03	.03	17.	1.01	18.15	219	.02	.02	.00	37.
1.01	6.20	76	.07	.03	.03	18.	1.01	18.20	220	.02	.02	.00	34.
1.01	6.25	77	.07	.04	.03	19.	1.01	18.25	221	.02	.02	.00	32.
1.01	6.30	78	.07	.04	.03	20.	1.01	18.30	222	.02	.02	.00	30.
1.01	6.35	79	.07	.04	.03	20.	1.01	18.35	223	.02	.02	.00	28.
1.01	6.40	80	.07	.04	.03	21.	1.01	18.40	224	.02	.02	.00	26.
1.01	6.45	81	.07	.04	.02	22.	1.01	18.45	225	.02	.02	.00	24.
1.01	6.50	82	.07	.04	.02	23.	1.01	18.50	226	.02	.02	.00	23.
1.01	6.55	83	.07	.04	.02	23.	1.01	18.55	227	.02	.02	.00	21.
1.01	7.00	84	.07	.04	.02	24.	1.01	19.00	228	.02	.02	.00	20.
1.01	7.05	85	.07	.05	.02	24.	1.01	19.05	229	.02	.02	.00	18.
1.01	7.10	86	.07	.05	.02	25.	1.01	19.10	230	.02	.02	.00	17.
1.01	7.15	87	.07	.05	.02	25.	1.01	19.15	231	.02	.02	.00	16.
1.01	7.20	88	.07	.05	.02	25.	1.01	19.20	232	.02	.02	.00	15.
1.01	7.25	89	.07	.05	.02	26.	1.01	19.25	233	.02	.02	.00	14.
1.01	7.30	90	.07	.05	.02	26.	1.01	19.30	234	.02	.02	.00	13.
1.01	7.35	91	.07	.05	.02	27.	1.01	19.35	235	.02	.02	.00	12.
1.01	7.40	92	.07	.05	.02	27.	1.01	19.40	236	.02	.02	.00	11.
1.01	7.45	93	.07	.05	.02	27.	1.01	19.45	237	.02	.02	.00	11.
1.01	7.50	94	.07	.05	.01	28.	1.01	19.50	238	.02	.02	.00	10.
1.01	7.55	95	.07	.05	.01	28.	1.01	19.55	239	.02	.02	.00	10.
1.01	8.00	96	.07	.05	.01	28.	1.01	20.00	240	.02	.02	.00	10.
1.01	8.05	97	.07	.05	.01	28.	1.01	20.05	241	.02	.02	.00	10.
1.01	8.10	98	.07	.05	.01	29.	1.01	20.10	242	.02	.02	.00	10.
1.01	8.15	99	.07	.05	.01	29.	1.01	20.15	243	.02	.02	.00	10.
1.01	8.20	100	.07	.05	.01	29.	1.01	20.20	244	.02	.02	.00	10.
1.01	8.25	101	.07	.05	.01	29.	1.01	20.25	245	.02	.02	.00	10.
1.01	8.30	102	.07	.05	.01	29.	1.01	20.30	246	.02	.02	.00	10.
1.01	8.35	103	.07	.05	.01	30.	1.01	20.35	247	.02	.02	.00	10.
1.01	8.40	104	.07	.06	.01	30.	1.01	20.40	248	.02	.02	.00	10.
1.01	8.45	105	.07	.06	.01	30.	1.01	20.45	249	.02	.02	.00	10.
1.01	8.50	106	.07	.06	.01	30.	1.01	20.50	250	.02	.02	.00	10.
1.01	8.55	107	.07	.06	.01	30.	1.01	20.55	251	.02	.02	.00	10.
1.01	9.00	108	.07	.06	.01	31.	1.01	21.00	252	.02	.02	.00	10.
1.01	9.05	109	.07	.06	.01	31.	1.01	21.05	253	.02	.02	.00	10.
1.01	9.10	110	.07	.06	.01	31.	1.01	21.10	254	.02	.02	.00	10.
1.01	9.15	111	.07	.06	.01	31.	1.01	21.15	255	.02	.02	.00	10.
1.01	9.20	112	.07	.06	.01	31.	1.01	21.20	256	.02	.02	.00	10.
1.01	9.25	113	.07	.06	.01	31.	1.01	21.25	257	.02	.02	.00	10.
1.01	9.30	114	.07	.06	.01	31.	1.01	21.30	258	.02	.02	.00	10.
1.01	9.35	115	.07	.06	.01	31.	1.01	21.35	259	.02	.02	.00	10.
1.01	9.40	116	.07	.06	.01	32.	1.01	21.40	260	.02	.02	.00	10.
1.01	9.45	117	.07	.06	.01	32.	1.01	21.45	261	.02	.02	.00	10.
1.01	9.50	118	.07	.06	.01	32.	1.01	21.50	262	.02	.02	.00	10.
1.01	9.55	119	.07	.06	.01	32.	1.01	21.55	263	.02	.02	.00	10.
1.01	10.00	120	.07	.06	.01	32.	1.01	22.00	264	.02	.02	.00	10.
1.01	10.05	121	.07	.06	.01	32.	1.01	22.05	265	.02	.02	.00	10.
1.01	10.10	122	.07	.06	.01	32.	1.01	22.10	266	.02	.02	.00	10.
1.01	10.15	123	.07	.06	.01	32.	1.01	22.15	267	.02	.02	.00	10.

1.01	10.20	124	.07	.06	.01	32.	1.01	22.20	268	.02	.02	.00
1.01	10.25	125	.07	.06	.01	32.	1.01	22.25	269	.02	.02	.00
1.01	10.30	126	.07	.06	.01	32.	1.01	22.30	270	.02	.02	.00
1.01	10.35	127	.07	.06	.01	33.	1.01	22.35	271	.02	.02	.00
1.01	10.40	128	.07	.06	.01	33.	1.01	22.40	272	.02	.02	.00
1.01	10.45	129	.07	.06	.01	33.	1.01	22.45	273	.02	.02	.00
1.01	10.50	130	.07	.06	.01	33.	1.01	22.50	274	.02	.02	.00
1.01	10.55	131	.07	.06	.01	33.	1.01	22.55	275	.02	.02	.00
1.01	11.00	132	.07	.06	.01	33.	1.01	23.00	276	.02	.02	.00
1.01	11.05	133	.07	.06	.01	33.	1.01	23.05	277	.02	.02	.00
1.01	11.10	134	.07	.06	.01	33.	1.01	23.10	278	.02	.02	.00
1.01	11.15	135	.07	.06	.00	33.	1.01	23.15	279	.02	.02	.00
1.01	11.20	136	.07	.06	.00	33.	1.01	23.20	280	.02	.02	.00
1.01	11.25	137	.07	.06	.00	33.	1.01	23.25	281	.02	.02	.00
1.01	11.30	138	.07	.06	.00	33.	1.01	23.30	282	.02	.02	.00
1.01	11.35	139	.07	.06	.00	33.	1.01	23.35	283	.02	.02	.00
1.01	11.40	140	.07	.06	.00	33.	1.01	23.40	284	.02	.02	.00
1.01	11.45	141	.07	.06	.00	33.	1.01	23.45	285	.02	.02	.00
1.01	11.50	142	.07	.06	.00	33.	1.01	23.50	286	.02	.02	.00
1.01	11.55	143	.07	.06	.00	33.	1.01	23.55	287	.02	.02	.00
1.01	12.00	144	.07	.06	.00	33.	1.02	0.00	288	.02	.02	.00

SUM 32.50 30.47 2.03 17140.  
( 825.)( 774.)( 51.)( 485.35)

CF8	1077.	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
	30.	1077.	188.	59.	59.	17115.
CMS			5.	2.	2.	485.
INCHES			25.03	31.59	31.59	31.59
4M			632.79	802.37	802.37	802.37
AC-FT			93.	118.	118.	118.
THOUS CU M			115.	145.	145.	145.

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION STATION AREA PLAN RATIO 1 RATIO 2 RATIO 3 RATIO 4 RATIOS APPLIED TO FLOWS  
 1.00 .20 .30 .50


HYDROGRAPH AT 1 .07 1 1077. 215. 323. 536.  
 (.18) ( 30.50)( 6.10)( 9.15)( 15.25)(  
 Routed to 2 .07 1 1026. 47. 195. 486.  
 (.18) ( 29.05)( 1.32)( 5.52)( 13.77)(

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 ..... ELEVATION INITIAL VALUE SPILLWAY CREST TOP OF DAM  
 STORAGE 709.90 709.90 711.50  
 OUTFLOW 25. 25. 29.  
 1. 1. 43.

RATIO OF PMF	MAXIMUM RESERVOIR W.S. ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.15	711.00	0.00	21.	40.	0.00	15.02	0.00
1.00	713.81	2.31	35.	1026.	6.25	15.67	0.00
.20	711.72	.22	29.	47.	.83	16.00	0.00
.30	712.58	1.08	31.	195.	2.58	15.75	0.00
.50	713.16	1.66	33.	486.	4.50	15.67	0.00


\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 20 AUG 78  
 \*\*\*\*\*



**HULEN LAKES &  
FAIRVIEW LAKE  
VICINITY TOPOGRAPHY  
PLATE I**



VICINITY MAP  
SCALE IN MILES




CITY  
OF  
COLUMBIA


BOONE

COUNTY


LOCATION MAP  
SCALE IN FEET







FAIRVIEW LAKE  
PROFILE  
AND  
CROSS SECTIONS



FAIRVIEW LAKE DAM  
 CROSS SECTION 1+20

PLATE 5



PHOTO 1

Curb opening drop inlet spillway, Fairview Lake Dam



PHOTO 2

30" CMP and Exit Portal, Fairview Lake Dam



PHOTO 3  
Exit Channel, Fairview Lake Dam




PHOTO 4  
Fairview Lake Dam



PHOTO 5

Downstream Slope of Fairview Lake Dam (1 of 2)




PHOTO 6

Downstream of Fairview Lake Dam (2 of 2)



PHOTO 7

14" CMP (Downstream) Fairview Lake Dam



PHOTO 8

Upstream slope of Fairview Lake Dam

DATE  
FILMED  
—8