

AD-A144 061


NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
WHIGVILLE RESERVOIR D. (U) CORPS OF ENGINEERS WALTHAM
MA NEW ENGLAND DIV FEB 80


1/1

UNCLASSIFIED

F/G 13/13

NL





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

AD-A144 061

FARMINGTON RIVER BASIN
BURLINGTON CONNECTICUT

WHIGVILLE RESERVOIR DAM
CT-00379

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM



DTIC
ELECTE
AUG 8 1984
S
A

DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEER
WALTHAM, MASS. 02154

DTIC FILE COPY

This document has been approved
for public release and sale. Its
distribution is unlimited.

FEBRUARY 1980

84 08 077

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER CT 00379	2. GOVT ACCESSION NO. <i>A144061</i>	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Whigville Reservoir Dam NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
		6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		8. CONTRACT OR GRANT NUMBER(s)
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		12. REPORT DATE February 1980
		13. NUMBER OF PAGES 55
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use coverdate for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Farmington River Basin Burlington Connecticut		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) Whigville Reservoir Dam is an earthen embankment structure with a concrete/boulder core wall. The dam is 460 feet long and has a maximum height of 54 feet. The dam is judged to be in generally poor condition. For the combination of dam size (intermediate) and downstream hazard (high), the magnitude of the spillway test flood is required to be the PMF.		

WHIGVILLE RESERVOIR DAM

CT 00379

FARMINGTON RIVER BASIN

BURLINGTON, CONNECTICUT

DTIC
ELECTRONIC

AUG 8 1984

S

A

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

This document has been prepared
for public release and sale, its
distribution is unlimited.

Accession For

NRIS GRA&I

FORM TAB

Unannounced

Classification

COPY
INSPECTED

By
Distribution/

Availability Code

Avail

A-1

NATIONAL DAM INSPECTION PROGRAM
PHASE I INSPECTION REPORT

Identification No.: CT 00379
Name of Dam: Whigville Reservoir Dam
Town: Burlington
County and State: Hartford, Connecticut
Stream: Whigville Brook
Date of Inspection: 24 October, 1979

BRIEF ASSESSMENT

Whigville Reservoir Dam is an earthen embankment structure with a concrete/boulder core wall. The dam is 460 feet long and has a maximum height of 54 feet. The 40 foot long concrete/boulder spillway is located at the right side of the dam. Slope paving forms the approach to the spillway. The downstream face is mortared stone masonry. Stone masonry training walls form the wasteway section. The outlet works consist of an upper and lower gatehouse each of which connect to submerged concrete intake structures. A 24 inch diameter blow off pipe passes under the wasteway channel to a stone masonry waste pot.

Whigville Reservoir is used as a public water supply source for the City of New Britain. The dam has a storage of 250 acre-feet. The size classification based on height is intermediate. A breach of the dam could affect several homes and commercial establishments along Main Street in the village of Whigville. With the possibility of some loss of life and the probability of excessive economic losses, the dam has been classified as having a high hazard potential.

The dam is judged to be in generally poor condition. The riprap on the upstream face is in generally good condition. The vertical and horizontal alignment is good. The downstream slope is covered with an extensive growth of trees and brush. Apparent seepage and wet areas were noted near the toe and at both sides of the spillway channel. The concrete parapet walls are in fair condition, with areas of erosion, spalling and deterioration noted. The concrete spillway weir is in poor condition with severely deteriorated concrete.


For the combination of dam size (intermediate) and downstream hazard (high), the magnitude of the spillway test flood is required to be the PMF. The spillway test flood inflow is 7,880 CFS. The maximum spillway capacity is 1,565 CFS at a stage of five feet.

no period

above the spillway crest (top of earth embankment). The spillway is not adequate to pass the PMF spillway test flood outflow (7730 CFS) without overtopping the dam. The test flood would overtop the dam by about 4.2 feet. The spillway would pass about 20 percent of the test flood outflow without overtopping the dam.

Within one year of receipt of the Phase I Inspection Report, the owner should retain a qualified registered engineer to accomplish the following: 1) investigate the seepage along the downstream toe and recommend measures for monitoring the seepage and for preventing piping of the embankment soils; 2) investigate the seepage through the joints in the stone masonry wingwalls and recommend measures for repair to prevent erosion and piping of the embankment soils; 3) remove trees growing on the downstream embankment and within 25 feet of the downstream toe ensuring that the root depressions are backfilled with appropriate soils; 4) investigate the source of water flowing into the spillway channel from several pipe outlets; 5) conduct more refined hydrologic and hydraulic analysis to determine the need for and methods of increasing the project discharge capacity; 6) repair failed portion of right retaining wall; 7) repair spalled and deteriorated concrete at spillway crest, downstream weir and parapet wall; and 8) locate and operate low level outlet and, if inoperable, provide a means of lowering water level in reservoir.

The owner should also carry out the following operational and maintenance procedures: 1) brush and small saplings growing on the downstream slope of the dam should be cut every year; 2) grass should be cut on a regular basis; 3) after the brush and saplings have been removed, the dam should be re-inspected by a qualified registered engineer; 4) a formal annual technical inspection program by a qualified registered engineer should be established; 5) grass should be planted on the crest of the dam and on the slopes to prevent erosion at these locations; 6) repair scour hole at end of spillway discharge channel; 7) repair and clean out deteriorated stilling well for "blow off"; 8) repair deteriorated concrete of stilling basin slab; 9) replace all missing riprap; 10) paint steel members of footbridge to prevent continued rusting; and 11) establish a formal surveillance program for use during and immediately after heavy rainfall and also a flood warning plan to follow in case of flood flow conditions or imminent dam failure.


S. Giavara, P.E.
President

Registered CT. 7634

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation: however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

The Phase I Investigation does not include an assessment of the need for fences, gates, no-trespassing signs, repairs to existing fences and railings and other items which may be needed to minimize trespass and provide greater security for the facility and safety to the public. An evaluation of the project for compliance with OSHA rules and regulations is also excluded.

TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
Letter of Transmittal	
Brief Assessment	
Review Board Page	
Preface	i
Table of Contents	ii - iv
Overview Photo	v
Location Map	vi

REPORT


1. PROJECT INFORMATION	
1.1 General	
a. Authority	1
b. Purpose of Inspection	1
1.2 Description of Project	
a. Location	1
b. Description of Dam and Appurtenances	1
c. Size Classification	2
d. Hazard Classification	2
e. Ownership	2
f. Operator	2
g. Purpose of Dam	2
h. Design and Construction History	3
i. Normal Operational Procedure	3
1.3 Pertinent Data	3-6
2. ENGINEERING DATA	
2.1 Design Data	7
2.2 Construction Data	7
2.3 Operation Data	7
2.4 Evaluation of Data	7-8

<u>Section</u>	<u>Page</u>
3. VISUAL INSPECTION	
3.1 Findings	
a. General	9
b. Dam	9
c. Appurtenant Structures	10
d. Reservoir Area	11
e. Downstream Channel	11
3.2 Evaluation	11
4. OPERATIONAL AND MAINTENANCE PROCEDURES	
4.1 Operational Procedures	
a. General	12
b. Description of any Warning System in Effect	12
4.2 Maintenance Procedures	
a. General	12
b. Operating Facilities	12
4.3 Evaluation	12
5. EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES	
5.1 General	13
5.2 Design Data	13
5.3 Experience Data	13
5.4 Test Flood Analysis	13-14
5.5 Dam Failure Analysis	14-15
6. EVALUATION OF STRUCTURAL STABILITY	
6.1 Visual Observation	16
6.2 Design and Construction Data	16
6.3 Post-Construction Changes	16
6.4 Seismic Stability	16


<u>Section</u>	<u>Page</u>
7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	
7.1 Dam Assessment	
a. Condition	17
b. Adequacy of Information	17
c. Urgency	17
7.2 Recommendations	17
7.3 Remedial Measures	
a. Operation and Maintenance Procedures	18
7.4 Alternatives	19

APPENDIXES

<u>Appendix</u>	<u>Description</u>
A	INSPECTION CHECKLIST
B	ENGINEERING DATA
C	PHOTOGRAPHS
D	HYDROLOGIC AND HYDRAULIC COMPUTATIONS
E	INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS



Overview Photo
Whigville Reservoir Dam



WHIGVILLE RESERVOIR DAM

LOCATION MAP

BURLINGTON, CONNECTICUT

NATIONAL DAM INSPECTION PROGRAM
PHASE I INSPECTION REPORT
WHIGVILLE RESERVOIR DAM - CT 00379

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL:

a. Authority. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a national program of dam inspection through the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Flaherty Giavara Associates, P.C. has been retained by the New England Division to inspect and report on selected dams in the State of Connecticut. Authorization and notice to proceed was issued to Flaherty Giavara Associates, P.C. under a letter of 19 October 1979 from William E. Hodgson, Jr., Colonel, Corps of Engineers. Contract No. DACW33-80-C-0001 has been assigned by the Corps of Engineers for this work.

b. Purpose.

- 1) Perform technical inspection and evaluation of non-federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-federal interests.
- 2) Encourage and assist the States to initiate quickly effective dam safety programs for non-federal dams.
- 3) To update, verify and complete the National Inventory of Dams.

1.2 DESCRIPTION OF THE PROJECT:

a. Location. The Whigville Reservoir Dam is located in Burlington, Connecticut on Whigville Brook. The reservoir is located approximately 2,000 feet northwest of the Village of Whigville. The reservoir is shown on the U.S.G.S. Map "Bristol, Connecticut" at a latitude of 41° 44' 00" and a longitude of 75° 57' 06". The Location Map on Page vi shows the location of the structure.

b. Description of Dam and Appurtenances. Whigville Reservoir Dam is 460 feet in length and 54 feet in height. The dam is concrete/boulder core wall. A concrete parapet wall 3 feet in width extends 2 feet above the downstream embankment and 7 feet above the upstream face. The elevation of the parapet crest is 574.3 NGVD. The core wall is composed of boulders encased in concrete. The downstream face of the core wall slopes at 4 inches horizontal to 12 inches vertical and is lined with stone paving. The upstream face of the core wall contains a 2 feet thick layer of concrete with a varying slope of 1-1/8 - 2-1/2 inches horizontal to 12 inches vertical. The

upstream earth embankment is lined with stone paving and slopes at 2 feet horizontal to 2 feet vertical. The upstream embankment begins at elevation 562.3. The width of the downstream embankment is 14 feet to the north of the spillway and 34 feet to the south of the spillway. Both downstream embankments slope at 2 feet horizontal to 1 foot vertical. The elevation of the crest of the downstream embankment is 572.3. At the left abutment the embankment elevation is at 572 feet for a distance of 40 feet. There is no concrete parapet wall at this location.

The spillway is 40 feet in width at a crest elevation of 567 feet. The spillway consists of a section of boulders encased in concrete, which is an extension of the core wall of the main dam. The upstream embankment slope paving forms the approachway to the spillway. The downstream face of the spillway is mortared stone masonry. At the toe of the spillway is a stilling basin with a concrete weir dissipator. Stone masonry training walls are located to either side of the spillway. Beyond the weir is the spillway wasteway. The base of the wasteway is paved with masonry stone and the sides of the channel are formed with stone masonry walls.

The outlet works consist of an upper and lower gatehouse each of which connects to submerged intake structures within the reservoir. 24-inch dia. conduits connect the upper intake structure to the upper gatehouse. A 24-inch conduit also connects the lower intake structure with the lower gatehouse. Water from both intakes can either pass through or bypass the lower gatehouse. A 24-inch diameter main transmits water from the gatehouses to the New Britain water supply system. A 24-inch diameter waste pipe passes under the wasteway channel to a stone masonry waste pot. This facility serves as the blow off. A gate valve just upstream of the waste pot controls the blow off.

c. Size Classification. The Whigville Reservoir has a storage volume of 250 acre feet and a dam height of 54 feet. A dam height of greater than 40 feet classifies this structure in the "intermediate" category according to guidelines established by the Corps of Engineers.

d. Hazard Classification. The dam is classified as having a "high" hazard potential. The areas of probable impact include Main Street in the Village of Whigville. The number of residential dwellings in the probable impact area are approximately 15. With the potential for the loss of more than a few lives and significant economic losses, the dam has been classified as having a high hazard potential.

e. Ownership. The Whigville Reservoir Dam is owned by the City of New Britain, Water Department, 1000 Shuttle Meadow Road, New Britain, Connecticut. The Superintendent of the Water Department is Mr. Jack McManus, telephone (203) 223-7515.

f. Operator. The New Britain Water Department, Superintendent, Mr. Jack McManus, operates this dam.

g. Purpose of Dam. The purpose of this dam is to impound water for public water supply to serve the City of New Britain.

h. Design and Construction History. Plans obtained for the dam are dated 1909. It is assumed that the dam was constructed within several years of this date. An extensive underdrain system is shown on plans dated 1912-1913, Daniel Crowley, Civil Engineers.- Outlets of this underdrain system were observed at the dam. In October and December of 1956 repairs were made to the spillway wasteway just below the toe, due to damages incurred during the October 1955 flood. A new wasteway bed was formed including a concrete weir dissipator. The work was constructed by Manafort Bros., New Britain, Connecticut.

i. Normal Operation Procedure. The reservoir is operated for use as a public water supply. Water is drawn for either the lower or upper intake structure for transmission to the 24 inch diameter water main conduit to New Britain.

1.3 PERTINENT DATA:

a. Drainage Area. The drainage area consists of 4.15 square miles of hilly to mountainous wooded terrain. Johnnycake and Scranton Mountains are contained within the watershed.

b. Discharge and Dam Site.

1) A 24 inch diameter waste pipe passes under the spillway and wasteway to the waste pot. The maximum outlet capacity has been computed to be approximately 90 cfs.

2) The October 1955 flood caused damage at this structure. The stage of this flood is unknown.

3) The ungated spillway capacity at the top of the left embankment (control) - 1565 cfs @ El. 572.0.

4) The ungated spillway capacity at the test flood elevation - 3907 cfs @ El. 576.2.

5) The gated spillway capacity at normal pool elevation is not applicable at this dam.

6) The gated spillway capacity at test flood elevation is not applicable at this dam.

7) The total spillway capacity at test flood elevation - 3907 cfs @ El. 576.2.

8) The total project discharge at the top of dam - 1565 cfs @ El. 572.

9) The total project discharge at test flood elevation - 7730 cfs @ El. 576.2.

c. Elevation (Ft. above National Geodetic Vertical Datum - NGVD)

- 1) Streambed at toe of dam.....520.3
- 2) Bottom of cutoff.....520
- 3) Maximum tailwater.....N/A
- 4) Recreation pool.....N/A
- 5) Full flood control pool.....N/A
- 6) Spillway crest.....567
- 7) Design surcharge.....Unknown
- 8) Top of dam.....Parapet: 574.3
Left Abutment: 572.0
- 9) Test flood design surcharge.....576.2

d. Reservoir (Length in Feet).

- 1) Normal pool.....700⁺
- 2) Flood control pool.....N/A
- 3) Spillway crest pool.....700⁺
- 4) Top of dam.....750⁺
- 5) Test flood pool.....800[±]

e. Storage (Acre-Feet).

- 1) Normal pool.....175
- 2) Flood control pool.....N/A
- 3) Spillway crest pool.....175
- 4) Top of dam.....250
- 5) Test flood pool.....270

f. Reservoir Surface (Acres.)

- 1) Normal pool.....11
- 2) Flood control pool.....N/A
- 3) Spillway crest.....11
- 4) Test flood pool.....14
- 5) Top of dam.....13.2

j. Regulating Outlets.

- 1) Invert.....Upper - 560 NGVD
Lower - 536 NGVD
Blow off - 527 NGVD
- 2) Size.....All 24"
- 3) Description.....Material:
Upper - Unknown
Lower - Unknown
Blow off - Cast Iron
- 4) Control mechanism.....Manually operated
gates for all outlets

SECTION 2 - ENGINEERING DATA

2.1 DESIGN:

The following documents which contain the principal information regarding this dam and its appurtenances were reviewed in the preparation of this report.

Drawings: Whigville Reservoir No. 1, New Britain Waterworks, Plan-Profile-Cross Section, dated 1909 (Sheet B).

Whigville Reservoir No. 1, New Britain Waterworks, Wasteway - Plan - Sections and Waste Pipe Outlet, dated 1909 (Sheet C).

Whigville Reservoir No. 1, New Britain Waterworks, subsurface drains and weep holes to accompany seepage chart, dated 1912-1913.

Additionally, several items of correspondence pertaining to the project and specifications for the repair work to the spillway (1956) were reviewed.

2.2 CONSTRUCTION:

No information is available concerning the foundation preparation or embankment construction. Apparently subsurface drains of various sizes were added to the original design drawings when springs were encountered during construction. Details shown on the drawings are in good agreement with field observations, although the size of sub-drains appear to have been modified from those shown on the seepage chart.

2.3 OPERATION:

Formal operational records are not available for this dam. Operation of the dam is by the New Britain Water Department.

2.4 EVALUATION:

a. Availability. Only minimal engineering information is available for this dam.

b. Adequacy. The lack of in-depth engineering data did not allow for a definitive review. Therefore, the adequacy of this dam could not be assessed from the standpoint of reviewing design and construction data, but is based primarily on visual inspection, past performance history and sound engineering judgement.

c. Validity. Only minor conflicts have been noted between the available data and the observations made during the inspection. In general, there is no reason to question the validity of the available data.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS:

a. General. Based on the visual inspection the dam and its appurtenances appear to be in poor condition. The dam is an earth embankment with a concrete core wall and exposed concrete parapet wall. The riprap on the upstream face is in generally good condition. However, it is missing from the bench in front of the upstream concrete wall. The vertical and horizontal alignment is good. The downstream slope is covered with an extensive growth of trees and brush. Apparent seepage and wet areas were noted near the toe of the dam and at both sides of the spillway channel. The concrete parapet wall is in fair condition, with areas of erosion, spalling and deterioration noted. The concrete spillway weir is in poor condition with severely deteriorated concrete.

b. Dam.

1) Upstream face - The upstream face is comprised of a 7 foot high concrete parapet and stone paving riprap which extends below the reservoir surface (see photo No. 1 and photo No. 2). The stone paving is in good condition with only a few openings visible which exposed the underlying embankment material. Spalling of the concrete parapet wall is evident and erosion/deterioration is especially noticeable at the recent waterline. The aggregate is exposed below the waterline (see photo No. 9).

2) Crest - The crest is covered with grass and weeds behind the upstream concrete parapet to the left of the spillway. A small path has been worn bare of vegetation at several locations to the left of the spillway structure as indicated in photo No. 3. To the right of the spillway channel, the crest has been worn bare over an extensive area due to vehicular traffic.

3) Downstream Slope - The downstream slope on the left-hand side of the dam is covered by grass and patches of brush as indicated in photos No. 6 and No. 7. Many small saplings are growing near and at the toe of the slope (see photo No. 8).

Several large trees are growing on the slope at the intersection with the left abutment, as indicated in photo No. 7 (background).

The downstream toe area is wet, and slightly soggy in numerous places. A small stream was observed flowing parallel to the toe of the dam and 10 feet downstream in the vicinity of Station 3+0. Approximately 150 feet downstream of the dam, two 4 inch pipe weep holes were noted. One was discharging a significant amount of water into the spillway channel (as shown in photo No. 15).

The downstream slope to the right side of the spillway channel is separated into two areas by a bench on which is located the lower gatehouse. The upper slope is covered with grass and brush. Stumps up to 4 inches diameter were observed near the crest of the slope. Several paths have been worn bare from the crest to the bench as a result of vehicular and motorbike traffic (photo No. 5). There is evidence of small area of sloughing of the slope adjacent to the right spillway wingwall near the toe of the upper slope.

Generally the lower slope contains an extensive growth of saplings, brush and other types of vegetation as indicated in photo No. 14. The area at or just upstream of the toe of the lower slope is generally wet and soggy (photo No. 4). Standing water was observed at several locations adjacent to the spillway channel.

A 2 inch diameter galvanized steel pipe was observed discharging water adjacent to the right bank of the spillway channel in the vicinity of the lower stilling basin. The purpose of this pipe is not known.

c. Appurtenant Structures.

1) Spillway - The 40' wide spillway has a stone and mortar masonry face, with a concrete cap along its crest. The concrete crest is in poor condition. Extensive deterioration and spalling of the surface concrete was observed as indicated in photo No. 11.

The nearly vertical downstream face of the spillway is generally in good condition, although there are numerous minor leaks and seepage noted at the joints (see photo No. 10).

2) Spillway Stilling Basin/Discharge Channel - The stilling basin at the toe of the spillway is in good condition. As shown in photo No. 10 the side walls are the extension of the spillway training walls, and have some leaks and efflorescence in the stone and mortar joints. The concrete slab that forms the floor is in good condition. The concrete weir at the downstream end of the stilling basin is in good condition. The spillway discharge channel is located downstream of the stilling basin, and has a concrete bottom with stone and mortar walls (photo No. 13). The concrete slab is in poor condition and shows evidence of surface wear, erosion and deterioration. The coarse aggregate is exposed, and there are numerous areas of spalling. A portion of the 4 foot high (right) south retaining wall has failed. Both walls shown signs of severe deterioration and seepage is occurring as indicated in photo No. 12.

3) Outlet Works - The upper gatehouse is used to operate the upper intake. The lower gatehouse is used to operate the lower intake. Both gatehouses are in good condition.

A 24" cast iron blow-off pipe (low level outlet) is intended to discharge into a stilling basin downstream of the dam, and thence over a weir into the main spillway discharge channel. The stilling well is severely deteriorated, and partially full of earth and debris. The pipe's outlet could not be found. A manhole, presumably with the controls for the blow off pipe, was also located, but could not be opened.

d. Reservoir Area. The perimeter area of the reservoir has moderate to steep slopes that are well wooded and stable. There is no evidence of slides or sloughing (see photo No. 17).

e. Downstream Channel. There is a 2 foot deep scour hole at the end of the spillway discharge channel, and the riprap has been displaced. The water level in this channel is controlled by a 4 foot high weir located 100 feet downstream of the spillway discharge channel. The weir is in very poor condition, with several horizontal cracks and has been complete deteriorated in some areas up to 12 inches.

The natural channel downstream of the weir is 10 feet wide and 2 feet deep, is in fair condition, and appears stable (see photo No. 16). Trees are close to the channel on both sides.

f. Service Bridge. The foot bridge over the spillway is in good condition (photo No. 10). Some rusting of the steel members is taking place.

3.2 EVALUATION:

On the basis of the results of the visual inspection the dam is considered to be in poor condition.

Trees and saplings growing on the downstream slope and the area immediately downstream of the toe of the dam may cause serious seepage or erosion problems if they blow over and pull out their roots or if they die or are cut and the roots rot.

The seepage through the joints in the stone masonry spillway wingwall could lead to long-term erosion problems if remedial action is not taken.

The presence of soft, wet ground and standing water at or near the downstream toe of the dam may be the result of seepage conditions which, if not controlled, could lead to failure of the dam. The source of seepage which exits into the spillway channel in the vicinity of the lower spillway stilling basin should be investigated.

The presence of extensive vegetation and saplings on the lower slope on the left side of the embankment and at the toe makes it impossible to inspect the wet areas adequately. It is important that those areas be thoroughly investigated.

The concrete on the spillway crest, downstream weir and parapet wall is severely deteriorated and in generally poor condition, with areas of erosion, spalling and deterioration noted.

SECTION 4 - OPERATIONAL AND MAINTENANCE PROCEDURES

4.1 OPERATIONAL PROCEDURES:

a. General. The Whigville Reservoir is a surface water storage facility for the New Britain Water Department. Water can be taken off at the upper intake to the upper gatehouse in a 24" diameter pipe and at the lower intake to the lower gatehouse in a 24" diameter pipe. Although the lower intake can discharge directly into the water supply line and bypass the lower gatehouse, this is not a normal operational procedure. A 24" diameter blow off can be operated to lower the water level in the reservoir.

b. Description of any Warning System in Effect. There is no formal warning system in effect in the event of a failure or partial failure of the structure.

4.2 MAINTENANCE PROCEDURES:

a. General. It does not appear that any formal maintenance procedures are practiced at the dam. Numerous trees and brush have overgrown the downstream slope and the concrete surface show considerable deterioration.

b. Operating Facilities. There are no formal maintenance procedures followed for the operating facilities.

4.3 EVALUATION:

Regular operation maintenance procedures for this dam and its appurtenances have not been developed or implemented.

An emergency action plan should be prepared to prevent or minimize the impact of failure. This plan should list the expedient action to be taken and authorities to be contacted in emergency situations.

SECTION 5 - EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES

5.1 GENERAL:

The Whigville Reservoir Dam is an earth embankment structure, with a concrete core wall and a stone and mortar spillway section in the vicinity of the right abutment. The crest length of the dam is 460 feet; its height is 54 feet.

The spillway is 40 feet wide and discharges directly into a stilling basin, and thence into a rectangular spillway raceway (wasteway) that passes through the dam, and extends downstream about 150 feet beyond the toe of slope.

The watershed area is 4.15 square miles of upland terrain that is well wooded. The land within the watershed is largely undeveloped.

5.2 DESIGN DATA:

No specific design data is available for this watershed or the structures of Whigville Reservoir Dam. In lieu of existing design information, U.S.G.S. Topographic Maps (Scale 1"=2,000') were utilized to develop hydrologic parameters. Some of the pertinent hydraulic design data was obtained and/or confirmed by actual field measurements at the time of the visual field inspection.

5.3 EXPERIENCE DATA:

Historical data for recorded discharges is not available for this dam.

The only known information concerning passage of flood flows is that the present operator has observed about 10 inches of water passing over the spillway. In addition, correspondence in the Department of Environmental Protection files indicates that flood flows in the fall of 1955 caused major damage to the toe of the spillway, requiring extensive repairs that were completed in 1956 (Appendix B).

5.4 TEST FLOOD ANALYSIS:

The test flood for determining the spillway adequacy is based upon Corps of Engineers guidelines. The size classification of the dam is "intermediate" based upon a height of 54 feet and storage volume of 250 acre-feet. The hazard potential is "high" due to the land use downstream of the dam (possibility of some loss of life and probability of excessive economic losses). The spillway test flood required by Corps of Engineers guidelines for this size dam and hazard potential is the probable maximum flood (PMF).

The magnitude of the Spillway Test Flood is based upon "Preliminary Guidance for Estimating PMF Discharges" by the New England Division, Corps of Engineers, dated December 1977. The watershed is rolling to steep, and has some floodwater storage areas in natural wetlands. The flood magnitude was based on the "rolling" watershed curve. The test flood inflow is 7880 cfs.

The maximum spillway capacity is 1560 cfs at a stage of 5 feet above the spillway crest (equal to the top of the earth embankment).

The spillway test flood was formed into a triangular hydrograph with a peak inflow of 7880 cfs and a duration of 12 hours. The duration was selected so that the triangular hydrograph would contain the same volume of water as the estimated storm runoff.

The hydrograph was routed through the reservoir using a computer program based on stage-storage and stage-discharge data. The reservoir was assumed to be full and level with the spillway prior to the storm event. The results of the flood routing computations indicate that the spillway test flood peak inflow rate of 7880 cfs is reduced to a peak outflow rate of 7730 cfs by the storage of water in the reservoir. The spillway can pass 20 percent of the spillway test flood outflow without overtopping the dam.

The peak flood stage from the test flood is at elevation 576.2, which is 4.2 feet above the crest of the embankment, and 1.9 feet above the parapet wall. The duration of the overflow is approximately 8 hours.

The dam was also evaluated for a flood flow equal to 1/2 PMF. The peak inflow is 3940 cfs. When this flood is routed through the reservoir the resulting flood stage is elevation 574.8, about 2.8 feet above the crest of the dam and 0.5 feet over the top of the parapet wall.

5.5 DAM FAILURE ANALYSIS:

The downstream impact of a dam failure was analyzed using the COE "Rule of Thumb Guidance for Estimating Downstream Dam Failure Hydrographs" dated April 1978.

Based upon an assumed breach width of 124 feet, equal to 40% of the dam's width at mid-height, the peak flood flow due to failure would be 82,000 cfs. The base flow would be negligible.

Using topography data from U.S.G.S. maps the evaluation indicates that the dam failure floodwave would move rapidly down the steep valley of Whigville Brook, flooding Main Street in the village of Whigville and the one-family houses on both sides of Main Street.

It is estimated that sixteen houses would be affected (three buildings in areas with 3 feet of water or less above ground level, nine buildings with 3 to 6 feet of water above ground level, and four buildings with over 6 feet of water). In addition, developed areas further downstream would also be subject to flooding damages. With the potential for the loss of more than a few lives and significant economic losses, the dam has been classified as having a high hazard potential.

SECTION 6 - EVALUATION OF STRUCTURAL STABILITY

6.1 VISUAL OBSERVATIONS

The visual inspection did not disclose any immediate stability problems. However, the following potential structural stability problems were indicated:

a. The presence of soft, wet ground and standing water at the downstream toe of the dam may be the result of a seepage condition, which, if not controlled, could lead to failure of the dam.

b. Seepage through the joints of the stone mortar spillway wing wall adjacent to the dam embankment.

c. Severe deterioration including erosion and spalling of concrete at the parapet wall, the spillway crest and downstream weir.

6.2 DESIGN AND CONSTRUCTION DATA

There is insufficient design and construction data to permit a formal evaluation of stability.

6.3 POST-CONSTRUCTION CHANGES

The available correspondence indicates a section of the spillway washed out during the floods in August and October of 1955. Plans and specifications for the required repairs were prepared by S. Wood in August 1956. The repairs were completed in December 1956.

6.4 SEISMIC STABILITY

The dam is located in Seismic Zone 1 and, in accordance with the recommended Phase I guidelines, does not warrant seismic stability analysis.

SECTION 7 - ASSESSMENT, RECOMMENDATIONS, AND REMEDIAL MEASURES

7.1 DAM ASSESSMENT

a. Condition. Based on the visual inspection, the dam appears to be in poor condition. There are several features which could adversely affect the condition of the dam in the future including: 1) Seepage along the toe of the dam and adjacent to the spillway wing walls. 2) Trees on downstream embankment slopes. 3) Existence of several pipe outlets discharging into the spillway channel from unknown sources. 4) Seepage through the joints of the stone masonry spillway wing walls.

The capacity of the spillway is inadequate to pass the PMF spillway test flood outflow of 7730 CFS without overtopping the dam. The test flood would overtop the dam by about 4.2 ft. The spillway is adequate to pass about 20 percent of the test flood outflow without overtopping the dam.

b. Adequacy of Information. The lack of in-depth engineering data did not allow for a definitive review. Therefore, the adequacy of this dam could not be assessed from the standpoint of reviewing design and construction data but is based primarily on visual inspection, past operational performance, and sound engineering judgement.

c. Urgency. The recommendations and remedial measures described below should be implemented by the owner within one year after receipt of the Phase I inspection report.

7.2 RECOMMENDATIONS

The following items should be performed under the direction of a qualified registered engineer:

a. Investigate the significance of the seepage along the downstream toe and recommend measures for monitoring the seepage and for preventing piping of the embankment soils.

b. Investigate the seepage through the joints in the stone masonry wing walls and recommend measures for repair to prevent erosion and piping of the embankment soils.

c. Remove trees growing on downstream embankment soils and within 25 ft. of the downstream toe. Backfill root depressions with appropriate soils.

d. Investigate source of water flowing into the spillway channel from several pipe outlets.

e. Conduct more refined hydrologic and hydraulic analysis to determine the need for and methods of increasing the project discharge capacity.

f. Repair failed portion of right retaining wall.

g. Repair spalled and deteriorated concrete at spillway crest, downstream weir and parapet wall.

h. Locate and operate low level outlet and, if inoperable, provide a means of lowering water level in reservoir.

7.3 REMEDIAL MEASURES

a. Operating and Maintenance Procedure.

1) Brush and small saplings growing on and downstream slope of the dam should be cut and the brush and saplings should be removed and the new growth cut every year.

2) Grass growing on the dam should be maintained on a regular basis.

3) After the brush and saplings have been removed, the dam should be re-inspected by a qualified registered engineer.

4) Grass should be planted on the bare areas on the crest of the dam and on the slopes to prevent erosion at these locations.

5) Repair scour hole at end of spillway discharge channel.

6) Repair and clean out deteriorated stilling well for "blow off."

7) Repair deteriorated concrete of stilling basin slab.

8) Replace all missing riprap.

9) Paint steel members of footbridge to prevent continued rusting.

10) Engage a qualified registered engineer to make a comprehensive technical inspection of the dam once a year.

11) Establish a formal surveillance program for use during and immediately after heavy rainfall and also a flood warning plan to follow in case of flood flow conditions or imminent dam failure.

7.4 ALTERNATIVES

There are no practical alternatives to the recommendations contained in Sections 7.2 and 7.3.

APPENDIX A

INSPECTION CHECK LIST

PERIODIC INSPECTION CHECK LIST
NATIONAL DAM INSPECTION PROGRAM

DAM: Whigville Reservoir Dam

DATE: Oct. 24, 1979

AREA EVALUATED	CONDITIONS
<p><u>DAM EMBANKMENT</u></p> <p>Crest Elevation</p> <p>Current Pool Elevation</p> <p>Maximum Impoundment to Date</p> <p>Surface Cracks</p> <p>Pavement Condition</p> <p>Movement or Settlement of Crest</p> <p>Lateral Movement</p> <p>Vertical Alignment</p> <p>Horizontal Alignment</p> <p>Condition at Abutment and at Concrete Structures</p> <p>Indications of Movement of Structural Items on Slopes</p> <p>Trespassing on Slopes</p> <p>Sloughing or Erosion of Slopes or Abutments</p> <p>Rock Slope Protection - Riprap Failures</p> <p>Unusual Movement or Cracking at or near Toes</p> <p>Unusual Embankment or Downstream Seepage</p> <p>Piping or Boils</p> <p>Foundation Drainage Features</p> <p>Toe Drains</p> <p>Instrumentation System</p> <p>Vegetation</p>	<p>None observed.</p> <p>Grass.</p> <p>None observed.</p> <p>None observed.</p> <p>Good.</p> <p>Good.</p> <p>Erosion adjacent to spillway wing wall. Concrete wall at upstream face spalling/erosion at water line.</p> <p>None observed.</p> <p>Vehicular path on the downstream slope near Sta. 0+20. Small scarp on slope adjacent to right wing wall at Sta. 1+0.</p> <p>Riprap missing from bench in front of upstream concrete wall, other areas riprap in good condition.</p> <p>None observed.</p> <p>Apparent seepage and wet area at the toe and on both sides of the spillway.</p> <p>None observed.</p> <p>Extensive growth of trees on the downstream slope below the lower gatehouse.</p>

PERIODIC INSPECTION CHECK LIST
NATIONAL DAM INSPECTION PROGRAM

DAM: Whigville Reservoir Dam DATE: Oct. 24, 1979

AREA EVALUATED	CONDITIONS
<p><u>DIKE EMBANKMENT</u></p> <p>Crest Elevation</p> <p>Current Pool Elevation</p> <p>Maximum Impoundment to Date</p> <p>Surface Cracks</p> <p>Pavement Condition</p> <p>Movement or Settlement of Crest</p> <p>Lateral Movement</p> <p>Vertical Alignment</p> <p>Horizontal Alignment</p> <p>Condition at Abutment and at Concrete Structures</p> <p>Indications of Movement of Structural Items on Slopes</p> <p>Trespassing on Slopes</p> <p>Sloughing or Erosion of Slopes or Abutments</p> <p>Rock Slope Protection - Riprap Failures</p> <p>Unusual Movement or Cracking at or near Toes</p> <p>Unusual Embankment or Downstream Seepage</p> <p>Piping or Boils</p> <p>Foundation Drainage Features</p> <p>Toe Drains</p> <p>Instrumentation System</p> <p>Vegetation</p>	<p>Not applicable.</p>

PERIODIC INSPECTION CHECK LIST
NATIONAL DAM INSPECTION PROGRAM

DAM: Whigville Reservoir Dam

DATE: Oct. 24, 1979

AREA EVALUATED	CONDITIONS
<p><u>OUTLET WORKS - CONTROL TOWER</u></p> <p>a. Concrete and Structural</p> <p>General Condition</p> <p>Condition of Joints</p> <p>Spalling</p> <p>Visible Reinforcing</p> <p>Rusting or Staining of Concrete</p> <p>Any Seepage or Efflorescence</p> <p>Joint Alignment</p> <p>Unusual Seepage or Leaks in Gate Chamber</p> <p>Cracks</p> <p>Rusting or Corrosion of Steel</p> <p>b. Mechanical and Electrical</p> <p>Air Vents</p> <p>Float Wells</p> <p>Crane Hoist</p> <p>Elevator</p> <p>Hydraulic System</p> <p>Service Gates</p> <p>Emergency Gates</p> <p>Lightning Protection System</p> <p>Emergency Power System</p> <p>Wiring and Lighting System in Gate Chamber</p>	<p>Generally appears to be in good condition, not used in operation of dam. Lower gate-house in good condition.</p>

PERIODIC INSPECTION CHECK LIST
NATIONAL DAM INSPECTION PROGRAM

DAM: Whigville Reservoir Dam DATE: Oct. 24, 1979

AREA EVALUATED	CONDITIONS
<p><u>OUTLET WORKS - TRANSITION AND CONDUIT</u></p> <p>General Condition of Concrete</p> <p>Rust or Staining on Concrete</p> <p>Spalling</p> <p>Erosion or Cavitation</p> <p>Cracking</p> <p>Alignment of Monoliths</p> <p>Alignment of Joints</p> <p>Numbering of Monoliths</p>	<p>Not applicable.</p>

PERIODIC INSPECTION CHECK LIST
NATIONAL DAM INSPECTION PROGRAM

DAM: Whigville Reservoir Dam DATE: Oct. 24, 1979

AREA EVALUATED	CONDITIONS
<p><u>OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL</u></p> <p>General Condition of Concrete</p> <p>Rust or Staining</p> <p>Spalling</p> <p>Erosion or Cavitation</p> <p>Visible Reinforcing</p> <p>Any Seepage or Efflorescence</p> <p>Condition at Joints</p> <p>Drain Holes</p> <p>Channel</p> <p>Loose Rock or Trees Overhanging Channel</p> <p>Condition of Discharge Channel</p>	<p>Not applicable.</p>

PERIODIC INSPECTION CHECK LIST
NATIONAL DAM INSPECTION PROGRAM

DAM: Whigville Reservoir Dam DATE: Oct. 24, 1979

AREA EVALUATED	CONDITIONS
<p><u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u></p>	
<p>a. Approach Channel</p> <p> General Condition</p> <p> Loose Rock Overhanging Channel</p> <p> Trees Overhanging Channel</p> <p> Floor of Approach Channel</p>	<p>Underwater.</p>
<p>b. Weir and Training Walls</p> <p> General Condition of Concrete</p> <p> Rust or Staining</p> <p> Spalling</p> <p> Any Visible Reinforcing</p> <p> Any Seepage or Efflorescence</p> <p> Drain Holes</p>	<p>Concrete in poor condition, with extensive spalling and deterioration observed.</p> <p>None observed.</p> <p>Major spalling of weir.</p> <p>None observed.</p> <p>Training walls show evidence of seepage (wet) and efflorescence.</p> <p>Discharging water, several contain extensive vegetation.</p>
<p>c. Discharge Channel</p> <p> General Condition</p> <p> Loose Rock Overhanging Channel</p> <p> Trees Overhanging Channel</p> <p> Floor of Channel</p> <p> Other Obstructions</p>	<p>The discharge channel is in fair condition.</p> <p>None observed.</p> <p>Trees close to channel on both sides.</p> <p>Natural bottom, has been concreted during recent repair.</p> <p>Small weir existing in the channel approximately 500 ft. below end of training walls.</p>

PERIODIC INSPECTION CHECK LIST
NATIONAL DAM INSPECTION PROGRAM

DAM: Whigville Reservoir Dam DATE: Oct. 24, 1979

AREA EVALUATED	CONDITIONS
<p><u>OUTLET WORKS - SERVICE BRIDGE</u></p> <p>a. Superstructure</p> <p>Bearings</p> <p>Anchor Bolts</p> <p>Bridge Seat</p> <p>Longitudinal Members</p> <p>Under Side of Deck</p> <p>Secondary Bracing</p> <p>Deck</p> <p>Drainage System</p> <p>Railings</p> <p>Expansion Joints</p> <p>Paint</p> <p>b. Abutment & Piers</p> <p>General Condition of Concrete</p> <p>Alignment of Abutment</p> <p>Approach to Bridge</p> <p>Condition of Seat and Backwall</p>	<p>Steel truss in good condition, with some rusting and staining taking place.</p> <p>Good condition.</p> <p>Rusting.</p> <p>Fair condition, with efflorescence observed at bridge seat.</p>

APPENDIX B

ENGINEERING DATA

CHECK LIST
ENGINEERING DATA

NAME OF DAM Whigville Res. Dam

DESIGN, CONSTRUCTION, OPERATION
PHASE I

I.D. NO. CT 00379

ITEM

REMARKS

AS-BUILT DRAWINGS

Construction Plans - New Britain Water Co. Files

REGIONAL VICINITY MAP

Available from U.S.G.S.

CONSTRUCTION HISTORY

Limited Data - New Britain Water Co. Files

TYPICAL SECTIONS OF DAM

From plans

OUTLETS - Plan

From plans

- Details

From plans

- Constraints

Unknown

- Discharge Ratings

None

RAINFALL/RESERVOIR RECORDS

New Britain Water Co.

DESIGN REPORTS

Unavailable.

GEOLOGY REPORTS

None

DESIGN COMPUTATIONS

None available

HYDROLOGY & HYDRAULICS

None available

DAM STABILITY

None available

SEEPAGE STUDIES

MATERIALS INVESTIGATIONS

None

BORINGS RECORDS

None

LABORATORY

None

FIELD

CHECK LIST

ENGINEERING DATA
 DESIGN, CONSTRUCTION, OPERATION
 PHASE I


NAME OF DAM Whigville Res. Dam

I.D. NO. CT 00379


ITEM	REMARKS
POST-CONSTRUCTION SURVEYS OF DAM	None available
BORROW SOURCES	Unknown
MONITORING SYSTEMS	None
MODIFICATIONS	Yes - DEP files
HIGH POOL RECORDS	None
POST-CONSTRUCTION ENGINEERING STUDIES AND REPORTS	None
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	No
MAINTENANCE OPERATION RECORDS	None
SPILLWAY PLAN	From plans
SECTIONS	From plans
DETAILS	From plans
OPERATING EQUIPMENT PLANS & DETAILS	From plans



POND




PL
NT



DOWNSTREAM

POND



PLAN

NTS

Top Parapet Wall
El. 498.0

Top Of Slope

Earth Embankment

Toe Of Slope

500

490



480

470

DOWNSTREAM ELEVATION OF DAM


NTS

WHIGVILLE RESERVOIR





DAM

WHIGVILLE RESERVOIR DAM





1



SHEET B
 NEW BRITAIN WATER WORKS
 WHIGVILLE RESERVOIR N
 1909
 PLAN - PROFILE - CROSS SECTION
 NATURAL SCALE - 10 FEET PER INCH

REDUCED NOT TO SCALE




SHEET B
 NEW BRITAIN WATER WORKS
 WHIGVILLE RESERVOIR No. 1
 1908
 PLAN - PROFILE - CROSS SECTION
 NATURAL SCALE - 10 FEET PER INCH

Ray W. ...
 Chief Engineer
 July 26, 1907

REDUCED NOT TO SCALE



SHEET C
NEW BRITAIN WATER WORKS
WHIGVILLE RESERVOIR NO. 1
1900
WASTEWAY
PLAN-SECTIONS AND
WASTE PIPE OUTLET
VARIOUS SCALES

Roy W. Blake
Chief Engineer
July 20, 1907




CROSS SECTION OF WASTEWAY CHANNEL
 NEW SCALE: 1/4" = 1'-0"

WASTEWAY, OVERFALL
 Scale: 1/4" per inch




PLAN OF DAM


CROSS SECTIONS OF WESTERN CHANNEL
Noted/Scale-10 ft per inch



PLAN OF WASTEWAY AND WASTE CHANNEL
Scale-10 ft per inch




REDUCED NOT TO SCALE



WASTEWAY AND WASTE CHANNEL
Scale - 10 Ft. per inch

REDUCED NOT TO SCALE





PLAN
N.T.S.


SOURCE:
 NEW BRITAIN WATER WORKS
 WHIGVILLE DAM #1

SUBSURFACE DRAINS & WEEP HOLES
 TO ACCOMPANY SEEPAGE CHART



1" = 20' 1912 - 1913
 DANIEL CROWLEY
 CIVIL ENGINEERS









4



Crims. to be permit
with gravel and rubble concrete

Approximate
End of Contract



APPROVED
FOR CONSTRUCTION
STATE BOARD OF SUPERVISION OF DAMS
By *J. Morzochi*
Date 8/8/56

RECEIVED
SEP 8 1956
RECEIVED
JOHN J. MORZOCCHI
CONSULTING ENGINEER

REDUCED NOT TO SCALE

BOARD OF WATER COMMISSIONERS
NEW BRITAIN, CONN
REPAIRS TO WHIGVILLE SPILLWAY
Aug 1956 Scale: 1" = 10'
S.W. Wood - Chief Eng.

S P E C I F I C A T I O N S

1. The work to be performed under this contract shall consist of furnishing all labor, materials and equipment necessary for making repairs to the spillway of the Whigville Reservoir located in Burlington, Conn.
2. The work consists of repairing a washed out area under the south wall of the spillway channel and repairing the bed of the spillway channel.
3. The work shall be strictly in accordance with the specifications and the accompanying drawing.
4. Care must be exercised to protect the 24-inch waste pipe from damage.
5. The contractor shall obtain all permits necessary for the prosecution of the work. The contractor shall comply with all local and state laws, ordinances, rules and regulations relating to the performance of the work.
6. The contractor is required to inspect the site of the work before he submits his bid.
7. Rubble concrete shall be used with large clean stones thoroughly embedded in the concrete and as near together as possible while still entirely surrounded by concrete. No stones shall extend above the finished grade of the spillway channel. There shall be at least one foot of concrete above all stones.
8. Concrete shall be in the proportion 1:3:5 and shall be in accordance with the latest recommendations of the Joint Committee A.C.I.A.S.T.M.
9. The concrete shall be brought to the finished grade as set by the Owner and given a screeded finish.
10. The gravel to be used for the gravel base shall consist of sound, tough, durable particles of crushed or uncrushed gravel free from soft, thin, elongated or laminated pieces and vegetable or other deleterious substances. Samples of the gravel to be used must be approved by the Owner.
11. The two 6-inch vent pipes shall be either wrought iron or extra heavy steel pipe and shall be securely fastened to the faces of the side walls of the spillway channel.
12. The contractor shall guarantee the quality of all materials used and the work performed for a period of one year from the time of completion.
13. The contractor shall take out and maintain during the life of this contract such Public Liability and Property Damage Insurance as shall protect him and any subcontractor performing work covered by this contract from claims for damages for personal injury, including accidental death, as well as from claims for property damages which may arise from operations under this contract, whether such operations be by himself or by any subcontractor or by anyone directly or indirectly employed by either of them and the amounts of such insurance shall be as follows:

**APPROVED
FOR CONSTRUCTION**

STATE BOARD OF SUPERVISION OF DAMS

BY

J. J. Mozzochi
9/15/56

B-8

(2)

Public Liability Insurance in an amount not less than \$50,000 for injuries, including accidental death, to any one person, and subject to the same limit for each person, in an amount not less than \$100,000 on account of one accident, and Property Damage Insurance in an amount not less than \$5,000.

14. The wages to be paid to any mechanic, laborer or workman employed upon the work herein contracted for shall be at the rate customary or prevailing for the same work in the same trade and occupation in the City of New Britain based upon the wage schedule and the rates therein set by the U. S. Department of Labor for the New Britain area.

JOHN J. MOZZOCHI AND ASSOCIATES
CIVIL ENGINEERS

GLASTONBURY, CONN.
217 HEBRON AVENUE
PHONE 633-9401

PROVIDENCE 3, R. I.
198 DYER STREET
PHONE GASPEE 1-0420

JOHN J. MOZZOCHI

June 14, 1965

ASSOCIATES

OWEN J. WHITE
JOHN LUCHS, JR.
ECTOR L. GIOVANNINI

REPLY TO: Glastonbury

William P. Sander-Engineer-Geologist
Water Resources Commission
State Office Building
Hartford 15, Connecticut


Re: Our File 57-73-69
Whigville Dam
Burlington

Dear Mr. Sander:


I inspected the referenced dam on June 10th in accordance with your instructions of May 10th and found that the work originally called for by the Preliminary Permit dated September 8, 1956, has been completed and the repairs are in good condition today with the possible exception of the 6" dia. vent pipes.

My recollection is that these vent pipes were to extend almost to the apron, whereas the bottom of the pipes are now about 12' above the apron and one of them is disjointed about at it's mid-point. Otherwise the work may be considered acceptable to issue a Final Permit.

Very truly yours,


John J. Mozzochi and Associates
Civil Engineers

JJM:hk






jck

CITY OF NEW BRITAIN
NEW BRITAIN, CONNECTICUT

October 28, 1965

State of Connecticut
Water Resources Commission
State Office Building
Hartford, Connecticut



Attention: Mr. William P. Sander
Engineer - Geologist

Re: Inspection Report of Whigville Dam
in Burlington

Dear Sir:

The items noted for action in your letter of June 24, 1965 on the subject matter have been reviewed by this department. An inspection of the area manifested that the vent pipes were installed in accordance with the contract plans. The joint in the vent pipes which had become disconnected have been sealed by enclosing them in a concrete encasement.

Funds are being requested in the 1966 budget to replace all old concrete that has deteriorated over the years because of weather action.

If there are any further questions, please contact the writer at 224-2491, Ext. 260.

Yours truly,

BOARD OF WATER COMMISSIONERS

Peter M. Arburr
Peter M. Arburr
Engineer III

jek



STATE OF CONNECTICUT

WATER RESOURCES COMMISSION

STATE OFFICE BUILDING · HARTFORD 15, CONNECTICUT

CERTIFICATE OF APPROVAL

April 5, 1966

City of New Britain
Board of Water Commissioners
27 West Main Street
New Britain, Connecticut

TOWN: Burlington
RIVER: Copper Mine Brook
TRIBUTARY: Whigville Brook
CODE NO.: P 6.6 CM 4.5 W 2.2

Gentlemen:

NAME AND LOCATION OF STRUCTURE: The Whigville Dam located on Whigville Brook in the Town of Burlington.

DESCRIPTION OF STRUCTURE AND WORK PERFORMED: Repairing a washed out area under the south wall of the spillway channel and repairing the bed of the spillway channel.

CONSTRUCTION PERMIT ISSUED UNDER DATE OF: September 8, 1956

This certifies that the work and construction included in the plans submitted, for the structure described above, has been completed to the satisfaction of this Commission and that this structure is hereby approved in accordance with Section 25-114 of the 1958 Revision of the General Statutes.

The owner is required by law to record this Certificate in the land records of the town or towns in which the structure is located.


WATER RESOURCES COMMISSION

BY: William S. Wise, Director

WSW:js

APPENDIX C

PHOTOGRAPHS



**WHIGVILLE RESERVOIR DAM
PHOTO LOCATION MAP**

LEGEND

Number refers to caption.
Arrow indicates direction
of photograph.




PHOTO #1: Upstream face of dam from right (south) abutment.



PHOTO #2: Upstream face of dam from left (north) abutment.



PHOTO #3: Crest of dam from left (north) abutment.



PHOTO #4: Downstream slope from vicinity of toe.




PHOTO #5: Downstream slope from right (south) abutment, looking towards spillway.



PHOTO #6: Downstream slope looking towards left (north) abutment.




PHOTO #7: Downstream slope.



PHOTO #8: Downstream slope. Note extensive vegetation.




PHOTO #9: Upstream face, looking towards spillway approach.



PHOTO #10: Spillway and service bridge.



PHOTO #11: Spillway weir.



PHOTO #12: Right (south) side spillway training wall.



PHOTO #13: Spillway channel from service bridge.



PHOTO #14: Looking upslope from end of spillway channel.



PHOTO #15: 4-inch diameter toe drains.



PHOTO #16: Spillway channel.




PHOTO #17: Reservoir Area.

APPENDIX D

HYDROLOGIC AND HYDRAULIC
COMPUTATIONS



DETERMINATION OF SPILLWAY TEST FLOOD*

A. SIZE CLASSIFICATION

Storage Volume (Ac.-Ft.) 250
Height of Dam (Ft.) 54
Size Classification INTERMEDIATE

B. HAZARD POTENTIAL CLASSIFICATION

<u>Category</u>	<u>Loss of Life</u>	<u>Economic Loss</u>
Low	None expected	Minimal
Significant	Few	Appreciable
<u>High</u>	<u>More than few</u>	Excessive

Hazard Classification HIGH

C. HYDROLOGIC EVALUATION GUIDELINES

<u>Hazard</u>	<u>Size</u>	<u>Spillway Test Flood*</u>
Low	Small	50 to 100-Year Frequency
	Intermediate	100-Year Frequency to 1/2 PMF
	Large	1/2 PMF to PMF
Significant	Small	100-Year Frequency to 1/2 PMF
	Intermediate	1/2 PMF to PMF
	Large	PMF
<u>High</u>	Small	1/2 PMF to PMF
	<u>Intermediate</u>	<u>PMF</u>
	Large	PMF

Spillway Test Flood" PMF

*Based upon "Recommended Guidelines for Safety Inspection of Dams" Department of the Army, Office of the Chief of Engineers, November 1976.



DETERMINATION OF THE
MAXIMUM PROBABLE FLOOD (MPF)

A. Drainage Area in Square Miles 4.15

B. Watershed Characteristic: Flat & Coastal
Rolling
Moutainous

C. M.P.F. in CFS/Square Mile,* 1900

M.P.F. = (CFS/Square Mile) x (Area in Square Miles)

$$\underline{1900} \times \underline{4.15} = \underline{7885}$$

*Based upon the figure "Maximum Probable Flood Peak Flow Rates"
U.S. Army Corps of Engineers, December 1977.



THE PMP RAINFALL IS 23.5 INCHES FOR A 6HR DURATION, 24 HR STORM. USING A 20% FACTOR FOR IMPERFECT FIT, THE EFFECTIVE RAINFALL IS 18.8 INCHES, (SEE FIG. 15, DESIGN OF SMALL DAMS).


RUNOFF

BASED ON AN ASSUMED CN VALUE OF 80 (FOR GLACIAL TILL SOILS), RUNOFF FOR THE PMP IS 16.0 INCHES (FIG. A-4 "DESIGN OF SMALL DAMS),

$$\begin{aligned} \text{VOLUME OF RUNOFF} &= (16 \text{ "/}12 \text{ "/FT}) (4.15 \text{ MI}^2) (640 \text{ AC/MI}^2) = \\ &= 3540 \text{ AC-FT} \end{aligned}$$

HYDROGRAPH

A TRIANGULAR HYDROGRAPH IS TO BE USED FOR THE ROUTING OF THE TEST FLOOD THROUGH THE RESERVOIR. PEAK FLOW EQUALS 7885 CFS, SET DURATION OF RUNOFF SO AS TO CONTAIN VOLUME OF RUNOFF, AND RECEEDING LIMB EQUAL TWICE THE RISING LIMB.



$$\text{VOL} = 4205 \text{ AC-FT} = \frac{1}{2} Q_p D$$

$$D = \frac{3540 \text{ AC-FT}}{0.5 (7885 \text{ CFS})} = \frac{(3540) (43560 \text{ ft}^2/\text{AC})}{0.5 (7885 \text{ CFS}) (60 \frac{\text{SEC}}{\text{MIN}}) (60 \frac{\text{MIN}}{\text{HR}})} = 10.8 \text{ HRS}$$

SAY $T_p = 4.0 \text{ HRS}$ $D = 12.0 \text{ HRS}$



FORM INFLOW TRIANGULAR HYDROGRAPH

$Q_p = 7885 \text{ CFS}$
 $T_p = 4.0 \text{ HRS}$
 $D = 12.0 \text{ HRS}$

<u>TIME (HRS)</u>	<u>PMF INFLOW (CFS)</u>	<u>1/2 PMF INFLOW, CFS</u>
0	0	0
1	1971	986
2	3942	1971
3	5914	2957
4	7885	3942
5	7000	3500
6	5914	2957
7	4925	2462
8	3943	1972
9	2957	1478
10	1971	985
11	986	493
12	0	0



FORM INFLOW TRIANGULAR HYDROGRAPH


$Q_p = 7885$ CFS
 $T_p = 4.0$ HRS
 $D = 12.0$ HRS

<u>TIME (HRS)</u>	<u>PMF INFLOW (CFS)</u>	<u>1/2 PMF INFLOW, CFS</u>
0	0	0
1	1971	986
2	3942	1971
3	5914	2957
4	7885	3942
5	7000	3500
6	5914	2957
7	4925	2462
8	3943	1972
9	2957	1478
10	1971	985
11	986	493
12	0	0



BURLINGTON

SPILLWAY AND OVERFLOW SECTION DATA
 N.T.S.



<u>SEGMENT</u>	<u>ITEM</u>	<u>C</u>	<u>LENGTH</u>	<u>ELEV.</u>
1	EARTH DIKE	2.5	40'	572.0
2	PARAPET	3.0	280	574.3
3	SPILLWAY	3.5	40	567.0
4	PARAPET	3.0	100	574.3


IE = 567.0 IV = 0.0 E = 567 A = 11 E = 590 A = 15

BREACH WIDTH = 124



11 BURLINGTON

STAGE DISCHARGE DATA
 N.T.S.




$Q_1 = C_1 L_1 H_1^{3/2}$
 (2.5)(40)

$Q_2 = C_2 L_2 H_2^{3/2}$
 30(280)

$Q_3 = C_3 L_3 H_3^{3/2}$
 35(40)

$Q_4 = C_4 L_4 H_4^{3/2}$
 3.0(100)


ELEV	568	569	570	571	572	573	574	575	576
					0	100	283	520	800
							0	492	1862
	0	140	396	727	1120	1565	2058	2593	3168
							0	176	665
TOTAL	140	396	727	1120	1565	2158	2876	4356	7107



DISCHARGE, CFS

STAGE - DISCHARGE CURVE

10 X 10 TO THE CENTIMETER 18 X 21 CM
K&E & ESS. MADE IN U.S.A.



INPUT DATA:
 SEGMENT 1 UNSUBMERGE WEIR = 2.5 LENGTH OF WEIR = 40 ELEVATION OF WEIR = 572
 SEGMENT 2 DISCHARGE COEFFICIENT = 3 LENGTH OF WEIR = 280 ELEVATION OF WEIR = 574.3
 SEGMENT 3 DISCHARGE COEFFICIENT = 3.5 LENGTH OF WEIR = 40 ELEVATION OF WEIR = 567
 SEGMENT 4 DISCHARGE COEFFICIENT = 3 LENGTH OF WEIR = 100 ELEVATION OF WEIR = 574.3
 IE=567.0 IV= 0.0 E=567.0 A= 11.00 E=580.0 A= 15.00

INFLOW	MASS INFLOW	WATE I EL.	TAIL WATER	OUTFLOW	MASS OUTFLOW	STORAGE(R)	STORAGE(A)
0.00	0CFS	567.00FT	.00FT	0CFS	0.00AC-F	0.00AC-F	0.00AC-F
1.00	1,971CFS	570.61FT	0.00FT	960CFS	39.70AC-F	41.73AC-F	41.73AC-F
2.00	3,942CFS	574.68FT	0.00FT	3,696CFS	232.15AC-F	93.63AC-F	93.63AC-F
3.00	5,914CFS	575.58FT	0.00FT	5,865CFS	627.26AC-F	105.79AC-F	105.79AC-F
4.00	7,885CFS	576.19FT	0.00FT	7,731CFS	1,189.13AC-F	114.13AC-F	114.13AC-F
5.00	7,000CFS	576.03FT	0.00FT	7,207CFS	1,806.44AC-F	111.89AC-F	111.89AC-F
6.00	5,914CFS	575.58FT	0.00FT	5,855CFS	2,346.23AC-F	105.74AC-F	105.74AC-F
7.00	4,925CFS	575.29FT	0.00FT	5,077CFS	2,798.02AC-F	101.85AC-F	101.85AC-F
8.00	3,943CFS	574.81FT	0.00FT	3,947CFS	3,170.98AC-F	95.33AC-F	95.33AC-F
9.00	2,957CFS	574.30FT	0.00FT	3,115CFS	3,462.86AC-F	88.57AC-F	88.57AC-F
10.00	1,971CFS	573.06FT	0.00FT	2,203CFS	3,682.66AC-F	72.42AC-F	72.42AC-F
11.00	986CFS	571.36FT	0.00FT	1,274CFS	3,826.38AC-F	50.88AC-F	50.88AC-F
12.00	0CFS	568.99FT	0.00FT	395CFS	3,895.41AC-F	22.60AC-F	22.60AC-F

WHIGVILLE RES. DAM 1/2 PMF 799010 FLOOD ROUTING RAC FEB. 12, 198

INPUT DATA:
 SEGMENT 1 UNSUBMERGED WEIR DISCHARGE COEFFICIENT = 2.5 LENGTH OF WEIR = 40 ELEVATION OF WEIR = 572
 SEGMENT 2 DISCHARGE COEFFICIENT = 3 LENGTH OF WEIR = 280 ELEVATION OF WEIR = 574.3
 SEGMENT 3 DISCHARGE COEFFICIENT = 3.5 LENGTH OF WEIR = 40 ELEVATION OF WEIR = 567
 SEGMENT 4 DISCHARGE COEFFICIENT = 3 LENGTH OF WEIR = 100 ELEVATION OF WEIR = 574.3
 IE=567.0 IV= 0.0 E=567.0 A= 11.00 E=580.0 A= 15.00

Hour	Inflow	Mass Inflow	Water El.	Tail Water	Outflow	Mass Outflow	Storage (R)	Storage (A)
0.00	0CFS	0.00AC-F	567.00FT	.00FT	0CFS	0.00AC-F	0.00AC-F	0.00AC-F
1.00	986CFS	40.74AC-F	569.07FT	0.00FT	418CFS	17.27AC-F	23.47AC-F	23.47AC-F
2.00	1,971CFS	162.93AC-F	572.14FT	0.00FT	1,639CFS	102.27AC-F	60.65AC-F	60.65AC-F
3.00	2,957CFS	366.57AC-F	573.84FT	0.00FT	2,759CFS	284.03AC-F	82.53AC-F	82.53AC-F
4.00	3,942CFS	651.65AC-F	574.76FT	0.00FT	3,845CFS	556.99AC-F	94.66AC-F	94.66AC-F
5.00	3,500CFS	959.17AC-F	574.65FT	0.00FT	3,632CFS	866.00AC-F	93.17AC-F	93.17AC-F
6.00	2,957CFS	1,225.99AC-F	574.14FT	0.00FT	2,987CFS	1,139.54AC-F	86.44AC-F	86.44AC-F
7.00	2,462CFS	1,449.91AC-F	573.62FT	0.00FT	2,595CFS	1,370.26AC-F	79.65AC-F	79.65AC-F
8.00	1,972CFS	1,633.14AC-F	572.87FT	0.00FT	2,074CFS	1,563.23AC-F	69.90AC-F	69.90AC-F
9.00	1,478CFS	1,775.70AC-F	572.09FT	0.00FT	1,614CFS	1,715.63AC-F	60.06AC-F	60.06AC-F
10.00	985CFS	1,877.47AC-F	571.08FT	0.00FT	1,154CFS	1,830.02AC-F	47.45AC-F	47.45AC-F
11.00	493CFS	1,938.55AC-F	569.86FT	0.00FT	678CFS	1,905.77AC-F	32.77AC-F	32.77AC-F
12.00	0CFS	1,958.92AC-F	568.39FT	0.00FT	229CFS	1,943.32AC-F	15.60AC-F	15.60AC-F

FGA FLOOD WAVE ROUTING

APPROXIMATE FLOOD WAVE ROUTING BASED UPON U.S. ARMY CORPS OF ENGINEERS' "RULE OF THUMB GUIDANCE FOR ESTIMATING DOWNSTREAM DAM FAILURE HYDROGRAPHS" DATED APRIL, 1978.

INITIAL STATION = 0 +0
 INITIAL BASE FLOW = 2,761 CFS.
 INITIAL WAVE HEIGHT = 54.0 FT
 ASSUMED BREACH WIDTH = 124.0 FT
 INITIAL RESERVOIR STORAGE = 250 ACRE-FT
 COMPUTED FLOOD WAVE PEAK FLOW = 82,679 CFS
 TOTAL FLOOD WAVE PEAK FLOW = 85,440CFS

STATION 1 +30

OFFSET	ELEV.	OFFSET	ELEV.	OFFSET	ELEV.
N = 0.070					
-720.0 FT	600.0 FT	-480.0 FT	580.0 FT	-300.0 FT	570.0 FT
-40.0 FT	560.0 FT	-10.0 FT	525.0 FT		
N = 0.050					
-10.0 FT	525.0 FT	-5.0 FT	523.0 FT	5.0 FT	523.0 FT
10.0 FT	525.0 FT				
N = 0.070					
10.0 FT	525.0 FT	100.0 FT	530.0 FT	160.0 FT	540.0 FT
200.0 FT	550.0 FT	360.0 FT	600.0 FT		

AREA	WETTED PERIMETER	N	VELOCITY	FLOW
181.9 SF	27.1 FT	0.070	15.8 FPS	2,881CFS
442.1 SF	20.7 FT	0.050	47.8 FPS	21,169CFS
2,328.7 SF	174.0 FT	0.070	25.0 FPS	58,436CFS

INVERT	DEPTH	W. SURFACE	AREA	VELOCITY	FLOW	SLOPE
523.0 FT	22.6 FT	545.6 FT	2,952 SF	27.9 FPS	82,486 CFS	0.0440

BASE FLOW = 2,761 CFS BASE STAGE = 528.7 FT.

STATION 10 +0

OFFSET	ELEV.	OFFSET	ELEV.	OFFSET	ELEV.
N = 0.070					
-530.0 FT	550.0 FT	-230.0 FT	500.0 FT	-20.0 FT	490.0 FT
-10.0 FT	488.0 FT				
N = 0.050					
-10.0 FT	488.0 FT	-5.0 FT	486.0 FT	5.0 FT	486.0 FT
10.0 FT	488.0 FT				
N = 0.070					
10.0 FT	488.0 FT	60.0 FT	490.0 FT	70.0 FT	500.0 FT
310.0 FT	530.0 FT	380.0 FT	540.0 FT	670.0 FT	540.0 FT
920.0 FT	550.0 FT				

AREA	WETTED PERIMETER	N	VELOCITY	FLOW
1,850.1 SF	238.7 FT	0.070	17.2 FPS	31,891CFS
330.2 SF	20.7 FT	0.050	38.9 FPS	12,870CFS
817.0 SF	88.4 FT	0.070	19.3 FPS	15,833CFS

INVERT	DEPTH	W. SURFACE	AREA	VELOCITY	FLOW	SLOPE
486.0 FT	17.0 FT	503.0 FT	2,997 SF	20.2 FPS	60,594 CFS	0.0430
BASE FLOW =		2,761 CFS	BASE STAGE =		491.3 FT.	

STATION 21+70

OFFSET	ELEV.	OFFSET	ELEV.	OFFSET	ELEV.
N = 0.070					
-950.0 FT	500.0 FT	-860.0 FT	490.0 FT	-730.0 FT	490.0 FT
-380.0 FT	490.0 FT	-80.0 FT	450.0 FT	-20.0 FT	440.0 FT
-10.0 FT	436.0 FT				
N = 0.050					
-10.0 FT	436.0 FT	-5.0 FT	434.0 FT	5.0 FT	434.0 FT
10.0 FT	436.0 FT				
N = 0.070					
10.0 FT	436.0 FT	30.0 FT	440.0 FT	300.0 FT	450.0 FT
400.0 FT	460.0 FT	690.0 FT	470.0 FT	780.0 FT	490.0 FT
1210.0 FT	500.0 FT				

AREA	WETTED PERIMETER	N	VELOCITY	FLOW
443.6 SF	74.1 FT	0.070	14.6 FPS	6,512CFS
316.6 SF	20.7 FT	0.050	38.3 FPS	12,135CFS
1,686.6 SF	293.9 FT	0.070	14.2 FPS	24,074CFS

INVERT	DEPTH	W. SURFACE	AREA	VELOCITY	FLOW	SLOPE
434.0 FT	16.3 FT	450.3 FT	2,446 SF	17.4 FPS	42,722 CFS	0.0440

BASE FLOW = 2,761 CFS BASE STAGE = 440.3 FT.

STATION 31+30

OFFSET	ELEV.	OFFSET	ELEV.	OFFSET	ELEV.
N = 0.070					
-1200.0 FT	460.0 FT	-880.0 FT	430.0 FT	-470.0 FT	430.0 FT
-400.0 FT	420.0 FT	-40.0 FT	410.0 FT	-10.0 FT	408.0 FT
N = 0.050					
-10.0 FT	408.0 FT	-5.0 FT	406.0 FT	5.0 FT	406.0 FT
10.0 FT	408.0 FT				
N = 0.070					
10.0 FT	408.0 FT	70.0 FT	410.0 FT	310.0 FT	430.0 FT
1000.0 FT	440.0 FT	1270.0 FT	450.0 FT	1330.0 FT	460.0 FT

AREA	WETTED PERIMETER	N	VELOCITY	FLOW
1,455.9 SF	321.9 FT	0.070	9.8 FPS	14,392CFS
232.1 SF	20.7 FT	0.050	25.2 FPS	5,872CFS
940.6 SF	157.6 FT	0.070	11.8 FPS	11,186CFS

INVERT	DEPTH	W. SURFACE	AREA	VELOCITY	FLOW	SLOPE
406.0 FT	12.1 FT	418.1 FT	2,628 SF	11.9 FPS	31,450 CFS	0.0290

BASE FLOW = 2,761 CFS BASE STAGE = 411.4 FT.

STATION 36 +0

OFFSET	ELEV.	OFFSET	ELEV.	OFFSET	ELEV.
		N = 0.070			
-2000.0 FT	440.0 FT	-1800.0 FT	430.0 FT	-1700.0 FT	420.0 FT
-1400.0 FT	420.0 FT	-1000.0 FT	410.0 FT	-950.0 FT	400.0 FT
-600.0 FT	400.0 FT	-400.0 FT	390.0 FT	-200.0 FT	390.0 FT
-5.0 FT	387.0 FT				

		N = 0.050	
-5.0 FT	387.0 FT	5.0 FT	387.0 FT

		N = 0.070			
5.0 FT	387.0 FT	100.0 FT	390.0 FT	125.0 FT	400.0 FT
250.0 FT	420.0 FT	950.0 FT	420.0 FT	2150.0 FT	420.0 FT

AREA	WETTED PERIMETER	N	VELOCITY	FLOW
1,896.6 SF	469.3 FT	0.070	10.7 FPS	20,428CFS
67.1 SF	10.0 FT	0.050	21.1 FPS	1,419CFS
512.3 SF	105.0 FT	0.070	12.2 FPS	6,256CFS

INVERT	DEPTH	W. SURFACE	AREA	VELOCITY	FLOW	SLOPE
387.0 FT	6.7 FT	393.7 FT	2,476 SF	11.3 FPS	28,105 CFS	0.0400

BASE FLOW = 2,761 CFS BASE STAGE = 390.1 FT.


STATION 43 +0

OFFSET	ELEV.	OFFSET	ELEV.	OFFSET	ELEV.
N = 0.070					
-2020.0 FT	410.0 FT	-1900.0 FT	400.0 FT	-1600.0 FT	380.0 FT
-10.0 FT	370.0 FT				
N = 0.050					
-10.0 FT	370.0 FT	-5.0 FT	368.0 FT	5.0 FT	368.0 FT
10.0 FT	370.0 FT				
N = 0.070					
10.0 FT	370.0 FT	270.0 FT	370.0 FT	750.0 FT	370.0 FT
1500.0 FT	370.0 FT	2250.0 FT	400.0 FT	2600.0 FT	450.0 FT

AREA	WETTED PERIMETER	N	VELOCITY	FLOW
335.6 SF	326.7 FT	0.070	3.8 FPS	1,297CFS
71.0 SF	20.7 FT	0.050	12.0 FPS	858CFS
3,114.4 SF	1541.4 FT	0.070	6.0 FPS	18,902CFS


INVERT	DEPTH	W. SURFACE	AREA	VELOCITY	FLOW	SLOPE
368.0 FT	4.0 FT	372.0 FT	3,521 SF	5.9 FPS	21,058 CFS	0.0320

BASE FLOW = 2,761 CFS BASE STAGE = 370.5 FT.



WHIGVILLE RESERVOIR DAM
DRAINAGE MAP
BURLINGTON, CONNECTICUT

FLAHERTY • GIAVARA ASSOCIATES, P.C.



 IMPACT AREA

SCALE IN FEET



**WHIGVILLE RESERVOIR DAM
DAM FAILURE ANALYSIS**

IMPACT AREA

BURLINGTON, CONNECTICUT

FLAHERTY • GIAVARA ASSOCIATES, P.C.

APPENDIX E

INFORMATION AS CONTAINED IN THE
NATIONAL INVENTORY OF DAMS

AND

FILMED

DTIC