

AD-A144 788


NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS  
BEAUPRE'S POND DAM (C. (U) CORPS OF ENGINEERS WALTHAM  
MA NEW ENGLAND DIV FEB 81


1/1

UNCLASSIFIED

F/G 13/13

NL





MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

AD-A144 788

1

THAMES RIVER BASIN  
POMFRET, CONNECTICUT

BEAUPRE'S POND DAM  
CT. 00584

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

This document has been approved  
for public release and wider in  
distribution is unlimited.



DTIC  
SELECTED  
AUG 23 1984  
A

DTIC FILE COPY

DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
WALTHAM, MASS.

84 08 20 035

FEBRUARY 1981

**UNCLASSIFIED**

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER <b>CT 00584</b>	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) <b>Beaupre's Pond Dam NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS</b>	5. TYPE OF REPORT & PERIOD COVERED <b>INSPECTION REPORT</b>	
	6. PERFORMING ORG. REPORT NUMBER	
7. AUTHOR(s) <b>U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION</b>	8. CONTRACT OR GRANT NUMBER(s)	
9. PERFORMING ORGANIZATION NAME AND ADDRESS	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS	
11. CONTROLLING OFFICE NAME AND ADDRESS <b>DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254</b>	12. REPORT DATE <b>February 1981</b>	
	13. NUMBER OF PAGES <b>50</b>	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)	15. SECURITY CLASS. (of this report) <b>UNCLASSIFIED</b>	
	15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	
16. DISTRIBUTION STATEMENT (of this Report) <b>APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED</b>		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES <b>Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.</b>		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) <b>DAMS, INSPECTION, DAM SAFETY, Thames River Basin Pomfret, Connecticut</b>		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) <b>Beaupre's Pond Dam is an earth embankment dam with an average crest width of 20 feet and irregular but general flat slopes. The maximum height of the dam is 12ft. and its length is 385 feet. The dam is classified as SMALL in size and a HIGH hazard structure. Based on a visual inspection at the site, the dam is considered to be in FAIR condition. The adopted test flood for this structure is equal to 1/2 the PMF.</b>		

BEAUPRE'S POND DAM

CT 00584

THAMES RIVER BASIN  
POMFRET, CONNECTICUT

PHASE 1 INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

DTIC  
SEL  
AUG 23 1984  
A

Approved for	<input checked="" type="checkbox"/>
DTIC	<input type="checkbox"/>
Unavail	<input type="checkbox"/>
Justification	
By	
Distribution	
Availability Codes	
Dist	Avail and/or Special
A-1	



This document has been approved for public release and sale; its distribution is unlimited.

# NATIONAL DAM INSPECTION REPORT

## PHASE 1 INSPECTION REPORT

IDENTIFICATION NO: CT 00627  
NAME OF DAM: Beaupre's Pond Dam  
COUNTY AND STATE: Windham County, Connecticut  
STREAM: Lyon Brook  
DATE OF INSPECTION: 3 December 1980

### Brief Assessment

Beaupre's Pond Dam is an earth embankment dam with an average crest width of 20 feet and irregular but generally flat slopes. The maximum height of the dam is 12 feet and its length is 385 feet. An earth channel emergency overflow spillway is located at the left abutment and has a crest elevation of 695.5 NGVD. This spillway is a trapezoidal channel with a 24 foot bottom width and 4:1 side slopes.

Outlets for the dam consist of a 4' x 4' concrete drop inlet overflow structure which controls the level of the pond at elevation 695.0 NGVD and a 6 inch diameter cast iron low level outlet located at the bottom of the overflow structure. The outlet is a 2' x 2' concrete box culvert which carries flow to the toe of the dam. The dam has an impoundment capacity of 66 acre-feet at the top of dam elevation of 697.0 and is used for recreation.

The dam is classified as SMALL in size and a HIGH hazard structure in accordance with recommended guidelines established by the Corps of Engineers. Based on the size and hazard classifications, the adopted test flood for this structure is equal to one-half the Probable Maximum Flood (PMF) which is estimated to be 424 CFS, equivalent to 1,060 CSM from the 0.4 square mile drainage basin. This test flood has a routed outflow discharge equal to 390 CFS and would overtop the dam by 0.4 feet. The maximum outlet and spillway capacity is equal to 200 CFS which represents only 50% of the test flood outflow.

Based on a visual inspection at the site, the dam is considered to be in FAIR condition. However, these are several areas of concern which must be investigated and corrected, as required, to assure the long-term performance of this dam. It is recommended that the owner engage the services of a registered engineer experienced in the design of dams to accomplish the following:

1. Perform a detailed hydrologic/hydraulic investigation to assess further the need for and means to increase the project discharge capacity and the ability of the dam to withstand overtopping.
2. Inspect the joint at the downstream end of the original outlet conduit and the joints of the new conduit to insure that these joints are all properly sealed.
3. Supervise the replacement of the material on the downstream face in the area of the outlet with a properly selected, compacted backfill to complete the downstream slope.

These and other recommendations and remedial measures as described in Section 7 should be implemented by the owner within one year after receipt of this Phase 1 Inspection Report.

NEW ENGLAND ENGINEERING, INC.

BY: David A. Sluter  
David A. Sluter, P. E.  
President



This Phase 1 Inspection Report on the dam at Beaupre's Pond has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgement and practice, and are hereby submitted for approval.

---

ARAMAST MAHTESIAN, MEMBER  
Geotechnical Engineering Branch  
Engineering Division

---

CARNEY M. TERZIAN, CHAIRMAN  
Design Branch  
Engineering Division

---

JOE FINEGAN, MEMBER  
Water Control Branch  
Engineering Division

APPROVAL RECOMMENDED:

---

JOE B. FRYAR, Chief,  
Engineering Division

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase 1 Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, DC 20314. The purpose of a Phase 1 Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, sub-surface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase 1 investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with the data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase 1 inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test Flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonable possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition, and the downstream damage potential.

The Phase 1 Investigation does not include an assessment of the need for fences, gates, no-trespassing signs, repairs to existing fences and railings and other items which may be needed to minimize trespass and provide greater security for the facility and safety to the public. An evaluation of the project for compliance with OSHA rules and regulations is also excluded.

## TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
LETTER OF TRANSMITTAL	
BRIEF ASSESSMENT	
REVIEW BOARD PAGE	
PREFACE	i
TABLE OF CONTENTS	ii
OVERVIEW PHOTO	
LOCATION MAP	
<u>REPORT</u>	
1. PROJECT INFORMATION	1-1
1.1 General	1-1
a. Authority	1-1
b. Purpose of Inspection	1-1
1.2 Description of Project	1-1
a. Location	1-1
b. Description of the Dam & Appurtenances	1-2
c. Size Classification	1-2
d. Hazard Classification	1-2
e. Ownership	1-2
f. Operator	1-2
g. Purpose of the Dam	1-2
h. Design and Construction History	1-2
i. Normal Operational Procedures	1-3
1.3 Pertinent Data	1-3
a. Drainage Area	1-3
b. Discharge at Damsite	1-3
c. Elevations	1-4
d. Reservoir Lengths	1-4
e. Storage	1-5
f. Reservoir Surface Area	1-5
g. Dam	1-5
h. Diversion and Regulating Tunnels	1-5
i. Spillway	1-6
j. Regulating Outlets	1-6

<u>Section</u>	<u>Page</u>
2. ENGINEERING DATA	2-1
2.1 Design Data	2-1
2.2 Construction Data	2-1
2.3 Operation Data	2-1
2.4 Evaluation of Data	2-1
a. Availability	2-1
b. Adequacy	2-1
c. Validity	2-1
3. VISUAL INSPECTION	3-1
3.1 Findings	3-1
a. General	3-1
b. Dam	3-1
c. Appurtenant Structures	3-2
d. Reservoir Area	3-2
e. Downstream Channel	3-2
3.2 Evaluation	3-3
4. OPERATIONAL PROCEDURES	4-1
4.1 Operational Procedures	4-1
a. General	4-1
b. Description of any Warning System in Effect	4-1
4.2 Maintenance Procedures	4-1
a. General	4-1
b. Operating Facilities	4-1
4.3 Evaluation	4-1
5. EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES	5-1
5.1 General	5-1
5.2 Design Data	5-1
5.3 Experience Data	5-1
5.4 Test Flood Analysis	5-1
5.5 Dam Failure Analysis	5-2

<u>Section</u>	<u>Page</u>
6. EVALUATION OF STRUCTURAL STABILITY	6-1
6.1 Visual Observations	6-1
6.2 Design & Construction Data	6-1
6.3 Post-Construction Changes	6-1
6.4 Seismic Stability	6-1
7. ASSESSMENT RECOMMENDATION & REMEDIAL MEASURES	7-1
7.1 Dam Assessment	7-1
a. Condition	7-1
b. Adequacy of Information	7-1
c. Urgency	7-1
7.2 Recommendations	7-1
7.3 Remedial Measures	7-2
a. Operation & Maintenance Procedures	7-2
7.4 Alternatives	7-2

APPENDICES

APPENDIX A	INSPECTION CHECKLIST
APPENDIX B	ENGINEERING DATA
APPENDIX C	PHOTOGRAPHS
APPENDIX D	HYDROLOGIC & HYDRAULIC COMPUTATIONS
APPENDIX E	INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS




OVERVIEW PHOTO - Beaupre's Pond Dam

December 12, 1980



LOCATION PLAN



BEAUPRE'S POND DAM

LOCATION PLAN

BEAUPRE'S POND DAM

Scale: 1" = 2.0 miles

PLATE NO. 1

# NATIONAL DAM INSPECTION PROGRAM

## PHASE 1 - INSPECTION PROGRAM

### BEAUPRE'S POND DAM

#### SECTION 1

#### PROJECT INFORMATION

##### 1.1 General

- a. Authority. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army through the Corps of Engineers to initiate a national program of dam inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. New England Engineering, Inc. has been retained by the New England Division to inspect and report on selected dams in the State of Connecticut. Authorization and notice to proceed was issued to New England Engineering, Inc. under a letter from William E. Hodgson, Jr., Colonel, Corps of Engineers. Contract No. DACW33-81-C-0007 has been assigned by the Corps of Engineers for this work.
- b. Purpose of Inspection.
  1. Perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interests.
  2. Encourage and assist the State to initiate quickly effective dam safety programs for non-Federal dams.
  3. To update, verify, and complete the National Inventory of Dams.

##### 1.2 Description of the Project

- a. Location. Beupre's Pond Dam is located in the town of Pomfret, in Windham County, Connecticut on Lyon Brook. Coordinates of the dam are approximately 41 degrees, 51.8' North Latitude, and 72 degrees, 2.6' West Longitude as shown on the Hampton, CT, USGS quadrangle sheet. The dam impounds water from Lyon Brook which drains a 0.4 square mile watershed of rolling, wooded terrain. The axis of the pond is oriented in a North-South direction with the dam at the southern end of the pond.

- b. Description of the Dam and Appurtenances. Beaupre's Pond Dam is an earth embankment with a 20 foot wide crest and irregular but generally flatter than 2:1 slopes. The dam is approximately 385 feet long and the maximum height of the dam is 12 feet. At the left abutment of the dam is an earth channel emergency overflow spillway. The spillway is a trapezoidal channel with a 24 foot bottom width and 4:1 side slopes and a crest elevation of 695.5 NGVD. The outlet for the dam is a 4' x 4' drop inlet overflow structure located about 20 feet upstream from the crest at the end of a wooden dock. The low level outlet consists of a 6 inch diameter cast iron pipe and gate valve located at the bottom of the drop inlet structure. The level of the pond is maintained at the crest elevation of the overflow structure which is 695.0 NGVD. Discharge is through a 2' x 2' concrete box culvert from the base of the overflow structure through the dam. The downstream end of the outlet works has been extended with 30 inch diameter concrete pipe and the transition is covered by earth fill which was placed on the downstream face to flatten the slope and fill a wet area.
- c. Size Classification. Beaupre's Pond Dam has an impoundment capacity at the top of the dam (elevation 697.0) equal to 66 Ac-Ft and a maximum height of 12.0 feet. In accordance with guidelines established by the Corps of Engineers, this dam is classified as a SMALL size structure based on its impoundment capacity. Corps of Engineers guidelines specify that dams with impoundment capacities less than 1,000 Ac-Ft and greater than or equal to 50 Ac-Ft or a height of less than 40 feet and greater than or equal to 25 feet be classified as SMALL in size.
- d. Hazard Classification. Beaupre's Pond Dam is classified a HIGH hazard potential because its failure could result in the loss of more than a few lives and damage to personal property in the camping area below the dam. The dam failure discharge of 2,600 CFS will cause a water depth of 4-5 feet in the campsites at the toe of the dam. There would be little to no prefailure flooding.
- e. Ownership. The dam is presently owned by Mr. & Mrs. Beaupre, Beaupre's Campground, Route 44, Abington, Connecticut 06230. Phone (203) 974-1373.
- f. Operator. Operation is at the direction of the owner.
- g. Purpose of Dam. The dam is used for recreational activity in conjunction with the campground at the site.
- h. Design and Construction History. The dam was reportedly built in the early 1950's. No construction history is available. One previous owner did report having filled

in a portion of the downstream toe area which had been swampy prior to that. He also flattened the downstream slopes by adding an unspecified amount of fill.

- i. Normal Operating Procedure. The reservoir is normally unregulated and all downstream flows result from flow over the uncontrolled overflow and spillway.

### 1.3 Pertinent Data

- a. Drainage Area. The drainage basin is oblong in shape with a length of approximately 1.3 miles, a width of 0.3 miles and a total drainage area of 0.4 square miles (See Appendix D for the basin map). Approximately 20 percent of the basin is natural storage. The topography consists of rolling terrain with elevations ranging from a high of 840 feet to 695 feet at the spillway crest.

- b. Discharge at Damsite. There are no discharge records available for this dam. Calculated discharge data for the dam is listed below.

#### 1. Outlet Works

##### a. Conduit & size

Overflow Structure	4' x 4' drop inlet with a 2' x 2' box culvert discharge overflow elevation = 695.0.
Low level outlet	6" diameter cast iron pipe. Invert = 686.6.

- b. Discharge capacity with pond at overflow crest elevation = 695.0

Overflow structure	0 CFS
Low level outlet	3 CFS

- c. Discharge capacity with pond at top of dam elevation = 697.0

Overflow structure	62 CFS
Low level outlet	3 CFS

- d. Discharge capacity at test flood elevation = 697.4

Overflow structure	62 CFS
Low level outlet	3 CFS

- |    |   |         |
|----|---|---------|
| 2. | Maximum known flood at<br>damsite                           | Unknown |
| 3. | Ungated spillway capa-<br>city at top of dam                | 135 CFS |
| 4. | Ungated spillway capa-<br>city at test flood ele-<br>vation | 200 CFS |
| 5. | Gated spillway capacity<br>at normal pool elevation         | N/A     |
| 6. | Gated spillway capacity<br>at test flood elevation          | N/A     |
| 7. | Total spillway capacity<br>at test flood elevation          | 200 CFS |
| 8. | Total project discharge<br>at top of dam                    | 200 CFS |
| 9. | Total project discharge<br>at test flood elevation          | 400 CFS |

c. Elevations (Datum assumed at 695.0 from USGS Quadrangle sheet for overflow structure crest)

- |     |  |         |
|-----|--|---------|
| 1.  | Streambed at toe of dam                | 685.0   |
| 2.  | Bottom of cutoff                       | Unknown |
| 3.  | Maximum tailwater                      | Unknown |
| 4.  | Normal pool                            | 695.0   |
| 5.  | Full flood control pool                | N/A     |
| 6.  | Overflow structure crest               | 695.0   |
| 7.  | Emergency overflow spill-<br>way crest | 695.5   |
| 8.  | Design surcharge<br>(Original Design)  | Unknown |
| 9.  | Top of dam                             | 697.0   |
| 10. | Test flood                             | 697.4   |

d. Reservoir Lengths (in feet)

- |    |                    |       |
|----|--------------------|-------|
| 1. | Normal pool        | 1,000 |
| 2. | Flood control pool | N/A   |

- |    |     |  |   |
|----|-----|--|---|
|    | 3.  | Spillway crest pool                        | 1,000                                     |
|    | 4.  | Top of dam                                 | 1,000                                     |
|    | 5.  | Test flood pool                            | 1,000                                     |
| e. |     | <u>Storage (acre-feet)</u>                 |   |
|    | 1.  | Normal pool                                | 50  |
|    | 2.  | Flood control pool                         | N/A                                       |
|    | 3.  | Spillway crest pool                        | 54  |
|    | 4.  | Top of dam                                 | 66  |
|    | 5.  | Test flood pool                            | 69  |
| f. |     | <u>Reservoir Surface Area (Acres)</u>      |   |
|    | 1.  | Normal pool                                | 8   |
|    | 2.  | Flood control pool                         | N/A                                       |
|    | 3.  | Spillway crest                             | 8   |
|    | 4.  | Top of dam                                 | 8   |
|    | 5.  | Test flood pool                            | 8   |
| g. |     | <u>Dam</u>                                 |   |
|    | 1.  | Type                                       | Earth embankment                          |
|    | 2.  | Length                                     | 385 feet                                  |
|    | 3.  | Height                                     | 12 feet maximum                           |
|    | 4.  | Top width                                  | 20 feet                                   |
|    | 5.  | Side slopes                                | Irregular, min. = U/S 2h:1v;<br>D/S 3h:1v |
|    | 6.  | Zoning                                     | Unknown                                   |
|    | 7.  | Impervious Core                            | Unknown                                   |
|    | 8.  | Cutoff                                     | Unknown                                   |
|    | 9.  | Grout Curtain                              | Unknown                                   |
|    | 10. | Other                                      | No comment                                |
| h. |     | <u>Diversion and Regulating<br/>Tunnel</u> | N/A                                       |

i. Spillway

- |                    |  |
|--------------------|--|
| 1. Type            | Trapezoidal earth channel.<br>Side slopes = 4:1. |
| 2. Length of weir  | 24 feet  |
| 3. Crest elevation | 695.5 feet                                       |
| 4. Gates           | None   |
| 5. U/S Channels    | Natural bed of reservoir                         |
| 6. D/S Channels    | Overland flow                                    |
| 7. General         | No formal spillway discharge channel.            |

j. Regulating Outlets

Low Level Outlet

- |                      |   |
|----------------------|---|
| 1. Invert            | 686.6 feet  |
| 2. Size              | 6 inch diameter                                   |
| 3. Description       | Cast iron pipe and gate valve                     |
| 4. Control Mechanism | Gate valve  |
| 5. Other             | Common discharge with drop inlet through culvert. |

SECTION 2  
ENGINEERING DATA

2.1 Design

There is no available documentation regarding the design of this facility.

2.2 Construction

No formal records of construction or subsequent repairs are available for this dam.

2.3 Operation

No operational records are maintained. The level of the pond is not generally controlled.

2.4 Evaluation

- a. Availability. There is no information available.
- b. Adequacy. The lack of in-depth engineering data did not allow for a definitive review. Therefore, the adequacy of this dam could not be assessed from the standpoint of reviewing design and construction data, but is based primarily on visual inspection, past performance and sound engineering judgement.
- c. Validity. No data is available.

## SECTION 3

### VISUAL INSPECTION

#### 3.1 Findings

- a. General. The Phase 1 visual inspection of Beaupre's Pond Dam was conducted on December 3, 1980, by representatives of New England Engineering, Inc. and Geotechnical Engineers, Inc. A visual checklist and photographic record of that inspection have been included in Appendix A and C, respectively, of this report. At the time of the inspection, the water level was at the overflow inlet crest height.

Based on the visual inspection, Beaupre's Pond Dam is judged to be in FAIR condition.

- b. Dam. The dam is an earth embankment structure with a 20 foot wide crest and generally flat slopes (Photo C-1).
1. Upstream Face. The upstream face (Photo C-2) of the dam is generally unprotected by riprap and therefore irregular and eroded in places.
  2. Crest. The crest of the dam (Photo C-5) is 18-20 feet wide, grass covered and varies in elevation by + 4 inches. Two dock platforms extend from the crest into the pond and are used for boating and swimming purposes.
  3. Downstream Face. The downstream face is also a grass covered earthen slope (Photos C-3 & C-4). The owner indicated that the dam originally had a steeper downstream slope and that fill (local bank-run gravel) was added on the downstream side to flatten the slope and widen the crest. At the same time, the outlet conduit was lengthened to increase their usable land. At the location where the conduit passes through the dam, the downstream slope is steeper than the rest of the dam (Photo C-3). This area was not filled at the same slope when additional fill was added. This area has since been partially filled with rubble and miscellaneous non-structural fill.

In spite of the rather wide crest, flat slopes, and low height of this dam, seepage through the dam does appear to be reaching the downstream slope to create zones of continual dampness. At three locations swamp grass was observed to be growing as high as half way up the downstream slope (visable as a green area in Photo C-4). No flowing water was observed at such locations.

c. Appurtenances.

1. Outlet Structure. The outlet works for this dam consists of a 4' x 4' concrete drop inlet structure located about 20 feet upstream from the crest of the dam. Normal discharge is over the top and into the drop inlet structure which is about 9 feet deep and then out through a 2' x 2' box culvert which passes through the dam. No trash rack is present on the overflow structure to prevent debris from entering the outlet. Pond drawdown is accomplished via a 6 inch cast iron pipe and gate valve near the bottom of the drop inlet structure (Photo C-7). The structure has no access to operate the gate valve. The control handle is located at the bottom of the structure, seven feet below water level. During inspection, a ladder was used to enter the overflow structure. Clear seepage of 5 to 10 gpm into the outlet structure was observed through construction joints in the concrete near the base of the overflow structure. This structure is in POOR condition.

Clear seepage was observed exiting at a rate of 15-20 gpm from the downstream side of the outlet conduit (Photo C-8). Since this flow appeared to be greater than the seepage into the overflow structure in the pond, some seepage may be entering the conduit along its length. The conduit shown in the photo is the end of several 30 inch diameter lengths of pipe that have been added by the Owner to extend the original rectangular conduit that passes through the dam. It is not known whether the connection between the old and new conduit was sealed. Seepage may be occurring at the joint between the original conduit and the concrete pipe.

2. Emergency Overflow Spillway. A shallow earthen channel has been excavated at the left abutment of the dam to provide overflow capacity during high flows (Photo C-9). Currently, this channel is full of brush and debris and its capacity is reduced as a result. This spillway has no formal discharge channel and flood discharges flow overland to the brook downstream of the dam. No erosion downstream of the spillway was visible.

3.2 Evaluation

- a. Based on the visual inspection, the following features could adversely affect the future performance of the dam and should be investigated or remedied:
  1. The connection between the old and new conduit and any leakage past the old conduit should be observed directly and necessary repairs made. The

joints between the new sections of the conduit within the embankment should be sealed. The miscellaneous fill over the conduit area should be removed and replaced with appropriate compacted fill. The final slope should be the same as the rest of the dam.

2. The overflow spillway channel should be cleared of brush and debris. A downstream discharge channel should be constructed.
3. The drawdown gate valve should be made to be operable from above the overflow structure.
4. Erosion protection of the upstream shoreline is required to ensure that erosion does not progress too far into the crest.
5. The zones where swamp grass is growing should be observed periodically to determine whether seepage is developing.

## SECTION 4

### OPERATIONAL AND MAINTENANCE PROCEDURES

#### 4.1 Operational Procedures

- a. General. Beaupre's Pond is used by the owner as the primary recreational facility of the camp ground at the dam site. Operational control is the responsibility of the owner. The pond level is lowered every 3-4 years in the late fall to remove aquatic vegetation in the pond. Normally, the outlet structures remain closed and the water level is maintained at the crest of the overflow structure.
- b. Warning System. There is no warning system in effect at Beaupre's Pond Dam. There is no formalized emergency action plan for the dam.

#### 4.2 Maintenance Procedures

- a. General. Maintenance performed on the dam consists of mowing grass on the crest and downstream slope lawn areas. The discharge channels and the emergency overflow spillway are not maintained.
- b. Operating Facilities. The low level outlet valve is reported to be operated each year and is in good operating order. The valve handle should be extended to the surface, however, so that it may be operated without entering the overflow structure.

#### 4.3 Evaluation

- a. Maintenance on the embankment is sufficient for its requirements except that an area of non-structural fill material should be removed and the practice of placing such material on the embankment should be discontinued. The emergency overflow spillway should be cleared of brush and maintained periodically.
- b. An emergency action plan should also be developed and implemented that includes procedures to lower the pond level locations of emergency equipment, materials or manpower to reduce or minimize dam failure damage, authorities to be contacted in emergency situations and a program of surveillance during unusual storm events.

## SECTION 5

### EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES

#### 5.1 General

Beaupre's Pond Dam was constructed in the early 1950's to create a pond for recreational purposes. The dam is located on Lyon Brook which is tributary to Mashamoquet Brook and the Quinebaug River in the Thames River Basin. The watershed for the pond is 0.4 square miles with approximately 20% of that area providing natural basin storage.

The main outlet control is a 4' x 4' drop inlet overflow structure. There is also an earth channel overflow spillway to accommodate higher flows. The earth embankment dam is 385 feet in length with a maximum height of 12 feet. The pond has a storage capacity at the overflow crest of 50 Ac-Ft. Each foot of depth above the spillway level can accommodate 8 Ac-Ft of water equivalent to 0.4 inches of runoff from the watershed.

It will take approximately 1 1/2 days to lower the reservoir 1 foot based on a surface area of area of 8 acres and an outflow of 3 CFS through the 6 inch diameter low level outlet.

#### 5.2 Design Data

Little specific data is available for this watershed or structure. In lieu of existing complete design information, U.S.G.S. topographic maps (scale 1" = 2,000 ft.) were utilized to develop hydrologic parameters such as drainage area, reservoir surface areas, basin slopes, and other runoff characteristics. Elevation-storage relationships for the reservoir were approximated. Some of the pertinent hydraulic data was obtained or confirmed by actual field measurements at the time of the visual inspection. Test flood inflows and outflows and dam failure flows were determined in accordance with the Corps of Engineers guidelines.

#### 5.3 Experience Data

No historical data for recorded discharges is available for this dam.

#### 5.4 Test Flood Analysis

Recommended guidelines for the Safety Inspection of Dams by the Corps of Engineers were used for selection of the Test Flood. This dam is classified under those guidelines as a HIGH hazard and SMALL in size. Guidelines indicate that

from one-half the PMF to the full PMF be used as a range of test floods for such a classification. A test flood equal to one-half the PMF was adopted for this analysis because the dam is on the low end of the size classification. The watershed has a total drainage area equal to 0.4 square miles of which approximately 20% is natural storage. This drainage area is wooded, with rolling topography.

A test value was selected from the Corps of Engineers PMF Curve for a flat to rolling watershed and reduced by 20% for storage within the watershed. The test flood inflow was calculated to be 1,060 CSM, equal to 425 CFS and was adopted for this analysis. The routed outflow discharge for the test flood inflow was 390 CFS. The project rating curve and pond storage curve are illustrated in Appendix D. Flood routing was performed assuming a full reservoir at the crest of the overflow structure elevation of 695.0 NGVD.

The analysis indicated that the peak test flood discharge would overtop the dam by approximately 0.4 feet assuming the overflow length of dam to be 250 feet. The peak test flood outflow capacity of the overflow structure and overflow spillway at the top of the dam elevation 697.0 is 200 CFS or 51% of the test flood.

#### 5.5 Dam Failure Analysis

For this analysis a full-depth, partial-width (45.0 feet) breach was assumed to have occurred in this dam. The adopted breach width of 45.0 feet was based on visual inspection of the physical features of the dam. The calculated dam failure discharge of 2,600 CFS assumes the reservoir is full (at top of dam elevation 697.0 feet) just prior to failure, and will produce an approximate water depth of 4.5 feet immediately downstream from the dam and a water depth of 1.4 feet through the first reach. There would be little to no prefailure flooding of this area. The first reach below the dam is a camping area with many campers present during the summer season. There are 15-20 camping spaces located immediately downstream of the dam. This area serves as a storage area for recreational vehicles during the winter season. Dam failure flood stages of 4-5 feet through this reach could possibly cause the loss of more than a few lives and would damage numerous recreational vehicles. Areas below this first reach are heavily wooded and uninhabited with no dam failure impact. The prime impact areas has been estimated, if the dam were to fail, and has been delineated on the Dam Failure Impact Area Map in Appendix D. As a result of the failure analysis, the dam has been classified as a HIGH hazard structure.

## SECTION 6

### EVALUATION OF STRUCTURAL STABILITY

#### 6.1 Visual Observations

Visual examination of the geotechnical and structural aspects of the dam do not indicate any immediate stability problems. However, the following features could affect the long-term stability of the dam.

- a. Based on visual observations made during this inspection, the most critical zone of the dam is at the downstream side where the conduit passes through the dam. The remainder of the dam has flat slopes and a wide crest, but at the location of the conduit the downstream slope is steeper and the condition of the conduit that passes through the dam cannot be observed directly since it has been covered by fill.

Direct observation of the downstream end of the original conduit should be made to determine whether any seepage is occurring around the outside. Also, the conduit was extended recently by the Owner, and the connection between the old and new conduit may not be sealed. The sections of concrete pipe used for the extension of the conduit also may not be sealed at the joints. These observations should be made and necessary repairs carried out. Then the downstream slope of the dam in the vicinity of the outlet conduit should be cleaned of miscellaneous fill and completed by placement of a properly selected and compacted fill. Erosion protection should be provided in the emergency spillway to withstand the velocity of flood overflows.

#### 6.2 Design and Construction Data

No design or construction drawings or records for the dam are available.

#### 6.3 Post-Construction Changes

There are no post-construction changes made that would adversely affect the stability of this dam, except that the downstream end of the original conduit cannot be observed directly, as described in Section 6.1.

#### 6.4 Seismic Stability

The dam is located in Seismic Zone 1 and, in accordance with recommended Phase 1 guidelines, does not warrant seismic stability analysis.

## SECTION 7

### ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

#### 7.1 Dam Assessment

- a. Condition. Based on the visual inspection, this dam appears to be in FAIR condition. Features which could adversely affect the condition of the dam in the future are:
  1. Seepage through the dam in the area of the outlet conduit.
- b. Adequacy of Information. This Phase 1 inspection was based on the visual inspection and on certain verbal information provided by the present owner regarding the placement of fill on the downstream side and the extension of the conduit.
- c. Urgency. The recommendations and remedial measures described below should be implemented by the owner within one year after receipt of the Phase 1 report.

#### 7.2 Recommendations

The following items should be carried out under the direction of a qualified registered engineer and recommendations resulting should be implemented by the owner.

- a. Perform a detailed hydrologic-hydraulic investigation to assess further the need for and the means to increase project discharge capacity and the ability of the dam to withstand overtopping.
- b. Inspect the downstream end of the original conduit that passes through the dam to determine whether any significant seepage is occurring along the outside of the conduit. Inspect the joint between the old and new conduit and between sections of the new conduit. Make necessary recommendations to prevent piping of fines at these locations.
- c. Select a proper fill to complete the downstream face over the conduit. Make recommendations for removal of existing miscellaneous fill, placement procedures for the new fill, and erosion protection of the new slope.
- d. Construct a formal spillway discharge channel to carry overflow to the brook downstream.
- e. Repair the drop inlet overflow structure to stop the seepage through the walls.

### 7.3 Remedial Measures

#### a. Operation and Maintenance Procedures

1. Modify or extend the operating handle to the draw-down gate valve so that it may be operated from above without entering the drop inlet pit.
2. Inspect the downstream slope annually, particularly in the zones where the swamp grass is growing, to ensure that no flowing seepage through the dam is observed.
3. Clear the brush and debris from the emergency overflow spillway.
4. Implement and intensify a program of diligent and periodic maintenance.
5. Establish a protective cover over all bare or disturbed areas.
6. Develop an "Emergency Action Plan" that will include an effective preplanned downstream warning system, locations of emergency equipment, materials and manpower, authorities to contact and potential areas that require evacuation.
7. Provide surveillance during and immediately after high intensity rainfall.
8. Construct a debris collecting structure along the crest of the overflow structure to prevent the outlet from becoming plugged with debris.

#### 7.4 Alternatives

There are no practical alternatives to the recommendations and remedial measures discussed above.

APPENDIX A  
INSPECTION CHECKLIST

VISUAL INSPECTION CHECKLIST  
PARTY ORGANIZATION

PROJECT NO NAME #42 - CT 584

Beaupres Pond Dam  
Pomfret, CT

DATE Dec. 3, 1980

TIME 0800

WEATHER Overcast, 40 degrees

W.S. ELEV. 695.0 U.S. 686.2 DN.S.  
NGVD

PARTY:

1. David Sluter - New England Engineering 6.
2. Stephen Fodor - New England Engineering 7.
3. Steve Poulos - GEI 8. \_\_\_\_\_
4. \_\_\_\_\_ 9. \_\_\_\_\_
5. \_\_\_\_\_ 10. \_\_\_\_\_

PROJECT FEATURE	INSPECTED BY	REMARKS
1. <u>Hydrology &amp; Hydraulics</u>	<u>D. Sluter</u>	
2. <u>Civil</u>	<u>S. Fodor</u>	
3. <u>Geotechnical</u>	<u>S. Poulos</u>	
4. _____		
5. _____		
6. _____		
7. _____		
8. _____		
9. _____		
10. _____		

PERIODIC INSPECTION CHECKLIST


PROJECT NO NAME #42 - BEAUPRE'S POND DAM DATE Dec. 3, 1980  
 PROJECT FEATURE Dam Embankment NAME Sluter/Fodor  
 DISCIPLINE Geotechnical/Civil NAME Poulos

AREA EVALUATED	CONDITION
<u>DAM EMBANKMENT</u>	Station 0+00 is at right end of dam.
Crest Elevation	695.0 NGVD
Current Pool Elevation	695.0
Maximum Impoundment to Date	Unknown.
Surface Cracks	None observed.
Pavement Condition	Grassed.
Movement or Settlement of Crest	Irregular, <u>± 4"</u> .
Lateral Movement	None observable
Vertical Alignment	No misalignment observable.
Horizontal Alignment	Not observable. Arched downstream.
Condition at Abutment and at Concrete Structures	Right: satisfactory. Left: runs into emergency spillway. Satisfactory.
Indications of Movement of Structural Items on Slopes	No structures
Trespassing on Slopes	Free access. Used as beach. Bulldozers run on it to clear beach.
Sloughing or Erosion of Slopes or Abutments	Station 1+25 to 1+75 on D/S slope: Misc. trash and steeper slope where conduit outlet formerly terminated. Upstream erosion due to beach activity. Bare spots at several locations.
Rock Slope Protection - Riprap Failures	No riprap along most of beach.
Unusual Movement or Cracking at or Near Toe	None observed.
Unusual Embankment or Downstream Seepage	Station 2+30 D/S along 15' length at downstream toe, grass is swampgrass. Same at Station 2+05 and 1+05 up to half way up slope in all cases. No seepage observed. See checklist for outlet conduit.
Piping or Boils	None observed.
Foundation Drainage Features	None
Toe Drains	None
Instrumentation System	None
Vegetation	Grassed.

PERIODIC INSPECTION CHECKLIST

PROJECT NO NAME #42 - BEAUPRE'S POND DAM DATE Dec. 3, 1980  
 PROJECT FEATURE Dike Embankment NAME Sluter/Fodor  
 DISCIPLINE Geotechnical/Civil NAME Poulos

AREA EVALUATED	CONDITION
<p><u>DIKE EMBANKMENT</u></p> <ul style="list-style-type: none"> <li>Crest Elevation</li> <li>Current Pool Elevation</li> <li>Maximum Impoundment to Date</li> <li>Surface Cracks</li> <li>Pavement Condition</li> <li>Movement or Settlement of Crest</li> <li>Lateral Movement</li> <li>Vertical Alignment</li> <li>Horizontal Alignment</li> <li>Condition at Abutment and at Concrete Structures</li> <li>Indications of Movement of Structural Items on Slopes</li> <li>Trespassing on Slopes</li> <li>Sloughing or Erosion of Slopes or Abutments</li> <li>Rock Slope Protection - Riprap Failures</li> <li>Unusual Movement or Cracking at or Near Toes</li> <li>Unusual Embankment or Downstream Seepage</li> <li>Piping or Boils</li> <li>Foundation Drainage Features</li> <li>Toe Drains</li> <li>Instrumentation System</li> <li>Vegetation</li> </ul>	<p>No dike present.</p>



PERIODIC INSPECTION CHECKLIST

PROJECT NO NAME #42 - BEAUPRE'S POND DAM DATE Dec. 3, 1980  
 PROJECT FEATURE Intake Structure NAME Sluter/Fodor  
 DISCIPLINE Hydraulic/Civil/Geotechnical NAME Poulos

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE</u></p> <p>a. Approach Channel</p> <p>Slope Conditions</p> <p>Bottom Conditions</p> <p>Rock Slides or Falls</p> <p>Log Boom</p> <p>Debris</p> <p>Condition of Concrete Lining</p> <p>Drains or Weep Holes</p> <p>b. Intake Structure</p> <p>Condition of Concrete</p> <p>Stop Logs and Slots</p>	<p>N/A</p> <p>Under water.</p> <p>None.</p> <p>None.</p> <p>N/A.</p> <p>N/A.</p> <p>N/A.</p> <p>4' x 4' concrete drop inlet</p> <p>Construction joint 2' above floor is 1' deep, 1" wide. Seepage at upstream right is 3-5 gpm. Seepage at upstream left is 2-4 gpm.</p> <p>No stop logs or slots.</p>

**PERIODIC INSPECTION CHECKLIST**

PROJECT NO NAME #42 - BEAUPRE'S POND DAM      DATE Dec. 3, 1980  
 PROJECT FEATURE Control Tower      NAME Sluter/Fodor  
 DISCIPLINE Civil/Geotechnical      NAME Poulos

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - CONTROL TOWER</u></p> <p>a. Concrete and Structural</p> <ul style="list-style-type: none"> <li>General Condition</li> <li>Condition of Joints</li> <li>Spalling</li> <li>Visible Reinforcing</li> <li>Rusting or Staining of Concrete</li> <li>Any Seepage or Efflorescence</li> <li>Joint Alignment</li> <li>Unusual Seepage or Leaks in Gate Chamber</li> <li>Cracks</li> <li>Rusting or Corrosion of Steel</li> </ul> <p>b. Mechanical and Electrical</p> <ul style="list-style-type: none"> <li>Air Vents</li> <li>Float Wells</li> <li>Crane Hoist</li> <li>Elevator</li> <li>Hydraulic System</li> <li>Service Gates</li> <li>Emergency Gates</li> <li>Lightning Protection System</li> <li>Emergency Power System</li> <li>Wiring and Lighting System</li> </ul>	<p>None.</p>

5

PERIODIC INSPECTION CHECKLIST

PROJECT NO NAME #42 - BEAUPRE'S POND DAM DATE Dec. 3, 1980  
 PROJECT FEATURE Outlet Conduit NAME Sluter/Fodor  
 DISCIPLINE Civil/Geotechnical NAME Poulos

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - TRANSITION AND CONDUIT</u></p> <p>General Condition of Concrete</p> <p>Rust or Staining on Concrete</p> <p>Spalling</p> <p>Erosion or Cavitation</p> <p>Cracking</p> <p>Alignment of Monoliths</p> <p>Alignment of Joints</p> <p>Numbering of Monoliths</p>	<p>2' x 2' box culvert.</p> <p>Fair to poor</p> <p>Staining and efflorescence on upstream end. Entire inside perimeter is wet but no flowing water observed.</p> <p>Seems to be more water exiting from downstream end of culvert than coming in through intake structure.</p> <p>Not observable.</p> <p>None observed.</p> <p>Not observable.</p> <p>Not observable.</p> <p>Not observable.</p>

6

PERIODIC INSPECTION CHECKLIST

PROJECT NO NAME #42 - BEAUPRE'S POND DAM DATE Dec. 3, 1980

PROJECT FEATURE Outlet Works NAME Sluter/Fodor

DISCIPLINE Civil/Geotechnical NAME Poulos

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL</u></p> <p>General Condition of Concrete</p> <p>Rust or Staining</p> <p>Spalling</p> <p>Erosion or Cavitation</p> <p>Visible Reinforcing</p> <p>Any Seepage or Efflorescence</p> <p>Condition at Joints</p> <p>Drain holes</p> <p>Channel</p> <p>Loose Rock or Trees Overhanging Channel</p> <p>Condition of Discharge Channel</p>	<p>Outlet of 2' x 2' box culvert has been extended with 30" diameter concrete pipe. Could not inspect that transition as it has been buried.</p> <p>Small trees to 6" in size overhanging. Vegetation: cattails in channel.</p> <p>Fair to poor.</p>

PERIODIC INSPECTION CHECKLIST

PROJECT NO NAME #42 - BEAUPRE'S POND DAM      DATE Dec. 3, 1980  
 PROJECT FEATURE Overflow Spillway      NAME Sluter/Fodor  
 DISCIPLINE Hydraulic/Civil/Geotechnical      NAME Poulos

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u></p> <p>a. Approach Channel</p> <p>    General Condition</p> <p>    Loose Rock Overhanging Channel</p> <p>    Trees Overhanging Channel</p> <p>    Floor of Approach Channel</p> <p>b. Weir and Training Walls</p> <p>    General Condition of Concrete</p> <p>    Rust or Staining</p> <p>    Spalling</p> <p>    Any Visible Reinforcing</p> <p>    Any Seepage or Efflorescence</p> <p>    Drain Holes</p> <p>c. Discharge Channel</p> <p>    General Condition</p> <p>    Loose Rock Overhanging Channel</p> <p>    Trees Overhanging Channel</p> <p>    Floor of Channel</p> <p>    Other Obstructions</p> <p>    Other Comments</p>	<p>Poor.</p> <p>None.</p> <p>Trees on left side of approach to 6" size.</p> <p>Large boulders, heavy vegetation, brush, debris, logs.</p> <p>The spillway is an earth cut. The weir is full of vegetation debris and logs.</p> <p>Obstructed by road of bank run gravel over a culvert which is a concrete pipe 2' dia.</p> <p>None.</p> <p>Fully forested on downstream side of above culvert. Sand has been washed in at downstream end of culvert.</p> <p>Trees and boulders downstream of culvert discharge, which is about 100' downstream from dam centerline.</p> <p>Culvert would not limit high flows through emergency spillway. Flow would wash over the road.</p>

APPENDIX B  
ENGINEERING DATA

0+00

1+00


2+00

3+00


4+00



# BEAUPRES POND



**BEAUPRES POND DAM**  
**GENERAL PLAN**  
 NO SCALE



STATE BOARD FOR THE SUPERVISION OF DAMS  
INVENTORY DATA

59  
CT584

Name of Dam or Pond 10 Beaupres Dam 11142

Code No. Q 32.1 MS 7.3 4718 U0.3

Location of Structure

LAT. 41° 51.8'

Town Poufret

LONG. 72° 02.6'

Name of Stream Lynn

U.S.G.S. Quad. Hampton

Owner Beaupres Dam

Address Poufret Route 414

Pond Used For Recreation DA 0.35 sm

Dimensions of Pond: Width \_\_\_\_\_ Length \_\_\_\_\_ Area 5 A

Total Length of Dam 225' Length of Spillway 30'

Depth of Water Below Spillway Level (Downstream) 12' in sect

Height of Abutments Above Spillway 2'

Type of Spillway Construction overland at foot of dam + drop inlet

Type of Dike Construction Fill

Downstream Conditions Woods

Summary of File Data \_\_\_\_\_

Remarks drop inlet 2' in a hole in

emergency 14m off goes one time 3-26-74

1955

APPENDIX C  
PHOTOGRAPHS

0+00

1+00


2+00

3+00

4+00



# BEAUFRES POND



BEAUFRES POND DAM  
 PHOTO INDEX  
 NO SCALE






PHOTO C-1: Crest and upstream face from left side. Brushy area in foreground is the emergency overflow spillway.



PHOTO C-2: Upstream face from right side.




PHOTO C-5: Close up of crest and upstream face. Note erosion and lack of riprap.




PHOTO C-6: Drop inlet for outlet works at end of dock.



PHOTO C-7: Inside the drop inlet structure - 2' x 2' box culvert outlet. 6" gate valve to draw down pond is under the ladder.



PHOTO C-8: 30" diameter extension of the outlet conduit with seepage on left side.




PHOTO C-9: Emergency overflow spillway.




PHOTO C-10: Discharge channel looking downstream.

APPENDIX D  
HYDROLOGIC & HYDRAULIC COMPUTATIONS

LIMIT OF DRAINAGE AREA

BEAUPRE'S POND DAM

LIMIT OF IMPACT AREA

**BEAUPRE'S POND DAM  
DRAINAGE BASIN &  
DAM FAILURE IMPACT AREA**

Datum: NGVD  
USGS Quadrangle Sheets  
Hampton, CT; Eastford, CT  
Scale: 1:24,000

PLATE NO. D-1

Job No. 80103 Sheet 1 of 3  
 Project DAM INSPECTION - NO NAME #42 Date 2/25/91  
 Subject HYDROLOGY & HYDRAULICS By SMF Ch'k. by

NO NAME # 42

BASIC DATA

DRAINAGE AREA = 0.40 SQ. MILES  
 NORMAL POOL ELEV. = 695.0  
 MAX POOL ELEV. = 697.0

RESERVOIR:

@ NORMAL POOL (695.0) AREA = 8 AC. STOR = 50 AC-FT  
 @ MAX POOL (697.0) AREA = 8.5 AC STOR = 66 AC-FT  
 @ TEST FLOOD POOL (697.4) AREA = 8.7 AC STOR = 69 AC-FT

DAM: EARTH FILL  
 MAX. HEIGHT = 12 FT.  
 LENGTH = 380 FT.

SPILLWAY: EARTH OVERFLOW CHANNEL AT  
 END OF DAM ELEV = 695.5



OUTLETS

MAIN OUTLET STRUCTURE: 4'x4' DROP INLET  
 ELEV = 695.0' (APPROXIMATED LATUM)  
 = CONTROL ELEVATION FOR POOL


DROP INLET STRUCTURE OUTLETS THRU  
 2'x2' BOX CULVERT @ INV. EL. = 686.0 FT

LOW DOWN OUTLET: 6" CE. PIPE AND GATE  
 VALVE TO INSIDE OF D.I. STRUCTURE @  
 INV. EL. = 686.6 FT

Job No. 20102 Sheet 2 of 3  
 Project DAM INSPECT. 200 - 100 NAME # - 2 Date 2/26/81  
 Subject \_\_\_\_\_ By CAF Ch'k. by \_\_\_\_\_



(EARTH CHANNEL)





Job No. 80102 Sheet 4 of 8  
 Project DAM INSPECTION - NO NAME 42 Date 2/25/81  
 Subject HYDROLOGY - HYDRAULICS By SMF Ch'k. by \_\_\_\_\_

OVERFLOW CHANNEL CAPACITY

USE  $Q = C L H^{3/2}$   $C = 2.4$   
 $L$  VARIES  
 $H = 0.2' \quad .5 \quad 1.0 \quad 1.5 \quad 2.0 \quad 1.7$   
 $L = 24' \quad 26 \quad 28 \quad 30 \quad 32 \quad 32$   
 $Q = 5 \text{ cfs} \quad 22 \quad 67 \quad 132 \quad 217 \quad 201$

EMBANKMENT


USE  $Q = C L H^{3/2}$   $C = 2.4$   $L = 250'$

$L = 250'$  CHOSEN AS TOP OF DAM IS IRREGULAR

TOTAL PROJECT DISCHARGE

WS EL	Height	Q <sub>OUT</sub>	Height	Q <sub>OVER</sub>	H <sub>DAM</sub>	Q <sub>DAM</sub>	Q <sub>TOTAL</sub>
695.0	-	-	-	-	-	-	0 CFS.
695.2	0.2'	4	-	-	-	-	4
695.4	0.4	11	-	-	-	-	11
695.5	0.5	15	-	-	-	-	15
695.7	0.7	25	0.2	5	-	-	30
696.0	1.0	43	0.5	22	-	-	65
696.5	1.5	59	1.0	67	-	-	126
697.0	2.0	65	1.5	135	-	-	200
697.2	10.2	65	1.7	170	0.2	55	290
697.5	10.5	65	2.0	220	0.5	215	500


STORAGE CURVE




NO. N/A M/V # 112 (U) (M)  
DISCHARGE RATING CURVE

EV = 677.4

TEST POINTS  
↓



DISCHARGE (CF)



Job No. 80103

Project DAM INSPECTION - 100 NAME #42

Subject

Sheet 6 of 5

Date 2/26/81

By SME Ch'k. by

CALCULATE EFFECT OF SURCHARGE STORAGE

$$\text{PEAK INFLOW} = 425 \text{ CFS} \quad \text{SURCHARGE} = 2.4'$$

$$\text{SURCHARGE VOLUME} = 67.50 = 19 \text{ AC-FT}$$

$$\text{STOR}_1 = \frac{19 \text{ AC-FT} \times 12 \text{ IN/FT}}{0.4 \text{ SQ.MI.} \times 640 \text{ AC/SQ.MI.}} = 0.9 \text{ IN}$$

$$Q_{P_2} = 425 \left(1 - \frac{0.9}{9.5}\right) = 384 \text{ CFS}$$

$$\text{SURCHARGE @ } 384 \text{ CFS} = 2.35' \quad U = 18.6$$

$$\text{STOR}_2 = \frac{18.6 \text{ AC-FT} \times 12}{0.4 \times 640} = 0.9 \text{ IN}$$

$$\text{STOR}_1 = \text{STOR}_2 - \text{STOR}_{RIG} = 0$$

$$\therefore Q_{P_3} = Q_{P_2} = 400 \text{ CFS.}$$

1. STORAGE WILL REDUCE THE TEST FLOOD BY 25 CFS OR 6%
2. THE OUTLET STRUCTURE AND OVERFLOW CHANNEL CAN HANDLE 193 CFS OR 20% OF THE TEST FLOOD DISCHARGE
3. AT THE TEST FLOOD DISCHARGE OF 383 CFS THE DAM WILL BE OVERTOPPED BY 0.35 FT.

Job No. 82103Project DAM INSPECTION - NO NAME # 42Subject DAM FAILURE ANALYSISSheet 7 of 8Date 2/24/81By SM Ch'k. by     DAM FAILURE ANALYSIS

DAM FAILURE DISCHARGE CALCULATED  
ACCORDING TO CORPS OF ENGINEERS  
GUIDELINES

$$Q_{\text{FAIL}} = 8/27 W_b \sqrt{g} Y_0^{3/2}$$

$$W_b = \text{BREACH WIDTH} = 45 \text{ FT (ASSUMED)}$$

$$Y_0 = \text{TOTAL HEIGHT} = 10 \text{ FT}$$

$$\begin{aligned} Q_{\text{FAIL}} &= 8/27 (45) \sqrt{32.2} (10^{3/2}) \\ &= 2393 \text{ CFS} \end{aligned}$$

$$\begin{aligned} \text{TOTAL FLOW} &= Q_F \quad 2393 \\ &\quad Q_{\text{RR}} + \underline{193} \\ Q_T &= 2586 \text{ CFS} \end{aligned}$$

DOWNSTREAM IMPACT

1ST REACH 800 FT LONG AVG 300 FT WIDE  
SLOPE =  $40'/300' = .057$   $n = 0.05$

TREAT AS WIDE CHANNEL  $R = Y$

$$\begin{aligned} Q &= \frac{1.49}{n} B Y^{2/3} S^{1/2} \\ Y &= \left( \frac{Q}{R} \left( \frac{n}{1.49} \right) \frac{1}{S^{1/2}} \right)^{3/2} \\ &= \left( \frac{2586}{300} \left( \frac{.05}{1.49} \right) \frac{1}{.057^{1/2}} \right)^{3/2} \\ &= (8.6 \times .034 \times 4.19)^{3/2} \\ &= 1.4 \text{ FEET} \end{aligned}$$

$$\text{MAX FLOW DEPTH} = 4/7 Y_0 = 4.5 \text{ FT}$$

Job No. 80103 Sheet 8 of 8  
Project DAM INSPECTION - NO NAME 42 Date 2/27/81  
Subject DAM FAILURE ANALYSIS By SMF Ch'k. by

### IMPACT SUMMARY

A DAM FAILURE AND SUBSEQUENT DISCHARGE OF 2400 CFS ± WOULD CAUSE FLOODING OF 4.5 TO 1.4 FEET THROUGH THE CAMPING AREA JUST BELOW THE DAM. THIS COULD CAUSE THE LOSS OF LESS THAN A FEW LIVES AND WOULD DAMAGE THE NUMEROUS CAMPING TRAILERS, ETC, IN THIS AREA. DURING THE WINTER SEASON THERE ARE NO DOWNSTREAM INHABITANTS BUT 10 TO 12 TRAVEL TRAILERS STAY STOKED IN THE HAZARD AREA.

BEYOND THE CAMPING AREA, DOWNSTREAM REACHES ARE UNINHABITATED WOODLANDS AND NO HAZARD EXISTS.

APPENDIX E

INFORMATION AS CONTAINED IN THE NATIONAL  
INVENTORY OF DAMS

**END**

**FILMED**

**10-84**

**DTIC**