


MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

AD-A145 347


THAMES RIVER BASIN
DUDLEY, MASSACHUSETTS



NEW POND DAM
MA 00113

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

DTIC FILE COPY



DTIC
ELECTE
S SEP 6 1984
D

DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASS. 02154

MARCH 1979

DISTRIBUTION STATEMENT
Approved for public release
Distribution Unlimited

84 09 05 108



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:

NEDED

MAY 29 1979

Honorable Edward J. King
Governor of the Commonwealth of
Massachusetts
State House
Boston, Massachusetts 02133

Dear Governor King:


I am forwarding to you a copy of the New Pond Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts. In addition, a copy of the report has also been furnished the owner, Stevens Linen Associates, Inc., Box 220, Webster, Massachusetts 01570, ATTN: Mr. Robert Javery, Plant Engineer.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Quality Engineering for your cooperation in carrying out this program.

Sincerely yours,


JOHN P. CHANDLER
Colonel, Corps of Engineers
Division Engineer

Incl
As stated

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A/1	

NEW POND DAM
MA 00113

00113
00113
00113

THAMES RIVER BASIN
DUDLEY, MASSACHUSETTS

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

Identification No.: MA 00113
Name of Dam: NEW POND DAM
Town: DUDLEY
County and State: WORCESTER COUNTY, MA
Stream: TRIBUTARY OF FRENCH RIVER
Date of Inspection: 14 SEPTEMBER and 20 SEPTEMBER 1978

BRIEF ASSESSMENT

New Pond Dam consists of two earthen embankments, one to the north and one to the south of the access road to the dam. The southerly embankment, considered the main dam, contains a masonry spillway and an abandoned outlet works. The northerly embankment is considered a separate dike. Each of the embankments is approximately 400 feet long. The dam has a height of approximately 20 feet, while the dike has a height of approximately 12 feet.

The structures are in fair condition. The embankments are heavily overgrown with trees and bush. Seepage or evidence of seepage was observed at both embankments. The outlet structure, which serves as the reservoir drain, is inoperative. The spillway has a limited capacity.

Based on the hazard potential downstream of the dam and in accordance with Corps of Engineers Guidelines, this dam is classified as having a low hazard potential. A 100 year flood was selected as the spillway test flood in accordance with Corps of Engineers Guidelines for "small" dams of "low" hazard. Hydraulic analysis indicates the test flood outflow at the dam would be approximately 580 cfs. The spillway can only pass approximately 17 percent of the test flood before overtopping of the embankments would occur. At test flood peak discharge, the average height of water overtopping the dam and dike would be approximately four inches.


It is recommended that detailed investigations be made to determine required modifications to increase spillway capacity, to determine the effect of seepage at the dam, to determine the geometry of the embankments and, if necessary, the character of embankment materials to check the stability of the dam, and to determine the measures required to make the reservoir drain operational. Remedial measures recommended are the cleaning of trees and brush from the embankments, the filling of eroded areas, the replenishment of riprap at embankment upstream face, the replacement of fallen stones from masonry walls, the reshaping of the embankments to provide uniform freeboard and permit vehicle access, and the removal of debris from both spillway and outlet works channels. It is recommended that the investigations

and remedial measures be accomplished within one year of receipt of the report by the Owner. In addition, it is recommended that the Owner establish formal operational procedures, maintenance program, emergency procedures plan and warning system and program of annual technical inspections.


CAMP DRESSER AND MCKEE INC.


Roger H. Wood


Roger H. Wood
Vice-President




This Phase I Inspection Report on New Pond Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.


JOSEPH W. FINEGAN, JR., MEMBER
Water Control Branch
Engineering Division


CARNEY M. TERZIAN, MEMBER
Design Branch
Engineering Division


JOSEPH A. MCELROY, CHAIRMAN
Chief, NED Materials Testing Lab.
Foundations & Materials Branch
Engineering Division

APPROVAL RECOMMENDED:


JOE B. FRYAR
Chief, Engineering Division

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I Investigations are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the test flood is based on the estimated "probable maximum flood" for the region (greatest reasonably possible storm runoff), or a fraction thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
Letter of Transmittal	
Brief Assessment	
Review Board Page	
Preface	i
Table of Contents	ii & iii
Overview Photo	iv
Location Map	v

REPORT

1. PROJECT INFORMATION	
1.1 General	
a. Authority	1-1
b. Purpose of Inspection	1-1
1.2 Description of Project	
a. Location	1-1
b. Description of Dam and Appurtenances	1-2
c. Size Classification	1-2
d. Hazard Classification	1-2
e. Ownership	1-2
f. Operator	1-3
g. Purpose of Dam	1-3
h. Design and Construction History	1-3
i. Normal Operational Procedures	1-3
1.3 Pertinent Data	1-3
2. ENGINEERING DATA	
2.1 Design	2-1
2.2 Construction	2-1
2.3 Operation	2-1
2.4 Evaluation	2-1
3. VISUAL INSPECTION	
3.1 Findings	
a. General	3-1
b. Dam	3-1
c. Appurtenant Structures	3-2
d. Reservoir Area	3-2
e. Downstream Channel	3-3
3.2 Evaluation	3-3
4. OPERATIONAL PROCEDURES	
4.1 Procedures	4-1
4.2 Maintenance of Dam	4-1
4.3 Maintenance of Operating Facilities	4-1
4.4 Description of any Warning System in Effect	4-1
4.5 Evaluation	4-1

TABLE OF CONTENTS (Cont'd)

	<u>Page</u>
5. HYDRAULIC/HYDROLOGIC	
5.1 Evaluation of Features	5-1
a. General	5-1
b. Design Data	5-1
c. Experience Data	5-1
d. Visual Observations	5-1
e. Test Flood Analysis	5-2
f. Dam Failure Analysis	5-2
6. STRUCTURAL STABILITY	
6.1 Evaluation of Structural Stability	6-1
a. Visual Observation	6-1
b. Design and Construction Data	6-1
c. Operating Records	6-1
d. Post-Construction Changes	6-1
e. Seismic Stability	6-1
7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	
7.1 Dam Assessment	7-1
a. Condition	7-1
b. Adequacy of Information	7-1
c. Urgency	7-1
d. Need for Additional Investigation	7-1
7.2 Recommendations	7-1
7.3 Remedial Measures	7-2
a. Operation and Maintenance Procedures	7-2
7.4 Alternatives	7-2

APPENDIXES

APPENDIX A - INSPECTION CHECKLIST	A-1
APPENDIX B - ENGINEERING DATA	B-1
APPENDIX C - PHOTOGRAPHS	C-1
APPENDIX D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS	D-1
APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS	E-1

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER MA 00113	2. GOVT ACCESSION NO. A145 347	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) New Pond Dam NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS		8. CONTRACT OR GRANT NUMBER(s)
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE March 1979
		13. NUMBER OF PAGES 75
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Thames River Basin Dudley, Massachusetts		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) New Pond Dam consists of two earthen embankments, one to the north and one to the south of the access road to the dam. Each of the embankments is approximately 400 feet long. The dam has a height of approximately 20 feet, while the dike has a height of approximately 12 feet. The structures are in fair condition. Based on hazard potential, this dam is classified as having a low hazard potential. A 100 year flood was selected as the spillway test flood. The dam is classified as a "small" dam.		



1. OVERVIEW OF DAM FROM RIGHT ABUTMENT (MARCH 1979).

NATIONAL DAM INSPECTION PROGRAM
PHASE I INSPECTION REPORT
NEW POND DAM
MA 00113

SECTION 1: PROJECT INFORMATION

1.1 General

- a. Authority - Public Law 92-367, 8 August 1972, authorized the the Secretary of the Army, through the Corps of Engineers, to initiate a national program of dam inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region.

Camp Dresser & McKee Inc. has been retained by the New England Division to inspect and report on selected dams in the State of Massachusetts. Authorization and notice to proceed was issued to Camp Dresser & McKee Inc. under a letter of 12 July 1978, from Colonel John P. Chandler, Corps of Engineers. Contract No. DACW 33-78-C-0354 has been assigned by the Corps of Engineers for this work. Haley and Aldrich, Inc. has been retained by Camp Dresser & McKee Inc. for the soils and geological portions of the work.

- b. Purpose - The primary purpose of the investigation is to:
- (1) Perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interests.
 - (2) Encourage and assist the States to initiate quickly effective dam safety programs for non-Federal dams.
 - (3) Update, verify and complete the National Inventory of Dams.

1.2 Description of Project

- a. Location - New Pond Dam is located on a tributary of the French River, approximately 1,400 feet west of Pierpoint Road in the town of Dudley, Massachusetts, as shown on the report's location map. The dam is located on the east side of New Pond, approximately 900 feet south of the north end of the pond. Waters impounded by the dam are called New Pond and Hayden Pond, a causeway dividing the two. Flow from New Pond passes through a pond known locally as Mosquito Pond and then into Wallis Pond.

- b. Description of Dam and Appurtenances - New Pond Dam consists of two irregularly aligned earth embankments, each a little over 400 ft long. The main dam has roughly an east-west orientation; the right half of the dam has a dry-stone masonry downstream face, a concrete overflow spillway and an abandoned stone masonry gated outlet. The dike embankment extends to the north from the left end of the dam. A sketch plan and sections prepared from Phase I inspection records are shown in Appendix C.

The main dam has a maximum height of about 20 ft at the gate location. The cut-stone masonry portion of the downstream face is nearly plane and vertical, but the earth slope portion varies from as steep as 1.5 horizontal to 1 vertical to approximately 3 to 1. The above-water portion of the upstream face slopes irregularly at approximately 1 to 1, and has a cobble slope protection that is partially obscured by roots and brush. The crest and slopes of the main dam are generally irregular and wooded.

The dike embankment is similar to the main dam, but has a maximum height of about 12 ft above a downstream pond. The wooded downstream slope is generally flatter than the slope at the main dam, being typically about 3 or 4 to 1, and the upstream slope cover varies from cobbles and boulders to cobbles and gravel. The crest and slopes of the dike are also generally irregular and wooded.

- c. Size classification - The height of the dam is approximately 20 ft and the estimated total storage capacity at the top of the embankment is 500 acre feet. According to guidelines established by the Corps of Engineers, the dam is classified in the small category, based on both storage capacity and height of dam.
- d. Hazard Classification - The results of the dam failure analysis indicate that a flood wave resulting from a failure of the dam embankment would cause only minor water damage to one home adjacent to the downstream pond, and the Dudley Street-Oxford, Charlton Road intersection would be overtopped by approximately two feet of water. There is no significant potential for loss of life indicated. It is therefore recommended that New Pond Dam be classified as having a low hazard potential.
- e. Ownership - The dam has been owned by Stevens Linen Associates for the last 39 years. The previous owner was J.P. Stevens, Inc. The present owners' address is: Stevens Linen Associates, Inc., Box 220, Webster, Massachusetts, 01570 (phone 617/943-0600). Mr. Robert Javery, Plant Engineer, at the above address is the owners' representative.

- f. Operator - Operation of the dam is the responsibility of Mr. Robert Javery, Plant Engineer for Stevens Linen Associates, Inc. His address is: Stevens Linen Associates, Inc., Box 220, Webster, Massachusetts, 01570 (phone 617/943-0600).
- g. Purpose of Dam - New Pond Dam originally served as a water supply for the mills downstream. The outlet works have been sealed, and New Pond is presently used for recreational purposes only.
- h. Design and Construction History - No records of the construction of the dam are available. The type of construction utilized indicates that the dam was constructed prior to 1900. A 1925 inspection report indicates that water had not run over the spillway for some years. The gate to the outlet works was sealed in approximately the last five years.
- i. Normal Operational Procedures - The structures are maintained on a demand basis. There are no operational controls present at the dam.

1.3 Pertinent Data

Elevations given in this report are on National Geodetic Vertical Datum (NGVD) formerly referred to as Mean Sea Level (MSL).

- a. Drainage area - The 2.04 square mile watershed surrounding New Pond and Hayden Pond is sparsely developed and heavily wooded. The terrain is hilly with some upland marsh areas. The combined surface areas of New Pond and Hayden Pond occupy about 5.6% of the total drainage area.
- b. Discharge at Dam Site - There are no records of discharges at the dam site.
 - (1) Outlet works size-----2' x 2'-4" (sealed)
 - (2) Maximum known flood at damsite-----No records available
 - (3) Ungated spillway capacity at top of dam
100 cfs @ 533 elev.
 - (4) Ungated spillway capacity at test flood elevation
150 cfs @ 533.35 elev.
 - (5) Gated spillway capacity at normal pool elevation-----N/A
 - (6) Gated spillway capacity at test flood elevation-----N/A

(7) Total spillway capacity at test flood elevation
150 cfs @ 533.35 elev.

(8) Total project discharge at test flood elevation
580 cfs @ 533.35 elev.

c. Elevation (ft. above MSL)

(1) Streambed at centerline of dam-----513
(2) Test flood tailwater-----516+ (Est.)
(3) Upstream portal invert diversion tunnel-----None
(4) Recreation pool-----531
(5) Full flood control pool-----N/A
(6) Spillway crest-----531
(7) Design surcharge (Original Design)-----Unknown
(8) Top dam-----533
(9) Test flood design surcharge-----533.35

d. Reservoir

(1) Length of test flood pool-----3,950 ft. (Est.)
(2) Length of recreation pool-----3,900 ft. (Est.)
(3) Length of flood control pool-----N/A

e. Storage (acre-feet)

(1) Recreation pool-----300 Ac-ft
(2) Flood control pool-----N/A
(3) Spillway crest pool-----300 Ac-ft
(4) Top of dam-----500 Ac-ft
(5) Test flood pool-----525 Ac-ft

f. Reservoir Surface (acres)

(1) Recreation pool-----74.4
(2) Flood-control pool-----N/A

- (3) Spillway crest-----74.4
- (4) Test flood pool-----86.0
- (5) Top of dam-----84.3

g. Embankments

	<u>Dam</u>	<u>Dike</u>
(1) Type	Earth embankment w/partial stone masonry D/S face	Earth embankment
(2) Length	Approx. 450 ft. incl. spillway	Approx. 420 ft.
(3) Height	Approx. 20 ft. max.	Approx. 12 ft. max.
(4) Top width	12 to 25 ft.	11 to 15 ft.
(5) Side slopes	ranges 1.5 to 3:1 D/S except at stone masonry	ranges from 3 to 4:1 D/S
(6) Zoning	Unknown	Unknown
(7) Impervious Core	Unknown, 2" wood noted in 1938 inspect. report	Unknown
(8) Cutoff	Unknown	Unknown
(9) Grout Curtain	Probably none	Probably none

h. Diversion and Regulating Tunnel-----None

i. Spillway

- (1) Type-----masonry broad crested weir with 1 ft. deep notch - 3.5 ft. wide
- (2) Length of weir-----29 ft.
- (3) Crest elevation-----531 for notch, 532 remainder
- (4) Gates-----None
- (5) U/S Channel-----None-edge of pond
- (6) D/S Channel-----25 ft.+ drop in 800 ft. then 1,200 ft. of marsh to next pond

- i. Regulating Outlets. There is no presently operating regulating outlet or pond drain for this structure. The gate at the intake end has been sealed and the valve stem is no longer in place. The size of the gate is unknown but the outlet conduit dimensions are 2 feet horizontal by 2 feet 4 inches vertical. The invert elevation at the outlet end of the conduit is approximately elevation 513.

SECTION 2: ENGINEERING DATA

- 2.1 Design Records - No design records were located for the New Pond Dam.
- 2.2 Construction Records - No records of the original construction were located.
- 2.3 Operation Records - No operational records were located for the dam.
- 2.4 Evaluation
 - a. Availability - No records for the dam other than prior inspection reports were located.
 - b. Validity - There are no known design, construction or operating records.
 - c. Adequacy - The absence of known records requires that the evaluation of the dam during this investigation be based on the visual examination described in the following section.

SECTION 3: VISUAL INSPECTION

3.1 Findings

- a. General - The hydraulic-hydrologic reconnaissance of the facility with the Owner took place on 14 September 1978. The structural and soils portions of the Phase I visual examination of New Pond Dam were conducted on 20 September 1978.

In general, the dam was observed to be in fair condition. The area is overgrown with trees and there has been a long standing condition of seepage at the embankments.

Visual inspection checklists for the site visits are included in Appendix A and selected photographs are given in Appendix C.

- b. Dam - The embankments at this site were divided into two areas for the purpose of this report. The embankment south of the entrance road was considered the dam, while the embankment to the north was considered a dike. There was no visual evidence of major lateral movement or settlement at the dam or dike; however, there is local seepage and erosion, and a heavy growth of brush and trees. The open joint stone masonry walls at the dam and spillway appear to be stable and in good condition. The following specific items were noted during the site examination.
- (1) The dam and dike crests and slopes have a heavy cover of brush and trees that limits visual observation of their condition, as shown in Photos 1, 2, 11, 13, 15, & 19. There are also numerous tree cuttings and stumps at the base of the wall below the spillway.
 - (2) The upstream cobble slope protection at the dam and dike is partly concealed by brush and roots, and does not appear to provide complete coverage on the slopes, as shown in Photos 12, 16, & 18. The root mat is locally undercut along the upstream face.
 - (3) The downstream toe of the main dam has slight seepage with "rust" staining at the left end as shown in Photo 14 and near the center, and moderate seepage flow from under rocks at the embankment bend near the left quarter point. There are also pockets of water below the stone masonry downstream face and slight flow at the location of the abandoned gate. No evidence of soil movement was observed at the various seepage locations.
 - (4) The downstream toe of the dike does not show active seepage, but there is currently a pond below the right end, as shown

in Photo 17, and there has been ponded water to a depth of several feet in another low area near the center, as shown in Photo 20.

- (5) The crests of both the main dam and the dike are irregular in both width and elevation, with the freeboard varying from as low as 1.8 ft at two locations to over 2 ft at others.
 - (6) There is an apparent eroded hole about 2 ft deep in the dam crest alongside the left edge of the spillway; this hole has seeping water at the bottom.
 - (7) The right wingwall at the upstream gate opening has been undercut by erosion.
 - (8) A few pieces of stone masonry have fallen from the main downstream wall of the dam and from a small wall above the steep downstream slope at the location of the moderate seepage.
 - (9) There is an apparent eroded notch about 10 ft long and 1 ft deep in the downstream face of the dike where the crest is low, as indicated on the plan in Appendix C.
 - (10) Vehicle access for maintenance or repairs is difficult at the main dam and nearly impossible at the dike, primarily because of the numerous trees.
- c. Appurtenant Structures - The stone masonry wall at the downstream face of the dam, as shown in Photos 5 and 6, is in good condition with very few voids. The outlet structure inlet, as shown in Photos 3 and 4, is also of rubble stone masonry and in good condition. Several of the training wall top stones have been displaced. The valve stem for the conduit inlet is lying on the upstream face of the dam to the right of the intake and the gate is reported to have been sealed. Seepage from the outlet conduit (or from beneath the dam) was observed at the downstream end of the conduit. Debris is present in the downstream channel, as shown in Photo 7.

The spillway, as shown in Photos 8, 9 and 10, is in good condition. The spillway foundation is rubble stone masonry which has been overlain with concrete paving. Minor cracking is present in the paving. A notch (or pilot channel) has been cut in the basic spillway and surfaced with concrete. The stones removed during the resurfacing of the spillway have been dumped at the downstream toe. The entrance of the notch or pilot channel has stop log guides present which are rusted. No stop logs were observed at the dam.

- d. Reservoir Area - The reservoir is divided by a causeway into two ponds, New Pond and Hayden Pond. While no outlet for Hayden Pond or connecting culvert to New Pond was located, the ponds apparently have the same water surface elevation. Either a submerged culvert is present or the causeway embankment is very porous. The causeway would therefore act as a flood retarding structure in the event of a dam failure. The area around the ponds is generally wooded and, particularly Hayden Pond, is extensively developed. The present shoreline development includes more than 40 structures.

The side slopes of the ponds are variable and generally wooded. There is no significant potential for landslides into the ponds which would create waves that might overtop the dam. No conditions were noted which would result in a sudden increase in sediment load into the ponds.

- e. Downstream Channel - Immediately downstream of the spillway, the channel contains discarded stones from former spillway modifications. The area adjacent to the outlet works contains brush and branch debris from probable former clearing operations. The channel drops approximately 25 feet in 800 feet through a wooded area. This section from the spillway follows a somewhat defined channel while there is little evidence of a channel coming from the outlet works. The next 1,200 feet in the watercourse is through a marsh area which empties into a small pond known locally as Mosquito Pond. The flow then passes through two 60 foot long 42 inch A.C.C.M. pipes under Oxford Road into Wallis Pond. Flow from Wallis Pond passes under Charleton Road via two 45 foot long 54 inch A.C.C.M. pipes into Larner Pond. The area from New Pond to Oxford Road is undeveloped and few houses are present along Wallis and Larner Ponds.

- 3.2 Evaluation - The New Pond Dam embankments and appurtenances appear to be performing satisfactorily at the present time; previous inspection reports indicate that seepage at the embankments is a long-standing condition. However, the continuing seepage, the low points along the crest, and the numerous large trees could provide significant potential for embankment failure under conditions of higher than normal water levels or heavy winds.

SECTION 4: OPERATIONAL PROCEDURES

- 4.1 Procedures - In general, there is no established routine for the operation of the dam.
- 4.2 Maintenance of Dam - The dam and spillway have received minimal maintenance and then only upon demand. There is no established formal procedure for the maintenance of the dam. The present dam and dike have become overgrown with tree and brush growth.
- 4.3 Maintenance of Operating Facilities - The only operating facility, the reservoir drain, has been sealed.
- 4.4 Description of any Warning System in Effect - There is no established warning system or emergency preparedness plan in effect for this structure.
- 4.5 Evaluation - There is currently no operational procedures in effect for this dam. Formal operational procedures, maintenance programs, warning systems and emergency preparedness plans should be established. Periodic observation should be made and the tree and brush growth at the dam and dike should be brought under control. Maintenance of the dam should be performed at regular intervals.

SECTION 5: HYDRAULIC/HYDROLOGIC

5.1 Evaluation of Features

- a. General - New Pond Dam is an earth embankment located in the town of Dudley. The dam consists of a main embankment and a dike, each having a length of approximately 400 feet with a concrete spillway located at the westerly end of the main embankment. The dam was formerly used to regulate flow for water power for downstream mills. It is no longer used for this purpose but rather to control levels for recreational use of New Pond and Hayden Pond. The pond has a water surface area of approximately 74 acres at a spillway crest elevation of 531, and an estimated total storage capacity of 300 acre feet. The spillway consists of a concrete flume in which a notch has been cut for controlling and lowering the water levels in New Pond. The spillway discharges to the downstream face of the dam where flow is received by a small brook which makes its way in a southeasterly direction for approximately 2,000 feet to Mosquito Pond. From here, flow passes beneath Oxford Road into Wallis Pond then into Larner Pond and, subsequently, to Merino Pond before eventually joining the French River in Webster. All of the information utilized in this report was obtained from visual examination as well as measurements made at the site during the inspection and supplemented by information contained on the U.S.G.S. quadrangle sheets. Data pertaining to the area-elevation-storage capacity of the pond was developed from the U.S.G.S. quad sheets.
- b. Design Data - No hydraulic/hydrologic design data are available for the dam site.
- c. Experience Data - No records of past floods are available for the dam site.
- d. Visual Observations - Inspection of the dam was made on 14 September 1978. At that time the water level was only one-quarter inch below the crest of the spillway. The spillway was noted to be a concrete flume having a width of 29 feet and a length of 22 feet with a drop of one foot in a 20-foot length. The sidewalls to the flume or spillway varied in height from 18 to 30 inches. In the center of the flume is a notch approximately 43 inches wide and about 12 inches deep which apparently had been cut out of the original flume or spillway within the last decade so as to provide releases from the pond at a stage 11 to 12 inches lower than the previous spillway elevation. The spillway was noted to be in good hydraulic condition and the discharge was to a pile of dumped rock some ten feet below the downstream side of the flume where the outlet stream commences. The outlet

stream was noted to drop rather rapidly, falling approximately 25 feet in the first 800 feet to a swampy area, thence flowing through the swampy area a distance of nearly 1,200 feet before entering Mosquito Pond.

- e. Test Flood Analysis - Based upon Corps of Engineers guidelines, the recommended test flood for the size (small) and hazard (low) is within the range of 50-year to 100-year flood. The drainage area tributary to the Hayden Pond-New Pond complex is approximately 2.04 square miles. This area is sparsely populated, is hilly with some upland marshy areas, and the combined water surface areas of New Pond and Hayden Pond occupy about five and one half percent of this drainage area. The water shed terrain was determined to be rolling, and an inflow rate of 2,250 cfs per square mile was utilized with the 2.04-square mile drainage area to produce a test flood inflow of approximately 2,300 cfs for one half PMF. The 100-year flood was found to have an inflow rate of 925 cfs. Storage routing of this flow indicated that this peak rate would be reduced to approximately 580 cfs by the storage and spillway characteristics of New Pond. However, routing of this flow indicated that, even with the reduced flow of 580 cfs, the test flood would still overtop the dam by 0.35 feet, resulting in an average flow depth of 4 inches over the embankment.

Hayden Pond shoreline has a low point at its north end leading to Pierpoint Meadow Pond. No culvert or outlet from the pond was located at this point nor did a resident ever hear of overland flow from the pond. However, the resident did report sand-bagging had been employed at this location at high pond levels and the residents have been troubled with seepage from the pond along this route.

- f. Dam Failure Analysis - Based on Corps of Engineers Guidelines for Estimating Dam Failure hydrographs, and assuming that a failure would occur along a section 67 feet in length in the vicinity of the high point of the dam with the water level 2 ft above the spillway crest (elevation 533), the failure would result in a peak outflow of 10,000 cfs. This flow, however, would undergo a drastic reduction to 3,700 cfs in the first reach between the dam and Mosquito Pond, due to the vast storage area available. The water level in Mosquito Pond would rise to elevation 512, or approximately 2 feet over Oxford Road, as the flow would make its way into Wallis Pond. This level would likely cause minor water damage to one house in the immediate area. The flow from Wallis Pond into Larner Pond would be through the existing twin 54-inch diameter corrugated metal pipes beneath Charleton Road. The reduced failure outflow would overtop Charleton Road by approximately 0.8 foot with no apparent hazard. The considerably greater storage in Larner Pond, just downstream, would be sufficient to completely dampen out the remaining dam failure

flow with no damage to be expected in Marino Pond and other points downstream. It is, therefore, recommended that the high hazard classification for this dam be reduced to "low."

SECTION 6: STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

- a. Visual Observation - There was no visible evidence of dam, dike, or spillway instability during the site examination on 20 September 1978. Seepage at the various locations along the downstream toe of the dam embankment showed no evidence of active erosion or piping, and is not considered to pose an immediate hazard to the stability of the downstream slope.
- b. Design and Construction Data - Except for old inspection report references to a 2-in. wood corewall and gravel embankment material, there is substantially no design or construction information on the dam and dike embankments. Local surface exposures do appear to confirm a gravelly sand embankment material, but the extent of such material is not certain. Thus, theoretical analyses of the structural stability of the embankments are not possible.

The above-water embankment geometry, as determined by limited measurements at the site, and the long period of service of the dam indicate that the embankments would be expected to be adequately stable under static loading conditions. Whether or not the seepage can cause future instability has not been determined.

- c. Operating Records - No operating records are known to exist for the dam, except for Inspection Reports by Worcester County.
- d. Post-Construction Changes - Without design or "as-built" drawings, it is not known if there have been post-construction changes to the embankments. A 1930 inspection report does make reference to "reconstructed and widened embankments." Based on comments in previous inspection reports and the appearance of the spillway, it appears that the spillway was paved with concrete after its original construction and subsequently the pond was lowered approximately one foot by the cutting of a notch in the broad-crested spillway.
- e. Seismic Stability - The dam is located in a Seismic Zone No. 2 and, in accordance with recommended Phase I guidelines, does not warrant seismic analysis.

SECTION 7: ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

7.1 Dam Assessment

- a. Condition - The visual examination of New Pond Dam, including the dike, did not reveal any evidence of failure or conditions which would warrant urgent remedial treatment. However, because of the need for maintenance and additional investigation that is outlined hereinafter, the project is considered to be in only fair condition.
- b. Adequacy of Information - All of the information for the Phase I Investigation had to be obtained from visual examination and limited measurements at the site. This information has been sufficient for the purpose of this investigation, but it does not permit detailed evaluation of stability, seepage or available freeboard.
- c. Urgency - The recommended additional investigations and remedial measures outlined in Sections 7.2 and 7.3, respectively, should be undertaken within one year after receipt of this report by the Owner.
- d. Need for Additional Investigations - Additional investigations should be performed by the Owner as outlined in the following section.

7.2 Recommendations

It is recommended that the following additional investigations be performed by the Owner:

1. An investigation to determine whether or not the seepage that is occurring at the downstream toe of the dam can have a significant effect on long-term dam stability. This would include regular monitoring of the various observed seepage locations, including checks during higher than normal pond levels, to determine if conditions are changing with time.
2. Topographic survey of the dam and dike embankments, including underwater portions, and evaluation of actual embankment configuration with respect to stability and available freeboard. If the survey does not provide sufficient information to confirm adequate stability, it might be necessary to carry out test borings and/or test excavations to determine the character of the embankment material and the existence and condition of core walls.

3. A detailed hydrologic-hydraulic investigation to determine the necessary discharge capabilities of the spillway and the measures required to significantly increase the spillway capacity to meet this requirement.
4. An investigation to determine the required measures to make the outlet works (reservoir drain) operational.

7.3 Remedial Measures

- a. Operation and Maintenance Procedures - It is recommended that the following remedial work be undertaken by the Owner, in addition to the investigations outlined in Section 7.2, to correct deficiencies noted during the visual examination:
 - (1) Clear brush and trees from the dam and dike embankments, including stump removal and backfilling, establish vegetation cover, and cut grass and weeds on the embankments at least once a year.
 - (2) Provide additional riprap or cobble slope protection where it is lacking or deficient on the upstream faces of the dam and dike; restore and reshape local eroded areas.
 - (3) Reshape the dam and dike crests to provide uniform freeboard and permit vehicle access for maintenance and repair. Repair eroded notch in dike downstream slope and hole in dam crest near spillway. The extent of the reshaping will be subject to the results of the evaluation of actual embankment configuration recommended in Section 7.2.
 - (4) Replace fallen stones in stone masonry walls.
 - (5) Remove debris from downstream side of spillway and outlet structures.

Due to the discharge capabilities of the spillway and the condition of the dam, it is recommended that during high reservoir levels and unusually heavy precipitation the Owner provide surveillance of the embankments and spillway. The Owner should also develop a formal emergency procedures plan and warning system in cooperation with local officials in downstream communities. Finally it is recommended that the owner establish a formal operational procedure and maintenance program and a program of annual technical inspections.

7.4 Alternatives - Not applicable.

APPENDIX A - INSPECTION TEAM

ORGANIZATION AND CHECKLIST

Page No.

VISUAL INSPECTION PARTY ORGANIZATION

A-1

VISUAL INSPECTION CHECKLIST

Dam Embankment, Stone
Dam Embankment, Earth (E-W)
Dike Embankment (N-S)
Spillway
Outlet Works
Hydrologic-Hydraulic Considerations
Downstream Culverts

A-2

A-3

A-4

A-5

A-6

A-7

A-8

VISUAL INSPECTION PARTY ORGANIZATION
NATIONAL DAM INSPECTION PROGRAM

DAM: New Pond

DATE: September 14, 1978 (Soils and structures on 20 September 1978)

TIME: 2:15 p.m.

WEATHER: Clear to partly cloudy - 65°F, lt. var. wind

WATER SURFACE ELEVATION UPSTREAM: ½" below spillway crest

STREAM FLOW: Only ds flow leakage through abandoned gate and seepage flow less than 1 cfs

INSPECTION PARTY:

1. Joseph E. Downing - CDM
2. Charles E. Fuller - CDM
3. _____
4. Roger H. Wood - CDM - 9/20/78
5. Peter LeCount - H&A - 9/20/78
6. _____

PRESENT DURING INSPECTION:

1. Robert Javery - Stevens Linen Associates
2. _____
3. _____
4. _____

VISUAL INSPECTION CHECK LIST
NATIONAL DAM INSPECTION PROGRAM

DAM: New Pond

DATE: 9/20/78

EMBANKMENT: Dam, Stone

CHECK LIST	CONDITION
1. Upstream Slope a. Vegetation b. Sloughing or Erosion c. Rock Slope Protection - Riprap Failures d. Animal Burrows	1. a. Thick brush, weeds, trees to 5 in. dia. b. Root mat locally undercut few inches c. Cobbles among roots & brush d. None observed
2. Crest a. Vegetation b. Sloughing or Erosion c. Surface cracks d. Movement or Settlement	2. a. Grass, weeds, overhanging brush & trees. b. Hole alongside spillway (2.5' x 4.5' x 2' deep-slight seepage on bottom) c. None observed d. Crest elevation varies approx. 6 in. cause not known.
3. Downstream Slope a. Vegetation b. Sloughing or Erosion c. Surface cracks d. Animal Burrows e. Movement or Cracking near toe f. Unusual Embankment or Downstream Seepage g. Piping or Boils h. Foundation Drainage Features i. Toe Drains	3. a. Brush above wall, trees & brush at base. b. N/A (stone masonry wall) c. N/A (stone masonry wall) d. N/A (stone masonry wall) e. N/A (stone masonry wall) f. Local small pockets of water at base of wall, slight flow at drain from gate, slight seepage (w/rust stain) at toe of slope below left abutment. g. None observed h. None known i. None known
4. General a. Lateral Movement b. Vertical Alignment c. Horizontal Alignment d. Condition at Abutments and at Structures e. Indications of Movement of Structural Items f. Trespassing g. Instrumentation Systems	4. a. Not evident b. Crest elev. varies approx. 6 in. c. Wall face looks good d. Hole alongside spillway, gate wingwall undercut e. None observed (except few stones from wall) f. Appears minor g. None

VISUAL INSPECTION CHECK LIST
NATIONAL DAM INSPECTION PROGRAM

DAM: New Pond DATE: 9/20/78
 EMBANKMENT: Dam, Earth (E-W)

CHECK LIST	CONDITION
1. Upstream Slope a. Vegetation b. Sloughing or Erosion c. Rock Slope Protection - Riprap Failures d. Animal Burrows	1. a. Brush, weeds, trees to 24 in. dia. b. Root mat locally undercut few inches c. Gravel & cobbles, local gaps d. None observed
2. Crest a. Vegetation b. Sloughing or Erosion c. Surface cracks d. Movement or Settlement	2. a. Grass, weeds, brush & trees b. None observed c. None observed d. Crest elevation varies approx. 6 in. cause not known.
3. Downstream Slope a. Vegetation b. Sloughing or Erosion c. Surface cracks d. Animal Burrows e. Movement or Cracking near toe f. Unusual Embankment or Downstream Seepage g. Piping or Boils h. Foundation Drainage Features i. Toe Drains	3. a. Grass, weeds, brush, trees to 24 in. dia. b. Slope irregular in few locations possibly from fallen trees; stone wall at steep location partly fallen down. c. None observed d. None observed e. None observed f. Local slight seepage with rust stain where ground is low at toe; moderate seepage flow from under rocks at one location. g. None observed h. None known i. None known
4. General a. Lateral Movement b. Vertical Alignment c. Horizontal Alignment d. Condition at Abutments and at Structures e. Indications of Movement of Structural Items f. Trespassing g. Instrumentation Systems	4. a., b., c. Dam shape somewhat irregular, movement not evident. d. N/A e. N/A f. Appears minor g. None

VISUAL INSPECTION CHECK LIST
NATIONAL DAM INSPECTION PROGRAM

DAM: New Pond

DATE: 9/20/78

EMBANKMENT: Dike (N-S)

CHECK LIST	CONDITION
1. Upstream Slope a. Vegetation b. Sloughing or Erosion c. Rock Slope Protection - Riprap Failures d. Animal Burrows	1. a. Brush, weeds, trees to 24 in. dia. b. Appears minor c. Gravel & cobbles, generally intact d. None observed
2. Crest a. Vegetation b. Sloughing or Erosion c. Surface cracks d. Movement or Settlement	2. a. Grass, weeds, brush & trees b. Shape varies, possibly due to past erosion by water or foot traffic. c. None evident d. Crest elevation varies approx. 1 ft. cause not known.
3. Downstream Slope a. Vegetation b. Sloughing or Erosion c. Surface cracks d. Animal Burrows e. Movement or Cracking near toe f. Unusual Embankment or Downstream Seepage g. Piping or Boils h. Foundation Drainage Features i. Toe Drains	3. a. Grass, weeds, brush, trees to 24 in. dia. b. Local eroded area, approx. 2' x 10' x 1' deep, appears to have been caused by overtopping. c. None observed d. None observed e. None observed f. No obvious active seepage but ponded water along approx. 1/2 of toe length g. None observed h. None known i. None known
4. General a. Lateral Movement b. Vertical Alignment c. Horizontal Alignment d. Condition at Abutments and at Structures e. Indications of Movement of Structural Items f. Trespassing g. Instrumentation Systems	4. a., b., c. Dam shape irregular, movement not evident. d. Gradual transition to natural ground at north abutment. e. N/A f. Appears minor g. None

VISUAL INSPECTION CHECK LIST
NATIONAL DAM INSPECTION PROGRAM

DAM: New Pond

DATE: Sept. 20, 1978

SPILLWAY: _____

CHECK LIST	CONDITION
1. Approach Channel a. General Condition b. Obstructions c. Log Boom etc.	1. a. Good condition, spillway adjacent to pond. b. Brush at right & left edge. c. None
2. Weir a. Flashboards b. Weir Elev. Control (Gate) c. Vegetation d. Seepage or Efflorescence e. Rust or Stains f. Cracks g. Condition of Joints h. Spalls, Voids or Erosion i. Visible Reinforcement j. General Struct. Condition	2. a. Steel guides for stop logs present in pilot channel. Some rust-good condition. b. No gate c. None observed in spillway d. None observed e. None observed f. Shrinkage and cold joint cracks g. Good condition h. Minor spalls and chips i. None observed j. Good condition
3. Discharge Channel a. Apron b. Stilling Basin c. Channel Floor d. Vegetation e. Seepage f. Obstructions g. General Struct. Condition	3. a. None present b. Vertical drop to channel below. Some loose rock & concrete from spillway modification present below. c., d. Heavily forested. Piled branches etc. e. Area moist-some trapped water present f. See 3 b, c & d g. Fair condition
4. Walls a. Wall Location <u>At end of weir</u> (1) Vegetation (2) Seepage or Efflorescence (3) Rust or Stains (4) Cracks (5) Condition of Joints (6) Spalls, Voids or Erosion (7) Visible Reinforcement (8) General Struct. Condition	4. a. Wall is open joint stone masonry wall at end of weir and also serves as downstream wall of dam. (1) Moss growth (2) N/A (3) None observed (4) N/A (5) Open-good condition (6) None observed (7) N/A (8) Good condition

VISUAL INSPECTION CHECK LIST
NATIONAL DAM INSPECTION PROGRAM

DAM: New Pond

DATE: Sept. 20, 1978

OUTLET WORKS: _____

CHECK LIST	CONDITION
1. Inlet a. Obstructions b. Channel c. Structure d. Screens e. Stop Logs f. Gates	1. a. None at surface b. 12' long, 3'-6" wide at inlet c. Open joint stone masonry walls. Inlet walls flared. Top slightly displaced. d. None e. None f. Gate abandoned and plugged. Anchor bolt for missing shaft still projecting from stone.
2. Control Facility a. Structure b. Screens c. Stop Logs d. Gates e. Conduit f. Seepage or Leaks	2. a., b., c., d. None e. Beneath dam - not visible f. See 3
3. Outlet a. Structure b. Erosion or Cavitation c. Obstructions d. Seepage or Leaks	3. a. Open joint stone masonry well chinked wall. Wall is downstream face of dam. Good condition. b. None observed c. Downstream overgrown - heavily forested. Piled branches and tree cuttings. d. Flow is coming out 2' Horiz. & 2'-4" Vert. outlet of conduit and beneath adjacent stones of downstream wall of dam.
4. Mechanical and Electrical a. Crane Hoist b. Hydraulic System c. Service Power d. Emergency Power e. Lighting f. Lightning Protection	4. None

VISUAL INSPECTION CHECK LIST
NATIONAL DAM INSPECTION PROGRAM

DAM: NEW POND

DATE: September 14, 1978

HYDROLOGIC-HYDRAULIC CONSIDERATIONS: _____


CHECK LIST	CONDITION
<p>1. Upstream Watershed</p> <p> a. Type of Terrain</p> <p> b. Hydrologic Controls</p> <p>2. Reservoir</p> <p> a. Type of Terrain</p> <p> b. Development</p> <p>3. Spillway</p> <p> a. Adjacent Low Points</p> <p> b. Spillway Approach (Slope)</p> <p> c. Spillway Discharge (Slope)</p> <p> d. Spillway Type</p> <p>4. Downstream Watershed</p> <p> a. Reach No.</p> <p> (1) Control (Bridge, dam, culvert, etc.)</p> <p> (2) Channel Characteristics</p> <p> (3) Development</p> <p> (4) Visible Utilities</p> <p> (5) Special Problems (Hospital, etc.)</p>	<p>1a. Slight to moderately hilly (5-10% av. slope)</p> <p>1b. Hydrologic controls include Easterbrook Pond and swampy area (20 acres) just d.s. in southwesterly corner of watershed as well as swampy area (10 acres) west of Corbin Rd. Further control from northerly portion of watershed by Hayden Pond which appears to be hydraulically connected, although no culvert opening could be found.</p> <p>2a. Slight to moderately hilly with shallow pond.</p> <p>2b. Development is presently sparse (12 houses around shoreline) although more residential development now evident in area adjacent to shoreline (n.e. of pond)</p> <p>3a. Low point on dam is on easterly leg (sta. 2+00) where wash area (2' wide) indicates previous spillage (see sketch)</p> <p>3b. Approach is edge of pond which is 2-3 ft. deep at stream bank.</p> <p>3c. Discharge is from concrete flume vertically downward about 9-10-ft on to damped rock and debris.</p> <p>3d. Concrete flume 29' wide x 22' long (see sketch) with 12" x 42" notch cut out for low flow discharge.</p> <p>4a. Reach No. 1 - 2000-ft from New Pond to westerly portion of Mosquito Pond (28' drop) with flow thru 1500-ft of swamp before easterly Wallis Pond. Flow from Mosquito Pond to Wallis Pond controlled by twin 42" ACCM as is flow from Wallis Pond to Larner Pond by twin 54" ACCM. Combined storage of Mosquito, Wallis and Larner Pond is probably sufficient to store waters released from New Pond by failure of dam.</p>

DOWNSTREAM COLLECTS


Hayden Pond to New Pond

No visible culvert but stone header suggests one. U.S. 3' below height of road.

Mosquito Pond to Wallis Pond



Wallis Pond to Larner Pond



APPENDIX B

LIST OF AVAILABLE DOCUMENTS AND
PRIOR INSPECTION REPORTS

Page No.

LIST OF AVAILABLE DOCUMENTS

None Available

PRIOR INSPECTION REPORTS

<u>DATE</u>	<u>BY</u>	
1. January 7, 1925	Worcester County Engineer	B-1
2. February 9, 1927	Worcester County Engineer	B-2
3. April 2, 1930	Worcester County Engineer	B-3
4. July 27, 1932	Worcester County Engineer	B-4
5. January 13, 1936	Worcester County Engineer	B-5
6. January 13, 1937	Worcester County Engineer	B-6
7. October 18, 1938	Worcester County Engineer	B-7 & 8
8. March 23, 1939	Worcester County Engineer	B-9
9. April 17, 1939	Worcester County Engineer	B-10
10. December 11, 1940	Worcester County Engineer	B-11
11. December 30, 1941	Worcester County Engineer	B-12
12. December 10, 1942	Worcester County Engineer	B-13
13. February 18, 1944	Worcester County Engineer	B-14
14. December 10, 1945	Worcester County Engineer	B-15
15. December 1, 1947	Worcester County Engineer	B-16
16. December 2, 1950	Worcester County Engineer	B-17
17. November 29, 1951	Worcester County Engineer	B-18
18. September 13, 1955	Worcester County Engineer	B-19
19. October 25, 1963	Worcester County Engineer	B-20 & 21
20. May 15, 1964	Worcester County Engineer	B-22
21. August 29, 1968	Worcester County Engineer	B-23 & 24
22. March 14, 1969	Worcester County Engineer	B-25
23. February 9, 1972	Unknown	B-26

COUNTY OF WORCESTER MASSACHUSETTS
COUNTY ENGINEER

Inspection of Dams, Reservoir Dams, and Reservoirs.

Inspected by L. O. Marden Date Jan. 7, 1925 Dam No. 14-10

Town Dudley - Hayden Res. Location 1.5 mi. S. Charlton T. Line
Owner Stevens Linc. Works Use Storage
Material and Type ⁴⁰⁰ Earth emb. - 220' main run cut ^{78'} stone dry laid wall 8' thick
1 1/2:1 rip rap upstream face
Dam Designed by _____ Constructed by _____ Year _____

SPILLWAY LENGTH 33' - spillway 23' east end dam
El. top Abutment 100 El. Crest 97 El. Apron _____ El. Streambed 8'
Width top Abutment 20-22 Width top Crest 40 Width bottom Spillway 50+-
Width Flashboards carried 3' Kind Flashboards _____
El. Flowline Cleanout Pipe _____ Size and Kind Cleanout Pipe _____
Kind of Foundation under Spillway Gravel soil
Condition Water has not run over top of spillway for some years, grassed
over. Filled in top of wall with mortar

EMBANKMENT LENGTH 400'
El. Top 100 El. Natural Ground 81 Width Top 20-22
Width of Bottom 50+- Upstream Slope 1 1/2:1 riprap Downstream Slope 1 1/2:1
Kind of Corewall _____ Riprap 1 1/2:1 4.5
Material in Embankment Gravel soil Foundation Gravel soil
Condition Good except cut off trees and brush

GATES 2x2 waste, main channel
3x2 waste, appears to be stoned up Location just e. ast spillway
Size _____ Kind _____ El. Flowline _____
Condition _____

WHEEL Kind _____ Size _____ Rated H. P. _____
Location _____ Ave. Head _____
Evidence of Leaks in Structure none

Recent Repairs and Date none
Topography of Country below Dam Woods d valley -- small slope

Nature of Buildings and Roads below Dam none

Number Acres in Pond _____ Drainage Area in Square Miles _____
Discharge in Second Feet per Square Mile _____
Estimated Storage Million Cubic Feet _____

Decree No.

Dam No. 14-10

COUNTY OF WORCESTER, MASSACHUSETTS
OFFICE OF COUNTY ENGINEER

SECOND REPORT

Neg. Nos.

INSPECTION OF DAMS, RESERVOIR DAMS AND RESERVOIRS

Town Dudley Date Feb. 9, 1927 Dam No. 14-10

Location Name of Pond or Stream Hayden Res.

Inspected by L.O. Marden

Owner Stevens Eining Works. Use

MATERIAL & TYPE See first Inspection Sheet

Elevations in feet: above (+) or below (-) full pond or reservoir level.

FOR DAM Bed of stream below top of spillway

FOR RESERVOIR

top of dam top of flashboards ground surface below

level of overflow pipe length in feet

width top in feet width bottom in feet size pipe to mill

inches length spillway in feet head in feet

Size of wheel H. P. developed

Size of gates location of gates

Foundation and details of construction

condition of embankment Cut off trees

Constructed by date and brush

Designed by location

Recent repairs and date

Evidence of leakage

Condition Fill in holes in embankment and top of downstream wall.

Topography of country below

Nature of buildings and roads below dam

No. Acres in watershed No. Acres in pond

Plans secured Percent watershed in cultivation

Percent in forests Note: Cross out word not applicable

COUNTY OF WORCESTER MASSACHUSETTS

COUNTY ENGINEER

Inspection of Dams, Reservoir Dams, and Reservoirs.

Inspected by L. O. Manden-H. W. Crawford Date April 2, 1930. Dam No. 14-10

Town Dudley Location Hayden Reservoir.
Owner Stevens Line Works Use storage.
Material and Type

Dam Designed by _____ Constructed by _____ Year _____

SPILLWAY—Length _____ Feet. Depth _____ Feet

El. top Abutment _____ El. Crest _____ El. Apron _____ El. Streambed _____

Width top Abutment _____ Width top Crest _____ Width bottom Spillway _____

Width Flashboards carried _____ Kind Flashboards _____

El. Flowline Cleanout Pipe _____ Size and Kind Cleanout Pipe _____

Kind of Foundation under Spillway _____

Condition should clean out brush etc and lower level to spillway

provide concrete sidewalls.

EMBANKMENT—Length overall _____ Feet

El. Top _____ El. Natural Ground _____ Width Top _____

Width of Bottom _____ Upstream Slope _____ Downstream Slope _____

Kind of Corewall _____ Riprap _____

Material in Embankment _____ Foundation _____

Condition Have reconstructed and widened embankments-OK.

GATES _____ Location _____

Size _____ Kind _____ El. Flowline _____

Condition OK

WHEEL _____ Kind _____ Size _____ Rated H. P. _____

Location _____ Ave. Head _____

Evidence of Leaks in Structure small leaks- seepage

Recent Repairs and Date see under embankment.

Topography of Country below Dam _____

Nature of Buildings and Roads below Dam _____

Number of Acres in Pond _____ Drainage Area in Square Miles _____

Discharge in Second Feet per Square Mile _____

Estimated Storage Million Cubic Feet _____

COUNTY OF WORCESTER MASSACHUSETTS
COUNTY ENGINEER

Inspection of Dams, Reservoir Dams, and Reservoirs.
Messr's. Crawford, Healy and

Inspected by..... L. O. Marden Date July 27, 1932 Dam No. 14-10

Town..... Dudley Location.....

Owner..... Stevens Linen Co. Use.....

Material and Type.....

Dam Designed by..... Constructed by..... Year.....

SPILLWAY—Length..... Feet. Depth..... Feet

El. top Abutment..... El. Crest..... El. Apron..... El. Streambed.....

Width top Abutment..... Width top Crest..... Width bottom Spillway.....

Width Flashboards carried..... Kind Flashboards.....

El. Flowline Cleanout Pipe..... Size and Kind Cleanout Pipe.....

Kind of Foundation under Spillway.....

Condition.....

EMBANKMENT—Length overall..... Feet

El. Top..... El. Natural Ground..... Width Top.....

Width of Bottom..... Upstream Slope..... Downstream Slope.....

Kind of Corewall..... Riprap.....

Material in Embankment..... Foundation.....

Condition.....

GATES..... Location.....

Size..... Kind..... El. Flowline.....

Condition..... Discussed means of improving gates.

WHEEL..... Kind..... Size..... Rated H. P.....

Location..... Ave. Head.....

Evidence of Leaks in Structure.....

Recent Repairs and Date.....

Topography of Country below Dam.....

Nature of Buildings and Roads below Dam.....

Number of Acres in Pond..... Drainage Area in Square Miles.....

Discharge in Second Feet per Square Mile.....

Estimated Storage Million Cubic Feet.....

COUNTY OF WORCESTER MASSACHUSETTS
COUNTY ENGINEER

Inspection of Dams, Reservoir Dams, and Reservoirs.

Inspected by L.O.M. Master Mcg. Healey Date Jan. 13, 36 Dam No. 14-10

Town Dudley Location Hayden Reservoir.

Owner Stevens Linen Works. Use _____

Material and Type _____

Dam Designed by _____ Constructed by _____ Year _____

SPILLWAY

El. top Abutment _____ El. Crest _____ El. Apron _____ El. Streambed _____

Width top Abutment _____ Width top Crest _____ Width bottom Spillway _____

Width Flashboards carried _____ Kind Flashboards _____

El. Flowline Cleanout Pipe _____ Size and Kind Cleanout Pipe _____

Kind of Foundation under Spillway _____

Condition abutment walls should be raised 2 feet-lower freeboard- new concrete crest

EMBANKMENT

El. Top _____ El. Natural Ground _____ Width Top _____

Width of Bottom _____ Upstream Slope _____ Downstream Slope _____

Kind of Cortwall _____ Riprap _____

Material in Embankment _____ Foundation _____

Condition believes large trees in embankment same cause of leaks if removed stumps should be entirely cut out.

GATES _____ Location _____

Size _____ Kind _____ El. Flowline _____

Condition large stream water coming thru gate with same closed leak about 20-35 feet from gate house water side of dam- also several bad leaks along foot of embankment.

WHEEL _____ Kind _____ Size _____ Rated H. P. _____

Location _____ Ave. Head _____

Evidence of Leaks in Structure _____

Recent Repairs and Date _____

Topography of Country below Dam _____

Nature of Buildings and Roads below Dam _____

Number Acres in Pond _____ Drainage Area in Square Miles _____

Discharge in Second Feet per Square Mile _____

Estimated Storage Million Cubic Feet _____

COUNTY OF WORCESTER MASSACHUSETTS

COUNTY ENGINEER

Inspection of Dams, Reservoir Dams, and Reservoirs.

Inspected by L.O.M., Mast. Mech. Healey Date 1-12-37 Dam No. 14-10

Town Dudley Location Hayden Reservoir

Owner Stevens Linen Works Use

Material and Type

Dam Designed by Constructed by Year

SPILLWAY—Length Feet Depth Feet

El. top Abutment El. Crest El. Apron El. Streambed

Width top Abutment Width top Crest Width bottom Spillway

Width Flashboards carried Kind Flashboards

El. Flowline Cleanout Pipe Size and Kind Cleanout Pipe

Kind of Foundation under Spillway

Condition Abutment walls should be raised 2 ft. Low free board new concrete crest.

EMBANKMENT—Length overall Feet

El. Top El. Natural Ground Width Top

Width of Bottom Upstream Slope Downstream Slope

Kind of Corewall Riprap

Material in Embankment Foundation

Condition Believe large trees in embankment cause some of leak. If removed stumps should be entirely cut out.

GATES Location

Size Kind El. Flowline

Condition Large stream water coming thru gate with same closed. Leak about 30-35 feet from gate house water side of dam. Also several bad leaks along foot of embankment

WHEEL Kind Size Rated H. P.

Location Ave. Head

Evidence of Leaks in Structure

Recent Repairs and Date

Topography of Country below Dam

Nature of Buildings and Roads below Dam

Number of Acres in Pond Drainage Area in Square Miles

Discharge in Second Feet per Square Mile

Estimated Storage Million Cubic Feet

WORCESTER COUNTY ENGINEER

Inspection of Dams, Reservoir Dams, and Reservoirs

Inspected by E. S. Grover Date 10-18-38 Dam No. 14-10

Town Dudley Location W. Charlton Road

Owner Stevens Linen Works Use _____

SPILLWAY 28'4" long x 1'6" above crest
El. top abutment _____ El. Crest 1" W.L. El. Apron _____ El. St. Bed _____
Width top Abut. _____ Width top Crest 16" Width bottom Sp. way _____
Width flashboards none Kind Flashboards _____
El. Flowline Cleanout Pipe _____ Size and Kind Pipe _____
Kind of Foundation under Spillway rock
Condition OK below narrow outlet, Water 1" below crest

EMBANKMENT _____ crest
E. Top 2'0" above El. Natural Ground _____ Width Top 22'0"
Width of Borrom _____ Upstream Slope gravel Downstream Slope Masonry
Kind of Corewall 2" wood Piprap none
Material in Embankment Gravel backed by masonry Foundation _____
Condition OK except for seepage at XXX in sketch

GATES _____ Location _____
Size _____ Kind _____ El. Flowline _____
Condition _____


Evidence of Leaks in Structure _____

Recent Repairs and Date _____

Number Acres in Pond _____ Drainage Area in Sq. Miles _____

Discharge in Second Feet per Square Mile _____

Estimated Storage Million Cubic Feet _____



APPENDIX B-8

**COUNTY OF WORCESTER MASSACHUSETTS
COUNTY ENGINEER**

Inspection of Dams, Reservoir Dams, and Reservoirs

Inspected by K.M. Finlayson Date 3-23-1939 Dam No. 14-10

Town Dudley Location Hayden Reservoir

Owner Stevens Linn Works Use _____


Material and Type _____ Measured _____

Dam Designed by _____ Constructed by _____ Year _____

SPILLWAY

El. top Abutment _____ El. Crest _____ El. Apron _____ El. Streambed _____

Width top Abutment _____ Width top Crest _____ Width bottom Spillway _____



Topography of Country below Dam _____

Nature of Buildings and Roads below Dam _____

Number Acres in Pond _____ Drainage Area in Square Miles _____

Discharge in Second Feet per Square Mile _____

Estimated Storage Million Cubic Feet _____

WORCESTER COUNTY ENGINEER

Inspection of Dams, Reservoir Dams, and Reservoirs

M.M. Healey

Inspected by L.O. Marden-J.B. Lowell Date 4-17-1939 Dam No. 17-16

Town Dudley Location Hayden Reservoir

Owner Stevens Linen Works Use _____

SPILLWAY

El. top abutment _____ El. Crest _____ El. Apron _____ El. St. Bed _____

Width top Abut. _____ Width top Crest _____ Width bottom Sp. way _____

Width flashboards _____ Kind Flashboards _____

El. Flowline Cleanout Pipe _____ Size and Kind Pipe _____

Kind of Foundation under Spillway _____

Condition Discuss raising the abutment walls to this spillway at least two feet, or perhaps lowering same- should raise embankment-riprap same

EMBANKMENT

El. Top _____ El. Natural Ground _____ Width Top _____

Width of Borrow _____ Upstream Slope _____ Downstream Slope _____

Kind of Corewall _____ Riprap _____

Material in Embankment _____ Foundation _____

Condition _____

GATES Location _____

Size _____ Kind _____ El. Flowline _____

Condition _____

Evidence of Leaks in Structure _____

Recent Repairs and Date _____

Number Acres in Pond _____ Drainage Area in Sq. Miles _____

Discharge in Second Feet per Square Mile _____

Estimated Storage Million Cubic Feet _____

**COUNTY OF WORCESTER MASSACHUSETTS
COUNTY ENGINEER**

Inspection of Dams, Reservoir Dams, and Reservoirs

Inspected by W.D. Lundquist Date Dec. 11, 1948 Dam No. 1728

Town DUDLEY Location Hayden Pond

Owner _____ Use _____

Material and Type _____

Dam Designed by _____ Constructed by _____ Year _____

SPILLWAY

El. top Abutment _____ El. Crest _____ El. Apron _____ El. Streambed _____

Width top Abutment _____ Width top Crest _____ Width bottom Spillway _____

Width Flashboards carried _____ Kind Flashboards _____

El. Flowline Cleanout Pipe _____ Size and Kind Cleanout Pipe _____

Kind of Foundation under Spillway _____

Condition OK Dam seems to be in good condition but Pond is empty.

EMBANKMENT

El. Top _____ El. Natural Ground _____ Width Top _____

Width of Bottom _____ Upstream Slope _____ Downstream Slope _____

Kind of Corewall _____ Riprap _____

Material in Embankment _____ Foundation _____

Condition OK

GATES

Location _____

Size _____ Kind _____ El. Flowline _____

Condition OK Wide open

WHEEL Kind _____ Size _____ Rated H. P. _____

Location _____ Ave. Head _____

Evidence of Leaks in Structure _____

Recent Repairs and Date _____

Topography of Country below Dam _____

Nature of Buildings and Roads below Dam _____

Number Acres in Pond _____ Drainage Area in Square Miles _____

Discharge in Second Feet per Square Mile _____

Estimated Storage Million Cubic Feet _____

WORCESTER COUNTY ENGINEER

Inspection of Dams, Reservoir Dams, and Reservoirs

Inspected by M. J. [unclear] Date 12-30-41 Dam No. 11-10

Town Oudley Location Hayden Pond

Owner _____ Use _____

SPILLWAY

El. top abutment _____ El. Crest _____ El. Apron _____ El. St. Bed _____

Width top Abut. _____ Width top Crest _____ Width bottom Sp. way _____

Width flashboards _____ Kind Flashboards _____

El. Flowline Cleanout Pipe _____ Size and Kind Pipe _____

Kind of Foundation under Spillway _____

Condition Pond still drawn down

No new repairs

EMBANKMENT

El. Top _____ El. Natural Ground _____ Width Top _____

Width of Bottom _____ Upstream Slope _____ Downstream Slope _____

Kind of Corewall _____ Riprap _____

Material in Embankment _____ Foundation _____

Condition No leaks

GATES

Location _____

Size _____ Kind _____ El. Flowline _____

Condition Gate open

Evidence of Leaks in Structure _____

Recent Repairs and Date _____

Number Acres in Pond _____ Drainage Area in Sq. Miles _____

Discharge in Second Feet per Square Mile _____

Estimated Storage Million Cubic Feet _____

WORCESTER COUNTY ENGINEER

Inspection of Dams, Reservoir Dams, and Reservoirs

Inspected by J. L. A. Harris Date 12-10-42 Dam No. 19-10

Town Dudley Location Hoyden Res

Owner Stevens Milk Assoc Use Storage

SPILLWAY

El. top Abutment _____ El. Crest _____ El. Apron _____ El. St. Bed _____

Width top Abut. _____ Width top Crest _____ Width bottom Sp. way _____

Width flashboards None Kind Flashboards _____

El. Flowline Cleanout Pipe _____ Size and Kind Pipe _____

Kind of Foundation under Spillway _____

Condition Good - No water over - See log

repair date 19-10

EMBANKMENT

El. Top _____ El. Natural Ground _____ Width Top _____

Width of Bottom _____ Upstream Slope _____ Downstream Slope _____

Kind of Corewall _____ Riprap _____

Material in Embankment Rubble & Earth Foundation _____

Condition _____

GATES

1 - open Location _____

Size _____ Kind _____ El. Flowline _____

Condition good

Evidence of Leaks in Structure see sand leak

on secondary embankment.

Recent Repairs and Date None

Number Acres in Pond _____ Drainage Area in Sq. Miles _____

Discharge in Second Feet per Square Mile _____

Estimated Storage Million Cubic Feet _____

COUNTY OF WORCESTER MASSACHUSETTS
COUNTY ENGINEER

Inspection of Dams, Reservoir Dams, and Reservoirs

Inspected by _____ Date 2-18-44 Dam No. 12

Town Dudley Location _____

Owner _____ Use _____

Material and Type _____

Dam Designed by _____ Constructed by _____ Year _____

SPILLWAY

El. top Abutment _____ El. Crest _____ El. Apron _____ El. Streambed _____

Width top Abutment _____ Width top Crest _____ Width bottom Spillway _____

Width Flashboards carried _____ Kind Flashboards _____

El. Flowline Cleanout Pipe _____ Size and Kind Cleanout Pipe _____

Kind of Foundation under Spillway _____

Condition Good

EMBANKMENT

El. Top _____ El. Natural Ground _____ Width Top _____

Width of Bottom _____ Upstream Slope _____ Downstream Slope _____

Kind of Corewall _____ Riprap _____

Material in Embankment _____ Foundation _____

Condition Good

GATES

Location _____

Size _____ Kind _____ El. Flowline _____

Condition Gate stem is rusted and in poor condition

Gate open probably OK Machinery protected by gate

WHEEL Kind _____ Size _____ Rated H. P. _____

Location _____ Ave. Head _____

Evidence of Leaks in Structure _____

Recent Repairs and Date _____

Topography of Country below Dam Heavy brush & woods

Nature of Buildings and Roads below Dam _____

Number Acres in Pond _____ Drainage Area in Square Miles _____

Discharge in Second Feet per Square Mile _____

Estimated Storage Million Cubic Feet _____

COUNTY OF WORCESTER MASSACHUSETTS
COUNTY ENGINEER

Inspection of Dams, Reservoir Dams, and Reservoirs.

Inspected by R. M. Fulayson Date 12-10-41 Dam No. 1410

Town Dudley Location Hayden Pond
Owner Hayden River Use Stream
Material and Type

Dam Designed by _____ Constructed by RECELY

SPILLWAY
El. top Abutment _____ El. Crest _____ El. Apron _____ El. Streambed 117.5

Width top Abutment _____ Width top Crest _____ Width bottom Spillway _____

Width Flashboards carried _____ Kind Flashboards _____

El. Flowline Cleanout Pipe _____ Size and Kind Cleanout Pipe _____

Kind of Foundation under Spillway _____

Condition Structure ok - cut gravel in spillway
Part 4 - below flow line

EMBANKMENT

El. Top _____ El. Natural Ground _____ Width Top _____

Width of Bottom _____ Upstream Slope _____ Downstream Slope _____

Kind of Corewall _____ Riprap _____

Material in Embankment _____ Foundation _____

Condition Surface for length of 20' under center
of dam

GATES _____ Location _____

Size _____ Kind _____ El. Flowline _____

Condition ok

WHEEL None Kind _____ Size _____ Rated H. P. _____

Location _____ Ave. Head _____

Evidence of Leaks in Structure _____

Recent Repairs and Date _____

Topography of Country below Dam _____

Nature of Buildings and Roads below Dam _____

Number Acres in Pond _____ Drainage Area in Square Miles _____

Discharge in Second Feet per Square Mile _____

Estimated Storage Million Cubic Feet _____

TOWN Dudley

THIS DAM
NEEDS ATTENTION

DAM NO. 14-10

LOCATION Hayden Reservoir

STREAM _____

WORCESTER COUNTY ENGINEERING DEPARTMENT
WORCESTER, MASSACHUSETTS

DAM INSPECTION REPORT

OWNED BY Stevens Line Associates PLACE Dudley USE storage

INSPECTED BY E.V. Meagher LOM DATE Dec. 1, 1947

TYPE OF DAM high earth emb.-downstream stone wall CONDITION fair
s one spillway with concrete crest

SPILLWAY

FLASHBOARDS IN PLACE none RECENT REPAIRS none

CONDITION Good, but new concrete abutments should be built
capacity of spillway about enough for 1973 flood-needs higher pts.
REPAIRS NEEDED _____

EMBANKMENT

RECENT REPAIRS brush should be cut, roots grubbed out in top
and face of embankment. Could raise embankment at least 12 inches.

CONDITION _____

REPAIRS NEEDED See above statement.

GATES

RECENT REPAIRS none

CONDITION gate OK, but should mortar joints in stone
supporting walls of forebay.

REPAIRS NEEDED _____

LEAKS

Good sized leaks exist at gate section-along downstream face
of the embankment wall and embankment.

DATE Dec. 1, 1947

L. O. Mardin
COUNTY ENGINEER

APPENDIX B-16

TOWN Dudley
LOCATION Hayden Reservoir

DAM NO. 14-10
STREAM _____

WORCESTER COUNTY ENGINEERING DEPARTMENT
WORCESTER, MASSACHUSETTS

DAM INSPECTION REPORT

OWNED BY Stevens Linen Associates PLACE Dudley USE Storage

INSPECTED BY LOM DATE Dec. 2, 1958

TYPE OF DAM High earth emb. - Stone wall CONDITION fair to good

SPILLWAY

FLASHBOARDS IN PLACE None RECENT REPAIRS None

CONDITION _____

REPAIRS NEEDED Should raise abts 2'-0" for
increased capacity. or lower spillway crest

EMBANKMENT

RECENT REPAIRS None

CONDITION Sh.

REPAIRS NEEDED Should raise 24"
leaks see below

GATES

RECENT REPAIRS None

CONDITION appears OK

REPAIRS NEEDED _____

LEAKS

HOW SERIOUS 6 inch sized leak at gate section - Also
thru emb at East Dike section DATE Dec. 2, 1958

L.O. Marden
COUNTY ENGINEER

TOWN Dudley DAM NO. 20
LOCATION Hayden Pond STREAM

WORCESTER COUNTY ENGINEERING DEPARTMENT
WORCESTER, MASSACHUSETTS
DAM INSPECTION REPORT

OWNED BY Stevens Union Co PLACE _____ USE NW
INSPECTED BY H. Spafford DATE 11/21/57
TYPE OF DAM Stone Breast Wall CONDITION _____

SPILLWAY

FLASHBOARDS IN PLACE None RECENT REPAIRS None
CONDITION Good
REPAIRS NEEDED None

EMBANKMENT

RECENT REPAIRS None
CONDITION Good
REPAIRS NEEDED None

GATES

RECENT REPAIRS New head screw put in in 1950
CONDITION Good
REPAIRS NEEDED None

LEAKS

HOW SERIOUS 2 Old leaks - one at gate and one at mid point of Embankment - both old - not particularly dangerous

DATE _____
COUNTY ENGINEER _____

TOWN Dudley
LOCATION _____

DAM NO. 116
STREAM _____

WORCESTER COUNTY ENGINEERING DEPARTMENT
WORCESTER, MASSACHUSETTS
DAM INSPECTION REPORT

OWNED BY _____ PLACE _____ USE _____
INSPECTED BY LHS & HPS DATE Sept 13, 1955
TYPE OF DAM _____ CONDITION _____

SPILLWAY

FLASHBOARDS IN PLACE _____ RECENT REPAIRS _____
CONDITION OK
REPAIRS NEEDED _____

EMBANKMENT

RECENT REPAIRS _____
CONDITION OK
REPAIRS NEEDED _____

GATES

RECENT REPAIRS _____
CONDITION Small Gate - lead screw taking out of discharge
REPAIRS NEEDED _____

LEAKS

HOW SERIOUS _____ DATE _____
COUNTY ENGINEER _____

TOWN Dudley DAM NO. N-15-103

LOCATION Watershed between R. "New Pond" STREAM New Pond Brook

on a dirt road

WORCESTER COUNTY ENGINEERING DEPARTMENT
WORCESTER, MASSACHUSETTS

DAM INSPECTION REPORT

Owned by Stevens Lewis Associates Place Dudley Use Storage Pond

Inspected by WOL Date Oct 25, 1963

Type of Dam Earth stone and concrete Condition Poor

SPILLWAY

Flashboards in Place No boards Recent Repairs _____

Condition This concrete stone spillway has a concrete floor

Repairs Needed The height of this spillway is only 2' - very little

headroom. The crest should be lowered at least 2'.

EMBANKMENT

Recent Repairs The existing embankment is 25' high and 24' wide on top

Condition The vertical down stream wall is good except some air stones

Repairs Needed are missing. The existing embankment is also 24' wide

(average) on top. Both these embankments are covered with brush and trees

GATES

Recent Repairs _____

Condition The gate and gate house are good. The gate is open

Repairs Needed The water level on this date is about 6' below the

spillway crest.

LEAKS

How Serious No leaks are visible

DATE: _____ County Engineer: _____

TOWN Dudley DAM NO. 4-104

LOCATION Wardwell Percent Rd STREAM New Pond Brook

New Pond

WORCESTER COUNTY ENGINEERING DEPARTMENT
WORCESTER, MASSACHUSETTS

DAM INSPECTION REPORT

Owned by Same as 14-10 Place Dudley Use Storage pond

Inspected by W.C.L. Date Oct 25, 1963

Type of Dam Earth dike Condition Fair

SPILLWAY

Flashboards in Place _____ Recent Repairs _____

Condition No spillway at this dike

Repairs Needed This is a long earth dike located on the outside of the pond and extends on the left from the main dam

EMBANKMENT

Recent Repairs This embankment is 18' to 20' high - 6' to 8' wide

Condition on top - 1 1/2 to 1 slope - there is some small stone

Repairs Needed repair the upstream slope. It is covered with brush and large trees

GATES

Recent Repairs _____

Condition No gates

Repairs Needed There is a 20' dia' pond 4' deep just below the head of this earth dike. This water probably comes from seepage through this dike

LEAKS

How Serious _____

DATE: _____ County Engineer _____

TOWN Dudley DAM NO. 1416

LOCATION 2500 Wycherly Point Rd STREAM Chayden Pond Brook

New Pond

WORCESTER COUNTY ENGINEERING DEPARTMENT
WORCESTER, MASSACHUSETTS

DAM INSPECTION REPORT

Owned by Stevens Linen Assoc's Place Dudley Use Storage Reservoir

Inspected by FFP-WOL Date May 15, 1964

Type of Dam Earth and Stone Condition Fair

SPILLWAY

Flashboards in Place No boards Recent Repairs _____

Condition Spillway area is too small - more free board should

Repairs Needed be provided - water level is too high

EMBANKMENT

Recent Repairs No recent repairs

Condition Brush and dead trees should be removed from dam

Repairs Needed No maintenance to this dam for many years

Missing stones on downstream wall should be replaced and wall repaired

GATES

Recent Repairs _____

Condition Gate is partly open - gate is located in locked gate house

Repairs Needed _____

LEAKS

How Serious No leaks visible

DATE: _____ County Engineer

TOWN Dudley DAM NO. 1470

LOCATION 100' north - Vermont St STREAM New Pond

200' East Road New Pond

WORCESTER COUNTY ENGINEERING DEPARTMENT
WORCESTER, MASSACHUSETTS

DAM INSPECTION REPORT

Owned by Wheeler Line Associates, Inc Place Mill St Use Storage Pond

Inspected by W.C. Date Aug. 29, 1968

Type of Dam Earth and stone dam Condition Fair to good

SPELLWAY

Flashboards in Place No boards Recent Repairs _____

Condition Provide accurate section on the upstream side of the spillway - flat

Repairs Needed scour spillway. The abutment walls should be extended to the crest
to form a wall. The water level is 1.5' below the crest.

EMBANKMENT

Recent Repairs The downstream wall is 30' high with some of the top stones

Condition missing. There are 3 or 4 leaks visible below this wall.

Repairs Needed (14-10A)
There is a 300' long earth dike Northwest side of the embankment at the
dam. It is 6' to 30' wide and 6' to 15' high - with large trees and brush on top and along
top of the upstream slope. There are 2 or 3 seepage pools below this dike.

GATES

Recent Repairs The small wood gate house is rotted. The gate leaks at the outlet


Condition There is a large leak at the old 2' x 2' canal gate. The old canal

Repairs Needed (14-10B)
is located 20' above the bank - is 500' long or 300' beyond the heel of
the 3' wide, walled canal - the old wheel pit and the old mill site are still in place.

LEAKS

How Serious _____

DATE: _____ County Engineer



TOWN Dudley

DAM NO. 14-10 Hayden Pond

LOCATION _____

STREAM _____

WORCESTER COUNTY ENGINEERING DEPARTMENT
WORCESTER, MASSACHUSETTS

DAM INSPECTION REPORT

Owned by _____

Place _____

Use _____

Inspected by R. J. [unclear]

Date _____

Type of Dam _____

Condition _____

SPILLWAY

Flashboards in Place None

Recent Repairs _____

Condition White paint on 3rd bellows pipe

Repairs Needed None

EMBANKMENT

Recent Repairs _____

Condition _____

Repairs Needed _____

GATES

Recent Repairs _____

Condition _____

Repairs Needed _____

LEAKS

How Serious _____

DATE: 2/11/69

County: _____

INSPECTION REPORT & DATA FOR DAMS

Owner: STEVENS LINEW Assoc. INC
 His Address: MILL ST
 Function of Dam: STORAGE RESEVOIR

Dam No. 14-10
 Town: DUDLEY
 Stream: BROOK
 Pond: HAYDEN POND
 Date: 2/9/72
 By: T. Fichler

Location & Access: 10 MILE WEST ON HAYDEN RD
 FROM JCT OF NIERPOINT & HAYDEN RDS TO
 USGS Quad. WEBSTER Lat. 42-04-15 Long. 72-55-10
 Drain. Ar.: 1.97 Sq. Mi. Ponds: 93 ac.; Res. @ Dam:
 Character of D.A.:

CONDITION RATING
 Structural: GOOD
 Hydraulic: 33' x 1' + 2' x 2.5' GAT
 General: GOOD
 PRIORITY: NONE


Path on 1st 500' before POND.

Estimated Discharge Capacity:


General Description of Dam and Discharge Control:

293' STON MASONRY DAM INCLUDES SPILLWAY (NO SLOTS FOR FLESHBOAT)
 1200'± EARTHEN DAM. ONE LEAK EAST OF GATE.
 MANY LARGE TREES ON DAM & DAM FACES.


Sketch (Not to Scale):



A-A DAM END VIEW



B-B STONE MASONRY SPILLWAY SIDE VIEW



Remarks and Recommendations:



Date: 2/9/72
 By: R. Fichler
 V. P.
 E. M.
 Comment:

Dam No. 3-14-80-10

APPENDIX C

SELECTED PHOTOGRAPHS OF PROJECT

LOCATION PLAN


Location of Photographs

Page No.

C-1

PHOTOGRAPHS


<u>No.</u>	<u>Title</u>	<u>Page No.</u>
1.	Overview of Dam and Dike from Across the Pond	
2.	Crest of Dam from Outlet Works to the Right Abutment	C-2
3.	Intake Channel of the Outlet Works	C-2
4.	Stone Masonry Walls of Outlet Works Intake Channel	C-3
5.	Downstream Face of Dam and Discharge End of Outlet Conduit	C-3
6.	Stone Masonry Wall at Downstream Face of Dam	C-4
7.	Terrain Downstream of Outlet Works Discharge Conduit	C-4
8.	View of Spillway from Upstream	C-5
9.	View of Spillway from Downstream	C-5
10.	Channel Downstream of Spillway	C-6
11.	View Northeast of Station 1+50+ Along Crest of Dam	C-6
12.	View of Upstream Face of Dam Between Stations 3+00+ and 4+00+	C-7
13.	View of Crest of Dam from Station 4+00+ Towards Station 3+00	C-7
14.	Slight Seepage Downstream of Dam at Station 3+50+	C-8
15.	View of Crest of Dike from Dike Station 1+25+ Towards Dike Station 0+00	C-8
16.	View of Upstream Face of Dike Between Dike Station 0+50+ To Station 2+00+	C-9
17.	View of Downstream Face of Dike Between Dike Station 0+50+ To Station 1+50+ and Kettle Pond from Access Road	C-9
18.	Riprap at Upstream Face of Dike at Approximately Station 2+00	C-10
19.	View of Dike Crest Looking North From Dike Station 1+80+	C-10
20.	Small Seepage Pond at Downstream Face of Dike at Approximate Dike Station 2+50+	C-11




APPEND C-1

3 OF DIKE

OLD EXCAVATION




SEE SECTIONS
THIS SHT. (TYP)




KETTLE
POND

NOTES:

1. PLAN SKETCH BASED ON FIELD OBSERVATIONS BY CAMP, DRESSER & MCKEE, INC.
2. ① DENOTES PHOTOGRAPH NUMBER AND DIRECTION OF VIEW.
3. ☞ DENOTES AREA OF OBSERVED SEEPAGE



SECTION A-A ②



SECTIONS

CAMP DRESSER & MCKEE, INC. BOSTON, MASSACHUSETTS	U.S. ARMY ENGINEER DIV. NEW ENGLAND CORPS OF ENGINEERS WALTHAM, MA.
NATIONAL PROGRAM OF INSPECTION OF NON FED. DAMS	
NEW POND DAM SITE PLAN SKETCH	
NEW POND	MASSACHUSETTS
DATE: SEPT. 1978	SCALE: NONE
	APPENDIX C-1



2. CREST OF DAM FROM OUTLET WORKS TO THE RIGHT ABUTMENT.



3. INTAKE CHANNEL OF THE OUTLET WORKS.



4. STONE MASONRY WALLS OF OUTLET WORKS INTAKE CHANNEL.



5. DOWNSTREAM FACE OF DAM AND DISCHARGE
END OF OUTLET CONDUIT.



6. STONE MASONRY WALL AT DOWNSTREAM FACE OF DAM.



7. TERRAIN DOWNSTREAM OF OUTLET WORKS DISCHARGE CONDUIT.



8. VIEW OF SPILLWAY FROM UPSTREAM.




9. VIEW OF SPILLWAY FROM DOWNSTREAM.



10. CHANNEL DOWNSTREAM OF SPILLWAY.




11. VIEW NORTHEAST OF STATION 1+50+ ALONG CREST OF DAM.



12. VIEW OF UPSTREAM FACE OF DAM BETWEEN STATIONS 3+00+ AND 4+00+.



13. VIEW OF CREST OF DAM FROM STATION 4+00+ TOWARDS STATION 3+00.



14. SLIGHT SEEPAGE DOWNSTREAM OF DAM AT STATION 3+50₊.



15. VIEW OF CREST OF DIKE FROM DIKE STATION 1+25₊ TOWARDS
DIKE STATION 0+00.



16. VIEW OF UPSTREAM FACE OF DIKE BETWEEN DIKE STATION
0+50+ TO STATION 2+00+ FROM DAM STATION 3+00.



17. VIEW OF DOWNSTREAM FACE OF DIKE BETWEEN DIKE STATIONS
0+50+ AND 1+50+ AND KETTLE POND FROM ACCESS ROAD.



19. VIEW OF DIKE CREST LOOKING NORTH FROM
DIKE STATION 1+80+



18. RIPRAP AT UPSTREAM FACE OF DIKE AT
APPROXIMATELY DIKE STATION 2+00.




20. SMALL SEEPAGE POND AT DOWNSTREAM FACE OF DIKE
AT APPROXIMATELY DIKE STATION 2+50.

APPENDIX D
OUTLINE OF DRAINAGE AREA AND
HYDRAULIC COMPUTATIONS

Page No.

COMPUTATIONS

Drainage Area Map	D-1
Drainage Area and Surface Areas	D-2
Field Sketch of Dam	D-3
Elevations and Storage Determination	D-4
Size Classification, Hazard Potential and Test Flood Determination	D-5
Spillway Rating Curve	D-6
Test Flood Inflow Determination	D-7
Surcharge-Storage Routing	D-11
Stage-Discharge and Storage Curves	D-12
Tailwater Analysis	D-13
Dam Failure Analysis	D-16



CAMP DRESSER & MCKEE Inc.
 Consulting Engineers
 Boston, Mass.



**NEW POND DAM
 DRAINAGE AREA MAP**
 SCALE: 1" = 2000'

APPENDIX D-1

Scale of Mappings: 1"=2000' ∴ 1 Sq. in x 91.63 = Acres (A)
A ÷ 640 = mi²

DRAINAGE AREA.

1. 14.17
2. 28.40 } 14.23 Ave = 14.20 Sq in = 1303.9 Acres = 2.037 Sq. mi

WATER SURFACES

EL. 531

1. 0.82
2. 1.62 } 0.80 Ave = 0.81 Sq in. = 74A = 0.116 mi²

EL. 540

1. 1.34
2. 2.59 } 1.25 Ave = 1.30 in² = 118.9 A = 0.186 mi²

EL. 550


1. 2.03
2. 4.04 } 2.01 Ave = 2.02 in² = 185.5 A = 0.290 mi²

LAMP, DRESSER & MCKEE
Environmental Engineers
Boston, Mass.

CLIENT _____
PROJECT _____
DETAIL _____

JOB NO _____
DATE CHECKED 9-15-78
CHECKED BY J.E. Downing


PAGE 6 of 6
DATE Sept. 14, 1978
COMPUTED BY J.F. Miller



APPENDIX D-3

ELEVATIONS

Spillway Crest 531
Top of Dam 533
Toe of Dam @ spillway 513
Embankment 533




Water Surface el 531 from USGS topo assumed to be crest el. Other elevations obtained from field measurements relative to crest

SURFACE AREAS

@ el 531: 74.4 Ac = 0.116 mi² (spillway crest)
540: 118.9 Ac = 0.186 mi²
550: 185.5 Ac = 0.290 mi²

STORAGE CAPACITIES

@ spillway crest el 531 $V = \frac{1}{3}AH = \frac{1}{3}(74.4)(12) = 297.6 \text{ Ac-ft}$
el 540 $V = \frac{(118.9 + 74.4)}{2}(9) + 297.6 = 1167 \text{ Ac-ft}$
el 550 $V = \frac{(185.5 + 118.9)}{2}(10) + 1167 = 2689 \text{ Ac-ft}$



SIZE CLASSIFICATION

Hydraulic Height: Top of Embankment = 533.0
Toe of Dam @ Spillway = 513.0
20'

Size Classification based on height = Small

Storage Capacities

@ El 531.0 = 2976 Ac-ft
@ El 533.0 = 500 Ac-ft

Size classification based on storage is small

∴ Size classification is Small

HAZARD CLASSIFICATION

Discharge from New Pond is conveyed through a large swamp area adjacent to New Pond, through Wallis Pond and Larner Pond. These storage areas should significantly reduce flows from New Pond. There are a few houses around the latter named ponds. There are no other developments in this downstream area. The existing homes in this area may experience minor water damage in the event of a dam failure. The Dudley St - Oxford, Charlton Rd intersection may be overtopped by floodwaters but should not be washed out.

∴ hazard classification is low

TEST FLOOD

Small size + low hazard → 50 yr to 100 yr



DRAINAGE AREA

1304 acres = 2.04 mi². The drainage area is sparsely populated. The terrain is hilly with some upland marshy areas. There is an abundance of brush and trees throughout the area. The combined areas of New Pond + Hayden Pond occupy about 5.6% of the D.A.

CAMP DRESSER & MCKEE
 Environmental Engineers
 Boston, Mass.

CLIENT Coast of Engineers Dam Inspection 380-5-01
 PROJECT New Pond Dam DATE CHECKED 20 Feb 1979
 DETAIL Spillway Rating Curve CHECKED BY JW

PAGE 4
 DATE Jan 17 1979
 COMPUTED BY CF Miller



APPENDIX D-6

100 YR INFLOW DETERMINATION

Use SCS TP-149 Method for Estimating Volume and Rate of Runoff in Small Watersheds

Drainage Area = 2.04 mi²

Slope = $(610 - 548) / 7760 = 0.0078$

Lag = $2^{0.8} (S+1)^{0.7} / 1900 (Y)^{0.5}$ where $L = 11,400 \text{ ft}$
 $Y = 0.78$
 $S = 100 / CN = 10$

Curve Number (CN) Analysis

<u>Land Use</u>	<u>Area</u>	<u>CN</u>	<u>Area x CN</u>
Pond	73.5 ac.	100	7350
Meadow	1232 ac.	60	73,920
Woods			
	1305.5		81,270

Wt. CN = $81,270 / 1,305.5 = 62$

$S = 100 / 62 = 10 = 6.129$

Lag = $(11,400)^{0.8} (6.129 + 1)^{0.7} / 1900 (0.78)^{0.5} = 4.15 \text{ hrs.}$

AD = $0.4 L = 0.4 \times 4.15 \text{ hrs} = 1.66 \text{ hrs.}$

TAD = $7 \times 1.66 = 11.62 \text{ hrs.}$

Assume midpoint @ max. increment of runoff is 11.62 hrs,
then start of storm = $11.62 \text{ hrs} - 4.15 (1.66) = 4.41 \text{ hrs}$
and time @ TAD = $4.41 + 11.62 = 16.03$

100-yr. Flood Flow Determination - SCS Method

These comp. by J.E. Denning: Drainage Area = 2.04 sq. mi.

$P_{34} = 6.75$ ^{Rankin}
for 100-yr. storm


$CK = 62$ (say 65) $S = \frac{1000}{62} - 10 = 6.129$

$Lag = \frac{(4.200)^{0.89} (6.129)^{0.7}}{1300^{0.73}} = 4.15$ hrs.

$\Delta D = 0.4L = 0.4(4.15 \text{ hrs.}) = 1.66$ hrs.

$T_{ad} = 11.62$ hrs. $11.62 \text{ hrs.} - 0.5(1.66) = 10.78$ hrs.

Time (hrs.)	P_{34} (inches)	Mass P (inches)	Mass Q (inches)
4.0	0.048	0.324	0.135
6.0	0.080	0.540	0.086
8.0	0.120	0.840	0.030
9.0	0.147	0.992	0.009
9.5	0.163	1.100	0.003
10.0	0.181	1.222	0.000026
10.5	0.204	1.377	0.0036
11.0	0.235	1.586	0.0200
11.5	0.283	1.910	0.0687
11.75	0.307	2.612	0.2556
12.0	0.663	4.475	1.1256
12.5	0.735	4.961	1.4143
13.0	0.772	5.211	1.5701
14.0	0.820	5.535	1.7788
16.0	0.880	5.940	2.049
20.0	0.952	6.426	2.387



CAMP DRESSER & MCKEE
Environmental Engineers
Boston, Mass.

CLIENT COE
PROJECT NEW POND
DETAIL _____

JOB NO. 30-5-01
DATE CHECKED 2-16-77
CHECKED BY [Signature]

PAGE 8
DATE 16 Feb 77
COMPUTED BY [Signature]

100 yd Flow VIA SCS

11.88 - 4.5 (1.66) = 4.41

1	2	3	4	5	6	7
Increment	Time (hr)	Mass R.O. (lb) <small>from curve</small>	ΔQ (in)	Δg^* (cfs)	Y	Y (Δg) (cfs)
	4.41	.35				
ΔD_1	6.07	.50	.15	29.7	.2	5.94
ΔD_2	7.73	.75	.25	49.5	.4	19.80
ΔD_3	9.39	1.05	.30	59.5	.6	35.70
ΔD_4	11.05	1.58	.53	105.1	.8	84.08
ΔD_5	12.71	5.05	3.47	688.0	1.0	688.00
ΔD_6	14.37	5.60	.55	109.0	.73	72.67
ΔD_7	16.03	5.90	.30	59	.73	19.67
						Q = 925.8 cfs

$$* \Delta g = \frac{48 + A(\Delta Q)}{\frac{\Delta D}{2} + L} = \frac{(48 + 2.04)(\Delta Q)}{\left(\frac{1.66}{2}\right) + 4.15}$$

$$= 198.265 \Delta Q$$

SURCHARGE - STORAGE ROUTING

@ $Q = 925 \text{ cfs}$ $el = 533.45$

Surcharge storage = $\frac{533.45 - 531}{.0104} = 235 \text{ Ac-ft}$

$STOR_1 = \frac{(235)(12)}{1304 \text{ Ac}} = 2.17 \text{ in}$

$Q_{p_2} = 925 \left(1 - \frac{2.17}{8}\right) = 570 \text{ cfs}$

@ 570 cfs $el = 533.35$

Surcharge storage = $\frac{533.35 - 531}{.0104} = 225 \text{ Ac-ft}$

$STOR_2 = \frac{(225)(12)}{1304} = 2.08 \text{ in}$

$STOR_{avg} = \frac{2.08 + 2.17}{2} = 2.12 \text{ in}$


$Q_{p_3} = 900 \left(1 - \frac{2.12}{8}\right) = 581 \text{ cfs}$

@ 581 cfs $el = 533.35$ OK

Top of Embankment 533

Surcharge El 533.35

100 yr Test Flood, after routing, would overtop dam by .35 ft (4.2 inches). As a practical matter, the spillway would be adequate for the 100 yr event. Technically, the spillway is inadequate.




TAILWATER ANALYSIS

Tailwater will be controlled by a storage area between New Pond and Oxford Rd. Mosquito Pond is located in this area.

@ el 503 surface area = 8.7 acres = 0 Ac-ft
el 510 = 30 acres = 142 Ac-ft
520 = 65 acres = 627 Ac-ft

Develop Rating Curve for Culvert under Oxford Rd

2 - 60' long 42" ϕ ACP Culverts assume $s = 0.00035$



Use CMP Nomograph

$$\text{weir flow} = CLH^{3/2} = (2.5)(500)(H)^{3/2} = 1250(H)^{3/2}$$


el	Q (from nomograph)	2 pipes	Weir Q	Total Q
507.5	49.5 cfs	x 2	-	99 cfs
508.5	69 cfs	x 2	-	138
510	84 cfs	x 2	-	168
510.5	95	x 2	(1250)(.5) ^{3/2}	632
511	102	x 2	(10) ^{3/2}	1454
511.2	106	x 2	(12) ^{3/2}	1855
511.5	110	x 2	(15) ^{3/2}	2516
512	114	x 2	(2) ^{3/2}	3764
513	122	x 2	(3) ^{3/2}	6739
513.5	125	x 2	(3.5) ^{3/2}	8435
514	130	x 2	(4) ^{3/2}	10260
514.5	135	x 2	(4.5) ^{3/2}	12202

CAMP DRESSER & MCKEE
Environmental Engineers
Boston, Mass.

CLIENT Corps of Engineers
PROJECT _____
DETAIL New Pond

JOB NO. 380-5-01
DATE CHECKED 1-12-79
CHECKED BY CE Fuller
Copied by RW

PAGE 12
DATE 16 Feb 79
COMPUTED BY JW




APPENDIX D-14

CAMP DRESSER & MCKEE
Environmental Engineers
Boston, Mass.

CLIENT COE
PROJECT _____
DETAIL NEW POND

JOB NO. 380-5-01
DATE CHECKED 4-17-78
CHECKED BY [Signature]

PAGE 13
DATE 13 Oct 1978
COMPUTED BY JW



Route Flow through Storage Area STOR₁ = 4 inches

$Q_p = 2000 \text{ cfs}$

Surcharge Ht to pass $Q_p = \text{el } 511.1$ Vol of surcharge storage = $\frac{511.1 - 510}{0.0206} + 142 = 195 \text{ Ac-Ft}$

$Q_p = 2000 (1 - \frac{1}{10}) = 1579 \text{ cfs}$

Surcharge Ht to pass $1579 \text{ cfs} = \text{el } 510.8$

Vol of surcharge storage at el $510.8 = \frac{510.8 - 510}{0.0206} + 142 = 180 \text{ Ac-Ft}$

AVG STOR = $\frac{195 + 180}{2} = 188 \text{ Ac-Ft}$

$\text{el} = (188 - 142)(0.0206) + 510 = 510.9$

This elevation is well below toe elevation of spillway. Spillway is able to discharge freely.

Toe of dam at el 513.0. No information is available on down stream channel geometry. Based on topo map analysis and above analysis, the is no backwater expected to influence spillway discharge.

Copied by R. W.

Dam Failure Analysis

Assume dam fails in area of max. height $L = 168'$
Assume water elevation at failure elev 533

$$S = 440 \text{ Ac-ft. } W_b = .4(168) = 67 \quad Y_0 = 533 - 513 = 20'$$

$$Q_p = \frac{8}{27} W_b \sqrt{g} \cdot Y_0^{3/2} = \frac{8}{27} (67) (\sqrt{32.2}) (20)^{3/2} \approx 10,000 \text{ cfs}$$

First Reach: Dam to Oxford Rd

for Q_p , stage = 513.9 $Y_0 | Y_1 = 340 \text{ Ac-ft.}$

$$\text{Trial } Q_{p2} = Q_p (1 - \frac{Y_1}{Y_0}) = 10000 (1 - \frac{340}{440}) = 2273 \text{ cfs}$$

$$\therefore Y_2 = 214 \text{ Ac-ft. } \text{Avg } Y_1 + Y_2 = \frac{(340 + 214)}{2} = 277 \text{ Ac-ft.}$$

$$Q_{p2} = 10,000 (1 - \frac{277}{440}) = 3705 \text{ cfs } \text{elev } 512.0 \text{ at Oxford Rd elev } 510'$$


Flood may do minor damage to one house as it flows over Oxford Rd to Wallis Pond.

Wallis Pond

Compute pressure flow via C.M.P. Nomograph.

2 - 54" ϕ C.M.P. Pipes 45' long

$$(2)(200) = 400 \text{ cfs}$$



Flow culverts can pass w/o overtopping Charlton Rd.

From topo map: Storage available in Wallis Pond is about double that provided by Mosquito Pond.

$$Q_1 = 3705 \text{ cfs } \text{stage} = 506.5 \text{ in Wallis Pond}$$

$$\text{Assume can store } 3' \text{ to elev. } 509.5 \quad (3 \text{ ac})(3)2 = 186 \text{ Ac-ft}$$

$$Q_{p2} = 3705 (1 - \frac{186}{440}) = 2139 \text{ cfs}$$

Flow overtops Charlton Rd for a length of about 1000 ft.

$$2139 - 400 = 1739 \text{ cfs in weir flow } H = \sqrt[3]{\frac{Q^2}{CL}} = \sqrt[3]{\frac{1739^2}{2.5(1000)}} = 0.8 \text{ ft.}$$

No structures are disturbed as Q flows into Lerner Pond. Storage available in Lerner Pond is a bit greater than that available in Wallis Pond. No data is available on dams on Lerner Pond. However, from previous analysis on upstream ponds, it is assumed enough storage is available in Lerner Pond to contain and abate the remaining dam failure flow with no damage to be expected further downstream.

APPENDIX E
INFORMATION AS CONTAINED IN
THE NATIONAL INVENTORY OF DAMS

AD-A145 347 NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS NEW 2/2
POND DAM (MA 0011) (U) CORPS OF ENGINEERS WALTHAM MA
NEW ENGLAND DIV MAR 79

UNCLASSIFIED


F/G 13/13 NL



END

FBI

DIC



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:

NEDED

MAY 29 1979

Honorable Edward J. King
Governor of the Commonwealth of
Massachusetts
State House
Boston, Massachusetts 02133

Dear Governor King:


I am forwarding to you a copy of the New Pond Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts. In addition, a copy of the report has also been furnished the owner, Stevens Linen Associates, Inc., Box 220, Webster, Massachusetts 01570, ATTN: Mr. Robert Javery, Plant Engineer.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Quality Engineering for your cooperation in carrying out this program.

Sincerely yours,


JOHN P. CHANDLER
Colonel, Corps of Engineers
Division Engineer

Incl
As stated



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:

NEDED

MAY 29 1979

Honorable Edward J. King
Governor of the Commonwealth of
Massachusetts
State House
Boston, Massachusetts 02133

Dear Governor King:


I am forwarding to you a copy of the New Pond Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts. In addition, a copy of the report has also been furnished the owner, Stevens Linen Associates, Inc., Box 220, Webster, Massachusetts 01570, ATTN: Mr. Robert Javery, Plant Engineer.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Quality Engineering for your cooperation in carrying out this program.

Sincerely yours,


JOHN P. CHANDLER
Colonel, Corps of Engineers
Division Engineer

Incl
As stated



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:

NEDED

MAY 29 1979

Honorable Edward J. King
Governor of the Commonwealth of
Massachusetts
State House
Boston, Massachusetts 02133

Dear Governor King:


I am forwarding to you a copy of the New Pond Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts. In addition, a copy of the report has also been furnished the owner, Stevens Linen Associates, Inc., Box 220, Webster, Massachusetts 01570, ATTN: Mr. Robert Javery, Plant Engineer.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Quality Engineering for your cooperation in carrying out this program.

Sincerely yours,


JOHN P. CHANDLER
Colonel, Corps of Engineers
Division Engineer

Incl
As stated



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED-E

MAY 29 1979

Mr. Anthony D. Cortese, Commissioner
Department of Environmental Quality
Engineering
Commonwealth of Massachusetts
100 Cambridge Street
Boston, Massachusetts 02202

Dear Commissioner Cortese:

Forwarded herewith for your information and use is a copy of the Inspection Report on New Pond Dam. This inspection was performed in accordance with Public Law 92-367 under the direction of the Corps of Engineers. Copies of the finished report have been forwarded to the Governor and the owner. We thank you for your cooperation and assistance in carrying out this program and hope this report will help you to develop an effective dam safety program.

Sincerely yours,

A handwritten signature in cursive script that reads "Joe E. Fryar".

JOE E. FRYAR
Chief, Engineering Division

Incl
As stated



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
NEEDED-^ATTENTION OF:
-E

MAY 29 1979

Mr. Robert Javery, Plant Engineer
Stevens Linen Associates, Inc.
Box 220
Webster, Massachusetts 01570

Dear Mr. Javery:

Forwarded herewith for your information and use is a copy of the Inspection Report on the New Pond Dam. This inspection was made under the authority of Public Law 92-367 by the firm of Camp, Dresser & McKee, Inc., Boston, Massachusetts under the direction and supervision of the Corps of Engineers. Copies of the finished report have been forwarded to the Governor and the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts.

Section 7 of the report contains an evaluation and recommendations. If you have any questions concerning this report, we suggest that you contact the Department of Environmental Quality Engineering first. Then, if there are further questions contact the Project Management Branch, Engineering Division of this office. We thank you for your cooperation and assistance in carrying out this program.

Sincerely yours,

A handwritten signature in cursive script that reads "Joe B. Fryar".

JOE B. FRYAR
Chief, Engineering Division

Incl
As stated