

AD-A154 501

NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
LOWER PORTER POND DAM. (U) CORPS OF ENGINEERS WALTHAM
MA NEW ENGLAND DIV JAN 80

1/1

UNCLASSIFIED


F/G 13/13

NL

END

FILMED

211



NATIONAL BUREAU OF STANDARDS
MICROCOPY RESOLUTION TEST CHART

AD-A154 501

TAUNTON RIVER BASIN
BROCKTON, MASSACHUSETTS

LOWER PORTER POND DAM
MA 00424

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

DTIC FILE COPY



DTIC
ELECTE
JUN 3 1985
S D E

DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASS. 02154

This document has been approved
for public release and sale; its
distribution is unlimited.

JANUARY 1980

Original contains color
plates: All DTIC reproductions
will be in black and
white.

85 5 20 103

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

ADA 154 501

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER MA 00424	2. GOVT ACCESSION NO	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Lower Porter Pond Dam NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS		8. CONTRACT OR GRANT NUMBER(s)
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE January 1980
		13. NUMBER OF PAGES 48
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		16a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) "Original contains color plates: All DTIC reproduct- ions will be in black and white"		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Taunton River Basin Brockton, Massachusetts Beaver Brook		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) Lower Porter Dam is an ill- defined earth embankment about 200 ft. long with a maximum height of about 12 ft. and a top width averaging 15 ft. The dam appears to be in fair condition. With a classification size of small and a hazard potential of significant, the recommended range for test flood is $\frac{1}{2}$ og the Probable Maximum Flood. The owner should implement various operat' al and maintenance procedures.		



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF

NEDED

MAY 19 1990

Honorable Edward J. King
Governor of the Commonwealth of
Massachusetts
State House
Boston, Massachusetts 02133

Dear Governor King:

Inclosed is a copy of the Lower Porter Pond Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts. In addition, a copy of the report has also been furnished the owner, the city of Brockton.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Quality Engineering for your cooperation in carrying out this program.

Sincerely,


MAX B. SCHEIDER

Colonel, Corps of Engineers
Division Engineer

Incl
As stated

LOWER PORTER POND DAM

MA 00424

TAUNTON RIVER BASIN
BROCKTON, MASSACHUSETTS

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM



Accession For	
NTIS GRA&I	
DTIC TAB	
Unannounced	
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or
AY	Special

NATIONAL DAM INSPECTION PROGRAM
PHASE I INSPECTION REPORT

Identification No.: MA 00424
Name of Dam: Lower Porter Pond Dam
Town: Brockton
County and State: Plymouth, Massachusetts
Stream: Beaver Brook
Date of Inspection: October 17, 1979

BRIEF ASSESSMENT

Lower Porter Pond Dam is an ill-defined earth embankment approximately 200 feet long with a maximum height of about 12 feet and a top width averaging 15 feet. The upstream slope, which is capped with a 2-foot high parapet wall, is unknown and the downstream slope is about 2H:1V. The broad-crested stone masonry service spillway is located near the right abutment. The broad-crested stone masonry auxiliary spillway is situated about 60 feet to the right of the service spillway. The dam was constructed in 1940 for the City of Brockton park development program and is currently used for recreational purposes.

The dam appears to be in fair condition. Roots of large trees growing on the dam crest may increase the seepage potential and high winds may dislodge the trees removing significant portions of embankment material. The absence of grass cover on a portion of the dam crest exposes the embankment to undesirable surface erosion.


Lower Porter Pond Dam has a maximum storage capacity of approximately 54 acre-feet and a maximum height of about 12 feet. Therefore, the dam is classified in the "Small" size category. Approximately 35 inhabitable structures are located downstream of Thirty Acre Pond, which is located immediately downstream of Lower Porter Pond. A densely populated urban neighborhood is located further downstream. A failure of Lower Porter Pond dam could cause appreciable property damage but little or no loss of life in the downstream communities. Therefore, the dam is classified in the "Significant" hazard category. The recommended range for the test flood for a "Small size, "Significant" hazard dam is from the 100-year flood to one-half of the Probable Maximum Flood (PMF). The selected test flood for this structure is one-half of the PMF.

The test flood peak inflow to Lower Porter Pond was computed as 2,510 cfs. The routed test flood outflow of 2,505 cfs overtops the embankment by 1.2 feet. The spillway system is capable of discharging 488 cfs prior to overtopping of the embankment, which is about 19 percent of the routed test flood outflow.

Within one year after receipt of the Phase I inspection report, the Owner, the City of Brockton, should retain the services of a registered professional engineer, experienced in the design and construction of dams, for the following purposes: (1) detailed hydrologic and hydraulic analyses should be performed to assess the need for increasing the project discharge capacity; and (2) a study should be made to examine the possibility of Waldo Lake (upstream of Lower and Upper Porter Pond) overflowing the area along the D.W. Field East Parkway and to evaluate the consequences of such an occurrence; (3) the trees and their root systems should be removed from the embankment to the extent possible and the voids in the embankment backfilled with appropriate compacted embankment materials; and (4) the seismic stability of the dam should be investigated.


In addition, the Owner should implement the following operational and maintenance procedures: (1) the bare spots on the embankment crest should be covered with suitable vegetation and protected from pedestrian traffic; (2) erosion protection should be provided for the upstream slope of the embankment; (3) the operating condition of the pond drain sluice gate should be determined and the gate should be repaired if necessary; (4) a program of annual periodic technical inspection should be instituted; and (5) a formal surveillance and flood warning plan, including round-the-clock monitoring during heavy precipitation, should be developed.

O'BRIEN & GERE ENGINEERS, INC.



Date 22 FEB 1980


This Phase I Inspection Report on Lower Porter Pond Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.



RICHARD DIBUONO, MEMBER
Water Control Branch
Engineering Division



ARAMAST MAHTESIAN, MEMBER
Foundation & Materials Branch
Engineering Division



CARNEY M. TERZIAN, CHAIRMAN
Design Branch
Engineering Division

APPROVAL RECOMMENDED:



JOE B. FRYAR
Chief, Engineering Division

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

The Phase I Investigation does not include an assessment of the need for fences, gates, no-trespassing signs, repairs to existing fences and railings and other items which may be needed to minimize trespass and provide greater security for the facility and safety to the public. An evaluation of the project for compliance with OSHA rules and regulations is also excluded.

TABLE OF CONTENTS

<u>SECTION</u>	<u>PAGE</u>
Letter of Transmittal	
Brief Assessment	
Review Board Page	
Preface	i
Table of Contents	ii-iv
Overview Photo	v
Location Map	vi

REPORT

1. PROJECT INFORMATION

1.1	General	1-1
	a. Authority	1-1
	b. Purpose of Inspection	1-1
1.2	Description	1-1
	a. Location	1-1
	b. Description of Dam and Appurtenances	1-2
	c. Size Classification	1-2
	d. Hazard Classification	1-2
	e. Ownership	1-2
	f. Operator	1-2
	g. Purpose of Dam	1-3
	h. Design and Construction History	1-3
	i. Normal Operational Procedure	1-3
1.3	Pertinent Data	1-3
	a. Drainage Area	1-3
	b. Discharge at Damsite	1-3
	c. Elevation	1-4
	d. Reservoir	1-4
	e. Storage	1-4
	f. Reservoir Surface	1-4
	g. Dam	1-4
	h. Diversion and Regulating Tunnel	1-5
	i. Spillway	1-5
	j. Regulating Outlets	1-5

TABLE OF CONTENTS (Con't)

<u>SECTION</u>	<u>PAGE</u>
2. ENGINEERING DATA	
2.1 Design Data	2-1
2.2 Construction	2-1
2.3 Operation	2-1
2.4 Evaluation	2-1
a. Availability	2-1
b. Adequacy	2-1
c. Validity	2-1
3. VISUAL INSPECTION	
3.1 Findings	3-1
a. General	3-1
b. Dam	3-1
c. Appurtenant Structures	3-1
d. Reservoir Area	3-2
e. Downstream Channel	3-2
3.2 Evaluation	3-2
4. OPERATIONAL AND MAINTENANCE PROCEDURES	
4.1 Operational Procedures	4-1
a. General	4-1
b. Description of Any Warning System in Effect	4-1
4.2 Maintenance Procedures	4-1
a. General	4-1
b. Operating Facilities	4-1
4.3 Evaluation	4-1
5. EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES	
5.1 General	5-1
5.2 Design Data	5-1
5.3 Experience Data	5-1
5.4 Test Flood Analysis	5-1
5.5 Dam Failure Analysis	5-2

TABLE OF CONTENTS (Con't)

<u>SECTION</u>	<u>PAGE</u>
6. EVALUATION OF STRUCTURAL STABILITY	
6.1 Visual Observations	6-1
6.2 Design and Construction Data	6-1
6.3 Post-Construction Changes	6-1
6.4 Seismic Stability	6-1
7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	
7.1 Dam Assessment	7-1
a. Condition	7-1
b. Adequacy of Information	7-1
c. Urgency	7-1
7.2 Recommendations	7-1
7.3 Remedial Measures	7-2
7.4 Alternatives	7-2

APPENDICES

APPENDIX A - INSPECTION CHECKLIST	A-1 to A-8
APPENDIX B - ENGINEERING DATA	B-1 to B-5
APPENDIX C - PHOTOGRAPHS	C-1 to C-6
APPENDIX D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS	D-1 to D-31
APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS	



AN OVERVIEW OF THE LOWER PORTER POND DAM. (10/17/79)



AN OVERVIEW OF THE LOWER PORTER POND DAM. (10/17/79)

SECTION 7

ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

7.1 Dam Assessment

a. Condition. The visual observations and review of the available information indicate that Lower Porter Pond Dam is in fair condition. The roots of trees growing on the dam crest may increase the seepage potential and high winds may dislodge the trees removing significant portions of embankment material. The absence of grass cover on a portion of the dam crest exposes the embankment to undesirable surface erosion.

The test flood peak inflow to Lower Porter Pond was computed as 2,510 cfs. The routed test flood outflow of 2,505 cfs overtops the embankment by 1.2 feet. The spillway system is capable of discharging 488 cfs prior to overtopping of the embankment, which is about 19 percent of the routed test flood outflow. A failure of the dam would cause a rise in stream elevation of approximately 1.1 feet at the downstream damage area which could result in appreciable property damage but little or no loss of life.

b. Adequacy of Information. The available information together with the visual inspection data are adequate for a Phase I assessment of Lower Porter Pond Dam.

c. Urgency. Further investigations and remedial measures should be implemented within one year of receipt of this Phase I Inspection Report.

7.2 Recommendations

The following recommendations should be implemented by a registered professional engineer experienced in the design and construction of dams.

1) Detailed hydrologic and hydraulic analyses should be performed to assess the necessity for increasing the project discharge capacity.

2) It appears that Waldo Lake, upstream of Lower and Upper Porter Pond, could overflow in the area along the D. W. Field East Parkway prior to overtopping the dam crest. A study should be made to examine this possibility and to evaluate the consequences of such an occurrence.

3) The trees and their root systems should be removed from the embankment to the extent possible and the voids in the embankment replaced with appropriate compacted embankment materials.

4) The seismic stability of the dam should be investigated utilizing conventional equivalent static load methods.

SECTION 6

STRUCTURAL STABILITY

6.1 Visual Observations

The roots of trees growing on the dam crest could provide increased seepage potential through the embankment. High winds could dislodge the trees and their root systems causing significant losses of embankment material. The roots of the deciduous tree growing within two feet of the eastern service spillway training wall may destroy the masonry joint material and cause dislocation of individual stones. The loss of grass cover on the dam crest exposes the embankment to surface erosion which might lead to a reduction of the effective top of dam elevation.

6.2 Design and Construction Data

No information was available concerning stability analyses, seepage computations, or embankment and foundation material properties.

6.3 Post Construction Changes

No post construction changes have been performed at this site.

6.4 Seismic Stability

Lower Porter Pond Dam is located in Seismic Zone 3 on the "Seismic Zone Map of Contiguous States." Therefore, according to the Recommended Guidelines for Safety Inspection of Dams, a seismic stability analysis should be performed as recommended in Section 7.

the east of Waldo Lake, noted in paragraph 5.1, were not included in the routing procedures.

The test flood peak inflow to Lower Porter Pond was computed as 2,510 cfs. The routed test flood outflow of 2,505 cfs overtops the embankment by 1.2 feet. The spillway system is capable of discharging 488 cfs prior to overtopping of the embankment, which is about 19 percent of the routed test flood outflow.

5.5 Dam Failure Analysis

A failure of the embankment was simulated by the HEC-1-DB computer program assuming a 20-foot wide and 7-foot deep breach with vertical side slopes developing within one hour. The failure is assumed to occur with the reservoir surface at the top of dam elevation. The resulting outflow was routed to the damage center, which was assumed to be the community of approximately 35 homes downstream of Thirty Acre Pond. The channel cross-section utilized in the computer program for the hazard area was taken at a point 1,200 feet downstream of Thirty Acre Pond and is shown on page D-12. The increase in stream depth at this location was computed to be 1.1 feet. This depth of flow could cause appreciable property damage and little or no loss of life in the downstream damage center.

SECTION 5

EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES

5.1 General

Lower Porter Pond Dam has an elongated watershed about 4 miles long and 0.9 miles wide. The drainage area is wooded with some residential developments and low-lying marshes in the upper reaches. The topography ranges from Elev. 250 to Elev. 160 at the normal pool surface. There are three impoundments upstream of Lower Porter Pond: Brockton Reservoir, Waldo Lake and Upper Porter Pond. The normal pool storage capacities of these three impoundments are about 190, 180 and 28 acre-feet, respectively. It was noted during the visual inspection that the area east of Waldo Lake may be lower in elevation than the top of the dam, thus forming a saddle about 2,000 feet long. Therefore, large inflows into Waldo Lake might be diverted over this saddle into the adjacent watershed. This would in turn reduce the impact of the selected test flood upon Lower Porter Pond Dam and its downstream hazard area.

5.2 Design Data

Neither hydraulic nor hydrologic design data are available for Lower Porter Pond Dam.

5.3 Experience Data

There are no records of high reservoir pools or dam overtoppings at this site.

5.4 Test Flood Analysis

The recommended test flood range for a "Small" size, "Significant" hazard dam is from the 100-year flood to one-half of the Probable Maximum Flood (PMF). Due to the potential for property damage and the possibility of loss of life (although remote) in the downstream damage center, the selected test flood is one-half of the PMF.

Hydrologic and hydraulic calculations were performed with the assistance of the HEC-1-DB computer program. The flood hydrographs were constructed from the Snyder unit hydrographs using average coefficients, an initial infiltration of zero and a constant loss rate of 0.05 inches per hour. The Hop Brook Adjustment Factor was used to reduce the Probable Maximum Precipitation based on the drainage area. The routing sequence consisted of dividing the watershed into sub basins for each impoundment and routing the inflow hydrographs through each reservoir. Stage vs. discharge and stage vs. storage relationships above the spillway crest and the top of the dam were developed for all five dams in the system to obtain outflow hydrographs. All impoundments were assumed to be at their respective spillway crest elevations at the beginning of the storm event. Possible overflow effects to

SECTION 4

OPERATIONAL AND MAINTENANCE PROCEDURES

4.1 Operational Procedures

a. General. Based upon information supplied by the City of Brockton and the Massachusetts DEQE, and that obtained through subsequent conversations with Mr. John Dorgan Sr., Park Commissioner, no formal operating procedures have been established for operation of Lower Porter Pond Dam.

b. Description of Any Warning System in Effect. According to Mr. Dorgan, no flood warning system is in effect for Lower Porter Pond Dam.

4.2 Maintenance Procedures

a. General. According to Mr. Dorgan, the grass on the embankment crest is cut on a regular basis during the growing season.

b. Operating Facilities. According to Mr. Dorgan, the outlet conduit sluice gate is operable and no formal maintenance program is in effect at this site.

4.3 Evaluation

There are no operational procedures in effect at this site. Recommendations for improving these conditions are given in Section 7.3.

missing at the time of inspection. The outlet end of this pipe appeared to be free of debris and was partially submerged.

d. Reservoir Area. The area surrounding the pond consists primarily of well-maintained grass areas which slope gradually up from the edge of the pond. Portions of the surrounding area are forested.

e. Downstream Channel. The stilling basin, which accepts discharge from both spillways and the outlet conduit, is lined with hand-placed riprap and is reported to be about four feet deep. There is no evidence of excessive erosion or displacement of the stone lining around the basin. The pool elevation in the basin was the same as that of Thirty Acre Pond at the time of inspection. The parkway bridge openings were clear of debris and the bridge itself appeared to be in good condition.

3.2 Evaluation.

The dam is considered to be in fair condition. Bare spots on the crest of the dam and lack of erosion protection on the upstream slope could lead to surface erosion of the embankment. The roots of the trees growing from the crest create potential seepage paths through the dam. In the event of severe winds uprooting the trees, portions of the embankment could be dislodged. Both spillways appear to be in satisfactory condition.

SECTION 3

VISUAL INSPECTION

3.1 Findings

a. General. The field inspection of Lower Porter Pond Dam was performed on October 17, 1979. At the time of the inspection, the reservoir water surface was about 2 inches above the spillway crest. No underwater areas were inspected.

The observations and comments of the field inspection team are in the checklist which is Appendix A of this report.

b. Dam. The dam is considered to be in fair overall condition. The visible portions of the upstream slope below reservoir level appear to grade very gently away from the spillway wingwalls and the vertical stone wall curbing. There is no evidence of riprap on the submerged slope. The masonry wingwalls and parapet wall appear to be in good condition. The embankment crest width varies from 15 to 20 feet and is grass covered. Bare earth is exposed parallel to the eastern service spillway training wall (see overview photo). It was observed that the left abutment area extends to the east of the embankment for a distance of at least 300 feet with the same elevation as the dam crest. A deciduous tree about forty feet tall and two smaller evergreens are growing on the dam crest. The downstream slope supports shrubs and flowers planted as part of a park beautification program. There was no evidence of seepage on the date of the inspection.

c. Appurtenant Structures. The broad-crested masonry service spillway located at the right abutment appears to be in fair condition. The masonry walls of the approach channel have a slope of 1H:1V and show little evidence of deterioration. The center five feet of the masonry weir crest is depressed about 3 inches below the remaining length of weir. It could not be determined if this section was constructed in this manner or if there is settlement of the spillway headwall.

The broad-crested auxiliary spillway is located about 60 feet northwest of the service spillway. The weir crest is composed of non-mortared loose stone and has a non-uniform surface elevation. The vertical non-mortared training walls are in good condition. It was noted that discharge was flowing between the large cobbles forming the downstream end of the weir crest. The downstream channel invert is less than one foot below the poorly defined weir crest and is composed of the same cobble size material. A low-lying area west of the auxiliary spillway appears to function as a stilling pool during high spillway discharges. The unlined outlet channel downstream of the stilling pool is trapezoidal in section and contains three one foot drops of non-mortared stone construction. Undermining of the left side of the outlet channel has created a vertical side wall about 3 feet high.

A 30-inch diameter pre-cast concrete outlet pipe is located about 10 feet west of the service spillway. The sluice gate is submerged and the operator was

SECTION 2

ENGINEERING DATA

2.1 Design

The following information was made available for review of Lower Porter Pond Dam:

1. Report entitled "Master Plan Study for D. W. Field Park," April 1968 prepared by Camp, Dresser and McKee, Boston, Massachusetts.
2. Dam inspection report prepared by Commonwealth of Massachusetts, Department of Environmental Quality and Engineering (DEQE), December, 1972.
3. Dam inspection report prepared by the County of Plymouth, Engineering Department, February, 1942.
4. Drawing entitled "Proposed Location and Design for Permanent Structures at Easton Dam" dated April, 1940.

Note 1: No design calculations, embankment cross-sections, or record drawings are available for this site.

Note 2: The principal design features for this dam are shown on the sketches enclosed in Appendix B.

2.2 Construction

No information is available concerning construction of Lower Porter Pond Dam except that it was part of the Works Progress Administration program in 1940.

2.3 Operation

No operational data is available for this site.

2.4 Evaluation

a. Availability. The information made available was obtained from the City of Brockton and the DEQE.

b. Adequacy. The drawing and reports together with the visual inspection data are adequate for a Phase I Investigation.

c. Validity. The data obtained for this site is in general conformance with the field measurements.

h. Diversion and Regulating Tunnel.

Not applicable.

i. Spillway.

Type (Service)	Broad-crested masonry weir
(Auxiliary)	Broad-crested loose stone weir
Length (Service)	12 feet
(Auxiliary)	20 feet
Crest Elevation (Service)	160.0
(Auxiliary)	160.0
Gates	None
Upstream Channel (Service)	11 feet long, masonry invert 12 feet wide, grouted stone side-slopes.
(Auxiliary)	None
Downstream Channel (Service)	Stilling basin & Thirty Acre Pond
(Auxiliary)	Stilling pool, trapezoidal drop sections, stilling basin & Thirty Acre Pond.

j. Regulating Outlets. A hand-operated sluice gate of unknown dimensions is situated at the upstream end of a 30 inch diameter pre-cast concrete outlet pipe. The gate invert elevation is approximately 154.0 MSL and is considered to be at or near the bottom of Lower Porter Pond.

c. Elevation. (feet above NGVD)

Streambed at Toe of Dam	151.0
Bottom of Cutoff	NA
Maximum Tailwater	158+
Normal Pool	160.0
Full Flood Control Pool	NA
Spillway Crest (Service and Auxiliary)	160.0
Design Surcharge (Original Design)	Unknown
Top of Dam	163.0
Test Flood Pool Design Surcharge	164.2

d. Reservoir. (Length in feet)

Normal Pool	900
Flood Control Pool	NA
Spillway Crest Pool	900
Top of Dam	920
Test Flood Pool	950

e. Storage. (Acre-feet)

Normal Pool	24
Flood Control Pool	NA
Spillway Crest Pool	24
Top of Dam	54
Test Flood Pool	69

f. Reservoir Surface. (Acres)

Normal Pool	8
Flood Control Pool	NA
Spillway Crest	8
Top of Dam	12
Test Flood Pool	14

g. Dam.

Type	Earth embankment
Length	200 feet
Height	12 feet
Top Width	15-20 feet
Side Slopes (upstream)	Unknown earth slope below the water capped with a parapet wall.
(downstream)	2H:1V
Zoning	Unknown
Impervious Core	Unknown
Cutoff	Unknown
Grout Curtain	Unknown

g. Purpose of Dam. The dam was constructed and is presently used for recreational purposes.

h. Design and Construction History. Lower Porter Pond Dam, originally called Easton Dam, was constructed in 1940 as part of the Works Projects Administration (WPA) program. Further information is unavailable.

i. Normal Operating Procedures. The reservoir is normally self-regulating with the normal pool slightly above the crest elevation of the service and auxiliary spillways.

1.3 Pertinent Data

a. Drainage Area. The watershed for Lower Porter Pond Dam is approximately 3.4 square miles in area and is wooded with some residential developments and low-lying marshes in the upper reaches. Three reservoirs (Brockton Reservoir, Waldo Lake, and Upper Porter Pond) are located upstream of Lower Porter Pond within the drainage area.

b. Discharge at Damsite.

1) Outlet Works. The outlet works consists of a gated 30-inch diameter pre-cast concrete pipe with an invert elevation of 154.0 MSL. The estimated discharge capacity is about 25 cfs when the reservoir surface is at the top of the dam.

2) Maximum Known Flood at Damsite. Unknown.

3) Ungated Spillway Capacity at Top of Dam. The combined discharge capacity of the service and auxiliary spillways with reservoir at top of dam Elev. 163.0 is 488 cfs.

4) Ungated Spillway Capacity at Test Flood Elevation. The combined spillway capacity with reservoir at test flood Elev. 164.2 is about 720 cfs.

5) Gated Spillway Capacity at Normal Pool. Not applicable.

6) Gated Spillway capacity at Test Flood Elevation. Not applicable.

7) Total Spillway Capacity at Test Flood Elevation. Same as 4) above.

8) Total Project Discharge at Top of Dam. Same as 3) above.

9) Total Project Discharge at Test Flood. The combined discharge capacity of the spillways and the flow over the dam at test flood Elev. 164.2 is 2,500 cfs.

b. Description of Dam and Appurtenances. Lower Porter Pond Dam is an ill-defined earth embankment approximately 200 feet long with a maximum height of about 12 feet. The top width is approximately 15 feet and the downstream slope is about 2H:1V. The upstream slope is unknown and is capped with a two-foot high parapet wall.

The broad-crested stone masonry service spillway is located near the right abutment. The trapezoidal approach apron is eleven feet long and consists of a masonry invert with grouted stone side slopes. The spillway has a 12-foot long weir and a 9-foot high vertical downstream headwall. Discharge over the service spillway is directed into a riprapped stilling basin and then into Thirty Acre Pond through a double arch reinforced concrete highway bridge. Each arch has a clear opening about 10 feet wide and 7 feet high.

The broad-crested stone masonry auxiliary spillway is situated about 60 feet to the right of the service spillway. The spillway is 20 feet long with vertical masonry training walls and a dumped rock invert. The initial outlet channel elevation is about one foot below the weir crest. The channel slopes gently downstream and outlets into a shallow stilling pool. The channel is constructed downstream of the stilling pool as a series of trapezoidal drop sections for a distance of approximately 50 feet where discharges from the auxiliary spillway are conveyed into the service spillway stilling basin.

c. Size Classification. Lower Porter Pond Dam has a maximum storage capacity of approximately 54 acre-feet and a maximum height of about 12 feet. The criteria for the "Small" size category includes dams which have less than 1,000 acre-feet storage capacity and are less than 40 feet high. Lower Porter Pond Dam is therefore classified as a "Small" size dam.

d. Hazard Classification. Lower Porter Pond Dam is located approximately 70 feet upstream of Thirty Acre Pond. Approximately 35 single family dwellings and commercial establishments are downstream of Thirty Acre Pond. In addition, the discharge from Thirty Acre Pond passes through two small ponds, a narrow man-made channel approximately one mile long and into a 1,800-foot long underground culvert. The region of potential flooding which borders the man-made channel and which is upstream of the culvert is a densely populated urban neighborhood. The dam is classified as "Significant" hazard since flood waters resulting from failure at Lower Porter Pond Dam could cause appreciable property damage but little or no loss of life. This assessment is based on the breach analysis, which computed a stream depth of 1.1 feet at the initial downstream damage center.

e. Ownership. The dam is owned by the City of Brockton, Department of Parks and Recreation, City Hall, Brockton, Massachusetts, 02401, Telephone 617-580-1100.

f. Operator. The dam is operated by the Department of Parks and Recreation. Mr. John Dorgan Sr., Park Commissioner, is in charge of dam operations. Telephone 617-580-1100.

NATIONAL DAM INSPECTION PROGRAM
PHASE I INSPECTION REPORT
LOWER PORTER POND DAM

SECTION 1

PROJECT INFORMATION

1.1 General

a. Authority. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspections throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. O'Brien & Gere Engineers, Inc. has been retained by the New England Division to inspect and report on selected dams in the Commonwealth of Massachusetts. Authorization and notice to proceed were issued to O'Brien & Gere Engineers, Inc. by a letter from the Corps of Engineers dated November 6, 1979 and signed by Colonel William E. Hodgson, Jr. Contract No. DACW33-80-C-0014 has been assigned by the Corps of Engineers for this work.

b. Purpose. The purpose of performing technical inspection and evaluation of non-federal dams is to:

1. Identify conditions which threaten public safety and make the Owner aware of any deficiencies to permit him to correct them in a timely manner.
2. Encourage and prepare the states to initiate effective dam safety programs for non-federal dams.
3. Update, verify, and complete the National Inventory of Dams.

1.2 Description of Project (Information for this dam was obtained from the City of Brockton and the Massachusetts Department of Environmental Quality and Engineering (DEQE).

a. Location. Lower Porter Pond Dam is located on Beaver Brook within the City of Brockton, Massachusetts. A 35-home community located about 0.5 miles downstream is considered the major damage center. Beaver Brook outlets into Salisbury Brook about 0.75 miles downstream and Salisbury Brook joins Trout Brook to form the Salisbury Plain River about 2 miles downstream of the dam. The dam is shown on the USGS Quadrangle entitled "Brockton, Massachusetts" at coordinates N 42° 05.9', W 71° 02.6'. A regional location plan of Lower Porter Pond Dam is enclosed as Figure 1, pg. vi.

7.3 Remedial Measures

- 1) The bare spots on the embankment crest should be covered with suitable vegetation and protected from pedestrian traffic.
- 2) Erosion protection should be provided for the upstream slope of the embankment.
- 3) The operating condition of the pond drain sluice gate should be determined and the gate should be repaired, if necessary. The gate operator should be stored in a convenient location for emergency use.
- 4) A program of annual periodic technical inspection should be instituted.
- 5) A formal surveillance and flood warning plan, including round-the-clock monitoring during heavy precipitation, should be developed.

7.4 Alternatives

As an alternative to the above recommendations and remedial measures, the dam could be breached and the pond drained.

APPENDIX A

INSPECTION CHECKLIST

VISUAL INSPECTION CHECK LIST

INSPECTION TEAM ORGANIZATION

Project: LOWER PORTER POND DAM
National I.D. #: MA 00424
Location: Brockton, MA
Type of Dam: Earth Embankment
Inspection Date(s): October 17, 1979
Weather: Overcast, 47°
Pool Elevation: 160.2 MSL

Inspection Team

Leonard Beck	O'Brien & Gere	Structures
Steven Snider	O'Brien & Gere	Foundations & Materials
Alan Hanscom	O'Brien & Gere	Structures
Rodney Georges	Bryant & Associates	Hydrology/Hydraulics

*Mr. John J. Williams, Vice-President, O'Brien & Gere has visited the site but not necessarily in conjunction with the inspection team.

Owner's Representative

Mr. John Dorgan, Park Commissioner, D.W. FIELD PARK
Brockton MA

VISUAL INSPECTION CHECK LIST

Project: LOWER PORTER POND DAM

National I.D. #: MA 00424

Date(s): October 17, 1979

AREA EVALUATED	CONDITIONS
<u>DAM EMBANKMENT</u>	
Crest Elevation	160.0 MSL
Current Pool Elevation	160.2 MSL
Maximum Impoundment to Date	Unknown.
Surface Cracks	None.
Pavement Condition	N/A
Movement or Settlement of Crest	None.
Lateral Movement	None.
Vertical Alignment	Good.
Horizontal Alignment	Good.
Condition at Abutment and at Concrete Structures	No problems noted.
Indications of Movements of Structural Items on Slopes	None.
Trespassing on Slopes	Bare ground on embankment crest near spillway.
Vegetation on Slopes	Flowers and small shrubs on d/s slope; part of beautification prog.
Sloughing or Erosion of Slopes or Abutments	None.
Rock Slope Protection - Riprap Failures	None.

VISUAL INSPECTION CHECK LIST

Project: LOWER PORTER POND DAM

National I.D. #: MA 00425

Date(s): October 17, 1979

AREA EVALUATED	CONDITIONS
<u>DAM EMBANKMENT (Con't)</u>	
Unusual Movement or Cracking at or near Toes	<i>None.</i>
Unusual Embankment or Downstream Seepage	<i>None.</i>
Piping or Boils	<i>None.</i>
Foundation Drainage Features	<i>None.</i>
Toe Drains	<i>None.</i>
Instrumentation System	<i>None.</i>

VISUAL INSPECTION CHECK LIST

Project: LOWER PORTER POND DAM

National I.D. #: MA 00425

Date(s): October 17, 1979

AREA EVALUATED	CONDITIONS
OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS <u>SERVICE SPILLWAY</u> a. Approach Channel General Condition Loose Rock Overhanging Channel Trees Overhanging Channel Floor of Approach Channel b. Weir and Training Walls General Condition of Concrete Rust or Staining Spalling Any Visible Reinforcing Any Seepage or Efflorescence Drain Holes c. Discharge Channel General Condition	<i>Fair.</i> <i>None.</i> <i>None.</i> <i>Grouted stones in good condition.</i> <i>Depression in stone masonry spillway head wall. N/A.</i> <i>None.</i> <i>None.</i> <i>None.</i> <i>None.</i> <i>Good. Riprapped stilling basin & Thirty Acre Pond.</i>

VISUAL INSPECTION CHECK LIST

Project: LOWER PORTER POND DAM

National I.D. #: MA 00425

Date(s): October 17, 1979

AREA EVALUATED	CONDITIONS
OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS (Con't)	
<u>SERVICE SPILLWAY</u>	
Loose Rock Overhanging Channel	None.
Trees Overhanging Channel	None.
Floor of Channel	Unknown. Submerged.
Other Obstructions	R/C double arch bridge about 45' d/s of Service Spillway.

VISUAL INSPECTION CHECK LIST

Project: LOWER PORTER POND DAM

National I.D. #: MA 00425

Date(s): October 17, 1979

AREA EVALUATED	CONDITIONS
OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS <u>AUXILIARY SPILLWAY</u> a. Approach Channel General Condition Loose Rock Overhanging Channel Trees Overhanging Channel Floor of Approach Channel b. Weir and Training Walls General Condition of Concrete Rust or Staining Spalling Any Visible Reinforcing Any Seepage or Efflorescence Drain Holes c. Discharge Channel General Condition	<i>Poor.</i> <i>None.</i> <i>None.</i> <i>Dumped stone.</i> <i>Vertical stone masonry walls in good condition. Irregular stone crest.</i> <i>None.</i> <i>Some loss of mortar.</i> <i>None.</i> <i>None.</i> <i>None.</i> <i>Fair. Some erosion of left channel bank.</i>

VISUAL INSPECTION CHECK LIST

Project: LOWER PORTER POND DAM

National I.D. #: MA 00425

Date(s): October 17, 1979

AREA EVALUATED	CONDITIONS
OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS (Con't)	
Loose Rock Overhanging Channel	Some at bank under mining.
Trees Overhanging Channel	One deciduous tree at location of undermining.
Floor of Channel	Dumped stone w/ three stone masonry steps.
Other Obstructions	None.

VISUAL INSPECTION CHECK LIST

Project: LOWER PORTER POND DAM

National I.D. #: MA 00425

Date(s): October 17, 1979

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE</u>	
a. Approach Channel	
Slope Conditions	Submerged.
Bottom Conditions	Submerged.
Rock Slides or Falls	None.
Log Boom	N/A
Debris	None.
Condition of Concrete Lining	Unknown.
Drains or Weep Holes	None.
b. Intake Structure - <u>OPEN AIR GATE VALVE</u>	
Condition of Concrete	Masonry headwall in good condition.
Stop Logs and Slots	None.
Sluice Gate	Operator missing. Unknown if operable according to owner's representative.

VISUAL INSPECTION CHECK LIST

Project: LOWER PORTER POND DAM

National I.D. #: MA 00425

Date(s): October 17, 1979

AREA EVALUATED	CONDITIONS
OUTLET WORKS - TRANSITION AND CONDUIT	
General Condition of Concrete	N/A
Rust or Staining on Concrete	N/A
Spalling	N/A
Erosion or Cavitation	None.
Cracking	None.
Alignment of Monoliths	N/A
Alignment of Joints	N/A
Numbering of Monoliths	N/A
Condition of Outlet Conduit	PCCP outlet in good condition. Partially submerged by stilling basin.

APPENDIX B

ENGINEERING DATA

LOWER PORTER POND DAM

SHEET

BY

DATE


JOB NO.

APPENDIX B


ENGINEERING DATA

TABLE OF CONTENTS


	<u>PAGE</u>
<i>SITE PLAN & SPILLWAY SECTIONS</i>	<i>B-1</i>
<i>BROCKTON RESERVOIR DAM SYSTEM</i>	<i>B-2</i>
<i>DESCRIPTION OF DAM (DEQE FILES)</i>	<i>B-3</i>
<i>INSPECTION OF DAM & RESERVOIR, PLYMOUTH CO. (DEQE FILES)</i>	<i>B-4</i>
<i>SPILLWAY PICTURES (DEQE FILES)</i>	<i>B-5</i>



SERVICE SPILLWAY SECTION



AUXILIARY SPILLWAY SECTION



Lower Porter Pond
WSE 160.0 MSL

Thirty Acre Pond
WSE 154.0 MSL

U S ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION	
Contract No. DACW 33-80-C-0014 LOWER PORTER POND DAM	
SITE PLAN & SPILLWAY SECTIONS	
DATE	JANUARY 1980
SCALE	NONE
8 - 1	






11. TYPICAL REACH OF SALISBURY BROOK ABOUT $1\frac{1}{2}$ MILES DOWNSTREAM OF LOWER PORTER POND DAM. (10/17/79)



12. ENTRANCE TO APPROXIMATELY 600 YARD LONG BOX CULVERT FOR SALISBURY BROOK IN BROCKTON ABOUT ONE AND $\frac{3}{4}$ MILES DOWNSTREAM OF LOWER PORTER POND DAM. (10/17/79)




9. E. BRETT POND (DRAINED) INLET STRUCTURE ABOUT 1150 YARDS DOWN-
STREAM OF LOWER PORTER POND DAM. (10/17/79)



10. CROSS POND SPILLWAY APPROXIMATELY 1450 YARDS DOWNSTREAM OF LOWER
PORTER POND DAM. (10/17/79)



7. UPPER PORTER POND DAM SPILLWAY APPROXIMATELY 350 YARDS UPSTREAM OF LOWER PORTER POND DAM. (10/17/79)




8. 30 ACRE POND DAM SPILLWAY ABOUT 700 YARDS DOWNSTREAM OF LOWER PORTER POND DAM. (10/17/79)



5. BROCKTON RESERVOIR DAM SPILLWAY APPROXIMATELY 2100 YARDS UP-
STREAM OF LOWER PORTER POND DAM. (10/17/79)



6. WALDO LAKE DAM SPILLWAY ABOUT 1050 YARDS UPSTREAM OF LOWER PORTER
POND DAM. (10/17/79)



3. BRIDGE APPROXIMATELY 50 FEET DOWNSTREAM OF THE SERVICE SPILLWAY
AND 150 FEET DOWNSTREAM OF THE AUXILARY SPILLWAY. (10/17/79)




4. CHANNEL DOWNSTREAM OF THE BRIDGE WHICH IS DOWNSTREAM OF THE
IMPOUNDMENT. (10/17/79)



1. SERVICE SPILLWAY LOOKING UPSTREAM TOWARD THE IMPOUNDMENT.
(10/17/79)



2. AUXILARY SPILLWAY OUTLET CHANNEL LOOKING DOWNSTREAM. (10/17/79)



LEGEND

① THE LOCATION AND DIRECTION IN WHICH EACH PHOTOGRAPH WAS TAKEN AND THE NUMBER OF THE PHOTOGRAPH

U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION	
Contract No. DACW 33-80-C-0014	
LOWER PORTER POND DAM	
SITE PLAN & SPILLWAY SECTIONS	
DATE: JANUARY 1980	SCALE: NONE
A	

DD FORM 100-2
10-66

APPENDIX C
SELECTED PHOTOGRAPHS OF PROJECT

<u>LOCATION PLAN</u>	<u>Page</u> <u>No.</u>
----------------------	---------------------------

Site Plan Sketch	A
------------------	---

Regional Plan	B
---------------	---

PHOTOGRAPHS

<u>No.</u>		<u>Page</u> <u>No.</u>
1.	Service spillway looking upstream toward the impoundment.	1
2.	Auxiliary spillway outlet channel looking downstream.	1
3.	Bridge approximately 50 feet downstream of the service spillway and 150 feet downstream of the auxiliary spillway.	2
4.	Channel downstream of the bridge which is downstream of the impoundment.	2
5.	Brockton Reservoir Dam spillway approximately 2100 yards upstream of Lower Porter Pond Dam.	3
6.	Waldo Lake Dam spillway about 1050 yards upstream of Lower Porter Pond Dam.	3
7.	Upper Porter Pond Dam spillway approximately 350 yards upstream of Lower Porter Pond Dam.	4
8.	30 Acre Pond Dam spillway about 700 yards downstream of Lower Porter Pond Dam.	4
9.	E. Brett Pond (drained) inlet structure about 1150 yards downstream of Lower Porter Pond Dam.	5
10.	Cross Pond spillway approximately 1450 yards downstream of Lower Porter Pond Dam.	5
11.	Typical reach of Salisbury Brook about 1½ miles downstream of Lower Porter Pond Dam.	6
12.	Entrance to approximately 600 yard long box culvert for Salisbury Brook in Brockton about 1 3/4 miles downstream of Lower Porter Pond Dam.	6

APPENDIX C

PHOTOGRAPHS

DAM NO 137.



Feb 1942



Feb 1942

From Commonwealth of Massachusetts DEQE Files

B-5

COUNTY OF PLYMOUTH, MASSACHUSETTS
ENGINEERING DEPARTMENT
INSPECTION OF DAM AND RESERVOIRS

DAM NO. 137

Inspector *Gfroerer* Date *Feb. 1942* City or Town *Brockton*
Location *Southerly end of Lower Porter's Pond on Field Parkway*
Owner *City of Brockton* Use *(Salisbury Br.)*
Material and Type *Gravel & Clay Dyke - Stone Spillway*

Maximum Head in Feet (Full Pond Level to Bottom of Spillway) *9 feet*
Length *200 feet* Width *10 feet plus*
Area of Watershed *7 Sq. Miles* Capacity *12,000,000* *56 3/4 A.F.* Gallons
Length of Overflow or Spillway *20 feet and 12 feet* Outlets (Pipes or Flumes)
30 inch diam. pipe.

Dam Constructed by *Under Construction by City - W.P.A.* Date *Aug. 1940*
Recent Repairs _____ Date _____

Evidence of Leakage *None*
Condition *New and sound*

Topography of Country Below *Slightly irregular - Salisbury Brook - Ponds - City - Mass*
Nature, extent, proximity, etc. of buildings, roads or other property in danger if failure should occur
No buildings near. Would be absorbed in 30 Acre Pond.

Remarks and Recommendations *Spillways ample for all conditions except serious failure of dams above.*
Sound & good condition May, 1944. No change Sept. 1946. Good - unchanged May, 1948.
Good - no change Nov. 1950. Sound May 1951. No change - good July 1952. Sound - must water
Feb. 1953. Good - plenty water Dec. 1954. Good as always. Sept. 1956. Good Oct. 1957
Good condition Sept. 1958. Good - no change Oct. 1960. Sound Oct. 1962. Good - no change
Oct. 1964. Good - no change Dec. 1966. Good - no change Oct. 1968. Good - no change
Oct. 1969.

B-4

From Commonwealth of Massachusetts DEQE Files

DESCRIPTION OF DAM

DISTRICT 7

Submitted by A. DUGAN

Dam No. 7-12-44-7

Date 12-5-72

City/Town BROCKTON

Name of Dam LOWER PORTER POND.

1. Location: Topo Sheet No. 32D

Provide 8½" x 11" in clear copy of topo map with location of Dam clearly indicated.

2. Year Built UNKNOWN Year/s of Subsequent Repairs _____

3. Purpose of Dam: Water Supply _____ Recreational X
Irrigation _____ Other _____

4. Drainage Area: 7 Sq.Mi. _____ Acres


5. Normal Ponding Area: _____ Acres _____ Ave. Depth
Impoundment: 12,000,000 Gals. _____ Acre Ft.

6. No. and Type of Dwellings Located Adjacent to Pond or Reservoir
i.e. Summer Homes, etc. NONE

7. Dimensions of Dam: Length 200' Max. Height 9'
Slopes: Upstream Face 5'
Downstream Face 25'
Width Across Top 40'

8. Classification of Dam by Material:
Earth X Conc. Masonry _____ Stone Mason. _____
Timber _____ Rockfill _____ Other _____

From Commonwealth of Massachusetts DEQE Files B-3



U.S. ARMY CORPS OF ENGINEERS
NEW ENGLAND DIVISION

Contract No. DACW 33-80-C-0014
LOWER PORTER POND DAM

BROCKTON RESERVOIR DAM SYSTEM



DATE: JANUARY 1980
SCALE: 1" = 1000'

B-2

BROCKTON PARK COMMISSION
BROCKTON, MASS.
D.W. FIELD PARK
PLAN

SHOWING AREAS OF PROPOSED
FORESTRY MANAGEMENT

Comp. Gresser & Messer
Consulting Engineers
Boston, Massachusetts

FIG. 3

April, 1968

APPENDIX D

HYDROLOGIC AND HYDRAULIC COMPUTATIONS

SUBJECT	SHEET	BY	DATE	JOB NO
LOWER PORTER POND DAM				

APPENDIX D

HYDROLOGIC & HYDRAULIC COMPUTATIONS

TABLE OF CONTENTS

	<u>PAGE</u>
REGIONAL VICINITY MAP, FIGURE 1, SHOWING FLOOD IMPACT AREA	D-1
T_p COMPUTATIONS	D-2
PMP DATA	D-2
ELEVATION SKETCH OF SPILLWAYS	D-2
STAGE-DISCHARGE & STAGE-STORAGE COMPUTATIONS	D-3
STAGE-DISCHARGE & STAGE-STORAGE GRAPHS	D-4
T_p COMPS., PMP DATA, ELEV. SKETCH DAM & SPWY (BROCKTON DAM)	D-5
STAGE-DISCHARGE & STAGE-STORAGE COMPS. (BROCKTON DAM)	D-6
T_p COMPS., PMP DATA, ELEV. SKETCH DAM & SPWYS. (WALDO LAKE DAM)	D-7
STAGE-DISCHARGE & STAGE-STORAGE COMPS. (WALDO LAKE DAM)	D-8
T_p COMPS., PMP DATA, ELEV. SKETCH DAM & SPWY. (UPPER PORTER DAM)	D-9
STAGE-DISCHARGE & STAGE-STORAGE COMPS. (UPPER PORTER DAM)	D-10
ELEV. SKETCH DAM & SPWYS., STAGE-DISCHARGE & STAGE-STORAGE COMPS. (THIRTY ACRE POND)	D-11
SECTION @ HAZARD AREA	D-12
HEC-1 DAM SAFETY VERSION, COMPUTER OUTPUT	D-13 to D-25
HEC-1 DAM SAFETY VERSION, BREACH ANALYSIS, COMPUTER OUTPUT	D-26 to D-31

BRYANT ASSOCIATES, INC.
648 Beacon Street
BOSTON, MASSACHUSETTS 02215
(617) 247-1800

JOB NED-COE, LOWER PORTER POND DAM

SHEET NO. D-2 OF

CALCULATED BY RG DATE

CHECKED BY SHS DATE

SCALE

LOWER PORTER DAM - H & H

11

SUBDRAINAGE AREA = 0.08 sq. mi

SNYDER HYDROGRAPH COEFFICIENTS

$C_t = 2.0$

$C_p = 0.5$

T_p COMPUTATIONS

$L = 0.64$ MILES $L_{ca} = 0.23$ MILES

$T_p = C_t \cdot (L \times L_{ca})^{.3}$


$T_p = 2 \times (.64 \times .23)^{.3} \approx \underline{1.13 \text{ HOURS}}$

PMP DATA

FROM HMS #33 THE 24 HOUR 200 sq. mi INDEX RAINFALL IS 21.5

6hr. %	OF INDEX FOR THIS BASIN	= 111
12hr. %	" " " " "	= 124
24hr. %	" " " " "	= 133

DAM ELEVATION & LENGTH and SPILLWAY DIMENSIONS SKETCH



$C = 2.9$ TOP OF DAM

LOOKING DOWNSTREAM

D-2

BRYANT ASSOCIATES, INC.
648 Beacon Street
BOSTON, MASSACHUSETTS 02215
(617) 247-1800

JOB NED-COE, LOWER PORTER POND DAM
SHEET NO D-3 OF _____
CALCULATED BY RG DATE _____
CHECKED BY SHS DATE _____
SCALE _____

LOWER PORTER DAM cont'd

STAGE DISCHARGE

$H = 0$ @ SERVICE SPILLWAY CREST (ELEV. 160.0 MSL)

1) SERVICE SPILLWAY : $C = 3.1$ $L = 12'$ $Z = 1$
 $b_0 = 12'$ FOR $H \leq 3$ $Q_1 = C \left(\frac{b_0 + b_H}{2} \right) H^{1.5}$
FOR $H > 3$ $Q_1 = C \left[\left(\frac{b_0 + b_H}{2} \right) 3^{1.5} + 1.8 \times (H - 3)^{1.5} \right]$

2) AUXILIARY SPILLWAY : $C = 2.7$ $L = 20'$ $Q_2 = CL(H - 0.25)^{1.5}$

3) TOP OF DAM : $C = 2.9$ $L = 200 - 38 = 162'$ $Q_3 = CL(H - 3)^{1.5}$


ELEVATION MSL	H Ft	Q_1 CFS	Q_2 CFS	Q_3 CFS	ΣQ CFS
160	0	0	0	0	0
161	1	40	35	0	75
162	2	123	125	0	248
163	3	242	246	0	488
164	4	297	392	1,339	2,028
165	5	399	559	3,790	4,748
166	6	532	745	6,962	8,239
167	7	688	947	10,718	12,353
168	8	865	1,165	14,979	17,009

STORAGE

ELEVATION (FT.) AREA (AC.) STORAGE (A. FEET)
 (PLANIMETERED FROM USGS) (COMP. BY HEC-1 PROGRAM)

	151	0	0
NORMAL POOL	160	8	24
TOP OF DAM	163	—	54
	170	24	177

STORAGE A-F



LOWER PORTER POND DAM

STAGE VS. STORAGE

STAGE VS. DISCHARGE

APPENDIX D

BRYANT ASSOCIATES, INC.
648 Beacon Street
BOSTON, MASSACHUSETTS 02215
(617) 247-1800

JOB NED-COF, LOWER PORTER POND DAM
SHEET NO D-5 OF _____
CALCULATED BY RG DATE _____
CHECKED BY SHS DATE _____
SCALE _____

BROCKTON LAKE DAM - H & H

11

DRAINAGE AREA = 2.8 sq. mi

SNYDER HYDROGRAPH COEFFICIENTS

$$C_t = 2.0$$

$$C_p = 0.5$$

T_p COMPUTATIONS

$$L = 2.70 \text{ MILES} \quad L_{ca} = 1.40 \text{ MILES}$$

$$T_p = C_t \cdot (L \times L_{ca})^{.3}$$


$$T_p = 2.0 \times (2.7 \times 1.4)^{.3} = \underline{\underline{3.0 \text{ HOURS}}}$$

PMP DATA

FROM HMS #33 THE 24 HOUR 200 sq. mi. INDEX RAINFALL IS 21.5

6hr. %	OF INDEX FOR THIS BASIN	= 111
12hr. %	" " " " "	= 124
24hr. %	" " " " "	= 133

DAM ELEVATION & LENGTH and SPILLWAY DIMENSIONS SKETCH



LOOKING DOWNSTREAM

$C = 5.3$ w/BOARDS

$C = 2.9$ w/out

$C = 2.9$ TOP OF DAM

D-5

BRYANT ASSOCIATES, INC.
648 Beacon Street
BOSTON, MASSACHUSETTS 02215
(617) 247-1800

JOB NED-COE, LOWER PORTER POND DAM
SHEET NO. D-6 OF _____
CALCULATED BY RG DATE _____
CHECKED BY SHS DATE _____
SCALE _____

BROCKTON LAKE DAM - H&H cont'd

STAGE DISCHARGE WITH FLASHBOARDS

(H = 0 @ SPILLWAY CREST)

1) SPILLWAY : $C = 3.3$ $L = 25'$ $Q_s = CLH^{1.5}$

2) TOP OF DAM : $C = 2.9$ $L = 1800 - 25 = 1775$ $Q_{dam} = CL(H - 3.3)^{1.5}$

ELEVATION MSL	H Ft.	Q_s CFS	Q_{top} CFS	ΣQ CFS
201	0	0	0	0
202	1	83	0	83
203	2	233	0	233
204	3	429	0	429
204.3	3.3	495	0	495
205	4	660	3,015	3,675
206	5	922	11,410	12,332
207	6	1,213	22,637	24,050
208	7	1,528	36,635	38,163
209	8	1,867	52,450	54,317
210	9	2,228	70,050	72,278

SPILLWAY DISCHARGE WITH NO FLASHBOARDS FOR TOP OF DAM EL.

$C = 2.8$ $L = 25$ $Q = CL(H + 2.5)^{1.5}$
 $Q = 978$ CFS

STORAGE

	ELEV. (MSL)	AREA (AC.) (PLANIMETERED FROM USGS)	STORAGE (ACRE FEET) (COMPUTED BY HEC-1 PROGRAM)
	194.3	0	0
NORMAL POOL	201	85	190
TOP OF DAM	204.3	—	493
	210	126	1133

BRYANT ASSOCIATES, INC.
648 Beacon Street
BOSTON, MASSACHUSETTS 02215
(617) 247-1800

JOB NED-COE, LOWER PORTER POND DAM

SHEET NO D-7 OF _____

CALCULATED BY RG DATE _____

CHECKED BY SHS DATE _____

SCALE _____

WALDO LAKE DAM - H&H

11

SUBDRAINAGE AREA = 0.38 sq Mi

SNYDER HYDROGRAPH COEFFICIENTS

$C_t = 2.0$ $C_p = 0.5$

TP COMPUTATIONS

$L = 0.85$ MILES

$L_{ca} = 0.28$

$T_p = C_t \cdot (L \times L_{ca})^{.3}$

$T_p = 2 \times (.85 \times .28)^{.3}$

$T_p \approx \underline{1.25 \text{ HOURS}}$


PMP DATA

FROM HMS #33 THE 24 HOUR 2.00 sq Mi INDEX RAINFALL IS 21.5

6 hr. %	OF INDEX FOR THIS BASIN	= 111
12 hr "	" " " " "	= 124
24 hr "	" " " " "	= 133

DAM ELEVATION & LENGTH and SPILLWAYS DIMENSIONS SKETCH

LOOKING DOWNSTREAM



LOOKING DOWNSTREAM

D-7

JOB YED-COE, LOWER PORTER POND DAM
SHEET NO. D- 8 OF _____
CALCULATED BY RG DATE _____
CHECKED BY SHS DATE _____
SCALE _____

BRYANT ASSOCIATES, INC.
648 Beacon Street
BOSTON, MASSACHUSETTS 02215
(617) 247-1800

JOB MED-COE, LOWER PORTER FOND DAM

SHEET NO D-9 OF

CALCULATED BY RG DATE

CHECKED BY SHS DATE

SCALE

UPPER PORTER DAM - H & H

11

SUBDRAINAGE AREA

= 0.11 sq. mi

SNYDER HYDROGRAPH COEFFICIENTS

$$C_L = 2.0$$

$$C_P = 0.5$$

T_p COMPUTATIONS

$$L = 0.44 \text{ MILES}$$

$$L_{ca} = 0.22 \text{ MILES}$$

$$T_p = C_L \cdot (L \times L_{ca})^{.3}$$

$$T_p = 2 \times (.44 \times .22)^{.3} \approx \underline{\underline{1.0 \text{ HOUR}}}$$

PMP DATA


FROM HMS #33 THE 24 HOUR 200 sq. mi INDEX RAINFALL IS 21.5

6hr. % OF INDEX FOR THIS BASIN = 111

12hr. % " " " " " = 124

24hr. % " " " " " = 133

DAM ELEVATION & LENGTH and SPILLWAY DIMENSIONS SKETCH



$C = 2.8$ TOP OF DAM

LOOKING DOWNSTREAM

D-9

BRYANT ASSOCIATES, INC.
648 Beacon Street
BOSTON, MASSACHUSETTS 02215
(617) 247-1800

JOB NED-COE

SHEET NO D- 10 OF

CALCULATED BY RG DATE

CHECKED BY SHS DATE

SCALE

UPPER PORTER DAM - H & H

STAGE DISCHARGE

(H=0 @ SPILLWAY CREST) ELEVATION = 167.5 MSL

1) SPILLWAY: $C = 3.1$ $L = 25'$ $Q_s = CLH^{1.5}$

2) TOP OF DAM: $C = 2.9$ $L = 340 - 25 = 315$ $Q_{TOP} = CL(H - 3.5)^{1.5}$

ELEVATION MSL	H FT.	Q_s CFS	Q_{TOP} CFS	ΣQ CFS
167.5	0	0	0	
168.5	1	78	0	78
169.5	2	219	0	219
170.5	3	403	0	403
171.0	3.5	508	0	508
172.0	4.5	740	913	1,653
173.0	5.5	1,000	2,584	3,584
174.0	6.5	1,284	4,747	6,031
175.0	7.5	1,592	7,308	8,900
176.0	8.5	1,921	10,213	12,134

STORAGE


	ELEV. (MSL)	AREA (AC) (PLANIMETERED FROM USGS)	STORAGE (AC. FEET) (COMP. BY HEC-1 PROGRAM)
	160	0	0
NORMAL POOL	167.5	11	28
TOP OF DAM	171	19	79

BRYANT ASSOCIATES, INC.
648 Beacon Street
BOSTON, MASSACHUSETTS 02215
(617) 247-1800

JOB NED-COE, LOWER FORTER POND DAM
SHEET NO. D-11 OF _____
CALCULATED BY RG DATE _____
CHECKED BY SHS DATE _____
SCALE _____

THIRTY ACRE POND

DAM ELEVATION & LENGTH and SPILLWAYS DIMENSIONS SKETCH



STAGE DISCHARGE

$H = 0$ @ SERVICE SPILLWAY CREST (ELEV. = 154.0 MSL)

1) SERVICE SPILLWAY FOR $H \leq 3$ $Q_1 = C \left(\frac{b_0 + bH}{2} \right) H^{1.5}$
FOR $H > 3$ $Q_1 = C \left[\left(\frac{b_0 + bH}{2} \right) 3^{1.5} + 12 \times (H-3)^{1.5} \right]$

2) AUXILIARY SPILLWAY $Q_3 = C L (H-1)^{1.5}$

3) TOP OF DAM: $L = 523'$ $Q_4 = C L (H-3)^{1.5}$

ELEVATION MSL	H FT.	Q_1	Q_2	Q_3	Q_4	EQ CFS
154	0	0		0	0	
155	1	23		0	0	23
156	2	75	PIPE FLOW	47	0	122
157	3	11	143	131	0	285
158	4	40	152	242	1517	1951
159	5	112	160	372	4290	4934
160	6	206	168	520	7881	8775

SURCHARGE STORAGE

	ELEVATION	AREA (AC.)	STORAGE (AC FT.)
NORMAL POOL	154	26	0
TOP OF DAM	157	-	86
	160	37	188

PLANIMETERED
FROM USGS

COMPUTED BY
HEC-1 PROGRAM


BRYANT ASSOCIATES, INC.
648 Beacon Street
BOSTON, MASSACHUSETTS 02215
(617) 247-1800

JOB NED-COE, LOWER PORTER POND DAM
SHEET NO. D-12 OF _____
CALCULATED BY RG DATE _____
CHECKED BY SHS DATE _____
SCALE _____

BROCKTON
DOWNSTREAM ROUTING

SECTION @ HAZARD AREA

1200 FEET DOWNSTREAM OF THIRTYACRE POND DAM



MANNING'S COEFFICIENTS : CHANNEL $\rightarrow$ 0.03
OVERBANKS $\rightarrow$ 0.08

CHANNEL SLOPE : .008 FT./FT.

FLOOD RESULTS AT LOWER
PORTER POND DAM

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1		ELEVATION STORAGE OUTFLOW		INITIAL VALUE		SPILLWAY CREST		TOP OF DAM		SPILLWAY DISCHARGE CAPACITY	
		24. 0.		160.00		160.00		163.00		54. 488.	
RATIO OF PMF	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS				
.10	161.38	0.00	36.	140.	0.00	31.67	0.00				
.20	162.41	0.00	47.	345.	0.00	29.50	0.00				
.30	163.20	.20	56.	799.	7.17	22.83	0.00				
.40	163.76	.76	63.	1663.	10.67	20.83	0.00				
.50	164.18	1.18	69.	2505.	12.67	19.83	0.00				
.60	164.43	1.43	72.	3195.	14.00	19.33	0.00				
.70	164.65	1.65	75.	3809.	15.17	19.17	0.00				
.80	164.87	1.87	78.	4381.	16.00	19.00	0.00				
1.00	165.23	2.23	84.	5559.	17.33	18.83	0.00				

FLOOD RESULTS AT BROCKTON RESERVOIR DAM

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 201.00 190. 0.	SPILLWAY CREST 201.00 190. 0.	TOP OF DAM 204.30 493. 495.
--------	---------------------------------	---------------------------------------	--	--------------------------------------

RATIO OF P.F.	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.10	202.93	0.00	353.	208.	0.00	23.00	0.00
.20	204.22	0.00	478.	478.	0.00	22.33	0.00
.30	204.57	.17	511.	1245.	5.50	19.57	0.00
.40	204.79	.29	523.	1826.	7.67	19.00	0.00
.50	204.70	.40	533.	2302.	9.33	18.83	0.00
.60	204.80	.50	543.	2765.	10.33	18.83	0.00
.70	204.90	.60	554.	3226.	11.33	18.83	0.00
.80	205.00	.70	564.	3694.	12.17	18.83	0.00
.90	205.11	.81	575.	4639.	13.50	18.67	0.00
1.00							

FLOOD RESULTS AT WALPOLE LAKE DAM

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 194.50 0. 0.	SPILLWAY CREST 194.50 0. 0.	TOP OF DAM 198.10 342. 499.
--------	---------------------------------	-------------------------------------	--------------------------------------	--------------------------------------

RATIO OF P.F.	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.10	194.00	0.00	126.	142.	0.00	29.67	0.00
.20	197.18	0.00	242.	351.	0.00	27.67	0.00
.30	194.22	.12	356.	804.	4.33	22.33	0.00
.40	194.54	.43	393.	1674.	7.50	20.50	0.00
.50	194.67	.57	410.	2445.	9.50	19.50	0.00
.60	195.79	.89	424.	3081.	10.67	19.17	0.00
.70	195.90	.80	437.	3644.	11.83	19.00	0.00
.80	195.99	.89	442.	4179.	12.67	19.00	0.00
.90	196.20	1.10	475.	5285.	14.00	18.83	0.00
1.00							

FLOOD RESULTS AT UPPER PORTER POND DAM

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 167.50 24. 0.	SPILLWAY CREST 167.50 28. 0.	TOP OF DAM 171.00 79. 508.
--------	---------------------------------	--------------------------------------	---------------------------------------	-------------------------------------

RATIO OF P.F.	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.10	164.94	0.00	46.	141.	0.00	30.83	0.00
.20	170.20	0.00	65.	347.	0.00	24.83	0.00
.30	171.25	.24	84.	794.	3.83	22.67	0.00
.40	172.00	1.00	109.	1653.	7.33	20.67	0.00
.50	172.43	1.43	119.	2476.	9.17	19.67	0.00
.60	172.77	1.77	117.	3144.	10.50	19.33	0.00
.70	173.06	2.06	124.	3738.	11.67	19.00	0.00
.80	173.29	2.29	130.	4237.	12.50	19.00	0.00
.90	173.70	2.76	142.	4441.	14.00	19.83	0.00
1.00							

D-24

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS									
				RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7	RATIO 8	RATIO 9	RATIO 10
HYDROGRAPH AT BROCKTON	2.40	7.25	1	465.	931.	1396.	1862.	2327.	2792.	3258.	3723.	4654.	4654.
ROUTED TO DAM 0	2.40	7.25	1	204.	478.	1245.	1826.	2302.	2765.	3226.	3694.	4639.	4639.
HYDROGRAPH AT WALDO	3.14	8.24	1	102.	204.	307.	409.	511.	613.	715.	817.	1022.	1022.
2 COMBINED	5.54	15.49	1	217.	434.	651.	868.	1073.	1278.	1483.	1688.	2126.	2126.
ROUTED TO WALDO	3.14	8.24	1	142.	284.	426.	568.	710.	852.	994.	1136.	1416.	1416.
HYDROGRAPH AT UPPER PORTER	1.1	3.29	1	33.	67.	100.	133.	166.	200.	233.	266.	333.	333.
2 COMBINED	6.64	18.73	1	175.	350.	525.	699.	874.	1049.	1224.	1399.	1759.	1759.
ROUTED TO UPPER PORTER	3.29	9.82	1	141.	282.	423.	564.	705.	846.	987.	1128.	1416.	1416.
HYDROGRAPH AT LOWER PORTER	1.08	3.21	1	24.	48.	73.	97.	121.	145.	170.	194.	242.	242.
2 COMBINED	7.72	21.94	1	165.	330.	495.	660.	825.	990.	1155.	1320.	1700.	1700.
ROUTED TO LOWER PORTER	3.21	9.63	1	141.	282.	423.	564.	705.	846.	987.	1128.	1416.	1416.
ROUTED TO LOWER PORTER	3.21	9.63	1	141.	282.	423.	564.	705.	846.	987.	1128.	1416.	1416.

TEST FLOOD PEAK INFLOW — ROUTED TEST FLOOD OUTFLOW

HYDROGRAPH ROUTING

ROUTED OUTFLOW FROM LOWER PORTER POND

ISTAQ ICUMP IECON ITAPE JPLT JPMT INAME ISTAGE IAUTO
LUNIT 1 0 0 0 0 0 0 0 0

ROUTING DATA
ULUSS CLOSS AVG IRES ISAME IOPT IPMP LSTR
0.0 0.000 0.000 1 1 0 0 0

NSTPS MSTOL LAG ANSKK K TSK STORA ISPRAY
1 0 0 0.000 0.000 0.000 -100. -1

STAGE 160.00 161.00 162.00 163.00 164.00 165.00 166.00 167.00 168.00 169.00 170.00 171.00 172.00 173.00 174.00 175.00 176.00 177.00 178.00 179.00 180.00
FL3 0.00 75.00 248.00 488.00 2028.00 4748.00 8239.00 12353.00 17009.00 17009.00 17009.00 17009.00 17009.00 17009.00 17009.00 17009.00 17009.00 17009.00 17009.00 17009.00 17009.00

STAGE STORAGE DATA FOR
LOWER PORTER POND DAM
CAPACITY 0. 24. 177. 170.
ELEVATION 151. 160. 170. 170.

SPILLWAY CREST ELEVATION → 160.0

TOPEL COOD EXPD DAMWTO
163.0 0.0 0.0 0.

TOP OF DAM ELEVATION → 163.0

1 PMF
PEAK OUTFLOW IS 160. AT TIME 31.67 HOURS

2 PMF
PEAK OUTFLOW IS 345. AT TIME 29.50 HOURS

3 PMF
PEAK OUTFLOW IS 749. AT TIME 22.73 HOURS

4 PMF
PEAK OUTFLOW IS 1663. AT TIME 20.33 HOURS

5 PMF
PEAK OUTFLOW IS 2506. AT TIME 19.83 HOURS

6 PMF
PEAK OUTFLOW IS 3195. AT TIME 19.33 HOURS

7 PMF
PEAK OUTFLOW IS 3409. AT TIME 19.17 HOURS

8 PMF
PEAK OUTFLOW IS 3491. AT TIME 19.00 HOURS

9 PMF
PEAK OUTFLOW IS 3454. AT TIME 18.43 HOURS

ROUTED OUTFLOWS FROM
LOWER PORTER POND DAM

TEST FLOOD

LOCAL RUNOFF TO LOWER PORTER POND

SUB-AREA RUNOFF COMPUTATION

INFLU= TO LOWER PORTER POND LESS UPPER PORTER POND													
ISTAU	ICOMP	IECON	ITAPE	JPLT	JPRI	INAME	ISTAGE	IAUTO					
LPRT	0	0	0	0	0	1	0	0					
HYDROGRAPH DATA													
LYNG	LONG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL				
1	1	.08	0.00	3.37	0.00	0.000	0	1	0				
PRECIP DATA													
SPEE	PMS	R6	R12	R24	R48	R72	R96						
0.00	21.50	111.00	124.00	133.00	0.00	0.00	0.00						
LOSS DATA													
LPRT	STIRK	ULTRK	RTIOL	ERAIN	STIRKS	RTIOL	STIRL	CNSTL	ALSMX	RTIMP			
0	0.00	0.00	1.00	0.00	0.00	1.00	0.00	.05	0.00	0.00			
UNIT HYDROGRAPH DATA													
TP= 1.00 CP= .50 NTA= 0													
RECESSION DATA													
STIRU= -1.70 ORCSN= -.10 RTIOR= 2.00													
UNIT HYDROGRAPH 16 END-OF-PERIOD ORDNATES, LAG= 1.00 HOURS, CP= .50 VOL= 1.00													
2.	6.	11.	18.	23.	26.	26.	23.	21.	18.				
16.	14.	13.	11.	10.	9.	8.	7.	6.	5.				
5.	4.	3.	3.	3.	2.	2.	2.	2.	1.				
1.	1.	1.	1.	1.	1.	1.	1.	1.	0.				
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.				
END-OF-PERIOD FLOW													
MO,DA	HR,MIN	PERIOD	RAIN	EXCS	LOSS	COMP Q	MO,DA	HR,MIN	PERIOD	RAIN	EXCS	LOSS	COMP Q
SUM 22.08 21.68 1.20 6748.													
(581.) (551.) (30.) (191.08)													
COMBINE HYDROGRAPHS													
COMBINING LOWER PORTER POND LOCAL RUNOFF AND UPPER PORTER POND ROUTED OUTFLOW													
ISTAU	ICOMP	IECON	ITAPE	JPLT	JPRI	INAME	ISTAGE	IAUTO					
TOTAL	2	0	0	0	0	1	0	0					

0 - 21

HYDROGRAPH ROUTING

ROUTED OUTFLOW FROM UPPER PORTER POND

ISTAG	ICOMP	TECON	ITAPE	JPLT	JGRT	INAME	ISTAGE	IAUTO
UPORT	1	0	0	0	0	1	0	0
ROUTING DATA								
CEUSS	CLOSS	AVG	THES	ISAME	IOPT	IPMP	LSTH	
0.0	0.000	0.00	1	1	0	0	0	
NSTPS NSTUL LAG ANSKK X TSK STORA TSPRAY								
1	0	0	0.000	0.000	0.000	-168.	-1	

STAGE	167.50	168.50	169.50	170.50	171.00	172.00	173.00	174.00	175.00	176.00
FLOW	0.00	78.00	219.00	403.00	508.00	1653.00	3584.00	6031.00	8900.00	12134.00

STAGE-STORAGE DATA
FOR UPPER PORTER POND DAM

SURFACE AREA 0. 11. 19.

CAPACITY 0. 28. 79.

ELEVATION 160. 168. 171.

SILLWAY CREST ELEVATION → 167.5 CHSL SP=10 COOL EXPW ELEV COOL CAHEA EXPL

DAM DATA
TOPEL COOLD EXPO DAMWID

→ 171.0 0.0 0.0 0.

.1 PMF
PEAK OUTFLOW IS 141. AT TIME 30.83 HOURS

.2 PMF
PEAK OUTFLOW IS 367. AT TIME 28.83 HOURS

.3 PMF
PEAK OUTFLOW IS 798. AT TIME 22.07 HOURS

.4 PMF
PEAK OUTFLOW IS 1653. AT TIME 20.67 HOURS

.5 PMF
PEAK OUTFLOW IS 2476. AT TIME 19.67 HOURS

.6 PMF
PEAK OUTFLOW IS 3164. AT TIME 19.33 HOURS

.7 PMF
PEAK OUTFLOW IS 3739. AT TIME 19.00 HOURS

.8 PMF
PEAK OUTFLOW IS 4297. AT TIME 19.00 HOURS

.9 PMF
PEAK OUTFLOW IS 5441. AT TIME 18.83 HOURS

ROUTED OUTFLOWS FROM
UPPER PORTER POND

LOCAL RUNOFF TO UPPER PORTER POND

SUB-AREA RUNOFF COMPUTATION

INFLOW TO UPPER PORTER POND LESS WALDO LAKE

ISTAO	ICOMP	IECON	ITAPE	JPLY	JPRI	INAME	ISTAGE	IAUTO
UPORT	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

SNAP	IRSDA	IRSPC	RATIO	ISNOW	ISAME	LOCAL
0.00	0.00	3.37	0.00	0.00	1	0

PRECIP DATA

R6	R12	R24	R48	R72	R96
0.00	21.50	111.00	124.00	133.00	0.00

THSPC COMPUTED BY THE PROGRAM IS .800

LOSS DATA

LRPT	STNKH	RTIOL	ERAIN	STRKS	RTIOK	SIRTL	CNSTL	ALSMX	RTIMP
0	0.00	0.00	1.00	0.00	1.00	0.00	.05	0.00	0.00

UNIT HYDROGRAPH DATA

UPE 1.00 CP= .50 NTA= 0

RECESSION DATA

SRTDZ= -1.70 MRESNE= -.10 RTIOR= 2.00

UNIT HYDROGRAPH 46 END-OF-PERIOD ORIGINATES. LAG= 1.00 HOURS, CP= .50 VOL= 1.00

2.	8.	16.	24.	31.	35.	32.	28.	25.
22.	20.	17.	15.	13.	12.	10.	9.	8.
6.	6.	5.	4.	4.	3.	3.	3.	2.
2.	2.	1.	1.	1.	1.	1.	1.	1.
1.	0.	0.	0.	0.	0.	0.	0.	0.

END-OF-PERIOD FLOW

MO.DA	HR.MM	PERIOD	RAIN	EACS	LOSS	COMP Q	MO.DA	HR.MM	PERIOD	RAIN	EACS	LOSS	COMP Q
SUM 22.89 21.68 1.20 9280. (581.11 551.11 30.11 262.78)													

COMBINE HYDROGRAPHS

COMBINE HYDROGRAPHS - COMBINING UPPER PORTER POND LOCAL RUNOFF AND WALDO LAKE RATED OUTFLOW

ISTAO	ICOMP	IECON	ITAPE	JPLY	JPRI	INAME	ISTAGE	IAUTO
TOTAL	2	0	0	0	0	1	0	0

HYDROGRAPH ROUTING

ROUTED OUTFLOW FROM WALDO LAKE

ISTAO ICOMP IECON ITAPE JPLT JPRT INAME ISTAGE IAUTO
WALDO 1 0 0 0 0 0 0 0

ROUTING DATA
QLOSS CLOSS AVG IRES ISAME IOPT IPMP LSTR
0.0 0.000 0.00 1 1 0 0 0

NSTPS NSTOL LAG ANSKK X TSK STORA ISPRAT
1 0 0 0.000 0.000 0.000 -195. -1

STAGE 194.50 195.50 196.50 197.50 198.10 198.50 199.50 200.50 201.50 202.50 } STAGE - DISCHARGE DATA
FLOW 0.00 75.00 209.00 418.00 499.00 1500.00 6916.00 24497.00 35743.00 } FOR WALDO LAKE DAM

SURFACE AREA 77. 137. } STAGE-STORAGE DATA
CAPACITY 581. }
ELEVATION 195. 200. } FOR WALDO LAKE DAM

SPILLWAY CREST ELEVATION → 194.5 CHEL SPWID CDDW EXPW ELEV COOL CAREN EXPL
→ 194.5 0.0 0.0 0.0 0.0 0.0 0.0 0.0

DAM DATA

TOPEL CDDW EXPW DAMDID
→ 198.1 0.0 0.0 0.

TOP OF DAM ELEVATION → 198.1

1 PMF PEAK OUTFLOW IS 142. AT TIME 29.07 HOURS

2 PMF PEAK OUTFLOW IS 351. AT TIME 27.67 HOURS

3 PMF PEAK OUTFLOW IS 804. AT TIME 22.33 HOURS

4 PMF PEAK OUTFLOW IS 1674. AT TIME 20.50 HOURS

5 PMF PEAK OUTFLOW IS 2445. AT TIME 19.50 HOURS

6 PMF PEAK OUTFLOW IS 3081. AT TIME 19.17 HOURS

7 PMF PEAK OUTFLOW IS 3644. AT TIME 19.00 HOURS

ROUTED OUTFLOWS
FROM WALDO LAKE

8 PMF PEAK OUTFLOW IS 4179. AT TIME 19.00 HOURS

PMF PEAK OUTFLOW IS 5245. AT TIME 18.41 HOURS

LOCAL RUNOFF TO WALDO LAKE

SUB-AREA RUNOFF COMPUTATION

INFLOW TO WALDO LAKE LESS BROCKTON

ISTAD ICOMP IECON ITAPE JPLT JPRT INAME ISTAGE IAUFO

HYDROGRAPH DATA

INVOG IORG IAREA SNAP IASDA TRSPC RATIO TSNOV TSAME LOCAL

PRECIP DATA

SPFE PMS R6 R12 R24 R48 R72 R96

TRSPC COMPUTED BY THE PROGRAM IS .800

LOSS DATA

LROPT STPKR ULTKR HTLOC ERAIN STRKS HTLOK STRIL CNSTL ALSHX RTIMP

UNIT HYDROGRAPH DATA

TP= 1.25 CP= .50 NTA= 0

RECESSION DATA

STARTO= -1.70 GRCSN= -.10 RTION= 2.00

UNIT HYDROGRAPH 59 END-OF-PERIOD ORIGINATES. LAQ= 1.26 HOURS. CP= .50 VOL= 1.00

4.	16.	32.	50.	69.	85.	95.	95.	86.
78.	71.	64.	58.	53.	48.	39.	36.	32.
24.	27.	24.	22.	20.	18.	15.	13.	12.
11.	10.	9.	8.	7.	6.	6.	5.	5.
4.	4.	3.	3.	3.	2.	2.	2.	2.
2.	1.	1.	1.	1.	1.	1.	1.	1.

END-OF-PERIOD FLOW

MO.DA HR.MN PERIOD RAIN EXCS LOSS COMPO MO.DA HR.MN PERIOD RAIN EXCS LOSS COMPO

SUM 22.MR 21.68 1.20 319MS.
(581.1(551.1(30.1(905.71)

D-17

COMBINE HYDROGRAPHS - COMBINING WALDO LAKE LOCAL RUNOFF AND BROCKTON RESERVOIR ROUTED OUTFLOW

COMBINE HYDROGRAPHS

ISTAD ICOMP IECON ITAPE JPLT JPRT INAME ISTAGE IAUFO

TAL

ROUTED OUTFLOW FROM BRUCKTON LAKE DAM

ROUTED OUTFLOWS
FROM BROCKTON
RESERVOIR

.6 PMF
 PEAK OUTFLOW IS 2765. AT TIME 18.83 HOURS
 .7 PMF
 PEAK OUTFLOW IS 3226. AT TIME 18.93 HOURS
 .9 PMF
 PEAK OUTFLOW IS 3696. AT TIME 18.83 HOURS
 PMF
 PEAK OUTFLOW IS 4639. AT TIME 18.67 HOURS

.....
 LOND JOMAY PAGE -11
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 26 FEB 79

RUN DATE 02/11/80.
 TIME 0 14.05.16.

HYDROLOGIC ANALYSIS OF LOWER PORTER POND
 NATIONAL DAM SAFETY PROGRAM
 NEW ENGLAND DIVISION - CORPS OF ENGINEERS

NO	NHR	NMIN	IDAY	JOPEH	NMT	LROPT	TRACE	IPLT	IPRT	INSTAN
300	0	10	0	5	0	0	0	0	-4	0

MULTI-PLAN ANALYSES TO BE PERFORMED

PERCENTAGES OF PMF USED → RTIOS= .10 .20 .30 .40 .50 .60 .70 .80 1.00

INFLOW HYDROGRAPH DEVELOPMENT FOR BROCKTON RESERVOIR

SUB-AREA RINOFF COMPUTATION

INFLOW TO BROCKTON LAKE

ISIAO	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
BROCK	0	0	0	0	0	1	0	0

IRYOS	ITUNG	ITAREA	ISCAP	IRSDA	IRSPC	RATIO	ISNOV	ISAME	LOCAL
1	1	2.80	0.00	3.37	0.00	0.000	0	1	0

SPFE	PMS	R6	R12	R24	R48	R72	R96
0.00	21.50	111.00	124.00	133.00	0.00	0.00	0.00

TRSPC COMPUTED BY THE PROGRAM IS .800

LOSS DATA

LROPT	STARR	ULTRA	WTOL	ERAIN	STARK	RTIOK	STYCL	CNSTL	ALSKA	RTIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	0.00	.05	0.00	0.00

UNIT HYDROGRAPH DATA

1P= 3.00 CP= .50 NTA= 0

RECESSION DATA

STARCE= -1.70 UNCSN= -.10 RTION= 2.00

UNIT HYDROGRAPH TO END-OF-PERIOD ORIGINATES. LAG= 2.99 HOURS CP= .50 VOL= .98

4.	14.	30.	48.	69.	91.	115.	141.	167.	194.
220.	243.	263.	279.	293.	303.	310.	313.	309.	299.
287.	276.	265.	254.	244.	234.	224.	215.	207.	198.
190.	183.	175.	168.	162.	155.	149.	143.	137.	132.
126.	121.	116.	112.	107.	103.	99.	95.	91.	87.

84.	80.	77.	74.	71.	68.	65.	63.	60.	58.
55.	53.	51.	49.	47.	45.	43.	42.	40.	38.
37.	35.	34.	32.	31.	30.	29.	28.	26.	25.
24.	23.	22.	21.	20.	19.	18.	17.	16.	15.
14.	13.	12.	11.	10.	9.	8.	7.	6.	5.

MO.DA HR.MM PERIOD MAIN EACS LOSS MO.DA HR.MM PERIOD MAIN EACS LOSS COMP H

FLOODS ROUTED THROUGH LOWER PORTER POND DAM WITHOUT BREACHING

.....
FLOOD HYDROGRAPH PACKAGE (HEC-1)
DAM SAFETY VERSION JULY 1978
LAST MODIFICATION 26 FEB 79
.....

INPUT

HYDROLOGIC ANALYSIS OF LOWER PORTER POND									
NATIONAL DAM SAFETY PROGRAM									
NEW ENGLAND DIVISION - COMPS OF ENGINEERS									
1	A								
2	A								
3	A								
4	B	300	0	10	0	0	0	0	0
5	B1	5							
6	J	1	9	1					
7	J1	.1	.2	.3	.4	.5	.6	.7	.8
8	K	0	BRUCK						
9	K1		INFLOW TO BRUCKTON LAKE						
10	M	1	1	2.8	0	3.37			
11	P	0	21.5	111	124	133			
12	T						0	.05	
13	V	3.0	0.5						
14	X	-1.7	-0.1	2					
15	K	1	DAM 0						
16	K1		ROUTED OUTFLOW FROM BRUCKTON LAKE DAM						
17	Y			1	1				
18	Y1	1							
19	Y4	201	202	203	204	204.3	205	-201.0	-1
20	Y4	210						206	207
21	Y5	0	83	233	429	495	3675	12332	24050
22	Y5	70278							38163
23	Y4	0	85	126					54317
24	SE	194.3	201	210					
25	SS	201							
26	SD	204.3							
27	K	0	WALDO						
28	K1		INFLOW TO WALDO LAKE LESS BRUCKTON						
29	M	1	1	0.38	3.37				
30	P	0	21.5	111	124	133			
31	T						0.0	0.05	
32	V	1.25	0.5						
33	X	-1.7	-0.1	2					
34	K	2 TOTAL							
35	K1		COMBINE HYDROGRAPHS						
36	K	1	WALDO						
37	K1		ROUTED OUTFLOW FROM WALL LAKE						
38	Y			1	1				
39	Y1	1							
40	Y4	194.5	195.5	196.5	197.5	198.1	198.5	-194.5	-1
41	Y5	0	75	209	418	499	1500	199.5	200.5
42	Y4	77	137					200.5	201.5
43	SE	194.5	200					200.5	201.5
44	SS	194.5						200.5	201.5
45	SD	194.1						200.5	201.5
46	K	0	UPPER						
47	K1		INFLOW TO UPPER PORTER POND LESS WALDO LAKE						
48	M	1	1	0.11	0	3.37			
49	P	0	21.5	111	124	133			
50	T						0.0	0.05	

WUN DATEO 02/12/89.
TIMEO 10.36.59.

HYDROLOGIC ANALYSIS OF LOWER PORTER POND
NATIONAL DAM SAFETY PROGRAM
NEW ENGLAND DIVISION - CORPS OF ENGINEERS

[illegible]

MULTI-PLAN ANALYSES TO BE PERFORMED
~~NPLAN-1-NR10-1-TRIVS-1~~

NO INFLOW → RFIOS= 0.00

HYDROGRAPH ROUTING

ROUTED FROM LOWER PORTER-POND---

ISTAG	ICOMP	IECON	IYAPE	JPLT	JPRI	INAME	ISTAGE	IAUTO
1	1	0	0	0	0	1	0	0

ROUTING DATA

QLOSS	CLOSS	AVG	IRES	ISAME	IOPT	IPMP	LSTR
-------	-------	-----	------	-------	------	------	------

NSRPS	NSSTUL	LAG	AMSKK	X	TSK	STORA	ISPRAT
-------	--------	-----	-------	---	-----	-------	--------

168.00	} STAGE-DISCHARGE DATA FOR LOWER PORTER POND DAM
17009.00	

SINCE - 303415

STAGE - STORAGE DAM FOR
LOWE'S PORTER POND DAM

ELEVATION=	151.	160.	170.
------------	------	------	------

CHEL	SPLIT	CUMW	PXW	ELEM	COOL	CAREA	EXPL
	→ 160.0	0.0	0.0	0.0	0.0	0.0	0.0

TOP OF DAM ELEVATION → 163.0

DAM DATA	
COOD	EXPO
0.0	0.0
DAMWID	DAMHID
	0.0

D-27

WSEL FAILURE } BREACH DATA - FAILURE BEGINS IMMEDIATELY
3:00-103:00 WITH RESERVOIR SURFACE AT TOP OF DAM

PEAK BREACH DISCHARGE

THE UNIVERSITY OF CHICAGO

HYDROGRAPH ROUTING

LOWER PORTER POND BREACH THROUGH THIRTYACRE POND

ISFAD	ICOMP	IECON	ITAPE	JPLT	JPRF	INAME	ISTAGE	IAUTO
TPOND	1	0	0	0	0	1	0	0
ROUTING DATA								
GLSS	CLSS	AVG	IRFS	ISAME	IOPT	IPMP	LSTR	
0.0	0.000	0.00	1	1	0	0	0	
NSIPS								
1	0	0	0.000	0.000	0.000	0.000	-154.	-1

STAGE	154.00	155.00	156.00	157.00	158.00	159.00	160.00
FLOW	0.00	23.00	122.00	285.00	1951.00	4934.00	8775.00

STAGE-DISCHARGE DATA FOR THIRTYACRE POND DAM

SURFACE AREA= 26. 37. } STAGE-STORAGE DATA
CAPACITY= 0. 188. }
ELEVATION= 154. 160. } FOR THIRTYACRE POND DAM

SPILLWAY CREST ELEVATION → 154.0 CREL SPWID COOM EXPW ELEV COOL CAHEA EXPL
→ 154.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

DAM DATA
TOPEL COUD EXPD DAMWID
157.0 0.0 0.0 0.0

PEAK OUTFLOW IS 71. AT TIME 1.83 HOURS

ROUTED OUTFLOW AT THIRTYACRE POND DAM DUE TO BREACH OF LOWER PORTER POND DAM

HYDROGRAPH ROUTING

CHANNEL ROUTING TO HAZARD CENTER

ISFAD	ICOMP	IECON	ITAPE	JPLT	JPRF	INAME	ISTAGE	IAUTO
HAZARD	1	0	0	0	0	1	0	0
ROUTING DATA								
GLSS	CLSS	AVG	IRFS	ISAME	IOPT	IPMP	LSTR	
0.0	0.000	0.00	1	1	0	0	0	
NSIPS								
1	0	0	0.000	0.000	0.000	0.000	-1.	0

NORMAL DEPTH CHANNEL ROUTING

QV(1) QV(2) QV(3) ELNVT ELMAX RLNTH SEL } CHANNEL CHARACTERISTICS AT
 .0000 .0300 .0600 138.0 150.0 1200. .00800 } DOWNSTREAM DAMAGE AREA

CHANNEL INVERT ELEVATION

CROSS SECTION COORDINATES--STA+ELEV+STA+ELEV--ETC
 0.00 150.00 540.00 140.00 543.00 138.00 555.00 138.00 558.00 140.00 } CHANNEL CROSS-SECTION AT
 1100.00 140.00 1700.00 145.00 2300.00 150.00 } DOWNSTREAM DAMAGE AREA

STORAGE	0.00	112.05	135.81	.23	.48	161.49	189.08	.77	9.61	21.90	36.11	52.22	70.25	90.19
														394.77
OUTFLOW	0.00	33745.64	25.09	80.84	161.54	1004.34	3526.43	7268.17	12147.89	18133.02	25212.25	318.56	355.70	
			42660.04	53046.06	64559.63	77215.15	91030.89	106025.57	122218.70	139430.39	158281.17			
STAGE	138.00	138.61	139.26	140.53	141.16	141.79	142.42	143.05	143.68					
	144.32	144.95	145.58	146.21	146.84	147.47	148.11	148.74	149.37					
FLOW	0.00	25.09	80.84	161.54	1004.34	3526.43	7268.17	12147.89	18133.02	25212.25				
	33385.64	42660.04	53046.06	64559.63	77215.15	91030.89	106025.57	122218.70	139430.39	158281.17				

MAXIMUM STAGE IS 139.1 → STREAM ELEVATION AT DAMAGE CENTER

.....

PRINTED IN U.S.A.

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1

ELEVATION
STORAGE
OUTFLOW

INITIAL VALUE
163.00
54.
489.

SPILLWAY CREST
160.00
24.
0.

TOP OF DAM
163.00
54.
488.

15

RATIO OF INF	MAXIMUM RESERVOIR W.S. ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
0.00	162.93	0.00	54.	489.	0.00	0.00	0.00

PEAK OUTFLOW DURING BREACHING

THIRTYACRE POND DAM

D-31

APPENDIX E

INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS

12-54
FD-35

INVENTORY OF DAMS IN THE UNITED STATES

IDENTITY NUMBER	DIVISION	STATE	COUNTY	CONGRESS DIST.	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE
MA 426 NED	MA 023 1				LOWER PORTER POND DAM	4205.0	7102.6	04 JAN 80

POPULAR NAME		NAME OF IMPONDMENT	
		LOWER PORTER POND	
REGION BASIN	RIVER OR STREAM	NEAREST DOWNSTREAM CITY - TOWN - VILLAGE	POPULATION
01 06	BEAVER BROOK	BROCKTON	0 90000

TYPE OF DAM	YEAR COMPLETED	PURPOSES	STRUCTURAL HEIGHT		IMPOUNDING CAPACITIES	
			EXISTING	PROPOSED	MAXIMUM	NORMAL
REGG	1932	R	12	12	54	24

DIST OWN FED R PHV/FED 8C8 A VER/DATE
NED N N N : N

REMARKS

D/S HAS	SPILLWAY LENGTH	MAXIMUM DISCHARGE (CFS)	VOLUME OF DAM (CY)	POWER CAPACITY INSTALLED (MW)	PROPOSED (MW)	NO. LENGTH	WIDTH	HEIGHT	THICKNESS
2	200 U 32	448	750						

OWNER	ENGINEERING BY	CONSTRUCTION BY
BROCKTON DEPT. PARKS & REC.	UNKNOWN	WORK PROJECTS ADMIN.

DESIGN		CONSTRUCTION		OPERATION		MAINTENANCE	
NONE		NONE		MA DEDE		MA DEDE	

INSPECTION BY	INSPECTION DATE	AUTHORITY FOR INSPECTION
O'BRIEN & GERE ENGINEERS INC.	17 OCT 79	PL 92-367

REMARKS
COMBINED SERVICE & AUX. SPILLWAY LENGTHS AT SAME CREST ELEV.

END

FILMED

7-85

DTIC