

MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS 1963-A

1

COASTAL BASIN
LYNN, MASSACHUSETTS

AD-A154 957

BIRCH POND DAM

MA 00237

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM



MMIC FILE COPY

215
ELECT
JUN 11 1985
G

DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASSACHUSETTS 02154

DISTRIBUTION STATEMENT A
Approved for public release
Distribution Unlimited

AUGUST 1978

85 5 22 052

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER MA 00237	2. GOVT ACCESSION NO. AD-A154 957	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Birch Pond Dam		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
6. NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		8. CONTRACT OR GRANT NUMBER(s)
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		12. REPORT DATE August 1978
		13. NUMBER OF PAGES 59
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Coastal Basin Lynn, Massachusetts Birch Brook		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The dam is "L" shaped, about 80 ft. long and 27 ft. high. The dam is in poor condition. The upstream face is overgrown and eroded, the embankment crest deteriorated and abused by improper usage. It falls within the small size category and in the high hazard category. Failure of the dam would cause a flood through a thickly settled area.		



RE PRODUCED AT GOVERNMENT EXPENSE
DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:

NEDED

Honorable Michael S. Dukakis
Governor of the Commonwealth of
Massachusetts
State House
Boston, Massachusetts 02133

NOV 28 1976

Dear Governor Dukakis:


I am forwarding to you a copy of the Birch Pond Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts. In addition, a copy of the report has also been furnished the owner, City of Lynn, Department of Public Works, Lynn, Massachusetts 01901, ATTN: Mr. Patrick McGrath, Superintendent of Water.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Quality Engineering for your cooperation in carrying out this program.

Sincerely yours,


JOHN P. CHANDLER
Colonel, Corps of Engineers
Division Engineer

Incl
As stated

BIRCH POND DAM

MA 00237

COASTAL BASIN
LYNN, MASSACHUSETTS

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By _____	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A/	

DTIC
COPY
INSPECTED
1

NATIONAL DAM INSPECTION PROGRAM

PHASE I INSPECTION REPORT

Identification No.: MA 00237
Name of Dam: Birch Pond Dam
Town: Lynn, Massachusetts
County and State: Essex County, Massachusetts
Stream: Birch Brook
Date of Inspection: July 7, 1978

BRIEF ASSESSMENT

The Birch Pond Dam is an over 100 year old earthfill structure with a core of puddled clay. It is "L" shaped, about 850 feet long and 27 feet high at maximum section. It has an 8-foot wide by 4-foot deep ungated sidehill spillway in the left abutment. The reservoir is part of the City of Lynn water supply system. Birch Pond receives water from another reservoir and pipes water to a City pumping station.

The dam is in poor condition. The upstream face is overgrown and eroded, the embankment crest deteriorated and abused by improper usage. The spillway contains growth and debris. Apart from an occasional motorbike trail, the downstream slopes are not eroded.


Owing to its height and impoundment volume, the dam falls within the small size classification. It is in the high hazard category and thus hydraulically analyzed using the full probable maximum flood.

Reservoir storage will reduce the maximum probable discharge of 613 cfs to a test flood of 420 cfs. The spillway can carry, before overtopping, about 190 cfs (45 percent of a test flood). In the event of a test flood, the embankment section would be overtopped by less than 3 inches, if at all. The threat of damage from overtopping at this dam is considered minimal.

A failure of the dam could result in a Peak Failure Outflow in the order of 42,500 cfs. Such a failure flood would flow through a thickly settled residential area and would undoubtedly cause much destruction and endanger human life.

Additional investigations or major modifications are not necessary. Remedial measures that should be implemented by the owner within one year after receipt of this Phase I Inspection Report are described in Section 7. The dam is in serious need of extensive maintenance. The upstream face should be restored, the crest brought to true grade and surfaced, erosion on the downstream face eliminated, and the spillway cleaned and improved.

The owner should also institute a regular inspection and maintenance program and develop a flood warning system.



Gustav A. Diezemann, P. E.
New York State Lic. 027062

This Phase I Inspection Report on the Birch Pond Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.

Charles G. Tiersch

CHARLES G. TIERSCH, Chairman
Chief, Foundation and Materials Branch
Engineering Division

Fred J. Ravens, Jr.

FRED J. RAVENS, Jr., Member
Chief, Design Branch
Engineering Division

Saul Cooper

SAUL COOPER, Member
Chief, Water Control Branch
Engineering Division

APPROVAL RECOMMENDED:

Joe B. Fryar

JOE B. FRYAR
Chief, Engineering Division

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection, along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.


Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

TABLE OF CONTENTS

BRIEF ASSESSMENT	i
REVIEW BOARD SIGNATURE SHEET	iii
PREFACE	iv
TABLE OF CONTENTS	v
OVERVIEW PHOTO	vi
LOCATION MAP	vii
REPORT	
SECTION 1 - PROJECT INFORMATION	1
SECTION 2 - ENGINEERING DATA	5
SECTION 3 - VISUAL INSPECTION	6
SECTION 4 - OPERATING PROCEDURES	8
SECTION 5 - HYDRAULIC/HYDROLOGIC	9
SECTION 6 - STRUCTURAL STABILITY	10
SECTION 7 - ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	11
APPENDIX A - VISUAL INSPECTION CHECKLIST	
APPENDIX B - EXISTING RECORDS	
APPENDIX C - PHOTOGRAPHS	
APPENDIX D - HYDRAULIC COMPUTATIONS	
APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS	



OVERVIEW PHOTO



BIRCH POND

BOSTON NORTH and LYNN, MASS.
Scale 1:24000

PHASE I INSPECTION REPORT

BIRCH POND DAM

SECTION I

PROJECT INFORMATION

1.1 General

a. Authority. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Chas. T. Main, Inc. has been retained by the New England Division to inspect and report on selected dams in the State of Massachusetts. Authorization and notice to proceed were issued to Chas. T. Main, Inc. under a letter of May 3, 1978, from Ralph T. Garver, Colonel, Corps of Engineers. Contract No. DACW33-78-D328 has been assigned by the Corps of Engineers for this work.

b. Purpose.

(1) Perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interests.

(2) Encourage and prepare the states to initiate quickly effective dam safety programs for non-Federal dams.

(3) To update, verify and complete the National Inventory of Dams.

1.2 Description of Project

a. Location. The Birch Pond Dam is in the City of Lynn, Essex County, Massachusetts.

b. Description of Dam and Appurtenances. The 105 year old dam, which was raised 94 years ago (1884), is an earthfill embankment with a puddled clay core, a 27-foot maximum height, and 850 feet long. The spillway structure narrows to a channel about 8 feet wide and 4 feet deep before discharging into a steep, rock-lined channel. The outlet

INSPECTION CHECK LIST

PROJECT BIRCH POND

DATE July 6, 1978

PROJECT FEATURE _____

NAME _____

AREA EVALUATED	CONDITION
<u>DIKE EMBANKMENT</u>	72 ±
Crest Elevation	EL 72
Current Pool Elevation	El. 62 ±
Surface Cracks	none
Pavement Condition	none
Movement of Settlement of Crest	none
Lateral Movement	none
Vertical Alignment	O.K.
Horizontal Alignment	O.K.
Condition at Abutment and at Concrete Structures	
Indications of Movement of Structural Items on Slopes	none crest blocks moved on U/s face
Trespassing on Slopes	
Sloughing or Erosion of Slopes or Abutments	trees growing on U/s slope
Rock Slope Protection - Riprap Failures	Rip rap sloughed off
Unusual Movement or Cracking at or near Toes	-
Unusual Embankment or Downstream Seepage	none
Piping or Boils	none
Foundation Drainage Features	-
Toe Drains	-
Instruments on System	

VISUAL INSPECTION CHECK LIST
PARTY ORGANIZATION

PROJECT Birch Pond

DATE JULY 6, 1978

TIME 1:30 P.M.

WEATHER WARM & SUNNY

W.S. ELEV. 62± U.S. _____ DN.S _____

PARTY:

1. J. GOODRICH
2. D. FISCHER
3. _____
4. _____
5. _____

	PROJECT FEATURE	INSPECTED BY	REMARKS
1.	_____	_____	_____
2.	_____	_____	_____
3.	_____	_____	_____
4.	_____	_____	_____
5.	_____	_____	_____
6.	_____	_____	_____
7.	_____	_____	_____
8.	_____	_____	_____
9.	_____	_____	_____
10.	_____	_____	_____

APPENDIX A

(5) The owner should then develop and implement procedures which would include annual inspection of the dam and the initiation of repairs, including the repair of all spalled concrete and the repair and painting of the service bridge as required.

(6) Around the clock surveillance should be provided by the owner during periods of unusually heavy precipitation.

(7) The owner should develop a formal warning system with local officials for alerting downstream residents in case of emergency.

SECTION 7

ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

7.1 Dam Assessment

- a. Condition. The condition of Birch Pond Dam must be considered poor.
- b. Adequacy of Information. The lack of in-depth engineering data did not allow for a definitive review. Therefore, the adequacy of this dam could not be assessed from the standpoint of reviewing design and construction data, but is based primarily on visual inspection, past performance history and engineering judgment.
- c. Urgency. The required repair and maintenance work should be accomplished within one year of the receipt of this report by the owner.
- d. Need for Additional Investigation. There is no need for additional investigation.

7.2 Recommendations

Additional engineering investigations or major modifications to the dam are not required.

7.3 Remedial Measures

- a. Alternatives. Not applicable.
- b. Operating and Maintenance Procedures.
 - (1) Growth should be removed from the upstream face of this dam and the slope maintained against further erosion by the application of a heavy rock facing.
 - (2) The crest should be brought to true and level grade and surfaced.
 - (3) The spillway channel should be cleaned up and hydraulically improved as much as practicable.
 - (4) Motorbike trails on the downstream face should be filled and seeded and motorbiking on the dam should be stopped.

SECTION 6
STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations. Nothing was noted which would indicate that the dam is unstable.

b. Design and Construction Data. No design or construction data are available.

c. Operating Records. Not applicable.

d. Post Construction Changes. No data concerning any post construction changes are available.

e. Seismic Stability. This dam is located in Seismic Zone 3. Because of its configuration and condition and the low head of water retained, a seismic analysis is not considered warranted.

SECTION 5

HYDRAULIC/HYDROLOGIC

5.1 Evaluation of Features

a. Design Data. The hydraulic/hydrologic analysis was made in accordance with "Preliminary Guidance for Estimating Maximum Probable Discharges in Phase I Dam Safety Investigations", "Estimating Effect of Surcharge Storage on Maximum Probable Discharges", and "Rule of Thumb Guidance for Estimating Downstream Dam Failure Hydrographs" as furnished by the New England Division, Corps of Engineers and "Recommended Guidelines for Safety Inspection of Dams" as issued by the Department of the Army, Office of the Chief of Engineers.

U.S.G.S. Quadrangle maps were used to determine reservoir and drainage areas. Where practicable, spillway dimensions were obtained by direct measurement. Hydraulic coefficients were assigned on the basis of experience and engineering judgment.

b. Experience Data. No specific experience data with respect to the hydraulic/hydrological characteristics of the project are known to exist.

c. Visual Observations. Spillway channel is very rough. It could be cleaned up and improved. Beyond the dam, the rock-lined spillway channel is steep. Discharge would not threaten the dam.

d. Overtopping Potential. A Probable Maximum Flood (PMF) of 613 cfs was determined. Owing to its small size and high hazard classification, the PMF was used to determine the Peak Outflow (or test flood) of 420 cfs. The spillway can discharge 190 cfs before the embankment section is overtopped. The test flood would cause the spillway to be overtopped by about 3 inches. This height would actually not be achieved as spill during the flood period was not considered in the calculations. Despite its poor condition, the dam can be considered relatively safe from failure due to overtopping.

The Peak Failure Outflow, considering a 180-foot breach of the dam, is of an altogether different magnitude - about 42,500 cfs. This flood would discharge through a thickly settled residential area, resulting in flows as much as 5 feet in depth in the earlier reaches, much property destruction and, potentially, the loss of human life before it flowed into the Saugus River about a mile away.

The areas of impact immediately downstream of the dam are shown on the location map.

SECTION 4
OPERATIONAL PROCEDURES

4.1 Procedures

Birch Pond receives water by means of gravity flow from Walden Pond. Water level is maintained by gravity feed to the Walnut Street pumping station.

4.2 Maintenance of Dam

There appear to be no definite maintenance procedures of the dam in effect.

4.3 Maintenance of Operating Facilities

The gates controlling the outflows are maintained on a yearly basis, according to the owner.

4.4 Warning System

There is no warning system.

4.5 Evaluation

Apart from the daily operation to meet the water supply demands, the operational procedures are minimal. Maintenance of the dam and spillway could be improved. Recommendations for improving this situation are given in Section 7.3.

3.2 Evaluation

The visual inspection indicates that the Birch Pond Dam and appurtenances with the exception of the gate house structure, have been neglected with respect to maintenance. The dam and spillway are badly deteriorated and must be considered in poor condition. The reservoir itself is not a factor in evaluating the dam. The watercourse below the dam is inhabited to the extent that property and life would be in jeopardy if the dam failed.

SECTION 3

VISUAL INSPECTION

3.1 Findings

a. General. The Phase I visual inspection of the Birch Pond Dam was conducted on July 7, 1978. The dam is located at the end of a bowl, the left bank of which is hilly and wooded, and the right bank primarily a residential area. The dam is adjacent to a major artery and is unprotected and obviously misused by the public. The project is in obviously poor condition and state of maintenance.

b. Dam. The dam appears to be in poor condition. There are many areas on the upstream face where the riprap is sloughed off. In addition, the upstream slope is overgrown with vegetation. The downstream slope is eroded by an occasional motorbike trail. The embankment crest is deteriorated due to improper usage by motorbikes. Other than that caused by general deterioration, there appear to be no serious horizontal or vertical misalignments. There is no evidence of seepage through the embankment.

c. Appurtenant Structures. The spillway is somewhat deteriorated and overgrown and is hydraulically inefficient. The spillway channel immediately downstream of the dam is stone lined. Owing to releases through the gate house, the spillway has probably not seen much use over the years. It contains growth and debris.

The brick gate house appears to be in fair condition and, as releases are made to the Walnut Street pumping station, the gates and conduits are in operable condition.

d. Reservoir Area. The banks surrounding the reservoir area present little or no possibility of landslides into the reservoir or are there conditions which might result in a sudden increase of sediment load into the reservoir. There are no houses immediately adjacent to the reservoir.

e. Downstream Channel. Below the dam and the stone-lined spillway channel there is no defined watercourse. Flows resulting from a failure of the dam would pass over Walnut Street and through thickly settled residential areas before reaching the Saugus River.

SECTION 2
ENGINEERING DATA

2.1 Design

There are no known existing design data.

2.2 Construction

The Birch Pond dam was built in 1873 and raised in 1884. There are no detailed construction records available.

2.3 Operation

Some flow data are kept but are not relevant to this investigation.

2.4 Evaluation

a. Availability. There are no engineering data available.

b. Adequacy. The lack of in-depth engineering data does not allow for a definitive review. Therefore, the adequacy of this dam, structurally and hydraulically, cannot be assessed from the standpoint of review of design calculations, but must be based primarily on the visual inspection, past performance history, and sound hydrologic and hydraulic engineering judgment.

c. Validity. N/A

g. Dam

(1)	Type	Earthfill
(2)	Length	850 ± feet
(3)	Height	27 ± feet
(4)	Top Width	17 ± feet
(5)	Side slope	Unknown
(6)	Zoning	Unknown
(7)	Impervious core	Puddled clay
(8)	Cutoff	Unknown
(9)	Grout curtain	Unknown
(10)	Other	N/A

h. Spillway

(1)	Type	Sidehill Channel
(2)	Length of weir	N/A
(3)	Crest elevation	El. 63 ±
(4)	Gates	None
(5)	U/S Channel	Stone
(6)	D/S Channel	Stone-lined
(7)	General	N/A

i. Regulating Outlets. The regulating outlets consist of two gated conduits of 22 and 30-inch diameter, operated from a gate house.

c. Elevation (Feet Above MSL)

(1)	Top of dam	El. 67 ±
(2)	Maximum design surcharge	El. 67 ±
(3)	Full flood control pool	N/A
(4)	Recreation pool	N/A
(5)	Spillway crest (gated)	El. 63 (ungated)
(6)	Upstream portal invert diversion tunnel	N/A
(7)	Streambed at centerline of dam	El. 40 ±
(8)	Maximum tailwater	N/A

d. Reservoir (Feet)

(1)	Length of maximum pool	5,000
(2)	Length of recreation pool	N/A
(3)	Length of flood control pool	N/A

e. Storage (Acre-Feet)

(1)	Recreation pool	950 ±
(2)	Flood control pool	N/A
(3)	Design surcharge	1,300 ±
(4)	Top of dam	1,300 ±

f. Reservoir Surface (Acres)

(1)	Top of dam	96
(2)	Maximum pool	96
(3)	Flood control pool	N/A
(4)	Recreation pool	N/A
(5)	Spillway crest	82

works offshore of the dam provide gravity flow to the City's Walnut Street pumping station. Birch Pond receives gravity flow from Walden Pond.

c. Size Classification. Owing to its height of 27 feet and its impoundment of approximately 950 acre feet below the crest, the dam falls within the small category.

d. Hazard Classification. The area below the dam which would be endangered if the dam failed is urban in nature. The dam is considered to have a high hazard potential.

e. Ownership. The dam is owned by the City of Lynn, Massachusetts.

f. Operator. Mr. Patrick McGrath, Superintendent of Water, Department of Public Works, Lynn, Massachusetts, (617) 592-7900, Ext. 242.

g. Purpose of Dam. The reservoir impounded by the dam is part of the City of Lynn's water supply system.

h. Design and Construction History. Nothing is known of the design and construction history of this project except that the original dam was raised almost a hundred years ago.

i. Normal Operating Procedures. The water level is normally kept below the spillway level by means of releases to the City's Walnut Street pumping station. Inflows exceeding outflow and storage capabilities would discharge through the spillway.

1.3 Pertinent Data

a. Drainage Area. The Birch Pond Reservoir has a drainage area of approximately 0.7 square miles of partly residential and partly wooded areas.

b. Discharge at Damsite.

(1) The outlet structure houses gates controlling 22 and 36-inch lines to the Walnut Street pumping station.

(2) The maximum known flood at the damsite is unknown.

(3) The ungated spillway capacity at maximum pool is about 190 cfs, or approximately 45 percent of the test flood.

(4) There is no gated spillway capacity.

(5) There is no gated spillway capacity.

(6) The total spillway capacity at maximum pool is 190 cfs.

INSPECTION CHECK LIST

PROJECT BIRCH PONDDATE JULY 6, 1978

PROJECT FEATURE _____

NAME _____

AREA EVALUATED	CONDITION
<p><u>CONCRETE DAM</u></p> <p>Concrete Surfaces</p> <p>Structural Cracking</p> <p>Movement -- Horizontal & Vertical Alignment</p> <p>Junctions</p> <p>Drains -- Foundation, Joint, Face</p> <p>Water Passages</p> <p>Seepage or Leakage</p> <p>Monolith Joints -- Construction Joints</p> <p>Foundation</p>	<p><i>NOT APPLICABLE</i></p> <p>3</p>

INSPECTION CHECK LIST

PROJECT BIRCH POND

DATE JULY 6, 1978

PROJECT FEATURE _____

NAME _____

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE</u></p> <p>a. Approach Channel</p> <p style="padding-left: 40px;">Slope Conditions</p> <p style="padding-left: 40px;">Bottom Conditions</p> <p style="padding-left: 40px;">Rock Slides or Falls</p> <p style="padding-left: 40px;">Log Boom</p> <p style="padding-left: 40px;">Debris</p> <p style="padding-left: 40px;">Condition of Concrete Lining</p> <p style="padding-left: 40px;">Drains or Weep Holes</p> <p>b. Intake Structure</p> <p style="padding-left: 40px;">Condition of Concrete</p> <p style="padding-left: 40px;">Stop Logs and Slots</p>	<p style="text-align: center; font-size: 2em;"><i>NOT APPLICABLE</i></p> <p style="text-align: right; font-size: 2em;">4</p>

INSPECTION CHECK LIST

PROJECT BIRCH POND

DATE JULY 6, 1978

PROJECT FEATURE _____

NAME _____

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - TRANSITION AND CONDUIT</u></p> <p>General Condition of Concrete</p> <p>Rust or Staining on Concrete</p> <p>Spalling</p> <p>Erosion or Cavitation</p> <p>Cracking</p> <p>Alignment of Monoliths</p> <p>Alignment of Joints</p> <p>Numbering of Monoliths</p>	<p style="text-align: center;">NOT APPLICABLE</p> <p style="text-align: right;">5</p>

INSPECTION CHECK LIST

PROJECT BIRCH POND

DATE JULY 6, 1972

PROJECT FEATURE _____

NAME _____

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u></p> <p>a. Approach Channel</p> <p> General Condition</p> <p> Loose Rock Overhanging Channel</p> <p> Trees Overhanging Channel</p> <p> Floor of Approach Channel</p> <p>b. Weir and Training Walls</p> <p> General Condition of Concrete</p> <p> Rust or Staining</p> <p> Spalling</p> <p> Any Visible Reinforcing</p> <p> Any Seepage or Efflorescence</p> <p> Drain Holes</p> <p>c. Discharge Channel</p> <p> General Condition</p> <p> Loose Rock Overhanging Channel</p> <p> Trees Overhanging Channel</p> <p> Floor of Channel</p> <p> Other Obstructions</p>	<p><i>Some spalling</i></p> <p><i>Some</i></p> <p><i>-No</i></p> <p><i>No</i></p> <p><i>-</i></p> <p><i>} debris & vegetation in channel</i></p> <p style="text-align: right;"><i>6</i></p>

INSPECTION CHECK LIST

PROJECT BIRCH POND

DATE JULY 6, 1978

PROJECT FEATURE _____

NAME _____

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - CONTROL TOWER</u></p> <p>a. Concrete and Structural</p> <p> General Condition</p> <p> Condition of Joints</p> <p> Spalling</p> <p> Visible Reinforcing</p> <p> Rusting or Staining of Concrete</p> <p> Any Seepage or Efflorescence</p> <p> Joint Alignment</p> <p> Unusual Seepage or Leaks in Gate Chamber</p> <p> Cracks</p> <p> Rusting or Corrosion of Steel</p> <p>b. Mechanical and Electrical</p> <p> Air Vents</p> <p> Float Wells</p> <p> Crane Hoist</p> <p> Elevator</p> <p> Hydraulic System</p> <p> Service Gates</p> <p> Emergency Gates</p> <p> Lightning Protection System</p> <p> Emergency Power System</p> <p> Wiring and Lighting System</p>	<p style="text-align: center;"><i>NOT APPLICABLE</i></p> <p style="text-align: right;">7</p>

INSPECTION CHECK LIST

PROJECT BIRCH PONDDATE JULY 6, 1978

PROJECT FEATURE _____

NAME _____

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL (Gate House)</u>	
General Condition of Concrete	POOR
Rust or Staining	SOME
Spalling	SOME
Erosion or Cavitation	-
Visible Reinforcing	NONE
Any Seepage or Efflorescence	NONE
Condition at Joints	O.K.
Drain holes	NONE
Channel	N/A
Loose Rock or Trees Overhanging Channel	N/A
Condition of Discharge Channel	

INSPECTION CHECK LIST

PROJECT BIRCH PONDDATE JULY 6, 1978

PROJECT FEATURE _____


NAME _____

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - SERVICE BRIDGE</u>	
a. Super Structure	
Bearings	O.K.
Anchor Bolts	O.K.
Bridge Seat	O.K.
Longitudinal Members	O.K.
Under Side of Deck	-
Secondary Bracing	-
Deck	O.K.
Drainage System	-
Railings	NONE
Expansion Joints	-
Paint	IN NEED OF PAINT
b. Abutment & Piers	
General Condition of Concrete	POOR
Alignment of Abutment	O.K.
Approach to Bridge	
Condition of Seat & Backwall	O.K.
9	

APPENDIX B

Only a few drawings were available.

Excerpts from these drawings follow.




DEPARTMENT OF WATER SUPPLY
CITY OF LYNN

THOMAS W. HEATH, COMMISSIONER.

OPERATION OF SUPPLY SYSTEM
1940

OF LYNN ARE
TO A PRIOR MILL RIGHT TO 10,000,000 GALS. PER DAY.



LYNNFIELD ST. STANDPIPE.
CAP. 1,280,000 GALS. 80'x30' ELL. 269'
FEEDS LYNNFIELD, WYOMA, & INTER-
CONNECTED WITH PINE HILL STANDPIPE
& HIGH SERVICE GRIDIRON.

NOTE.
STANDPIPES.

2-12" LINES FROM THE PUMPING STATION
JOIN A 16" LINE FROM WHICH A 12" LINE EX-
TENDS TO THE INLET OF THE PINE-HILL
STANDPIPE. IT HAS A 12" OUTLET &
ALSO 12" BY-PASS FOR PUMPING AROUND
DIRECT TO DISTRIBUTION.
LYNNFIELD STREET. STANDPIPE HAS 12"
INLET & OUTLET & ACTS AS A BALANCE
BETWEEN THE TWO STANDPIPES & THE
S. SYSTEM. THE H.S. SYSTEM IS SE-
PARATED FROM L.S. SYSTEM BY A SERIES
OF GATES BUT BY THEIR OPERATION H.S.
CAN BE FED BY L.S. AT REDUCED PRESSURE.
DAILY H.S. CONSUMPTION. 900,000 GALS.

RESERVOIR
CAP. 20,000,000 GALS.
ELL. 269'

PINE HILL STANDPIPE
CAP. 500,000 GALS. ELL. 269'
HIGH SERVICE. FEEDS
PINE HILL & HIGHLANDS.


POND.
2,000,000,000 GALS.

GLEN LEWIS STATION PUMPS 16,500,000 GALS. PER
DAY TO BREEDS POND.

36" PUMP LINE TO BREEDS POND
GRAVITY LINE IF BREEDS LOWERED 7FT.

THE RESERVOIR ACTS AS A
EQUALIZER FOR THE L.S.
INLET & OUT-LET AT THE WESTERN
END BEING THRU 1-20" & 1-30"
BOTH OF WHICH CONNECT AT THE
PUMPING STATION WITH SUPPLY
LINES TO THE DISTRIBUTING
SYSTEM. A 80" WHICH IS CON-
NECTED BY A 20" BY-PASS FROM
THE WESTERN LINES LEAVES
THE EASTERN END OF THE RES.
TO THE L.S. GRIDIRON.

BREEDS POND
CAP. 1,600,000,000 DAILY L.S. CONSUMPTION
7,500,000 GALS.



LORETZ
WALNUT ST. STATION


6250 FT BIRCH POND TO PUMPING STATION. GRAVITY FLOW.

36"
2-LINES 20 & 36" BREEDS TO PUMPING STATION
GRAVITY FLOW

22"

30"

APPENDIX C




PLAN
BIRCH POND



2


Upstream Face of Dam



3

Collapse of Upstream Block

BIRCH POND



4

Downstream Embankment



5

Downstream Spillway Channel



6

View of Reservoir and Shoreline from Dam



7


Hole at Junction of Granite Block and Crest

APPENDIX D


DMF = 613 cfs
 RES A = 82 AC
 Dr. A = .686 mi² = 439 AC

SPILLWAY RATING

EFF L = 600'



H	Q	Q _{TOT}
2	68	68
4	192	192
5	268 + 1350	1618
4.6	353 + 3520	4173



$$S_1 = 4.4'$$

$$STOR_1 = \frac{4.4 (12)(82)}{439} = 9.86''$$

$$Q_{P2} = 613 \left(1 - \frac{9.86}{19}\right) = 295 \text{ cfs.}$$

$$S_2 = 4.10'$$

$$STOR_2 = \frac{4.10 (12)(82)}{439} = 9.19''$$

$$STOR_{AVE} = 9.53''$$

DAM OVERTOPPED BY ONLY .25' HOWEVER
 THIS DAM SEEMED TO BE IN VERY BAD REPAIR - MUCH
 erosion has
 taken place already

$$S_{AVE} = \frac{(9.53)(439)}{(12)(82)} = 4.25'$$

$$Q_{P3} = 420 \text{ cfs (NOT A GOOD EST.)}$$

USING ANOTHER ITERATION

$$Q_{P3} = 613 \left(1 - \frac{9.53}{19}\right) = 306 \text{ cfs. } S = 4.13'$$

$$STOR_3 = \left(\frac{4.13}{4.10}\right) 9.19'' = 9.56''$$

$$Q_{P4} = 613 \left(1 - \frac{9.56}{19}\right) = 305 \text{ cfs}$$

PEAK FAILURE OUTFLOW $H = 27'$ $L = 600'$

$$S = 27 (82)(.5) = 1107 \text{ AC.FT.}$$

$$Q_{P1} = \frac{S}{27} (180)(\sqrt{32.2})(27)^{1.5} = 42,460 \text{ cfs}$$

$$y_0 = 27$$

$$W_b = .3(600) = 180$$

$$P.F.O = 42,460 + 192 = 42,652 \text{ cfs.}$$

Client C of E
 Subject LIRCH FOND

Job No. 1345-065 Sheet 3 of 8
 By VEITCH Date 10 AUG. 1976
 Ckd. _____ Rev. _____

I	A	E A	WP.
50	-	-	200
55	1625	1625	450
60	2750	4375	650
65	3375	7750	700

II			
50	1000	1000	350
55	2975	3975	640
60	3263	7236	665
65	3413	10650	700

III			
40	2500	2500	1000
45	5375	7875	1150
50	6000	13875	1250
55	6375	20250	1300
60			

Plan # 1 EL. $Q = \frac{1.49}{11} AR^{2/3} S^{3/2}$

$S = .01$ 50 $Q = \frac{1.49}{.028} (500) \left(\frac{500}{275} \right)^{2/3} \sqrt{.01} = 3,970 \text{ cfs.}$
 $R = .028$

55 $Q = \frac{1.49}{.028} (2800) \left(\frac{2800}{595} \right)^{2/3} \sqrt{.01} = 44,600 \text{ cfs.}$




60 $Q = \frac{1.49}{.028} (5807) \left(\frac{5807}{658} \right)^{2/3} \sqrt{.01} = 132,925 \text{ cfs.}$

Reach # 2 40 $Q = \frac{1.49}{.028} (1250) \left(\frac{1250}{500} \right)^{6/7} \sqrt{.017} = 16,025 \text{ cfs.}$
 $S = .017$

$R = .028$ 45 $Q = \frac{1.49}{.028} (3938) \left(\frac{3938}{575} \right)^{6/7} \sqrt{.017} = 99,170 \text{ cfs.}$

50 $Q = \frac{1.49}{.028} (7438) \left(\frac{7438}{800} \right)^{6/7} \sqrt{.017} = 229,890 \text{ cfs.}$


Client Cof E Job No. 1345-065 Sheet 4 of 8
Subject BIRCH POND By J. Vatch Date 10 AUG 1978
Ckd. _____ Rev. _____



Client C of E
Subject BIRCH POND

Job No. 1345-065 Sheet 5 of 8
By J. VEITCH Date 10 AUG. 1975

Ckd. _____ Rev. _____



Client C of E

Job No. 1345-065 Sheet 6 of 8

Subject URCH FOND

By Veitch Date 10 AUG 1978

Ckd. _____ Rev. _____

PFC CRITICAL:

$Q_p = 42,652 \text{ cfs}$ URCH 1 EL. = 54.8'

$V_1 = \frac{58}{9} \left(\frac{2800(320)}{43560} \right) = 18.9 \text{ AC FT}$

$Q_{p2} (\text{TRIAL}) = 42652 \left(1 - \frac{18.9}{1107} \right) = 41,924 \text{ cfs.}$

NEGLECT V_1 .

$Q_{p2} = 42652 \text{ cfs}$ EL. 42.0

$V_1 = \frac{7}{10} \left(\frac{3940(700)}{43560} \right) = 49.3 \text{ AC FT.}$

$Q_{p2} (\text{TRIAL}) = 42652 \left(1 - \frac{49.3}{1107} \right) = 40,857 \text{ cfs.}$

$V_2 = \frac{6.9}{7} (49.3) = 48.7 \text{ AC FT.}$

$V_{ave} = 44$

$Q_{p2} = 42652 \left(1 - \frac{44}{1107} \right) = 40,957 \text{ cfs}$

BREACH. 42,460 cfs.

Much flooding to residential AREA IN CHANNEL - heavily developed.
Walnut St flooded, some hazard to life due to population density.

Test Flood 305 cfs.

Flooding basin below dam, eventually flooding Walnut St.
Minor flooding to RESIDENCES IN close proximity.

Client CORP OF ENGRS

Job No. 1345-065 Sheet 7 of 8

Subject - BIRCH POND -

By J VEITCH Date 25 SEPT. 1978

Ckd. _____ Rev. _____

TEST FLOOD.

$$Q_{P3} = 305 \text{ cfs} \quad \text{REACH \#1} \quad \text{EL. } 50.0'$$

$$V_1 = \frac{4.0}{9.0} (500) \frac{300}{93560} = 3.44 \text{ AC FT.}$$


$$Q_{P2}(\text{TRIAL}) = 305 \left(1 - \frac{3.44}{1107}\right) = 304$$

Neglect Vol

$$Q_{P1}(\text{into REACH 2}) = 305 \text{ cfs}$$

the volume within the reaches at the flood level of this magnitude is minimal \therefore it is a fair approximation to assume a flow of 306 cfs. throughout.

Client COFE Job No. 1345-065 Sheet 8 of 8
Subject BIRCH By J VETCH Date 25 AUG. 1978
CAPACITY CURVE Ckd. _____ Rev. _____



APPENDIX E
INFORMATION AS CONTAINED IN
THE NATIONAL INVENTORY OF DAMS



INVENTORY OF DAMS IN THE UNITED STATES

IDENTITY NUMBER	CONGR. DIST.	CONGR. STATE	CONGR. COUNTY	CONGR. DIST.	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE DAY MO YR
MA 237 MED	MA 009 06				BIRCH POND DAM	4228.5	7058.6	08SEP78

POPULAR NAME	NAME OF IMPOUNDMENT		
	BIRCH POND		
REGION	RIVER OR STREAM	NEAREST DOWNSTREAM CITY - TOWN - VILLAGE	POPULATION
U106	TH SAUGUS RIVER	LYNN	0 90000

TYPE OF DAM	YEAR COMPLETED	PURPOSES	STRUCT. HEIGHT (FT.)	HYDRAU. HEIGHT (FT.)	IMPOUNDING CAPACITIES		DIST. ORN. N	FED. R. N	PRY/PED. N	SC8. A N	VER/DATE N
					MAXIMUM (ACRE-FT.)	NORMAL (ACRE-FT.)					
RECTPG	1872	S	27	27	1100	1100	1100	MEU	N	N	30AUG78

REMARKS

D/S HAS	SPILLWAY CREST LENGTH (FT.)	MAXIMUM DISCHARGE (CFS)	VOLUME OF DAM (CU FT.)	POWER CAPACITY (MW)	INSTALLED PROPOSED (MW)	LENGTH (FT.)	WIDTH (FT.)	LENGTH (FT.)	WIDTH (FT.)
1	600	U	8	190	45000				

OWNER	ENGINEERING BY	CONSTRUCTION BY
CITY OF LYNN		

DESIGN	CONSTRUCTION	OPERATION	MAINTENANCE
NONE	NONE	NONE	NONE

INSPECTION BY	INSPECTION DATE DAY MO YR	AUTHORITY FOR INSPECTION
CHAS. T. MAIN, INC	07JUL78	PL 92-367

REMARKS

END

FILMED

7-85

DTIC