

AD-A156 123


NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
LAKE GLORINETTE DAM AM. (U) CORPS OF ENGINEERS WALTHAM
MA NEW ENGLAND DIV AUG 79


1/1

UNCLASSIFIED

F/G 13/13

NL





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

AD-A156 123

CONNECTICUT RIVER BASIN
DIXVILLE, NEW HAMPSHIRE

LAKE GLORINETTE DAM AND DIKE
NH00171 & 00168

STATE NO 65.02 & 65.01

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

Copy available to DTIC does not
permit fully legible reproduction



DTIC
SELECTED
JUL 08 1985
S D
G

DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASS. 02154

DTIC FILE COPY

DISTRIBUTION STATEMENT A
Approved for public release;
Distribution Unlimited

AUGUST 1979

85 06 12 053

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NH 00171/00168	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Lake Gloriette Dam and Dike NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS	5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT	
	6. PERFORMING ORG. REPORT NUMBER	
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION	8. CONTRACT OR GRANT NUMBER(s)	
9. PERFORMING ORGANIZATION NAME AND ADDRESS	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS	
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254	12. REPORT DATE August 1979	
	13. NUMBER OF PAGES 68	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)	15. SECURITY CLASS. (of this report) UNCLASSIFIED	
	15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Connecticut River Basin Dixville, New Hampshire Lake Gloriette		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) -The dam has a hydraulic height of 33 ft. and is 100 ft. long. It is an earthen embankment with a roadway running along the crest. The dam and dike are in fair condition. There are various concerns which should be corrected. It is small in size with a significant hazard potential for the dam and low hazard for the dike. A major breach at top of dam could result in appreciable damage to farmland as well as the possible loss of sections of Rt. 26, which would be subjected to erosive velocities.-		

DISCLAIMER NOTICE

THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

NATIONAL DAM INSPECTION PROGRAM
PHASE I INSPECTION REPORT

Identification No.: NH00171 and NH00168
Name of Dam: Lake Gloriette Dam and Dike
Town: Dixville
County and State: Coos County, New Hampshire
Lake: Lake Gloriette
Date of Inspection: June 7, 1979

BRIEF ASSESSMENT

Lake Gloriette Dam has a hydraulic height of 33 feet, is 32 feet wide at the crest, and is 100 feet long. It is an earthen embankment with a roadway running along the crest. The spillway discharges into a corrugated metal arch pipe which measures 7' 7" H x 11' 10" W. This conduit runs downstream for a length of about 75 feet with a slope of approximately 24%.

Located approximately 1000 feet north of Lake Gloriette Dam is Lake Gloriette Dike. The dike has a hydraulic height of 34', is 43' wide at the crest, and is 240 feet long. It is an earth embankment with a paved roadway along its crest. A 3' x 3' square masonry conduit extends under the road through the dike embankment and has been plugged at its downstream end.

The dam and dike are located in northern New Hampshire and combine to impound Lake Gloriette. Lake Gloriette is used for recreational purposes by the Balsams Hotel. It has a maximum storage capacity of about 640 acre-feet. Normal pool is approximately 1600 feet in length with a surface area of about 26 acres.

The dam and dike are in fair condition. Major concerns are: the absence of a dewatering facility, the existence of an open conduit under the crest of the dike which has its downstream end buried under fill, the presence of a trench for a TV cable on the downstream slope of the dike, the growth of brush and trees in several spots on the upstream and downstream slopes of the dam and dike, the erosion of the upstream slope of the dam on both sides of the concrete spillway entrance structure, the evidence of minor settlement and cracking of the roadway pavement on the crest of the dam, and an animal burrow on the downstream slope of the dike.

Based on small size for the dam and dike and a significant hazard classification for the dam (low hazard for the dike) in accordance with Corps guidelines, the test flood is $\frac{1}{2}$ the Probable Maximum Flood (PMF). A test flood outflow of 2350 cfs (1300 csm) would overtop the dam by 1.7 feet and the dike by 1.2 feet. The spillway will pass 820 cfs or about 35 percent of the test flood.

A major breach at top of dam could result in appreciable damage to farmland as well as the possible loss of sections of Route 26 which would be subjected to erosive velocities.

The Balsams, Inc. should implement the results of recommendations and remedial measures given in Sections 7.2 and 7.3 within one year after receipt of this Phase I Inspection Report.

Warren A. Guinan
Warren A. Guinan
Project Manager
N.H. P.E. 2339

Accession For		<input checked="" type="checkbox"/>
NTIS GRA&I		<input checked="" type="checkbox"/>
DTIC TAB		<input checked="" type="checkbox"/>
Unannounced		<input type="checkbox"/>
Justification		
By		
Distribution/		
Availability Codes		
Dist	Avail and/or Special	
<i>A/1</i>	<i>23</i>	<i>cont</i>



PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

TABLE OF CONTENTS

Title	Page
LETTER OF TRANSMITTAL.....	
BRIEF ASSESSMENT.....	
REVIEW BOARD PAGE.....	
PREFACE.....	v
TABLE OF CONTENTS.....	vi
OVERVIEW PHOTO.....	vii
LOCATION MAP.....	viii

REPORT

Section

1	PROJECT INFORMATION.....	1-1
	1.1 General.....	1-1
	1.2 Description of Project.....	1-1
	1.3 Pertinent Data.....	1-3
2	ENGINEERING DATA.....	2-1
	2.1 Design.....	2-1
	2.2 Construction.....	2-1
	2.3 Operation.....	2-1
	2.4 Evaluation.....	2-1
3	VISUAL INSPECTION.....	3-1
	3.1 Findings.....	3-1
	3.2 Evaluation.....	3-3
4	OPERATIONAL PROCEDURES.....	4-1
	4.1 Procedures.....	4-1
	4.2 Maintenance of Dam.....	4-1
	4.3 Maintenance of Operating Facilities.....	4-1
	4.4 Description of Any Warning System in Effect.....	4-1
	4.5 Evaluation.....	4-1
5	HYDROLOGIC/HYDRAULIC.....	5-1
	5.1 Evaluation of Features.....	5-1
6	STRUCTURAL STABILITY.....	6-1
	6.1 Evaluation of Structural Stability.....	6-1
7	ASSESSMENT, RECOMMENDATIONS & REMEDIAL MEASURES.....	7-1
	7.1 Dam Assessment.....	7-1
	7.2 Recommendations.....	7-2
	7.3 Remedial Measures.....	7-2
	7.4 Alternatives.....	7-2


APPENDICES

Designation

VISUAL INSPECTION CHECKLIST.....	A
ENGINEERING DATA.....	B
PHOTOGRAPHS.....	C
HYDROLOGIC AND HYDRAULIC COMPUTATIONS.....	D
INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS..	E



Figure 1 - Overview of Lake Gloriette Dam.



Map prepared by permission of the Department of Resources and Economic Development, Concord, N.H. 03301, and the copyright owners, The United States Geological Survey, Chester, VT. 0-17-76.

SCALE IN MILES



MAP BASED ON STATE OF NEW HAMPSHIRE OFFICIAL HIGHWAY MAP.

Anderson-Nichols & Co., Inc.		U.S. ARMY ENGINEER DIV. NEW ENGLAND	
CONCORD		CORPS OF ENGINEERS	
NEW HAMPSHIRE		WALTHAM, MASS.	
NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS			
LAKE GLORIETTE DAM AND DIKE			
LOCATION MAP			
MOHAWK RIVER		NEW HAMPSHIRE	
		SCALE: SEE BAR SCALE	
		DATE: AUGUST 1974	

NATIONAL DAM INSPECTION PROGRAM
PHASE I INSPECTION REPORT
LAKE GLORIETTE DAM AND DIKE

SECTION 1
PROJECT INFORMATION

1.1 General

a. Authority. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Anderson-Nichols & Company, Inc. has been retained by the New England Division to inspect and report on selected dams in the State of New Hampshire. Authorization and notice to proceed were issued to Anderson-Nichols under a letter of March 22, 1979 from John P. Chandler, Colonel, Corps of Engineers. Contract No. DACW33-79-C-0050 has been assigned by the Corps of Engineers for this work.

b. Purpose.

(1) To perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interests.

(2) To encourage and prepare the States to initiate quickly effective dam safety programs for non-Federal dams.

(3) To update, verify and complete the National Inventory of Dams.

1.2 Description of Project

a. Location. The Lake Gloriette Dam and Dike are located in Dixville, New Hampshire in the Dixville Notch area. The project consists of an earthen dam and an earthen dike. It spans the headwaters of the Mohawk River to form Lake Gloriette, which is utilized for recreational purposes. The dam and dike are shown on the U.S.G.S. Quadrangle, Dixville, New Hampshire with coordinates approximately at N 44° 52' 05", W 71° 18' 23". (See Location Map page viii.)

In the New Hampshire Water Resources Board (NHWRB) files the dam is referred to as the south outlet to Lake Gloriette and the dike is referred to as the north outlet to Lake Gloriette.

b. Description of the Dam and Appurtenances. Lake Gloriette impoundment structures consist of an earthen dam and an earthen dike. The dam is the more southerly of the embankments and is the closer to Route 26. The dam is about 100 feet long. A paved section of roadway leading from Route 26 to the Balsams Hotel runs along the crest of both the dam and dike. The dam has a 19' concrete spillway with a 4.5' high and 4' wide stoplog section located at its center. The spillway discharges into a 7.7' H x 11' 10" W corrugated metal pipe arch which runs downstream for a length of about 75 feet at an approximate slope of 24%. The pipe arch discharges into a stream which becomes the Mohawk River further downstream.

The Lake Gloriette Dike is located approximately 1000 feet north of the dam. It is about 240 feet long. A 3' x 3' square stone masonry conduit runs under the paved road through the dike embankment, but has been plugged at its downstream end. The upstream end is filled almost to the crown. A television cable and 1" plastic pipe pass through the conduit. The Balsams Hotel golf course is located on the downstream side of the dike embankment.

c. Size Classification. Small (hydraulic height - 33 feet (dam) and 34 feet (dike) storage - 640 acre-feet) based on criteria (small size corresponds to an impoundment structure with height ≥ 25 and < 40 feet storage ≥ 50 and < 1000 acre-feet) in Recommended Guidelines for Safety Inspection of Dams.

d. Hazard Classification. Significant Hazard (dam). A major breach in the dam would result in appreciable damage to farms and farmland in the downstream Mohawk River floodplain; as well as loss of major sections of Route 26 that runs adjacent to the river. Low Hazard (dike). A major breach of the dike would result in flooding of the golf course below it which offers sufficient storage to preclude downstream damage.

e. Ownership. Lake Gloriette Dam and Dike are owned by the Balsams, Inc. and have been since their construction.

f. Operator. The current owner and operator of the dam and dike at Lake Gloriette is the Balsams, Inc., Dixville, New Hampshire 03528. Phone: (603) 255-3400. (Mr. Rouland Joulin is the resident maintenance manager).

g. Purpose of the Dam. This dam and dike impound Lake Gloriette, which is used for recreational purposes by the Balsams Hotel.

h. Design and Construction History. The Lake Gloriette Dam was reconstructed in 1968. The New Hampshire Department of Public Works and Highways (NHDPWH) designed and supervised the construction of the dam as part of the New Hampshire Route 26

reconstruction project. The construction was performed by
aledonia Sand and Gravel of St. Johnsbury, Vermont. Little
nformation was disclosed relating to the design and construction
f the original dam which was completed prior to 1913.

onstruction of the dike occurred concurrently with the original
am construction and was completed prior to 1913. Little
nformation was disclosed relating to its design and construc-
ion.

i. Normal Operating Procedures. No written operating
rocedures were disclosed for Lake Gloriette Dam and Dike.

.3 Pertinent Data

a. Drainage Area. The drainage area consists of 1.82 square
miles (1165 acres) of rolling to mountainous terrain.

b. Discharge at Damsite.

(1) Outlet works (conduits) - Concrete spillway dis-
charges in 7'7" H x 11'10" W corrugated metal pipe arch at invert
elevation 1845.0' MSL.

(2) The maximum discharge at damsite is unknown.

(3) Ungated spillway capacity @ maximum pool elevation -
320 cfs @ 1855.5' MSL.

(4) Ungated spillway capacity @ test flood elevation -
930 cfs @ 1857.2' MSL.

(5) Gated spillway capacity @ top of dam elevation -
not applicable.

(6) Gated spillway capacity @ test flood elevation -
not applicable.

(7) Total spillway capacity @ test flood elevation -
930 cfs @ 1857.2' MSL.

(8) Total project discharge @ test flood elevation -
2350 cfs @ 1857.2.

c. Elevation. (ft. above MSL)

(1) Top of dam - 1855.5

(2) Top of dike - 1856.0

(3) Test flood pool - 1857.2

SECTION 7
ASSESSMENT, RECOMMENDATIONS, AND REMEDIAL MEASURES

7.1 Dam Assessment

a. Condition. The visual examination indicates that Lake Gloriette Dam and Dike are in fair condition. The major concerns with respect to the integrity of the dam and dike, if left uncorrected, are:

(1) Existence of an open culvert under the crest of the dike with its downstream end buried under fill.

(2) Erosion of the upstream slope of the dam on both sides of the concrete spillway-entrance structure.

(3) Brush growing on the upstream slope near the north abutment of the dam.

(4) Trees growing on the north bank of the downstream channel of the dam immediately adjacent to the contact between the downstream slope and the dam abutment.

(5) Minor settlement and cracking of the roadway pavement on the crest of the dam.

(6) Trees growing on the downstream slope near the abutments of the dike.

(7) Brush growing on the upstream slope of the dike.

(8) Animal burrow on the downstream slope of the dike.

(9) Trench, backfilled with unknown material, for a TV cable laid under the downstream slope of the dike.

b. Adequacy of Information. The information available is such that the assessment of this dam and dike must be based primarily on the NHDPWH plans and sketches for the dam and on the results of the visual inspection.

c. Urgency. The recommendations made in 7.2 and 7.3 below should be implemented by the owner within one year after receipt of this Phase I report.

d. Need for Additional Investigation. There is no need for additional investigation for the purposes of the Phase I inspection.

c. Operating Records. No operating records pertinent to the structural stability were disclosed.

d. Post-Construction Changes. According to a representative of Balsams, Inc. additional fill was placed on the downstream slope of the dike when the roadway was widened in 1968.

e. Seismic Stability. The dam and dike are located in Seismic Zone 2 and in accordance with Phase I guidelines do not warrant seismic stability analyses.

SECTION 6
STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations. The visual examination indicates the following evidence of potential problems:

- (1) Existence of an open culvert under the crest of the dike with its downstream end buried under fill.
- (2) Erosion of the upstream slope of the dam on both sides of the concrete spillway-entrance structure.
- (3) Brush growing on the upstream slope near the north abutment of the dam.
- (4) Trees growing on the north bank of the downstream channel of the dam immediately adjacent to the contact between the downstream slope and the abutment.
- (5) Minor settlement and cracking of the roadway pavement on the crest of the dam.
- (6) Trees growing on the downstream slope near the abutments of the dike.
- (7) Brush growing on the upstream slope of the dike.
- (8) Animal burrow on the downstream slope of the dike.
- (9) Trench, backfilled with unknown material, for a TV cable laid under the downstream slope of the dike.

b. Design and Construction Data. NHDPWH plans and sketches dated 5/67 show the design of the spillway discharge pipe which was built at the time of the reconstruction of State Highway 26. The logs of two borings made under the downstream section of the spillway pipe show that it is founded on silty till and boulders; the logs of two other borings show that the concrete inlet structure is founded on "silty sand, small stone, and muck" which, in turn, is underlain by "silty till and boulders." The drawings also show that the design called for a sheet pile cutoff wall driven to a depth of 24 feet below the base of the concrete inlet structure to a distance of 15 feet on either side of the centerline. It also shows a 4-foot wide cutoff of "impervious material" extending the entire width (which is not specified) of the excavation. It is not possible to verify these subsurface details on the basis of the visual inspection alone.

would result in a reservoir pool elevation of 1857.2 MSL. This would result in the overtopping of the dam by 1.7 feet and would overtop the dike by 1.2 feet. The total project capacity is 820 cfs which is about 35 percent of the test flood discharge.

f. Dam Failure Analysis. The analysis of the impact of the failure of the dam covered the entire reach of the Mohawk River located downstream of the dam. Within this reach a low lying area extending from the dam to a point just upstream of Kidderville, a section covering approximately 3.1 miles, was analyzed for high hazard potential. A breach occurring with the reservoir level at the top of dam would result in the discharge of 16,815 cfs. At a point just upstream of Kidderville and approximately 3.1 miles downstream of the dam, the breach discharge would increase the stage depth 9.7 feet above the antecedent stage depth of 5.5 feet resulting from the antecedent flow rate of 800 cfs. The total stage depth of 15.2 feet would probably result in appreciable property damage to farmland and the probable loss of sections of Route 26 which would be susceptible to high erosive velocities.

SECTION 5
HYDROLOGIC/HYDRAULIC

5.1 Evaluation of Features

a. General. Lake Gloriette impoundment features consist of a low earthen dam and low earthen dike which impounds a reservoir of small size. The length of the dam embankment is about 100 feet and the top of the dam is about 6.5 feet above the concrete spillway crest. The dike, located approximately 1000 feet north of the dam, is about 240 feet long and the top of the dike is about 7.0 feet above concrete spillway crest.

b. Design Data. Limited hydrologic and hydraulic data for the Lake Gloriette Dam and Dike were disclosed. NHDPWH design data indicated that a design flow, based on a 10-year event, of 300 cfs was used to guide outlet selection. A drainage area of 1.60 square miles was also given. (See Appendix B.) The drainage area shown herein, as measured by planimeter, was found to be 1.82 square miles.

c. Experience Data. In April, 1960, Lake Abeniki Dam failed releasing flow into Lake Gloriette which resulted in the overtopping of the original Lake Gloriette dam (south outlet), and dike (north outlet). It also resulted in the erosion of a section of Route 26 adjacent to the dam. Presently Lake Abeniki contains approximately one third the volume of water that was impounded at the time of the 1960 dam failure. Therefore it is probable that the effects of a failure of the present Lake Abeniki Dam would be less severe than the effects which resulted from the 1960 dam failure.

d. Visual Observations. At the time of inspection, no visual evidence was noted of damage to any portions of the embankments or of the concrete structure caused by excessive discharges.

e. Test Flood Analysis. Both dam and dike are classified as being small in size, having a hydraulic height of 33 feet and 34 feet respectively, and a maximum (top of dam) storage of approximately 640 acre-feet. Using the Recommended Guidelines for Safety Inspection of Dams, the test flood was determined to be 1/2 the Probable Maximum Flood (PMF). The watershed above the dam, determined to have an average slope of 413 feet mile, is classified as mountainous. From the PMF Peak Flow Rates graph the discharge for a mountainous watershed of 1.82 square miles is 2600 cubic feet per second per square mile (csm). Thus, the PMF flow rate is 4732 cubic feet per second (cfs) and the test flood (1/2 PMF) inflow is 2366 cfs. The test flood outflow discharge is 2350 cfs. Analysis of the elevation versus discharge curve indicates that a flood of this magnitude (2350 cfs)

SECTION 4
OPERATIONAL PROCEDURES

4.1 Procedures

No written operational procedures were disclosed for Lake Gloriette Dam and Dike.

4.2 Maintenance of Dam

The Balsams, Inc. is responsible for the maintenance of Lake Gloriette Dam and Dike.

4.3 Maintenance of Operating Facilities

No formal maintenance program was disclosed.

4.4 Description of Any Warning System in Effect

No written warning system was disclosed for Lake Gloriette Dam and Dike.

4.5 Evaluation

The present operational and maintenance procedures are not adequate to insure that all problems encountered be remedied within a reasonable amount of time.

has a boulder-covered bottom. The south bank of the channel is the fill for State Highway 26 and is riprapped to a height of about 3 feet above the channel bottom. Many saplings are growing up through the riprap. The north bank of the channel is covered with large trees, many of which overhang the channel. Two small logs and a barrel were noted in the discharge channel. (See Appendix C - Figure 20.)

3.2 Evaluation

a. General. The absence of a means of dewatering the reservoir (no low-flow outlet) causes an overall evaluation of fair for the general condition of Lake Gloriette Dam (South Outlet) and Dike (North Outlet).

b. Dam. The minor settlement and cracking of the roadway pavement on the crest of the dam indicates that some settlement of the embankment fill has occurred.

Erosion of the upstream slope of the dam on both sides of the concrete spillway-entrance structure, if not repaired, could become a significant stability problem.

Brush on the upstream face near the north abutment may grow into trees if not cleared. If the trees should blow over and pull out their roots, or if a tree dies and its roots rot, serious erosion and seepage problems could result.

Trees overhanging the north side of the discharge channel and a barrel and two logs in the channel could result in temporary damming of the discharge channel during periods of floodflow. Saplings on the south bank of the discharge channel, if allowed to grow into trees, could result in a similar problem.

c. Dike. There are trees growing on the downstream slope near the abutments. If any trees blow over and pull out their roots, or if a tree dies and its roots rot, serious seepage and erosion problems may result. Brush growing on the upstream slope will become trees, if not cleared, and could cause problems similar to those associated with the trees on the downstream slope.

The old culvert beneath the crest of the dam, the outlet of which has been covered with fill, could result in major erosion and piping problems if the lake level rises high enough so that water enters the culvert on the upstream end.

The animal burrow on the downstream face could be a focus for a concentration of seepage and piping if the animal(s) is not removed and the burrow is not backfilled.

The trench in which the TV cable was laid on the downstream face of the dam could be a focus for concentration of seepage and piping if it was not backfilled with a suitable, properly compacted soil.

(See Appendix C - Figure 12.) Near the south abutment there is a low dry masonry wall at the downstream edge of the crest. This wall apparently extended along the entire length of the downstream side of crest at one time (according to a sketch dated 10/9/39, which was found in the NHWRB files), and may have been buried under additional fill that is reported to have been placed for widening the roadway on the crest. At one time there was a culvert (3' x 3' box) with its invert 6 feet below the crest. This culvert apparently served as a spillway (sketch dated 10/9/39). On the present downstream slope, no visual evidence could be found of this culvert at the time of the inspection. The inlet to the culvert was visible on the upstream face and was partially filled with sand and gravel. (See Appendix C - Figures 13 & 14.) A TV cable comes out of the culvert entrance and continues underground to the Balsams Hotel nearby. About 4 feet of the same TV cable is visible on the surface of the downstream slope near the toe, and it is reported that the rest of the cable is buried beneath the downstream slope. The area downstream of the north outlet has been filled and regraded for use as a golf course, and, as a result, there is no defined channel for a distance of several hundred feet. (See Appendix C - Figure 15.) Several soft, wet areas and a small pond are downstream of the dike embankment, but they appear to be the result of a generally high water table in the broad, flat valley and not the result of seepage through the dike and its foundation. The old culvert beneath the crest of the dike, the outlet of which has been covered with fill, could result in major erosion and piping problems if the lake level rises high enough so that water enters the culvert on the upstream end.

d. Appurtenant Structures. The overflow spillway is located in the center of the dam (south embankment). The concrete spillway is 6.5 feet high and 19 feet long with a 4.0 foot wide wood stoplog section at the center. (See Appendix C - Figure 16.) Overflow discharges into a 7'7" high by 11'10" wide corrugated metal arch pipe which passes through the dam embankment and discharges to the tailwater approximately 22 feet below the crest of the spillway. (Appendix C - Figures 17 & 18.) The overflow structure and outlet pipe were observed to be in excellent condition with no evidence of deterioration or distress. The wooden stops and steel stoplog slots were also observed to be in good condition. However, some surface rust was noted on the steel stoplog slots.

e. Reservoir Area. The watershed above the reservoir is steeply sloping and heavily wooded. A large stately residence and the Balsams Hotel are located on the shore of the reservoir. State Highway 26 is located along much of the south bank of the reservoir. No evidence of significant sedimentation in the reservoir was observed. (See Appendix C - Figure 19.)

f. Downstream Channel. The channel downstream of the dam

SECTION 3
VISUAL INSPECTION

3.1 Findings

a. General. Lake Gloriette impoundment features consist of an earthen dam and dike each of small height. The dike is located approximately 1000 feet north of the dam. The dam and dike impound a reservoir of small size. The watershed above the reservoir is steeply sloping and heavily wooded. The area immediately downstream of the dam is gently to steeply sloping and partially wooded; below the dike is an open plain (golf course).

b. Dam. Lake Gloriette Dam is an earthen embankment about 33 feet high (hydraulic and structural), 100 feet long, and 32 feet wide at the crest. (Appendix C - Figures 2 & 3.) There is a paved roadway on the crest of the dam. Some minor settlement of the roadway has occurred and two minor longitudinal cracks near the downstream edge of the pavement were observed. The upstream slope of the dam is covered with riprap from an elevation about 2 feet above the reservoir level at the time of the inspection to an unknown elevation below the reservoir level. (See Appendix C - Figure 4.) Between the top of the riprap and the crest of the dam there is a poorly established cover of grass and weeds, except close to the north abutment where there is brush. There is extensive erosion of the upstream slope on either side of the concrete spillway-entrance structure. The downstream slope of the dam is covered with riprap. (See Appendix C - Figure 5.) A few small saplings are growing up through the riprap. Many large trees are growing on the north abutment immediately downstream of its contact with the downstream face. (See Appendix C - Figure 6.)

A ridge of natural terrain, about 2,800 feet long, separates the dam and dike. The north abutment of the dam and the south abutment of the dike are contained in this ridge.

c. Dike. The dike, approximately 1000' north of the Lake Gloriette Dam, is an earth embankment about 34 feet high, 240 feet long, and 43 feet wide at the crest. (See Appendix C - Figures 7 & 8.) The crest has a paved roadway. (See Appendix C - Figure 9.) The upstream slope is riprapped from about one foot above the reservoir level (at the time of the inspection) to an unknown elevation below the water level. From the top of the riprap to the crest the upstream slope is covered with brush and in limited areas, grass. Minor erosion of the upstream slope has occurred where water has run off from the roadway. (See Appendix C - Figure 10.) The downstream slope is covered with grass and weeds over its central portion and there are trees on the downstream slope near the abutments. (See Appendix C - Figure 11.) At least one large animal burrow was noted on the downstream slope.

tion with visual inspections and hydrologic and hydraulic calculations.

c. Validity. The visual inspection disclosed that the present visible portions of the dam are consistent with the NHDPWH design plans and sketches.

SECTION 2
ENGINEERING DATA

2.1 Design

The Lake Gloriette Dam was designed by the New Hampshire Department of Public Works and Highways (NHDPWH), Bridge Design Division, in 1967. Design data were found at the NHDPWH office in Concord, New Hampshire. These data consisted of:

- 1) General plan and section
- 2) Layout and log of borings; stoplog design
- 3) Dam masonry and dam reinforcing
- 4) Roadway plan and profile
- 5) Preliminary hydrology and hydraulics for dam outlet

These data may be seen in Appendix B.

Plan and sectional sketches of the dam and dike prepared by Frank Doudera, Inc. dated October 9, 1939, were located in the files of the New Hampshire Water Resources Board (NHWRB) and may be seen in Appendix B.

2.2 Construction

Caledonia Sand and Gravel of St. Johnsbury, Vermont completed construction of the dam in 1968. No revisions to the design plans which reflect as-built conditions were disclosed.

2.3 Operation

No engineering operational data were disclosed.

2.4 Evaluation

a. Availability. NHDPWH engineering plans and sketches, limited geologic data, and limited detailed hydrologic and hydraulic calculations for the Lake Gloriette Dam, reconstructed in 1968, are on file at the NHDPWH Concord, New Hampshire office.

A search of the NHWRB files and direct contact with the owner revealed only a limited amount of available information on the Lake Gloriette Dike.

b. Adequacy. Field inspection of the Lake Gloriette Dam indicated that NHDPWH plans and sketches were adequate. Because of the limited amount of detailed available data for the dike and the limited amount of detailed hydrologic and hydraulic calculations, the final assessments and recommendations were based on the NHDPWH plans and sketches for the dam in conjunc-

(3) Crest elevation - 1849 MSL

(4) Gates - none

(5) Stoplogs - A 4' wide stoplog section is located at the center of the dam. Invert elevation - 1845.5 MSL.

(6) U/S Channel - Lake Gloriette - recreational lake with clean and forested banks.

(7) D/S Channel - the downstream channel is relatively wide and unobstructed. It is clear of debris but contains many large boulders. There are many trees overhanging the banks. The downstream channel of the dike is a wide flat plain used as a golf course.

k. Regulating Outlets. A 7' 7" W x 11' 10" H corrugated metal pipe arch is the only outlet from the dam; the outlet through the dike is plugged at the downstream end, but is slightly open at the upstream end.

- (2) Length - 100'
- (3) Height - 33' (structural height)
- (4) Top width - 32' (paved with guard rails)
- (5) Side slopes - downstream face of dam is inclined at $1\frac{1}{2}H:1V$; both upstream and downstream slopes are riprapped.
- (6) Zoning - Unknown
- (7) Impervious core - a 4' width impervious core is shown on the NHDPWH plans.
- (8) Cutoff - (NHDPWH) design plans indicate a 4' wide cutoff core of impervious material and a sheet piling cutoff wall.
- (9) Grout curtain - unknown

h. Dike.

- (1) Type - earthen embankment with paved roadway on the crest.
- (2) Length - 240'
- (3) Height - 34'
- (4) Top width - 43'
- (5) Side slopes - upstream 1H:1V
downstream 2H:1V
- (6) Zoning - unknown
- (7) Impervious core - unknown
- (8) Cutoff - unknown
- (9) Grout curtain - unknown

i. Diversion and Regulating Tunnel. Not applicable.

(see j. below)

j. Spillway.

- (1) Type - concrete
- (2) Length of weir - 19'

- (4) Maximum pool - design surcharge - unknown
- (5) Full flood control pool - not applicable
- (6) Recreation pool - 1845.5
- (7) Stoplog invert - 1845.5
- (8) Spillway crest - 1849.0
- (9) Upstream portal invert - 1845.0
Downstream portal invert - 1827.0
- (10) Streambed at centerline of main dam - 1822.2
(at downstream toe)

d. Reservoir. (feet)

- (1) Length of maximum pool - 1800
- (2) Length of spillway crest pool - 1600
- (3) Length of flood control pool - not applicable

e. Storage. (acre-feet)

- (1) Spillway crest pool - 300 (approximate)
- (2) Test flood pool - 705 (approximate)
- (3) Design surcharge - unknown
- (4) Top of dam - 640 (approximate)

f. Reservoir Surface. (acres)

- (1) Top of dam - 36.7 (approximate)
- (2) Test flood pool - 38.2 (approximate)
- (3) Flood control pool - not applicable
- (4) Recreation pool - 25.6
- (5) Spillway crest - 25.6 (approximate)

g. Dam.

- (1) Type - earthen embankment with paved roadway on the crest.

7.2 Recommendations

The owner should engage a registered professional engineer to:

- (1) Properly seal the culvert which extends under the road through the dike embankment.
- (2) Design and install an adequate dewatering facility.
- (3) Design repairs for the erosion of the upstream slope next to the concrete spillway-entrance structure of the dam.
- (4) Design and oversee procedures for clearing trees and root systems on north abutment immediately adjacent to the contact between the downstream slope and the abutment of the dam.
- (5) Investigate the minor settlement and cracking of the roadway pavement on the crest of the dam.
- (6) Design and oversee procedures for clearing trees, brush, and root systems from the upstream and downstream slopes of the dike.
- (7) Design and oversee procedures for removing and relocating the TV cable that has been laid underground on the downstream slope of the dike and through the culvert which extends under the road through the dike embankment.
- (8) Spillway adequacy should be reviewed in light of the New Hampshire Department of Public Works and Highways standards, because the arch culvert outlet was designed as a highway design item for the 1968 reconstruction.

7.3 Remedial Measures

a. Operating and Maintenance Procedures. The owner should:

- (1) Remove the animal and its burrow on the downstream face of the dike.
- (2) Visually inspect the dam and dike once a month.
- (3) Engage a registered professional engineer to make a comprehensive technical inspection of the dam and dike once a year.
- (4) Establish a round the clock surveillance program for use during and immediately after heavy rainfall and also a warning program to follow in case of floodflow conditions or imminent dam failure.

7.4 Alternatives. None.

APPENDIX A
VISUAL INSPECTION CHECKLIST

VISUAL INSPECTION CHECKLIST
PARTY ORGANIZATION

PROJECT Lake Gloriette Dam & Dike DATE June 7, 1979

TIME 8 AM

WEATHER Sunny, cool, 55°

W.S. ELEV. U.S. DN.S.
 1846.0 1822

PARTY:

- | | |
|---------------------------------|-----------|
| 1. <u>Warren Guinan</u> | 6. _____ |
| 2. <u>Stephen Gilman</u> | 7. _____ |
| 3. <u>Kathryn Hively</u> | 8. _____ |
| 4. <u>Ronald Hirschfeld</u> | 9. _____ |
| 5. <u>Pattu Kesavan (NHWRB)</u> | 10. _____ |

PROJECT FEATURE	INSPECTED BY	REMARKS
1. <u>Hydrology/Hydraulics</u>	<u>W. Guinan</u>	
2. <u>Structural Stability</u>	<u>S. Gilman</u>	
3. <u>Soils & Geology</u>	<u>R. Hirschfeld</u>	
4. _____		
5. _____		
6. _____		
7. _____		
8. _____		
9. _____		
10. _____		

PERIODIC INSPECTION CHECKLIST

PROJECT Lake Gloriette Dam & Dike DATE June 7, 1979

PROJECT FEATURE Dam Embankment NAME _____

DISCIPLINE _____ NAME _____

AREA EVALUATED	CONDITION
<u>DAM EMBANKMENT</u>	
Crest Elevation	1855.5
Current Pool Elevation	1846.0
Maximum Impoundment to Date	Unknown
Surface Cracks	See "Pavement Condition"
Pavement Condition	Minor settlement of pavement, two
Movement or Settlement of	minor longitudinal cracks near
Crest	downstream edge
Lateral Movement	See "Pavement Condition"
Vertical Alignment	None observed
Horizontal Alignment	Good
Condition at Abutment and	Good
at Concrete Structures	
Indications of Movement of	None observed
Structural Items on Slopes	
Trespassing on Slopes	None observed
Sloughing or Erosion of	Significant erosion adjacent to
Slopes or Abutments	upstream edge of pavement to spill-
Rock Slope Protection -	way box structure
Riprap Failures	Riprap on upstream and downstream
Unusual Movement or Cracking	slopes-no failures observed
at or Near Toe	None observed
Unusual Embankment or Down-	None observed
stream Seepage	
Piping or Boils	None observed
Foundation Drainage Features	None observed
Toe Drains	None observed
Instrumentation System	None observed
Vegetation	Paved roadway on crest. A few small
	saplings growing through riprap on
	downstream slope, minor amount of
	brush growing above riprap level on
	upstream slope

PERIODIC INSPECTION CHECKLIST

PROJECT Lake Gloriette Dam & Dike DATE June 7, 1979

PROJECT FEATURE Dike Embankment NAME _____

DISCIPLINE _____ NAME _____

AREA EVALUATED	CONDITION
<u>DIKE EMBANKMENT</u>	
Crest Elevation	1856.0
Current Pool Elevation	1846.0
Maximum Impoundment to Date	Unknown
Surface Cracks	None observed
Pavement Condition	Good
Movement or Settlement of Crest	None observed
Lateral Movement	None observed
Vertical Alignment	Good
Horizontal Alignment	Good
Condition at Abutment and at Concrete Structures	Good
Indications of Movement of Structural Items on Slopes	None observed
Trespassing on Slopes	None observed
Sloughing or Erosion of Slopes or Abutments	Small channel eroded on upstream face next to roadway
Rock Slope Protection - Riprap Failures	No riprap failures observed
Unusual Movement or Cracking at or Near Toes	None observed
Unusual Embankment or Downstream Seepage	None observed
Piping or Boils	None observed
Foundation Drainage Features	None observed
Toe Drains	None observed
Instrumentation System	None observed
Vegetation	Brush and small trees on upstream slope; grass on downstream slope appears to have been mowed last year.

Note: 3'x3' stone masonry culvert has been plugged on D/S end. Inside of U/S end not visible. Visible portion of U/S end shows concrete head wall in deteriorated condition.

PERIODIC INSPECTION CHECKLIST

PROJECT Lake Gloriette Dam & Dike DATE June 7, 1979
 PROJECT FEATURE Outlet Works NAME _____
 DISCIPLINE _____ NAME _____

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u></p> <p>a. Approach Channel</p> <p> General Condition</p> <p> Loose Rock Overhanging Channel</p> <p> Trees Overhanging Channel</p> <p> Floor of Approach Channel</p> <p>b. Weir and Training Walls</p> <p> General Condition of Concrete</p> <p> Rust or Staining</p> <p> Spalling</p> <p> Any Visible Reinforcing</p> <p> Any Seepage or Efflorescence</p> <p> Drain Holes</p> <p>c. Discharge Channel</p> <p> General Condition</p> <p> Loose Rock Overhanging Channel</p> <p> Trees Overhanging Channel</p> <p> Floor of Channel</p> <p> Other Obstructions</p> <p>d. Stoplogs and Slots</p>	<p>Good</p> <p>None</p> <p>A few trees overhanging right bank</p> <p>Not visible beneath water surface</p> <p>Good</p> <p>Very little - only surface rust on steel stoplog slots</p> <p>None</p> <p>None</p> <p>None</p> <p>None</p> <p>None</p> <p>Good</p> <p>None</p> <p>Many trees overhanging right bank</p> <p>Boulders</p> <p>One log</p> <p>Good condition-little surface rust on slots</p> <p>Stoplogs weathered on exterior but sound.</p>

PERIODIC INSPECTION CHECKLIST

PROJECT Lake Gloriette Dam & Dike - DATE June 7, 1979
 PROJECT FEATURE Outlet Conduit NAME _____
 DISCIPLINE _____ NAME _____

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL</u>	OUTLET CONDUIT
General Condition of Concrete	Good
Rust or Staining	None visible
Spalling	None visible
Erosion or Cavitation	None visible
Visible Reinforcing	None
Any Seepage or Efflorescence	None visible
Condition at Joints	Good-No indications of movement
Drain holes	None visible
Channel	
Loose Rock or Trees Overhanging Channel	Riprap lined along the channel
Condition of Discharge Channel	Good
Corrugated Steel Culvert	Good condition - little erosion of asphalt on invert.

PROJECT Lake Gloriette Dam & Dike

DATE June 7, 1979

PROJECT FEATURE Reservoir

NAME

AREA EVALUATED	REMARKS
Stability of Shoreline	Good
Sedimentation	None observed.
Changes in Watershed Runoff Potential	None
Upstream Hazards	None
Downstream Hazards	N.H. Route 26, farmland.
Alert Facilities	None posted.
Hydrometeorological Gages	None apparent.
Operational & Maintenance Regulations	None posted.

APPENDIX B
ENGINEERING DATA

TO BE BY BRIDGE NW.
 2-15-67 per H.R.
 OUTLET STRUCTURE
 AT LAKE GLORINETTE

Watershed Area

The watershed encompasses the total areas tributary to lakes Gloriette and Abernaki and receives limited flow from Mud Pond. Flood flows from Mud Pond will overflow to Moose Brook or Sugar Hill Brook and will not reach lake Abernaki.

Lake Abernaki is basically a water supply and therefore should not be considered as having effective flood storage.

Areas (Lake Gloriette & Abernaki)

10.45	12.20	
<u>8.75</u>	<u>8.75</u>	Use 1.7 th
1.70	3.45	
	$\frac{(1.7)(62,500)^2}{(144)(43,560)}$	1,060 ac. (1.6 sq. mi.)

Mud Pond

3.52	5.20	
<u>1.86</u>	<u>1.86</u>	Use 1.7 th
1.66	2.334 = 1.67	

Same as above 1,060
(1.6 sq. mi.)

Assume 10% of Mud Pond area is effective in flood design for Lake Gloriette outlet

Total Watershed area =
 1,060 + 106 = 1,166 acres
 = (1.82 sq. mi.)

Available storage Lake Gloriette only

$$\frac{14.73}{51.23} = 0.046$$

$$\frac{(0.046)(167,500)^2}{(1.44)(12.5)^2} = 29 \text{ ac.}$$

$$\% \text{ storage} = \frac{29}{1160} = 2.5\%$$

Design Flow
(Use 10 year storm)


(from BPR Chart No 2 Peak Rates of Runoff For Adirondack White Mountains and Maine Woods)

Rintail index = 1.7
Storage Factor = 2.5

$Q_{10} = 300 \text{ cfs}$
 $Q_{50} = 400 \text{ cfs}$

Use 300 cfs for design

Exist. Box Cuv. Capacity



Assume no step above and headwater at 853 (max. before overflow) Assume inlet control

Waterway opening

from chart 1045 (Headwater depths For Box Culverts with Entrance Control inlet type ?)

$$\frac{HDW}{L} = \frac{853 - 845.5}{6.5} = \frac{7.2}{6.5} = 1.1$$

$$Q/FT = 49 \text{ cfs}$$


$$6 \times 49 = 334 \text{ cfs}$$

Exist Box Culv. Capacity (cont)

Assume step boards in to El 845.0

Treat as an orifice
formula

$$Q = CA\sqrt{2gh}$$



E. EL. 852.3

E. EL. 848

$$h = 852 - \frac{852.3 - 848 + 848}{2}$$

$$h = 852 - 850.2$$

$$= 2.8$$

$$C = 0.62 \text{ (Orifice Hydr. Handbook)}$$

$$A = 3.2 \times 4 = 20.8 \text{ ft}^2$$

fig. 23 Series

$$\begin{aligned} Q &= (0.62)(20.8)\sqrt{2g(2.8)} \\ &= (12.9)(13.4) \\ &= \underline{174 \text{ cfs}} \end{aligned}$$

Division Eng. Bean indicated this culvert overtopped once in last 5 years. It was assumed that the step boards were in place.

OUTLET 222.00 40.00 1.50
INLET 853.00 20.00

MAT.	SHAPE	RISE	OFF.	OUTLET ELEV.	ELEV. INLET OFF.	FT.
2	1	4.50	40.0	833.50	835.04	36.0 4
2	1	5.00	31.4	832.73	834.63	31.2 2
2	1	5.50	26.7	842.34	842.51	26.5 2
2	1	6.00	24.1	843.57	844.56	22.5 3
2	1	6.50	22.9	844.11	844.19	21.4 3
2	1	7.00	21.8	844.56	845.65	19.2 3

B-4

**NEW HAMPSHIRE WATER CONTROL COMMISSION
DATA ON DAMS IN NEW HAMPSHIRE**

ION STATE NO. 05.01

Dixville : County Cook

Lake Floriette

Primary Connecticut River : Secondary Connecticut River

Name

Coordinates—Lat. 44° 52' : Long. 71° 20'

AL DATA

Age area: Controlled.....Sq. Mi.: Uncontrolled..... Sq. Mi.: Total 1.92 Sq. Mi.

Full length of dam 75 ft.: Date of Construction

Height: Stream bed to highest elev. 13 ft.: Max. Structure 13.25' ft.

Dam : Reservoir

PTION

Gate

Type None

Number 2 : Size ft. high x ft. wide

Elevation Invert : Total Area sq. ft.

Distance

Gate Conduit

Number None : Materials

Size ft.: Length ft.: Area sq. ft.

ankment

Type Earth with roadway on top

Height—Max. 13 ft.: Min. ft.

Top—Width 30 : Elev. ft.

Slopes—Upstream on : Downstream on

Length—Right of Spillway : Left of Spillway

Materials of Construction Stone and concrete culvert under roadway

Length—Total 19 ft.: Net 2'4" ft.

Height of permanent section—Max. ft.: Min. ft.

Flashboards—Type Removable stop planks : Height 3'3" ft.

Elevation—Permanent Crest : Top of Flashboard

Flood Capacity 390 cfs.: cfs/sq. mi.

ments

Materials: Stone masonry

Flashboard: Max. 3'6" ft.: Min. 3'6" ft.













Works to Power Level.—(See "Data on Power Development")

R The Balsans, Inc., Dixville, N. H.

RKS Use - recreation. One of two outlets to Lake Floriette.

tion By Richard G. Holman Date June 1, 1961

NO.	DATE	BY	REVISION



STATE OF NEW HAMPSHIRE
DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS
BRIDGE DESIGN DIVISION
Project No. 1000
Date: 10/1/10
Scale: 1/10
Sheet No. 1000-1000-1000-1000

SECTION A-A
Scale 1/10


SECTION B-B
Scale 1/10

SECTION C-C
Scale 1/10

SECTION D-D
Scale 1/10

SECTION E-E
Scale 1/10

SECTION F-F
Scale 1/10



Propose Quantities

Type No.	Description	Quantity	Unit
101	Earth Structure Excavation	180	CY
102	Concrete Foundation	18	CY
103	Concrete for Proposed Structure	110	CY
104	Reinforcing Steel for Proposed Structure	100	LB
105	Formwork for Proposed Structure	100	SQ. FT.
106	Formwork for Proposed Structure	100	SQ. FT.
107	Formwork for Proposed Structure	100	SQ. FT.
108	Formwork for Proposed Structure	100	SQ. FT.
109	Formwork for Proposed Structure	100	SQ. FT.
110	Formwork for Proposed Structure	100	SQ. FT.

Approximate floor outside the amount of the above quantities.

GRADING WORK
Design Location: 100-44
Specification: 100-44
N.Y. Dept. of Public Works, 1910

SUBMITTAL SHEET
This sheet is to be submitted
Pending the final plan.

STATE OF NEW HAMPSHIRE
DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS
DESIGN DIVISION

Date: 10/10/10
Scale: 1/4" = 1'-0"

PROJECT: 100-44
SHEET: 100-44-100

DESIGNED BY: [Name]
CHECKED BY: [Name]
APPROVED BY: [Name]

Approved: [Signature]
Chief Engineer


Section 100-44
Scale 1/4" = 1'-0"

Section 100-44
Scale 1/4" = 1'-0"

Section 100-44
Scale 1/4" = 1'-0"

Section 100-44
Scale 1/4" = 1'-0"

Section 100-44
Scale 1/4" = 1'-0"



FOR SPILLWAY SECTION AND ELEVATION OF DAM (SOUTH OUTLET)
SEE FOLLOWING N.H.D.P.W.H. PLANS AND SKETCHES.

Anderson - Nichols & Co., Inc. CONSULTING ENGINEERS NEW HAMPSHIRE 251-7200, N.H.	U.S. ARMY ENGINEER DISTRICT NEW ENGLAND CORPS OF ENGINEERS CONCORD, MASSACHUSETTS 661-7200, U.S.A.
NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS	
LAKE GLORIETTE DAM & DIKE	
MONMOUTH RIVER	NEW HAMPSHIRE

PLAN

Lake Glorietta - Both N & S outlets
 Source - General File of Dixville

Town No. 5 Town Dixville No. _____
 Date by L.W.B File _____
 Owner Dixville Notch Corp 60-4105
 River or Stream _____
 Public Utility No Drainage area 0.5 sq. mi.
 Wheel Capacity H. P. _____
 Type of Construction _____
 Height 15 ft. Operating Head _____ ft.
 Length 200 ft. Spillway Length (No. 1) _____ ft. (No. 2) _____ ft.
 Would Failure of Dam do Harm? _____
 Present Condition _____ Date _____

Town No. 5 Town Dixville No. _____
 Data by S.V.L Lot 12-7-26 File I 1097
 Owner V.V. Lamin Co.
 River or Stream Mud Pond
 Public Utility No Drainage area 1.0 sq. mi.
 Wheel Capacity H. P. _____
 Type of Construction Rock Filled Log Crib
 Height 10 ft. Operating Head _____ ft.
 Length 246 ft. Spillway Length (No. 1) 130 ft. (No. 2) _____ ft.

Town No. 2 Town Dixville No. 1-323
 Date by L.W.B. File I-323
 Owner Dixville Notch Corp. (Balsams Valley Pond)
 River or Stream.....
 Public Utility NO Drainage area 2.0 sq. mi.
 Wheel Capacity H. P. { Primary H. P. }
 { 90% time }
 Type of Construction Earth with Concrete Core
 Height 30 ft. Operating Head 375 ft.
 Length 1575 ft. Spillway Length (No. 1) 90 ft. (No. 2).....ft.
 Would Failure of Dam do Harm? See Let S.J.L 12-30-26
 Present Condition..... Date.....

1774

DIXVILLE, Dams in

1. Dixville Notch Corporation No Plan Dixville Notch, NH
2. Dixville Notch Corporation "The Balsams" - Construction of, Balsams Valley Dam 1913 - (unincorporated) 1-523 Plan D-7
3. Dixville Notch Corporation Dixville Notch, "Proposed dam at the Golf Links Plan D-11
4. Dixville Notch Corporation Dixville Notch "Construction of dam at Dixville Notch (I-1174) Plan D-34

15 Dixville Notch Corp. No Plan 1-523
 1-1897 Built 1926

NEW HAMPSHIRE WATER CONTROL COMMISSION
 DATA ON RESERVOIRS & PONDS IN NEW HAMPSHIRE

LOCATION AT DAM NO. 65.01
 Town Dixville: County Coos
 Stream Lake Gloriette
 Basin—Primary Coon R.: Secondary Mohawk R.
 Local Name

DRAINAGE AREA

Controlled Sq. Mi.: Uncontrolled Sq. Mi.: Total Sq. Mi.

ELEVATION vs. WATER SURFACE AREA vs. VOLUME

Point	Head Feet	Surface Area Acres	Volume Acre Ft.
(1) Max. Flood Height
(2) Top of Flashboards
(3) Permanent Crest
(4) Normal Drawdown	31
(5) Max. Drawdown
(6) Original Pond	U.S.G.S.....1871

Base Used: Coef. to change to U.S.G.S. Base

RESERVOIR CAPACITY

	Total Volume	Useable Volume
Drawdownft.ft.
Volumeac. ft.ac. ft.
Acre ft. per sq. mi.
Inches per sq. mi.

USE OF WATER Use- Recreation

OWNER The Balsams, Inc. Dixville Notch N H

REMARKS

B-12

Compilation By A. A. N. & R. L. T. Date November 15, 1938
 June 6, 1941

NEW HAMPSHIRE WATER RESOURCES BOARD

INVENTORY OF DAMS AND WATER POWER DEVELOPMENTS

DAM

65.02

BASIN Connecticut NO. 2- I-5401
 RIVER Lake Glorietta MILES FROM MOUTH D.A.SQ.MI.
 TOWN Dixville OWNER Frank Doudera Co., Inc.
 LOCAL NAME OF DAM
 BUILT DESCRIPTION Earth Dike - Concrete + Earth on Earth

POND AREA-ACRES DRAWDOWN FT. POND CAPACITY-ACRE FT.
 HEIGHT-TOO TO BED OF STREAM-FT. 35± MAX. MIN.
 OVERALL LENGTH OF DAM-FT. 200± MAX. FLOOD HEIGHT ABOVE CREST-FT.
 PERMANENT CREST ELEV. U.S.G.S. LOCAL GAGE
 TAILWATER ELEV. U.S.G.S. LOCAL GAGE
 SPILLWAY LENGTHS-FT. 3.417 FREEBOARD-FT. 1.5 and 3.917
 FLASHBOARDS-TYPE, HEIGHT ABOVE CREST 1.5± Removable stop Planks
 WASTE GATES-NO. WIDTH MAX. OPENING DEPTH SILL BELOW CREST

REMARKS Condition Good

6B into Lake Abenaki, Moose Bk, Mohawk R.

POWER DEVELOPMENT

UNITS	NO.	RATED HP	HEAD FEET	C.F.S. FULL GATE	KW	MAKE

USE Domestic, Recreation

REMARKS Mendce

DATE 5/7/36

PUBLIC SERVICE COMMISSION OF NEW HAMPSHIRE—DAM RECORD

I-5401

TOWN	DIXVILLE	TOWN NO.	2	STATE NO.	65.02
RIVER STREAM	Lake Gloriette	DIKE			
DRAINAGE AREA		POND AREA			
DAM TYPE	Earth	FOUNDATION NATURE OF	Earth		
MATERIALS OF CONSTRUCTION	Earth, Concrete				
PURPOSE OF DAM	POWER—CONSERVATION—DOMESTIC—RECREATION—TRANSPORTATION—PUBLIC UTILITY				
HEIGHTS, TOP OF DAM TO BED OF STREAM	Approx. 35'	TOP OF DAM TO SPILLWAY CRESTS	4'-6"		
SPILLWAYS, LENGTHS DEPTHS BELOW TOP OF DAM	3'-5" wide, 3'-11" deep			LENGTH OF DAM	Approx. 200'
FLASHBOARDS TYPE, HEIGHT ABOVE CREST	Removable stop planks 19"				
OPERATING HEAD CREST TO N. T. W.		TOP OF FLASHBOARDS TO N. T. W.			
WHEELS, NUMBER KINDS & H. P.					
GENERATORS, NUMBER KINDS & K. W.					
H. P. 90 P. C. TIME 100 P. C. EFF.		H. P. 75 P. C. TIME 100 P. C. EFF.			
REFERENCES, CASES, PLANS, INSPECTIONS					

REMARKS

OWNER: Frank Doudera Co., Inc.
 CONDITION: Good
 MENACE: Yes. Will be subject to periodic inspection.

To the Public Service Commission:

The foregoing memorandum on the above dam is submitted covering inspection made Aug. 7, 1936, according to notification to owner dated July 28, 1936, and bill for same is enclosed.

D. Waldo White
 Chief Engineer

Aug. 11, 1936
 Copy to Owner

PUBLIC SERVICE COMMISSION OF NEW HAMPSHIRE—DAM RECORD

I-5400

TOWN DIXVILLE	TOWN NO. 1	STATE NO. 65.01
RIVER STREAM Lake Gloriette		
DRAINAGE AREA	POND AREA 31	
DAM TYPE Gravity	FOUNDATION NATURE OF Earth	
MATERIALS OF CONSTRUCTION	Split Stone - Concrete - Earth	
PURPOSE OF DAM	POWER—CONSERVATION—DOMESTIC—RECREATION—TRANSPORTATION—PUBLIC UTILITY	
HEIGHTS, TOP OF DAM TO BED OF STREAM	Approx. 18'	TOP OF DAM TO SPILLWAY CRESTS
SPILLWAYS, LENGTHS	4'-2 1/2" wide x 5'-9" deep	LENGTH OF DAM Approx. 150'
DEPTHS BELOW TOP OF DAM	4'-4" wide x 5'-9" deep	
FLASHBOARDS TYPE, HEIGHT ABOVE CREST	Removable stop planks 5'-3"	
OPERATING HEAD CREST TO N. T. W.		TOP OF FLASHBOARDS TO N. T. W.
WHEELS, NUMBER KINDS & H. P.		
GENERATORS, NUMBER KINDS & K. W.		
H. P. 90 P. C. TIME 100 P. C. EFF.		H. P. 75 P. C. TIME 100 P. C. EFF.
REFERENCES, CASES, PLANS, INSPECTIONS		

REMARKS

OWNER: Frank Doudera Co. Inc.

CONDITION: Good

MENACE: Yes. Will be subject to periodic inspection.

To the Public Service Commission:

The foregoing memorandum on the above dam is submitted covering inspection made Aug. 7, 1936, according to notification to owner dated July 28, 1936, and bill for same is enclosed.

D. Waldo White
Chief Engineer

Aug. 11, 1936
Copy to Owner

AMPSHIRE
RESOURCES
BOARD
ORD. N. H.

PROJECT

SUBJECT LAKE GLOPIETLE

DIXVILLE

FILE 65.01

Contractor

FRANK SOUDERA INC.

DIVISION 14.11

COMPUTER G.S.W.




CHECKER R.L.T.

CONT. FROM ACC.

CONT. ON ACC.

SUMMARY ON ACC.

DATE 10/9/89



APPENDIX C
PHOTOGRAPHS

Anderson - Nichols & Co., Inc.
 CONCORD NEW HAMPSHIRE

U.S. ARMY ENGINEER DIV. NEW ENGLAND
 CORPS OF ENGINEERS
 WALTHAM, MA.

NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS

LAKE GLORINETTE DAM & DIKE

PHOTO INDEX

MOHAWK RIVER NEW HAMPSHIRE

SCALE: NOT TO SCALE
 DATE: AUGUST 1979







Figure 2 - Looking north across the crest of
Lake Gloriette Dam.



Figure 3 - View south across the crest.



Figure 4 - Upstream face of the spillway.



Figure 5 - Downstream face of Lake Gloriette Dam.




Figure 6 - View downstream from center of dam.



Figure 7 - Upstream face of the dike from south side of reservoir.



Figure 8 - Small trees and brush growing on upstream face of dike.



Figure 9 - View north along crest of dike.



Figure 10 - Erosion on upstream face near edge of roadway.



Figure 11 - Trees and brush growing on downstream face of dike.



Figure 12 - Animal burrow on downstream face of dike.



Figure 13 - Filled inlet to culvert showing TV cable.



Figure 14 - Filled culvert. Note riprap extending about one foot above and one foot below water level.



Figure 15 - Downstream from center of dike.



Figure 16 - View across spillway and stoplog notches at Lake Gloriette Dam.



Figure 17 - Looking downstream through corrugated metal spillway pipe.



Figure 18 - Downstream toe of dam on right side of spillway.




Figure 19 - Upstream view towards the Balsams Hotel.



Figure 20 - Downstream channel from center of dam.

APPENDIX D
HYDROLOGIC AND HYDRAULIC COMPUTATIONS



FEDERAL PROGRAM OF INSPECTION OF
NON-FED. DAMS

LAKE GLORLETTE DAM AND DIKE
DIXVILLE, NEW HAMPSHIRE

REGIONAL VICINITY MAP

DEPARTMENT OF THE ARMY
WATERWAYS DIVISION, CORPS OF ENGINEERS
WASHINGTON, MASSACHUSETTS

NICHOLS & CO., INC.

CONCORD, NH

SCALE IN MILES




MAP BASED ON U.S.G.S. 15 MINUTE QUADRANGLE
SHEET. DIXVILLE, N.H., 1930

Hydraulic Charts for the Selection of Highway Culverts (HFC-5)

Attachment "A"

7 of 12
CHART 6



*ADDITIONAL SIZES NOT DIMENSIONED ARE LISTED IN FABRICATOR'S CATALOG

BUREAU OF PUBLIC ROADS JAN 1963

5-3

D-15

Sizing curve for storm flow

Pg 1 of 2

PROJECT: <u>3273-04</u> Designer: <u>JMR</u> DATE: <u>8-1-79</u>		SKETCH STATION: _____ 											
HYDROLOGIC AND CHANNEL INFORMATION $Q_1 =$ _____ $TW_1 =$ _____ $Q_2 =$ _____ $TW_2 =$ _____ ($Q_1 =$ DESIGN DISCHARGE, SAY Q_{25} $Q_2 =$ CHECK DISCHARGE, SAY Q_{50} OR Q_{100})		MEAN STREAM VELOCITY = _____ MAX. STREAM VELOCITY = _____											
CULVERT DESCRIPTION (ENTRANCE TYPE)	SIZE	Chart #6 HEADWATER COMPUTATION						COMMENTS					
		INLET CONT. $\frac{HW}{D}$	OUTLET CONTROL	K_e	H	d_c	$\frac{d_c + D}{2}$						
Trial #1 Assume Elev = 1850	1000	1.68	13	0.5	4.7	5.5	6.6	0	6.6	18.5	6.7	13	
Trial #2 Assume Elev = 1860	1100	1.95	15	0.5	10.8	6.6	7.2	0	7.2	18.5	0.5	15	
Trial #3 Assume Elev = 1855	800	1.36	10.5										
Trial #4 Elev = 1853	600	1.03	8.0										
SUMMARY & RECOMMENDATIONS: 1 Assume no tailwater Trials #1 & #2 demonstrate that inlet controls for the smaller discharges.													

5-18

D-13

Assume H & calculate Q

Figure 7

3273-04

lake elevation " " "
Attachment A

3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

$H_1 = 7.5$

$H_2 = 4.0$

$= 2.6(1.0)(7.5)^{3/2} + 2.6(15.0)(4.0)^{3/2}$
 $= 214 + 312$
 $= 526 \text{ cfs}$

trial #6 Elev. = 1855.4 (1' below l.c. of spillway outlet box)

$Q = 800 \text{ cfs}$ ← NOTE: Pipe arch becomes the controlling feature @ higher elev. (See Figure "A")

@ 1855.5 pressure flow governs @ concrete spillway section. Discharge capacity of spillway increases greatly as change in flow condition occurs. (From weir to pressure)

no. 3273-04Lake Cloniette
Attachment "A"

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

Trial #2 Elev. = 1847.0

$$Q = CLH^{3/2}$$

C = 2.6 (assuming broad-crested weir)

$$Q = 2.6(4.0)(1.5)^{3/2}$$

$$H = 1.5'$$

$$Q = 19 \text{ cfs}$$

$$L = 4.0'$$

Trial #3 Elev = 1849.0 (Invent of concrete weir)

$$Q = CLH^{3/2}$$

$$H = 3.5'$$

$$Q = 2.6(4.0)(3.5)^{3/2}$$

$$L = 4.0'$$

$$Q = 68 \text{ cfs}$$

Trial #4 Elev = 1851.0

$$Q = C_1 L_1 H_1^{3/2} + C_2 L_2 H_2^{3/2}$$

$$H_1 = 5.5'$$

 C_2, L_2, H_2 - pertain to 19' concrete weirC₂ = 2.6 (assuming broad crested weir)

$$L_2 = 15'$$

$$Q = (2.6)(4.0)(5.5)^{3/2} + (2.6)(15)(2.0)^{3/2}$$

$$= 134 + 110$$

$$Q = 234 \text{ cfs}$$


Trial #5 Elev = 1853.0

$$Q = C_1 L_1 H_1^{3/2} + C_2 L_2 H_2^{3/2}$$

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29

Outlet Works - Dam (South Outlet)

Top of road = 1855.0



Top of road = 1855.0
CONCRETE spillway
C Invert = 1849.0
7.7' H x 11.8' W CMP
pipe arch
Stoplog Section
of conc. spillway
C Invert = 1845.5
CMP Invert = 1845.0
Stationing
d/s Invert of cmp = 1822.2
cmp pipe is located approx 6.3' d/s of concrete spillway


D-10

INO. 3273-04 Lake Glenette

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

Rating Curve Calcs. - Attachment "A"

Sketch of Lake Glenette Outlet Structure

Elements

- 1) Stop log section
- 2) Concrete spillway
- 3) Top of road
- 4) 7.7' H X 11.8' W
CMP PIPE located
6.3' downstream
of concrete spillway

Rating Curve is a composite curve resulting from contributions from elements 1, 2, and 4 or 3 and 4 whichever combination controls for a particular range of elevations. (Refer to x-section of outlet works which provides elevation and geometric data)

CONCRETE SPILLWAY SECTION

Total #1 Elev = 1845.5 (invert of stop log section)

$$Q = 0 \text{ cfs}$$

DB NO. Lake Glorietta 6273-01

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

Lake Glorietta Dam and Dike - TEST Flood Elev.

Drainage Area = 1.82 mi²

Size Classification = intermediate

Hazard Classification = significant

Test Flood - Full PMF

Calculate PMF Using "Preliminary Guidance For Estimating Maximum Probable Discharges in Phase I Dam Safety Investigations, March, 1978"

Average slope of the watershed is 413 ft/mi. A mountainous curve will be used to compute the PMF. Use a CSM value of 2.600,

$1.82 \text{ mi}^2 \times 2.600 = 4732 \text{ cfs} = \text{PMF}$

$Q_{P1} = \frac{1}{2} \text{ PMF} = 2366 \text{ cfs (test Flood inflow)}$

$Q_{P1} = 2366 \text{ cfs} \rightarrow 1857.4 \text{ MSL} \rightarrow 705 \text{ ac-Ft (1.11")}$
STOR1

$Q_{P2} = Q_{P1} \times (1 - \frac{\text{STOR1}}{9.5})$ $\frac{1}{2}$ PMF runoff

$Q_{P2} = 2366 (1 - \frac{1.11}{9.5}) = 2339 \text{ cfs}$

$Q_{P2} = 2339 \text{ cfs} \rightarrow 1857.2 \rightarrow 705 \text{ ac-Ft (1.11")}$
STOR2

Aug. Surcharge Storage = $\frac{\text{STOR1} + \text{STOR2}}{2} = 1.11" = 705 \text{ ac-Ft}$

$Q_{P3} = 2350 \text{ cfs}$
← Elev = 1857.2
TEST Flood OutFlow

IES SCALE

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29

ELEV | DEPTH

CALCULATION

1306 | 0

Q = 0 CFS

1307 | 1'
(NORMAL FLOW)

$A = \frac{2}{3} T y$ (parabolic shape)
 $A = \frac{2}{3} (20)(1) = 13.33 \text{ ft}^2$

$W.P. = T + \left(\frac{8}{3}\right) \left(\frac{y^2}{T}\right)$
 $W.P. = 20 + \left(\frac{8}{3}\right) \left(\frac{1^2}{20}\right) = 20.13$

$R = A/W.P. = 13.33/20.13 = 0.662$
 $R^{2/3} = 0.76$

$Q = \frac{1.49}{0.05} (0.76)(0.1025)(13.33)$

Q = 31 CFS

1310 | 4'
(Top of bank)

$A = 13.33 + 3(20) = 73.33 \text{ ft}^2$
 $W.P. = 20.13 + 2(3) = 26.13$

$R = A/W.P. = 73.33/26.13 = 2.81$
 $R^{2/3} = 1.99$

$Q = \frac{1.49}{0.05} (1.99)(0.1025)(73.33)$

Q = 446 CFS

1320 | 14'

$A = 73.33 + 10(20) + 2\left(\frac{1}{2}\right)(10)(200)$
 $A = 2273 \text{ ft}^2$

$W.P. = 26.13 + 2\left(\sqrt{(10)^2 + (200)^2}\right)$

W.P. = 426.6

$R = A/W.P. = 2273/426.6 = 5.33$
 $R^{2/3} = 3.05$

D-21
 $n = \frac{26.13 (0.05)}{426.6} + \frac{1}{0.08} (0.08) = 0.047$
 D-6

JOB NO. P/S Hazard Rating Curve Calculations A of 6

ES SCALE 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29

$$Q = \frac{1.49}{0.08} (3.05)(0.1025)(2273)$$

$$Q = \underline{13,235 \text{ cfs}}$$

1315/9'

$$A = 73.33 + 5(20) + 2\left(\frac{1}{2}\right)(5)(100)$$

$$A = 673 \text{ ft}^2$$

$$W.P. = 26.13 + 2 \sqrt{(5)^2 + (100)^2}$$

$$W.P. = 226.4$$

$$R = A/W.P. = 673/226.4 = 2.97$$

$$R^{2/3} = 2.07$$

$$n = \frac{26.13}{226.4} (0.05) + \frac{200.3}{226.4} (0.08)$$

$$n = 0.08$$

$$Q = \frac{1.49}{0.08} (2.07)(0.1025)(673)$$

$$Q = \underline{2660 \text{ cfs}}$$

1325/19'

$$A = 73.33 + 15(20) + 2\left(\frac{1}{2}\right)(10)(200) + \frac{1}{2}(200)(5)$$

$$+ \frac{1}{2}(145)(5) + (2)(5)(200)$$

$$= 5235.8 \text{ ft}^2$$

$$W.P. = 426.6 + \sqrt{200^2 + 5^2} + \sqrt{145^2 + 5^2}$$

$$= 426.6 + 200.1 + 145.1$$

$$= 771.8 \text{ ft}$$

$$R = 6.78$$

$$R^{2/3} = 3.58$$


$$n = 0.08$$

$$Q = \frac{1.49}{0.08} (3.58)(0.1025)(5235.8) = 35,785 \text{ cfs}$$

Lake Gloriette

3 of 6

Downstream Hazard Rating Curve



Breach Analysis - D/S Hazard 2 of 6

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

- FIELD NOTE REDUCTION - 6/29/79 FIELD TRIP
JRL/SM

- TRAILER - 150 yds EAST OF KIDDERVILLE INT.
x 1322 (rd) (FROM QUAD SHIT)
SILL = 1322 + 1 = 1323' MSL

- YOGI'S CAFE -

$$\frac{(1340 - 1322)}{2220'} (845') + 1322 = 1329' (rd)$$

$$SILL = 1329 + 2' = 1331' MSL$$

- HSE'S WEST OF MOHAWK R. ON RD LEADING TO UPPER KIDDERVILLE

$$\frac{(1320 - 1300)}{2535} (210) + 1320 = 1318 (rd)$$

$$SILL = 1318 + 2 = 1320 WESTERLY HSE$$

$$1318 + 12 = 1330 EASTERLY HSE$$

- ELEV BREACH = 1320 W/ Q_B = 12,382 CFS

- STAGE INCREASE ABOVE ANTECEDENT FLOW =
1320 - 1311.6 = 8.4

- CONC:

HAZARD CLASSIFICATION - SIGNIFICANT
POSSIBLE LOSS OF LIFE (1 HOUSE)
APPRECIABLE DAMAGE TO FARMS AND
FARMLAND IN FLOOD PLAIN; AS WELL AS
LOSS OF MAJOR SECTIONS OF ROUTE 26
WHICH WOULD BE SUSCEPTIBLE TO HIGH
EROSIVE VELOCITIES W/ A FLOW EQUAL TO
THE BREACH DISCHARGE

JOB NO. Lake Coloma Ho5273-05SQUARES
1/4 IN. SCALE

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28

BREACH ANALYSIS

1 of 6

A. Breach analysis performed assuming breach occurs with reservoir level @ top of dam (elev = 1355.5)

B. Determine peak failure outflow - Q_{p1}

$$Q_{p1} = \frac{8}{27} W_b \sqrt{g} Y_0^{3/2}$$

W_b = breach width
 g = 32.2 ft/sec²
 Y_0 = breach height

W_b = 80' (based on field inspection)
 Y_0 = pool elev. - invert @ midpoint of dam embankment
 Y_0 = 1855.5 - 1836 = 19.5'

NOTE: Invert of dam @ midpoint of dam embankment obtained by using NHDPAW & H plans for pipe arch extending under dam and taking invert elevation @ halfway point.

$$Q_{p1} = \frac{8}{27} (80) \sqrt{32.2} (19.5)^{3/2}$$

$$= 11,582 \text{ cfs}$$


Total Breach Discharge = Q_{p1} + Flow thru spillway @ time of breach

$$Q_u = 11,582 + 800$$

$$Q_u = 12,382 \text{ cfs}$$

← obtain from outlet rating curve.

Lake Gloniette - Figure A
 Outlet Rating Curve - Controlling Feature



JOB NO. 3273-04 Lake Glorietta
Attachment "A"

COMBINED DISCHARGE (Outlet Structure & Flow over Earth Embankments)
Trial #7 Elev = 1856.0 (top of dike)

$$Q = C_3 L_3 H_3^{3/2} + Q_{pa}$$

$$Q = (2.6)(150')(0.5)^{3/2} + 840$$

$$Q = 138 + 840$$

$$= 978 \text{ cfs}$$

Q_{pa} = discharge thru
 7.7' H X 11.8' W comp
 pipe arch

$C_3 = 2.6$ (assuming broad-crested weir)

H_3 = avg. head over roadway weir (dam)

L_3 = length of roadway weir (dam)

Q_{pa} = discharge thru
 pipe arch - See Figure "A"

Trial #8 Elev = 1857.0

$$Q = C_3 L_3 H_3^{3/2} + Q_{pa} + C_4 l_4 H_4^{3/2}$$

$$Q = (2.6)(150)(1.5)^{3/2} + 920$$

$$+ 2.6(200)(1.0)^{3/2}$$

$$Q = 714 + 920 + 520$$

$$= 2156 \text{ cfs}$$

$C_4 = 2.6$ (assuming broad-crested weir)

H_4 = avg. head over road weir (dike)

l_4 = length of effective weir (dike)

JOB NO. Lake Glorietta 5273-04
Attachment "A"

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

Trial #9 Elev = 1858.0

$$Q = C_3 L_3 H_3^{3/2} + Q_{pa} + C_4 L_4 H_4^{3/2}$$

$$Q = 2.6(150)(2.5)^{3/2} + 1000 + (2.6)(200)(1.5)^{3/2}$$

$$Q = 1542 + 1000 + 955$$

$$= 3497 \text{ cfs}$$

Trial #10 Elev = 1859.0

$$Q = C_3 L_3 H_3^{3/2} + Q_{pa} + C_4 L_4 H_4^{3/2}$$

$$Q = (2.6)(150)(3.5)^{3/2} + 1100 + (2.6)(200)(2.5)^{3/2}$$

$$Q = 2554 + 1100 + 2055$$

$$= 5709 \text{ cfs}$$

Trial #11 Elev = 1860.0


$$Q = C_3 L_3 H_3^{3/2} + Q_{pa} + C_4 L_4 H_4^{3/2}$$

$$Q = 2.6(150)(4.5)^{3/2} + 1190 + (2.6)(200)(3.5)^{3/2}$$

$$= 3723 + 1190 + 3405$$

$$= 8318 \text{ cfs}$$

Elevation - Discharge Rating Curve



JOB NO. Lake Gloriette Dam and Dike
3273-05

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

Effective Weir Lengths

Dam (South Outlet)

- 1) Assume constant weir elevation = 1855.5
- 2) Assume effective weir length = 150'

Dike (North Outlet)

- 1) Assume constant weir elevation = 1856.0
- 2) Assume effective weir length = 200'

JOB NO. Lake Gloriette 7273-01
 Attachment "B"

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

Storage Calcs

@ Normal Pool Elev. - 1845.5 (invert. of stoplog section)

Sfc Area @ 1845.5 = 25.6 acres (obtained from U.S.G.S. topo)
 Assumed Avg Depth = 15.0 ft
 Assumed Sfc @ Lake Invert = 15 acres (1830.5)

Calculate Storage using Frustrum of pyramid formula

$$V = \frac{1}{3} h (B_1 + B_2 + \sqrt{B_1 B_2})$$

B₁ = lower base (15 acres)
 B₂ = upper base (25.6 ac)
 h = 15'

@ 1845.5 $V = 301 \text{ acre-ft}$

@ 1860.0

Sfc Area @ 1860.0 = 41.6 acres (obtained from U.S.G.S. topo)

$$V = \frac{1}{3} h (B_1 + B_2 + \sqrt{B_1 B_2}) \quad (\text{Frustrum of pyramid})$$

$$V = \frac{1}{3} (15.5) [25.6 + 41.6 + \sqrt{(25.6)(41.6)}] B_1 = 25.6 \text{ acres}$$

$$B_2 = 41.6 \text{ acres}$$


$$h = 15.5 \text{ Feet}$$

$$V = 515 \text{ ac-ft}$$

$$V_T = 515 + 301 = 816 \text{ ac-ft}$$

@ 1860.0

Lake Gloriette
Storage-Elevation Curve



JMR
B-277

Lake Gloriette Dixville, New Hampshire
Surface Area Calcs.

Drainage Area

1 sq in = .973 mi²
Total D.A = 1.87 in²
= 1.82 mi²

Slope = $\frac{3022-1849}{2.84}$
= 413 ft/mi



Attachment "C"

Source: U.S.G.S. 15' Quad Sheet

D-23
Surface Area
Normal Pond Area = 4 sq. acres
= 25.6 acres

1 sq in = .973 mi² = 100 sq. acres = 640 acres
= 1 sq. acre = 6.4 acres

1860 contour area = 6.55 squares
= 41.6 acres


Setting = 10
R₁ = 1.85
R₂ = 1.89
R_{avg} = 1.87

Results


- a) Surface Area @ normal pool elev (1845.5) = 25.6 acres
- b) Surface Area @ elev = 1860 = 41.6 acres

JMR 7-30-79

1072



Surface Area



Jmr
8-6-79

1870
D-24
1855
1850
1845

25 30 35 40

APPENDIX E
INFORMATION AS
CONTAINED IN THE NATIONAL
INVENTORY OF DAMS

END

FILMED

8-85

DTIC