

MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963 A

AD-A156 367

11

ORANGE RIVER BASIN
WHITING, MAINE

ROCKY LAKE DAMS
ME - 00399

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM



DTIC
SELECTED
JUL 05 1985
S G D

DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASS. 02154

DIG FILE COPY

MARCH 1979

MENT A
Public release
unlimited

85 06 10 00 5

DISCLAIMER NOTICE

THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM	
1. REPORT NUMBER ME 00399	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER	
4. TITLE (and Subtitle) Rocky Lake Dams NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT	
		6. PERFORMING ORG. REPORT NUMBER	
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		8. CONTRACT OR GRANT NUMBER(s)	
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS	
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		12. REPORT DATE March 1979	
		13. NUMBER OF PAGES 58	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		15. SECURITY CLASS. (of this report) UNCLASSIFIED	
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED			
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)			
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.			
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Orange River Basin Whiting Maine Rocky Lake			
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The dams consist of two stone filled timber crib structures located about 400 ft. apart. The dams are assessed to be in poor condition. Because the south-erly dam has been breached, it poses no threat to life or property downstream. It is intermediate in size with a hazard potential of low.			



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED

MAY 29 1979

Honorable Joseph E. Brennan
Governor of the State of Maine
State Capitol
Augusta, Maine 04330

Dear Governor Brennan:


I am forwarding to you a copy of the Rocky Lake Dams Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Agriculture and the Department of Transportation, cooperating agencies for the State of Maine. In addition, a copy of the report has also been furnished the owner, M.J. Garber and Herman Galvin, c/o Mr. Warren Strout, MacDonald Page Co., 562 Congress Street, Portland, Maine 04112.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you, the Department of Agriculture and the Department of Transportation for your cooperation in carrying out this program.

Sincerely yours,


JOHN P. CHANDLER
Colonel, Corps of Engineers
Division Engineer

Incl
As stated

ORANGE RIVER BASIN

WHITING, MAINE

ROCKY LAKE DAMS

ME-00399

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

Approved by	
Special	X
Dist	A/1
Special	



NATIONAL DAM INSPECTION PROGRAM

PHASE I INSPECTION REPORT

ME-00399

ROCKY LAKE DAMS

WASHINGTON COUNTY, MAINE

ROCKY LAKE

November 28, 1978

BRIEF ASSESSMENT


The Rocky Lake Dams consists of two stone-filled timber crib structures located about 400 feet apart, separated by an island. The northerly dam is in seriously dilapidated condition and the southerly dam has been breached and retains no water. The northerly dam is about 14 feet high, and is about 150 feet long.

Based on the visual inspection, the Rocky Lake Dams are assessed to be in poor condition. Because the southerly dam has been breached, it poses no threat to life or property downstream. Although the northerly dam is in poor condition, the structure appears to present little threat to the safety of downstream residents or property. Based on the Corps of Engineers guidelines, the dams are classified as intermediate size dams having a low hazard potential.


The spillway test flood is one-half the probable maximum flood (PMF). The test flood outflow is about 1450 cfs. The spillway capacity of the northerly dam plus capacity of the culvert under the road, located about 100 feet downstream of the breached southerly dam, is about 59 percent of the routed test flood.

Due to the dilapidated condition of both dams, it appears that an attempt to repair the structures would be impractical. Complete reconstruction would be required to upgrade the condition of the structures. Within 12 months of receipt of this report, the Owner should engage a qualified engineer to advise him whether to remove or reconstruct the


dams. Reconstruction or removal should be done under the supervision of a qualified engineer. If the dams are to be reconstructed, a program of annual periodic technical inspection should be instituted.





EDWARD C. JORDAN CO., INC.


Stanley E. Walker, P.E.
Project Officer


This Phase I Inspection Report on Rocky Lake Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.


JOSEPH W. FINEGAN, JR., MEMBER
Water Control Branch
Engineering Division


CARNEY M. TERZIAN, MEMBER
Design Branch
Engineering Division


JOSEPH A. MCELROY, CHAIRMAN
Chief, NED Materials Testing Lab.
Foundations & Materials Branch
Engineering Division

APPROVAL RECOMMENDED:


JOE B. FRYAR
Chief, Engineering Division

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established guidelines, the spillway test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonable possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

TABLE OF CONTENTS

	<u>PAGE</u>
LETTER OF TRANSMITTAL	
BRIEF ASSESSMENT.....	i
REVIEW BOARD SIGNATURE SHEET.....	iii
PREFACE.....	iv
TABLE OF CONTENTS.....	v
OVERVIEW PHOTOGRAPH.....	vii
LOCATION AND DRAINAGE MAP.....	viii

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL.....	1-1
1.2 DESCRIPTION OF PROJECT.....	1-1
1.3 PERTINENT DATA.....	1-3

SECTION 2 - ENGINEERING DATA

2.1 DESIGN.....	2-1
2.2 CONSTRUCTION.....	2-1
2.3 OPERATION.....	2-1
2.4 EVALUATION.....	2-1

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS.....	3-1
3.2 EVALUATION.....	3-2

SECTION 4 - OPERATING PROCEDURES

4.1 PROCEDURES.....	4-1
4.2 MAINTENANCE OF DAM.....	4-1
4.3 MAINTENANCE OF OPERATING FACILITIES.....	4-1
4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT.....	4-1
4.5 EVALUATION.....	4-1

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES.....	5-1
---------------------------------	-----

TABLE OF CONTENTS (Continued)

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY..... 6-1

SECTION 7 - ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES


7.1 DAM ASSESSMENT..... 7-1
7.2 RECOMMENDATIONS..... 7-1
7.3 REMEDIAL MEASURES..... 7-2
7.4 ALTERNATIVES..... 7-2

APPENDICES

A FIELD INSPECTION NOTES
B ENGINEERING DATA
C PHOTOGRAPHS
D HYDROLOGIC AND HYDRAULIC COMPUTATIONS
E INVENTORY FORMS



OVERVIEW



**ROCKY LAKE DAMS
WATERSHED BOUNDARY**

ROCKY LAKE DAMS

U.S. GEOLOGICAL SURVEY MAP
GARDNER LAKE, ME. QUADRANGLE
EASTPORT, ME. QUADRANGLE



CHARLES J. JORDAN, JR. PORTLAND, MAINE	ARMELINDA M. NEWELL, JR. LEWIS, MAINE
NATIONAL PROGRAM OF INSPECTION OF NON-FEE DAMS	
ROCKY LAKE DAMS	
LOCATION & DRAINAGE AREA MAP	
ROCKY LAKE	ME.
207991B	DATE AS SHOWN MARCH 1979

PHASE I INSPECTION REPORT

ROCKY LAKE DAMS

SECTION 1

PROJECT INFORMATION

1.1 GENERAL

a. Authority. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of dam inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Edward C. Jordan Co., Inc. has been retained by the New England Division to inspect and report on selected dams in the states of Maine and New Hampshire. Authorization and notice to proceed were issued to Edward C. Jordan Co., Inc. under a letter of December 1, 1978 from Max B. Scheider, Colonel, Corps of Engineers. Contract No. DACW33-79-C-0017 has been assigned by the Corps of Engineers for this work.

b. Purpose

- (1) To perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interests.
- (2) To encourage and prepare the states to initiate quickly effective dam safety programs for non-Federal dams.
- (3) To update, verify and complete the National Inventory of Dams.

1.2 DESCRIPTION OF PROJECT

a. Location. The Rocky Lake Dams are located at the outlet of Rocky Lake in the town of Whiting, Maine. N 44°-46.1', W 67°-16.0'.

b. Description of Dam and Appurtenances. The Rocky Lake Dams consist of two stone-filled timber crib structures located about 400 feet apart and separated by an island. The northerly dam is in seriously deteriorated condition and the southerly dam has been breached and retains no water. The northerly dam is about 14 feet high and is about 150 feet long.

Plan and profile and cross-sections are presented in Appendix B.

c. Size Classification. The Rocky Lake Dams have a storage capacity of about 9000 acre-feet and a height of 14 feet. According to Corp of Engineer's "Recommended Guidelines for Safety Inspection of Dams," a dam with storage capacity greater than 1,000 acre-feet but less than 50,000 acre-feet or a height greater than 40 feet but less than 100 feet is classified as an intermediate size dam.

d. Hazard Classification. The Rocky Lake Dams are classified as having a low hazard potential. The peak flow from the hypothetical failure of the dams was estimated to be about 6900 cfs based on guideline procedures provided by the Corps of Engineers. Failure of the dams would result in water surface elevations about 6.5 feet higher than normal at the outlet of Orange Lake and about 7 feet higher than normal at the first downstream bridge, about 2.2 miles below the dam. Downstream of this bridge the water surface elevation would essentially be retained within swampy areas located in the flood plain.

e. Ownership.

Current Co-Owners: M.J. Garber & Herman Galvin
Contact: M.J. Garber
c/o Warren Strout
MacDonald Page Co.
562 Congress Street
Portland, Maine 04112
Tel. 207-774-5701

Previous Owner: Unknown

f. Operator.

None. (See e. above for contact person.)

g. Purpose of Dam. This dam is presently used to control the water level at Rocky Lake Dam for recreational purposes.

h. Design and Construction History. There is no available design and construction data pertinent to the dams.

i. Normal Operating Procedure. No operating and maintenance program is followed.

1.3 PERTINENT DATA

a. Drainage Areas. The drainage area consists of approximately 16.8 square miles of gently sloping forested terrain. Rocky Lake has an area of 1.8 square miles (1150 acres), which represents about 11 percent of the drainage area.

b. Discharge at Damsite. No record of high water could be located. The impounding system consists of a northerly and a southerly dam separated by an island. The southerly dam has been breached and hydraulic control for flood waters is at the road culvert, about 100 feet downstream of the dam.

(1) Outlet Works - The outlet works at the northerly dam are inoperable. At the southerly dam (roadway hydraulic control), there is a culvert that measures 8.8 feet wide by 11.8 feet high with an invert elevation of 79 MSL, about 7.5 feet below the lake outlet. The capacity of the culvert flowing full is about 460 cfs.

(2) The maximum flood at the damsite is unknown.

(3) Ungated spillway capacity with the pond at the top of the northerly dam is 400 cfs. There is no spillway at the southerly dam.

(4) Gated spillway capacity is not applicable.

(5) Total project discharge at test flood (1/2 PMF) elevation of 93 is 1450 cfs.

c. Elevation. The survey datum was adjusted to mean sea level (MSL) datum based on the assumption that spillway crest of the northerly dam is equal to normal water surface elevation of 90 (MSL), as shown on the Gardner Lake, Maine U.S. Geologic Survey quadrangle. Due to the breaching of the southerly dam, present normal water surface is assumed to be elevation 88 (MSL).

The following elevations above mean sea level are approximate only.

<u>Item</u>	<u>Elevation (Feet Above MSL)</u>
Top of northerly dam	92.0
Top of roadway downstream of southerly dam	93.7
Test flood (1/2 PMF) pool	93.0
North dam spillway crest	90.0
Full flood control pool	N/A
Recreation pool	88
Invert culvert located downstream of southerly dam	78.9
Streambed at centerline of northerly dam	78
Maximum tailwater	Unknown

d. Reservoir.

<u>Item</u>	<u>Length (Miles)</u>
Maximum pool	3.8
Recreation pool	3.5
Flood control pool	N/A

e. Storage.

Item	Storage (Acre-Feet)
Recreation pool (elev. 88)	4200
Northerly dam spillway crest (elev. 90)	6510
Top of dam (elev. 92)	9320
Test flood (1/2 PMF) (elev. 93.0)	10430

f. Reservoir Surface.

Item	Surface Area (Acres)
Recreation pool	1100
Flood control pool	N/A
Spillway crest pool	1150
Test flood (1/2 PMF) pool	1465
Top of dam	1360

g. Dam.

Type - the dams are stone-filled timber crib structures abutted by earth embankments.

Length - The southerly dam has been breached; it was about 160 ft long. The length of the northerly dam is about 150 feet.

Height - The northerly dam is about 14 feet high.

Top Width - See plan and profile and cross-sections in Appendix B.

Side Slopes - See sketches in Appendix B.

Zoning - None.

Impervious Core - None.

Cutoff - Timber planking and mud seal.

Grout Curtain - None.

h. Diversion and Regulating Tunnel. Not applicable.

i. Spillway.

Type - The northerly dam has two self-loading timber deck spillways. See sketches in Appendix B.

Length - 39+ and 14+ feet.

Crest Elevation (Northerly Dam) - 90 (MSL).

Gates - None.

Downstream Channel - The channels below the northerly and southerly dams are narrow with a slope of about 0.7 percent. See Photographs 5 and 7. Both streambeds are composed primarily of gravel and cobbles. Located about 100 feet downstream of the southerly dam is an 8.8-foot wide by 11.8-foot high culvert beneath a road. This culvert appears to restrict the channel and is likely the hydraulic control during flood flow. The north channel is littered with debris, including two fallen trees. The two channels join as they enter Orange Lake about 1500 feet downstream of the dams.

j. Regulating Outlets.

Invert - Southerly dam - none
Northerly dam - 83 (MSL)

Size - Southerly dam - none
Northerly dam - two bays 5 ft wide by 9 ft high

Description - Control of the northerly dam outlet was by stop logs located between timber supports. Due to the deteriorated condition of the timber in the dam and the damming performed by beavers, the stop log outlet is not operable.

Control Mechanism - None

SECTION 2
ENGINEERING DATA

2.1 DESIGN

No design data were available for the Rocky Lake Dams.

2.2 CONSTRUCTION

No engineering data were available regarding construction of the dams.

2.3 OPERATION

No engineering operational data were available.

2.4 EVALUATION

- a. Availability. There are no engineering data or plans available that would be useful in evaluating the integrity of the Rocky Lake Dams.
- b. Adequacy. The lack of engineering data did not allow for a definitive review. Therefore, the adequacy of this dam could not be assessed from the standpoint of reviewing design and construction data, but is based primarily on visual inspection, performance history and engineering judgment.
- c. Validity. Not applicable.

SECTION 3
VISUAL INSPECTION

3.1 FINDINGS

- a. General. The Rocky Lake Dams consists of two structures which close the outlets from Rocky Lake. The structures are about 400 feet apart, separated by an island. The southerly dam has been breached and the northerly dam is in a dilapidated condition.
- b. Dams. The northerly dam is a stone-filled, timber cribwork structure. It is about 150 feet long and about 14 feet high. It is badly dilapidated as can be seen in Photograph 6. The timber members are rotted, split and broken, and many have become dislodged. The dam was retaining about 10 feet of water on November 28, 1978. Leakage through the structure was estimated to be 200 gpm. The stop log outlet works at the dam are dilapidated and inoperable and one outlet is presently closed by beaver workings.

The southerly dam was also a timber cribwork structure. It has been breached and presently retains no water. The timber structure is extremely dilapidated as shown in Photograph 5.

About 150 feet upstream of the remnants of the south dam, there is an earth embankment dike which appears to have been constructed since the breaching of the timber dam. This dike is about 200 feet long, 6 feet high and appears to close the old stream channel, as shown on the general site plan in Appendix B-1. The existing channel is just north of the northerly end of the dike. This channel has a bed consisting of bedrock overlain by cobbles and boulders. The channel is somewhat restricted by boulders and cobbles placed in the channel apparently to maintain low water hydraulic control. The earth dike appears to be in good condition. Some seepage is occurring at the downstream toe.

- c. Appurtenant Structures. Not applicable.

- d. Reservoir Area. The reservoir consists of Rocky Lake which is about 1150 acres and has a forested shoreline as shown in Photograph 3. There are a few cottages on the shore of the lake. The potential for slope failure above the dam appears minimal.
- e. Downstream Channel. The channels below the northerly and southerly dams are narrow with a slope of about 0.7 percent. See Photographs 5 and 7. Both streambeds are composed primarily of gravel and cobbles. Located about 100 feet downstream of the southerly dam is an 8.8-foot wide by 11.8-foot high culvert beneath a road. This culvert appears to restrict the channel and is likely the hydraulic control during flood flow. The north channel is littered with debris, including two fallen trees. The two channels join as they enter Orange Lake about 1500 feet downstream of the dams.

3.2 EVALUATION

Based on the visual inspection, the Rocky Lake Dams appears to be in poor condition. The northerly timber dam is badly dilapidated but presently intact and is retaining about 10 feet of water. The southerly timber dam has been breached. At the southerly dam low flow control is provided by a dike and restricted channel located about 150 feet upstream, and flood flows are controlled by the culvert beneath the road located about 100 feet downstream of the dam. Although in poor condition, the structure appears to present little threat to the safety of downstream residents or property. Further deterioration and eventual breaching will likely occur at the northerly dam. However, due to its timber cribwork construction, the breaching will likely occur in stages as opposed to a rapid failure of the entire structure.

SECTION 4
OPERATING PROCEDURES

4.1 PROCEDURES

There are no operating procedures.

4.2 MAINTENANCE OF DAM

There is apparently no maintenance program for the dams.

4.3 MAINTENANCE OF OPERATING FACILITIES

There is apparently no maintenance program for operating facilities.

4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT

No warning system is known to be in effect.

4.5 EVALUATION

The Rocky Lake Dam operating equipment is in poor condition and is inoperable. No formal warning system for either high water or structural distress is in effect at the dams.

SECTION 5

HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

- a. General. Both the north and south dams are stone-filled timber crib structures. The south dam has been breached and the roadway just downstream serves as the flood water hydraulic control at the southerly damsite. The two dams are about 400 feet apart and are separated by an island.
- b. Design Data. Design data were not available.
- c. Experience Data. No information regarding specific overtopping events or other notable hydrologic occurrences was disclosed. However, it is reported by a local resident that the southerly dam breached about 10 years ago. The timbers on the northerly dam are rotted, split and broken, and many have become dislodged. However, the dam is still intact.
- d. Visual Observations. The outlet of Rocky Lake is controlled by two dams. The northerly dam outlet section is inoperable, and flow is controlled by two spillway sections. On November 28, 1978, the water surface of Rocky Lake was about 2 feet below spillway crest. About 150 feet upstream of the remnants of the breached southerly dam, there is an earth dike which reportedly has been constructed since the breaching of the timber dam. This dike is about 200 feet long, 6 feet high and appears to close the old stream channel. The existing channel is just north of the northerly end of the dike. This channel has a bed consisting of bedrock overlain by cobbles and boulders. The channel is somewhat restricted by boulders and cobbles placed about 2 feet high in the channel, apparently to maintain low water hydraulic control.

Below the breached southerly dam is a roadway culvert that provides flood water hydraulic control.
- e. Test Flood Analysis. The Rocky Lake Dams are classified as having a low hazard potential. Based on Corps of Engineers "Recommended Guidelines for

Safety Inspection of Dams" the spillway test flood is 1/2 of the probable maximum flood (PMF). The test flood was calculated to be about 5500 cfs, based on the COE's "Preliminary Guidance for Estimating Probable Maximum Discharges in Phase I Dam Safety Investigations." Consideration of the effect of surcharge storage reduces the test flood to 1450 cfs. The spillway capacity of the north dam plus the culvert capacity at the south damsite is about 860 cfs, which is about 59 percent of the routed 1/2 PMF. During the test flood event, the north dam would be overtopped by about 1 foot.

- f. Dam Failure Analysis. The hazard potential was determined by analyzing downstream dam failure hydrographs based on rule of thumb methods presented in an attachment to ETL 1100-2-234. The failure analysis assumes a breaching of the northerly dam with water surface at the top of the dam.

The peak flood flow including a breaching of the north dam, and flow through the culvert at the south damsite would be about 5700 cfs. Rocky Lake would empty in about 38 hours. The wave height at the north dam would be about 10 feet. At the outlet from Orange Lake, about 1.3 miles downstream, the flood peak would be attenuated to about 4200 cfs, and the normal elevation of the lake would rise about 6.5 feet. At the first downstream bridge, 2.2 miles below the dams, the flood peak would be reduced to about 3400 cfs and the flood depth would be about 7 feet. Downstream of the bridge the flood wave would essentially be maintained within swampy areas adjacent to the Orange River.

It appears that no downstream residences would be affected by failure of the dam. Potential damage appears to be limited to the cemetery on the north bank of the north discharge channel, and the bridge located about 2.2 miles downstream of the dams.

Since the timber crib structure of the north dam is badly dilapidated, resistance to overtopping is considered to be poor. Based on test flood calculations, the roadway at the south dam site would not be overtopped by the 1/2 PMF.

SECTION 6

STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

- a. Visual Observations. Based on the visual inspections, the Rocky Lake Dams appear to be in poor condition. The northerly timber dam is badly dilapidated but presently intact. However, flood flows overtopping the spillway sections would likely cause progressive breaching of the dam. Due to its timber cribwork construction, breaching will likely occur in stages. The southerly timber dam has been breached. The flow control at the south damsite is provided by a dike and restricted channel upstream and the road and culvert downstream.
- b. Design and Construction Data. None available.
- c. Operating Records. None available.
- d. Post Construction Changes. Since original construction, both the north and south dams have undergone progressive deterioration and the south dam has been breached. Subsequent to the breaching of the south dam, an earth dike had been constructed upstream of the timber dam to restrict the channel and maintain pond level.
- e. Seismic Stability. The dam is located in Seismic Zone No. 1 and in accordance with recommended Phase I Guidelines, does not warrant seismic analysis.

SECTION 7

ASSESSMENT, RECOMMENDATIONS, AND REMEDIAL MEASURES

7.1 DAM ASSESSMENT

- a. Condition. Based on the visual inspection and performance history of the Rocky Lake Dams, they are assessed to be in poor condition. The southerly dam has been breached. Low flow control is provided presently by an earth dike which restricts the upstream channel and, high flow control is provided by a roadway culvert in the downstream channel. The northerly dam is intact and retains about 10 feet of water. This timber structure is seriously dilapidated and flows overtopping the spillway section will likely cause progressive breaching. Due to the lack of significant downstream hazard, however, the condition presents little threat to the safety of downstream residents or property.
- b. Adequacy of Information. The information available is such that the assessment of the condition of the dam must be based primarily on the visual inspection, the past operational performance of the dam, and engineering judgment.
- c. Urgency. The recommendations and remedial measures outlined in 7.2 and 7.3 below should be implemented within 12 months after receipt of this report by the owner.
- d. Need for Additional Investigation. Additional investigation is not considered necessary for the current assessment.

7.2 RECOMMENDATIONS

A qualified engineer should be engaged to advise the Owner whether to remove or reconstruct the dams. Reconstruction or removal should be done under the supervision of a qualified engineer with consideration given to potential release of accumulated sediments or other possible environmental impacts of lowering the level of Rocky Lake. Any structure built to maintain the lake in back of the breached dam, such as the present dike, should be appropriately designed by a qualified engineer.

7.3 REMEDIAL MEASURES

- a. Operation and Maintenance Procedures. Due to their dilapidated condition, it appears that an attempt to repair the structures from their present condition would be impractical. Complete reconstruction would be required to upgrade the condition of the structures. If the dams are to be reconstructed, a program of annual periodic technical inspection should be instituted.

The remains of the south dam should be removed from the channel. Further break-up of this breached dam could clog the downstream culvert causing flooding.

7.4 ALTERNATIVES

The alternatives available appear to be removal of the structures or replacement (reconstruction) of the structures.

VISUAL INSPECTION CHECKLIST
PARTY ORGANIZATION

PROJECT Rocky Lake Dams

DATE 11/28/78

TIME P.M.

WEATHER Snow, rain, cold

W.S. ELEV. _____ U.S. _____ DN.S. _____

PARTY:

- | | |
|---------------------------|-----------|
| 1. <u>Stephen Cole</u> | 6. _____ |
| 2. <u>Brian Bisson</u> | 7. _____ |
| 3. <u>Scott Decker</u> | 8. _____ |
| 4. <u>John Kimble</u> | 9. _____ |
| 5. <u>Charles Goodwin</u> | 10. _____ |

PROJECT FEATURE	INSPECTED BY	REMARKS
1. <u>Geotechnical</u>	<u>Cole</u>	
2. <u>Structural</u>	<u>Cole, Decker</u>	
3. <u>Hydraulics/Hydrology</u>	<u>Bisson</u>	
4. <u>Civil</u>	<u>Decker</u>	
5. <u>Photography</u>	<u>Decker, Bisson</u>	
6. <u>Survey</u>	<u>Kimble, Goodwin</u>	
7. _____		
<u>Review Inspection</u>	<u>Stanley Walker and</u>	
<u>Dec. 14, 1978</u>	<u>Charles Horstmann</u>	
<u>No significant differences observed from 11/28/78 inspection</u>		

NOTE: See Supplementary Inspection Notes Following Checklist

INSPECTION CHECKLIST

PROJECT <u>Rocky Lake Dams</u>	DATE <u>11/28/78</u>
PROJECT FEATURE <u>Embankment</u>	NAME <u>Cole</u>
DISCIPLINE <u>Geotechnical</u>	NAME _____

AREA EVALUATED	CONDITIONS
<u>DAM EMBANKMENT</u>	South dam dike* at pond, above old dam
	North dam - no dike embankment
Crest Elevation	92+ (MSL)
Current Pool Elevation	88 (MSL) NOT APPLICABLE
Maximum Impoundment to Date	Unknown
Surface Cracks	None
Pavement Condition	Turf
Movement or Settlement of Crest	None
Lateral Movement	None
Vertical Alignment	Okay
Horizontal Alignment	Okay
Condition at Abutment and at Concrete Structures	N/A
Indications of Movement of Structural Items on Slopes	None
Trespassing on Slopes	None
Sloughing or Erosion of Slopes or Abutments	None
Vegetation	Turf

*Dike does not close the stream, about 40 feet of open channel exists north of the dike. This section controls at low flow.

AREA EVALUATED	CONDITIONS	
<u>DAM EMBANKMENT</u> (cont.)	South Dam	North Dam
Rock Slope Protection - Riprap Failures	None	NOT APPLICABLE
Unusual Embankment or Downstream Seepage	Minor seepage near midpoint of dike.	
Piping or Boils	None	
Foundation Drainage Features	None	
Toe Drains	None	
Instrumentation System	None	

INSPECTION CHECKLIST

PROJECT Rocky Lake Dams DATE 11/28/78
 PROJECT FEATURE Intake Channel, Structural NAME Cole, Decker
 DISCIPLINE Structural, Geotechnical NAME Bisson
Hydraulics/Hydrology

AREA EVALUATED	CONDITION	
<u>OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE</u>	South Dam	North Dam
a. Approach Channel		
Slope Conditions	Flat, stable	Flat, stable
Bottom Conditions	Gravel	Ice covered, could not be observed.
Rock Slides or Falls	None	None
Log Boom	None	None
Debris	None	Beaver workings
Condition of Concrete Lining	N/A	N/A
Drains or Weep Holes	N/A	N/A
b. Intake Structure		
Condition of Concrete	N/A	Timber, poor
Stop Logs and Slots	N/A	Timber, poor

INSPECTION CHECKLIST

PROJECT Rocky Lake Dams DATE 11/28/78
 PROJECT FEATURE Control Tower NAME Cole, Decker
 DISCIPLINE Structural, Civil NAME Bisson
Hydraulics/Hydrology

AREA EVALUATED	CONDITION	
	South Dam	North Dam
<u>OUTLET WORKS - CONTROL TOWER</u>		
a. Masonry and Structural		
General Condition	Old timber dam downstream of earth dike has been breached.	Control tower consists of deteriorated timber stop log bays.
Condition of Joints		
Spalling	Control tower has collapsed.	
Visible Reinforcing		
Rusting or Staining of Concrete		
Any Seepage or Efflorescence		
Joint Alignment		
Unusual Seepage or Leaks in Gate Chamber		
Cracks		
Rusting or Corrosion of Steel		
b. Mechanical and Electrical		
Air Vents		Stop log bays are inoperable and filled with debris.
Float Wells	N/A	
Gate Hoist		
Elevator		

AREA EVALUATED	CONDITIONS	
<u>OUTLET WORKS - CONTROL TOWER (cont.)</u>	South Dam	North Dam
Hydraulic System	N/A	Stop log bays inoperable
Service Gates		
Emergency Gates		
Lightning Protection System		
Emergency Power System		
Wiring and Lighting System		

INSPECTION CHECKLIST

PROJECT Rocky Lake Dams DATE 11/28/78
 PROJECT FEATURE Transition, conduit NAME Cole, Bisson
 DISCIPLINE Structural, Civil NAME Decker
Hydraulics/Hydrology

AREA EVALUATED	CONDITION	
<u>OUTLET WORKS - TRANSITION AND CONDUIT</u>	South Dam	North Dam
General Condition of Concrete	Old timber dam	Deteriorated timber
Rust or Staining on Concrete	has been breached.	sill and training
Spalling		walls. Intact but
Erosion or Cavitation		badly rotted.
Cracking	NOT APPLICABLE	
Alignment of Monoliths		
Alignment of Joints		
Numbering of Monoliths		

PERIODIC INSPECTION CHECKLIST

PROJECT Rocky Lake Dams DATE 11/28/78
 PROJECT FEATURE Outlet Structure, Channel NAME Cole, Decker
 DISCIPLINE Structural, Geotechnical NAME Bisson
Hydraulics/Hydrology

AREA EVALUATED	CONDITION	
<u>OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL</u>	South Dam	North Dam
General Condition of Concrete	Old timber dam	Outlet structure
Rust or Staining	has been breached.	consists of timber
Spalling		cribwork, badly
Erosion or Cavitation		rotted.
Visible Reinforcing	NOT APPLICABLE	
Any Seepage or Efflorescence		
Condition at Joints		
Drain holes		
Channel		
Loose Rock or Trees Overhanging Channel	None	Trees in channel and on both sides of channel.
Condition of Discharge Channel	Bedrock, some cobbles and boulders. 8.8'x 11.8' culvert just below dam.	Channel bed consists of cobbles, gravel and boulders, no erosion evident.

INSPECTION CHECKLIST

PROJECT Rocky Lake Dams DATE 11/28/78
 PROJECT FEATURE Spillway NAME Cole, Decker
 DISCIPLINE Structural, Civil NAME Bisson
Hydraulics/Hydrology

AREA EVALUATED CONDITION

OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS

	South Dam	North Dam
a. Approach Channel		
General Condition	Good	Good
Loose Rock Overhanging Channel	None	None
Trees Overhanging Channel	None	None
Floor of Approach Channel	Bedrock, gravel, cobbles, boulders	Could not be observed, ice
b. Weir and Training Walls		
General Condition of Concrete and Masonry	Timber dam breached.	Timber cribwork, very rotten.
Rust or Staining		
Spalling		NOT APPLICABLE
Any Visible Reinforcing		
Any Seepage or Efflorescence		
Drain Holes		
c. Discharge Channel		
General Condition		
Loose Rock Overhanging Channel	None	None
Trees Overhanging Channel	None	Trees in channel
Floor of Channel	Bedrock, cobble and boulders	Gravel, cobbles and boulders
Other Obstructions	Culvert just downstream	None

INSPECTION CHECKLIST

PROJECT Rocky Lake Dam DATE 11/28/78
 PROJECT FEATURE Service Bridge NAME Cole
 DISCIPLINE Structural NAME _____

AREA EVALUATED	CONDITION
----------------	-----------

OUTLET WORKS - SERVICE BRIDGE

a. Superstructure

Bearings

Anchor Bolts

Bridge Seat

Longitudinal Members

NOT APPLICABLE

Under Side of Deck

Secondary Bracing

Deck

Drainage System

Railings

Expansion Joints

Paint

b. Abutment & Piers

General Condition of Concrete

Alignment of Abutment

Approach to Bridge

Condition of Seat & Backwall

SUPPLEMENTARY INSPECTION NOTES

ROCKY LAKE DAMS WHITING, MAINE

APPENDIX A

The Rocky Lake Dams consists of two structures about 400 feet apart and separated by an island. The spillway section of the southerly dam has been breached. The breached width is approximately 20 feet and the stream is flowing in its natural streambed through this opening. The northerly dam was found to be retaining approximately 10 feet of water.

1. TIMBER STRUCTURES IN GENERAL

Both dams are constructed of stone-filled self-loading timber cribs. The timber members are seriously deteriorated and rotted. The broken timber members have become displaced and stone fill has fallen through. The penstock area and powerhouse at the southerly dam have collapsed and could not be inspected due to the hazardous condition of the dilapidated structure. The northerly dam, although seriously deteriorated is generally intact.

2. EMBANKMENT STRUCTURES

An earth embankment dike, located approximately 150 feet upstream of the southerly dam, partially closes the southerly outlet from Rocky Lake. This embankment is approximately 6 feet high with about an 8 foot top width and 2 to 1 side slopes. This embankment has a grassed surface and appears to be well maintained with little or no brush growth apparent. This embankment appears to have been constructed subsequent to the breaching of the dam downstream.

The embankment does not entirely close off the southerly outlet channel. It appears that the embankment was either not extended across the channel or has been breached. The channel is partially filled with stones and retains approximately 1 to 2 feet of water.

- a. Settlement. The southerly earthen embankment dike section was found to be in good condition with little or no settlement.

- b. Slope Stability. The slopes of the embankment appear generally true to line and grade and no slope stability problem appears to exist.
- c. Seepage. Very minor seepage was occurring at the downstream toe of this structure.
- d. Drainage Systems. None were observed.
- e. Slope Protection. Logs were lying on the upstream slope of the northerly dam, a little above the water line. No other form of slope protection was in evidence. Little or no erosion was apparent on the upstream slope.

3. SPILLWAY STRUCTURES

The spillway structure at the southerly dam has been breached. The northerly dam has a timber self-loading timber deck spillway. The timber is seriously deteriorated and in poor condition. There are no control gates on the spillway.

a. Control Gates and Operating Machinery.

None operable.

b. Unlined Saddle Spillways. The area north of the earth embankment dike upstream of the southerly dam is an unlined saddle spillway. It is about 40 feet in width, and consists of cobbles and boulders overlying bedrock.

c. Approach and Outlet Channels. Southerly dam approach appears to be clear and unobstructed both at the embankment dike upstream and at the breached dam. The southerly dam outlet channel is generally unobstructed, however, a 8.8 foot wide by 11.8 foot high culvert exists approximately 100 feet downstream from the dam. Debris from the old timber spillway plus this culvert during high flow conditions. The approach channel to the northerly dam was generally clear. However, a beaver lodge exists approximately 30 feet upstream of the dam near the north bank and debris from this area could clog the spillway or outlet sections of the dam structure. The outlet channel is lined with trees and could be easily obstructed by debris from the dam or debris passing over the dam.

d. Stilling Basin. The stilling basin at the southerly dam is a bedrock channel with no erosion apparent. The stilling basin at the northerly dam is a channel, no erosion was evident.

e. Drawdown Facilities. There are no drawdown facilities at either dam. Although the south dam has been breached, the lake outlet channel has been partially filled with stone to a height of about 2 feet, and at low flows the stone fill controls hydraulically. The north dam gates are inoperable.

4. OUTLET WORKS

There are no outlet works at the southerly dam. At the northerly dam there are two stop log outlet structures. One has been closed with vertical planking over the deteriorated stop logs. The other outlet has apparently been closed by debris and the work of beavers.

5. SAFETY AND PERFORMANCE INSTRUMENTATION

There is no safety performance instrumentation at the dam.

6. RESERVOIR

a. Shoreline. No major active or inactive landslide areas on the Rocky Lake shoreline were observed.

b. Sedimentation. The extent of sedimentation in the pond could not be observed during the visual inspection, but it does not appear to impede flow to either of the two dams.

c. Potential Upstream Hazard Area. No significant upstream hazard was observed.

d. Watershed Runoff Potential. The watershed is essentially rural with flat to mildly sloping terrain.

7. DOWNSTREAM CHANNEL

The channels below the northerly and southerly dams are narrow with a slope of about 0.7 percent. See Photographs 5 and 7. Both streambeds are composed primarily of gravel and cobbles. Located about 100 feet downstream of the southerly dam is an 8.8 foot wide by

11.8 foot high culvert beneath a road. This culvert appears to restrict the channel and is the hydraulic control during flood flow. The north channel is littered with debris, including two fallen trees. The two channels join as they enter Orange Lake about 1500 feet downstream of the dams.

8. OPERATION AND MAINTENANCE FEATURES

- a. Maintenance. Based on the observations made and information reported by a local resident, no maintenance has been performed on the dam in the past 10 years. It was reported that the southerly dam was breached approximately 10 years ago.

APPENDIX B

ENGINEERING DATA

This appendix lists the engineering data collected either from project records or other sources of data developed as a result of the visual inspection. The contents of this appendix are listed below.

<u>Appendix</u>	<u>Description</u>
B-1	General Project Data


APPENDIX B-1

GENERAL PROJECT DATA

The following plan, profile and cross-sections of the dams were developed from a limited stadia survey performed during visual inspection, field notes taken by inspection team members, and photographs taken during the visual inspection. The survey was referenced to an arbitrary local datum. Approximate U.S.G.S. elevations were obtained by noting the dam's location on the Gardner Lake, Maine U.S. Geologic Survey quadrangle and assuming that the spillway crest of the northerly dam to be equal to normal water surface of approximate elevation 90 (MSL).

B-1.1

Rocky Lake Dam



CORRUGATED METAL PIPE-ARCH
8.8' ± X 11.8' ±

LEGEND


-  SEEPAGE
-  PHOTOGRAPH LOCATION/ORIENTATION

NOT TO SCALE

8-1.2

EDWARD C. JORDAN CO., INC. PORTLAND, ME 04102	U.S. ARMY CORPS OF ENGINEERS PORTLAND DISTRICT PORTLAND, ME 04102
NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS	
ROCKY LAKE DAMS	
GENERAL SITE SKETCH	
ORANGE RIVER	MAINE
DATE: MARCH 1978	

2079915




PLAN

DOWNSTREAM PROFILE


EDWARD J. JOHAN, INC. PROF. ENG. REG. NO.	U.S. ARMY ENGINEER DISTRICT OFFICE WALTON, MASS.
NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS	
ROCKY LAKE DAMS	
SOUTHERLY DAM	
PLAN AND PROFILE	
ORANGE RIVER	MAINE
SCALE	DATE MARCH 1975

2079915

B-1.3



PLAN




DOWNSTREAM PROFILE


2079915

B-1.4


EDWARD J. JORDAN, JR. INC. PROF. ENG. REG. NO. 10406	U.S. ARMY CORPS OF ENGINEERS DISTRICT OFFICE BANGOR, MAINE
NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS	
ROCKY LAKE DAMS NORTHERLY DAM PLAN AND PROFILE	
ORANGE RIVER	MAINE
SCALE	DATE: MARCH 1973



SECTION A




SECTION B




2079915

B-1.5


PROJECT NUMBER: 2079915	DATE: 11/28/78
NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS	
ROCKY LAKE DAMS	
NORTHERLY DAM	
X-SECTIONS	
ORANGE RIVER	MAINE
SCALE	DATE: 11/28/78



SECTION C



SECTION D



2079915

B-1.6

FORWARD APPROVED BY	DATE	FORWARD APPROVED BY	DATE
NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS		ROCKY LAKE DAMS	
ORANGE RIVER		MAINE	
SCALE		DATE	

APPENDIX C


PHOTOGRAPHS

The following are photographs referenced in this report.
See Sheet B-1 for photograph locations and orientations.




1

SOUTH DAM - DOWNSTREAM FACE



2

NORTH DAM - DOWNSTREAM FACE



3

UPSTREAM CHANNEL



4

SOUTH DAM - EARTH DIKE UPSTREAM



5

SOUTH DAM - DOWNSTREAM CHANNEL



6

SOUTH DAM - UPSTREAM CONTROL



7

NORTH DAM - DOWNSTREAM CHANNEL



3

UPSTREAM CHANNEL



4


SOUTH DAM - EARTH DIKE UPSTREAM

APPENDIX D

HYDROLOGIC AND HYDRAULIC COMPUTATIONS

Hydrologic computations pertinent to this investigation are attached. The following Location and Drainage area map shows the Rocky Lake watershed at the Rocky Lake Dams.

**ROCKY LAKE DAMS
WATERSHED BOUNDARY**




U.S. GEOLOGICAL SURVEY MAP
GARDNER LAKE, ME. QUADRANGLE
EASTPORT, ME. QUADRANGLE



DATE	PROJECT	NO.	DEVELOPER	SCALE	ON
	STATE	NO.	NO.	NO.	NO.
NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS					
ROCKY LAKE DAMS					
LOCATION & DRAINAGE AREA MAP					
ROCKY LAKE			ME.		
2075915			AS SHOWN		
			MARCH 1979		

PROJECT STORAGE AND DISCHARGE RATIO CURVE FOR NORTH AND SOUTH DAMS	COMP BY STL	JOB NO. E-7-15
	CHK BY JL	DATE 3-22-77



D-3

Rocky Lake Dam

PROJECT ARCA EDWARDS LAKE DAMS	COMP BY STJ	JOB NO. E-115-15
	CHK BY JJC	DATE 2-5-77

ITEM	AREA sq. ft. In ³	AREA sq. ft.	AREA sq. ft.
Rocky Lake D.A.	16.8	16.8	10750
Rocky Lake @ EL 90	1.80	1.80	1150
Rocky Lake @ EL 100	3.43	3.43	2195
Rocky Lake @ EL 105	6.00	6.00	3891
George Lake @ EL 75	0.38	0.38	243
George Lake @ EL 80	0.66	0.66	422
George Lake @ EL 100	1.16	1.16	742

FINAL COE INVENTORY OF DAMS:

Normal Operating Capacity = 6510 A-S-F
 Maximum " " " " = 7420 A-S-F

Normal Capacity shown in blue

Maximum Capacity @ Top of Dam
 (@ EL 90):

$$6510 + 21150 + \left[\frac{21150 - 1150}{2} \left(\frac{1}{10} \right) \right] = \underline{9020 \text{ A-S-F}}$$

To be used for max. capacity

PROJECT ROCKY LAKE DAM WATER CONTROL	COMP BY LTC	JOS NO. 2-799-15
	CHK BY CDD	DATE 1-2-78

WEIR DESIGNATION	LENGTH	C
South Dam	95	variable ←
North Dam Spilling	54	"
South Dam Road ¹	63	"

¹ South Dam is breached. Any weir flow at the South Dam site would be over the roadway just downstream of the dam.

5-40 HANDBOOK OF HYDRAULICS
KING & KRATER
Table 5-3. Values of C in the Formula $Q = CLH^{3/2}$ for Broad-crested Weirs

Measured head in feet, H	Breadth of crest of weir in feet												
	0.50	0.75	1.00	1.50	2.00	2.50	3.00	4.00	5.00	10.00	15.00		
0.2	2.80	2.75	2.69	2.62	2.54	2.48	2.44	2.38	2.31	2.49	2.68		
0.4	2.92	2.80	2.72	2.64	2.61	2.60	2.58	2.54	2.50	2.56	2.70		
0.6	3.08	2.89	2.75	2.64	2.61	2.60	2.68	2.69	2.70	2.70	2.70		
0.8	3.30	3.04	2.85	2.68	2.60	2.60	2.67	2.68	2.68	2.69	2.64		
1.0	3.32	3.14	2.98	2.75	2.66	2.64	2.65	2.67	2.68	2.68	2.63		
1.2	3.32	3.20	3.08	2.84	2.70	2.65	2.64	2.67	2.66	2.69	2.64		
1.4	3.32	3.26	3.20	2.92	2.77	2.68	2.64	2.65	2.65	2.67	2.64		
1.6	3.32	3.29	3.28	3.07	2.89	2.75	2.68	2.66	2.65	2.64	2.63		
1.8	3.32	3.32	3.31	3.07	2.88	2.74	2.68	2.66	2.65	2.64	2.63		
2.0	3.32	3.31	3.30	3.03	2.85	2.76	2.72	2.68	2.65	2.64	2.63		
2.5	3.32	3.32	3.31	3.26	3.07	2.89	2.81	2.72	2.67	2.64	2.63		
3.0	3.32	3.32	3.32	3.32	3.20	3.05	2.92	2.73	2.66	2.64	2.63		
3.5	3.32	3.32	3.32	3.32	3.32	3.19	2.97	2.76	2.68	2.64	2.63		
4.0	3.32	3.32	3.32	3.32	3.32	3.32	3.07	2.79	2.70	2.64	2.63		
4.5	3.32	3.32	3.32	3.32	3.32	3.32	3.32	2.58	2.74	2.64	2.63		
5.0	3.32	3.32	3.32	3.32	3.32	3.32	3.32	3.07	2.79	2.64	2.63		
5.5	3.32	3.32	3.32	3.32	3.32	3.32	3.32	3.32	2.88	2.64	2.63		

PROJECT ROCKY LAKE DAM HYDRA LOG NORTH DAM	COMP BY BTE	JOB NO. E-730
	CHK BY SD	DATE 4-2-57

MSL DATE ELEV	SPILLW HEAD FEET	SPILLW G CFS	DAM HEAD FEET	1 AM CFS	TOTAL DAM CFS
9.0	0	-		-	
	1	143			143
	2	403	0		403
	3	741	1	250	911
9.4	4	1140	2	707	1847
	5	1536	3	1298	2834
	6	2095	4	1999	4094
	7	2640	5	2793	5433
	8	3220	6	3672	6892
	9	3849	7	4607	8456
10.0	10	4505	8	5653	10158
	11	5251	9	6746	11997
10.2	12	5906	10	7901	13907
	13	6682	11	9115	15897
	14	7468	12	10386	17954
	15	8272	13	11711	20083
10.4	16	9106	14	13083	22289
	17	9971	15	14513	24584
10.6	18	10867	16	15991	26958
	19	11805	17	17510	29415
10.8	20	12751	18	19070	31921

PROJECT ROCKY LAKE DAM	COMP BY LTC	JOB NO. 5-75-11
	CHK BY	DATE

25.00
2700.00

DATE ELEV	CULVERT AREA SQ	CULVERT FLOW CFS	WEIR CFS	TOTAL CULVERT AND FLOW
75	2.0	35		35
80	18.1	102		102
85	34.3	193		193
90	50.5	284		284
95	66.1	371		371
97	77.4	435		435
100	81.7	457		457
102			27	484
103			246	730
104			578	1308
105			993	1432
106			1211	1936
107			2021	2411
108			2620	3077
109			3202	3722
110			3961	4411
111			4671	5151
112			5411	5922
113			6274	6751
114			7127	7656
115			8037	8611
116			8916	9611
117			9904	10611

1 since no water in culvert was observed for 1.5 days, it may be 1.0 foot.

PROJECT STORM - ESCAPE TABLE	COMP BY BTE	JOB NO. E-579115
	CHK BY CC	DATE 2-5-77

MIS- LATITUDE ELEV	TOTAL- ELEV FEET	STORAGE ¹ AREA-FT
88	371	4206
	403	5357
90	435	6510
	570	7714
92	562	8923
	1450	10435
94	2222	11751
	3577	13504
96	5131	15247
	6575	17122
98	8224	17064
	10957	21177
100	13240	23247
	15674	25514
102	18242	27974
	20755	30573
104	23777	33211
	26746	36340
106	27212	37467
	33013	42765
108	32276	45231
	37275	47567
110	42194	53675

¹ Normal water surface taken as ELEV.

PROJECT KANE LAKE DAM	COMP BY BTE	JOB NO. 2571-15
	CHK BY BTE	DATE 2-5-70

According to "PROVISIONAL GUIDANCE FOR ESTIMATING MAX PROBABLE DISCHARGE" by CCE

For Flat D.A. = 10 ft $\frac{1}{4}$ M., $Q = 65$ CSM

$$Q = 65 (15 F) = 10750 \text{ CFS} = \text{PME}$$

$$5460 \text{ CFS} = \frac{1}{2} \text{ PME}$$

ESTIMATING EFFECT OF SURCHARGE STORAGE:

$$Q_{P2} = Q_{P1} \left(1 - \frac{\text{STOR}_1}{\text{Puroft}} \right)$$

$$\text{PME Puroft} = 19'' ; \frac{1}{2} \text{ PME Puroft} = 9.5''$$

$$\text{Elev to pass } Q_{P2} (\text{PME}) = \underline{77.5'}$$

$$\text{STOR}_1 = 21102 - 4005 = 16270 \text{ AC-ft}$$

$$\text{OR } \frac{16270}{10750} \times \frac{12 \text{ in}}{1 \text{ ft}} = 18.26''$$

$$Q_{P2} = 10920 \left(1 - \frac{18.26}{19} \right) = 82$$

$$\text{STOR}_2 \cong 0$$

$$Q_{P3} = 10920 \left(1 - \frac{(18.26 + 0)/2}{19} \right) = 5500$$

$$\text{Elev to pass } Q_{P3} = \underline{96.2}$$

PROJECT D-10 ROCKY LAKE DAM	COMP BY LTK	JOB NO. E-37-15
	CHK BY LTK	DATE 2-5-75

$$STOR_3 = 15000 - 4000 = 11000 \text{ A.F.}$$

$$\text{OR } \frac{11477}{10752} \times 12 = 12.7$$

$$STOR_{AVE} = \frac{12.7 + 11.12}{2} = 11.91$$

$$Q_{p4} = 10900 \left(1 - \frac{11.91}{17}\right) = 4520$$

$$\text{Elev. to pass } Q_{p4} = 95.6$$

$$STOR_4 = 14622 - 4000 = 10622 \text{ A.F.}$$

$$\text{OR } \frac{10416}{10752} \times 12 = 11.63$$

$$STOR_{AVE} = \frac{11.63 + 11.12}{2} = 11.37$$

$$Q_{p5} = 10900 \left(1 - \frac{11.37}{17}\right) = \underline{\underline{4354}} \text{ CFS}$$

$$\text{Elev. to pass } Q_{p5} = \underline{\underline{95.5}}$$

PROJECT V ₂ P.A.	COMP BY DT	JOB NO. 2070015
	CHK BY DT	DATE 2-5-57

Elev. to pass Q_{p2} (K. 51) = 543.0
is 93.2'

$$STOR_{p2} = 15043 - 4200 = 11430 \text{ A. - Ft}$$

$$\text{OR } \frac{11430}{1.75} \times 12 = 78.24''$$

$$Q_{p2} = 5430 \left(1 - \frac{78.24}{9.5}\right) < 0$$

$$\therefore STOR_{p2} = 0, \text{ \& } STOR_{p1} = \frac{10700}{1.5} = 7133''$$

$$Q_{p2} = 5430 \left(1 - \frac{7133}{9.5}\right) = 1775 \text{ cfs}$$

Elev. to pass Q_{p3} = 93.4

$$STOR_{p3} = 11070 - 4200 = 7070 \text{ A. - Ft}$$

$$\text{OR } \frac{7070}{1.5} \times 12 = 56.56''$$

$$STOR_{p3} = 7070 - 7000 = 70''$$

$$Q_{p3} = 5430 \left(1 - \frac{70}{9.5}\right) = 1440 \text{ cfs}$$

Elev. to pass Q_{p4} = 93.0

$$STOR_{p4} = 10435 - 4200 = 6227 \text{ A. - Ft}$$

$$\text{OR } \frac{6227}{1.075} \times 12 = 69.5''$$

$$STOR_{p4} = 695 + 700 = 1395''$$

$$Q_{p4} = 5430 \left(1 - \frac{1395}{9.5}\right) = 1450 \text{ cfs}$$

\& FL 93.0

PROJECT Dam Failure Hydrographs	COMP BY EJC	JOB NO. 7-1-1
	CHK BY EJC	DATE 1-1-71

$$Q_p = 8100 \sqrt{14} \cdot Y_0^{3/2}$$

$$Y_0 = Q_p T = 12.1 \text{ S}$$

Note: Dam is most vulnerable to failure

$$\therefore V_0 = 0.4 (147) = 57.6$$

$$Y_0 = 14'$$

$$Q_{T2} = 1.7 (57.6) \sqrt{14} \cdot 14^{3/2} = 5700 \text{ cfs}$$

Top of Dam at EL 90

Assumed Failure in Spillway River
 Section Below Spillway at EL 90
 Section Dam = 40000 cfs


$$\text{Total Failure Flow}^1 = \underline{5700 \text{ cfs}}$$

$$\text{Storage} = 90000 \text{ Ac-ft}$$

$$T = \frac{12.1 (90000)}{1/2 (5700)} = \underline{38.3 \text{ hrs}}$$

¹ Failure is assumed to occur through the spillway section. Therefore, no additional flow is added to the total failure flow for spillway discharge.

PROJECT STATION 1+00 TO 1+100 CULVERT UNDER ROAD	COMP BY DTL	JOB NO. 10115
	CHK BY CS	DATE 2-6-7



Slope = $\frac{10}{25} = 0.4000$

EL E V	A	A	A	Q = 1.49 A ^{1.49} S ^{0.485}
	AREA	PERIMETER	WET AREA	DISCHARGE
78	240	—	—	—
80	400	130.0	118.0	118.0
82	420	135.0	125.0	125.0
84	440	140.0	132.0	132.0
86	460	145.0	140.0	140.0
88	480	150.0	148.0	148.0
90	500	155.0	156.0	156.0
92	520	160.0	164.0	164.0
94	540	165.0	172.0	172.0
96	560	170.0	180.0	180.0
98	580	175.0	188.0	188.0
100	600	180.0	196.0	196.0

PROJECT D. Failure Hydrographs	COMP BY LTC	JOB NO. 20799 15
	CHK BY SC	DATE 2-6-75

$Q_{p2} = 5700 \text{ cfs}$
 AT OUTLET OF DRAINER POND
 $Q_{p2} @ \text{EL } 83.4$
 $V_2 = 2651 \text{ ft}^2$

$$Q_1 (\text{TRAIL}) = Q_{p2} \left(1 - \frac{V_1}{V_2}\right)$$

$$Q_1 (\text{TRAIL}) = 5700 \left(1 - \frac{2051}{9225}\right) = 4025 \text{ cfs}$$

$Q_{p2} (\text{TRAIL}) @ \text{EL } 72.4$, $V_2 = 2424 \text{ ft}^2$

$$Q_{p2} = 5700 \left(1 - \frac{2651 + 2424}{9225}\right) = \underline{\underline{4155 \text{ cfs}}}$$


@ EL 72.4'

OR APPROX. 64'
above normal pond
Elevation.

$$T = \frac{12.1 (4155)}{V_2 (4155)} = 52.5 \text{ hrs}$$

PROJECT STORAGE - DISCHARGE AT FIRST BRIDGE BELOW CRANES LAKE	COMP BY BTR	JOB NO. 2075-15
	CHK BY CD	DATE 2-6-79

300,000 ft. $n = 0.03$
 X-Section 100 - bridge
 Location



Slope = 0.25:1

FLFV	Area Ac STORAGE	Ac-Ft STORAGE	DISCHARGE CFS
67	14	7	
	28	22	
70	41	62	180
	55	110	
	69	172	
	83	248	
	96	337	
75	110	441	1667
	124	556	2217
	137	677	2863
	151	793	3613
	165	911	4473
80	177	1164	5455

PROJECT Downstream Hydrographs	COMP BY S.E.	JOB NO. 2-7-75
	CHK BY C.	DATE 2-6-75

$$Q_p = 4155$$

AT BRIDGE 2 MILES DOWNSTREAM OF DAM.

$$Q_p @ EL 78.6'$$

$$V_1 = 933 \text{ A. FT}$$

$$Q_p (\text{TRIAL}) = 4155 \left(1 - \frac{933}{900}\right) = 3725 \text{ CFS}$$

$$S_T (\text{TRIAL}) @ FL 75.1', V_2 = 854 \text{ A. FT}$$

$$Q_p = 3725 \left(1 - \frac{(933 + 854)/2}{900}\right) = \underline{\underline{3150 \text{ CFS}}}$$


@ FL 77.7'

Downstream of bridge the future hydrograph would be maintained within the study design as shown on the Fort St. Vrain USB map.

$$T = 1.48 \left(\frac{L}{V}\right) = \underline{\underline{65 \text{ hrs}}}$$

$$V = 325 \text{ A. FT}$$

PROJECT DRAINAGE - ...	COMP BY ...	JOB NO. ...
	CHK BY ...	DATE ...



PROJECT CLASSIFICATION:	COMP BY BTL	JOB NO. 2071.15
	CHK BY SD	DATE 2-6-71

ACCORDING TO "RECOMMENDED
GUIDELINES FOR SAFETY INSPECTION
OF DAMS":

Rocky Lake Dam is an arch gravity dam.
 side dam, Storage = 7,700 A.-Ft
 Height = 14'

From Guidelines \rightarrow Storage ≥ 1000 A. (< 5000)
 or Height ≥ 40 or (< 100)

Hazard Potential Classification:

LOW

\therefore Recommended Spillway Design Flow
 is 100% to $\frac{1}{2}$ PMF.

USE $\frac{1}{2}$ PMF

Route of $\frac{1}{2}$ PMF = 1450 CFS @ EL 93.0

Capacity of Reservoir at Top of Dam
 EL 92.7 = 8000 CFS

Spillway Capacity = 59% of $\frac{1}{2}$ PMF

APPENDIX E

Information as Contained in the National
Inventory of Dams



INVENTORY OF DAMS IN THE UNITED STATES

IDENTITY NUMBER	DIVISION	STATE	COUNTY	DIST.	CONGR. DIST.	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE DAY MO YR
4E	329	TX	029	02		ROCKY LAKE DAM	4446.1	6715.9	22 MAR 79

POPULAR NAME	NAME OF IMPURDIMENT		
	ROCKY LAKE		
REGION/DASH	RIVER OR STREAM	NEAREST DOWNSTREAM CITY - TOWN - VILLAGE	POPULATION
11 01	ROCKY LAKE STREAM	WHITING	279

TYPE OF DAM	YEAR COMPLETED	PURPOSES	STORAGE CAPACITY (CU FT)	HYDRAULIC CAPACITY (CU FT)	IMPOUNDING CAPACITIES (CU FT)	DIST FROM DAM (MI.)
EGCM	14	H	14	10	6510	4200

REMARKS

D/S HAS	SPILLWAY	MAXIMUM DISCHARGE (CFS)	VOLUME OF DAM (CU FT)	POWER CAPACITY (KW)	INSTALLED	PROPOSED	NAVIGATION LOCKS
1	150	1154	400				

OWNER	ENGINEERING BY	CONSTRUCTION BY
A. GARDNER & SONS, GALVESTON		


DESIGN	CONSTRUCTION	OPERATION	MAINTENANCE
	NONE	NONE	


INSPECTION BY	INSPECTION DATE DAY MO YR	AUTHORITY FOR INSPECTION
PEARL C. JORDAN CO., INC.	2 JAN 78	PUBLIC LAKE 92-367 AUG 1972


REMARKS

DIST OWN FED R PHV/FED SCS A VER/DATE
 N N N N N N N N N N


This Phase I Inspection Report on Rocky Lake Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.


JOSEPH W. FINEGAN, JR., MEMBER
Water Control Branch
Engineering Division



CARNEY M. TERZIAN, MEMBER
Design Branch
Engineering Division



JOSEPH A. MCELROY, CHAIRMAN
Chief, NED Materials Testing Lab.
Foundations & Materials Branch
Engineering Division


APPROVAL RECOMMENDED:


JOE B. FRYAR
Chief, Engineering Division


This Phase I Inspection Report on Rocky Lake Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.


JOSEPH W. FINEGAN, JR., MEMBER
Water Control Branch
Engineering Division


CARNEY M. TERZIAN, MEMBER
Design Branch
Engineering Division


JOSEPH A. MCELROY, CHAIRMAN
Chief, NED Materials Testing Lab.
Foundations & Materials Branch
Engineering Division

APPROVAL RECOMMENDED:


JOE B. FRYAR
Chief, Engineering Division

INVENTORY OF DAMS IN THE UNITED STATES

DATE	IDENTITY NUMBER	DIVISION	STATE	COUNTY	DIST	COWB	COM	NAME	LONGITUDE (WEST)	LONGITUDE (EAST)	HEIGHT DATE DAY	HEIGHT DATE MO	HEIGHT DATE YR
1E	322	FD	VT	ADDY	02			ROCKY LAKE DAM	6715.9	4446.1	22	ART	79

POPULAR NAME	NAME OF IMPROVEMENT
ROCKY LAKE	ROCKY LAKE
REGION/DASH	NEAREST DOWNSTREAM CITY-TOWN-VILLAGE
11	WHITING
	DIST FROM DAM (MI)
	1
	POPULATION
	279

TYPE OF DAM	YEAR COMPLETED	PURPOSES	STILLING HYDRAULIC HEIGHT	HYDRAULIC HEIGHT	REASONING CAPACITIES
EM	14	M	10	6510	4200

DIST OWN FED R PHV/FED SCS A VER/DATE

N N N N N N N N N N

REMARKS

D/S HAS	SPILLWAY	MAXIMUM DISCHARGE (FEET)	VOLUME OF DAM (CUYD)	POWER CAPACITY (KW)	INSTALLATION PROPOSED (KW)	LENGTH (FEET)	WIDTH (FEET)	HEIGHT (FEET)	DEPTH (FEET)	NAVIGATION LOCKS
1	150	53	400			150	15	15	15	

OWNER	ENGINEERING BY	CONSTRUCTION BY

DESIGN	CONSTRUCTION	OPERATION

INSPECTION BY	INSPECTION DATE DAY

AUTHORITY FOR INSPECTION	PUBLIC LAW 92-567 AUG 6 1972

REMARKS

INVENTORY OF DAMS IN THE UNITED STATES

DATE	IDENTITY NUMBER	DIVISION	STATE	COUNTY	DIST.	CONTRACT NUMBER	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE
4E	324	FED	VT	ADD	02		ROCKY LAKE DAM	44°05.1	67°15.9	22 MAR 79

POPULAR NAME	NAME OF IMPROVEMENT
ROCKY LAKE	
RIVER OR STREAM	NEAREST DOWNSTREAM CITY-TOWN-VILLAGE
ROCKY LAKE STREAM	WHITING
POPULATION	POPULATION
	1

TYPE OF DAM	YEAR COMPLETED	PURPOSES	STORAGE CAPACITY (MG)	HYDRAULIC CAPACITY (MG)	IMPROVING CAPACITIES (MG)	DIST	OWN	FED	R	N	N	N
EGCM	N		14	10	6510	4200	N	N	N	N	N	N

REMARKS

D.S. HAS (TYPE)	SPILLWAY TYPE	MAXIMUM DISCHARGE (CFS)	VOLUME OF DAM (MG)	POWER CAPACITY INSTALLED (MW)	POWER CAPACITY PROPOSED (MW)	NAVIGATION LOCKS
1	150	53	400			

OWNER	ENGINEERING BY
GARDNER BROTHERS, CALVERT	CONSTRUCTION BY

DESIGN	REGULATORY AGENCY
CONSTRUCTION	OPERATION
MAINTENANCE	

INSPECTION BY	INSPECTION DATE
FORBARD C. JORDAN CO., INC.	24 NOV 74
	AUTHORITY FOR INSPECTION
	PUBLIC LAW 92-567 AUG 1972

REMARKS

INVENTORY OF DAMS IN THE UNITED STATES

FACILITY NUMBER	DIVISION	STATE	COUNTY	DISTRICT	CONTRACT NUMBER	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE
16		CA	PLUMAS			ROCKY LAKE DAM	40° 06.1'	121° 15.9'	22 MAR 79

POPULAR NAME	NAME OF IMPROVEMENT
	ROCKY LAKE
REGION/DASH	NEAREST DOWNSTREAM CITY - TOWN - VILLAGE
11	WHITING
	POPULATION
	1 279

TYPE OF DAM	YEAR COMPLETED	PURPOSES	STRAIN RELIEF HEIGHT (FT)	HYDRAULIC HEIGHT (FT)	IMPROVING CAPACITIES (ACRES FT)	DISTANCE FROM DAM (MI)	POPULATION
	14	10	6510	4200	N	N	N

REMARKS

DISCHARGE (CFS)	SPILLWAY TYPE	MAXIMUM DISCHARGE (CFS)	VOLUME OF DAM (CY)	POWER CAPACITY (KW)	INSTALLED (KW)	POWER CAPACITY (KW)	LENGTH OF DAM (FT)	WIDTH OF DAM (FT)	HEIGHT OF DAM (FT)	LENGTH OF DAM (FT)	WIDTH OF DAM (FT)	HEIGHT OF DAM (FT)
150	1	56	410									

OWNER	ENGINEERING BY	CONSTRUCTION BY

DESIGN	CONSTRUCTION	OPERATION	MAINTENANCE

INSPECTION BY	INSPECTION DATE
	DAY MO YR
	22 MAR 79
	AUTHORITY FOR INSPECTION
	PUBLIC LAW 92-567 AUG 1972

REMARKS

DIST CAN FED R PHV/FED SCS A VER/DATE



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED

MAY 29 1979

Honorable Joseph E. Brennan
Governor of the State of Maine
State Capitol
Augusta, Maine 04330

Dear Governor Brennan:


I am forwarding to you a copy of the Rocky Lake Dams Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Agriculture and the Department of Transportation, cooperating agencies for the State of Maine. In addition, a copy of the report has also been furnished the owner, M.J. Garber and Herman Galvin, c/o Mr. Warren Strout, MacDonald Page Co., 562 Congress Street, Portland, Maine 04112.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you, the Department of Agriculture and the Department of Transportation for your cooperation in carrying out this program.

Sincerely yours,


JOHN P. CHANDLER
Colonel, Corps of Engineers
Division Engineer

Incl
As stated



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED

MAY 29 1979

Honorable Joseph E. Brennan
Governor of the State of Maine
State Capitol
Augusta, Maine 04330

Dear Governor Brennan:


I am forwarding to you a copy of the Rocky Lake Dams Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Agriculture and the Department of Transportation, cooperating agencies for the State of Maine. In addition, a copy of the report has also been furnished the owner, M.J. Garber and Herman Galvin, c/o Mr. Warren Strout, MacDonald Page Co., 562 Congress Street, Portland, Maine 04112.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you, the Department of Agriculture and the Department of Transportation for your cooperation in carrying out this program.

Sincerely yours,


JOHN P. CHANDLER
Colonel, Corps of Engineers
Division Engineer

Incl
As stated



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED

MAY 29 1979

Honorable Joseph E. Brennan
Governor of the State of Maine
State Capitol
Augusta, Maine 04330

Dear Governor Brennan:


I am forwarding to you a copy of the Rocky Lake Dams Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Agriculture and the Department of Transportation, cooperating agencies for the State of Maine. In addition, a copy of the report has also been furnished the owner, M.J. Garber and Herman Galvin, c/o Mr. Warren Strout, MacDonald Page Co., 562 Congress Street, Portland, Maine 04112.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you, the Department of Agriculture and the Department of Transportation for your cooperation in carrying out this program.

Sincerely yours,


JOHN P. CHANDLER
Colonel, Corps of Engineers
Division Engineer

Incl
As stated



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED-E

M.J. Garber and Herman Galvin
c/o Mr. Warren Strout
MacDonald Page Co.
562 Congress Street
Portland, Maine 04112

Gentlemen:

Forwarded herewith for your information and use is a copy of the Inspection Report on the Rocky Lake Dams. This inspection was made under the authority of Public Law 92-367 by the firm of E.C. Jordan Co., Inc., Portland, Maine under the direction and supervision of the Corps of Engineers. A copy of the finished report has been forwarded to the Governor and the Department of Transportation and Department of Agriculture, the cooperating agencies for the State of Maine.

Section 7 of the report contains an evaluation and recommendations. If you have any questions concerning this report, we suggest that you contact the Department of Agriculture first. Then, if there are further questions contact the Project Management Branch, Engineering Division of this office. We thank you for your cooperation and assistance in carrying out this program.

Sincerely yours,

JOE B. FRYAR
Chief, Engineering Division

Incl
As Stated



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED-E

M.J. Garber and Herman Galvin
c/o Mr. Warren Strout
MacDonald Page Co.
562 Congress Street
Portland, Maine 04112

Gentlemen:

Forwarded herewith for your information and use is a copy of the Inspection Report on the Rocky Lake Dams. This inspection was made under the authority of Public Law 92-367 by the firm of E.C. Jordan Co., Inc., Portland, Maine under the direction and supervision of the Corps of Engineers. A copy of the finished report has been forwarded to the Governor and the Department of Transportation and Department of Agriculture, the cooperating agencies for the State of Maine.

Section 7 of the report contains an evaluation and recommendations. If you have any questions concerning this report, we suggest that you contact the Department of Agriculture first. Then, if there are further questions contact the Project Management Branch, Engineering Division of this office. We thank you for your cooperation and assistance in carrying out this program.

Sincerely yours,

Joe B. Fryar
JOE B. FRYAR
Chief, Engineering Division

Incl
As Stated



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED-E

Mr. Martin C. Rissel, Engineer of
Maintenance and Operations
Bureau of Highways
Department of Transportation
State of Maine
Transportation Building
Augusta, Maine 04330

Dear Mr. Rissel:

Forwarded herewith for your information and use is a copy of the Inspection Report on Rocky Lake Dams. This inspection was performed in accordance with Public Law 92-367 under the direction of the Corps of Engineers. Copies of the finished report have been forwarded to the Governor, the Department of Agriculture, and the owner. We thank you for your cooperation and assistance in carrying out this program and hope this report will help you to develop an effective dam safety program.

Sincerely yours,

A handwritten signature in cursive script that reads "Joe B. Fryar".

JOE B. FRYAR
Chief, Engineering Division

Incl
As stated



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED-E

Mr. Martin C. Rissel, Engineer of
Maintenance and Operations
Bureau of Highways
Department of Transportation
State of Maine
Transportation Building
Augusta, Maine 04330

Dear Mr. Rissel:

Forwarded herewith for your information and use is a copy of the Inspection Report on Rocky Lake Dams. This inspection was performed in accordance with Public Law 92-367 under the direction of the Corps of Engineers. Copies of the finished report have been forwarded to the Governor, the Department of Agriculture, and the owner. We thank you for your cooperation and assistance in carrying out this program and hope this report will help you to develop an effective dam safety program.

Sincerely yours,

A handwritten signature in cursive script that reads "Joe B. Fryar".

JOE B. FRYAR
Chief, Engineering Division

Incl
As stated



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED-E

Mr. Frank Ricker
Soil and Water Conservation Commission
Department of Agriculture
State of Maine
Augusta, Maine 04330

Dear Mr. Ricker:

Forwarded herewith for your information and use is a copy of the Inspection Report on Rocky Lake Dams. This inspection was performed in accordance with Public Law 92-367 under the direction of the Corps of Engineers. Copies of the finished report have been forwarded to the Governor, the Department of Transportation, and the owner. We thank you for your cooperation and assistance in carrying out this program and hope this report will help you to develop an effective dam safety program.

Sincerely yours,

A handwritten signature in cursive script that reads "Joe B. Fryar".

JOE B. FRYAR
Chief, Engineering Division

Incl
As stated



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED-E

Mr. Frank Ricker
Soil and Water Conservation Commission
Department of Agriculture
State of Maine
Augusta, Maine 04330

Dear Mr. Ricker:

Forwarded herewith for your information and use is a copy of the Inspection Report on Rocky Lake Dams. This inspection was performed in accordance with Public Law 92-367 under the direction of the Corps of Engineers. Copies of the finished report have been forwarded to the Governor, the Department of Transportation, and the owner. We thank you for your cooperation and assistance in carrying out this program and hope this report will help you to develop an effective dam safety program.

Sincerely yours,

A handwritten signature in cursive script, reading "Joe B. Fryar", is positioned above the typed name.

JOE B. FRYAR
Chief, Engineering Division

Incl
As stated

END

FILMED

8-85

DTIC