

AD-A156 444


NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS  
MEREDITH RESERVOIR DA. (U) CORPS OF ENGINEERS WALTHAM  
MA NEW ENGLAND DIV APR 79


1/1

UNCLASSIFIED

F/G 13/13

NL





NATIONAL BUREAU OF STANDARDS  
MICROCOPY RESOLUTION TEST CHART


2

MERRIMACK RIVER BASIN  
MEREDITH NEW HAMPSHIRE

AD-A156 444

MEREDITH RESERVOIR DAM  
N.H.00308

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM



DTIC  
ELECT.  
S JUL 09 1985 D  
G

DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
WALTHAM, MASS. 02154

APRIL 1979

DISTRIBUTION STATEMENT A  
Approved for public release  
Distribution Unlimited

DTIC FILE COPY 85 06 17 014

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NH 00308	2. GOVT ACCESSION NO. AD-A156444	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Meredith Reservoir Dam NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS	5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT	
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION	6. PERFORMING ORG. REPORT NUMBER	
9. PERFORMING ORGANIZATION NAME AND ADDRESS	8. CONTRACT OR GRANT NUMBER(s)	
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)	12. REPORT DATE April 1979	
	13. NUMBER OF PAGES 45	
	15. SECURITY CLASS. (of this report) UNCLASSIFIED	
	15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY,  Merrimack Rvver Basin Meredith New Hampshire		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number)  The dam is an earthfill dam about 400 ft. long with a maximum height of 25 ft. The dam is small in size with a significant hazard potential. The dam is judged to be in fair overall condition. Trees and brush are growing on the dam embankment and the spillway is showing signs of deterioration. It is recommended that a periodic annual technical inspection be implemented.		

## **DISCLAIMER NOTICE**

**THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.**

MEREDITH RESERVOIR DAM

NH 00308

MEREDITH, NEW HAMPSHIRE

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input checked="" type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By _____	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A/1	23 GAY



PHASE I INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM

NATIONAL DAM INSPECTION PROGRAM  
PHASE I INSPECTION REPORT

Identification No: NH 00308  
Name of Dam: Meredith Reservoir Dam  
Town: Meredith  
County and State: Belknap County, New Hampshire  
Stream: Unnamed  
Date of Inspection: November 13, 1978

BRIEF ASSESSMENT

The Meredith Reservoir Dam is an earthfill dam approximately 400 feet long with a maximum height of 25 feet. The dam is presently used as a pump/storage reservoir for the Town's water supply system. Water is pumped to the reservoir from Lake Waukegan and let down to the supply system only during emergency conditions. The dam has a 0.17 square mile drainage area and a normal impoundment of 15 acre-feet.

Based on a size classification of small and a significant hazard category, in accordance with the "Recommended Guidelines for Safety Inspection of Dams, Department of the Army 1976," the test flood for this dam is one-half the probable maximum flood (1/2 PMF). The routed test flood outflow of 381 CFS overtops the dam by 0.2 feet. The spillway capacity of 318 CFS is 83 percent of the test flood.



The dam is judged to be in fair overall condition. The following conditions were noted as possible future problems:

1. Trees and brush are growing on the dam embankment.
2. The spillway is showing signs of deterioration.
3. A wet area was found at the base of the dam.

It is recommended that a periodic annual technical inspection program be implemented within one year of the receipt of this report containing the following:

1. Remove trees and brush on a yearly basis.
2. Inspect the downstream slope of the dam for seepage on a yearly basis.
3. Inspect the spillway every two years.

4. Maintain all gates in operational condition.
5. Inspect the upstream embankment at low water conditions.
6. Establish a formal warning system.



*Walter A. Henry*

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test Flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

## TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
Letter of Transmittal	
Brief Assessment	
Review Board Page	
Preface	i
Table of Contents	ii-iv
Overview Photo	v
Location Map	vi


### REPORT

1. PROJECT INFORMATION	
1.1 General	1-1
a. Authority	1-1
b. Purpose	1-1
1.2 Description of Project	1-1
a. Location	1-1
b. Description of Dam and Appurtenances	1-1
c. Size Classification	1-2
d. Hazard Classification	1-2
e. Ownership	1-2
f. Operator	1-2
g. Purpose	1-3
h. Design and Construction History	1-3
i. Normal Operation Procedures	1-3
1.3 Pertinent Data	1-3
a. Drainage	1-3
b. Discharge at the Dam Site	1-3
c. Elevations	1-4
d. Reservoir	1-5
e. Storage	1-5
f. Reservoir Surface	1-5
g. Dam	1-6
h. Diversion and Regulating Tunnel	1-6
i. Spillway	1-6
j. Regulating Outlets	1-7


<u>Section</u>	<u>Page</u>
7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	
7.1 Dam Assessment	7-1
a. Condition	7-1
b. Adequacy of Information	7-1
c. Urgency	7-1
d. Need for Additional Investigations	7-1
7.2 Recommendations	7-1
7.3 Remedial Measures	7-1
a. Operation and Maintenance Procedures	7-1
7.4 Alternatives	7-1

APPENDICES

APPENDIX A - VISUAL INSPECTION CHECK LIST	A-1
APPENDIX B - PROJECT RECORDS AND PLANS	B-1
APPENDIX C - PHOTOGRAPHS	C-1
APPENDIX D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS	D-1
APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS	E-1



OVERVIEW OF  
MEREDITH RESERVOIR DAM  
MEREDITH, NEW HAMPSHIRE



SOURCE OF MAP:  
 U.S. GEOLOGICAL SURVEY  
 HOLDERNESS & WINNIPESAUKEE  
 QUADRANGLES  
 NEW HAMPSHIRE  
 SERIES V712  
 1:62500 1956

DUFRESNE-HENRY ENGINEERING CORP. ARCHITECT-ENGINEER		U.S. ARMY ENGINEER DIV. NEW ENGLAND CORPS OF ENGINEERS WALTHAM, MASS.	
NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS			
LOCATION MAP MEREDITH RESERVOIR DAM			
MEREDITH		NEW HAMPSHIRE	
CLIENT NO	04-0082	SCALE	1" = 1 MILE
ENGR	JAD	DATE	3-14-79

NATIONAL DAM INSPECTION PROGRAM  
PHASE I INSPECTION REPORT  
NAME OF DAM: MEREDITH RESERVOIR

SECTION 1 - PROJECT INFORMATION

1.1 General

a. Authority

Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Dufresne-Henry Engineering Corporation has been retained by the New England Division to inspect and report on selected dams in the State of New Hampshire. Authorization and notice to proceed were issued to Dufresne-Henry Engineering Corporation under a letter of November 20, 1978 from Max B. Scheider, Colonel, Corps of Engineers. Contract No. DACW33-79-C-0010 has been assigned by the Corps of Engineers for this work.

b. Purpose

- (1) Perform technical inspection and evaluation of non-federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by nonfederal interests.
- (2) Encourage and prepare the states to initiate quickly effective dam safety programs for nonfederal dams.
- (3) To update, verify and complete the National Inventory of Dams.

1.2 Description of Project

a. Location

The Meredith Reservoir Dam is located in central New Hampshire in the Town of Meredith, Belknap County, and is in the Merrimack-Winnepesaukee basin.

b. Description of Dam and Appurtenances

Meredith Reservoir Dam is an earth fill dam, approximately 400 feet long and has a maximum height of 25 feet. The reservoir was originally actively utilized as a water supply source for

the Town of Meredith. The Town has recently developed alternate supply sources and the reservoir is only used during emergency conditions. A control tower located approximately 30 feet from the upstream face of the dam houses the potable water intake facilities and reservoir drain valve.

The maximum reservoir level is controlled by a concrete and stone spillway structure. A channel has been constructed to convey any overflow around the dam and into the natural streambed. A vehicle service bridge spans the outlet channel approximately 15 feet downstream of the spillway crest.

c. Size Classification

The Meredith Reservoir Dam has a maximum height of 25 feet and a maximum storage volume of 28 acre-feet. The USCE Guidelines place dams with maximum heights between 25 and 40 feet and maximum storage less than 50 acre-feet in the small category. Therefore, the size classification of the Meredith Dam is small.

d. Hazard Classification

A failure of the Meredith Dam Reservoir would route a flood wave into a relatively small natural channel with extensive overbank flow. Approximately 2000 feet downstream the flood wave would encounter a culvert under Reservoir Road and a single family dwelling on the banks of the stream, resulting in considerable damage and possible loss of life. Thus, in accordance with USCE Guidelines, the hazard classification is significant.

e. Ownership

The present owner of the Meredith Reservoir Dam is:

Meredith Fire District  
Town of Meredith  
Meredith, New Hampshire 03253

f. Operator

The reservoir is operated by the:

Meredith Fire District  
Meredith, New Hampshire 03253  
Telephone 603-279-4537

g. Purpose

The reservoir is part of the Town of Meredith's water supply system. At the present time the reservoir is used to store water for emergency purposes. Water is pumped from Lake Waukegan, stored in the reservoir and used as needed in emergency situations. Because of the limited drainage area of 0.17 square miles, the yield for water supply is minimal.

h. Design and Construction History

Little information is available concerning the design and construction of the Meredith Reservoir Dam. Previous inspection data indicates an original construction date prior to 1934. Subsequent construction activity disclosed by the inspection includes minor concrete facing of portions of the stone spillway walls and a gunite facing of the control tower foundation. The exact dates of these construction repairs is not known.

i. Normal Operation Procedure

In recent years, a pumping station was constructed along the reservoir transmission line approximately 0.4 miles downstream of the reservoir. The flow from the reservoir is controlled at this location, with the valve at the reservoir control tower remaining open. As mentioned previously, the reservoir is used only in emergency situations.

1.3 Pertinent Data

a. Drainage

The drainage area to the Meredith Reservoir is a relatively small 0.17 square miles and consists of gently rolling hills and open fields. There are no significant channels upstream of the dam. A diversion ditch and pipeline have been constructed upstream of the reservoir in the northeast portion of the drainage basin. From the topography of the area it appears that the purpose of the diversion was to prevent undesirable runoff and possible contamination from reaching the reservoir from an upstream pasture which may have contained manure or fertilizer.

b. Discharge at the Dam Site

(1) Outlet Works

There are two outlets for the Meredith Reservoir, a pipeline connected to the Town's municipal water system and an overflow spillway. The pipeline is actually

both an inlet and an outlet because of the pump-storage operation. The stored water is only utilized under emergency conditions.

The total capacity of the spillway with the water level at the top of the training walls is 418 CFS. The low point in the earth dam, however, is one foot lower than the top of the training walls thus reducing the actual capacity to 318 CFS.

(2) Maximum Known Flood at Dam Site

No records or recollections of any flooding were found during the investigations.

(3) Spillway Capacity

318 CFS.

c. Elevations (Based on an assumed bench mark elevation of 100.0, see plan for T.B.M. location.)

(1) Streambed at Centerline of Dam

75+.

(2) Maximum Tailwater

Not applicable.

(3) Upstream Portal Invert

Not applicable.

(4) Recreation Pool (at time of inspection)

94.5.

(5) Full Flood Control Pool

Not applicable.

(6) Spillway Crest

95.8.

(7) Design Surcharge

Not known.

(8) Top of Dam (Minimum)

99.6.

(9) Test Flood Surcharge

99.8

d. Reservoir

(1) Length of Maximum Pool

400 feet ±

(2) Length of Recreation Pool

400 feet ±

(3) Length of Flood Control Pool

400 feet ±

e. Storage

(1) Recreation Pool

15 acre-feet.

(2) Flood Control Pool

Not applicable.

(3) Test Flood Pool

28 acre-feet.

(4) Spillway Crest Pool

15 acre-feet.

(5) Top of Dam

27.6 acre-feet.

f. Reservoir Surface

(1) Top of Dam

3 acres.

(2) Test Flood Pool

3 acres.

(3) Recreation Pool

3 acres.

(4) Spillway Crest

3 acres.

g. Dam

(1) Type

Earth dam.

(2) Length

400 feet (approximately).

(3) Height

25 feet (maximum).

(4) Top Width

15 feet  $\pm$

(5) Side Slopes

Upstream: 1.0H to 1.0V.

Downstream: 1.5H to 1.0V.

(6) Zoning

None known.

(7) Impervious Core

None known.

(8) Cutoff

None known.

(9) Grout Curtain

None known.

h. Diversion and Regulating Tunnel

Not applicable.

i. Spillway

The overflow spillway has a triangular concrete crest with stone training walls and a crest elevation of 95.8. The spillway width is 14.3 feet and maximum height is 4.2 feet.

An earth spillway channel has been constructed downstream of the spillway, routing the overflow to the original channel without endangering the earth portions of the dam. The channel is approximately 20 feet wide by 3 feet deep.

j. Regulating Outlets

The valves located in the valve house at the dam have not been routinely maintained and operated. There was evidence in the form of wrench teeth marks on the operating stems indicating that undue force is necessary to adjust the valves. The present control of water to and from the dam is at the new pumping station 1800 feet downstream of the dam.

## SECTION 2 - ENGINEERING DATA

### 2.1 Design

There is no design data available for this dam.

### 2.2 Construction

There is no information on the construction other than an approximate construction date prior to 1934.

### 2.3 Operation

The Meredith Reservoir is currently being operated as a pump storage reservoir. Water is pumped from Lake Waukegan and stored at the reservoir for emergency situations. All operations take place at the new pumping station and there is no physical operation at the dam.

### 2.4 Evaluation

#### a. Availability

The design and construction records for this dam are not available.

#### b. Adequacy

The lack of in-depth engineering data does not allow for a definitive review. Therefore, the adequacy of the evaluation cannot be based on a review of design calculations but on the visual inspection, past performance history and sound hydrologic and hydraulic engineering judgment.

#### c. Validity

Not applicable.

## SECTION 3 - VISUAL INSPECTION

### 3.1 Findings

#### a. General

The on-site inspection of the Meredith Reservoir Dam was performed on November 13, 1978. The water level at the time of inspection was approximately 1.3 feet below the spillway crest. No emergency conditions were observed on the day of the inspection.

#### b. Dam Embankment

The dam embankment is in generally good condition. Some evidence of seepage was found just downstream of the toe at the highest section of the dam. The area was damp with some depressions filled with standing water. A marsh-type vegetation indicates that the area is permanently wet and thus the condition is ground water or seepage related rather than trapped surface runoff.

The top and downstream slope of the dam are covered with grass and brush. There are numerous tree stumps on the downstream slope. Several large trees are located on both sides of the spillway. The root systems of at least one of these trees appears to be in the dam embankment on the downstream slope.

The downstream slope is approximately 1.5H:1V, while the upstream slope is somewhat steeper at 1H:1V. The water level at the time of inspection was approximately 1.3 feet below the spillway crest and therefore a complete visual inspection of the upstream slope could not be performed. The upper portion which could be viewed indicated a uniform riprap facing which was in good condition.

#### c. Appurtenant Structures

##### (1) Control Tower and Service Bridge

The control tower is located approximately 30 feet from the upstream dam embankment and is connected to the embankment via a steel girder service bridge. The control tower and service bridge are in good condition with the exception of the bridge abutment at the dam embankment which has settled and cracked (see Photo 9). The control tower concrete foundation received a 6-inch gunite coating in recent years.

The main floor of the control tower houses six hand wheel valve operators and a reservoir level indicator (see Photo 8). The valves are located below the water level and the function of each respective valve could not be determined by a visual inspection. The valve operator shafts showed signs of excessive force applied with a pipe wrench during valve operation. It could not be determined at the time of inspection if the valves were operational. One of the valves is assumed to be a drain valve. The outlet of the drain conduit was located but the size or material of the conduit could not be determined. The drain conduit discharges to a stone masonry culvert which enters the natural channel downstream of the service road (see site plan).

(2) Spillway

The original spillway was constructed with concrete crest and apron, and stone masonry training walls. A steel girder vehicle bridge spans the spillway channel approximately 15 feet downstream of the crest. At some time subsequent to original construction a concrete facing was applied to the upstream ends of the stone masonry training walls.

The concrete sections of the spillway structures are in poor condition. Most of the concrete is either cracked or spalled with major spalling occurring on the left training wall facing. There were no signs of significant leakage through the spillway structure during inspection, but leakage may be present during higher water levels.

The stone masonry training walls were in fair to poor condition with very little of the original mortar remaining. Several stones on the downstream end of the walls have fallen into the channel due to erosion of the channel banks.

A 12-inch clay tile drain outlet was found at the downstream end of the right training wall. The drain was traced to a surface inlet and diversion ditch on the upstream side of the reservoir. It is assumed that the drain was used to divert undesirable runoff around the potable water reservoir. Approximately 1/4-inch of clear flow was flowing at the drain outlet while no water was found at the inlet. The origin of this flow is unknown.

d. Reservoir Area

The reservoir area was found to be in good condition. The banks are covered with grass and small brush. There are no

overhanging trees, floating debris or other sources of possible spillway obstructions.

e. Downstream Channel

The original streambed that constitutes the downstream channel had very little flow at the time of inspection. The channel is a typical stream channel flowing through a heavily wooded area.

The spillway overflow channel is a manmade channel approximately 20 feet wide by 3 feet deep (see Photo 10). The banks of the channel are overgrown with small trees and brush and there is no evidence of any recent flow.

## SECTION 4 - OPERATIONAL PROCEDURES

### 4.1 Procedures

None.

### 4.2 Maintenance of Dam

At the present time there is no scheduled maintenance program for the dam. Several trees were removed recently from the area downstream of the dam embankment as required by the Water Resources Board subsequent to their August 15, 1975 inspection.

### 4.3 Maintenance of Operating Facilities

The operating facilities at the dam are not maintained on a regular basis. The last shutdown of the water supply line at the reservoir occurred 1-1/2 to 2 years ago. All current operations are now performed at the new pumping station downstream of the reservoir.

### 4.4 Description of Warning System in Effect

None exists for this dam.

### 4.5 Evaluation

The operation and maintenance appears to be adequate for the dam's present status. Improvements could be made by instituting a routine inspection and maintenance program on an annual or semi-annual basis, as outlined in Section 7.

## SECTION 5 - HYDRAULIC/HYDROLOGIC

### 5.1 Evaluation of Features

#### a. General

The Meredith Reservoir is a storage reservoir with an earth embankment dam. The drainage area is relatively small and during hot summer months it is necessary to pump water from Lake Waukegan to maintain water in the reservoir.

#### b. Design Data

There is no existing design data for this dam relative to hydraulic/hydrologic computations.

#### c. Experience Data

There are no records of high flow conditions at the site.

#### d. Visual Observations

The visual inspection of the dam indicated that the overflow spillway had not been utilized in the recent past.

#### e. Test Flood Analysis

The dam is classified to be small with a significant hazard classification. Since the hazard classification is significant, a test flood of one-half the probable maximum flood was selected as a criterion for this study. The calculation was performed using the HEC-1 computer program which produced a routed test flood outflow of 381 CFS. Input data and results are contained in Appendix D of this report.

The test flood of 381 CFS would overtop the dam by 0.2 feet. The spillway capacity of 318 CFS represents 83.5 percent of the HEC-1 test flood.

#### f. Dam Failure Analysis

A failure of the Meredith Dam would route a significant flood wave into a relatively small stream channel. Assuming a flood wave of two-thirds the height of the dam, a seventeen-foot wave would produce extensive overbank flow and major erosion damage. Approximately 2000 feet downstream, the flood wave would contact Reservoir Road and a single family

residence with extensive erosion to the roadway and the potential for loss of life. A cemetery in this area would also receive erosion damage with possible public health problem .

The flood wave would continue down the natural stream valley for another 1800 feet until reaching a new highway embankment for relocated Route 104. The embankment is approximately 20 to 30 feet high and contains two reinforced concrete culverts. The embankment and culverts would effectively dampen the flood wave and no further damage would result downstream of that point.

## SECTION 6 - STRUCTURAL STABILITY

### 6.1 Evaluation of Structural Stability

#### a. Visual Observations

The visual inspection did not disclose any findings indicating stability problems.

#### b. Design and Construction Data

The design and construction data available do not include information concerning the types of soils in the cross-section of the dam, and thus it is not possible to analyze its stability. There is no design data available to indicate whether a stability or seepage analysis was performed.

#### c. Operating Records

The operating records available do not include any indication of dam instability.

#### d. Post-Construction Changes

The records do not contain reference to post-construction changes except for gate house and spillway repairs.

#### e. Seismic Stability

The dam is located in Seismic Zone 2 and in accordance with recommended Phase I guidelines does not warrant seismic analysis.

SECTION 7 - ASSESSMENT, RECOMMENDATIONS/  
REMEDIAL MEASURES

7.1 Dam Assessment

a. Condition

The visual inspection and records indicate that the dam is in fair condition. The following areas of concern for possible future problems were determined during the inspection.

1. Trees and brush are growing on the dam embankment.
2. The spillway is showing signs of deterioration.
3. A wet area was found at the base of the dam.

b. Adequacy of Information

There is practically no data available for this dam and this evaluation is based solely on the visual inspection.

c. Urgency

The recommendations given in Section 7.2 should be carried out within one year of the receipt of this report.

d. Need for Additional Investigations

None.

7.2 Recommendations

The dam is judged to be in fair overall condition. It is recommended that the following items be performed under the guidance of a qualified engineer:

1. Repair the spalled and cracked concrete on the spillway walls and floor.
2. Repair the operating valves in the control tower.
3. Perform an inspection of the upstream dam embankment at low water conditions.

7.3 Remedial Measures

a. Operation and Maintenance Procedures

1. Institute a program of annual periodic technical inspections.

2. The trees and bushes growing on the dam should be removed yearly.
3. The existing tree stumps on the downstream slope should be inspected yearly for indications of seepage in their vicinity.
4. The wet area downstream of the dam should be observed periodically to detect any possible seepage flows.
5. The spillway should be subject to maintenance every two years. This would include repairs to the stone training walls, and patching of any cracked and spalled concrete. The first maintenance should be performed within one year.
6. Establish a formal warning system.
7. Maintain all gates in operational condition.

APPENDIX A

VISUAL INSPECTION CHECK LIST

VISUAL INSPECTION CHECK LIST  
PARTY ORGANIZATION

PROJECT MEREDITH RESERVOIR DAM                      DATE November 13, 1978  
 TIME 11:15-2:15  
 WEATHER Cool-Clear  
 W.S. ELEV. \_\_\_\_\_ U.S. \_\_\_\_\_ DN.S. \_\_\_\_\_

PARTY:

- |                                    |            |           |
|------------------------------------|------------|-----------|
| 1. <u>James H. Maynes</u>          | <u>D-H</u> | 6. _____  |
| 2. <u>James A. Dohrman</u>         | <u>D-H</u> | 7. _____  |
| 3. <u>Vern Clifford</u>            | <u>D-H</u> | 8. _____  |
| 4. <u>Gonzalo Castro</u>           | <u>GEI</u> | 9. _____  |
| 5. <u>Ken Stern, New Hampshire</u> |            | 10. _____ |
| <u>Water Resources Board</u>       |            |           |

PROJECT FEATURE	INSPECTED BY	REMARKS
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

PERIODIC INSPECTION CHECK LIST

PROJECT MEREDITH RESERVOIR DAM DATE November 13, 1978

PROJECT FEATURE \_\_\_\_\_ NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_ NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>DAM EMBANKMENT</u>	
Crest Elevation	
Current Pool Elevation	
Maximum Impoundment to Date	Not known.
Surface Cracks	None.
Pavement Condition	None.
Movement or Settlement of Crest	Not observable. Traffic ruts.
Lateral Movement	Not observable.
Vertical Alignment	Too irregular to judge.
Horizontal Alignment	Too irregular to judge.
Condition at Abutment and at Concrete Structures	Erosion at discharge end of spillway walls.
Indications of Movement of Structural Items on Slopes	None except for bridge footing.
Trespassing on Slopes	None apparent.
Sloughing or Erosion of Slopes or Abutments	Minimum - downstream.
Rock Slope Protection - Riprap Failures	Good condition.
Unusual Movement or Cracking at or Near Toes	None observed.
Downstream Seepage	Apparent seepage at highest section at downstream toe.
Piping or Boils	None observed.
Foundation Drainage Features	None known.
Toe Drains	None known.
Instrumentation System	None.

PERIODIC INSPECTION CHECK LIST

PROJECT MEREDITH RESERVOIR DAM

DATE November 13, 1978

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - CONTROL TOWER</u>	
a. Concrete and Structural	
General Condition	Good condition - recent concrete work.
Condition of Joints	Existing are good.
Spalling	None observed.
Visible Reinforcing	None observed.
Rusting or Staining of Concrete	None observed.
Any Seepage or Efflorescence	None observed.
Joint Alignment	Good.
Unusual Seepage or Leaks in Gate Chamber	Fall of water - not drained.
Cracks	None observed.
Rusting or Corrosion of Steel	Moderate.
b. Mechanical and Electrical	
Air Vents	None.
Float Wells	None.
Crain Hoist	None.
Elevator	None.
Hydraulic System	None.
Service Gate Valves	6 - gates may be operable only with undue force. No regular maintenance program.
Emergency Gates	None.
Lightning Portection System	None.
Emergency Power System	None.
Wiring and Lighting System in Gate Chamber	No power at site.
A-3	

PERIODIC INSPECTION CHECK LIST

PROJECT MEREDITH RESERVOIR DAM

DATE November 13, 1978

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
----------------	-----------

OUTLET WORKS - TRANSITION  
AND CONDUIT

General Condition of Concrete  
Rust or Staining on Concrete  
Spalling  
Erosion or Cavitation  
Cracking  
Alignment of Monoliths  
Alignment of Joints  
Numbering of Monoliths

Under Water

PERIODIC INSPECTION CHECK LIST

PROJECT MEREDITH RESERVOIR DAM

DATE November 13, 1978

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL</u></p> <p>General Condition of Concrete</p> <p>Rust or Staining</p> <p>Spalling</p> <p>Erosion or Cavitation</p> <p>Visible Reinforcing</p> <p>Any Seepage or Efflorescence</p> <p>Condition at Joints</p> <p>Drain Holes</p> <p>Channel</p> <p>    Loose Rock or Trees Overhanging     Channel</p> <p>    Condition of Discharge Channel</p>	<p>Break in cover.</p> <p>Stone masonry culvert.</p> <p>Downstream of road - natural stream.</p>

PERIODIC INSPECTION CHECK LIST

PROJECT MEREDITH RESERVOIR DAM

DATE November 13, 1978

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u></p>	
<p>a. Approach Channel                      General Condition                      Loose Rock Overhanging Channel                      Trees Overhanging Channel                      Floor of Approach Channel</p>	<p>Reservoir.</p>
<p>b. Weir and Training Walls                      General Condition of Concrete                      Rust or Staining                      Spalling                      Any Visible Reinforcing                      Any Seepage or Efflorescence                      Drain Holes</p>	<p>Poor.                      None.                      Major.                      Some.                      None.                      None.</p>
<p>c. Discharge Channel                      General Condition                      Loose Rock Overhanging Channel                      Trees Overhanging Channel                      Floor of Channel                      Other Obstructions</p>	<p>Concrete to bridge; stone under bridge.                      Stone masonry wall collapsed.                      Small.                      Riprap.                      Rock falling in.</p>

PERIODIC INSPECTION CHECK LIST

PROJECT MEREDITH RESERVOIR DAM

DATE November 13, 1978

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE</u></p> <p>a. Approach Channel</p> <p style="padding-left: 20px;">Slope Conditions</p> <p style="padding-left: 20px;">Bottom Conditions</p> <p style="padding-left: 20px;">Rock Slides or Falls</p> <p style="padding-left: 20px;">Log Boom</p> <p style="padding-left: 20px;">Debris</p> <p style="padding-left: 20px;">Condition of Concrete Lining</p> <p style="padding-left: 20px;">Drains or Weep Holes</p> <p>b. Intake Structure</p> <p style="padding-left: 20px;">Condition of Concrete</p> <p style="padding-left: 20px;">Stop Logs and Slots</p>	<p>None.</p>

PERIODIC INSPECTION CHECK LIST

PROJECT MEREDITH RESERVOIR DAM

DATE November 13, 1978

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - SERVICE BRIDGE</u>	
a. Super Structure	
Bearings	Concrete.
Anchor Bolts	None.
Bridge Seat	None.
Longitudinal Members	Good.
Under Side of Deck	Good.
Secondary Bracing	None.
Deck	Good condition.
Drainage System	Good.
Railings	Good
Expansion Joints	Not applicable.
Paint	Good
b. Abutments and Piers	
General Condition of Concrete	Cracked - 6-inch openings.
Alignment of Abutment	Poor.
Approach to Bridge	Good.
Condition of Seat & Backwall	
	Will be under water during flood conditions.

PERIODIC INSPECTION CHECK LIST

PROJECT MEREDITH RESERVOIR DAM

DATE November 13, 1978

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
----------------	-----------

RESERVOIR

Stability of Shoreline  
 Sedimentation  
 Changes in Watershed Runoff Potential  
 Upstream Hazards  
 Downstream Hazards  
 Alert Facilities  
 Hydrometeorological Gages  
 Operational & Maintenance Regulations

Good.  
 None observable - minimal.  
 Possible development.  
 None.  
 Reservoir Road - low downtown.  
 None.  
 Homemade water level - nonrecording.  
 Nonexistent.

1. All valves not operated recently.
2. Headworks not used.
3. Last shutdown 1-1/2 - 2 years.
4. Pressure from gate/pump house Lake Waukegan.

APPENDIX B

PROJECT RECORDS AND PLANS

1. Listing of Design, Construction and Maintenance Records:

None.

2. Copies of Past Inspection Reports:

- a. N.H. Water Resources Board, September 9, 1934.
- b. N.H. Water Control Commission, July 10, 1939.
- c. N.H. Water Control Commission, June 20, 1951.
- d. N.H. Water Resources Board, August 15, 1975

3. Plans:

- a. Site Plan
- b. Details-Sections

HAMPSHIRE WATER RESOURCES BOARD

INVENTORY OF DAMS AND WATER POWER DEVELOPMENTS

D.M.  
 BASIN Merrimack NO. A - 509 - I-2770 0.2  
 RIVER Pepperis MILES FROM MOUTH \_\_\_\_\_ D.A.SQ.MI. 0.5  
 TOWN Merrill OWNER Merrill Village Fire Dept.  
 LOCAL NAME OF DAM \_\_\_\_\_  
 E.ILT \_\_\_\_\_ DESCRIPTION Earth Embankment  
Earth Complete on Earth

FOOD AREA-ACRES \_\_\_\_\_ DRAINAGE FT. \_\_\_\_\_ POND CAPACITY-ACRE FT. \_\_\_\_\_  
 HEIGHT-TOP TO BED OF STREAM-FT. \_\_\_\_\_ MAX. \_\_\_\_\_ MIN. \_\_\_\_\_  
 OVERALL LENGTH OF DAM-FT. 300 MAX. FLOOD HEIGHT ABOVE CREST-FT. \_\_\_\_\_  
 PERMANENT CREST ELEV. U.S.G.S. \_\_\_\_\_ LOCAL GAGE \_\_\_\_\_  
 TOP WATER ELEV. U.S.G.S. \_\_\_\_\_ LOCAL GAGE \_\_\_\_\_  
 SPILLWAY LENGTHS-FT. 14.32 FREEBOARD-FT. 4.0  
 FLASHBOARDS-TYPE, HEIGHT ABOVE CREST None  
 W. STR. GATES-NO. \_\_\_\_\_ WIDTH MAX. OPENING \_\_\_\_\_ DEPTH SILL BELOW CREST \_\_\_\_\_

REMARKS Condition Fair

S.G. Int. Lake Bank on Lake Merrimack, Merrimack

POWER DEVELOPMENT						
UNITS	NO.	RATED HP	HEAD FEET	C.F.S. FULL GAGE	KW	MAKE

USE Domestic

REMARKS Fire Pond

DATE 9/20/69

**NEW HAMPSHIRE WATER CONTROL COMMISSION  
DATA ON DAMS IN NEW HAMPSHIRE**

**LOCATION**

STATE NO. 155.04

Town Meredith ✓ : County Bellnap  
 Stream Reservoir ✓  
 Basin-Primary Merrimack ✓ : Secondary Winnepesaukee ✓  
 Local Name \_\_\_\_\_  
 Coordinates—Lat. 43° 40' - 12200 : Long. 71° 50' + 1250

**GENERAL DATA**

0.54 ✓

Drainage area: Controlled \_\_\_\_\_ Sq. Mi.: Uncontrolled \_\_\_\_\_ Sq. Mi.: Total 0.54 Sq. Mi.  
 Overall length of dam 400 ft.: Date of Construction \_\_\_\_\_  
 Height: Stream bed to highest elev. 16 ft.: Max. Structure 21 ft.  
 Cost—Dam \_\_\_\_\_ : Reservoir \_\_\_\_\_

**DESCRIPTION**

Earth embankment stone Earth concrete on earth ✓

**Waste Gates**

Type \_\_\_\_\_  
 Number \_\_\_\_\_ : Size \_\_\_\_\_ ft. high x \_\_\_\_\_ ft. wide  
 Elevation Invert \_\_\_\_\_ : Total Area \_\_\_\_\_ sq. ft.  
 Hoist \_\_\_\_\_

**Waste Gates Conduit**

Number \_\_\_\_\_ : Materials \_\_\_\_\_  
 Size \_\_\_\_\_ ft.: Length \_\_\_\_\_ ft.: Area \_\_\_\_\_ sq. ft.

**Embankment**

Type \_\_\_\_\_  
 Height—Max. \_\_\_\_\_ ft.: Min. \_\_\_\_\_ ft.  
 Top—Width \_\_\_\_\_ : Elev. \_\_\_\_\_ ft.  
 Slopes—Upstream \_\_\_\_\_ on \_\_\_\_\_ : Downstream \_\_\_\_\_ on \_\_\_\_\_  
 Length—Right of Spillway \_\_\_\_\_ : Left of Spillway \_\_\_\_\_

**Spillway**

Materials of Construction \_\_\_\_\_  
 Length—Total 10.4 ✓ ft.: Net \_\_\_\_\_ ft.  
 Height of permanent section—Max. 21 ft.: Min. \_\_\_\_\_ ft.  
 Flashboards—Type Roller : Height \_\_\_\_\_ ft.  
 Elevation—Permanent Crest \_\_\_\_\_ : Top of Flashboard \_\_\_\_\_  
 Flood Capacity 325 cfs.: \_\_\_\_\_ cfs./sq. mi.

**Abutments**

601

Materials: \_\_\_\_\_  
 Freeboard: Max. 41 ✓ ft.: Min. \_\_\_\_\_ ft.

Headworks to Power Devel.—(See "Data on Power Development")

**OWNER**

Meredith Village Fire District

**REMARKS**

Condition fair fire pond - Water supply  
 about 1 acre about 3 acres of asphalt

C.D.C

7/10/70

NEW HAMPSHIRE WATER CONTROL COMMISSION

REPORT ON DAM INSPECTION

TOWN Meredith DAM NO. 125 STREAM Pepper Brook

OWNER Town of Meredith ADDRESS Meredith, N.H.

In accordance with Section 20 of Chapter 133, Laws of 1937, the above dam was inspected by me on 4/1/57 accompanied by \_\_\_\_\_

NOTES ON PHYSICAL CONDITION

Abutments Excellent

Spillway Good

Gates Acceptable

Other \_\_\_\_\_

CHANGES SINCE LAST INSPECTION \_\_\_\_\_

FUTURE INSPECTIONS Y-5

This dam (is) (~~is not~~) a nonce because it is not

REMARKS Water capacity increased

Water level 1.5 ft above spillway crest

Copy to Owner	Date

Robert W. Moore  
INSPECTOR

WATER RESOURCES BOARD

SITE EVALUATION DATA

OWNER: Town of Meredith (Water Works) TELEPHONE NO. \_\_\_\_\_

MAILING ADDRESS: \_\_\_\_\_

SITE LOCATION (TOWN OR CITY) Meredith

NAME OF STREAM OR WATERBODY: Reservoir

QUADRANGLE: Holderness LOCATION 1E 0.35 Dn 9.27

HEIGHT OF (PROPOSED, EXISTING) DAM 25 LENGTH 100

TYPE OF (PROPOSED, EXISTING) STRUCTURE Earth embankment with spillway with concrete & stone Abutments

DRAINAGE AREA 0.54 SM POND AREA 3 A

AVAILABLE ARTIFICIAL STORAGE: PERMANENT: \_\_\_\_\_ TEMPORARY: \_\_\_\_\_ TOTAL 15

EXISTING DEVELOPMENT DOWNSTREAM OF (PROPOSED, EXISTING) STRUCTURE None 1/2 mi down stream

POTENTIAL DEVELOPMENT DOWNSTREAM OF (PROPOSED, EXISTING) STRUCTURE Possible Home development

POTENTIAL DAMAGE DOWNSTREAM OF STRUCTURE (EXPLAIN IN DETAIL AND INCLUDE ANY ESTIMATED LOSS OF LIFE ESTIMATE) damage to Road and some

OTHER COMMENTS: Town Water Supply

CLASS OF STRUCTURE -- ~~REVENUE~~ MANAGE A ~~B~~ ~~C~~ ~~D~~ ~~E~~ ~~F~~ ~~G~~ DAM # 155.09

DATE OF INSPECTION: 15 Aug 75

SIGNER J. B. [Signature]  
SIGNATURE

N. H. WATER RESOURCES BOARD  
Concord, N. H. 03301

DAM SAFETY INSPECTION REPORT FORM

Town: Merridith Dam Number: 135.04

Inspected by: J Burnett Date: 15 Aug 1955

Local name of dam or water body: Reservoir

Owner: Town Address: \_\_\_\_\_

Owner was/was not interviewed during inspection.

Drainage Area: 54 sq. mi. Stream: No Name

Fond Area: 3 Acre, Storage 15 Ac-Ft. Max. Head 25 Ft.

Foundation: Type Earth, Seepage present at toe - Yes/No No

Spillway: Type Overflow, Freeboard over perm. crest: 4 ft

Width 14.3, Flashboard height 0

Max. Capacity 325 c.f.s.

Embankment: Type Earth, Cover Grass Width 15

Upstream slope 1 1/2 to 1; Downstream slope 1 1/2 to 1

Abutments: Type Concrete & Stone, Condition: Good, Fair, Poor

Gates or Pond Drain: Size \_\_\_\_\_ Capacity \_\_\_\_\_ Type \_\_\_\_\_

Lifting apparatus \_\_\_\_\_ Operational condition \_\_\_\_\_

Changes since construction or last inspection: \_\_\_\_\_

Downstream development: \_\_\_\_\_


This dam would/~~would not~~ be a menace if it failed.

Suggested reinspection date: \_\_\_\_\_


Remarks: Concrete in spillway needs Repair

Small Trees on embankment






SECTION A  
SCALE: 1" = 20'



SECTION B  
SCALE: 1" = 20'

VEREDITH RESERVOIR DAM	
DETAILS - SECTIONS	
DATE: _____	SCALE: _____
BY: _____	CHECKED: _____
APPROVED: _____	DESIGNED: _____
DRAWN BY: _____	



PLAN  
SCALE: 1" = 30'

APPENDIX C

PHOTOGRAPHS





#1. VIEW OF EARTH DAM AND CONTROL TOWER



#2. VIEW OF UP-  
STREAM DAM  
EMBANKMENT



#5. VIEW OF DOWNSTREAM SPILLWAY CHANNEL



#6. VIEW OF LEFT  
SPILLWAY TRAINING  
WALL AND TREES ON  
EMBANKMENT



#9. VIEW OF CONTROL  
TOWER BRIDGE  
ABUTMENT



#10. VIEW OF DOWNSTREAM SPILLWAY CHANNEL

APPENDIX D

HYDROLOGIC AND HYDRAULIC COMPUTATIONS

DUFRESNE-HENRY ENGINEERING CORPORATION

BY W.H. Leonard  
DATE 1/19/79

SUBJECT Mountain Meadows  
Domestic Area  
CLASSIFICATION

SHEET NO. 1 OF 2  
JOB NO. 28-2047

SCALE 1:62500

PLANNING SCALE READING:

DOUBLE ENDING 0.85

$(.175)(.986) = \underline{\underline{.17 \text{ SQ MILES}}}$

PLANNING SCALE READING:

1:62500 HEIGHT 21' STATION 151 100 00'

SIZE 200000000 SMALL

1:62500 HEIGHT 21' STATION 151 100 00'

SIZE 200000000 SMALL

DUFRESNE-HENRY ENGINEERING CORPORATION

BY W. H. Leonard  
DATE 2-2-59

SUBJECT TEST FLUID SELECTION & CURVES

SHEET NO. 2 OF 2  
JOB NO. 2-1-11-59

DESIGNER'S VALUE OF TOTAL EFFICIENCY  
EFFICIENCY VALUE 85%


Q = 0.047 L = 14.1  
C VALUES TAKEN FROM  
TABLE OF EFFICIENCY  
TABLE 1-1

h	Q
h = 0	Q = 0
h = 1	$Q = 0.021 (14.1)(1)^{3/4} = \underline{\underline{0.021}}$
h = 1.5	$Q = 0.021 (14.1)(1.5)^{3/4} = \underline{\underline{0.026}}$
h = 2	$Q = 0.021 (14.1)(2)^{3/4} = \underline{\underline{0.031}}$
h = 2.5	$Q = 0.021 (14.1)(2.5)^{3/4} = \underline{\underline{0.035}}$
h = 3	$Q = 0.021 (14.1)(3)^{3/4} = \underline{\underline{0.038}}$
h = 3.5	$Q = 0.021 (14.1)(3.5)^{3/4} = \underline{\underline{0.041}}$
h = 4	$Q = 0.021 (14.1)(4)^{3/4} = \underline{\underline{0.043}}$
h = 4.5	$Q = 0.021 (14.1)(4.5)^{3/4} = \underline{\underline{0.045}}$

TOP OF DAM CURVE  
POINTS

h	Q	h	Q
h = 1	0.021	h = 1	0.021
h = 1.5	0.026	h = 1.5	0.026
h = 2	0.031	h = 2	0.031
h = 2.5	0.035	h = 2.5	0.035
h = 3	0.038	h = 3	0.038
h = 3.5	0.041	h = 3.5	0.041
h = 4	0.043	h = 4	0.043
h = 4.5	0.045	h = 4.5	0.045
h = 5	0.047	h = 5	0.047

STAGE VS. DISCHARGE



TOP OF TRAINING WEIRS

TOP OF DAM

400

300


200

100

DISCHARGE (Q IN C.F.S.)

STAGE (IN FEET)

STAGE VS. STORAGE



TOP OF DAM

(2000) 11-30-1962

DUFRESNE-HENRY ENGINEERING CORPORATION

BY W.A. LEONARD

SUBJECT Medicine Reservoir

SHEET NO. 5 OF 8

DATE 3-5-79

SOIL CLASSIFICATION

JOB NO. 04-0089

PRELIMINARY SOILS FOR THE MEDICINE RESERVOIR -  
 DRINKING WATER (TAKEN FROM THE SOIL CLASSIFICATION  
 SERVICE) PIPE

2nd	PAYSON	30% - C
8th	KIDDERMAN	15% - C
7th	GLOUCESTER	50% - B

LAND USE - WOODS  
 SUBJECT - GRAZING

SOIL TYPE SURVEY NO. 64 FROM 1975.

THE SOIL IS OF THE USDA TYPE USDA, USDA, USDA.  
USDA USDA USDA

UNIFORM PENETRATION LOSS = 2.25/100

DUFRESNE-HENRY ENGINEERING CORPORATION

BY W. F. LEONARD  
DATE 3-5-79

SUBJECT MOUNTAIN RESERVOIR  
COMPUTED FLOOD

SHEET NO. 6 OF 8  
JOB NO. 04-0159

AVERAGE SLOPE

ELEV @ 10% 780  
ELEV @ 35% 840

$$\frac{840 - 780 (5750)}{1307} = \underline{\underline{324.42' / MILE}}$$

$$\frac{1}{T_p} = 2.2 \left( \frac{4.4}{15} \right)^{.37} \Rightarrow 2.2 \left( \frac{1724.1 (1724.1)}{1324.4} \right)^{.37} = \underline{\underline{.27}}$$

100 YEAR FLOOD

100 YEAR AVERAGE LENGTH = 6.0 INCHES

WATERWAY AREA = (.17) (6.0) = 100.5 ACRES

FORM ES-1021  
S.C.S.

100 cfs

DUFRESNE-HENRY ENGINEERING CORPORATION

BY W.A. LEONARD  
DATE 3-5-79

SUBJECT MERIDIAN DAM  
DAM FAILURE ANALYSIS

SHEET NO. 7 OF 8  
JOB NO. 04-1850

IF DAM WERE TO FAIL

$h \approx 3' \therefore WSEL = 98.8$

$y_0 = 24'$

$Q = \frac{8}{27} W_b \sqrt{g} y_0^{3/2}$

$Q = \frac{8}{27} (.4)(340) \sqrt{32.2} (24)^{3/2} = \underline{\underline{26,985 \text{ cfs}}}$

UNDE: 100% FLOOD CONDITIONS (1200's)

$h = 1.8$   
 $\therefore WSEL = 1.8 + 98.8 = 94.6$

$Q = \frac{8}{27} W_b \sqrt{g} y_0^{3/2}$

$y_0 = 23'$

$Q = \frac{8}{27} (.4)(340) \sqrt{32.2} (23)^{3/2} = \underline{\underline{25,322 \text{ cfs}}}$

UNDE: 100% FLOOD, DAM CONDITIONS

$WSEL = 98.8$

$y_0 = 21'$

$Q = \frac{8}{27} W_b \sqrt{g} y_0^{3/2}$

$Q = \frac{8}{27} (.4)(340) \sqrt{32.2} (21)^{3/2} = \underline{\underline{22,000 \text{ cfs}}}$

DUFRESNE-HENRY ENGINEERING CORPORATION

BY W.A. LEONARD  
DATE 2-9-79

SUBJECT UPPER DAM DESIGN  
DAM DESIGN ANALYSIS  
USING COMPUTER  $1/2$  P.M.F.

SHEET NO. 5 OF 5  
JOB NO. 04-0000

FROM HEK-1 COMPUTER OUTPUT

$1/2$  P.M.F. = 331 cfs

FROM STAGE DISCHARGE CURVE  $h \approx 4.0'$

$WSEL = 25.8 + 4 = 99.8$

WATER WOULD OVERTOP BY  $\approx 2$  FEET

IF DAM WERE TO FAIL UNDER THESE CONDITIONS

$Q = 3.47 WSEL^{3/2} \sqrt{1/2} \quad U_n = 25.2'$

$Q = 3.47 (14.3)(99.8)^{3/2} = \underline{\underline{318.5 cfs}}$

Final Design

MAX  $h = 1.2'$  @ TOP OF TRAINING WALLS

$Q = 3.47 (14.3)(1.2)^{3/2} = \underline{\underline{21.5 cfs}}$

$h = 3.5$  AT TOP OF DAM (LOW POINT)

$Q = 3.47 (14.3)(3.5)^{3/2} = \underline{\underline{318.5 cfs}}$

HEREDITH RESERVOIR  
HEREDITH, NEW HAMPSHIRE  
RESERVOIR STORAGE-OUTFLOW

NO. 144    HHR 0    AMY 10    JHR SPECIFICATION  
1    0    0    1    0    0    0    2    0    0  
JUPER    Nat    0  
3    0

SUB-AREA RUNOFF COMPUTATION

WATERSHED RUNOFF  
ISTAD 1    ICOMP 0    IECUN 0    ITAPE 0    JPLI 0    JPRT 0    INAME 1

HYDROGRAPH DATA  
IHYD 1    IAD 1    TAREA 0.17    SNAP 0.0    TSSA 0.0    TSSPL 1.00    NATI 0.500    ISMU 0    ISAM 0    LUGAL 0

PRECIP DATA  
SPPE 0.0    PMS 18.00    R6 111.00    R12 122.00    R24 133.00    R48 0.0    R72 0.0    R96 0.0

LOSS DATA  
STRAR 0.0    JLEK 0.0    RTIUL 1.00    EKAIN 0.0    STRKS 0.0    RTIJK 1.00    STRIL 0.47    CMSTL 0.20    ALSMA 0.0    RTIMP 0.0

UNIT HYDROGRAPH DATA  
TPR 0.27    CPO0.75    NTAB 0

REGRESSION DATA

SEPTOR 4.00    WRSSE 0.13    RTIUR 1.50

APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNYDER CP AND IP ARE 1.08 2.19 AND RR 0.76 INTERVALS

UNIT HYDROGRAPH 5 END-OF-PERIOD COORDINATES, LAUR 0.27 HOURS, CPO 0.75 VOLR 1.00

114.    275.    204.    52.    11.

END-OF-PERIOD FLOW

TIME	RAIN	EXCS	CUMP Q
1 0 10	0.02	0.02	5.
1 0 20	0.02	0.00	5.
1 0 30	0.02	0.00	4.
1 0 40	0.02	0.00	4.
1 0 50	0.02	0.00	4.
1 0 00	0.02	0.00	4.
1 1 10	0.02	0.00	4.
1 1 20	0.02	0.00	3.
1 1 30	0.02	0.00	3.
1 1 40	0.02	0.00	3.
1 1 50	0.02	0.00	3.
1 1 00	0.02	0.00	3.
1 2 10	0.02	0.00	3.
1 2 20	0.02	0.00	3.
1 2 30	0.02	0.00	3.
1 2 40	0.02	0.00	3.
1 2 50	0.02	0.00	3.
1 3 00	0.02	0.00	2.
1 3 10	0.02	0.00	2.
1 3 20	0.02	0.00	2.
1 3 30	0.02	0.00	2.
1 3 40	0.02	0.00	2.
1 3 50	0.02	0.00	2.
1 4 00	0.02	0.00	2.
1 4 10	0.02	0.00	2.
1 4 20	0.02	0.00	2.
1 4 30	0.02	0.00	2.
1 4 40	0.02	0.00	2.
1 4 50	0.02	0.00	2.
1 4 00	0.02	0.00	1.
1 4 10	0.02	0.00	1.
1 4 20	0.02	0.00	1.
1 4 30	0.02	0.00	1.
1 4 40	0.02	0.00	1.
1 4 50	0.02	0.00	1.
1 5 00	0.02	0.00	1.
1 5 10	0.02	0.00	1.
1 5 20	0.02	0.00	1.
1 5 30	0.02	0.00	1.
1 5 40	0.02	0.00	1.
1 5 50	0.02	0.00	1.
1 6 00	0.05	0.00	4.
1 6 10	0.05	0.00	4.
1 6 20	0.05	0.00	9.
1 6 30	0.05	0.00	14.
1 6 40	0.05	0.00	15.
1 6 50	0.05	0.00	15.
1 7 00	0.05	0.00	15.
1 7 10	0.05	0.00	15.
1 7 20	0.05	0.00	15.
1 7 30	0.05	0.00	15.
1 7 40	0.05	0.00	15.
1 7 50	0.05	0.00	15.
1 7 00	0.05	0.00	15.
1 8 10	0.05	0.00	15.
1 8 20	0.05	0.00	15.
1 8 30	0.05	0.00	15.
1 8 40	0.05	0.00	15.
1 8 50	0.05	0.00	15.
1 9 00	0.05	0.00	15.
1 9 10	0.05	0.00	15.
1 9 20	0.05	0.00	15.
1 9 30	0.05	0.00	15.
1 9 40	0.05	0.00	15.
1 9 50	0.05	0.00	15.
1 9 00	0.05	0.00	15.
1 10 10	0.05	0.00	15.
1 10 20	0.05	0.00	15.
1 10 30	0.05	0.00	15.
1 10 40	0.05	0.00	15.
1 10 50	0.05	0.00	15.
1 11 00	0.05	0.00	15.
1 11 10	0.05	0.00	15.
1 11 20	0.05	0.00	15.
1 11 30	0.05	0.00	15.
1 11 40	0.05	0.00	15.
1 11 50	0.05	0.00	15.
1 11 00	0.05	0.00	15.
1 12 10	0.05	0.00	15.
1 12 20	0.05	0.00	15.
1 12 30	0.05	0.00	15.
1 12 40	0.05	0.00	15.
1 12 50	0.05	0.00	15.
1 13 00	0.05	0.00	15.
1 13 10	0.05	0.00	15.
1 13 20	0.05	0.00	15.
1 13 30	0.05	0.00	15.
1 13 40	0.05	0.00	15.
1 13 50	0.05	0.00	15.
1 14 00	0.05	0.00	15.
1 14 10	0.05	0.00	15.
1 14 20	0.05	0.00	15.
1 14 30	0.05	0.00	15.
1 14 40	0.05	0.00	15.
1 14 50	0.05	0.00	15.
1 15 00	0.05	0.00	15.
1 15 10	0.05	0.00	15.
1 15 20	0.05	0.00	15.
1 15 30	0.05	0.00	15.
1 15 40	0.05	0.00	15.
1 15 50	0.05	0.00	15.
1 16 00	0.05	0.00	15.
1 16 10	0.05	0.00	15.
1 16 20	0.05	0.00	15.
1 16 30	0.05	0.00	15.
1 16 40	0.05	0.00	15.
1 16 50	0.05	0.00	15.
1 17 00	0.05	0.00	15.
1 17 10	0.05	0.00	15.
1 17 20	0.05	0.00	15.
1 17 30	0.05	0.00	15.
1 17 40	0.05	0.00	15.
1 17 50	0.05	0.00	15.
1 18 00	0.05	0.00	15.
1 18 10	0.05	0.00	15.
1 18 20	0.05	0.00	15.
1 18 30	0.05	0.00	15.
1 18 40	0.05	0.00	15.
1 18 50	0.05	0.00	15.
1 19 00	0.05	0.00	15.
1 19 10	0.05	0.00	15.
1 19 20	0.05	0.00	15.
1 19 30	0.05	0.00	15.
1 19 40	0.05	0.00	15.
1 19 50	0.05	0.00	15.
1 20 00	0.05	0.00	15.
1 20 10	0.05	0.00	15.
1 20 20	0.05	0.00	15.
1 20 30	0.05	0.00	15.
1 20 40	0.05	0.00	15.
1 20 50	0.05	0.00	15.
1 21 00	0.05	0.00	15.
1 21 10	0.05	0.00	15.
1 21 20	0.05	0.00	15.
1 21 30	0.05	0.00	15.
1 21 40	0.05	0.00	15.
1 21 50	0.05	0.00	15.
1 22 00	0.05	0.00	15.
1 22 10	0.05	0.00	15.
1 22 20	0.05	0.00	15.
1 22 30	0.05	0.00	15.
1 22 40	0.05	0.00	15.
1 22 50	0.05	0.00	15.
1 23 00	0.05	0.00	15.
1 23 10	0.05	0.00	15.
1 23 20	0.05	0.00	15.
1 23 30	0.05	0.00	15.
1 23 40	0.05	0.00	15.
1 23 50	0.05	0.00	15.
1 24 00	0.05	0.00	15.
1 24 10	0.05	0.00	15.
1 24 20	0.05	0.00	15.
1 24 30	0.05	0.00	15.
1 24 40	0.05	0.00	15.
1 24 50	0.05	0.00	15.
1 25 00	0.05	0.00	15.
1 25 10	0.05	0.00	15.
1 25 20	0.05	0.00	15.
1 25 30	0.05	0.00	15.
1 25 40	0.05	0.00	15.
1 25 50	0.05	0.00	15.
1 26 00	0.05	0.00	15.
1 26 10	0.05	0.00	15.
1 26 20	0.05	0.00	15.
1 26 30	0.05	0.00	15.
1 26 40	0.05	0.00	15.
1 26 50	0.05	0.00	15.
1 27 00	0.05	0.00	15.
1 27 10	0.05	0.00	15.
1 27 20	0.05	0.00	15.
1 27 30	0.05	0.00	15.
1 27 40	0.05	0.00	15.
1 27 50	0.05	0.00	15.
1 28 00	0.05	0.00	15.
1 28 10	0.05	0.00	15.
1 28 20	0.05	0.00	15.
1 28 30	0.05	0.00	15.
1 28 40	0.05	0.00	15.
1 28 50	0.05	0.00	15.
1 29 00	0.05	0.00	15.
1 29 10	0.05	0.00	15.
1 29 20	0.05	0.00	15.
1 29 30	0.05	0.00	15.
1 29 40	0.05	0.00	15.
1 29 50	0.05	0.00	15.
1 30 00	0.05	0.00	15.
1 30 10	0.05	0.00	15.
1 30 20	0.05	0.00	15.
1 30 30	0.05	0.00	15.
1 30 40	0.05	0.00	15.
1 30 50	0.05	0.00	15.
1 31 00	0.05	0.00	15.
1 31 10	0.05	0.00	15.
1 31 20	0.05	0.00	15.
1 31 30	0.05	0.00	15.
1 31 40	0.05	0.00	15.
1 31 50	0.05	0.00	15.
1 32 00	0.05	0.00	15.
1 32 10	0.05	0.00	15.
1 32 20	0.05	0.00	15.
1 32 30	0.05	0.00	15.
1 32 40	0.05	0.00	15.
1 32 50	0.05	0.00	15.
1 33 00	0.05	0.00	15.
1 33 10	0.05	0.00	15.
1 33 20	0.05	0.00	15.
1 33 30	0.05	0.00	15.
1 33 40	0.05	0.00	15.
1 33 50	0.05	0.00	15.
1 34 00	0.05	0.00	15.
1 34 10	0.05	0.00	15.
1 34 20	0.05	0.00	15.
1 34 30	0.05	0.00	15.
1 34 40	0.05	0.00	15.
1 34 50	0.05	0.00	15.
1 35 00	0.05	0.00	15.
1 35 10	0.05	0.00	15.
1 35 20	0.05	0.00	15.
1 35 30	0.05	0.00	15.
1 35 40	0.05	0.00	15.
1 35 50	0.05	0.00	15.
1 36 00	0.05	0.00	15.
1 36 10	0.05	0.00	15.
1 36 20	0.05	0.00	15.
1 36 30	0.05	0.00	15.
1 36 40	0.05	0.00	15.
1 36 50	0.05	0.00	15.
1 37 00	0.05	0.00	15.
1 37 10	0.05	0.00	15.
1 37 20	0.05	0.00	15.
1 37 30	0.05	0.00	15.
1 37 40	0.05	0.00	15.
1 37 50	0.05	0.00	15.
1 38 00	0.05	0.00	15.
1 38 10	0.05	0.00	15.
1 38 20	0.05	0.00	15.
1 38 30	0.05	0.00	15.
1 38 40	0.05	0.00	15.
1 38 50	0.05	0.00	15.
1 39 00	0.05	0.00	15.
1 39 10	0.05	0.00	15.
1 39 20	0.05	0.00	15.
1 39 30	0.05	0.00	15.
1 39 40	0.05	0.00	15.
1 39 50	0.05	0.00	15.
1 40 00	0.05	0.00	15.
1 40 10	0.05	0.00	15.
1 40 20	0.05	0.00	15.
1 40 30	0.05	0.00	15.
1 40 40	0.05	0.00	15.
1 40 50	0.05	0.00	15.
1 41 00	0.05	0.00	15.
1 41 10	0.05	0.00	15.
1 41 20	0.05	0.00	15.
1 41 30	0.05	0.00	15.
1 41 40	0.05	0.00	15.
1 41 50	0.05	0.00	15.
1 42 00	0.05	0.00	15.
1 42 10	0.05	0.00	15.
1 42 20	0.05	0.00	15.
1 42 30	0.05	0.00	15.
1 42 40	0.05	0.00	15.
1 42 50	0.05	0.00	15.
1 43 00	0.05	0.00	15.
1 43 10	0.05	0.00	15.
1 43 20	0.05	0.00	15.
1 43 30	0.05	0.00	15.
1 43 40	0.05	0.00	15.
1 43 50	0.05	0.00	15.
1 44 00	0.05	0.00	15.
1 44 10</			

1 15 00	1.27	1.23	807.
1 16 10	0.47	0.43	716.
1 16 20	0.47	0.43	497.
1 16 30	0.47	0.43	334.
1 16 40	0.47	0.43	292.
1 16 50	0.47	0.43	284.
1 16 60	0.47	0.43	284.
1 17 10	0.37	0.33	272.
1 17 20	0.37	0.33	269.
1 17 30	0.37	0.33	274.
1 17 40	0.37	0.33	219.
1 17 50	0.37	0.33	218.
1 17 60	0.37	0.33	218.
1 18 10	0.03	0.00	180.
1 18 20	0.03	0.00	89.
1 18 30	0.03	0.00	78.
1 18 40	0.03	0.00	75.
1 18 50	0.03	0.00	72.
1 18 60	0.03	0.00	69.
1 19 10	0.03	0.00	66.
1 19 20	0.03	0.00	64.
1 19 30	0.03	0.00	61.
1 19 40	0.03	0.00	59.
1 19 50	0.03	0.00	56.
1 19 60	0.03	0.00	54.
1 20 10	0.03	0.00	52.
1 20 20	0.03	0.00	50.
1 20 30	0.03	0.00	48.
1 20 40	0.03	0.00	46.
1 20 50	0.03	0.00	44.
1 20 60	0.03	0.00	42.
1 21 10	0.03	0.00	41.
1 21 20	0.03	0.00	39.
1 21 30	0.03	0.00	38.
1 21 40	0.03	0.00	36.
1 21 50	0.03	0.00	35.
1 21 60	0.03	0.00	33.
1 22 10	0.03	0.00	32.
1 22 20	0.03	0.00	31.
1 22 30	0.03	0.00	29.
1 22 40	0.03	0.00	28.
1 22 50	0.03	0.00	27.
1 22 60	0.03	0.00	26.
1 23 10	0.03	0.00	25.
1 23 20	0.03	0.00	24.
1 23 30	0.03	0.00	23.
1 23 40	0.03	0.00	22.
1 23 50	0.03	0.00	21.
1 23 60	0.03	0.00	20.

SUM 23.64 19.50 14377.

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	807.	338.	100.	100.	14375.
INCHES		18.49	21.85	21.85	21.85
AC-FT		168.	198.	198.	198.

23 60. 1  
 23 15. 1  
 23 30. 1  
 23 45. 1  
 23 60. 1

RUNOFF MULTIPLIED BY 0.50

2.	2.	2.	2.	2.	2.	2.	2.	2.	2.
2.	2.	1.	1.	1.	1.	1.	1.	1.	1.
1.	1.	1.	1.	1.	1.	1.	1.	1.	1.
1.	1.	1.	1.	1.	1.	1.	2.	3.	7.
8.	8.	8.	8.	8.	8.	7.	7.	7.	7.
7.	7.	7.	7.	7.	7.	7.	7.	7.	7.
7.	7.	7.	7.	7.	7.	7.	7.	7.	7.
7.	7.	23.	51.	90.	97.	98.	93.	102.	111.
113.	120.	120.	120.	126.	139.	150.	152.	153.	153.
176.	101.	380.	400.	404.	404.	358.	248.	167.	166.
142.	142.	136.	122.	112.	110.	109.	109.	90.	46.
39.	37.	36.	34.	33.	32.	31.	29.	28.	27.
26.	25.	24.	23.	22.	21.	20.	20.	19.	18.
17.	17.	16.	15.	15.	14.	14.	13.	13.	12.
12.	11.	11.	10.						

CFS	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
INCHES	404.	169.	50.	50.	7187.
AC-FT		9.25	10.92	10.92	10.92
		84.	99.	99.	99.









1 9 40	15.	7.	7.
1 9 50	15.	7.	7.
1 9 60	15.	7.	7.
1 10 10	15.	7.	7.
1 10 20	15.	7.	7.
1 10 30	15.	7.	7.
1 10 40	15.	7.	7.
1 10 50	15.	7.	7.
1 10 60	15.	7.	7.
1 11 10	15.	7.	7.
1 11 20	15.	7.	7.
1 11 30	15.	7.	7.
1 11 40	15.	7.	7.
1 11 50	15.	7.	7.
1 11 60	15.	7.	7.
1 12 10	16.	15.	9.
1 12 20	16.	42.	15.
1 12 30	17.	75.	27.
1 12 40	18.	93.	39.
1 12 50	18.	98.	54.
1 12 60	19.	93.	68.
1 13 10	19.	170.	78.
1 13 20	19.	107.	88.
1 13 30	20.	115.	98.
1 13 40	20.	119.	105.
1 13 50	20.	120.	111.
1 13 60	20.	120.	114.
1 14 10	20.	123.	117.
1 14 20	21.	133.	123.
1 14 30	21.	145.	131.
1 14 40	21.	151.	138.
1 14 50	21.	152.	144.
1 14 60	21.	153.	148.
1 15 10	22.	175.	158.
1 15 20	23.	249.	195.
1 15 30	24.	341.	254.
1 15 40	26.	390.	319.
1 15 50	26.	402.	360.
1 15 60	27.	404.	381.
1 16 10	27.	391.	381.
1 16 20	26.	303.	343.
1 16 30	25.	208.	279.
1 16 40	23.	156.	224.
1 16 50	22.	144.	190.
1 16 60	22.	142.	170.
1 17 10	22.	139.	158.
1 17 20	21.	129.	146.
1 17 30	21.	117.	135.
1 17 40	21.	111.	126.
1 17 50	20.	109.	120.
1 17 60	20.	107.	116.
1 18 10	20.	100.	110.
1 18 20	20.	67.	94.
1 18 30	19.	42.	76.
1 18 40	19.	38.	64.
1 18 50	18.	37.	55.
1 18 60	18.	35.	49.
1 19 10	18.	34.	45.
1 19 20	18.	32.	42.
1 19 30	18.	31.	40.
1 19 40	18.	30.	38.
1 19 50	17.	29.	36.
1 19 60	17.	28.	35.
1 20 10	17.	27.	33.
1 20 20	17.	25.	32.
1 20 30	17.	24.	30.
1 20 40	17.	23.	27.
1 20 50	17.	23.	28.
1 20 60	17.	22.	27.
1 21 10	17.	21.	25.
1 21 20	17.	20.	24.
1 21 30	17.	19.	23.
1 21 40	16.	18.	22.
1 21 50	16.	18.	22.
1 21 60	16.	17.	21.
1 22 10	16.	16.	20.
1 22 20	16.	16.	19.
1 22 30	16.	15.	18.
1 22 40	16.	14.	18.
1 22 50	16.	14.	17.
1 22 60	16.	13.	16.
1 23 10	16.	13.	16.
1 23 20	16.	12.	15.
1 23 30	16.	12.	14.
1 23 40	16.	11.	14.
1 23 50	16.	11.	13.
1 23 60	16.	10.	13.

SUM

7140.


CFS INCHES AC-FT	PEAK 3hr.	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
	381.	165.	50.	50.	7140.
		9.00	10.85	10.85	10.85
		82.	94.	98.	98.

.....

FUTURE SUMMARY, AVERAGE FLOW

	PEAK	6-11-75	24-11-75	72-11-75	ASFA
1975-76 AT	1	52%	10%	5%	0-17
1976-77	1	36%	10%	5%	0-17

1 23 50. 10  
1 25 60. 10  
1 21 19. 10  
1 21 20. 10  
1 21 30. 10  
1 21 40. 1  
1 21 50. 1  
1 21 50. 10  
1 22 10. 10  
1 22 20. 10  
1 22 30. 10  
1 22 40. 10  
1 22 50. 1  
1 23 10. 1  
1 23 20. 10  
1 23 30. 10  
1 23 40. 1  
1 23 50. 10  
1 23 60. 10



SOURCE OF MAP:  
 U.S. GEOLOGICAL SURVEY  
 HOLDERNESS & WINNIPESAUKEE  
 QUADRANGLES  
 NEW HAMPSHIRE  
 SERIES V712  
 1:62500 1956

DUFRESNE-HENRY ENGINEERING CORP. ARCHITECT-ENGINEER		U.S. ARMY ENGINEER DIV. NEW ENGLAND CORPS OF ENGINEERS WALTHAM, MASS.	
NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS			
LOCATION MAP MEREDITH RESERVOIR DAM			
MEREDITH		NEW HAMPSHIRE	
CLIENT NO	04-0082	SCALE	1" = 1 MILE
ENGR	JAD	DATE	3-14-79

APPENDIX E

Information as Contained in the National Inventory of Dams

**END**

**FILMED**

8-85

**DTIC**