

N-1804

NCEL

December 1989

By David E. Pendleton

Technical NoteSponsored By Office of Naval Technology
Arlington, Virginia 22217-5000

AD-A218 263

**SUMMARY OF EXPERIMENTAL
PILING INSPECTIONS AT
PEARL HARBOR, HAWAII**

ABSTRACT Two hundred seventy-three treated Douglas-fir and southern pine piling were installed at Pearl Harbor, Hawaii from 1963 to 1966 and periodically inspected to determine cross-sectional area loss caused by teredine, limnorian, and pholad marine borers. All piling treated with creosote and copper-nickel sheathing, chlordane, creosote and dieldrin, basic zinc sulfate, and most piling treated with an arsenical salt and creosote (dual treatment) have sustained little loss. Piling treated with phenylmercuric oleate in creosote or with copper oxinate have performed relatively well. Arsenical salt treatments (at low retentions), treatments of copper naphthenate with creosote, and most creosote treatments are rated fair to good. Two creosote treatment groups have sustained little loss. In general, little or no apparent enhancement of performance was imparted by the inclusion of Victoria green base, tributyltin oxide, or copper sulfate to treatment chemicals tested.


DTIC
ELECTE
FEB 22 1990
S **E** **D**

NAVAL CIVIL ENGINEERING LABORATORY PORT HUENEME CALIFORNIA 93043-5003

METRIC CONVERSION FACTORS

Approximate Conversions to Metric Measures				Approximate Conversions from Metric Measures			
Symbol	When You Know	Multiply by	To Find	Symbol	When You Know	Multiply by	To Find
in ft yd mi	inches	2.54	centimeters	mm	millimeters	0.04	inches
	feet	30	centimeters	cm	centimeters	0.4	inches
	yards	0.9	meters	m	meters	3.3	feet
	miles	1.6	kilometers	km	kilometers	1.1	yards
in ² ft ² yd ² mi ²	square inches	6.5	square centimeters	cm ²	square centimeters	0.16	square inches
	square feet	0.09	square meters	m ²	square meters	1.2	square yards
	square yards	0.8	square meters	km ²	square kilometers	0.4	square miles
	square miles	2.6	square kilometers	ha	hectares (10,000 m ²)	2.5	acres
oz lb	ounces	28	grams	g	grams	0.035	ounces
	pounds	0.45	kilograms	kg	kilograms	2.2	pounds
	short tons (2,000 lb)	0.9	tonnes	t	tonnes (1,000 kg)	1.1	short tons
tsp Tbsp fl oz c pt qt gal ft ³ yd ³	teaspoons	5	milliliters	ml	milliliters	0.03	fluid ounces
	tablespoons	15	milliliters	ml	liters	2.1	pints
	fluid ounces	30	milliliters	ml	liters	1.06	quarts
	cups	0.24	liters	l	liters	0.26	gallons
oF	pints	0.47	liters	l	cubic meters	35	cubic feet
	quarts	0.95	liters	l	cubic meters	1.3	cubic yards
	gallons	3.8	liters	l			
	cubic feet	0.03	cubic meters	m ³			
	cubic yards	0.76	cubic meters	m ³			
TEMPERATURE (exact)				TEMPERATURE (exact)			
	Fahrenheit temperature	5/9 (after subtracting 32)	Celsius temperature		Celsius temperature	9/5 (then add 32)	Fahrenheit temperature

* 1 in. = 2.54 (exactly). For other exact conversions and more detailed tables, see NBS Misc. Publ. 286, Units of Weights and Measures, Price \$2.25, SD Catalog No. C13.10.286.




REPORT DOCUMENTATION PAGE			Form Approved OMB No. 0704-0188	
Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.				
1. AGENCY USE ONLY (Leave blank)		2. REPORT DATE December 1989		3. REPORT TYPE AND DATES COVERED Final - FY89
4. TITLE AND SUBTITLE SUMMARY OF EXPERIMENTAL PILING INSPECTIONS AT PEARL HARBOR, HAWAII			5. FUNDING NUMBERS PE - 62234N WU - DN287268 Block - YE2A Task - E-2 PR - RS34S58	
6. AUTHOR(S) David E. Pendleton				
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) Naval Civil Engineering Laboratory Port Hueneme, CA 93043-5003			8. PERFORMING ORGANIZATION REPORT NUMBER TN-1804	
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES) Office of Naval Technology Arlington, VA 22217-5000			10. SPONSORING/MONITORING AGENCY REPORT NUMBER	
11. SUPPLEMENTARY NOTES				
12a. DISTRIBUTION/AVAILABILITY STATEMENT Approved for public release; distribution is unlimited.			12b. DISTRIBUTION CODE	
13. ABSTRACT (Maximum 200 words) Two hundred seventy-three treated Douglas-fir and southern pine piling were installed at Pearl Harbor, Hawaii from 1963 to 1966 and periodically inspected to determine cross-sectional area loss caused by teredine, limnorian, and pholad marine borers. All piling treated with creosote and copper-nickel sheathing, chlordane, creosote and dieldrin, basic zinc sulfate, and most piling treated with an arsenical salt and creosote (dual treatment) have sustained little loss. Piling treated with phenyl-mercuric oleate in creosote or with copper oxinate have performed relatively well. Arsenical salt treatments (at low retentions), treatments of copper naphthenate with creosote, and most creosote treatments are rated fair to good. Two creosote treatment groups have sustained little loss. In general, little or no apparent enhancement of performance was imparted by the inclusion of Victoria green base, tributyltin oxide, or copper sulfate to treatment chemicals tested.				
14. SUBJECT TERMS Wood preservation, marine piling, marine borers, creosote, arsenical salts, basic zinc sulfate, biodeterioration, biocides.			15. NUMBER OF PAGES 17	
			16. PRICE CODE	
17. SECURITY CLASSIFICATION OF REPORT Unclassified	18. SECURITY CLASSIFICATION OF THIS PAGE Unclassified	19. SECURITY CLASSIFICATION OF ABSTRACT Unclassified	20. LIMITATION OF ABSTRACT UL	

CONTENTS

	Page
INTRODUCTION	1
PILING TREATMENTS AND INSTALLATIONS	1
PILING INSPECTIONS	2
INSPECTION RESULTS	2
DISCUSSION	3
Creosote Treatments	3
Other Single Treatments	4
Dual Treatments With Creosote	4
Dual Treatments Without Creosote	5
Multiple Treatments With Creosote	5
FINDINGS AND CONCLUSIONS	5
RECOMMENDATIONS	6
REFERENCES	6

Accession For	
NTIS GRA&I	☒
DTIC TAB	☒
Unannounced	☐
Justification	
By _____	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A-1	



INTRODUCTION

The efficacy of a wood preservative in preventing marine borer damage can be determined by the marine exposure of either treated small wood panels or full-size timber piling. Small panel testing provides an inexpensive, accelerated means of determining the relative worth of experimental treatments but a more accurate determination requires the installation of treated, full-size piling.

The Naval Civil Engineering Laboratory (NCEL) installed 273 experimental piling at Pearl Harbor, Hawaii, during the years 1963 through 1966 (Figure 1). The piling driven in 1963 were produced by the Kopper's Company for the Cooperative Marine Piling Committee (COOP). The COOP included representatives from NCEL, the wood-treating industry, the Forest Products Laboratory, and the W.F. Clapp laboratory (now Batelle Laboratories). The piling installed from 1964 to 1966 were produced and driven solely under the guidance of NCEL. The treatment chemicals selected were first included in laboratory screening tests, in which the antiborer activity of 786 chemicals was determined, followed by small panel exposure testing of the most promising agents (Ref 1). Although many of the piling have been accidentally or deliberately removed or completely destroyed by marine borers, the value of the remaining test piling increases yearly as the relative efficacies of the various treatments become evident.

This report is an update of the 1987 inspection summary report (Ref 2).

PILING TREATMENTS AND INSTALLATIONS

A summary of piling treatments with the year driven is provided in Table 1. All piling were pressure-treated and were driven near Waipio Peninsula, Pearl Harbor, Hawaii. Details of original treatments and installations can be found in References 3 through 7; brief descriptions of treatments, installations, and removals are provided below.

All Douglas-fir and southern yellow pine piling installed in 1963 were pressure-treated with creosote and most were also treated with another preservative (dual treatment). Of the 66 piling driven in 1963, 42 were inadvertently removed in August 1972. Most broke during removal, while some were lost or could not be identified. Four of the piling were redriven in May 1973; thus, 28 piling remained for subsequent inspections. One was subsequently reported broken by impact and lost in 1978.

In 1964, 69 creosoted Douglas-fir piling were driven. Most piling were treated with one or two additional preservatives. Four piling in this group were removed in 1982 and examined to assess the accuracy of visual inspection techniques.

All of the 78 Douglas-fir piling installed in 1965 were accidentally removed in 1972; 47 were redriven in 1973. One of these piling was removed in 1982 for examination at NCEI. The treatments included experimental preservatives in xylene or in creosote.

The last series, consisting of 60 Douglas-fir piling, were installed in 1966. A variety of single and dual treatments were employed. None of these piling were lost in 1972 but six were purposely removed in 1982.

PILING INSPECTIONS

From 1975 to 1989, eight underwater inspections were completed by professional divers. The piling are cleaned of surface fouling and then evaluated visually and by touch from the mud line to high water. Diver inspection reports include for each pile: (1) an estimate of the percent loss of cross-sectional area in the region of greatest damage, (2) any boring organisms present, and (3) any splits, checks, or other damage present. In a few cases, untreated heartwood was exposed by checks that occurred after treatment, e.g., during piledriving; borer damage to this heartwood was largely discounted by divers when estimating cross-sectional loss.

Visual examinations can readily detect damage caused by Limnoria tripunctata, a crustacean, and Martesia striata, a wood-boring clam (pholad), both prevalent in Pearl Harbor. Damage by shipworms (teredines), also abundant in Hawaiian waters, is mainly internal and difficult for divers to observe directly. Diver inspection reports, however, indicated that the majority of damage was caused by Limnoria and that any shipworm attack was most often preceded by extensive Limnoria damage. In order to confirm this observation and evaluate the accuracy of visual inspections, the 1982 inspection also included direct observations of nine piling removed from the water one week after visual inspections. These piling were cut in the area of greatest damage and photographed. Sound wood was outlined on the photographs and a planimeter was used to determine cross-sectional area. From these data, cross-sectional area loss for each pile was calculated and compared with diver estimates (Table 2). Observations of cut piling confirmed that the majority of damage was caused by Limnoria. Where cut piling had an actual cross-sectional loss of 13% or less, the diver estimates were close to actual damages. Where cut piling had an actual cross-sectional loss from 31 to 65%, the diver estimates were consistently lower (about 1/2 of actual damage).

INSPECTION RESULTS

The performances of the various treatments are included in Tables 3 through 7 in terms of the average number of years of exposure until piling cross-sectional area loss as determined by diver inspections exceeded 5%, 15%, and 50%. In those cases where a number of years passed between inspections and rapid change occurred, the years of exposure until a loss category was reached is determined by extrapolation. For those

piling inadvertently removed in 1972 and then redriven in 1973, the time spent out of the water is discounted in determining years of exposure. Most treatment retention values listed in Tables 3 through 7 were determined by analysis of core borings before installation; some were determined by treatment gage measurement at the time of treatment.

Where all the piling of a particular treatment have not yet exceeded an area loss category, the average number of exposure years for that category cannot be calculated. In those cases, the number of piling remaining which did not exceed that cross-sectional loss category by 1989 are given in parentheses in Tables 3 through 7. For example, in Table 3 it can be seen that five Douglas-fir piling treated with marine grade creosote were driven in 1963. All five sustained a loss of more than 15% by 1989. It took an average of 19.5 years for the loss to exceed 5% and an average of 23.4 years for the loss to exceed 15%. In addition, two piling have lost a cross-sectional area greater than 15% but not greater than 50% by the 1989 inspection. The remaining three piling have lost a cross-sectional area greater than 50%.

Early inspections reported that the majority of damage was caused by a boring clam, Martesia striata, with limited attack by the crustacean, Limnoria tripunctata. No shipworms were found. Later inspections reported increased Limnorian attack and it is now the major cause of damage to most piling. Martesia are, however, the main cause of damage to salt-treated piling (i.e., treated with BZS, ACA, or CCA) that have sustained damage of 20% or less. Some shipworm damage is reported in recent inspections in association with extensive limnorian attack. These observations do not preclude the possibility that some internal shipworm attack has occurred unnoticed.

DISCUSSION

It has been only after the most recent inspections that some differences in treatment efficacies could be measured. The treated piling have generally lasted a very long time. This longevity is likely a result of the inherent worth of the treatments and the care taken in treatments and installations.

It is evident that loss of piling cross-sectional area in this test proceeds in two stages. The initial stage is represented by the number of years it takes to sustain a loss of greater than 5%. This stage is generally slow and reflects the level of protection the treatment offers. After a pile has suffered a loss of from 5% to 10% the damage proceeds rapidly; the loss rate during this latter stage apparently differs little between treatments. Many of the Hawaii experimental piling have only recently begun this rapid stage of deterioration.

Creosote Treatments

The performances of creosote-treated piling are inconsistent but the majority of treatments have performed well (Table 3). No consistent relationship between performance and preservative retention is evident between treatment groups. Only one piling group of three treated with marine grade creosote was heavily damaged as of the 1989 inspection.

Likewise, only one group of three treated with 70-30 creosote-coal tar was heavily damaged. This performance range makes direct comparisons of other treated piling with creosoted piling difficult. The wide variation in performance of seemingly like-treated piling has often plagued those charged with the task of assessing the relative efficacies of preservative treatments.

Limnoria are the principal agents of damage to creosoted wood. Shipworms apparently become established only after the heartwood is exposed by limnorian attack. Martesia damage to these piling is generally limited.

Other Single Treatments

Basic zinc sulfate has been the most successful single treatment in this test followed by copper oxinate (Table 4). The relatively good performances of these treatments along with their low environmental hazard may warrant further development of these preservatives. Single treatments of ammoniacal copper arsenate (ACA) and chromated copper arsenate (CCA) at low retentions have not performed as well. The recommended retention for these modern, multi-salt treatments, however, is 2.5 pcf for marine use; this is considerably greater than the retentions of the Hawaii test piling.

Borer damage to salt-treated timber is generally initiated by Martesia. The holes caused by these borers apparently provide an entry for Limnoria and shipworms into inner layers of the wood that have less preservative retention.

Dual Treatments With Creosote

Creosote treatments in combination with ACA, CCA at 2.7 pcf, or chlordane (a chlorinated organic pesticide) at 0.3 pcf have performed very well in these tests (Table 5). An exception is the CCA-creosote piling with a creosote retention of only 8.4 pcf and CCA retention of 1.7 pcf; these piling are all now severely damaged. Current AWWA recommendations call for 20 pcf creosote and 1.0 pcf arsenical salt for dual-treated piling. Chlordane is an apparently effective additive to creosote, but its use is unlikely because of environmental concerns.

Piling pressure-treated with a combination of creosote and phenylmercuric oleate (PMO) have generally endured. Analyses of core borings after treatment showed that considerably less than the nominal percentage of PMO got into the wood. Improved performance is likely if a greater PMO retention can be affected. Any mercurial compound, however, would be an unlikely candidate for marine wood preservation because of a high potential environmental hazard.

The one remaining creosoted piling that is completely covered with copper-nickel sheathing is still intact with the sheathing showing some corrosion but still apparently effective. Several like-treated piling were removed accidentally in 1972 and not redriven. The sheathings on these piling were reported to be severely corroded about midway between the mud line and high tide mark.

Dual-treated piling containing creosote and copper naphthenate have performed reasonably well. The relatively low preservative concentrations in these piling suggest that greater protection is possible with higher concentrations.

The addition of tributyltin oxide (TBTO) to creosote treatments provided no apparent additional protection.

Dual Treatments Without Creosote

This test indicates that the performance of copper oxinate as a wood preservative in the marine environment is not enhanced by the inclusion of tributyltin oxide (TBTO), a controversial but effective antifoulant, or Victoria green base, a common dye (Table 6). Piling treated with TBTO in combination with CCA, ACA, or basic zinc sulfate, on the other hand, have lasted slightly longer than respective piling treated with nearly equal amounts of these salts without TBTO. TBTO in combination with copper sulfate has been relatively ineffective. The inclusion of TBTO in piling treatments is now unlikely because of environmental constraints.

Multiple Preservatives With Creosote

Piling treated with copper naphthenate and creosote with added TBTO have performed similarly to piling with similar retentions of the dual treatment without TBTO (Table 7). Likewise, piling treated with creosote, copper oxinate, and Victoria green base have performed no better than like-treated piling but without creosote. The very good performance of piling treated with a combination of creosote, TBTO, and the chlorinated organic, dieldrin, is tempered by the unlikely environmental acceptability of this chlorinated pesticide.

FINDINGS AND CONCLUSIONS

1. Visual inspections of these experimental piling by divers provide an accurate assessment of borer damage when there is very little or severe cross-sectional loss. Pile damage estimates are generally lower than actual damages when cross-sectional losses are from 15 to 60%.
2. Damage to creosoted piling is primarily by limnoria. Damage to salt-treated piling is initiated by pholads, but in later stages damage is mainly by Limnoria. Some shipworm attack is evident in most severely damaged piling.
3. Damage to piling proceeds in two stages. The length of the first stage (until cross sectional loss is 5% or greater) is a fair measure of treatment efficacy. Soon after damage exceeds 5%, Limnoria and shipworms are established and damage rapidly accelerates.
4. The following treatments are considered excellent (more than 20 years average exposure until cross-sectional loss greater than 5%) and are listed in approximate order of success:

Creosote (17.4 pcf), TBTO (0.18 pcf), and dieldrin (0.18 pcf)
Creosote (24.3 pcf) and Cu-Ni sheathing
Creosote (26.3 - 28.6 pcf) and chlordane (0.3 - 1.4 pcf)

Creosote (16.2 - 19.6 pcf) and ACA (0.51 pcf)
Basic zinc sulfate (2.66 pcf) and TBTO (0.20 pcf)
Creosote (23.2 pcf) and CCA (2.7 pcf)
Chlordane (1.3 - 1.5 pcf) and TBTO (0.27 - 0.62 pcf)

4. The following treatments are considered good (from 15 to 20 years average exposure until cross-sectional loss greater than 5%) and are listed in approximate order of success:

Basic zinc sulfate (2.77 pcf)
Creosote (13.0 - 27.5 pcf) and phenylmercuric oleate (1 - 5%)
ACA (0.51 pcf) and TBTO (0.11 pcf)
Copper oxinate (0.49 - 0.87 pcf)
Creosote (15.3 - 32.9 pcf)
Creosote (8.3 - 10.9 pcf) and copper naphthenate (0.09 - 0.27 pcf)
CCA (0.5 pcf) and TBTO (0.13 pcf)
Copper oxinate (0.69 pcf) and Victoria green base (0.26 pcf)
ACA (0.51 pcf)
Creosote (8.4 pcf) and CCA (1.7 pcf)

5. The following treatments are considered poor to fair (less than 15 years average exposure until cross-sectional loss greater than 5%) and are listed in approximate order of success:

Creosote (8.6 - 10.9 pcf), copper naphthenate (0.09 - 0.27 pcf) and TBTO (0.08 - 0.15 pcf)
Creosote (9.2 - 24.7 pcf), copper oxinate (0.25 - 0.27 pcf), and Victoria green base (0.08 - 0.09 pcf)
Copper oxinate (0.25 pcf) and TBTO (0.25 pcf)
Copper sulfate (0.03 - 0.06 pcf) and TBTO (0.19 - 0.20 pcf)
Creosote (13.9 pcf) and TBTO (0.14 pcf)
CCA (0.5 pcf)

RECOMMENDATIONS

1. Additional inspections of these experimental piling in Hawaii should be completed. It is anticipated that many treatment systems under test will continue to provide excellent marine borer protection for many more years and should be evaluated on a timely basis.
2. The continued success of basic zinc sulfate warrants further investigation as an environmentally acceptable alternative to creosote, CCA, and ACA for marine timber.

REFERENCES

1. Civil Engineering Laboratory. Technical Report R-850: Harbor screening tests of marine borer inhibitors -- Final report, by T. Roe, Jr. Port Hueneme, CA, Dec 1976.

2. D.E. Pendleton. "Inspection of experimental piling at Pearl Harbor, Hawaii," Proc. of Amer. Wood-Preservers' Assoc. Ann. Mtg., 84: 267-274, 1988.
3. Naval Civil Engineering Laboratory. Technical Note N-503: Cooperative marine piling investigation, phase 2 - Pile driving at Pearl Harbor, Hawaii, by H. Hochman. Port Hueneme, CA, Jul 1963.
4. _____. Technical Note N-672: Experimental wood piling treatments FY-64, by T. Roe, Jr. and H. Hochman. Port Hueneme, CA, Dec 1964.
5. _____. Technical Note N-677: Driving of piling treated with creosote containing additives, by H. Hochman. Port Hueneme, CA, Dec 1964.
6. _____. Technical Note N-736: Experimental wood piling treatments FY-65, by T. Roe, Jr. and H. Hochman. Port Hueneme, CA, Aug 1965.
7. _____. Technical Note N-898: Experimental wood preservative systems: Treatment FY 66; Driving FY 67, by H. Hochman and T. Roe, Jr. Port Hueneme, CA, Jan 1967.

Table 1. Index to Treatment Performance Tables

Treatment	Year Installed	Table No.
Creosote:		
Marine Grade	1963, 1964	3
70-30 Creosote-Coal Tar	1963, 1966	3
Other Single Treatments:		
Copper oxinate	1965	4
Basic zinc sulfate	1966	4
Ammoniacal copper arsenate	1966	4
Chromated copper arsenate	1966	4
Dual Treatments With Creosote and:		
Ammoniacal copper arsenate	1963, 1966	5
Chromated copper arsenate	1963	5
Phenylmercuric oleate	1963	5
Chlordane	1964	5
Copper naphthenate	1964	5
Tributyltin oxide	1964	5
Copper-nickel sheathing	1966	5
Other Dual Treatments:		
Copper oxinate & tributyltin oxide	1965	6
Copper oxinate & Victoria green base	1965	6
Chlordane & tributyltin oxide	1965	6
Chromated copper arsenate & tributyltin oxide	1966	6
Basic zinc sulfate & tributyltin oxide	1966	6
Ammoniacal copper arsenate & tributyltin oxide	1966	6
Copper sulfate & tributyltin oxide	1966	6
Multiple Treatments With Creosote and:		
Copper naphthenate & tributyltin oxide	1964	7
Tributyltin oxide & dieldrin	1964	7
Copper oxinate & Victoria green base	1965	7

Table 2. Diver Estimates of Damage to Selected Piling Compared with Actual Damage Determined After Removal in 1982

Piling Treatment	Cross-Sectional Area Loss %	
	Actual	Estimated
Creosote & TBTO & dieldrin	0	2
Basic zinc sulfate	2	2
Ammoniacal copper arsenate	11	18
30% Copper naphthenate	13	9
Creosote & copper oxinate and Victoria green base	31	8
Ammoniacal copper arsenate	42	30
Ammoniacal copper arsenate	50	11
15% Copper naphthenate	65	28
Copper sulfate and TBTO	65	45

Table 3. Performances of Creosote-Treated Piling

Treatment	Year Driven	Average Retention (pcf)	Number of Piles and Species	Average Years Exposure Until X-Sectional Loss Greater Than		
				5%	15%	50%
Marine grade creosote	1963	17.2	5 DF	19.5	23.4	(2) ^b
	1964	18.6	4 DF	10.5	11.0	15.3
	1964	32.9	6 DF	19.2	(3) ^a	(2) ^b
70-30 creosote-coal tar	1963	11.1	3 DF	21.0	(1) ^a	(2) ^b
	1963	13.5	2 SP	14.0	17.0	21.0
	1966	31.7	6 DF	16.8	(3) ^a	(2) ^b

a = number piles in 1989 with X-sectional loss greater than 5% but not greater than 15%

b = number piles in 1989 with X-sectional loss greater than 15% but not greater than 50%

Table 4. Performance of Piling With Single Treatments
Other than Creosote

Treatment	Year Driven	Average Retention (pcf)	Number of Piles and Species	Average Years Exposure Until X-Sectional Loss Greater Than		
				5%	15%	50%
Copper oxinate	1965	0.49	6 DF	16.7	19.0	(5) ^d
	1965	0.87	6 DF	18.2	(1) ^a	(3) ^d
Basic zinc sulfate	1966	2.77	6 DF ^c	19.2	(2) ^a	(3) ^b
Ammoniacal copper arsenate	1966	0.51	6 DF ^d	15.5	17.0	19.7
Chromated copper arsenate (Type B)	1966	0.50	6 DF	9.7	11.5	12.3

a = number piles in 1989 with X-sectional loss greater than 5% but not greater than 15%

b = number piles in 1989 with X-sectional loss greater than 15% but not greater than 50%

c = 1 pile removed in 1982

d = 3 piles removed in 1982

Table 5. Performances of Piling Treated With Creosote and One Other Additive

Treatment	Year Driven	Average Retention (pcf)	Number of Piles and Species	Average Years Exposure Until X-Sectional Loss Greater Than		
				5%	15%	50%
Creosote & ammoniacal copper arsenate	1963	16.2	3 DF	24.3	(2) ^b	(1) ^c
	1966	19.6	6 DF	(1) ^a	(5) ^b	(0) ^c
		0.51				
Creosote & chromated copper arsenate	1963	8.4	3 DF	15.0	16.7	19.3
		1.7				
	1963	23.2	3 ^d SP	23.0	(2) ^b	(0) ^c
Creosote & phenyl-mercuric oleate (1%)		2.7				
	1963	20.7	2 DF	23.0	(1) ^b	(1) ^c
		24.1	2 SP	18.0	20.0	(1) ^c
Creosote & phenyl-mercuric oleate (5%)	1963	13.0	1 DF	19.0	20.0	22.0
	1963	27.5	2 SP	18.5	21.0	(1) ^c
Creosote & copper-nickel sheathing	1963	24.3	1 DF	(1) ^a	(0) ^b	(0) ^c
Creosote & chlordane	1964	26.3	6 ^e DF	21.0	(4) ^b	(0) ^c
		0.3				
	1964	28.5	6 DF	(2) ^a	(4) ^b	(0) ^c
		0.7				
Creosote & copper naphthenate	1964	28.6	6 DF	(4) ^a	(2) ^b	(0) ^c
		1.4				
	1964	10.9	6 DF	16.5	17.7	(1) ^c
		0.09 ^g				
Creosote & tributyltin oxide	1964	9.4	6 ^e DF	14.7	15.8	18.0
		0.15 ^g				
	1964	8.3	6 ^f DF	16.2	(1) ^b	(1) ^c
		0.27 ^g				
Creosote & tributyltin oxide	1964	13.9	5 DF	11.0	12.2	14.4
		0.14				

a = number piles in 1989 with X-sectional loss 5% or less

b = number piles in 1989 with X-sectional loss greater than 5% but not greater than 15%

c = number piles in 1989 with X-sectional loss greater than 15% but not greater than 50%

d = 1 pile destroyed by impact in 1978

e = 2 piles removed in 1982

f = 1 pile removed in 1982

g = as metallic copper

Table 6. Performances of Dual-Treated Piling Without Creosote

Treatment	Year Driven	Average Retention (pcf)	Number of Piles and Species	Average Years Exposure Until X-Sectional Loss Greater Than		
				5%	15%	50%
Copper oxinate & tributyltin oxide	1965	0.25 0.25	6 DF	13.3	15.5	18.2
Copper oxinate & Victoria green base	1965	0.69 0.26	5 DF	16.2	19.0	(2) ^c
Chlordane & tributyltin oxide	1965	1.3 0.27	6 DF	21.2	(4) ^b	(2) ^c
	1965	1.5 0.62	6 DF	(1) ^a	(5) ^b	(0) ^c
Ammoniacal copper arsenate & tributyltin oxide	1966	0.51 0.11	6 DF	(1) ^a	(2) ^b	(3) ^c
Chromated copper arsenate & tributyltin oxide	1966	0.50 0.13	6 DF	16.3	18.0	19.5
Basic zinc sulfate & tributyltin oxide	1966	2.66 0.09	6 ^a DF	(2) ^a	(3) ^b	(0) ^c
Copper sulfate & tributyltin oxide	1966	0.03 0.20	6 DF	12.5	14.5	16.0
	1966	0.06 0.19	6 ^a DF	12.3	14.8	17.4

a = number piles in 1989 with X-sectional loss 5% or less

b = number piles in 1989 with X-sectional loss greater than 5% but not greater than 15%

c = number piles in 1989 with X-sectional loss greater than 15% but not greater than 50%

d = 1 pile removed in 1982

Table 7. Performances of Multi-Treated Piling With Creosote

Treatment	Year Driven	Average Retention (pcf)	Number of Piles and Species	Average Years Exposure Until X-Sectional Loss Greater Than		
				5%	15%	50%
Creosote & copper naphthenate & tributyltin oxide	1964	8.6	6 DF	15.7	(1) ^b	(1) ^b
		0.07				
	1964	0.08	6 DF	13.0	15.0	16.8
		14.8				
Creosote & tributyltin oxide & dieldrin	1964	0.23	6 DF	(5) ^a	(0) ^b	(0) ^c
		0.15				
	1964	17.4	6 DF	(5) ^a	(0) ^b	(0) ^c
		0.18				
Creosote & copper oxinate & Victoria green base	1965	0.18	6 DF	12.8	15.0	17.2
		9.2				
	1965	0.27	6 DF	15.5	(1) ^b	(0) ^c
		0.09				
		24.7				
		0.25				
		0.08				

a = number piles in 1989 with X-sectional loss 5% or less

b = number piles in 1989 with X-sectional loss greater than 5% but not greater than 15%

c = number piles in 1989 with X-sectional loss greater than 15% but not greater than 50%

d = 1 pile removed in 1982




Figure 1. Location of experimental piling.

DISTRIBUTION LIST

ADMINSUPU PWO, Bahrain
 CBC Code 10, Davisville, RI; Code 15, Port Hueneme, CA; Library, Davisville, RI; PWO (Code 80), Port Hueneme, CA; PWO, Davisville, RI; Tech Library, Gulfport, MS
 CINCPACFLT Code 442, Pearl Harbor, HI
 CINCUSNAVEUR London, UK
 CNA Tech Library, Alexandria, VA
 CNO DCNO, Logs, OP-424C, Washington, DC
 COMCBLANT Code S3T, Norfolk, VA
 COMFAIR Med, SCE, Naples, Italy
 COMFLEACT PWO, Kadena, Japan; PWO, Sasebo, Japan; SCE, Yokosuka, Japan
 COMNAVACT PWO, London, UK
 COMNAVRESFOR Code 08, New Orleans, LA
 COMNAVSUPFORANTARCTICA DET, PWO, Christchurch, NZ
 COMOCEANSYS Lant, Code N9, Norfolk, VA
 COMSUBPAC SCE, Pearl Harbor, HI
 COMTRA Lant, SCE, Norfolk, VA
 DIRSSP Tech Lib, Washington, DC
 DTIC Alexandria, VA
 DTRCEN Code 4120, Annapolis, MD
 EFA-SW Code 101.1, San Diego, CA
 MARCORBASE Maint Offr, Camp Pendleton, CA; PAC, PWO, Camp Butler, JA; PWO, Camp Lejeune, NC; PWO, Camp Pendleton, CA; Pac, FE, Camp Butler, JA
 MCAS Code 6EDD, Iwakuni, Japan; PWO, Kaneohe Bay, HI
 MCRD PWO, San Diego, CA
 MCRDAC M & L Div Quantico, VA
 NAF AROICC, Midway Island
 NALF OIC, San Diego, CA
 NAS Chase Fld, Code 18300, Beeville, TX; Code 110, Adak, AK; Code 15, Alameda, CA; Code 18700, Brunswick, ME; Code 70, South Weymouth, MA; Code 725, Marietta, GA; Code 8, Patuxent River, MD; Code 83, Patuxent River, MD; Fac Mgmt Offc, Alameda, CA; NI, Code 183, San Diego, CA; PW Engrg (Branson), Patuxent River, MD; PWO (Code 182) Bermuda; PWO, Adak, AK; PWO, Keflavik, Iceland; PWO, Key West, FL; PWO, Kingsville TX; PWO, Moffett Field, CA; PWO, New Orleans, LA; PWO, South Weymouth, MA; SCE, Cubi Point, RP
 NAVAIRENGCEN Code 182, Lakehurst, NJ; PWO, Lakehurst, NJ
 NAVAIRTESTCEN PWO, Patuxent River, MD
 NAVAVNDEPOT Code 61000, Pensacola, FL
 NAVCAMS PWO, Norfolk, VA
 NAVCHAPGRU Code 50, Williamsburg, VA
 NAVCOASTSYSCEN Code 2360, Panama City, FL; Code 423, Panama City, FL; Code 715 (J. Mittleman) Panama City, FL; PWO (Code 740), Panama City, FL; Tech Library, Panama City, FL
 NAVCOMMSTA PWO, Exmouth, Australia
 NAVCONSTRACEN Code D2A, Port Hueneme, CA; Code T12, Gulfport, MS
 NAVELEXCEN DET, OIC, Winter Harbor, ME
 NAVEODTEHCEN Tech Library, Indian Head, MD
 NAVFAC Centerville Bch, PWO, Ferndale, CA; N62, Argentia, NF; PWO, Oak Harbor, WA
 NAVFACENGCOM Code 00, Alexandria, VA; Code 03, Alexandria, VA; Code 03T (Essoglou), Alexandria, VA; Code 04A, Alexandria, VA; Code 04A1, Alexandria, VA; Code 04A1D, Alexandria, VA; Code 04A3, Alexandria, VA; Code 04A3C, Alexandria, VA; Code 04A4E, Alexandria, VA; Code 0631, Alexandria, VA; Code 07, Alexandria, VA; Code 09M124 (Lib), Alexandria, VA; Code 163, Alexandria, VA
 NAVFACENGCOM - CHES DIV. FPO-1PL, Washington, DC
 NAVFACENGCOM - LANT DIV. Br Ofc, Dir, Naples, Italy; Code 1112, Norfolk, VA; Library, Norfolk, VA
 NAVFACENGCOM - NORTH DIV. Code 04, Philadelphia, PA; Code 04AL, Philadelphia, PA; Code 11, Philadelphia, PA; Code 111, Philadelphia, PA; Code 202.2, Philadelphia, PA; Code 408AF, Philadelphia, PA
 NAVFACENGCOM - PAC DIV. Code 09P, Pearl Harbor, HI; Code 2011, Pearl Harbor, HI; Library, Pearl Harbor, HI
 NAVFACENGCOM - SOUTH DIV. Code 04A3, Charleston, SC; Code 406, Charleston, SC; Library, Charleston, SC
 NAVFACENGCOM - WEST DIV. Code 04A2.2 (Lib), San Bruno, CA; Code 04B, San Bruno, CA; Code 102, San Bruno, CA; Code 2031C, San Bruno, CA; Code 406.2 (Smith), San Bruno, CA; Code 408.2 (Jeung) San Bruno, CA; Pac NW Br Offc, Code C/42, Silverdale, WA; Pac NW Br Offc, Code C/50, Silverdale, WA

NAVFACENGCOM CONTRACTS Code 460, Portsmouth, VA; Code 923, Everett, WA; DROICC, Rota, Spain; Earle, ROICC, Colts Neck, NJ; North Bay, Code 1042.AA, Vallejo, CA; OICC, Guam; OICC/ROICC, Norfolk, VA; OICC/ROICC, Virginia Beach, VA; ROICC (Code 495), Portsmouth, VA; ROICC, Corpus Christi, TX; ROICC, Crane, IN; ROICC, Keflavik, Iceland; ROICC, Point Mugu, CA; SW Pac, OICC, Manila, RP
 NAVFUEL DET OIC, Yokohama, Japan
 NAVHOSP Hd, Fac Mgmt, Camp Pendleton, CA; SCE, Newport, RI; SCE, Pensacola, FL
 NAVMAG Code 10, Lualualei, HI; SCE, Subic Bay, RP
 NAVMEDCOM NWREG, Fac Engr, PWD, Oakland, CA; SCE, Jacksonville, FL
 NAVOCEANO Library, Bay St Louis, MS
 NAVOCEANSYSCEN Code 94, San Diego, CA
 NAVPETOFF Code 40, Alexandria, VA
 NAVPGSCOL Code 68 (C.S. Wu), Monterey, CA; Code 68WY (Wyland), Monterey, CA
 NAVPHIBASE PWO, Norfolk, VA; SCE, San Diego, CA
 NAVSEACENPAC Code 32, San Diego, CA
 NAVSEASYSKOM Code 05M3, Washington, DC; Code 56W23 (J Coon), Washington, DC; Code PMS296L22 (J Rekas), Washington, DC
 NAVSECGRUACT PWO, Adak, AK
 NAVSHIPREPAC Library, Guam; SCE, Subic Bay, RP; SCE, Yokosuka, Japan
 NAVSHIPYD Carr Inlet Acoustic Range, Bremerton, WA; Code 134, Pearl Harbor, HI; Code 202.4, Long Beach, CA; Code 202.5 (Library), Bremerton, WA; Code 308.3, Pearl Harbor, HI; Code 420, Long Beach, CA; Code 440, Portsmouth, NH; Code 443, Bremerton, WA; Code 903, Long Beach, CA; Library, Portsmouth, NH; Mare Island, Code 106.4, Vallejo, CA; Mare Island, Code 202.13, Vallejo, CA; Mare Island, Code 280, Vallejo, CA; Mare Island, Code 401, Vallejo, CA; Mare Island, Code 421, Vallejo, CA; Mare Island, Code 457, Vallejo, CA; Mare Island, PWO, Vallejo, CA; Norfolk, Code 380, Portsmouth, VA; Norfolk, Code 440, Portsmouth, VA; Norfolk, Code 450-HD, Portsmouth, VA; PWO, Bremerton, WA
 NAVSTA A. Sugihara, Pearl Harbor, HI; CO, Long Beach, CA; CO, Roosevelt Roads, PR; Code 423, FPBO Guantanamo Bay; Dir, Engr Div, PWD, Guantanamo Bay, Cuba; Engr Div, PWD, Rodman, Panama Canal; Engrg Dir, PWD, Rota, Spain; PWO, Guantanamo Bay, Cuba; PWO, Mayport, FL; SCE, San Diego, CA; SCE, Subic Bay, RP; WC 93, Guantanamo Bay, Cuba
 NAVSUPPACT PWO, Holy Loch, UK
 NAVSUPPFAC Contract Admin Tech Library, Diego Garcia
 NAVSUPPO Sec Offr, La Maddalena, Italy
 NAVSUPSYSCOM Code 0622, Washington, DC
 NAVSWC Code E211 (Miller), Dahlgren, VA; Code W42 (GD Haga), Dahlgren, VA; DET, White Oak Lab, PWO, Silver Spring, MD; PWO, Dahlgren, VA; W41C1, Dahlgren, VA
 NAVWARCOL Code 24, Newport, RI
 NAVWPNSTA Code 092, Concord, CA; Code 093, Yorktown, VA; Dir, Maint Control, PWD, Concord, CA; Earle, Code 092, Colts Neck, NJ; Earle, PWO (Code 09B), Colts Neck, NJ; PWO, Charleston, SC; PWO, Seal Beach, CA; PWO, Yorktown, VA
 NAVWPNSUPPCEN PWO, Crane, IN
 NETC Code 42, Newport, RI; PWO, Newport, RI
 NCR 20, CO
 NETPMSA Tech Library, Pensacola, FL
 NMCB 3, Ops Offr; 40, CO; 5, Ops Dept
 NORDA Code 1121SP, Bay St. Louis, MS; Code 440, Bay St. Louis, MS
 NRL Code 6127 (Bultman), Washington, DC
 NSC Cheatham Annex, PWO, Williamsburg, VA; Code 43, Oakland, CA; Code 54.1, Norfolk, VA; Code 700, Norfolk, VA; SCE, Charleston, SC; SCE, Norfolk, VA
 NSD SCE, Subic Bay, RP
 NUSC DET AUTEC Andros Is, Asst Wpns Offr, Bahamas; Code 2143 (Varley), New London, CT; Code 44 (RS Munn), New London, CT; Code TA131, New London, CT
 OCNR Code 1121 (EA Silva), Arlington, VA
 PACMISRANFAC HI Area, PWO, Kekaha, HI
 PHIBCB 1, CO, San Diego, CA; 1, P&E, San Diego, CA; 2, CO, Norfolk, VA
 PMTC Code 5041, Point Mugu, CA
 PWC Code 10, Oakland, CA; Code 101 (Library), Oakland, CA; Code 110, Oakland, CA; Code 123-C, San Diego, CA; Code 30, Norfolk, VA; Code 400, Guam, Mariana Islands; Code 400, Oakland, CA; Code 400, Pearl Harbor, HI; Code 400, San Diego, CA; Code 412, San Diego, CA; Code 420, Oakland, CA; Code 420B (Waid), Subic Bay, RP; Code 421 (Kaya), Pearl Harbor, HI; Code 421 (Quin), San Diego, CA; Code 421 (Reynolds), San Diego, CA; Code 422, San Diego, CA; Code 423, San Diego, CA; Code 424, Norfolk, VA; Code 430 (Kyi), Pearl Harbor, HI

PWC Code 430 (Kyi), Pearl Harbor, HI
PWC Code 50, Pensacola, FL; Code 500, Norfolk, VA; Code 500, Oakland, CA; Code 505A, Oakland, CA;
Code 590, San Diego, CA; Code 612, Pearl Harbor, HI; Code 700, San Diego, CA; Library (Code 134),
Pearl Harbor, HI; Library, Guam, Mariana Islands; Library, Norfolk, VA; Library, Pensacola, FL; Library,
Yokosuka, Japan; Tech Library, Subic Bay, RP
SUBASE Bangor, PWO (Code 8323), Bremerton, WA; SCE, Pearl Harbor, HI
SUPSHIP Tech Library, Newport News, VA
UCT ONE, CO, Norfolk, VA; TWO, CO, Port Hueneme, CA
USNA Ocean Engrg Dept (McCormick), Annapolis, MD; PWO, Annapolis, MD
USS USS FULTON, Code W-3
UNIVERSITY OF CALIFORNIA CE Dept (Fourney), Los Angeles, CA
CORRIGAN, LCDR S. USN, CEC, Stanford, CA

INSTRUCTIONS

The Naval Civil Engineering Laboratory has revised its primary distribution lists. The bottom of the label on the reverse side has several numbers listed. These numbers correspond to numbers assigned to the list of Subject Categories. Numbers on the label corresponding to those on the list indicate the subject category and type of documents you are presently receiving. If you are satisfied, throw this card away (or file it for later reference).

If you want to change what you are presently receiving:

- Delete - mark off number on bottom of label.
- Add - circle number on list.
- Remove my name from all your lists - check box on list.
- Change my address - line out incorrect line and write in correction (DO NOT REMOVE LABEL).
- Number of copies should be entered after the title of the subject categories you select.

Fold on line below and drop in the mail.

Note: Numbers on label but not listed on questionnaire are for NCEL use only. please ignore them.

Fold on line and staple.

DEPARTMENT OF THE NAVY

Naval Civil Engineering Laboratory
Port Hueneme, CA 93043-5003

Official Business
Penalty for Private Use, \$300

BUSINESS REPLY CARD

FIRST CLASS PERMIT NO. 12503 WASH D.C.
POSTAGE WILL BE PAID BY ADDRESSEE

NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES

Commanding Officer
Code L34
Naval Civil Engineering Laboratory
Port Hueneme, California 93043-5003

DISTRIBUTION QUESTIONNAIRE

The Naval Civil Engineering Laboratory is revising its Primary distribution lists.

SUBJECT CATEGORIES

- 1 SHORE FACILITIES
- 2 Construction methods and materials (including corrosion control, coatings)
- 3 Waterfront structures (maintenance/deterioration, control)
- 4 Utilities (including power conditioning)
- 5 Explosives safety
- 6 Aviation Engineering Test Facilities
- 7 Fire prevention and control
- 8 Antenna technology
- 9 Structural analysis and design (including numerical and computer techniques)
- 10 Protective construction (including hardened shelters, shock and vibration studies)
- 11 Soil/rock mechanics
- 14 Airfields and pavements
- 15 ADVANCED BASE AND AMPHIBIOUS FACILITIES
- 16 Base facilities (including shelters, power generation, water supplies)
- 17 Expedient roads/airfields/bridges
- 18 Amphibious operations (including breakwaters, wave forces)
- 19 Over-the-Beach operations (including containerization, material transfer, lighterage and cranes)
- 20 POL storage, transfer and distribution

TYPES OF DOCUMENTS

- 85 Techdata Sheets
- 86 Technical Reports and Technical Notes
- 83 Table of Contents & Index to TDS

28 ENERGY/POWER GENERATION

- 29 Thermal conservation (thermal engineering of buildings, HVAC systems, energy loss measurement, power generation)
- 30 Controls and electrical conservation (electrical systems, energy monitoring and control systems)
- 31 Fuel flexibility (liquid fuels, coal utilization, energy from solid waste)
- 32 Alternate energy source (geothermal power, photovoltaic power systems, solar systems, wind systems, energy storage systems)
- 33 Site data and systems integration (energy resource data, energy consumption data, integrating energy systems)
- 34 ENVIRONMENTAL PROTECTION
- 35 Hazardous waste minimization
- 36 Restoration of installations (hazardous waste)
- 37 Waste water management and sanitary engineering
- 38 Oil pollution removal and recovery
- 39 Air pollution

44 OCEAN ENGINEERING

- 45 Seafloor soils and foundations
- 46 Seafloor construction systems and operations (including diver and manipulator tools)
- 47 Undersea structures and materials
- 48 Anchors and moorings
- 49 Undersea power systems, electromechanical cables, and connectors
- 50 Pressure vessel facilities
- 51 Physical environment (including site surveying)
- 52 Ocean-based concrete structures
- 54 Undersea cable dynamics

- 82 NCEL Guides & Abstracts
- 91 Physical Security

☐ None -
remove my name