

**NAVAL POSTGRADUATE SCHOOL  
Monterey, California**



**THESIS**

**A COST ANALYSIS OF THE DECISION TO  
CANNIBALIZE MAJOR COMPONENTS OF THE NAVY'S  
H-60 HELICOPTERS AT THE OPERATIONAL LEVEL**

by

Danny E. Kowalski

June 2000

Thesis Advisors:

Donald Eaton  
Shu S. Liao

**Approved for Public release; Distribution is Unlimited**

**DMC QUALITY INSPECTED 4**

20000724 035

# REPORT DOCUMENTATION PAGE

Form Approved  
OMB No. 0704-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instruction, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188) Washington DC 20503.

1. AGENCY USE ONLY (Leave blank)

2. REPORT DATE  
June 2000

3. REPORT TYPE AND DATES COVERED  
Master's Thesis

4. TITLE AND SUBTITLE : A COST ANALYSIS OF THE DECISION TO  
CANNIBALIZE MAJOR COMPONENTS OF THE NAVY'S H-60 HELICOPTERS  
AT THE OPERATIONAL LEVEL

5. FUNDING NUMBERS

6. AUTHOR(S)  
Kowalski, Danny E.

7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES)  
Naval Postgraduate School  
Monterey, CA 93943-5000

8. PERFORMING  
ORGANIZATION REPORT  
NUMBER

9. SPONSORING / MONITORING AGENCY NAME(S) AND ADDRESS(ES)  
N/A

10. SPONSORING /  
MONITORING  
AGENCY REPORT  
NUMBER

11. SUPPLEMENTARY NOTES The views expressed in this thesis are those of the author and do not reflect the official policy or position of the Department of Defense or the U.S. Government.

12a. DISTRIBUTION / AVAILABILITY STATEMENT  
Approved for public release; distribution is unlimited.

12b. DISTRIBUTION CODE

13. ABSTRACT Cannibalization is a technique, sanctioned by the Navy, for maintenance managers to optimize aircraft availability by circumventing a slow or inadequate logistics support system. Maintenance managers often make a decision to cannibalize without considering the total cost of their decision. This thesis examines the costs incurred by an operational H-60 helicopter squadron to cannibalize major components and addresses the impact of cannibalization on the mean time between failure for the cannibalized components. The costs to cannibalize a T700-GE-401C engine, a tail rotor blade and an auxiliary power electronic control unit were calculated by assigning a dollar value to the increased manpower, consumables and flight time that could have been avoided if cannibalization were not used. The units cannibalized in 1996 were tracked by serial number through 1999 to compare their mean time between failure to similar non-cannibalized units tracked for the same period. The findings were that cannibalization considerably decreases the time between failure for cannibalized components which can have far-reaching effects on the size and costs of the Navy's inventory of spare parts. The increased manpower, consumables and flight time required has a significant impact on an operational squadron's workforce and budget.

14. SUBJECT TERMS  
Cannibalization, Aircraft Maintenance, Cost Analysis

15. NUMBER  
OF PAGES  
88

16. PRICE  
CODE

17. SECURITY  
CLASSIFICATION OF REPORT  
Unclassified

18. SECURITY CLASSIFICATION  
OF THIS PAGE  
Unclassified

19. SECURITY  
CLASSIFICATION OF  
ABSTRACT  
Unclassified

20.  
LIMITATION  
OF ABSTRACT  
UL

**THIS PAGE INTENTIONALLY LEFT BLANK**

**Approved for public release; distribution is unlimited**

**A COST ANALYSIS OF THE DECISION TO CANNIBALIZE MAJOR  
COMPONENTS OF THE NAVY'S H-60 HELICOPTERS AT THE  
OPERATIONAL LEVEL**


Danny E. Kowalski  
Commander, United States Navy Reserve  
M.B.A., University of Phoenix, 1996  
B.S., United States Naval Academy, 1982

Submitted in partial fulfillment of the  
requirements for the degree of

**MASTER OF SCIENCE IN MANAGEMENT**


from the

**NAVAL POSTGRADUATE SCHOOL  
June 2000**

Author: 

Danny E. Kowalski


Approved By:



Donald Eaton, Thesis Advisor



Shu S. Liao, Thesis Advisor



Ruben T. Harris, Chairman  
Department of Systems Management

**THIS PAGE INTENTIONALLY LEFT BLANK**

## **ABSTRACT**

### **A COST ANALYSIS OF THE DECISION TO CANNIBALIZE MAJOR COMPONENTS OF THE NAVY'S H-60 HELICOPTERS AT THE OPERATIONAL LEVEL**

Cannibalization is a technique, sanctioned by the Navy, for maintenance managers to optimize aircraft availability by circumventing a slow or inadequate logistics support system. Maintenance managers often make a decision to cannibalize without considering the total cost of their decision. This thesis examines the costs incurred by an operational H-60 helicopter squadron to cannibalize major components and addresses the impact of cannibalization on the mean time between failure for the cannibalized components. The costs to cannibalize a T700-GE-401C engine, a tail rotor blade and an auxiliary power electronic control unit were calculated by assigning a dollar value to the increased manpower, consumables and flight time that could have been avoided if cannibalization were not used. The units cannibalized in 1996 were tracked by serial number through 1999 to compare their mean time between failure to similar non-cannibalized units tracked for the same period. The findings were that cannibalization considerably decreases the time between failure for cannibalized components which can have far-reaching effects on the size and costs of the Navy's inventory of spare parts. The increased manpower, consumables and flight time required has a significant impact on an operational squadron's workforce and budget.

**THIS PAGE INTENTIONALLY LEFT BLANK**

## TABLE OF CONTENTS

|      |  |    |
|------|--|----|
| I.   | INTRODUCTION.....  | 1  |
| A.   | PURPOSE .....  | 1  |
| B.   | BACKGROUND .....   | 2  |
| 1.   | The Helicopter .....   | 2  |
| 2.   | Cannibalization .....  | 2  |
| 3.   | Costs Associated with Cannibalization .....                    | 5  |
| 4.   | Research Questions .....                                       | 6  |
| II.  | LITERATURE REVIEW.....   | 7  |
| A.   | INTRODUCTION .....   | 7  |
| B.   | CANNIBALIZATION POLICY .....                                   | 7  |
| C.   | WHY SQUADRONS CANNIBALIZE .....                                | 9  |
| D.   | SUMMARY.....   | 14 |
| III. | DATA COLLECTION .....  | 17 |
| A.   | INTRODUCTION .....   | 17 |
| B.   | RESEARCH DESIGN .....  | 17 |
| C.   | RESEARCH DESIGN STRATEGY .....                                 | 20 |
| D.   | RESEARCH LIMITATION.....                                       | 21 |
| IV.  | DATA PRESENTATION AND ANALYSIS .....                           | 23 |
| A.   | INTRODUCTION .....   | 23 |
| B.   | TIME BETWEEN FAILURE RATE AND FAILURE RATE<br>COMPARISON ..... | 23 |

|    |  |    |
|----|--|----|
| 1. | T700-GE-401C Turbo Shaft Engine .....  | 23 |
| 2. | Tail Rotor Blades .....  | 25 |
| 3. | Auxiliary Power Electronic Control Unit .....  | 26 |
| C. | ORGANIZATIONAL COST ASSOCIATED WITH MAJOR COMPONENT CANNIBALIZATION .....              | 28 |
| 1. | T700-GE-401C Turbo Shaft Engine .....  | 28 |
| 2. | Tail Rotor Blade .....   | 32 |
| 3. | Auxiliary Power Electronic Control Unit .....  | 33 |
| D. | SUMMARY .....  | 35 |
| V. | CONCLUSIONS AND RECOMMENDATIONS .....  | 37 |
| A. | INTRODUCTION .....   | 37 |
| B. | CONCLUSION OF DATA ANALYSIS .....  | 37 |
| C. | RESEARCH QUESTIONS ANSWERED .....  | 39 |
| 1. | What are the Total Costs to Cannibalize Major Components on the H-60 Helicopter? ..... | 39 |
| a. | Direct Costs .....   | 40 |
| b. | Indirect Costs .....   | 41 |
| c. | Intangible Cost .....  | 42 |
| 2. | Why Do Squadrons Cannibalize? .....  | 41 |
| 3. | Does Cannibalization Reduce the Installed Life of the Cannibalized Component? .....    | 42 |
| 4. | What is the Cost of the Increased Maintenance Associated with Cannibalization .....    | 42 |
| C. | EFFECTS OF LIMITATIONS .....   | 43 |
| D. | RECOMMENDATIONS .....  | 43 |

|   |    |
|---|----|
| E. RECOMMENDATION FOR FURTHER STUDY .....   | 44 |
| APPENDIX A. T700-GE-401C ENGINES THAT RECEIVED UNSCHEDULED<br>MAINTENANCE IN 1996 .....                     | 47 |
| APPENDIX B. TAIL ROTOR BLADES THAT RECEIVED UNSCHEDULED<br>MAINTENANCE IN 1996 .....                        | 51 |
| APPENDIX C. AUXILLARY POWER ELECTRONIC CONTROL UNITS<br>THAT RECEIVED UNSCHEDULED MAINTENANCE IN 1996 ..... | 57 |
| APPENDIX D. T700-GE-401C CANNIBALIZED 1995-1999.....  | 59 |
| APPENDIX E. TAIL ROTOR BLADES CANNIBALIZED 1995-1999.....   | 63 |
| APPENDIX F. AUXILIARY POWER ELECTRONIC CONTROL UNITS<br>CANNIBALIZED 1995-1999 .....                        | 69 |
| LIST OF REFERENCES.....   | 71 |
| INTIAL DISTRIBUTION LIST.....   | 73 |

**THIS PAGE INTENTIONALLY LEFT BLANK**

## LIST OF FIGURES

|      |   |    |
|------|---|----|
| 2-1. | H-60 Cannibalizations per 100 Flight Hours and Percent<br>Supply Material Availability..... | 10 |
| 2-2. | H-60 Cannibalizations per 100 Flight Hours and Mission Capable rates .....                  | 12 |

**THIS PAGE INTENTIONALLY LEFT BLANK**

## LIST OF TABLES

|      |   |    |
|------|---|----|
| 1-1. | Cannibalization Rates for Navy Aircraft and H-60 Helicopter .....   | 4  |
| 1-2. | Change in H-60 Annual Flight Hours, Cannibalization rates<br>and DMMH/FH for FY95-FY99.....                                       | 5  |
| 2-1. | Supply Response Time .....  | 13 |
| 3-1. | Military Reimbursement Rates .....  | 18 |
| 3-2. | Hourly Labor Cost for T700-GE-401C Engine 1997-1999.....  | 19 |
| 3-3. | Annual Average Cost per Flight Hour H-60 Helicopter .....   | 20 |
| 4-1. | Failure Rates and Times Comparison Between Cannibalized and<br>Non-cannibalized T700-GE-401C .....                                | 24 |
| 4-2. | Failure Rates and Times Comparison Between Cannibalized and<br>Non-cannibalized H-60 Tail Rotor Blades.....                       | 25 |
| 4-3. | Failure Rates and Time Comparison Between Cannibalized and<br>Non-cannibalized H-60 Auxiliary Power Electronic Control Units..... | 26 |
| 4-4. | T700-GE-401C Consumables.....   | 29 |
| 4-5. | Tail Rotor Blade Consumables .....  | 31 |
| 4-6. | Auxiliary Power Electronic Control Unit Consumables .....   | 33 |

**THIS PAGE INTENTIONALLY LEFT BLANK**

## I. INTRODUCTION

### A. PURPOSE

The purpose of this thesis is to determine the total cost to a Navy operational H-60 Seahawk Helicopter Squadron when cannibalization is used as a technique to increase the aircraft mission readiness. By identifying and quantifying the total cost of cannibalization, squadron commanders will be able to make informed decisions to efficiently manage their resources. Specifically, this thesis will focus on the cannibalization practices involved with major components of the H-60. Archival maintenance records will be examined to calculate the additional man-hours required to cannibalize a major component from one aircraft for installation in another. A dollar value will be assigned to the man-hours incurred for the increased maintenance actions that would not have been required if the component was obtained through the regular Navy supply channels. Standard military pay equivalent charts will be used to assign a direct labor cost to the cannibalization action based on the number and pay grade of technicians involved.

This thesis will also determine if cannibalization results in an additional cost to the Navy through the degradation of the installed service life of a cannibalized component as compared to a component that remains installed in the same aircraft for its entire useful life. Three dissimilar high value H-60 components, frequently cannibalized over the past five years, will be analyzed to determine if a relationship exist between cannibalization and reduced installed useful life. Service life, maintenance and supply data will be obtained from Naval Aviation Logistics Data Analysis (NALDA) databases

and reports. A base year will be selected to determine if a relationship exist between cannibalization and service life.

## **B. BACKGROUND**

### **1. The H-60 Helicopter**

The H-60 Seahawk is a twin-engine multipurpose helicopter, manufactured by the United Technologies Corporation, Sikorsky Aircraft Division. Its missions include anti-submarine warfare, search and rescue, drug interdiction, anti-ship warfare, cargo lift, and special operations. The Navy's SH-60B Seahawk is an airborne platform based aboard cruisers, destroyers, and frigates. The helicopter deploys sonobouys and torpedoes in an anti-submarine role and extends the range of the ship's radar capabilities. The Navy's SH-60F is carrier-based and deploys a dipping sonar. The SH-60B Light Airborne Multi-Purpose System (LAMPS) MK III Block II/multi-mission helicopter upgrade will provide the Navy with a multi-mission platform capable of conducting undersea and surface warfare for the next 20-25 years.

### **2. Cannibalization**

Cannibalization in Naval Aviation refers to the practice of physically removing a fully functioning part or component from one aircraft for installation in place of a similar defective part or component in another aircraft. In an effort to ensure that the maximum possible number of aircraft are maintained in a fully mission capable status, maintenance managers frequently use cannibalization under the following two scenarios with little regard to the total cost incurred by their decision to cannibalize. First, cannibalization is used during high-tempo operations when systems fail and must be immediately repaired to avoid jeopardizing the mission. Second, when replacement parts are not readily

available through the Navy's normal supply channels, maintenance managers will sacrifice one squadron aircraft so that its parts will be available to repair other squadron aircraft. This practice tends to further exacerbate the supply deficiencies by masking the true demand and urgency for spare parts. Through cannibalization, Squadron Commanders are able to circumvent a slow or inadequately stocked supply system and optimize the number of mission capable aircraft available to meet short-term mission requirements and achieve readiness-reporting goals.

Although cannibalization can be an effect tool for successfully achieving short-term mission goals, the long-term effects tend to be negative. The Navy clearly discourages dependence on cannibalization and advocates a reduction in its use. As stated in The Naval Aviation Maintenance Program OPNAVINST 4790.2:

Cannibalization, with few exceptions, is a manifestation of a logistic or maintenance support system failure. Cannibalization has a tendency to adversely impact morale and worsen a non-mission capable supply or partial-mission capable supply situation which theoretically it is intended to overcome. One goal of logistics and maintenance operations should be the elimination of unnecessary cannibalization. However, when properly supervised, cannibalization is a viable management tool. Policies regarding its use should be flexible in nature. Simultaneously, it must be recognized that the broader objectives of asset management and system discipline are fundamental to cannibalization reduction. [Ref. 1: para. 12.1.11]

Cannibalization is normally reported as a rate, determined by the ratio of the number of cannibalization actions per 100 flight hours. Over the past five years the cannibalization rate for all Navy aircraft including the H60 helicopter have shown a slight increase. Table 1.1 lists cannibalization rates for all Navy aircraft and specifically the H-60 helicopter for FY95-FY99. As an aggregate, the Navy's airforce averaged a cannibalization rate of 8.82, while the H-60 averaged 6.58. [Ref. 2]

Table 1-1 also shows that total number of Navy aircraft decreased by 24 percent from FY95-FY99. The number of H-60 helicopters decreased 7.3 percent during the same period.

| ACFT     | CATEGORY    | FY95   | FY96   | FY97   | FY98   | FY99   | %CHANGE | AVE  |
|----------|-------------|--------|--------|--------|--------|--------|---------|------|
| ALL NAVY | # OF ACFT   | 2565.5 | 2283.2 | 2016.0 | 2055.4 | 1951.1 | -24%    |      |
| ALL NAVY | CANN/100 FH | 8.4    | 8.4    | 9.1    | 9.3    | 8.9    |         | 8.82 |
| H-60     | # OF ACFT   | 144.0  | 138.5  | 132.4  | 136.5  | 133.5  | -7.3%   |      |
| H-60     | CANN/100 FH | 7.0    | 6.3    | 6.0    | 6.3    | 7.3    |         | 6.58 |

Source: NAMS0 4790.A7049-01 DTD 21 Oct 99

Table 1-1 Cannibalization Rates for Navy Aircraft and H-60 Helicopter

Even though the cannibalization rate per 100 flight hours remained relatively stable, the number of cannibalizations per aircraft increased as the result of the smaller inventory. Table 1-2 shows that even though the number of H-60 hours flown per year decreased by 13.9 percent the cannibalization rate increased by 4.3 percent while the direct maintenance man hour (DMMH) per flight hour increased by 34.8 percent. One probable explanation for the dramatic increase in DMMH is that the fewer remaining aircraft were burdened by more cannibalization. Each of the remaining aircraft incurred the additional DMMH and the wear and tear associated with the removal and reinstallation of aircraft components for cannibalization.

| ACFT | CATEGORY                | FY95  | FY96  | FY97  | FY98  | FY99  | %CHANGE       |
|------|-------------------------|-------|-------|-------|-------|-------|---------------|
| H-60 | TOT A/C<br>HRS<br>FLOWN | 22406 | 21329 | 18324 | 20311 | 19277 | 13.9 DECREASE |
| H-60 | CANN/100<br>FH          | 7.0   | 6.3   | 6.0   | 6.3   | 7.3   | 4.3 INCREASE  |
| H-60 | DMMH/FH                 | 20.4  | 19.7  | 22.1  | 24.5  | 27.5  | 34.8 INCREASE |

Source: NAMS0 4790.A7049-01 DTD 21 Oct 99

Table 1-2. Change in H-60 Annual Flight Hours, Cannibalization Rate and DMMH/FH for FY95-FY99

### 3. Costs Associated with Cannibalization

In order to maximize readiness and meet pressing mission requirement, Commanders often discount the following costs associated with cannibalization: (1). Increased direct labor cost. Cannibalization requires triple work. Maintenance technicians must first impair one aircraft to repair a second aircraft only to repair the first aircraft later when the replacement part is available from the supply system. Decision-makers often ignore the additional direct labor cost incurred by cannibalization. Military labor costs remain constant regardless of the number of hours Sailors work. Since labor is not funded by the squadron's operational budget, Commanders have no financial incentive to reduce manpower requirements. (2). Increased material costs through the reduced life cycles of cannibalized parts. Removing a major component from one aircraft and installing it in another reduces the total useful installed service life of the component. The amortized cost of the reduced life of the component is a hidden cost of cannibalization. Over the long run, the Navy must purchase additional spare parts and maintain a larger inventory of ready spares to off set the effects of reduced service life. (3). Increased use of consumables and breakage. Less significant costs of cannibalization are the increased

use of consumables such as lubricants, oils and packing associated with the increased maintenance actions and the losses related to accidental breakage in handling.

### **C. RESEARCH QUESTIONS**

This thesis focuses on the following research questions:

Primary: What are the total costs to cannibalize high value components on the H-60 helicopter?

Secondary:

(1) Why do squadrons cannibalize?

(2) Does cannibalization reduce the installed service life of the cannibalized component?

(3) What is the cost of the increased maintenance associated with cannibalization?

## II. LITERATURE REVIEW

### A. INTRODUCTION

This chapter provides insight into official policies and attitudes related to cannibalization and how these policies and attitudes effect cannibalization practices in operational fleet squadrons. It also explains how squadrons use cannibalization.

### B. CANNIBALIZATION POLICY

The Naval Aviation Maintenance Program (NAMP) recognizes cannibalization as a viable short-term solution to overcome failures of a logistics or maintenance support system. In this light, cannibalization is sanctioned as a tool to be used under close supervision to help squadron commanders maintain the highest possible aircraft readiness. Squadron commanders are directed to develop local policies that allow flexibility while at the same time recognizing that cannibalization is no substitute for skillful asset, logistic, and support system management. Commanders are to ensure that Cannibalization actions are limited to those necessary to meet mission requirements and are not used simply to improve Full Mission Capability statistics.[Ref. 3]

The NAMP also addresses the negative effects of cannibalization and recognizes the practice's adverse impact on the morale of the technicians whose workload is increased and the long term increased strain on the logistics support system. Rear Admiral David Keller, director of the Supply Programs and Policy Division for the Chief of Naval Operations, believes excessive cannibalization hurts personnel retention more than readiness but concedes that eventually the two issues are the same. In an interview with *Defense Week*, Rear Adm. Keller stated, "If we're driving people out because of

spares shortfalls, we're exacerbating the problem." [Ref. 4] In a June 1999 survey on fleet perceptions of logistics support conducted by the Center for Naval Analyses at the request of the Assistant Deputy Chief of Naval Operations, dissatisfaction with logistics support among the aviation community was 39 percent, up from 5 percent five years ago. Cannibalization and excessive down time was one of the reasons most often mentioned for the decline in satisfaction [Ref. 5].

The Aircraft Inventory Reporting System (AIRS) instruction, OPNAVINST 5442.4, addresses the adverse effect of multiple cannibalizations on aircraft which have not flown for extended periods. The AIRS designates aircraft that have not flown for 60 consecutive days as Special Interest Aircraft (SPINTAC). Cannibalization is tightly controlled on SPINTAC because it is acknowledged that aircraft, which have had multiple cannibalizations, require an extraordinary effort to return to normal flying status. SPINTAC also alerts material and logistics managers to provide pointed assistance to help squadrons return the affected aircraft to flyable status as soon as possible.[Ref. 3]


In contrast to the Navy, the Airforce has explored cannibalization as a powerful management tool to help the logistics system to cope with the uncertainties in spare parts demand. In 1993 the Rand Institution published a study, *Estimating Aircraft Recoverable Spares Requirements with Cannibalization of Designated Items*, for the Airforce. Rand's research considered using cannibalization as a possible substitute for substantial capital investment required to maintain extensive inventories of spare parts. This study attempted to use a mathematical model to determine when cannibalization could be a cost-effective practice to reduce the investment in safety stock while maintaining a desired aircraft availability rate. By designating about 58 percent of all aircraft repairables as

cannibalizable, based on ease of cannibalization and historic practice, the model demonstrated that the safety stock for the F-16 weapon system could be reduced by 30% while maintaining a 83% readiness rate.[Ref. 6]

Although this model appears to be cost effective for the logistics and supply system, it fails to consider the cost of cannibalization at the operational unit level. The study did not consider the additional cost of manpower, the adverse effect of cannibalization on the service life of parts, the increase use of consumables and breakage, and the negative impact cannibalization has on the morale and retention of skilled technicians. The study also did not consider the increased potential and associated cost of maintenance error when technicians are under extreme pressure to meet the tightly controlled launch schedule under the harsh conditions of an operationally deployed aircraft carrier.

### **C. WHY SQUADRONS CANNIBALIZE**

The most common reason given for cannibalization is that there is a shortage of spares available from the normal supply system. In this case, squadron level maintenance managers choose to cannibalize in order to compensate for the lack of logistic support from the supply system. However, since fiscal year 1995 supply material availability (SMA) has improved considerably, while cannibalizations per 100 flight hours have remained the same or have shown a slight increase [Ref. 4:p7]. Figure 2-1 shows the increase in SMA and cannibalization rate per 100 flight hours for the Navy's H-60 helicopter for FY95-FY99.



Source: Department of Defense Program Budget Decision 423 DTD 1 December 1999

Figure 2-1. H-60 Cannibalizations per 100 Flight Hours and Percent Supply Material Availability


Based on the increase in SMA and the decrease in the number of H-60 helicopters in the fleet, it is reasonable to conclude that the number of cannibalizations should have declined instead of remaining relatively flat. A regression analysis of SMA (the independent variable) to cannibalizations per 100 flight hours, (the dependent variable) provides a t-statistic of .466 and a P value of .67. With a small sample size these values indicate that no relationship exist between cannibalization rate and SMA. Therefore, other factors presumably have a more significant influence in a squadron maintenance manager's decision to cannibalize.

Aircraft readiness statistics and supply response times are two additional factors that weigh heavily on maintenance managers' decision to cannibalize. Aircraft readiness is reported as a ratio of the number of hours an aircraft is mechanically capable of

performing a mission to the number of hours available in a reporting period. The normal reporting period is one month. Most maintenance departments use aircraft readiness as a performance measure. Managers use cannibalization as a technique to improve readiness. By consolidating mission impacting discrepancies into one aircraft, managers are able to report a higher number of mission capable aircraft. Figure 2-2 shows a plot of mission capable rates and cannibalizations per 100 flight hours for the H-60 helicopter from FY95 – FY99. Despite the use of cannibalization, mission capable rates have declined as cannibalization rates have increased slightly.

A regression analysis of mission capable rates (dependant variable) and cannibalization per 100 flight hours (independent variable) provided a t-statistic of .227 and a P value of .227 indicating that there is no strong relationship between mission capable rates and cannibalization. One explanation for this anomaly is that fewer aircraft are flying more and longer flights. Cannibalizations can not occur on flying aircraft and aircraft that are flown regularly tend to have fewer problems. Additionally, many quick flight line cannibalizations impair the cannibalized aircraft for a relatively short period of time and have little impact or are not reported as negatively effecting readiness. Another explanation is that squadrons are adhering to the NAMP and are not using cannibalization as a method to boost readiness statistics.

Supply response time can have a major influence in the decision to cannibalize. During high-tempo operations, squadrons are under pressure to launch aircraft according to an intricately coordinated and timed flight plan.



Source: Department of Defense Program Budget Decision 423 DTD 1 December 1999

Figure 2-2. H-60 Cannibalization per 100 Flight Hours and Mission Capable Rates

When systems fail during operations maintenance managers often perceive that it is quicker to cannibalize than to wait for the supply system to respond, thereby reducing the possibility of jeopardizing the mission. To combat this perception the Navy has established maximum acceptable elapsed response times for the supply system to issue items available in the local supply stocks. Response time begins when the squadron's Material Control places a requirement on the supply system and ends when the requested material or its status is received at the requesting unit. Supply response time is a function

of Issue Priority Group or Priority Designator. Table 2-1 shows the relationship among Issue Priority Group, Priority Designator and Processing Time.

| Issue Priority Group | Priority Designator | Processing Time |
|----------------------|---------------------|-----------------|
| 1                    | 1-2                 | 1 Hour          |
| 2                    | 4-8                 | 2 Hours         |
| 3                    | 9-15                | 24 Hours        |

Source: Naval Aviation Maintenance Program OPNAVINST 4790.2  
Table 2-1 Supply Response Time

Issue Priority Group is assigned based on the impact of the requested part on the aircraft's readiness status. For example, requisitions for a part which causes an aircraft to be not mission capable is assigned as an Issue Priority Group 1. Priority Designator is assigned based on the criticality of the unit's mission. Most deployed peacetime squadrons are assigned a Priority Designator 3, shore based operational squadrons are generally assigned a Priority Designator 4. [Ref. 1: para. 18.4]

During high-tempo operations, maintenance managers feel pressure to repair a mission degrading discrepancy in less than the hour it can expect to wait for supply to deliver the part. Two crews working simultaneously, one to remove the faulty part from the scheduled aircraft while the other impairs a non-flying aircraft, can at many times greatly expedite the repair by circumventing the supply chain. The scheduled aircraft can launch on its mission while the impaired aircraft waits for the logistics and supply system to produce the part. Although cannibalization may reduce elapsed clock time, the

additional direct maintenance man-hours and administrative time greatly exceeds that which would have been required if the part was obtained through the supply system.

Cannibalization always requires twice the direct maintenance man-hours. In aviation where most actions require three technicians, (one to make the repair, a second to inspect the work and a third to make a quality control inspection for safety of flight repairs) cannibalization can greatly increase the direct man-hours and the workload of the squadron's maintenance technicians. In addition to direct maintenance man-hours, time spent in tool control and administrative documentation is also doubled. This increased administrative burden can lend itself to potential errors as workers focus on expediting the physical repair and preparing the aircraft for launch. During flight line cannibalization the is push is to get the aircraft in the air while allowing the paperwork to catch up once the aircraft is gone. This practice can result in poor quality control and potential aircraft safety of flight problems.

#### **D. SUMMARY**

The Navy sanctions cannibalization as a technique to help maintenance managers overcome short-term logistics failures to meet operational mission requirements. The Navy acknowledges the long-term negative effect of cannibalization on both morale and the normal logistic support system and discourages its use as a substitute for the normal supply system.

From FY95 though FY99 cannibalization for the H-60 helicopter has remained stable. SMA has increased while mission capability has decreased. Regression analysis indicated that there is no strong relationship between the number of cannibalizations and SMA or mission capable rates for the H-60 helicopter. Squadrons appear to abiding by

the NAMP and using cannibalization only when necessary to meet critical mission requirements and not as a means merely to boost readiness statistics.

**THIS PAGE INTENTIONALLY LEFT BLANK**

### **III. DATA COLLECTION**

#### **A. INTRODUCTION**

This chapter explains the plan and procedures used to gather and analyze the data to answer the research questions stated in Chapter 1. The research design is presented to explain the procedures used to ensure the validity and reliability of the data. The research design strategy describes the data used in this thesis and how the data was obtained and organized. It explains the how the data was analyzed and the sources of unit costs. The research instrument describes the database in detail and indicates the techniques employed to ensure the validity and reliability of the data.

#### **B. RESEARCH DESIGN**

This thesis addressed the total costs associated with using cannibalization at the organization level to increase the mission readiness of the Navy's H-60 helicopter. The author studied three dissimilar high value components that were frequently cannibalized by operational squadrons over the past five years.

To determine the total cost associated with cannibalization to an operational squadron, the author calculated the cost of the additional manpower, flight time and consumables used in cannibalization that would not have been required if the component was obtained through the normal supply system. Additionally, the service life of cannibalized components was compared to non-cannibalized components to determine if a relationship exist between cannibalization and reduced service life of components. The costs associated with reduced service life are potentially significant, far reaching. Calculation of these costs are beyond the scope of this thesis.

The primary data source used in this thesis was archival data compiled and maintained by the Naval Air Systems Command. The author accessed the Naval Air Logistics Data Analysis (NALDA) databases and reports via a computer internet connection. NALDA databases are compiled from the raw data collected from various source documents such as the Navy's 3-M system, squadron flight files and the Naval Air Logistics Command Management Information System (NALCOMIS).

As a secondary source of data, the author contacted Helicopter Anti-Submarine Wing Light Pacific, Helicopter Anti-Submarine Wing Pacific and Helicopter Wing Reserve in San Diego, California to verify that the NALDA database fairly represented the actual cannibalization experiences of the fleet.

The military equivalent manpower hourly wage rates used in this thesis were obtained from the Office of the Under Secretary of Defense (Comptroller) Reimbursable Rates tab K-3. [Ref. 7] Table 3-1 Summarizes the rates for Naval Personnel.

| Pay Grade | Billable Annual Rate \$ | Hourly Rate \$ |
|-----------|-------------------------|----------------|
| O-3       | 91,200                  | 50.16          |
| E-7       | 67,625                  | 37.19          |
| E-6       | 58,675                  | 32.27          |
| E-5       | 50,100                  | 27.55          |
| E-4       | 41,225                  | 22.67          |
| E-3       | 34,250                  | 18.37          |

Source: USD Comptroller

Table 3-1: Military Reimbursement Rates

Labor cost per cannibalization action was calculated using equation 3-1

below.

$$\text{Labor Cost} = (\text{Hours} \times \text{Pay Grade1}) + (\text{Hours} \times \text{Pay Grade2})$$

In the case of the T700-GE-401C engine, actual labor costs were derived from LDMSS engine data displayed in Table 3-2.

| <b>T700-GE-401C 1997-1999</b> |              |                           |                           |
|-------------------------------|--------------|---------------------------|---------------------------|
| Engines Removed               |              | 1,063                     |                           |
| Flight Hours                  |              | 721,666                   |                           |
| Flight Hours per Removal      |              | 678.9                     |                           |
|                               | <b>Total</b> | <b>ML-1<br/>(I-Level)</b> | <b>ML-2<br/>(O-Level)</b> |
| Labor Hours                   | 141,035      | 18,319                    | 122,715                   |
| Labor Cost                    | \$7,198,544  | \$1,272,488               | \$5,926,056               |
| Cost per Hour                 | \$50.04      | \$69.46                   | \$48.29                   |

Source: LMDSS ad hoc report

Table 3-2: Hourly Labor Cost for T700-GE-401C Engine  
1997-1999

In addition to direct labor costs, the cannibalization of components that are directly related to safety of flight require a post maintenance functional check flight prior to assigning the aircraft to an operational or training mission. The cannibalization of an engine or tail rotor blade requires a post maintenance functional check flight. The typical check flight requires 1.4 flight hours. Table 3-3 contains the average cost per flight hour of all H-60 types/models/series.

| FY95   | FY96   | FY97   | FY98   | FY99   | AVERAGE<br>ALL YEARS |
|--------|--------|--------|--------|--------|----------------------|
| \$1383 | \$1615 | \$1189 | \$1126 | \$1232 | \$1309               |

Source: LMDSS Budget Analysis (OP-20 Report FY95-FY99)

Table 3-3: Annual Average Cost per Flight Hour H-60 Helicopter

Component maintenance data was obtained from the NALDA Equipment Condition Analysis System report number 520. This report is a user designed ad hoc report that generates a list of the individual maintenance actions performed on a particular component by either part number or serial number entered by the user.

Consumables used in the removal and replacement of components were determined by consulting the appropriate Maintenance Instruction Manual. The actual costs of the consumables used in cannibalization were obtained from the Navy's Visibility and Management of Operations and Support Cost (VAMOSC) databases. The Federal Logistic Data (FEDLOG) was used to determine the current price of consumables not tracked by VAMOSC.

### **C. RESEARCH DESIGN STRATEGY**

The top three high value components cannibalized were determined by examining Naval Aviation 3-M data for FY95 – FY99. To ensure that the selected component's installation and service life history were available, only components tracked by a Maintenance Record Card (MRC) were considered for this thesis. The three MRC tracked components with the highest cannibalization rate per 100 flight hours were identified as the tail rotor blade (2.566 cannibalizations per 100 flight hours), the T700-GE-401C turbo shaft engine (1.361 cannibalizations per 100 flight hours), and the

auxiliary power electronic control unit (.899 cannibalizations per 100 flight hours). [Ref. 8]

The author used 1996 as a base year and then followed the maintenance history of individual components by serial number through 1999 to derive a comparison between cannibalization and reduced time between failure of the selected components.

#### **D. RESEARCH LIMITATIONS**

The primary limitation of this study is the inadequacy of data and incomplete reporting by operational squadrons. This limitation is highlighted in the following excerpt from the Aviation Maintenance and Supply Readiness Cannibalization Issue number 62:

There appears to be significant differences in reporting engine cannibalizations between AV-3M, which compiles from Engine Transaction Reports (ERTs) and AEMS. The AV-3M system shows a mild picture of the cannibalization issues with a slight problem in the 4<sup>th</sup> quarter of FY97. AMES system shows a significant increase in cannibalizations in the 2<sup>nd</sup> quarter of FY97, that has remained at an average of 25 engine assembly cannibalizations per quarter. [Ref. 9]

NALDA databases are compiled from data submitted by several operational units dispersed throughout the world. The reliability of NALDA databases is dependent on the accuracy and completeness of the data collected and entered by the various units.

Although aircraft engine data is well organized and easily accessed, other aircraft components are not tracked in detail.

This thesis was limited to examining the cost of the top three components with a MRC. Detailed data required for this thesis is collected and maintained only on major components tracked with a MRC. Although cannibalizations of these major components are frequent and have a longer negative impact on aircraft readiness, the majority of cannibalizations that occur at the organizational level are for minor components whose

installed service life is not tracked in detail. The top three cannibalized items for the SH-60B for FY1995-FY1999 were the stabilizer actuator, tail rotor coupling and UHF antenna [Ref. 7]. Detailed information on those components is not maintained in an accessible database.

Incidental costs associated with cannibalization were not included in this thesis. The increased maintenance actions required by cannibalization results in a corresponding increase in waste due to breakage and packaging. Parts damaged in handling are not reported as cannibalizations and therefore were not considered in this thesis. The cost associated with aircraft mishaps associated with poor quality control when cannibalization is used during high tempo operations to get aircraft in the air is beyond the scope of this thesis. The cost to the Navy of reduced mean time between failure in additional spares and inventory can be significant. Calculation of this cost is dependant on many variables and is beyond the scope of this thesis.

The findings in this thesis are applicable only to the Navy's H-60 helicopter. Every military aircraft model has both unique supply support and maintenance requirements. The availability of replacement parts, the dynamic life of parts and the man-hours required to repair and replace aircraft parts vary among aircraft models.

## **IV. DATA PRESENTATION AND ANALYSIS**

### **A. INTRODUCTION**

This chapter presents the data obtained through the data collection methods described in Chapter III. Archival maintenance data for the Navy's H-60 helicopter's T700-GE-401C turbo shaft engine, tail rotor blade and auxiliary power electronic control unit was extracted from NALDA databases. Aviation 3-M reports were used to determine manpower requirements to cannibalize each of the three components studied. The cost that an operational unit incurs when it chooses to cannibalize was calculated based on the additional manpower, flight time and consumables required.

To illustrate the relationship between cannibalization and component service life, 1996 was selected as the base year for comparison. To determine if cannibalized components have a reduced time between failure, the author collected data on every T700-GE-401C engine, H-60 tail rotor blade and auxiliary power electronic control unit that received organizational maintenance or was cannibalized in 1996. Each component was tracked by its discreet serial number through 1999 to determine if subsequent maintenance was required. Each of the three components addressed in this thesis experienced a higher failure rate and decreased time between failures for cannibalized units as compared to similar components that were not cannibalized. A summary of the data obtained for each component follows.

### **B. TIME BETWEEN FAILURE AND FAILURE RATE COMPARISON**

#### **1. T700-GE-401C Turbo Shaft Engine**

In 1996, the Navy's operational H-60 helicopter squadrons performed non-scheduled maintenance on 161 T700-GE-401C engines. Twenty-nine of the 161 engines

serviced were cannibalized from one aircraft for installation in another aircraft. To effect a comparison between cannibalized and non-cannibalized engines, each of the 161 engines was tracked via its discreet serial number through 1999 to determine if and when additional unscheduled maintenance (considered component failure for this thesis) was required. The raw data is displayed in Appendix A.

The 29 units cannibalized at the organizational maintenance level experienced a 34 percent subsequent failure rate compared to 17 percent for both the non-cannibalized and the total population. The mean time between failure for cannibalized units was 721 hours as compared to 1336 hours for non-cannibalized units. This comparison is displayed in Table 4-1.

| <b>T700GE401C ENGINE 1996-1999</b>  |                    |                           |                         |
|-------------------------------------|--------------------|---------------------------|-------------------------|
|                                     | <b>Total Units</b> | <b>Cannibalized Units</b> | <b>Non-Cannibalized</b> |
| <b>1996 O-Level Maintenance</b>     | <b>161</b>         | <b>29</b>                 | <b>132</b>              |
| <b>Number of Failures 1996-1999</b> | <b>27</b>          | <b>10</b>                 | <b>17</b>               |
| <b>Failure Rate</b>                 | <b>17%</b>         | <b>34%</b>                | <b>17%</b>              |
| <b>Mean Time Between Failure</b>    |                    | <b>721 hrs</b>            | <b>1336 hrs</b>         |

Table 4-1. Failure Rates and Times Comparison Between Cannibalized and Non-cannibalized T700GE401C Engines

An analysis of variance (ANOVA) was performed to determine if the difference in the mean time between failure of cannibalized and non-cannibalized units is statistically significant. The ANOVA revealed the mean time between failure for cannibalized engines to be 721 hours with a standard deviation of 387.9. For non-

cannibalized engines the mean is 1336 hours with a standard deviation of 1196.7. The ANOVA f-factor is 2.45 and the p-value 0.13 indicating that the difference in mean time between failure for the two groups is significant at the 87 percent confidence level.

**2. Tail Rotor Blades**

The Navy's H-60 helicopter squadrons performed unscheduled maintenance on 233 tail rotor blades in 1996. Of these 233 blades, 37 were cannibalized. Using the same technique used for T700-GE-401C engines, the failure rate and mean time between failure for cannibalized and non-cannibalized was determined. The raw data is displayed in Appendix B. The failure rate for cannibalized tail rotor blades was 59 percent compared to 24 percent for non-cannibalized units and 30 percent for the total population. The mean time between failure for cannibalized tail rotor blades was 775 hours compared to 1365 hours for non-cannibalized units. Table 4-2 illustrates this comparison.

| <b>Tail Rotor Blades 1996-1999</b>  |                    |                           |                         |
|-------------------------------------|--------------------|---------------------------|-------------------------|
|                                     | <b>Total Units</b> | <b>Cannibalized Units</b> | <b>Non-Cannibalized</b> |
| <b>1996 O-Level Maintenance</b>     | <b>233</b>         | <b>37</b>                 | <b>196</b>              |
| <b>Number of Failures 1996-1999</b> | <b>70</b>          | <b>22</b>                 | <b>48</b>               |
| <b>Failure Rate</b>                 | <b>30%</b>         | <b>59%</b>                | <b>24%</b>              |
| <b>Mean Time Between Failure</b>    |                    | <b>775 hrs</b>            | <b>1365 hrs</b>         |

Table 4-2. Failure Rates and Times Comparison Between Cannibalized and Non-cannibalized H-60 Tail Rotor blades

An ANOVA was performed to determine if the difference in the mean time between failure of cannibalized and non-cannibalized units is statistically significant. The

ANOVA revealed the mean time between failure for cannibalized units to be 775 hours with a standard deviation of 881. The mean time between failure for non-cannibalized units is 1365 hours with a standard deviation of 1238. The ANOVA f-factor is 4.02 and the p-value 0.049 indicating that the difference in mean time between failure for the two groups is significant at a confidence level greater than 95 percent.

### 3. Auxiliary Power Electronic Control Unit

Finally, auxiliary power electronic control units were studied using the same techniques as above. Similar comparisons were derived. Sixty-one units received organizational maintenance in 1996. Sixteen of the 61 units were cannibalized. The subsequent failure rate for cannibalized units was 50 percent compared to 17 percent for non-cannibalized units and 26 percent for the total population. The raw data is displayed in Appendix C. The mean time between failure for cannibalized units was 775 hours compared to 1864 hours for non-cannibalized units. Table 4-3 summarizes the comparison.

| <b>Auxiliary Power Electronic Control Unit 1996-1999</b> |                    |                           |                         |
|--|--------------------|---------------------------|-------------------------|
|  | <b>Total Units</b> | <b>Cannibalized Units</b> | <b>Non-Cannibalized</b> |
| <b>1996 O-Level Maintenance</b>                          | <b>61</b>          | <b>16</b>                 | <b>45</b>               |
| <b>Number of Failures 1996-1999</b>                      | <b>16</b>          | <b>8</b>                  | <b>8</b>                |
| <b>Failure Rate</b>                                      | <b>26%</b>         | <b>50%</b>                | <b>17%</b>              |
| <b>Mean Time Between Failure</b>                         |                    | <b>705 hrs</b>            | <b>1864 hrs</b>         |

Table 4-3. Failure Rates and Time Comparison Between Cannibalized and Non-Cannibalized H-60 Auxiliary Power Electronic Control Units

An ANOVA was performed to determine if the difference in the mean time between failure of cannibalized and non-cannibalized units is statistically significant. The ANOVA revealed the mean time between failure for cannibalized units to be 705 hours with a standard deviation of 489. The mean time between failure for non-cannibalized units is 1864 hours with a standard deviation of 1430. The ANOVA f-factor is 4.71 and the p-value 0.048 indicating that the difference in mean time between failure for the two groups is significant at confidence level greater than 95 percent.

The above comparisons of three dissimilar H-60 components indicate that cannibalization has a negative effect on the reliability and service life of aircraft parts. Because cannibalization increases failure rates and decreases the time between failures, a squadron's decision to cannibalize has far-reaching financial implications for the Navy.

The Navy Inventory Control Point (NAVICP) uses a maintenance replacement factor (MRF) in determining the optimal number of spare parts to purchase and maintain in inventory in order to support a desired readiness rate for each aircraft model at its particular location.

The MRF is comprised of the number of units found to be beyond the capability of maintenance (BCM) at the local Aircraft Intermediate Maintenance Department (AIMD) divided by the mean time before failure (MTBF) [Ref. 10]. Equation 4-1 below refers.

$$\text{MRF} = \text{IBCM} / \text{MTBF}$$

A decrease in MTBF as the result of cannibalization yields a corresponding increase in MRF. In response to the higher MRF, NAVICP must incur the additional costs of both purchasing additional spares and maintaining the larger inventory if it is to support the same readiness rates. An alternative to purchasing spare would be to invest in the local AIMD to expand its maintenance capabilities. The calculation of a dollar value for the increased support costs to NAVICP and the various AIMDs associated with cannibalization is beyond the scope of this thesis. The costs incurred at the squadron level to cannibalize each of the three components selected for this study are calculated below.

**C. ORGANIZATIONAL COST ASSOCIATED WITH MAJOR COMPONENT CANNIBALIZATION**

**1. T700-GE-401C Turbo Shaft Engine**

The maintenance and repairs for the T700-GE-401C turbo shaft engine is well documented in NALDA databases. For the five year period addressed in this thesis, The Navy cannibalized 134 engines from the H-60 helicopter at the organizational level. A list of these engines was extracted from the NALDA equipment condition analysis database and is displayed in Appendix D.

The costs incurred by an organizational unit when it chooses to cannibalize a T700-GE-401C engine in lieu of waiting and installing an engine received through the supply system are: (1) The additional manpower cost required for the maintenance department to remove a fully functional engine from one aircraft and then later replace it with an engine received from supply, (2) The cost of the flight time required to perform an in-flight functional check of the aircraft impaired by cannibalization once an engine is

received from supply, (3) The labor cost for the flight crews and ground crews to perform the functional checks, and (4) The cost of consumable items used during the process.

Manpower required to remove and replace an engine on the H-60 helicopter averaged 11.1 man-hours per procedure. Based on the hourly wage rate of \$48.42 for the T700-GE-401C engine displayed in Table 3-2, the incremental labor cost to cannibalize was calculated below.

$$\text{Labor Cost} = (11.1\text{hr} \times \$48.42)$$

$$\text{Labor Cost} = \$535.46$$

The T700-GE-401C is a critical component for safety of flight; therefore an in-flight post maintenance functional check of the engine and its systems is required before the aircraft can be assigned to a mission. The typical function check flight requires 1.4 flight hours, a crew of two pilots and one system operator, and a two-person ground crew.

The cost of the additional flight time incurred from the decision to cannibalize is calculated by multiplying the average cost per flight hour, listed in Table 3-3 as \$1309, by the required flying time of the in-flight check.

$$\text{Flying Time cost} = \$1309 \times 1.4 \text{ hours}$$

$$\text{Flying Time Cost} = \$1832.60$$

Flight crew costs are determined by the wage rates of the flight crew and the total time required to complete the check flight and related task. The typical check flight crew is composed of two pilots (normally O-3s) and a system operator (typically an E-5). The customary time allotted by the H-60 community for preflight activities is two hours. An

additional thirty minutes are assigned for post flight duties. The additional flight crew costs incurred by the decision to cannibalize are computed below.

$$\text{Flight Crew Cost} = (\text{Flying Time} + \text{Preflight Time} + \text{Post Flight Time}) \times 2(\text{O-3 Hourly Rate}) + \text{E-5 Rate}$$

$$\text{Flight Crew Cost} = (1.4\text{hrs} + 2\text{hrs} + .5\text{hrs}) \times 2(\$50.16) + \$27.55$$

$$\text{Flight Crew Cost} = \$418.80$$

Each shore based helicopter flight requires a ground crew consisting of a least two persons to assist and direct the flight crew during launch and recovery. One hour is allotted for two ground crew personnel one E-4 and one E-3 to perform ground crew duties for each flight. The cost of the ground crew is calculated below.

$$\text{Ground Crew Cost} = (\$22.67) \times 1\text{hr} + 18.37 \times 1\text{hr}$$

$$\text{Ground Crew Cost} = \$41.04$$

A list of consumables used to remove and replace a T700-GE-401C engine was obtained from the H-60 power plants organizational maintenance instructions manual and is displayed in Table 4-4.

| Specification/Part Number | Nomenclature | Cost   |
|---------------------------|--------------|--------|
| AN960-416                 | Washer       | \$.10  |
| AN960C516                 | Washer       | \$2.36 |
| ANC516L                   | Washer       | \$2.19 |

|                   |                            |         |
|-------------------|----------------------------|---------|
| AN960C616         | Washer                     | \$2.19  |
| AN960C616L        | Washer                     | \$4.51  |
| AN960C816         | Washer                     | \$5.30  |
| MIL-A-907         | Anti-seize Thread Compound | \$2.96  |
| MIL-L-23699       | Lubricating Oil (8 qrts.)  | \$69.60 |
| MIL-C-5501        | Protective Caps and Plugs  | \$3.86  |
| MS20002C5         | Washer                     | \$4.95  |
| MS20002C6         | Washer                     | \$5.52  |
| MS21043-4         | Nut (Self Locking)         | \$17.57 |
| MS24665-153       | Cotter Pin (4)             | \$.80   |
| MS24665-302       | Cotter Pin (3)             | \$.24   |
| MS3367-2-9        | Tie Down Strap (Electric)  | \$2.27  |
| MS9724-09         | Bolt                       | \$3.27  |
| P-C-451           | Abrasive Cloth             | \$1.01  |
| P-C-458           | Crocus Cloth               | \$1.83  |
| P-D-680, Type III | Solvent                    | \$9.35  |

Table 4-4. T700-GE-401C Consumables

The total cost of consumables used per engine change is \$139.88.

The decision to cannibalize cost the operational unit \$2967.78 per engine. For the five years 1994-1999 the Navy's operational units incurred an additional cost of \$397,682 to cannibalize 134 T700-GE-401C engines.

## 2. Tail Rotor Blade

Maintenance and life cycle data for helicopter tail rotor blades are not as well documented as the T700-GE-402C turbo shaft engine. For the five year period addressed in this thesis, the Navy cannibalized 264 tail rotor blades from the H-60 helicopter at the organizational level. Data on these tail rotor blades were extracted from the NALDA equipment condition analysis database and is displayed in Appendix E.

The manpower required to remove and replace a tail rotor blade on the H-60 helicopter averaged 12.0 man-hours per procedure. The author assumed a manpower allocation rate of 20 percent for supervision and inspection and 80 percent for direct labor. The supervisor rate was charged at the average of the E7 and E-6 rate. The remaining 80 percent were assigned the E-5 rate for direct labor. Based on these assumptions and using the labor rates shown in Table 3-1, the additional labor cost incurred to cannibalize a tail rotor blade was calculated as follow:

$$\text{Labor Cost} = (12\text{hr} \times 20\% \times \$34.73/\text{hr}) + (12\text{hr} \times 80\% \times \$27.55/\text{hr})$$

$$\text{Labor Cost} = \$347.83$$

Like the engine, tail rotor blades are critical to safe flight and require a post maintenance in-flight functional check before the aircraft can be used for squadron missions. The cost associated with the check flight are the same as those for the engine, \$1832.60 for flight time, \$418.80 for flight crew, and \$41.05 for ground crew.

A list of consumables used to remove and replace a rotor blade was obtained from the H-60 airframes organizational maintenance instructions manual and is displayed in Table 4-5.

| Specification/Part Number | Nomenclature                    | Cost    |
|---------------------------|---------------------------------|---------|
| CCC-C-440                 | Cheesecloth                     | \$.90   |
| MIL-C-5501                | Protective caps                 | \$3.60  |
| MIL-C-85043               | Low Lint Cloth                  | \$1.25  |
| MIL-C-85285               | High Solids Polyurthane Coating | \$17.55 |
| MIL-S-8784                | Sealing Compound                | \$3.50  |
| MIL-S-8802, B-2           | Sealing Compound                | \$11.56 |
| MS20995NC32               | Safety Wire                     | \$1.86  |
| MS28778-6                 | Packing                         | \$.08   |
| MS29512-07                | Packing                         | \$.11   |
| VV-P-236                  | Petrolatum                      | \$4.44  |

Table 4-5. Tail Rotor Blade Consumables

The total cost of consumables used per tail rotor blade change is \$44.85.

The decision to cannibalize cost the operational units \$2685.13 per blade. For the five years 1994-1999 the Navy's operational units incurred an additional cost of \$708,874 to cannibalize 264 H60 tail rotor blades.

### 3. Auxiliary Power Electronic Control Unit

Similar tail rotor blades, the maintenance and life cycle data for auxiliary power electronic control units are not as well documented as the T700-GE-402C turbo shaft engine. For the five year period addressed in this thesis, the Navy cannibalized 65 auxiliary power electronic control units from the H-60 helicopter at the organizational

level. Data on these auxiliary power electronic control units were extracted from the NALDA equipment condition analysis database and is displayed in Appendix F.

The manpower required to remove and replace an auxiliary power electronic control unit on the H-60 helicopter averaged 5.0 man-hours per procedure. Manpower was allocated as 20 percent at the average of E7 and E-6 rate for supervision and inspection. The remaining 80 percent were assigned the E-5 rate for direct labor. Based on these assumptions and using the labor rates shown in Table 3-1, the additional labor cost incurred to cannibalize a auxiliary power electronic control unit was calculated as follow:

$$\text{Labor Cost} = (5\text{hr} \times 20\% \times \$34.73/\text{hr}) + (5\text{hr} \times 80\% \times \$22.67/\text{hr})$$

$$\text{Labor Cost} = \$125.41$$

The auxiliary power electronic control unit is not critical to the safety of flight; therefore an in-flight post maintenance check is not required. An operational check is performed on the ground as part of the installation procedure.

A list of consumables used to remove and replace an auxiliary power electronic control unit was obtained from the H-60 organizational maintenance instructions manual and is displayed in Table 4-6.

| Specification/Part Number | Nomenclature              | Cost     |
|---------------------------|---------------------------|----------|
| MIL-C-5501                | Protective Caps and Plugs | \$3.86   |
| MIL-G-21164               | Grease                    | \$6.58   |
| MS20995C32                | Safety Wire               | \$1.86   |
| MS9135-01                 | Gasket                    | \$0.06   |
| 169037-1 (55820)          | Grommet Tube              | \$128.31 |

Table 4-6. Auxiliary Power Electronic Control Unit Consumables

The total cost of consumables used per auxiliary power electronic control unit change is \$44.85.

The decision to cannibalize cost the operational squadrons \$170.26 per unit. For the five years 1994-1999 the Navy's operational units incurred an additional cost of \$11,066.90 to cannibalize 65 auxiliary power electronic control units on the H60 helicopter.

#### **D. SUMMARY**

This chapter clearly illustrated the relationship between cannibalization and the decreased time between failures and the relationship between cannibalization and the higher rate of failure of major aircraft components. The three major components studied in this thesis experienced a substantial decrease in the time before failure for a cannibalized component as compared to a similar component that was not cannibalized. Similarly, cannibalized units experienced a higher re-failure rate as compared to non-cannibalized units. This chapter also reveals the direct cost to squadrons in terms of the additional manpower, consumables and flight time required to accomplish the redundant maintenance procedures that are an inherent part of cannibalization.

A Cannibalized T700-GE-401C engine required unscheduled maintenance 615 hours sooner than a similar non-cannibalized engine. In the time period of this study 34 percent of engines cannibalized in 1996 required unscheduled maintenance prior to the end of 1999 compared to 17 percent of engines that received other unscheduled maintenance in 1996. Cannibalized tail rotor blades failed 590 hours sooner and had a 59 percent failure rate as compared to a 25 percent failure rate for non-cannibalized blades. Finally, cannibalized auxiliary power electronic control units failed 1159 hours sooner

and had a 50 percent failure rate as compared to 17 percent failure rate for non-cannibalized unit.

The decrease time between failure has a direct impact on the cost of supply support. NAVICP uses mean time between failure as a factor in determining how many spares are required to support a given readiness goal. As mean time between failure decreases, NAVICP must increase its inventory of spare part and bare the additional costs associated with larger inventories. Determining these costs is beyond the scope of this study.

Squadrons engender substantial cost when they decide to cannibalize. Notably, cannibalizing components that require an in-flight post maintenance functional check flight have a substantially higher cost to a squadron than those that do not require a check flight. The cost of consumables and additional flight time required for in-flight functional checks have a direct negative impact a squadron's operational budget. Although the additional manpower required to cannibalize is not directly funded by the operational unit, it does have a direct impact on the morale and retention of highly trained and skilled technicians.

## **V. CONCLUSIONS AND RECOMMENDATIONS**

### **A. INTRODUCTION**

This chapter presents the conclusions derived from the data analysis presented in Chapter IV. The research questions are answered and the effects of the research limitations listed in Chapter III are discussed. Recommendations for using cannibalization and further study are provided.

### **B. CONCLUSIONS**

#### **1. Cannibalization is an Expensive Alternative to the Normal Supply System for Operational Squadrons to Obtain Spare Parts.**

An analysis of the data presented in Chapter IV clearly indicates that cannibalization has a significant negative impact on the resources of an operation squadron. This study identified and quantified the high costs associated with cannibalization of three dissimilar aircraft components frequently cannibalized by the H-60 helicopter community, the T700-GE-701C turbo prop engine, H-60 tail rotor blade, and the auxiliary power electronic control unit. By assigning a fair market value to the redundant manpower, extra consumables used and flight time required, cannibalization added \$2967.78 to the costs of replacing a T700-GE-401C engine, \$2685.13 to a tail rotor Blade and \$170.26 to the costs of a auxiliary power electronic control unit. For the five years 1995-1999, the Navy's H-60 squadrons spent a total of \$1,117,622 to cannibalize the three components listed above.

#### **2. Cannibalization Reduces the Mean Time Between Failure for Cannibalized Components as Compared to Similar Non-cannibalized Units.**

The three components studied in this thesis illustrated a direct relationship between cannibalization and reduced time between failure. Cannibalized T700-GE-401C engines experienced both a higher failure rate and shorter time between failure than non-cannibalized engines. Of the 161 engines studied from 1996-1999, cannibalized engines reported a 34 percent failure rate and 721 hours between failure as compared to 17 percent failure rate and 1336 hours between failure for non-cannibalized engines. The historic mean time between failure for all T700-GE-401C engines as reported in the Aircraft Engine Management System is 1071.97 hours [Ref. 11].

Of the 233 tail rotor blades studied from 1996-1999, cannibalized blades experienced a 59 percent failure rate and 775 hours between failure compared to a 24 percent failure rate and 1365 hours between failure for non-cannibalized blades. The historic time between failure for all H-60 tail rotor blades is 1301 hours [Ref 11].

Auxiliary power electronic control units showed similar results for the 61 units studied from 1996-1999. The failure rate for cannibalized units was 50 percent with the time between failure of 705 hours compared to a 17 percent failure rate and 1864 hours between failure for non-cannibalized units. The historic time between failure for this component is 3014 hours and includes those units installed on Navy aircraft other than the H-60 helicopter [Ref. 11].

### **3. Cannibalization Has a Negative Impact on Organizations Outside of the Operational Unit.**

Cannibalization imposes added costs to organizations outside of the operational unit by reducing the time between failure for cannibalized components as compared to similar component that were not cannibalized. For example, NAVICP uses meantime

between failures as an input function to determine the size of inventory required for a particular part. A decrease in the time between failure of a component requires a larger inventory of spares. To support a constant readiness rate NAVICP must invest in and bear the related expenses of the larger inventory. Additionally, the higher turn over in repairables caused by decreased time between failures precipitates an increase in labor, consumables, and packing and shipping cost for Aircraft Intermediate Maintenance Departments (AIMD) and Aviation Depots.

**4. Cannibalizing Items Requiring an In-flight Post Maintenance Functional Check Have a Greater Negative Impact on the Squadron's Resources Than Those That Do Not.**

The additional flight time and manpower required as the result of cannibalization must be diverted from other priorities to the performance of the required in-flight checks. In the case of the H-60 helicopter, a typical post maintenance check flight added \$2,292.44 in flight time and related labor to the costs of an aircraft repair when cannibalization was used for flight critical components.

**B. RESEARCH QUESTIONS ANSWERED**

**1. What are the Total Costs to Cannibalize Major Components on The H-60 Helicopter?**

The researcher identified three types of costs associated with cannibalization: 1) direct costs, 2) indirect costs and 3) intangible costs. Direct costs are those costs that directly impact the resources of the unit which decides to cannibalize. Indirect costs are those costs imposed on organizations outside of the cannibalizing unit. Intangible costs are those that go unreported or are indirectly the result of cannibalization.

*a. Direct Costs*

The direct costs of cannibalization are labor, consumables, and flight time. Direct labor increases with cannibalization in two ways. First maintenance technicians must impair one aircraft to repair a second only to repair the second aircraft later when the appropriate part is received from supply. This results in a redundant removal and replacement that would not have occurred if cannibalization were not used. Second, if the cannibalized component is considered critical to the airworthiness of the aircraft, a flight crew and supporting ground crew is required to perform an in-flight post maintenance check of the component and its related systems.

The costs of consumables are doubled as the result of the redundant maintenance actions. The removal and replacement of most major components requires preparation materials, non-reusable hardware and lubricants. The squadrons must divert funds from other priorities to pay for these items.

Cannibalizing components that are deemed critical to the safety of flight create the requirement to perform an in-flight post maintenance check flight on both the repaired aircraft and then later an additional flight on the aircraft that was impaired by cannibalization, once the required part is received from supply. The number of flight hours required for an in-flight check vary and can become burdensome if unexpected problems occur with the aircraft's systems. The flight hours to perform these flights are diverted from those hours allocated to the squadron to perform its required missions and training.

*b. Indirect Costs*

The indirect costs of cannibalization are those costs imposed upon organizations outside of the operational unit. These costs are manifested in the additional investments the supporting activities must make in their infrastructure and core competencies, due to the higher demand created by cannibalization, to continue to support the operational unit at a constant readiness level.

This thesis identified a direct relationship between cannibalization and a decrease in time mean between failure for cannibalized components. The size of NAVICP's inventory for a particular part is a function of that part's mean time between failure. As the time between failure decreases, NAVICP is forced to incur the cost of procuring and maintaining a larger standing inventory to compensate for the higher failure rate. The shorter installed life of cannibalized components also increases the work load and processing cost for AIMDs and aviation depots that are charged with repairing the failed parts. Indirect costs can be considerable. The current cost to purchase just one additional T700-GE401C engine is \$619,079 [Ref. 11] while the specialized labor required to repair aircraft components commands an ample wage.

*c. Intangible Cost*

Intangible costs are those that arise after the cannibalization but are not planned or expected. These include the costs from breakage during handling, lost parts, work force injury, collateral damage to the aircraft during the maintenance procedure and possibly the loss of an aircraft and crew if short cuts are used to effect a quick repair. Intangible costs are not officially recorded or track as part of cannibalization, however they can be greatly increase the costs of cannibalization.

## **2. Why do Squadrons Cannibalize?**

Cannibalization is a technique sanctioned by the Navy to help maintenance managers overcome short-term logistics failures to meet operational mission requirements. This thesis found that there is no relationship between supply material availability (SMA) and cannibalization rates. Cannibalization rates remained constant during both increases and decreases in SMA, indicating that commanders are using cannibalization only when necessary to increase short-term aircraft availability requirements.

## **3. Does Cannibalization Reduce the Installed Service Life of the Cannibalized Component?**

This thesis clearly illustrated that cannibalized components on the H-60 helicopter have a shorter time between failure than similar components that were not cannibalized. Three dissimilar H-60 components, T700-GE-401C engine, H-60 tail rotor blade, and the auxiliary power electronic control unit, were studied to determine if cannibalized units experienced a shorter time between failure than similar non-cannibalized units within the same time frame. Each of the three components studied demonstrated a marked decrease in time between failure for the cannibalized unit as compared to a similar unit that was not cannibalized. Additionally, the cannibalized units experienced a higher failure rate than non-cannibalized units during the same period.

## **4. What is the Cost of the Increased Maintenance Associated with Cannibalization?**

This thesis determined the direct costs of the increased maintenance to an operational H-60 helicopter squadron for three major components frequently cannibalized. The costs of the additional labor, consumables, and flight time to perform

in-flight post maintenance checks were computed. The cost to cannibalize a T700-GE-401C engine is \$2967.78 per unit, for a tail rotor blade the cost is \$2685.13 and for an auxiliary power electronic control unit the cost is \$170.26. The indirect costs and intangible costs resulting from cannibalization can substantially increase these costs, however calculation of these costs is beyond the scope of this thesis.

### **C. EFFECTS OF LIMITATIONS**

This research was limited by the accuracy, completeness and consistency of the data extracted from the NALDA maintenance databases. Many components were missing complete maintenance histories, others were tracked by aircraft time for some maintenance actions and then component time for other actions. Units with incomplete or inconsistent data were excluded from the study.

The author defined 'failure' as any unscheduled maintenance when calculating mean time between failure and failure rate. In some cases the subsequent unscheduled maintenance required could have been minor repairs that had little impact on the continued operation of the component.

The study was limited to major components that are tracked by MRCs. This limitation prevented the researcher from capturing data on the many minor parts that are routinely cannibalized during flight operations. Of the top three items reported cannibalized, none are sufficiently tracked for inclusion in this study.

### **D. RECOMMENDATIONS**

**1. When Considering Cannibalization, Decision-makers Must Weigh the Expected Short-term Benefits in Terms of Aircraft Availability and Mission Readiness with the Total Cost of Cannibalization.**

Cannibalization is an expensive technique to increase aircraft readiness statistics. Before deciding to cannibalize, maintenance managers should consider the impact of their decision on the unit's operational budget, the morale of their workforce and the far-reaching effects their decision has on the costs to peripheral support activities. They must be aware of that cannibalization can decrease the mean time between failure of major components. Shorter time between failure results in fewer spares available. This trend can lead to even more cannibalization, further exacerbating the problem it was intended to overcome and creating more serious aircraft maintenance and logistic systems short falls.

**2. Cannibalization Must be a Closely Supervised Event Conducted with the Same Controls in Place as any Other Aircraft Repair Procedure.**

When cannibalizing, the speed of the repair must be secondary to the quality and safety of the repair in order to minimize the possibility and amount of intangible costs. Unreported cost associated with cannibalization such as breakage and injuries to workers can substantially increase the cost of cannibalization. During high tempo operations the pressure to launch aircraft on schedule creates an atmosphere ripe for errors. The probability of damaging a component during handling greatly increases when it is removed from one aircraft and transported without the proper container. Under these conditions the possibility of losing an aircraft and crew to maintenance error is more likely as short cuts in procedures and documentation are used to expedite repairs.

**E. RECOMMENDATIONS FOR FURTHER STUDY**

**1. Research is Needed to Determine the Indirect and Intangible Costs of Cannibalization.**

These costs can greatly increase the costs of cannibalization to both the Navy and the operational unit. Further study is needed to quantify these costs so that maintenance managers can appreciate the full impact of their decision to cannibalize on both the resources under their control and those of the organizations charged with supporting them.

Although this study focuses on the cost to cannibalize major components of the H-60 helicopter, it is possible that cannibalization of components in other aircraft types could have a similar negative impact on squadron resources and supporting activities.

**THIS PAGE INTENTIONALLY LEFT BLANK**

**APPENDIX A. T700-GE-401C ENGINES THAT RECEIVED UNSCHEDULED  
MAINTENANCE IN 1996**

|    | <b>BUREAU<br/>NUMBER</b> | <b>SERIAL<br/>NUMBER</b> | <b>TIME at<br/>Maintenance</b> | <b>CANN<br/>Y/N</b> | <b>Time at<br/>FAILURE</b> | <b>TIME<br/>BEFORE<br/>FAILURE<br/>CANN</b> | <b>TIME<br/>BEFORE<br/>FALURE<br/>NON-CANN</b> |
|----|--------------------------|--------------------------|--------------------------------|---------------------|----------------------------|---|--|
| 1  | 163288                   | 336000                   | 1912                           | N                   |                            |   |  |
| 2  | 164101                   | 336149                   | 2819                           | N                   |                            |   |  |
| 3  | 164456                   | 336489                   | 2416                           | N                   |                            |   |  |
| 4  | 164446                   | 336514                   | 2504                           | N                   |                            |   |  |
| 5  | 164451                   | 366010                   | 1304                           | N                   |                            |   |  |
| 6  | 164099                   | 366013                   | 4346                           | N                   |                            |   |  |
| 7  | 162344                   | 366019                   | 3590                           | N                   |                            |   |  |
| 8  | 163249                   | 366021                   | 3817                           | N                   |                            |   |  |
| 9  | 163237                   | 366048                   | 1580                           | N                   |                            |   |  |
| 10 | 164084                   | 366054                   | 3696                           | N                   |                            |   |  |
| 11 | 163244                   | 366055                   | 1724                           | N                   |                            |   |  |
| 12 | 164454                   | 366058                   | 2565                           | N                   |                            |   |  |
| 13 | 164812                   | 366066                   | 3687                           | N                   | 3980                       |   | 293  |
| 14 | 164071                   | 366067                   | 3794                           | Y                   |                            |   |  |
| 15 | 164074                   | 366068                   | 2386                           | N                   |                            |   |  |
| 16 | 165259                   | 366070                   | 2155                           | N                   |                            |   |  |
| 17 | 162115                   | 366073                   | 2083                           | N                   |                            |   |  |
| 18 | 164447                   | 366082                   | 2477                           | N                   |                            |   |  |
| 19 | 164455                   | 366084                   | 2462                           | Y                   |                            |   |  |
| 20 | 162121                   | 366086                   | 2633                           | N                   |                            |   |  |
| 21 | 162095                   | 366095                   | 2434                           | N                   | 3887                       |   | 1453   |
| 22 | 163784                   | 366097                   | 2556                           | Y                   |                            |   |  |
| 23 | 163796                   | 366100                   | 2460                           | N                   |                            |   |  |
| 24 | 164091                   | 366110                   | 3246                           | N                   |                            |   |  |
| 25 | 163786                   | 366111                   | 2725                           | N                   |                            |   |  |
| 26 | 162344                   | 366112                   | 2206                           | N                   |                            |   |  |
| 27 | 366114                   | 366114                   | 4186                           | N                   |                            |   |  |
| 28 | 161561                   | 366117                   | 3626                           | N                   |                            |   |  |
| 29 | 164101                   | 366119                   | 2819                           | N                   |                            |   |  |
| 30 | 163286                   | 366122                   | 1681                           | N                   |                            |   |  |
| 31 | 163233                   | 366134                   | 5770                           | Y                   |                            |   |  |
| 32 | 162128                   | 366135                   | 1589                           | N                   |                            |   |  |
| 33 | 161560                   | 366138                   | 2998                           | N                   |                            |   |  |
| 34 | 164103                   | 366149                   | 3307                           | Y                   |                            |   |  |
| 35 | 162342                   | 366150                   | 2319                           | N                   |                            |   |  |
| 36 | 164091                   | 366153                   | 2213                           | N                   |                            |   |  |
| 37 | 163795                   | 366155                   | 2640                           | N                   |                            |   |  |

|    |        |        |      |   |      |     |      |
|----|--------|--------|------|---|------|-----|------|
| 38 | 164100 | 366161 | 2809 | N |      |     |      |
| 39 | 162342 | 366165 | 2931 | N |      |     |      |
| 40 | 163786 | 366167 | 2698 | N |      |     |      |
| 41 | 164461 | 366168 | 3337 | N |      |     |      |
| 42 | 164808 | 366170 | 3404 | N |      |     |      |
| 43 | 164609 | 366174 | 2998 | N |      |     |      |
| 44 | 163792 | 366176 | 1801 | N |      |     |      |
| 45 | 164450 | 366193 | 2100 | Y | 2353 | 253 |      |
| 46 | 165113 | 366203 | 1964 | N |      |     |      |
| 47 | 163284 | 366209 | 2946 | N |      |     |      |
| 48 | 163237 | 366211 | 3281 | N |      |     |      |
| 49 | 164088 | 366219 | 2372 | N |      |     |      |
| 50 | 164075 | 366220 | 2412 | N | 2774 |     | 362  |
| 51 | 164075 | 366221 | 1770 | N |      |     |      |
| 52 | 163237 | 366228 | 3191 | N |      |     |      |
| 53 | 164854 | 366229 | 1467 | N |      |     |      |
| 54 | 161563 | 366238 | 1640 | N |      |     |      |
| 55 | 162130 | 366240 | 2782 | Y | 3468 | 686 |      |
| 56 | 162115 | 366241 | 1884 | N |      |     |      |
| 57 | 164451 | 366245 | 3389 | Y |      |     |      |
| 58 | 164084 | 366248 | 2503 | N | 2912 |     | 409  |
| 59 | 162347 | 366249 | 2367 | N |      |     |      |
| 60 | 162341 | 366252 | 2647 | N |      |     |      |
| 61 | 161567 | 366253 | 1711 | N | 3396 |     | 1685 |
| 62 | 163792 | 366254 | 1748 | N |      |     |      |
| 63 | 164075 | 366258 | 1379 | N |      |     |      |
| 64 | 161570 | 366261 | 3772 | N |      |     |      |
| 65 | 161566 | 366263 | 2339 | N |      |     |      |
| 66 | 164073 | 366264 | 1077 | N |      |     |      |
| 67 | 163789 | 366270 | 2643 | N |      |     |      |
| 68 | 163285 | 366271 | 2377 | N |      |     |      |
| 69 | 163786 | 366283 | 1905 | Y | 2313 | 408 |      |
| 70 | 162347 | 366285 | 2307 | N | 3849 |     | 1542 |
| 71 | 164455 | 366287 | 1163 | N |      |     |      |
| 72 | 164174 | 366303 | 1621 | N |      |     |      |
| 73 | 163234 | 366310 | 2651 | N |      |     |      |
| 74 | 164460 | 366322 | 1964 | N | 2623 |     | 659  |
| 75 | 162139 | 366323 | 2424 | N | 2931 |     | 517  |
| 76 | 163791 | 366334 | 2083 | N |      |     |      |
| 77 | 161556 | 366335 | 1933 | N |      |     |      |
| 78 | 164456 | 366338 | 1324 | N |      |     |      |
| 79 | 164455 | 366339 | 2402 | N |      |     |      |
| 80 | 163799 | 366340 | 2238 | N |      |     |      |
| 81 | 164100 | 366345 | 988  | N |      |     |      |
| 82 | 161567 | 366348 | 500  | N |      |     |      |

|     |        |        |      |   |      |      |      |
|-----|--------|--------|------|---|------|------|------|
| 83  | 162136 | 366354 | 1760 | Y | 2286 | 526  |      |
| 84  | 165122 | 366355 | 1046 | N |      |      |      |
| 85  | 163285 | 366357 | 1483 | N | 3773 |      | 2290 |
| 86  | 164451 | 366365 | 2208 | Y |      |      |      |
| 87  | 163286 | 366376 | 2661 | N |      |      |      |
| 88  | 164076 | 366378 | 1158 | N |      |      |      |
| 89  | 164458 | 366381 | 2237 | N |      |      |      |
| 90  | 163795 | 366384 | 2432 | N |      |      |      |
| 91  | 162117 | 366393 | 906  | N |      |      |      |
| 92  | 163795 | 366401 | 1240 | Y | 2101 | 861  |      |
| 93  | 165122 | 366403 | 325  | N | 1040 |      | 715  |
| 94  | 162115 | 366405 | 890  | N |      |      |      |
| 95  | 164455 | 366411 | 2389 | N | 3318 |      | 929  |
| 96  | 162131 | 366414 | 2281 | Y |      |      |      |
| 97  | 162139 | 366417 | 1692 | N |      |      |      |
| 98  | 164455 | 366418 | 1459 | Y |      |      |      |
| 99  | 164457 | 366432 | 2522 | Y |      |      |      |
| 100 | 164451 | 366434 | 2213 | Y | 2753 | 540  |      |
| 101 | 164098 | 366436 | 1590 | N |      |      |      |
| 102 | 164800 | 366451 | 1229 | N |      |      |      |
| 103 | 161554 | 366455 | 2605 | N |      |      |      |
| 104 | 164087 | 366457 | 2067 | N |      |      |      |
| 105 | 164447 | 366460 | 1721 | N | 3480 |      | 1759 |
| 106 | 164095 | 366470 | 1423 | N |      |      |      |
| 107 | 164449 | 366472 | 1076 | N |      |      |      |
| 108 | 163799 | 366476 | 1413 | Y | 2199 | 786  |      |
| 109 | 162114 | 366478 | 3001 | N |      |      |      |
| 110 | 164084 | 366485 | 1854 | N | 2474 |      | 620  |
| 111 | 164458 | 366488 | 1534 | N |      |      |      |
| 112 | 164071 | 366493 | 1476 | N |      |      |      |
| 113 | 164084 | 366499 | 1686 | N |      |      |      |
| 114 | 162139 | 366505 | 1626 | Y | 2920 | 1294 |      |
| 115 | 163288 | 366516 | 1062 | N |      |      |      |
| 116 | 162117 | 366518 | 1906 | Y |      |      |      |
| 117 | 162131 | 366521 | 1900 | N |      |      |      |
| 118 | 161565 | 366522 | 1208 | Y |      |      |      |
| 119 | 163784 | 366523 | 1953 | Y |      |      |      |
| 120 | 163286 | 366527 | 2448 | N |      |      |      |
| 121 | 164609 | 366531 | 1458 | N |      |      |      |
| 122 | 164456 | 366532 | 2535 | N | 5285 |      | 2750 |
| 123 | 163795 | 366550 | 1548 | N |      |      |      |
| 124 | 165259 | 366551 | 1884 | N |      |      |      |
| 125 | 164447 | 366552 | 1871 | N |      |      |      |
| 126 | 164610 | 366554 | 826  | N |      |      |      |
| 127 | 164460 | 366558 | 1951 | N |      |      |      |

---

|     |        |        |      |   |      |      |
|-----|--------|--------|------|---|------|------|
| 128 | 164103 | 366562 | 2201 | N |      |      |
| 129 | 164609 | 366568 | 1601 | N |      |      |
| 130 | 164854 | 366575 | 2212 | N |      |      |
| 131 | 165256 | 366579 | 431  | N |      |      |
| 132 | 163234 | 366589 | 2407 | N |      |      |
| 133 | 162128 | 366595 | 1589 | Y |      |      |
| 134 | 164797 | 366608 | 2868 | Y |      |      |
| 135 | 164459 | 366613 | 1284 | N |      |      |
| 136 | 164617 | 366618 | 1237 | N |      |      |
| 137 | 164620 | 366631 | 1671 | N |      |      |
| 138 | 164076 | 366657 | 1273 | N |      |      |
| 139 | 164620 | 366671 | 1671 | N |      |      |
| 140 | 164797 | 366676 | 1390 | N |      |      |
| 141 | 164100 | 366683 | 1055 | Y | 1475 | 420  |
| 142 | 164610 | 366694 | 845  | Y |      |      |
| 143 | 164087 | 366697 | 1072 | N |      |      |
| 144 | 164812 | 366707 | 62   | Y |      |      |
| 145 | 161554 | 366708 | 512  | N |      |      |
| 146 | 161560 | 366714 | 1637 | N |      |      |
| 147 | 161556 | 366715 | 1637 | Y |      |      |
| 148 | 164449 | 366727 | 1438 | N | 2667 | 1229 |
| 149 | 163791 | 366728 | 911  | N |      |      |
| 150 | 164614 | 366729 | 218  | N |      |      |
| 151 | 162121 | 366739 | 1549 | N |      |      |
| 152 | 164075 | 366741 | 1197 | Y |      |      |
| 153 | 164800 | 366764 | 1662 | N |      |      |
| 154 | 161561 | 366765 | 1662 | N |      |      |
| 155 | 161565 | 366786 | 2007 | Y | 2451 | 1444 |
| 156 | 163789 | 366794 | 455  | N |      |      |
| 157 | 164841 | 366797 | 1334 | N |      |      |
| 158 | 162341 | 366800 | 4513 | N | 9560 | 5047 |
| 159 | 164609 | 366814 | 399  | Y |      |      |
| 160 | 165122 | 366821 | 990  | N | 1445 | 455  |
| 161 | 165259 | 366885 | 658  | N |      |      |

---

**APPENDIX B. TAIL ROTOR BLADES THAT RECEIVED UNSCHEDULED  
MAINTENANCE IN 1996**

|    | BUREAU<br>NUMBER | SERIAL<br>NUMBER | TIME AT<br>MAINTENANCE | CANN<br>Y/N | TIME AT<br>FAILURE | TIME<br>BEFORE<br>FAILURE<br>CANN | TIME<br>BEFORE<br>FAILURE<br>NON-<br>CANN |
|----|------------------|------------------|------------------------|-------------|--------------------|-----------------------------------|---|
| 1  | 164179           | A23800011        | 1906                   | N           | 3023               |                                   | 1117                                      |
| 2  | 164445           | A23800016        | 2503                   | Y           |                    |                                   |   |
| 3  | 163238           | A23800028        | 4880                   | N           | 5626               |                                   | 746                                       |
| 4  | 164858           | A23800035        | 1906                   | N           | 3521               |                                   | 1615                                      |
| 5  | 163791           | A23800037        | 1015                   | N           |                    |                                   |   |
| 6  | 162990           | A23800039        | 2006                   | N           |                    |                                   |   |
| 7  | 162341           | A23800043        | 4413                   | N           | 5039               |                                   | 626                                       |
| 8  | 162121           | A23800058        | 4150                   | Y           | 4878               | 728                               |   |
| 9  | 164098           | A23800061        | 2158                   | N           |                    |                                   |   |
| 10 | 163238           | A23800064        | 3969                   | N           |                    |                                   |   |
| 11 | 163286           | A23800073        | 3011                   | N           |                    |                                   |   |
| 12 | 164101           | A23800076        | 2852                   | Y           |                    |                                   |   |
| 13 | 162989           | A23800083        | 2787                   | N           |                    |                                   |   |
| 14 | 162115           | A23800089        | 4150                   | N           |                    |                                   |   |
| 15 | 163286           | A23800098        | 3011                   | N           |                    |                                   |   |
| 16 | 163905           | A23800099        | 3429                   | Y           | 4550               |                                   | 1121                                      |
| 17 | 164849           | A23800100        | 2383                   | N           |                    |                                   |   |
| 18 | 162127           | A23800101        | 3839                   | Y           |                    |                                   |   |
| 19 | 164097           | A23800103        | 1424                   | N           |                    |                                   |   |
| 20 | 164445           | A23800113        | 2361                   | N           |                    |                                   |   |
| 21 | 162989           | A23800125        | 7819                   | N           |                    |                                   |   |
| 22 | 164080           | A23800128        | 2457                   | N           |                    |                                   |   |
| 23 | 162125           | A23800130        | 3276                   | N           | 4097               |                                   | 821                                       |
| 24 | 162330           | A23800133        | 4980                   | N           |                    |                                   |   |
| 25 | 162120           | A23800134        | 4032                   | N           |                    |                                   |   |
| 26 | 164801           | A23800136        | 823                    | N           | 1148               |                                   | 325                                       |
| 27 | 164798           | A23800141        | 1404                   | N           |                    |                                   |   |
| 28 | 162111           | A23800168        | 1894                   | N           |                    |                                   |   |
| 29 | 163248           | A23800183        | 4455                   | N           |                    |                                   |   |
| 30 | 164463           | A23800189        | 1258                   | N           |                    |                                   |   |
| 31 | 164092           | A23800196        | 2977                   | N           |                    |                                   |   |
| 32 | 163246           | A23800197        | 5386                   | N           |                    |                                   |   |
| 33 | 162984           | A23800203        | 1106                   | Y           | 1231               | 125                               |   |
| 34 | 164102           | A23800213        | 1543                   | N           | 7964               |                                   | 6421                                      |
| 35 | 164615           | A23800225        | 1652                   | N           |                    |                                   |   |
| 36 | 164098           | A23800230        | 2158                   | N           |                    |                                   |   |
| 37 | 164076           | A23800231        | 2939                   | Y           |                    |                                   |   |
| 38 | 161561           | A23800234        | 3123                   | N           |                    |                                   |   |

|    |        |           |      |   |      |      |      |
|----|--------|-----------|------|---|------|------|------|
| 39 | 161566 | A23800237 | 5630 | N |      |      |      |
| 40 | 162130 | A23800239 | 3496 | N | 5941 |      | 2445 |
| 41 | 164445 | A23800242 | 2503 | N |      |      |      |
| 42 | 164086 | A23800248 | 1906 | N | 3581 |      | 1675 |
| 43 | 164841 | A23800249 | 2940 | N |      |      |      |
| 44 | 162101 | A23800259 | 3649 | N |      |      |      |
| 45 | 163796 | A23800260 | 1981 | Y | 2010 | 29   |      |
| 46 | 162117 | A23800269 | 6982 | N |      |      |      |
| 47 | 164080 | A23800275 | 2457 | N | 4081 |      | 1624 |
| 48 | 162114 | A23800282 | 7212 | N |      |      |      |
| 49 | 162332 | A23800283 | 4332 | N |      |      |      |
| 50 | 164179 | A23800288 | 2702 | N |      |      |      |
| 51 | 164850 | A23800292 | 1393 | N | 1903 |      | 510  |
| 52 | 163241 | A23800293 | 2692 | Y |      |      |      |
| 53 | 162121 | A23800296 | 4878 | N | 5479 |      | 601  |
| 54 | 162990 | A23800298 | 2915 | N | 3357 |      | 442  |
| 55 | 164175 | A23800301 | 2026 | N |      |      |      |
| 56 | 162136 | A23800305 | 346  | N |      |      |      |
| 57 | 163243 | A23800314 | 4666 | Y | 5598 | 932  |      |
| 58 | 162128 | A23800315 | 3810 | N |      |      |      |
| 59 | 163799 | A23800318 | 2398 | N | 5441 |      | 3043 |
| 60 | 162986 | A23800320 | 6214 | N |      |      |      |
| 61 | 162099 | A23800321 | 3981 | N |      |      |      |
| 62 | 163243 | A23800323 | 4841 | N |      |      |      |
| 63 | 164463 | A23800328 | 2931 | N |      |      |      |
| 64 | 162094 | A23800337 | 6634 | N | 8293 |      | 1659 |
| 65 | 163237 | A23800339 | 5479 | N |      |      |      |
| 66 | 162982 | A23800342 | 4462 | N | 5077 |      | 615  |
| 67 | 164459 | A23800344 | 1803 | N |      |      |      |
| 68 | 162127 | A23800345 | 3839 | N | 5628 |      | 1789 |
| 69 | 163787 | A23800364 | 2734 | N |      |      |      |
| 70 | 162115 | A23800368 | 2929 | N |      |      |      |
| 71 | 163795 | A23800377 | 3359 | N |      |      |      |
| 72 | 164850 | A23800378 | 2493 | N | 2509 |      | 16   |
| 73 | 162095 | A23800379 | 7603 | Y |      |      |      |
| 74 | 162133 | A23800387 | 6997 | N |      |      |      |
| 75 | 162332 | A23800393 | 4332 | N |      |      |      |
| 76 | 164455 | A23800396 | 2390 | Y | 3226 | 836  |      |
| 77 | 162987 | A23800403 | 3830 | Y | 5206 | 1376 |      |
| 78 | 164102 | A23800406 | 1694 | N | 2852 |      | 1158 |
| 79 | 163235 | A23800411 | 4823 | Y | 4880 | 57   |      |
| 80 | 164618 | A23800416 | 2885 | N |      |      |      |
| 81 | 163242 | A23800417 | 4665 | N | 5324 |      | 659  |
| 82 | 162109 | A23800420 | 6079 | N |      |      |      |
| 83 | 162988 | A23800421 | 4623 | N |      |      |      |

|     |        |           |      |   |      |     |      |
|-----|--------|-----------|------|---|------|-----|------|
| 84  | 163790 | A23800422 | 2766 | N |      |     |      |
| 85  | 163798 | A23800424 | 1598 | N |      |     |      |
| 86  | 162114 | A23800440 | 7495 | Y | 7603 | 108 |      |
| 87  | 163792 | A23800443 | 4035 | N |      |     |      |
| 88  | 164858 | A23800445 | 1906 | N | 3918 |     | 2012 |
| 89  | 164075 | A23800461 | 2588 | N | 3411 |     | 823  |
| 90  | 164465 | A23800472 | 3903 | N | 4085 |     | 182  |
| 91  | 164086 | A23800480 | 1906 | Y |      |     |      |
| 92  | 163246 | A23800484 | 5386 | N |      |     |      |
| 93  | 163910 | A23800492 | 3305 | N | 4570 |     | 1265 |
| 94  | 163787 | A23800500 | 2010 | N |      |     |      |
| 95  | 164465 | A23800541 | 2958 | N |      |     |      |
| 96  | 164850 | A23800544 | 1750 | N | 3128 |     | 1378 |
| 97  | 162134 | A23800545 | 3805 | N |      |     |      |
| 98  | 162111 | A23800549 | 4611 | N |      |     |      |
| 99  | 161562 | A23800554 | 6490 | N | 8086 |     | 1596 |
| 100 | 162326 | A23800557 | 1581 | N |      |     |      |
| 101 | 163248 | A23800570 | 2772 | N |      |     |      |
| 102 | 163596 | A23800573 | 1316 | N |      |     |      |
| 103 | 163796 | A23800591 | 1981 | N |      |     |      |
| 104 | 162100 | A23800592 | 6381 | N | 6520 |     | 139  |
| 105 | 163800 | A23800600 | 1797 | N | 3303 |     | 1506 |
| 106 | 162989 | A23800603 | 2286 | Y | 2364 | 78  |      |
| 107 | 162133 | A23800612 | 3359 | N |      |     |      |
| 108 | 163799 | A23800615 | 2271 | N |      |     |      |
| 109 | 162125 | A23800622 | 2042 | Y | 2457 | 415 |      |
| 110 | 163905 | A23800624 | 3756 | N |      |     |      |
| 111 | 162333 | A23800635 | 4665 | N | 7203 |     | 2538 |
| 112 | 164082 | A23800636 | 2849 | N |      |     |      |
| 113 | 164448 | A23800640 | 3763 | Y |      |     |      |
| 114 | 164448 | A23800656 | 2157 | N |      |     |      |
| 115 | 161561 | A23800657 | 3123 | N |      |     |      |
| 116 | 164103 | A23800661 | 2913 | Y | 3139 | 226 |      |
| 117 | 163247 | A23800662 | 3256 | N |      |     |      |
| 118 | 164448 | A23800663 | 2309 | N |      |     |      |
| 119 | 164619 | A23800673 | 2141 | N | 3144 |     | 1003 |
| 120 | 163596 | A23800684 | 4089 | N |      |     |      |
| 121 | 162100 | A23800685 | 6520 | N | 7441 |     | 921  |
| 122 | 161564 | A23800686 | 5356 | N | 7105 |     | 1749 |
| 123 | 164457 | A23800688 | 2141 | N | 2500 |     | 359  |
| 124 | 163288 | A23800704 | 1909 | N | 2575 |     | 666  |
| 125 | 162123 | A23800718 | 1611 | Y | 2411 | 800 |      |
| 126 | 164092 | A23800723 | 2977 | N | 4741 |     | 1764 |
| 127 | 162338 | A23800726 | 8086 | Y |      |     |      |
| 128 | 164104 | A23800738 | 1909 | N |      |     |      |

|     |        |           |      |   |      |      |
|-----|--------|-----------|------|---|------|------|
| 129 | 164459 | A23800740 | 1803 | N |      |      |
| 130 | 163285 | A23800742 | 2500 | N |      |      |
| 131 | 164618 | A23800743 | 1351 | Y | 2683 | 1332 |
| 132 | 164453 | A23800744 | 2411 | N |      |      |
| 133 | 162109 | A23800753 | 2847 | N |      |      |
| 134 | 163790 | A23800754 | 2575 | N |      |      |
| 135 | 163787 | A23800755 | 2079 | N |      |      |
| 136 | 164618 | A23800763 | 435  | N |      |      |
| 137 | 163798 | A23800769 | 1598 | N |      |      |
| 138 | 164617 | A23800781 | 1154 | N | 2405 | 1251 |
| 139 | 162326 | A23800786 | 474  | N |      |      |
| 140 | 164617 | A23800791 | 1154 | N |      |      |
| 141 | 163795 | A23800796 | 4574 | N |      |      |
| 142 | 164104 | A23800804 | 1909 | N |      |      |
| 143 | 164617 | A23800817 | 1154 | N | 1404 | 250  |
| 144 | 164176 | A23800831 | 965  | N |      |      |
| 145 | 165120 | A23800834 | 1944 | N |      |      |
| 146 | 164444 | A23800839 | 2325 | N |      |      |
| 147 | 164448 | A23800840 | 2575 | N |      |      |
| 148 | 163233 | A23800845 | 2200 | N |      |      |
| 149 | 162095 | A23800846 | 7603 | N |      |      |
| 150 | 164449 | A23800850 | 2747 | N |      |      |
| 151 | 163796 | A23800853 | 981  | N |      |      |
| 152 | 162115 | A23800854 | 4150 | N |      |      |
| 153 | 164082 | A23800857 | 2849 | N |      |      |
| 154 | 164454 | A23800863 | 2131 | N |      |      |
| 155 | 163910 | A23800868 | 1816 | N |      |      |
| 156 | 164850 | A23800873 | 1089 | N |      |      |
| 157 | 165120 | A23800875 | 2013 | N |      |      |
| 158 | 164103 | A23800889 | 2241 | N |      |      |
| 159 | 164448 | A23800890 | 2287 | Y | 2431 | 144  |
| 160 | 163242 | A23800900 | 5324 | N |      |      |
| 161 | 164103 | A23800905 | 2696 | N | 7096 | 4400 |
| 162 | 164460 | A23800912 | 2148 | N |      |      |
| 163 | 162333 | A23800915 | 1027 | N |      |      |
| 164 | 163594 | A23800917 | 4590 | N |      |      |
| 165 | 162124 | A23800923 | 2356 | N |      |      |
| 166 | 164446 | A23800927 | 2431 | N | 2727 | 296  |
| 167 | 162095 | A23800935 | 3123 | Y | 3297 | 174  |
| 168 | 162112 | A23800937 | 6924 | N |      |      |
| 169 | 164455 | A23800938 | 2390 | N |      |      |
| 170 | 163237 | A23800941 | 5479 | N | 6392 | 913  |
| 171 | 162130 | A23800948 | 5941 | N |      |      |
| 172 | 163905 | A23800951 | 1973 | N | 2696 | 723  |
| 173 | 162338 | A23800973 | 2313 | Y |      |      |

|     |        |           |      |   |      |      |
|-----|--------|-----------|------|---|------|------|
| 174 | 162112 | A23800974 | 1922 | N |      |      |
| 175 | 162102 | A23800983 | 306  | N |      |      |
| 176 | 164798 | A23800991 | 1404 | Y |      |      |
| 177 | 164069 | A23800994 | 475  | N |      |      |
| 178 | 164797 | A23800998 | 1390 | N |      |      |
| 179 | 162128 | A23801005 | 3810 | N |      |      |
| 180 | 164618 | A23801006 | 1182 | N |      |      |
| 181 | 164618 | A23801007 | 1580 | N |      |      |
| 182 | 164850 | A23801013 | 2705 | N |      |      |
| 183 | 162103 | A23801014 | 1519 | N |      |      |
| 184 | 164457 | A23801017 | 2141 | Y | 2823 | 682  |
| 185 | 162984 | A23801020 | 1573 | N |      |      |
| 186 | 163238 | A23801022 | 4880 | N |      |      |
| 187 | 164175 | A23801028 | 3361 | N | 8218 | 4857 |
| 188 | 162134 | A23801030 | 1458 | Y |      |      |
| 189 | 164850 | A23801031 | 1106 | N |      |      |
| 190 | 162114 | A23801032 | 7495 | Y | 8382 | 887  |
| 191 | 164614 | A23801038 | 1141 | N |      |      |
| 192 | 161561 | A23801042 | 3123 | Y |      |      |
| 193 | 164797 | A23801043 | 1390 | N |      |      |
| 194 | 163905 | A23801057 | 6377 | N |      |      |
| 195 | 162099 | A23801058 | 810  | Y |      |      |
| 196 | 163249 | A23801059 | 1330 | N |      |      |
| 197 | 164459 | A23801060 | 1163 | Y | 1435 | 272  |
| 198 | 163284 | A23801069 | 2913 | Y | 4081 | 1168 |
| 199 | 164798 | A23801070 | 1404 | N |      |      |
| 200 | 163800 | A23801083 | 1797 | N |      |      |
| 201 | 162338 | A23801094 | 8086 | Y | 8857 | 771  |
| 202 | 164801 | A23801101 | 1148 | N | 2308 | 1160 |
| 203 | 164858 | A23801112 | 1906 | Y |      |      |
| 204 | 162341 | A23801114 | 1335 | Y |      |      |
| 205 | 163910 | A23801116 | 3305 | N | 4301 | 996  |
| 206 | 164811 | A23801133 | 1820 | N |      |      |
| 207 | 164858 | A23801137 | 1906 | Y | 5878 | 3972 |
| 208 | 164841 | A23801154 | 1202 | N |      |      |
| 209 | 164842 | A23801156 | 895  | N |      |      |
| 210 | 164816 | A23801157 | 589  | N |      |      |
| 211 | 164080 | A23801161 | 2457 | N | 3884 | 1427 |
| 212 | 164846 | A23801178 | 243  | N |      |      |
| 213 | 165121 | A23801180 | 959  | N |      |      |
| 214 | 165121 | A23801181 | 1073 | N |      |      |
| 215 | 162984 | A23801183 | 406  | Y | 2337 | 1931 |
| 216 | 162986 | A23801195 | 6214 | N |      |      |
| 217 | 162109 | A23801210 | 6392 | N |      |      |
| 218 | 161566 | A23801234 | 5629 | N | 6221 | 592  |

---

|     |        |           |      |   |     |     |
|-----|--------|-----------|------|---|-----|-----|
| 219 | 161569 | A23801235 | 5403 | N |     |     |
| 220 | 164615 | A23801238 | 1652 | N |     |     |
| 221 | 165114 | A23801239 | 304  | N |     |     |
| 222 | 162338 | A23801242 | 8086 | Y |     |     |
| 223 | 165114 | A23801244 | 233  | N |     |     |
| 224 | 162130 | A23801246 | 5941 | N |     |     |
| 225 | 165114 | A23801251 | 233  | N | 936 | 703 |
| 226 | 164842 | A23801254 | 895  | N |     |     |
| 227 | 163243 | A23801259 | 4841 | N |     |     |
| 228 | 164849 | A23801267 | 2383 | N |     |     |
| 229 | 164082 | A27200872 | 2679 | N |     |     |
| 230 | 164842 | A28301156 | 895  | N |     |     |
| 231 | 164454 | A32800128 | 2457 | N |     |     |
| 232 | 164850 | A39803965 | 2926 | N |     |     |
| 233 | 165114 | A39808940 | 233  | N |     |     |

---

**APPENDIX C. AUXILIARY POWER ELECTRONIC CONTROL UNITS THAT  
RECEIVED UNSCHEDULED MAINTENANCE IN 1996**

|    | <b>BUREAU<br/>NUMBER</b> | <b>SERIAL<br/>NUMBER</b> | <b>TIME at<br/>MAINTENANCE</b> | <b>CANN<br/>Y/N</b> | <b>TIME AT<br/>FAILURE</b> | <b>TIME BEFORE<br/>FAILURE<br/>CANN</b> | <b>TIME<br/>BEFORE<br/>FAILURE<br/>NON-<br/>CANN</b> |
|----|--------------------------|--------------------------|--------------------------------|---------------------|----------------------------|---|--|
| 1  | 162131                   | 73750239                 | 5573                           | N                   |                            |   |  |
| 2  | 163907                   | 73750063                 | 3165                           | N                   |                            |   |  |
| 3  | 162982                   | 73750377                 | 4697                           | N                   | 5009                       |   | 312  |
| 4  | 163286                   | 73750495                 | 3076                           | N                   |                            |   |  |
| 5  | 163906                   | 73750602                 | 4064                           | N                   | 5504                       |   | 1440   |
| 6  | 163235                   | 73750642                 | 5009                           | N                   |                            |   |  |
| 7  | 164082                   | 73750661                 | 2848                           | Y                   |                            |   |  |
| 8  | 165107                   | 73750691                 | 602                            | N                   |                            |   |  |
| 9  | 162975                   | 73750704                 | 3975                           | N                   |                            |   |  |
| 10 | 163906                   | 73750756                 | 4064                           | Y                   | 5504                       | 1440                                    |  |
| 11 | 163259                   | 73750757                 | 2438                           | N                   |                            |   |  |
| 12 | 162124                   | 73750778                 | 4892                           | N                   |                            |   |  |
| 13 | 164809                   | 73750787                 | 1498                           | N                   |                            |   |  |
| 14 | 163598                   | 73750819                 | 4424                           | N                   |                            |   |  |
| 15 | 162982                   | 73750829                 | 4697                           | N                   |                            |   |  |
| 16 | 163905                   | 73750832                 | 3429                           | N                   | 4579                       |   | 1150   |
| 17 | 162344                   | 73750833                 | 6120                           | N                   |                            |   |  |
| 18 | 163797                   | 73750881                 | 1912                           | Y                   |                            |   |  |
| 19 | 164099                   | 75840075                 | 2476                           | Y                   |                            |   |  |
| 20 | 164081                   | 75840152                 | 2429                           | N                   |                            |   |  |
| 21 | 164466                   | 75840436                 | 3030                           | N                   |                            |   |  |
| 22 | 162136                   | 75840495                 | 6301                           | Y                   | 6724                       | 423                                     |  |
| 23 | 162095                   | 75840514                 | 4258                           | N                   | 7603                       |   | 3345   |
| 24 | 162333                   | 75840544                 | 6554                           | N                   |                            |   |  |
| 25 | 162136                   | 75840678                 | 6402                           | Y                   | 7264                       | 862                                     |  |
| 26 | 164463                   | 75840683                 | 3359                           | N                   |                            |   |  |
| 27 | 163593                   | 75840740                 | 4454                           | Y                   | 5077                       | 623                                     |  |
| 28 | 164849                   | 75840752                 | 2664                           | N                   |                            |   |  |
| 29 | 161554                   | 75840755                 | 570                            | N                   |                            |   |  |
| 30 | 162131                   | 75840880                 | 5577                           | Y                   |                            |   |  |
| 31 | 163797                   | 75840902                 | 1913                           | N                   | 2767                       |   | 854  |
| 32 | 162099                   | 75840913                 | 7305                           | Y                   | 7332                       | 27                                      |  |
| 33 | 162133                   | 75840924                 | 6514                           | N                   |                            |   |  |
| 34 | 164102                   | 75840987                 | 1141                           | Y                   |                            |   |  |
| 35 | 161567                   | 75841109                 | 5641                           | N                   | 8239                       |   | 2595   |
| 36 | 162115                   | 75841169                 | 4258                           | Y                   | 5617                       | 1359                                    |  |
| 37 | 161556                   | 75841250                 | 3601                           | Y                   | 4008                       | 407                                     |  |

|    |        |          |       |   |      |     |      |
|----|--------|----------|-------|---|------|-----|------|
| 38 | 162102 | 75841222 | 7006  | N |      |     |      |
| 39 | 163266 | 75841252 | 2454  | N |      |     |      |
| 40 | 163261 | 75841257 | 2366  | N |      |     |      |
| 41 | 162117 | 75841282 | 6816  | N |      |     |      |
| 42 | 173790 | 75841437 | 1912  | N | 2736 |     | 824  |
| 43 | 163284 | 75841548 | 2704  | N |      |     |      |
| 44 | 164445 | 75841560 | 2283  | N |      |     |      |
| 45 | 165095 | 75841566 | 1501  | N |      |     |      |
| 46 | 164081 | 75841578 | 2429  | N |      |     |      |
| 47 | 162133 | 75841580 | 6444  | N |      |     |      |
| 48 | 163233 | 75841683 | 5077  | N |      |     |      |
| 49 | 162104 | 75841715 | 1103  | N | 5494 |     | 4391 |
| 50 | 164447 | 75841813 | 2480  | Y | 2977 | 497 |      |
| 51 | 162095 | 75841820 | 7603  | N |      |     |      |
| 52 | 164101 | 75841935 | 2540  | Y |      |     |      |
| 53 | 164812 | 75842007 | 1317  | N |      |     |      |
| 54 | 164801 | 75842015 | 1103  | N |      |     |      |
| 55 | 164813 | 75842036 | 1199  | N |      |     |      |
| 56 | 164455 | 75842040 | 2390  | Y |      |     |      |
| 57 | 164450 | 75842058 | 2405  | N |      |     |      |
| 58 | 162985 | 75842509 | 4350  | N |      |     |      |
| 59 | 162123 | 75842537 | 6381  | N |      |     |      |
| 60 | 163794 | 75842547 | 28774 | Y |      |     |      |
| 61 | 163795 | 75842576 | 3345  | N |      |     |      |

**APPENDIX D. T700-GE-401C CANNIBALIZED 1995-1999**

|    | <b>Bureau<br/>Number</b> | <b>Serial<br/>Number</b> | <b>Engine Hrs at<br/>Cannibalization</b> |
|----|--------------------------|--------------------------|--|
| 1  | 162100                   | 366321                   | 1818                                     |
| 2  | 163791                   | 366023                   | 1880                                     |
| 3  | 163791                   | 366155                   | 2516                                     |
| 4  | 164102                   | 366420                   | 846                                      |
| 5  | 164102                   | 366143                   | 846                                      |
| 6  | 162128                   | 366135                   | 2921                                     |
| 7  | 162128                   | 366595                   | 1589                                     |
| 8  | 162130                   | 366240                   | 2782                                     |
| 9  | 164455                   | 366418                   | 1459                                     |
| 10 | 164455                   | 366084                   | 2462                                     |
| 11 | 164461                   | 366786                   | 2007                                     |
| 12 | 164451                   | 366365                   | 2208                                     |
| 13 | 164451                   | 366434                   | 2213                                     |
| 14 | 164451                   | 366245                   | 3389                                     |
| 15 | 164451                   | 366505                   | 1626                                     |
| 16 | 163784                   | 366523                   | 1953                                     |
| 17 | 163784                   | 366097                   | 2556                                     |
| 18 | 164450                   | 366401                   | 1240                                     |
| 19 | 164450                   | 366193                   | 2100                                     |
| 20 | 163786                   | 366476                   | 1413                                     |
| 21 | 163786                   | 366283                   | 1905                                     |
| 22 | 162136                   | 366354                   | 1760                                     |
| 23 | 162136                   | 366814                   | 398                                      |
| 24 | 163247                   | 236682                   | 676                                      |
| 25 | 163247                   | 366707                   | 676                                      |
| 26 | 164610                   | 366694                   | 845                                      |
| 27 | 164610                   | 388201                   | 2085                                     |
| 28 | 164071                   | 366067                   | 3794                                     |
| 29 | 164075                   | 366741                   | 1197                                     |
| 30 | 164798                   | 366608                   | 2869                                     |
| 31 | 161559                   | 366715                   | 1641                                     |
| 32 | 164610                   | 366201                   | 2907                                     |
| 33 | 164610                   | 366775                   | 2907                                     |
| 34 | 164072                   | 366642                   | 2026                                     |
| 35 | 164457                   | 366723                   | 889                                      |
| 36 | 164457                   | 366416                   | 2570                                     |
| 37 | 164810                   | 366527                   | 2938                                     |
| 38 | 164810                   | 366220                   | 2774                                     |
| 39 | 163596                   | 366800                   | 1407                                     |

---

|    |        |        |      |
|----|--------|--------|------|
| 40 | 163596 | 366646 | 1407 |
| 41 | 165258 | 366871 | 1101 |
| 42 | 165258 | 366609 | 1100 |
| 43 | 162114 | 366683 | 1055 |
| 44 | 162114 | 366362 | 2740 |
| 45 | 162330 | 366216 | 3276 |
| 46 | 161565 | 366668 | 1657 |
| 47 | 164798 | 366750 | 1849 |
| 48 | 164798 | 366443 | 1849 |
| 49 | 162327 | 366147 | 2250 |
| 50 | 162327 | 366629 | 2928 |
| 51 | 161565 | 366279 | 4809 |
| 52 | 161565 | 366230 | 4809 |
| 53 | 161554 | 366066 | 3980 |
| 54 | 161554 | 366477 | 1854 |
| 55 | 162127 | 366072 | 1904 |
| 56 | 162127 | 366350 | 1873 |
| 57 | 162349 | 366839 | 960  |
| 58 | 162349 | 366700 | 1043 |
| 59 | 164446 | 366308 | 202  |
| 60 | 164446 | 366219 | 202  |
| 61 | 161566 | 366520 | 2276 |
| 62 | 164614 | 366156 | 3077 |
| 63 | 164614 | 366143 | 1789 |
| 64 | 164446 | 366718 | 2732 |
| 65 | 164101 | 366149 | 2655 |
| 66 | 161556 | 366532 | 5285 |
| 67 | 164465 | 366581 | 3277 |
| 68 | 164465 | 366016 | 2341 |
| 69 | 162099 | 366240 | 2783 |
| 70 | 164088 | 366582 | 1251 |
| 71 | 163285 | 366778 | 1462 |
| 72 | 163285 | 366315 | 1462 |
| 73 | 161556 | 366114 | 3297 |
| 74 | 161556 | 366064 | 3515 |
| 75 | 164445 | 366613 | 1518 |
| 76 | 163285 | 366733 | 1139 |
| 77 | 164609 | 366026 | 4840 |
| 78 | 162988 | 366692 | 2067 |
| 79 | 162988 | 366745 | 2067 |
| 80 | 163906 | 366266 | 3586 |
| 81 | 162124 | 366433 | 3706 |
| 82 | 165258 | 366300 | 1663 |

---

---

|     |        |        |      |
|-----|--------|--------|------|
| 83  | 163906 | 366853 | 675  |
| 84  | 163906 | 366266 | 3586 |
| 85  | 164450 | 366119 | 1276 |
| 86  | 164450 | 366034 | 1276 |
| 87  | 164610 | 366183 | 1349 |
| 88  | 164610 | 366345 | 1118 |
| 89  | 164450 | 366193 | 2100 |
| 90  | 164450 | 366430 | 3450 |
| 91  | 162124 | 366362 | 2970 |
| 92  | 162124 | 366773 | 1808 |
| 93  | 162327 | 366800 | 1711 |
| 94  | 162327 | 366727 | 2667 |
| 95  | 164453 | 366831 | 1811 |
| 96  | 164610 | 366790 | 2051 |
| 97  | 163287 | 366468 | 1249 |
| 98  | 163287 | 366357 | 1483 |
| 99  | 162341 | 366853 | 984  |
| 100 | 162341 | 366693 | 1954 |
| 101 | 162341 | 366460 | 3480 |
| 102 | 162330 | 366106 | 2630 |
| 103 | 162330 | 366669 | 3553 |
| 104 | 164081 | 366380 | 3460 |
| 105 | 164081 | 366229 | 2791 |
| 106 | 162341 | 366615 | 7529 |
| 107 | 162341 | 366693 | 7529 |
| 108 | 164798 | 366331 | 2609 |
| 109 | 163284 | 366609 | 3302 |
| 110 | 163284 | 366338 | 3150 |
| 111 | 164072 | 366485 | 2474 |
| 112 | 164072 | 366522 | 1880 |
| 113 | 162126 | 366665 | 5807 |
| 114 | 162126 | 366200 | 4143 |
| 115 | 164449 | 366308 | 3321 |
| 116 | 164449 | 366485 | 2474 |
| 117 | 164615 | 366469 | 3593 |
| 118 | 164615 | 366013 | 4964 |
| 119 | 162104 | 366179 | 3869 |
| 120 | 162104 | 366886 | 1278 |
| 121 | 163794 | 366448 | 2497 |
| 122 | 164803 | 366074 | 2126 |
| 123 | 164449 | 366191 | 2797 |
| 124 | 164449 | 366308 | 3321 |
| 125 | 161569 | 366853 | 985  |

---

---

|     |        |        |      |
|-----|--------|--------|------|
| 126 | 164443 | 366024 | 1564 |
| 127 | 164443 | 366661 | 2209 |
| 128 | 164450 | 366018 | 4395 |
| 129 | 164450 | 366449 | 3042 |
| 130 | 164450 | 366026 | 5368 |
| 131 | 164450 | 366139 | 4233 |
| 132 | 161568 | 366542 | 2845 |
| 133 | 161568 | 366671 | 2845 |
| 134 | 164841 | 366583 | 3246 |

---

**APPENDIX E. TAIL ROTOR BLADES CANNIBALIZED 1995-1999**

---

|    | <b>Bureau<br/>Number</b> | <b>Serial Number</b> | <b>Flight Hrs at<br/>Cannibalization</b> |
|----|--------------------------|----------------------|--|
| 1  | 164178                   | A23801023            | 2822                                     |
| 2  | 162125                   | A23800720            | 1963                                     |
| 3  | 162125                   | A23800622            | 2702                                     |
| 4  | 163797                   | A23800754            | 2074                                     |
| 5  | 164102                   | A28300123            | 1141                                     |
| 6  | 164102                   | A28300213            | 1141                                     |
| 7  | 162105                   | A23800488            | 4121                                     |
| 8  | 162105                   | A23800596            | 0  |
| 9  | 164457                   | A23800124            | 2057                                     |
| 10 | 164457                   | A23800688            | 2057                                     |
| 11 | 164457                   | A23500162            | 2057                                     |
| 12 | 164457                   | A23801005            | 2057                                     |
| 13 | 162123                   | A23800995            | 1927                                     |
| 14 | 162123                   | A23801002            | 4309                                     |
| 15 | 162123                   | A23800426            | 4309                                     |
| 16 | 162123                   | A23800351            | 3386                                     |
| 17 | 164081                   | A23800275            | 2429                                     |
| 18 | 164081                   | A23800734            | 2429                                     |
| 19 | 163784                   | A23800641            | 2264                                     |
| 20 | 163784                   | A23801061            | 2264                                     |
| 21 | 163784                   | A23800110            | 2664                                     |
| 22 | 163784                   | A23801018            | 2664                                     |
| 23 | 163784                   | A23800312            | 2664                                     |
| 24 | 162139                   | A23800622            | 2764                                     |
| 25 | 162139                   | A23800773            | 1678                                     |
| 26 | 164102                   | A23800776            | 1855                                     |
| 27 | 164102                   | A23800759            | 1141                                     |
| 28 | 164100                   | A23800776            | 1855                                     |
| 29 | 164100                   | A2380035             | 2617                                     |
| 30 | 164099                   | A23800997            | 2783                                     |
| 31 | 164099                   | A23800396            | 2022                                     |
| 32 | 164099                   | A23800294            | 1811                                     |
| 33 | 162136                   | A23800301            | 2026                                     |
| 34 | 162136                   | A23800305            | 346                                      |
| 35 | 164086                   | A23800480            | 1906                                     |
| 36 | 164086                   | A23800248            | 1906                                     |
| 37 | 164797                   | A23801043            | 1390                                     |
| 38 | 164797                   | A23801047            | 1390                                     |
| 39 | 164797                   | A23801060            | 1390                                     |

---

---

|    |        |           |      |
|----|--------|-----------|------|
| 40 | 164797 | A23800998 | 1390 |
| 41 | 161562 | A23801094 | 6490 |
| 42 | 161562 | A23800726 | 6490 |
| 43 | 162338 | A23801242 | 8086 |
| 44 | 162338 | A23800554 | 8086 |
| 45 | 162338 | A23800726 | 8086 |
| 46 | 162338 | A23801094 | 8086 |
| 47 | 164455 | A23800396 | 2390 |
| 48 | 164804 | A23800113 | 4158 |
| 49 | 164804 | A23800282 | 2776 |
| 50 | 164071 | A23800314 | 4666 |
| 51 | 164071 | A23800688 | 2337 |
| 52 | 162128 | A23801005 | 3810 |
| 53 | 162128 | A23800570 | 3810 |
| 54 | 162128 | A23801032 | 3810 |
| 55 | 162128 | A23800315 | 3810 |
| 56 | 164082 | A23800857 | 2849 |
| 57 | 163241 | A23800293 | 2692 |
| 58 | 163241 | A23800403 | 3830 |
| 59 | 162112 | A23801210 | 6924 |
| 60 | 162112 | A23800937 | 6924 |
| 61 | 164448 | A23800890 | 2287 |
| 62 | 164448 | A23801180 | 2287 |
| 63 | 162127 | A23800101 | 3839 |
| 64 | 162127 | A23800345 | 3839 |
| 65 | 164101 | A23800406 | 2852 |
| 66 | 163238 | A23800411 | 4880 |
| 67 | 163238 | A23800028 | 4880 |
| 68 | 162338 | A23800973 | 2313 |
| 69 | 161561 | A23800935 | 3123 |
| 70 | 161561 | A23800657 | 3123 |
| 71 | 161561 | A23800234 | 3123 |
| 72 | 161561 | A23801042 | 3123 |
| 73 | 162984 | A23801183 | 406  |
| 74 | 162984 | A23800203 | 1106 |
| 75 | 162095 | A23800379 | 7603 |
| 76 | 162095 | A23800234 | 3123 |
| 77 | 162989 | A23800603 | 2286 |
| 78 | 163284 | A23800661 | 2913 |
| 79 | 163284 | A23801069 | 2913 |
| 80 | 162095 | A23800846 | 7603 |
| 81 | 162095 | A23800440 | 2411 |
| 82 | 162095 | A23800379 | 7603 |
| 83 | 161554 | A23801030 | 1458 |
| 84 | 164618 | A23800743 | 1351 |

---

|     |        |           |      |
|-----|--------|-----------|------|
| 85  | 164618 | A23800416 | 2285 |
| 86  | 164071 | A23801183 | 2337 |
| 87  | 164071 | A23801013 | 2337 |
| 88  | 164446 | A23800890 | 2431 |
| 89  | 164446 | A23800927 | 2431 |
| 90  | 164448 | A23800640 | 3763 |
| 91  | 164448 | A23800656 | 2037 |
| 92  | 161566 | A23800237 | 5630 |
| 93  | 161566 | A23801234 | 5629 |
| 94  | 161569 | A23800983 | 5403 |
| 95  | 161569 | A23801235 | 5403 |
| 96  | 163796 | A23800591 | 1981 |
| 97  | 163796 | A23800260 | 1981 |
| 98  | 163796 | A23800500 | 1981 |
| 99  | 163796 | A23800853 | 1981 |
| 100 | 164097 | A23800103 | 1424 |
| 101 | 164619 | A23801017 | 2141 |
| 102 | 164619 | A23800673 | 2141 |
| 103 | 162982 | A23801059 | 1330 |
| 104 | 162982 | A23800342 | 4462 |
| 105 | 164618 | A23801006 | 1182 |
| 106 | 164618 | A23800763 | 435  |
| 107 | 162115 | A23800058 | 4150 |
| 108 | 162115 | A23800854 | 4150 |
| 109 | 162115 | A23800368 | 2929 |
| 110 | 162115 | A23800089 | 4150 |
| 111 | 162111 | A23800549 | 4611 |
| 112 | 162111 | A23800168 | 1894 |
| 113 | 164453 | A23800744 | 2411 |
| 114 | 164453 | A23800440 | 2411 |
| 115 | 164454 | A23800863 | 2131 |
| 116 | 164454 | A32800128 | 2457 |
| 117 | 164798 | A23800991 | 1404 |
| 118 | 164798 | A23800141 | 1404 |
| 119 | 164798 | A23800817 | 1404 |
| 120 | 164798 | A23801070 | 1404 |
| 121 | 164445 | A23800016 | 2503 |
| 122 | 164445 | A23800242 | 2503 |
| 123 | 164619 | A23800756 | 2307 |
| 124 | 164619 | A23800162 | 2307 |
| 125 | 164619 | A23800697 | 2307 |
| 126 | 164619 | A23800756 | 2307 |
| 127 | 164619 | A23801379 | 2307 |
| 128 | 164074 | A23801124 | 3601 |
| 129 | 164074 | A23806850 | 3601 |

---

|     |        |           |      |
|-----|--------|-----------|------|
| 130 | 164074 | A23800737 | 3601 |
| 131 | 164074 | A23801048 | 3601 |
| 132 | 162099 | A23801058 | 7683 |
| 133 | 162099 | A23800672 | 1115 |
| 134 | 162136 | A23801021 | 6402 |
| 135 | 162136 | A23801064 | 6402 |
| 136 | 162099 | A23800944 | 1944 |
| 137 | 162099 | A23800456 | 3917 |
| 138 | 163237 | A23807071 | 5938 |
| 139 | 163237 | A23800178 | 5938 |
| 140 | 164095 | A23800272 | 2887 |
| 141 | 164095 | A23800268 | 2887 |
| 142 | 164095 | A23800258 | 2887 |
| 143 | 164095 | A23801338 | 2887 |
| 144 | 162114 | A23800001 | 7747 |
| 145 | 162114 | A23801032 | 7747 |
| 146 | 164095 | A23800337 | 2887 |
| 147 | 162120 | A23801122 | 7018 |
| 148 | 164176 | A23801258 | 1373 |
| 149 | 164176 | A23800754 | 2074 |
| 150 | 165154 | A23801277 | 89   |
| 151 | 164449 | A23800889 | 2768 |
| 152 | 164101 | A23801306 | 2852 |
| 153 | 162122 | A23800957 | 3778 |
| 154 | 162122 | A23801028 | 1595 |
| 155 | 162327 | A23801114 | 7562 |
| 156 | 162327 | A23800628 | 7562 |
| 157 | 163249 | A23800231 | 6340 |
| 158 | 163249 | A23800622 | 6340 |
| 159 | 163249 | A23800689 | 6340 |
| 160 | 164070 | A23800148 | 1856 |
| 161 | 164070 | A23801313 | 1856 |
| 162 | 164449 | A23800871 | 2768 |
| 163 | 164449 | A23800880 | 2768 |
| 164 | 164614 | A23800971 | 2535 |
| 165 | 164614 | A23800292 | 2535 |
| 166 | 164086 | A23800066 | 1906 |
| 167 | 162348 | A23801161 | 6392 |
| 168 | 162348 | A23800847 | 6392 |
| 169 | 162348 | A23800941 | 6392 |
| 170 | 164086 | A23800011 | 1906 |
| 171 | 164445 | A23800608 | 2581 |
| 172 | 164445 | A23800682 | 2581 |
| 173 | 164817 | A23800450 | 1291 |
| 174 | 164817 | A23800318 | 1291 |

---

---

|     |        |           |      |
|-----|--------|-----------|------|
| 175 | 163249 | A23801265 | 6340 |
| 176 | 163249 | A23801115 | 6340 |
| 177 | 162335 | A23800372 | 7526 |
| 178 | 162335 | A23800213 | 1446 |
| 179 | 164085 | A23800162 | 3725 |
| 180 | 164085 | A23800250 | 3725 |
| 181 | 164070 | A23800412 | 1856 |
| 182 | 164070 | A23800879 | 1856 |
| 183 | 162122 | A23800957 | 8103 |
| 184 | 162109 | A23801161 | 7772 |
| 185 | 162109 | A23800969 | 6392 |
| 186 | 163233 | A23800342 | 5795 |
| 187 | 163233 | A23801265 | 5795 |
| 188 | 163233 | A23800751 | 5795 |
| 189 | 163233 | A23801115 | 5795 |
| 190 | 162335 | A23801058 | 811  |
| 191 | 162335 | A23800603 | 2364 |
| 192 | 164084 | A23800473 | 6116 |
| 193 | 164799 | A23800458 | 2499 |
| 194 | 164799 | A23801066 | 2499 |
| 195 | 162344 | A23801002 | 6513 |
| 196 | 162344 | A23800844 | 6724 |
| 197 | 164803 | A23800777 | 2595 |
| 198 | 164803 | A23800805 | 2595 |
| 199 | 162124 | A23800924 | 5627 |
| 200 | 162124 | A23800022 | 5627 |
| 201 | 164803 | A23800078 | 2595 |
| 202 | 164620 | A23800671 | 2665 |
| 203 | 164620 | A23801121 | 2665 |
| 204 | 164854 | A23801097 | 3401 |
| 205 | 164854 | A39810128 | 3401 |
| 206 | 164074 | A23800752 | 3601 |
| 207 | 164074 | A23200240 | 3601 |
| 208 | 164074 | A23800654 | 3719 |
| 209 | 164074 | A23801234 | 3601 |
| 210 | 164074 | A23800268 | 3601 |
| 211 | 164450 | A23800916 | 2745 |
| 212 | 164450 | A23800790 | 2978 |
| 213 | 164100 | A23801139 | 2678 |
| 214 | 164100 | A23802658 | 2678 |
| 215 | 163237 | A23800957 | 5938 |
| 216 | 163237 | A23800647 | 5938 |
| 217 | 164074 | A23801338 | 3601 |
| 218 | 164074 | A23800752 | 3601 |
| 219 | 162326 | A23800786 | 1611 |

---

---

|     |        |           |      |
|-----|--------|-----------|------|
| 220 | 162326 | A23801313 | 1611 |
| 221 | 164074 | A23800654 | 3719 |
| 222 | 164074 | A23801338 | 3601 |
| 223 | 164074 | A23806850 | 3601 |
| 224 | 164074 | A23801234 | 3601 |
| 225 | 164074 | A23800636 | 3601 |
| 226 | 164074 | A23801125 | 3601 |
| 227 | 164074 | A23800654 | 3601 |
| 228 | 164074 | A23801125 | 3601 |
| 229 | 164074 | A23800654 | 3601 |
| 230 | 162124 | A23800130 | 5627 |
| 231 | 162124 | A23800272 | 4346 |
| 232 | 164074 | A23801125 | 3601 |
| 233 | 162096 | A23800053 | 5016 |
| 234 | 162096 | A23800049 | 3658 |
| 235 | 164074 | A23801417 | 3601 |
| 236 | 164074 | A23801421 | 3601 |
| 237 | 164074 | A23801048 | 3601 |
| 238 | 164074 | A23800752 | 3601 |
| 239 | 164074 | A23801348 | 3601 |
| 240 | 164458 | A23800473 | 6116 |
| 241 | 164458 | A23800048 | 1820 |
| 242 | 162330 | A23800764 | 8364 |
| 243 | 162330 | A23801479 | 8364 |
| 244 | 163287 | A23801060 | 2926 |
| 245 | 163287 | A23800618 | 2926 |
| 246 | 163287 | A23800999 | 2926 |
| 247 | 164089 | A23800996 | 3032 |
| 248 | 162109 | A23800891 | 8209 |
| 249 | 162109 | A23801011 | 8209 |
| 250 | 164074 | A23800268 | 3601 |
| 251 | 164074 | A23800971 | 3601 |
| 252 | 164074 | A23801094 | 3601 |
| 253 | 163284 | A23801069 | 4101 |
| 254 | 163284 | A23800292 | 4101 |
| 255 | 164074 | A23800752 | 3601 |
| 256 | 162121 | A23800318 | 6335 |
| 257 | 162121 | A23800345 | 6335 |
| 258 | 162121 | A23800587 | 6051 |
| 259 | 163788 | A23801146 | 3439 |
| 260 | 163788 | A23800253 | 3439 |
| 261 | 162330 | A23801479 | 8364 |
| 262 | 162330 | A23800909 | 8364 |
| 263 | 162106 | A23801250 | 8103 |
| 264 | 162106 | A23801109 | 8103 |

---

**APPENDIX F. AUXILIARY POWER ELECTRONIC CONTROL UNITS  
CANNIBALIZED 1995-1999**

|    | <b>Bureau<br/>Number</b> | <b>Serial<br/>Number</b> | <b>Flight Hrs at<br/>Cannibalization</b> |
|----|--------------------------|--------------------------|--|
| 1  | 164449                   | 75842623                 | 2524                                     |
| 2  | 164099                   | 75840075                 | 2476                                     |
| 3  | 164099                   | 75841176                 | 2476                                     |
| 4  | 164447                   | 75841813                 | 2480                                     |
| 5  | 162131                   | 75840880                 | 5577                                     |
| 6  | 162131                   | 73750239                 | 5573                                     |
| 7  | 164455                   | 75842044                 | 2390                                     |
| 8  | 161556                   | 75841250                 | 3601                                     |
| 9  | 164797                   | 75842415                 | 1390                                     |
| 10 | 164082                   | 73750661                 | 2848                                     |
| 11 | 162136                   | 75840495                 | 6301                                     |
| 12 | 163906                   | 73750756                 | 4064                                     |
| 13 | 162095                   | 75841169                 | 4258                                     |
| 14 | 163593                   | 75840740                 | 4454                                     |
| 15 | 163797                   | 73750881                 | 1912                                     |
| 16 | 164101                   | 75841935                 | 2540                                     |
| 17 | 162348                   | 75840028                 | 6162                                     |
| 18 | 163794                   | 75842547                 | 2874                                     |
| 19 | 164100                   | 75680021                 | 2092                                     |
| 20 | 162985                   | 75841260                 | 4350                                     |
| 21 | 164102                   | 75840987                 | 1141                                     |
| 22 | 164466                   | 75840436                 | 3030                                     |
| 23 | 164074                   | 75841250                 | 2880                                     |
| 24 | 161563                   | 75840688                 | 6024                                     |
| 25 | 162114                   | 73750110                 | 7747                                     |
| 26 | 163249                   | 75842574                 | 6340                                     |
| 27 | 164801                   | 756879674                | 1590                                     |
| 28 | 164095                   | 75842623                 | 2887                                     |
| 29 | 164095                   | 75841099                 | 3210                                     |
| 30 | 164074                   | 75841250                 | 3601                                     |
| 31 | 163248                   | 75840985                 | 4925                                     |
| 32 | 164102                   | 73750732                 | 2257                                     |
| 33 | 162980                   | 75841858                 | 5832                                     |
| 34 | 162095                   | 75840346                 | 8177                                     |
| 35 | 163237                   | 73750381                 | 5938                                     |
| 36 | 162121                   | 75840712                 | 5617                                     |
| 37 | 162139                   | 75842015                 | 5959                                     |
| 38 | 162096                   | 75840913                 | 7305                                     |
| 39 | 162095                   | 73750187                 | 8873                                     |
| 40 | 161553                   | 75840417                 | 7188                                     |

---

|    |        |          |      |
|----|--------|----------|------|
| 41 | 162328 | 75841811 | 7243 |
| 42 | 164098 | 75841250 | 3254 |
| 43 | 164098 | 73750689 | 2880 |
| 44 | 163906 | 75840447 | 2052 |
| 45 | 164080 | 75841778 | 3501 |
| 46 | 164450 | 7584475  | 2978 |
| 47 | 164074 | 7581778  | 2333 |
| 48 | 162345 | 73750646 | 6659 |
| 49 | 164074 | 75841508 | 3601 |
| 50 | 162096 | 73750107 | 7305 |
| 51 | 163285 | 75842482 | 2870 |
| 52 | 162101 | 75841109 | 8238 |
| 53 | 162335 | 75840063 | 8558 |
| 54 | 162095 | 73750187 | 9304 |
| 55 | 162989 | 75841049 | 6520 |
| 56 | 163245 | 75841560 | 5794 |
| 57 | 164615 | 75840085 | 2882 |
| 58 | 164443 | 75842057 | 1944 |
| 59 | 164101 | 75842472 | 3659 |
| 60 | 162106 | 73750187 | 8103 |
| 61 | 164444 | 73750405 | 3603 |
| 62 | 164808 | 75840415 | 3783 |
| 63 | 163234 | 7584262  | 8671 |

---

## LIST OF REFERENCES

1. Chief of Naval Operations, *Naval Aviation Maintenance Program, OPNAVINST 4790.2G Volume II*, para 12.1.11, 1 February 1998.
2. Naval Aviation Maintenance Support Office Report 4790.A7040-01. *3M Aviation Maintenance Summary*, 21 October 1999.
3. Naval Air Systems Command, *Aviation Maintenance Manager's Guide*, Section 9, [[http://greenshirt.nalda.navy.mil/mngr\\_guide/toc9.htm](http://greenshirt.nalda.navy.mil/mngr_guide/toc9.htm)]
4. Donnelly, J., "Top Carrier Warplanes Run Low on Parts," *Defense Week*. 18 January, 1999.
5. Deputy Secretary of Defense, *Program Budget Decision 423*, p5, Government Printing Office, Washington D.C., 1 December 1999.
6. Rand Institution, *Estimating Aircraft Recoverable Spares Requirements with Cannibalization of Designated Items*, By D.P. Graver, p. 9, 1993.
7. Under Secretary of Defense Comptroller, "Military Composite Standard Pay and Reimbursements Rates" [<http://www.dtic.mil/comptroller/rates/2000-k2pdf.>]. October 1999.
8. Naval Aviation Maintenance Support Office Report 4790.A8855-10, *Cannibalization Analysis Summary*, 21 October 1999.
9. Commander Naval Air Force Atlantic, Commander Naval Air Force Pacific, *Aviation Maintenance and Supply Readiness Cannibalization Issue 62*, By J. Rosa, p. 2, 26 August 1999.
10. Naval Air Systems Command, *Maintenance Trade Cost Guidebook*, Appendix E p.3, NAVAIR 4.2, 17 July 1997.
11. Naval Supply Command, Logistics Management Decision Support System, [[https://nast20.nalda.navy.mil/cgi-bin/ssm\\_mfhbf\\_submit.pl](https://nast20.nalda.navy.mil/cgi-bin/ssm_mfhbf_submit.pl)]
12. Commander Naval Safety Center, radio message 128-076 to AIG 6940, Subject: 2000 Engine Cost Data for Aviation Mishap Reporting, 141401Z Mar 2000.

**THIS PAGE INTENTIONALLY LEFT BLANK**

## INITIAL DISTRIBUTION LIST

|  |   |
|--|---|
| Defense Technical Information Center .....       | 2 |
| 8725 John J. Kingman Rd., STE 0944               |   |
| Ft. Belvoir, Virginia 22060-6218                 |   |
| Dudley Knox Library .....                        | 2 |
| Naval Postgraduate School                        |   |
| 411 Dyer Rd.                                     |   |
| Monterey, California 93943-5101                  |   |
| Multi-Mission Helicopter Program (PMA-299) ..... | 1 |
| Naval Air Systems Command                        |   |
| 47123 Buse Road Unit Moffett Building            |   |
| Patuxent River, Maryland 20650-1547              |   |
| Naval Support Activity .....                     | 1 |
| H-60 Integrated Weapons Support Team             |   |
| 700 Robins Avenue                                |   |
| Philadelphia, Pennsylvania 19111-5098            |   |
| Donald Eaton Code SM/ET .....                    | 1 |
| Department of Systems Management                 |   |
| Naval Postgraduate School                        |   |
| Monterey, Ca 93934-5000                          |   |
| Dr. Shu S. Liao Code SM/LC .....                 | 1 |
| Department of Systems Management                 |   |
| Naval Postgraduate School                        |   |
| Monterey, Ca 93934-5000                          |   |
| CDR Danny E. Kowalski Pers9D .....               | 1 |
| Navy Personnel Command                           |   |
| 5720 Integrity Drive                             |   |
| Millington, Tennessee 38055                      |   |