


LOAN DOCUMENT

PHOTOGRAPH THIS SHEET

①

DTIC ACCESSION NUMBER



LEVEL

INVENTORY

A M Effort for the Bioventing System...

DOCUMENT IDENTIFICATION

24 Mar 93

DISTRIBUTION STATEMENT A
Approved for Public Release
Distribution Unlimited

DISTRIBUTION STATEMENT

ACCESSION FOR	
NTIS	GRAM <input checked="" type="checkbox"/>
DTIC	TRAC <input type="checkbox"/>
UNANNOUNCED	<input type="checkbox"/>
JUSTIFICATION	<input type="checkbox"/>
BY	
DISTRIBUTION/	
AVAILABILITY CODES	
DISTRIBUTION	AVAILABILITY AND/OR SPECIAL
<i>A-1</i>	

DISTRIBUTION STAMP

--

DATE ACCESSIONED

--

DATE RETURNED

--

REGISTERED OR CERTIFIED NUMBER

DTIC QUALITY INSPECTED 4
20010116 006

DATE RECEIVED IN DTIC

PHOTOGRAPH THIS SHEET AND RETURN TO DTIC-FDAC

H
A
N
D
L
E

W
I
T
H

C
A
R
E

ENGINEERING-SCIENCE, INC.

Suite 590 • 57 Executive Park South, N.E. • Atlanta, Georgia 30329-2265 • (404) 325-0770 • Fax: (404) 325-8369

March 24, 1993

Mr. Jim Williams P.G., C.G.W.P.
Department of the Air Force
Center for Environmental Excellence
DERA Restoration Division (ESR)
8001 Inner Circle Drive Suite 2
Brooks AFB, Texas 78235-5328

Subject: F33615 - 90 - D - 4014, Order 04,
O&M Effort for the Bioventing System at the 7th Street BX Service
Station (May 1992 through March 1993), Eglin, AFB

Dear Mr. Williams:

A copy of the letter report for the monitoring effort for the Bioventing System at the 7th Street BX Service Station, over the referenced period are attached. This report includes a summary of operation and maintenance, and monitoring efforts performed since May 1992 through March 1993.

Upon your approval, two copies of this report will be sent to Mr. Jay Baynes (Eglin AFB). If you have any questions please call me.

Sincerely,

ENGINEERING-SCIENCE, INC.



Ola A. Awosika, P.G.
Project Manager

OAA:bb
Attachment

cc/att: Major Miller (AFCEE)
D. Downey, (ES)

DEFENSE TECHNICAL INFORMATION CENTER REQUEST FOR SCIENTIFIC AND TECHNICAL REPORTS

Title AFCEE Collection

1. Report Availability (Please check one box)

- This report is available. Complete sections 2a - 2f.
- This report is not available. Complete section 3.

2a. Number of
Copies Forwarded

1 each

2b. Forwarding Date

July/2000

2c. Distribution Statement (Please check ONE box)

DoD Directive 5230.24, "Distribution Statements on Technical Documents," 18 Mar 87, contains seven distribution statements, as described briefly below. Technical documents MUST be assigned a distribution statement.

- DISTRIBUTION STATEMENT A: Approved for public release. Distribution is unlimited.
- DISTRIBUTION STATEMENT B: Distribution authorized to U.S. Government Agencies only.
- DISTRIBUTION STATEMENT C: Distribution authorized to U.S. Government Agencies and their contractors.
- DISTRIBUTION STATEMENT D: Distribution authorized to U.S. Department of Defense (DoD) and U.S. DoD contractors only.
- DISTRIBUTION STATEMENT E: Distribution authorized to U.S. Department of Defense (DoD) components only.
- DISTRIBUTION STATEMENT F: Further dissemination only as directed by the controlling DoD office indicated below or by higher authority.
- DISTRIBUTION STATEMENT X: Distribution authorized to U.S. Government agencies and private individuals or enterprises eligible to obtain export-controlled technical data in accordance with DoD Directive 5230.25, Withholding of Unclassified Technical Data from Public Disclosure, 6 Nov 84.

2d. Reason For the Above Distribution Statement (in accordance with DoD Directive 5230.24)

2e. Controlling Office

HQ AFCEE

2f. Date of Distribution Statement
Determination

15 Nov 2000

3. This report is NOT forwarded for the following reasons. (Please check appropriate box)

- It was previously forwarded to DTIC on _____ (date) and the AD number is _____
- It will be published at a later date. Enter approximate date if known. _____
- In accordance with the provisions of DoD Directive 3200.12, the requested document is not supplied because: _____

Print or Type Name

Laura Peña

Telephone

210-536-1431

Signature

[Handwritten Signature]

AC Number

M01-04-0633

O&M EFFORT FOR THE BIOVENTING SYSTEM AT THE 7TH STREET BX SERVICE STATION (MAY 1992 THROUGH MARCH 1993), EGLIN, AFB

OPERATION AND MAINTENANCE

Operation and maintenance (O&M) effort since installation of the bioventing system in May 1992 has included a check on each of the bioventing system components (i.e., blower, gauges, air filter, vapor extraction wells, and injection trenches) to evaluate operating status and to make adjustment where appropriate or necessary. The O&M effort also involved measurement of the following physical parameters:

- Temperature at both blower suction and exhaust;
- Vacuum at air filter;
- Head loss through filter; and
- Pressure at Blower exhaust

May-July, 1992

Over the period May 20 through July 22, 1992, no significant adjustment was made to the system other than increasing the air dilution rate at the air dilution valve on the intake to the blower unit. This adjustment was made to reduce off gas concentration at the injection trenches and to minimize emission of gases into the atmosphere. Prior to making this adjustment a pressure relief valve was installed downstream of the blower. The air filter was changed twice to maximize air flow from the air intake line to the blower and to ensure removal of fugitive materials.

August 1992

Because of continued reports of strong gasoline odor at the gasoline station, a decision was made to replace the existing 2.5 horse power (hp) blower unit being used with a 1 hp unit. On August 3, 1992, the 2.5 hp blower was replaced with a 1 hp blower. A visit to the site on August 20 revealed the blower has not been operating continuously because of power failures associated with frequent storms in the area. A decision was made to rewire the starter for the blower to allow continued operation once power is restored after a storm event. Rewiring of the starter was completed the week ending August 28. A summary of the data gathered since the 1 hp blower was installed in August is presented in Table 1.

September 1992

An in-situ respiration test was performed on September 2 and 3. The respiration test was performed to ensure that nutrients, moisture, or oxygen are not limiting biodegradation. The respiration test included oxygen and carbon dioxide monitoring over a 24 to 48 hour period. The results of the respiration test were presented in a letter report dated October 7, 1992. Based on the results of this test, a fuel biodegradation rate of 5.36 to 25.85 mg/kg/day was estimated. This variation in the biodegradation rate is related to the location of the monitoring point where the rate was calculated. When compared to rates estimated at startup of system

operation, current fuel biodegradation rates are indicative of significant increase in bioactivity and suggest that a more active bacterial population has been established. During this period no adjustments were made to the system.

October 1992

O&M effort in October involved replacement of the air filter and measurement of physical parameters. A summary of the data gathered since the 1 hp blower was installed is presented on Table 1.

November-December 1992

Monitoring effort in November was delayed to early December (Dec. 3). An in-situ respiration test was also scheduled for December 3. This test could not be completed as planned because high water table condition prevented collection of representative samples for analysis during the test. Available information indicated that the Eglin area had experienced heavy rainfall during the month of November. Long range weather forecast indicated this high water table condition may continue into the spring. Engineering - Science monitored storm events during December and January to explore possible opportunity to perform the respiration test.

January 1993

An O&M visit was made on January 8, 1993. Water level measurements collected during this visit indicated the high water table condition persisted. However, samples were collected at routine sampling ports (e.g., vapor monitoring points - VMP-1D and VMP-2D, well MW10, and blower suction and discharge). The air filter was replaced with a new part. A repeat of the respiration test may not be possible until the 3rd Quarter O&M effort scheduled for the first week in March. On the basis of the data collected to date, adjustments to system components were not warranted during this O&M visit.

February 1993

Off gas monitoring effort in February reflected a similar trend in attenuation of total hydrocarbons in the soil gas as in previous months. Other physical parameters measured in the field were consistent with previous data and indicated adjustment to the system components was not warranted. A fair amount of rainfall occurred during early to mid February but was not as much as in previous months (November through January). An in-situ respiration test was scheduled for the 2nd week in March. Data gathered during the month of February is included in Tables 1 and 2 and depicted in Figure 2.

March 1993

ES visited the site on March 10. O&M and monitoring efforts were performed on March 11. Water level measurements obtained during this visit indicated high water table conditions persisted. Therefore, the in-situ respiration test was again postponed. From all indications further attempts to perform this test will not be made again until May. It was observed during this visit that only two recovery wells were in operation. Effort was in progress to get two additional recovery wells back in service. If operation of these four wells is maintained, the wells should initiate a

drawdown that would lower the water table to a depth possibly below the screened portion of the vapor monitoring points. As of March 11, 1993, the four wells FP-1, FP-2, GW-1, and GW-2 were operating at a flow rate of 16gpm, 16gpm, 8gpm, and 4gpm respectively. The data collected during this visit is provided in Tables 1 and 2 and depicted in Figure 2. The air filter for the blower was in good condition. No adjustments were made to the bioventing system components.

OVERVIEW OF ANALYTICAL RESULTS (Update)

Results of biweekly/monthly concentrations of oxygen, carbon dioxide and Total Hydrocarbons throughout the bioventing system are presented in Table 2 and depicted in the attached charts. These results continued to indicate increased biological activity in the subsurface and suggest potential increase in aerobic bacterial population. Results indicate oxygen supply to the subsurface has been adequately sustained. Notably, pre-venting condition indicated a soil oxygen concentration of zero at VMP-1 and VMP-2. As of March 11, oxygen concentrations at monitoring locations VMP-1 and VMP-2 have increased to values ranging from 15.5 to 16.5 percent. In contrast, carbon dioxide that was in excess of 15 percent prior to startup has declined to values ranging from 2.0 to 4.2 percent at all monitoring points. Available data indicate a rapid decline in total hydrocarbon concentration over the past four months (December through March). Volatilization and to a greater extent biodegradation are believed to be responsible for the total hydrocarbons removed.

TABLE 2
RESULTS OF SOIL GAS ANALYSES
DURING BIOVENTING (5/20/92 - 3/11/93)
AT 7TH STREET BX SERVICE STATION
EGLIN AFB

Location	Baseline(1) 05/20/92			1st Week(2) 05/26/92			3rd Week 06/10/92		
	TH ppmv	O2 %	CO2 %	TH ppmv	O2 %	CO2 %	TH ppmv	O2 %	CO2 %
Air Discharge to Injection Trench	-	0.0%	> 15.0%	12,000	20.0%	0.6%	5,800	20.3%	0.7%
Inflow into Blower	90,000	0.0%	> 15.0%	-	-	-	-	-	-
VMP-1D	-	0.0%	> 15.0%	-	-	-	680	0.7%	12.1%
VMP-2D	-	0.0%	> 15.0%	-	-	-	> 20,000	17.6%	1.8%
MW10	-	0.0%	> 15.0%	-	-	-	320	20.5%	0.5%

(1) - Baseline background conditions were: Oxygen - 20.4%, Carbon Dioxide - 0.6%.

(2) - Week since start-up of system operation

TH - Total Hydrocarbons

ppmv - parts per million by volume

TABLE 2 - Continued
RESULTS OF SOIL GAS ANALYSES
DURING BIOVENTING (5/20/92 - 3/11/93)
AT 7TH STREET BX SERVICE STATION
EGLIN AFB

Location	11th Week 08/05/92			13th Week 08/19/92			15th Week 09/02/92			17th Week 09/18/92		
	TH ppmv	O2 %	CO2 %	TH ppmv	O2 %	CO2 %	TH ppmv	O2 %	CO2 %	TH ppmv	O2 %	CO2 %
Air Discharge to Injection Trench	-	-	-	-	-	-	480	20.5%	0.4%	340	20.0%	0.5%
Inflow into Blower	-	-	-	-	-	-	6,550	14.5%	3.2%	4,600	15.0%	4.0%
VMP-1D	-	-	-	-	-	-	390	8.0%	6.5%	200	9.5%	6.0%
VMP-2D	-	-	-	-	-	-	> 20,000	5.5%	3.5%	> 20,000	11.0%	2.8%
MW10	-	-	-	-	-	-	2,200	19.5%	1.2%	1,600	19.0%	1.5%

TABLE 2 - Continued
RESULTS OF SOIL GAS ANALYSES
DURING BIOVENTING (5/20/92 - 3/11/93)
AT 7TH STREET BX SERVICE STATION
EGLIN AFB

Location	19th Week 10/02/92		21st Week 10/16/92		23rd Week 10/30/92		28th Week 12/04/92 *	
	TH ppmv	O2 %	TH ppmv	O2 %	TH ppmv	O2 %	TH ppmv	O2 %
Air Discharge to Injection Trench	20	20.5%	-	-	35	21.0%	10	21.0%
Inflow into Blower	2,500	18.5%	-	-	2,000	20.5%	1,000	20.5%
VMP-1D	300	5.5%	-	-	360	10.0%	80	21.0%
VMP-2D	> 20,000	10.0%	-	-	> 10,000	20.0%	650	21.0%
MW10	2,000	20.0%	-	-	3,000	20.0%	400	21.0%
		CO2 %		CO2 %		CO2 %		CO2 %
		11.0%		-		1.0%		0.5%
		7.5%		-		1.2%		0.1%
		0.5%		-		8.5%		0.1%
		2.5%		-		2.0%		0.9%
		0.5%		-		2.0%		0.2%

* - High water table condi

TABLE 2 - Continued
RESULTS OF SOIL GAS ANALYSES
DURING BIOVENTING (5/20/92 - 3/11/93)
AT 7TH STREET BX SERVICE STATION
EGLIN AFB


Location	33rd Week 01/08/93		39th Week 02/19/93		42nd Week 03/11/93	
	TH ppmv	O2 %	TH ppmv	O2 %	TH ppmv	O2 %
Air Discharge to Injection Trench	34	20.5%	100	21.0%	45	21.0%
Inflow into Blower	998	19.5%	ND	ND	1,000	2.0%
VMP-1D	200	16.5%	400	21.0%	500	15.5%
VMP-2D	800	20.5%	1,200	21.0%	700	16.5%
MW10	68	20.5%	250	21.0%	ND	ND

ND - Sample could not be obtained at this sampling location.

ions observed.

Figure 1


**CARBON DIOXIDE LEVELS DURING BIOVENTING
AT 7TH STREET BX SERVICE STATION (5/20/92 - 3/11/93)
EGLIN AFB**



Note: "?" indicates no data was recorded on this date; slopes are assumed to be linear.

Figure 1.a.b


**OXYGEN LEVELS DURING BIOVENTING
AT 7TH STREET BX SERVICE STATION (5/20/92 - 3/11/93)
EGLIN AFB**



Note: "?" indicates no data was recorded on this date; slopes are assumed to be linear.

Figure 1.c

**TOTAL HYDROCARBON LEVELS DURING BIOVENTING
AT 7TH STREET BX SERVICE STATION (5/20/92 - 3/11/93)**



Note: "?" indicates no data was recorded on this date; slopes are assumed to be linear.