




PB2000-910402
NTSB/AAR-00/02
DCA97MA055

NATIONAL TRANSPORTATION SAFETY BOARD

WASHINGTON, D.C. 20594

AIRCRAFT ACCIDENT REPORT

CRASH DURING LANDING
FEDERAL EXPRESS, INC.
MCDONNELL DOUGLAS MD-11, N611FE
NEWARK INTERNATIONAL AIRPORT
NEWARK, NEW JERSEY
JULY 31, 1997



7047B

20010309 088

Aircraft Accident Report

Crash During Landing

Federal Express, Inc.

McDonnell Douglas MD-11, N611FE

Newark International Airport

Newark, New Jersey

July 31, 1997

DISTRIBUTION STATEMENT A
Approved for Public Release
Distribution Unlimited

NTSB/AAR-00/02

DCA97MA055

PB2000-910402

Notation 7047B

Adopted July 25, 2000



National Transportation Safety Board

490 L'Enfant Plaza, S.W.

Washington, D.C. 20594

National Transportation Safety Board. 2000. *Crash During Landing Federal Express, Inc. McDonnell Douglas MD-11, N611FE, Newark International Airport, Newark, New Jersey, July 31, 1997. Aircraft Accident Report NTSB/AAR-00/02. Washington, DC.*

Abstract: This report explains the accident involving Federal Express flight 14, an MD-11, which crashed while landing on runway 22R at Newark International Airport, Newark, New Jersey, on July 31, 1997. Safety issues discussed in this report focus on landing techniques, bounced landing recovery, and training tools and policies that promote proactive decision-making to go around if an approach is unstabilized. Safety issues also include the use of on board computers to determine the required runway length for landing, MD-11 handling characteristics and structural integrity requirements, hard landing inspection requirements, and tracking hazardous materials.

The National Transportation Safety Board is an independent Federal agency dedicated to promoting aviation, railroad, highway, marine, pipeline, and hazardous materials safety. Established in 1967, the agency is mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The Safety Board makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Recent publications are available in their entirety on the Web at <<http://www.nts.gov>>. Other information about available publications also may be obtained from the Web site or by contacting:

**National Transportation Safety Board
Public Inquiries Section, RE-51
490 L'Enfant Plaza, S.W.
Washington, D.C. 20594
(800) 877-6799 or (202) 314-6551**

Safety Board publications may be purchased, by individual copy or by subscription, from the National Technical Information Service. To purchase this publication, order report number **PB2000-910402** from:

**National Technical Information Service
5285 Port Royal Road
Springfield, Virginia 22161
(800) 553-6847 or (703) 605-6000**

Contents

Figures	v
Abbreviations	vii
Executive Summary	ix
1. Factual Information	1
1.1 History of Flight	1
1.1.1 Airplane Performance During the Approach and Landing	6
1.1.2 Flight Crew and Witness Statements	10
1.2 Injuries to Persons	11
1.3 Damage to Airplane	11
1.4 Other Damage	11
1.5 Personnel Information	11
1.5.1 The Captain	11
1.5.2 The First Officer	12
1.6 Airplane Information	13
1.6.1 Airplane Maintenance and Incident History	13
1.6.2 Weight and Balance	15
1.7 Meteorological Information	15
1.8 Aids to Navigation	16
1.9 Communications	16
1.10 Airport Information	16
1.11 Flight Recorders	16
1.11.1 Flight Data Recorder	16
1.11.2 Cockpit Voice Recorder	17
1.12 Wreckage and Impact Information	17
1.13 Medical and Pathological Information	22
1.14 Fire	22
1.15 Survival Aspects	22
1.15.1 Flight Crew and Passenger Egress	22
1.15.2 Emergency Response	23
1.16 Tests and Research	24
1.16.1 Landing Gear Energy and Load Limit Certification	24
1.16.2 Dynamic Failure Simulation of MD-11 Right Wing Structure and Right Main Landing Gear Assembly	29
1.16.3 Tests of Airplane Systems	31
1.17 Organizational and Management Information	32
1.18 Additional Information	32
1.18.1 Dissemination of Hazardous Materials Information	32
1.18.2 Cargo Operator Review and FedEx Postaccident Actions	36
1.18.3 FedEx MD-11 Tailstrike Awareness and Training Initiatives	37
1.18.4 MD-11 Hard Landing Accident at Hong Kong International Airport	41
1.18.5 DC-10 Hard Landing Accident in Faro, Portugal	41
1.18.6 Lockheed L-1011 Hard Landing Accident in New York	43

1.18.7 Other Landing Accidents	45
1.18.8 Safety Board Recommendations Relating to DC-10 and MD-11 Spoiler Pitch-up Incidents	47
1.18.9 MD-11 Flight Control Computer Software Changes	49
2. Analysis	51
2.1 General	51
2.2 Accident Scenario	52
2.2.1 Airplane Performance During the Approach and Landing	52
2.2.2 Flight Crew Factors During the Approach and Landing	55
2.3 MD-11 Handling Characteristics and Flight Control System Design	62
2.3.1 MD-11 Nose-Up Pitching Moment Because of Ground Spoiler Deployment	62
2.3.2 MD-11 Pitch Handling Characteristics and the FCC-908 Software Upgrade	62
2.3.3 Digital Flight Data Recorder Update Required by FCC-908	63
2.3.4 MD-11 Ground Spoiler Knockdown Feature	63
2.4 Transport-Category Airplane Stability and Control During the Landing Phase	64
2.5 Structures	65
2.5.1 Right-Wing Structural Design and Failure	65
2.5.2 Landing Gear Certification	66
2.6 Hazardous Materials Information Dissemination	67
3. Conclusions	69
3.1 Findings	69
3.2 Probable Cause	71
4. Recommendations	72
4.1 New Recommendations	72
4.2 Previously Issued Recommendations Classified in This Report	74
5. Appendixes	75
A: Investigation and Hearing	75
B: Cockpit Voice Recorder Transcript	76
C: Excerpts from the Flight Data Recorder	113
D: Prior Incident Flight Data Recorder Data for the Accident Airplane	121
E: FedEx Tail Strike Awareness Information Bulletin	124
F: FedEx Tail Strike Awareness Training Instructor's Guide	129

Figures

1. Aerial view of the accident site.	2
2. N611FE at the height of the firefighting effort.	3
3. N611FE during the final portion of the firefighting effort.	3
4. N611FE after the fire was extinguished.	4
5. Comparison of selected FDR parameters for accident landing and previous two landings (correlated by radio altitude – 50 feet).	7
6. Comparison of selected FDR parameters for accident landing and previous two landings (correlated by first touchdown).	8
7. Wreckage distribution diagram.	18
8. Right MLG components.	20
9. Boeing calculations of right MLG energy in the Newark accident.	28
10. Boeing calculations of right MLG energy in the Faro accident.	43
11. Boeing calculations of right MLG energy in the TWA L-1011 accident.	45

Abbreviations

ABS	automatic brake system
AC	advisory circular
agl	above ground level
AGS	automatic ground spoiler
ANC	Anchorage International Airport
AND	airplane nose-down
ANPRM	advance notice of public rulemaking
ANU	airplane nose-up
APLC	airport performance laptop computer
ARFF	aircraft rescue and firefighting
ATP	airline transport pilot
AWAB	automated weight and balance
CAWS	central aural warning system
CFR	Code of Federal Regulations
c.g.	center of gravity
CHEMTREC	Chemical Transportation Emergency Center
CVR	cockpit voice recorder
DEP	Department of Environmental Protection
DFDR	digital flight data recorder
DG	dangerous goods
DGAC	Director-General of Civil Aviation
EWR	Newark International Airport
FAA	Federal Aviation Administration
FCC	flight control computer
FCOM	flight crew operating manual
FCP	flight control panel
FDR	flight data recorder
FedEx	Federal Express, Inc.
FL	flight level
FMC	flight management computer
FMS	flight management system
fpm	feet per minute
fps	feet per second
FSAT	flight standards information bulletin for air transportation

g	acceleration of gravity
GOCC	Global Operations Command Center
HMRU	Hazardous Materials Response Unit
ICAO	International Civil Aviation Organization
ILS	instrument landing system
IRU	inertial reference unit
KIAS	knots indicated airspeed
LASE	low altitude stability enhancement
LSAS	longitudinal stability augmentation system
MAX	maximum
MDI	Mechanical Dynamics, Inc.
MED	medium
MEL	minimum equipment list
MLG	main landing gear
msl	mean sea level
NASA	National Aeronautics and Space Administration
NFD	Newark Fire Department
NOTOC	notification to captain
NOTAM	notice to airmen
NPRM	notice of proposed rulemaking
PAP	pitch attitude protection
PIO	pilot-induced oscillation
PNL	pitch nose lowering
POI	principal operations inspector
PRD	pitch rate damper
RSPA	Research and Special Programs Administration
sm	statute miles
SN	serial number
STA	station
TRA	throttle resolver angle
TWA	Trans World Airlines
UN	United Nations
V_1	takeoff decision speed
V_2	takeoff safety speed
VASI	visual approach slope indicator
V_{ref}	reference speed
WS	wing station

Executive Summary

On July 31, 1997, about 0132 eastern daylight time, a McDonnell Douglas MD-11, N611FE, operated by Federal Express, Inc., (FedEx) as flight 14, crashed while landing on runway 22R at Newark International Airport, Newark, New Jersey (EWR). The regularly scheduled cargo flight originated in Singapore on July 30 with intermediate stops in Penang, Malaysia; Taipei, Taiwan; and Anchorage, Alaska. The flight from Anchorage International Airport to EWR was conducted on an instrument flight rules flight plan and operated under the provisions of 14 Code of Federal Regulations Part 121. On board were the captain and first officer, who had taken over the flight in Anchorage for the final leg to EWR, one jumpseat passenger, and two cabin passengers. All five occupants received minor injuries in the crash and during subsequent egress through a cockpit window. The airplane was destroyed by impact and a postcrash fire.

The National Transportation Safety Board determines that the probable cause of this accident was the captain's overcontrol of the airplane during the landing and his failure to execute a go-around from a destabilized flare. Contributing to the accident was the captain's concern with touching down early to ensure adequate stopping distance.

Safety issues discussed in this report focus on landing techniques, bounced landing recovery, and training tools and policies that promote proactive decision-making to go around if an approach is unstabilized. Safety issues also include the use of on board computers to determine the required runway length for landing, MD-11 handling characteristics and structural integrity requirements, and hard landing inspection requirements. Tracking hazardous materials continues to be a safety issue and is also discussed in the report.

Safety recommendations concerning these issues are addressed to the Federal Aviation Administration.

1. Factual Information

1.1 History of Flight

On July 31, 1997, about 0132 eastern daylight time,¹ a McDonnell Douglas MD-11,² N611FE, operated by Federal Express, Inc., (FedEx) as flight 14, crashed while landing on runway 22R at Newark International Airport (EWR), Newark, New Jersey. The regularly scheduled cargo flight originated in Singapore on July 30 with intermediate stops in Penang, Malaysia; Taipei, Taiwan; and Anchorage, Alaska. The flight from Anchorage International Airport (ANC), Anchorage, Alaska, to EWR was conducted on an instrument flight rules flight plan and operated under provisions of 14 Code of Federal Regulations (CFR) Part 121. On board were the captain and first officer, who had taken over the flight in Anchorage for the final leg to EWR, one jumpseat passenger, and two cabin passengers.³ All five occupants received minor injuries in the crash and during subsequent egress through a cockpit window. The airplane was destroyed by impact and a postcrash fire (see figures 1 through 4).

According to flight plan and release documents, the airplane was dispatched to ANC with the No. 1 (left engine) thrust reverser inoperative.⁴ The flight plan time from ANC to EWR was 5 hours and 51 minutes—47 minutes shorter than the scheduled time of 6 hours and 38 minutes because of 45-knot tail winds en route. The flight crew stated that at flight level (FL) 330 (about 33,000 feet mean sea level [msl]), the flight from ANC to EWR was routine and uneventful.

At 0102:11, a Federal Aviation Administration (FAA) Boston Air Route Traffic Control Center air traffic controller instructed flight 14 to descend and maintain FL 180, according to the airplane's cockpit voice recorder (CVR).⁵ About 0103, the captain and first officer discussed the approach and landing to runway 22R and the airplane's landing performance.⁶ Using the airport performance laptop computer (APLC),⁷ the first officer

¹ Unless otherwise indicated, all times are eastern daylight time based on a 24-hour clock.

² Boeing Commercial Airplane Group acquired the holdings of Douglas Aircraft Company and McDonnell Douglas in 1997. The MD-11 was developed by McDonnell Douglas as a follow-on to the DC-10, which first flew in 1970. According to *Jane's All the World's Aircraft*, the MD-11, which was granted a type certificate on November 8, 1990, has, among many design changes, a longer fuselage, a redesigned tailplane, winglets above and below the wingtips, and advanced cockpit instrumentation.

³ The jumpseat passenger was a pilot for another airline, and the two cabin passengers were FedEx employees.

⁴ A jet engine thrust reverser deflects airflow in the forward direction to help reduce the airplane's speed after touchdown. Maintenance personnel at ANC deactivated the No. 1 thrust reverser after finding a delaminated door on it. Flight 14's departure with an inoperative thrust reverser was approved under provisions of the airplane's minimum equipment list (MEL). The MEL is developed by each operator of an aircraft and must be equivalent to or more conservative than the master MEL, which is developed by the manufacturer and approved by the FAA.

⁵ See appendix B for a transcript of the recording.



Figure 1. Aerial view of the accident site.

determined that the airplane's runway stopping distance would be approximately 6,080 feet using medium (MED) autobrakes. According to the CVR, at 0103:33, the flight crew then compared the APLC approximate landing distance for MED braking (6,080 feet) to the after-glideslope touchdown distance (6,860 feet) provided on the instrument approach plate.⁸ Based on the flight crew's calculation (6,860 – 6,080), MED braking provided a 780-foot margin after stopping.⁹ The flight crew then compared the APLC approximate landing distance for maximum (MAX) braking (5,030 feet) to the same 6,860-foot after-glideslope touchdown distance provided on the instrument approach plate. Based on the flight crew's calculation (6,860 – 5,030), MAX braking provided a 1,830-foot margin after stopping.¹⁰ On the basis of these calculations, the first officer suggested using MAX autobrakes. The captain agreed, stating “we got a lot of stuff going

⁶ Runway 22R is 1,100 feet shorter than runway 22L, which was closed (see section 1.10 for a discussion of airport information).

⁷ As an airplane approaches the landing airport, pilots enter several parameters (for example, weather information and airplane weight) into the APLC, which generates landing data, including the approximate landing distances for usable runways at a selected airport.

⁸ The APLC approximate landing distance is intended to be compared with the APLC runway distance, which, in this case, is 7,760 feet.

⁹ Based on APLC data (7,760 – 6,080), MED braking would have provided a 1,680-foot margin after stopping.

¹⁰ Based on APLC data (7,760 – 5,030), MAX braking would have provided a 2,730-foot margin after stopping. Following the accident, FedEx expanded the APLC training presentation that was originally included in initial and upgrade training. This expanded presentation has also been added to recurrent training programs.



Figure 2. N611FE at the height of the firefighting effort.



Figure 3. N611FE during the final portion of the firefighting effort.



Figure 4. N611FE after the fire was extinguished.

against us here so we'll...start with max." The first officer added, "I mean...I mean if we don't have the reverser."

At 0114:22, the captain asked the first officer to advise the passengers that "we're gonna have a pretty abrupt stop because of those brakes and the thrust reversers and all that stuff." Twice during the approach, the captain asked the first officer to remind him to only use the No. 2 and No. 3 thrust reversers.¹¹ At 0116:16, the captain noted that the left landing light was inoperative, adding "... just the right's working."¹²

The EWR tower controller cleared flight 14 to land at 0129:45 and advised the flight crew "winds two five zero at five." At 0130:02, the first officer stated "max brakes" during the before-landing checklist. The captain replied "max brakes will be fine," and the first officer responded "if they work."¹³ At 0130:34, the captain stated "[landing gear] down in four green" and called for "flaps fifty."

¹¹ At 0102:22, during the approach briefing, the captain stated "ah...remind me to, we just want two and three for reverse." At 0130:59, the captain stated "two and three on reverse...just in case I forget." The No. 3 thrust reverser can be deployed on main gear spinup. The No. 2 thrust reverser cannot be deployed until after nose gear touchdown.

¹² Landing lights are located on the fuselage aft of the L1 and R1 cabin doors. According to the MEL, flights can be conducted at night with inoperative landing lights if the nose gear lights are functioning. The captain told National Transportation Safety Board investigators that the inoperative left landing light did not affect his ability to judge sink rate and land the airplane.

At 0130:45, the captain disengaged the autopilot at an altitude of 1,200 feet during the approach and “hand flew” the airplane to touchdown. The autothrottles were engaged, as recommended by McDonnell Douglas and FedEx procedures.¹⁴ According to information from the airplane’s flight data recorder (FDR), the approach was flown on the glideslope and localizer until touchdown,¹⁵ and the airplane’s approach airspeed was about 158 knots until the flare. According to the CVR, the pilots had selected an approach reference speed of 157 knots, or V_{ref} plus 5 knots.¹⁶ Altitude callouts were made by the on board central aural warning system (CAWS) at 1,000 feet and 500 feet, and the first officer called out minimums (211 feet) at 0132:03. At 0132:09, the first officer stated “brakes on max,” and CAWS callouts followed for 100, 50, 40, 30, 20, and 10 feet until the sound of initial touchdown at 0132:18.75. One-half second later, the CVR recorded an expletive by the captain. At 0132:20.26, the CVR recorded increasing high-frequency tones consistent with engine spool-up (accelerating engine rpms), and at 0132:21.06, the CVR recorded a decrease in high-frequency tones consistent with engine spool-down. The sound of a “loud thump” consistent with another touchdown was recorded at 0132:21.62. A series of expletives by the captain and first officer followed until sounds of “metallic breakup” were recorded at 0132:27.

FDR data indicated that after the airplane’s initial touchdown, it became airborne and rolled to the right as it touched down again (see section 1.1.1 for a detailed description of the airplane’s performance during the landing sequence). The airplane continued to roll as it slid down the runway, coming to rest inverted about 5,126 feet beyond the runway threshold and about 580 feet to the right of the runway centerline. The accident occurred during the hours of darkness. Visual meteorological conditions prevailed at the time of the accident.

¹³ The MD-11’s autobrakes, or automatic brake system (ABS), automatically apply brakes during landing and rejected takeoff. The takeoff mode is armed by selecting “T.O. [takeoff] with the AUTO BRAKE selector,” according to the MD-11 flight crew operating manual (FCOM). The ABS landing mode is armed after the gear is down. The accident airplane’s maintenance logs contained three write-ups about instances in which the autobrakes failed to arm at takeoff or failed to function properly on landing. Maintenance personnel checked the system after each reported failure but found no anomalies. The captain told Safety Board investigators that he discussed the reliability of the autobrakes with the first officer in ANC and elected to execute a MAX power takeoff because of the possibility of autobrake failure in the takeoff mode. However, he added that the autobrakes performed normally on takeoff in ANC. He stated that he kept the possibility of autobrake failure in mind when planning for landing at EWR.

¹⁴ During the approach, the captain selected APPROACH LAND and FMS SPEED rather than selecting SPEED SELECT on the flight control panel (FCP) of the flight management system (FMS). In the FMS SPEED mode, the flight management computer (FMC) adjusts the airplane’s speed in relation to configuration changes (for example, leading edge slat, flap, and landing gear extension). In the SPEED SELECT mode, the captain would have had to adjust the airplane’s speed after each configuration by changing the speed on the FCP.

¹⁵ The first officer told Safety Board investigators that runway 22R’s three-bar visual approach slope indicator (VASI) was in operation and visible from the cockpit. He stated that during the approach, the airplane was on the lower path of the VASI system, or red-red-white. Three-bar VASI installations provide two visual glidepaths. The lower glidepath, provided by the near and middle bars, is normally set at 3°. The upper glidepath, provided by the middle and far bars, is normally set 1/4 degree higher.

¹⁶ V_{ref} in this case, was a target or reference approach speed. Reference approach speeds are typically about 1.35 V_{so} (stalling speed with flaps in the landing configuration).

1.1.1 Airplane Performance During the Approach and Landing

The National Transportation Safety Board used FDR and CVR information, radar data,¹⁷ and integrated vertical speed and position data to develop a time history of the accident airplane's performance and flight crew control inputs during final approach and landing (see appendix C).¹⁸ Excerpts from the FDR are presented in figures 5 and 6 for comparison to the accident airplane's two previous landings.

According to FDR and radar data, the airplane was stabilized on the approach, with flaps set at 50° and the landing gear down. The airspeed was between 157 knots and 159 knots indicated airspeed (KIAS), and the vertical speed was about 800 feet per minute (fpm). Pitch attitude was about 2° to 3° airplane nose-up (ANU) and throttle resolver (lever) angles (TRA)¹⁹ were between 55° and 58° until flare was initiated at 38 feet radio altitude.²⁰ After the flare was initiated, pitch attitude increased to 4.9°, TRA and airspeed decreased, and vertical acceleration increased to about 1.18 g.²¹

As the airplane descended through 17 feet radio altitude, an airplane nose-down (AND) elevator deflection was initiated and pitch attitude and vertical acceleration began to decrease. Pitch attitude decreased to 4.2°, and vertical acceleration decreased from about 1.18 g to about 0.93 g as the airplane descended through 7 feet radio altitude. At 0132:17.6, FDR data indicated an ANU elevator deflection of up to 26° out of a maximum possible deflection of 37.5°, a nose-left-rudder deflection of up to 5.5°, a right-wing-down aileron deflection of 5°, ²² and a TRA increase to 74°. Airspeed was decreasing through 152 knots at this time.

¹⁷ Radar data were obtained from the FAA airport surveillance radar at EWR.

¹⁸ Ground scar and wreckage locations were also used to reconstruct landing events (see section 1.12 for details of wreckage and ground scar locations).

¹⁹ The MD-11 is equipped with an electronic automated engine power control system. The throttle resolver levers on the cockpit's power control pedestal are linked to a throttle switch and cam assembly that sends electronic signals, based on power setting, to a full authority digital engine control unit located on the engine. Throttle resolver (lever) degree angles represent the total travel of the throttle lever from the "forward limit stop" (of about 85°), to the idle aft limit (of about 41°), to just below the "reverse stop" (of 7.7°). Forward travel of the throttles is limited by an overboost stop (about 81°). This stop has a detent that allows continued forward movement of the throttles when they are pushed with a strong force. Among other things, this extra forward travel causes autothrottle disengagement.

²⁰ Radio altitude is measured by the on board radio altimeter, which provides a readout of height above ground level (agl). McDonnell Douglas data indicate that the MD-11 radio altitude system is calibrated to read 0 feet when the main landing gear (MLG) tires touch the runway with the struts fully extended at 4° pitch attitude. The radio altitude sensor is 22.8 feet ahead of the MLG; therefore, when pitch is greater than 4°, the radio altitude will read too high, and when pitch is below 4°, it will read too low. The equation to convert from FDR radio altitude to pitch-corrected radio altitude is $RADALT_{corrected} = RADALT - 22 \times \sin(\text{pitch} - 4^\circ)$.

²¹ A g is a measure of force on a body undergoing acceleration as a multiple of the force imposed by the acceleration of Earth's gravity.

²² Aileron deflection values represent the average value of all four aileron positions recorded by the FDR after accounting for any offsets resulting from instrumentation error or misrigging.

FEDEX MD-11 - Accident & Previous 2 Landings

(Selected DFDR Parameters)
Correlated by Radio Altitude - 50 feet




Figure 5. Comparison of selected DFDR parameters for accident landing and previous two landings (correlated by radio altitude - 50 feet).



FEDEX MD-11 - Accident & Previous 2 Landings(Selected DFDR Parameters)
Correlated by First Touchdown

Figure 6. Comparison of selected DFDR parameters for accident landing and previous two landings (correlated by first touchdown).

As the airplane touched down at 0132:18.6, pitch attitude and vertical acceleration were increasing (along with engine speeds). It touched down 1,126 feet beyond the runway displaced threshold with a 7° nose-up pitch attitude. Vertical speed at the time of the first touchdown was about 7.6 feet per second (fps).²³ Vertical acceleration peaked at 1.67 g. About 1/2 second after the first touchdown, the FDR recorded an 18° AND elevator deflection (maximum possible MD-11 AND elevator deflection is 27°) and a TRA decrease.²⁴ At 0132:19, rudder deflection decreased to near zero, and the magnetic heading stabilized at 217.4° (the published magnetic heading for the runway was 219°). Pitch attitude peaked at 8.44° and began decreasing. Thrust continued to increase with N_1 values of about 65 percent. Airspeed began to increase and the airplane became airborne.²⁵

As the airplane's altitude increased, it pitched nose-down and rolled right-wing-down, consistent with the AND elevator deflection and right-wing-down aileron deflection. Engine speeds peaked at 80 percent N_1 and began to decrease. The airplane reached an altitude of about 5 feet²⁶ above ground level (agl) and began to descend. At 0132:20.8, as the airplane descended back to the runway, the FDR recorded about 23° ANU elevator, about 12° nose-left rudder, and additional right-wing-down aileron deflections. The airplane touched down the second time about 1,889 feet from the displaced threshold at 0132:21.6 with a 9.5° right-wing-down roll angle, a -0.70° pitch attitude and on a 216.7° magnetic heading. Roll rate was about 7° per second right-wing-down and peak vertical speed at the right main landing gear (MLG) was about 13.5 fps.²⁷ Vertical acceleration at the beginning of the second touchdown was about 0.5 g and peaked at about 1.70 g just after touchdown (see sections 1.16.1 and 2.5.2 for a discussion of vertical acceleration values in relation to landing gear energy absorption limits). Maximum elevator deflection at the second touchdown was about 24° ANU, and TRAs were about 51°.

ANU elevator deflection continued for about 1 second after the second touchdown, TRAs increased to about 81°, and a left-wing-down aileron deflection was initiated. The airplane pitched up 5° and began rolling right wing down. An aural "tire failure" warning sounded in the cockpit at 0132:26 as the airplane rolled through 45° right wing down. The right-wing-down roll angle increased to 90° and the pitch attitude decreased to 5° AND

²³ This value was the computed vertical speed at the right MLG and includes 6.6 fps vertical speed at the center of gravity (c.g.) and 1.0 fps vertical speed caused by nose-up pitch rate and right-wing-down roll rate. The MD-11 MLG are aft and outboard of the c.g.; therefore, pitch and roll rates affect the vertical speed of the MLG.

²⁴ Ground spoilers on the accident airplane did not deploy after touchdown because the TRA was greater than 49°. The No. 2 engine throttle lever mechanically prevents ground spoiler deployment if its position is greater than 44° to 49° (about 1.05 inches) forward of idle and knocks down extended spoilers if the No. 2 engine throttle lever exceeds this range. Ground spoilers, or speed brakes, are hinged or otherwise moveable surfaces on the upper rear surface of a wing that reduce lift and increase drag when extended.

²⁵ According to the FDR, the airplane touched down at 149 KIAS. The ground speed was 152 knots.

²⁶ The bounce altitude was determined by correcting radio altitude for pitch attitude, as well as by integrating accelerations.

²⁷ This value includes 11.5 fps vertical speed at the c.g. and 2 fps vertical speed caused by the right-wing-down roll rate.

when the FDR stopped recording at 0132:27.6. The CVR stopped 1.3 seconds later, after recording sounds of “metallic breakup.”

1.1.2 Flight Crew and Witness Statements

The captain told Safety Board investigators in a postaccident interview that he “wasn’t going to grease it [the landing]...but put it [the airplane] on the end of the runway and to try to make sure...not [to] get any float out of it.” He stated that the glideslope, airspeed, and localizer were “completely nailed” during the approach. He also stated that he noticed an increased sink rate at 20 feet, “felt the airplane sink,” and made a “slight pitch and power change.” The captain stated that the airplane touched down “very firmly” and that he was not certain if the ground spoilers deployed but believed that they had. He also stated that he moved the control column forward and added power to compensate for a pitch-up tendency that occurs when the spoilers are deployed. He stated that his pitch and power response “was instinctive” and in accordance with the response called for in his FedEx tailstrike awareness training (see section 1.18.3 for details about FedEx’s tailstrike awareness training program). The captain further stated that when the airplane touched down the second time, “it started rolling to the right” and that he applied left rudder as the airplane began to roll. He added that he could not understand why the airplane kept rolling to the right and that the rolling was “gradual” and not as violent as he thought it would be.

The first officer stated in a postaccident interview that he felt the airplane begin to settle at an altitude of about 20 feet²⁸ and “could tell it was going to be a firm landing.” He added that he had experienced firmer landings in the MD-11. The first officer stated that the airplane bounced about 5 to 10 feet into the air and was on the centerline. He stated that his FedEx training advocated avoiding a nose-high attitude and not controlling sink rate with pitch during a bounce. He added that the training also advocated adding power until the sink rate has been arrested or a landing accomplished. He stated that he observed the captain doing this, adding that he believed the nose attitude was about 7°. The first officer stated that no attempt was made to execute a go-around.

A FedEx DC-10 captain, whose airplane was taxiing to the departure end of runway 22R, stated that he watched the accident airplane land. He stated that he saw the airplane pitch nose down and bank to the right. He stated it was not a “normal bank” and that he saw the right wing strike the ground, break off, and catch fire.

The EWR tower controller stated that he saw the airplane touch down hard and bounce. He stated that the airplane was in a bank when it touched down again and that he saw sparks and debris coming from the airplane “before something appeared to break off from under the aircraft.”

²⁸ The first officer noted that this was a “seat of the pants” feeling and was not based on indications of cockpit instruments.

1.2 Injuries to Persons

Injuries	Flight Crew	Cabin Crew	Passengers	Other	Total
Fatal	0	0	0	0	0
Serious	0	0	0	0	0
Minor	2	0	3	0	5
None	0	0	0	0	0
Total	2	0	3	0	5

1.3 Damage to Airplane

The airplane and its cargo were destroyed by impact and a postcrash fire. The airplane was valued at \$112 million.

1.4 Other Damage

A 1,574-foot area along the right side of runway 22R was sooted and scarred. Soil samples taken from the accident site were analyzed and were not found to contain hazardous levels of fuel or other chemical contamination.²⁹ Five runway/taxi signs along the right side of the runway were damaged or destroyed. Cost of cleanup and repairs was estimated at \$500,000.

1.5 Personnel Information

1.5.1 The Captain

The captain, age 46, was hired by Flying Tigers, Inc., in 1979 and became a FedEx pilot when Flying Tigers merged with FedEx in 1989. The captain held an airline transport pilot (ATP) certificate and was type-rated in the MD-11. In addition to his ATP, the captain held a commercial certificate and a turbojet flight engineer certificate. His most recent FAA first-class medical certificate was issued on April 15, 1997, with limitations requiring him to wear corrective lenses. The captain's most recent proficiency check was April 15, 1997, and his most recent line check was July 11, 1997. According to company records, the captain had logged a total of 11,000 flying hours, 2,621 hours of which were with FedEx. He had logged a total of 1,253 hours in the MD-11, of which 318 hours were as pilot-in-command. He had flown 155 hours, 96 hours, 41 hours, 6 hours, and 6 hours in the last 90 days, 60 days, 30 days, 7 days, and 24 hours, respectively. A review of training

²⁹ FedEx hired a New York-based, independent laboratory, Environmental Testing Laboratories, Inc., to test soil samples taken from the accident site. The laboratory report concluded that the accident "did not have an adverse" impact on the environment and that "no further soil investigation" was warranted.

records indicated that the captain had received an unsatisfactory evaluation on an upgrade proficiency check ride on October 29, 1996. The captain received additional training in V_1 cuts³⁰ and multiple engine failures and accomplished a successful recheck. FedEx records indicated that the captain had successfully completed the company's tailstrike awareness training program twice, on July 10, 1996, during annual recurrent training as a first officer and again on November 15, 1996, during captain upgrade training. A search of FAA and company records showed no enforcement actions, accidents or incidents, or company disciplinary actions, and a search of records at the National Driver Register found no history of driver's license revocation or suspension.

The captain had not flown in the 7 days before the accident. He arrived at ANC from his home in Nevada the evening before the accident flight departed. He reported routine activities and normal sleep in Anchorage and feeling rested upon waking about 0830 local time the day of the accident. The accident occurred approximately 14 hours later. The captain reported eating meals en route and that, typical of flights of similar duration, he felt tired at the end of the accident flight but that his performance was not affected. The captain was in good health, reported a stable personal life, and did not take medications or consume alcohol in the 24 hours before the accident.

1.5.2 The First Officer

The first officer, age 39, was hired by FedEx on September 6, 1994, as a ground service employee after serving as a pilot in the U.S. Navy and as a flight engineer for another airline. He had logged a total of 1,911 hours of flying time as a pilot and 1,200 hours as a flight engineer at the time of his transfer to FedEx's air operations division in October 1995. He held an ATP and a turbojet flight engineer's certificate and was type-rated in the MD-11. His most recent FAA first-class medical certificate was issued on March 25, 1997, with no limitations. His most recent proficiency check was on May 18, 1997, and his most recent line check was on June 28, 1997. According to company records, he had logged a total of 3,703 flying hours, 592 hours of which were with FedEx. He had logged a total of 95 hours in the MD-11. He had flown 95 hours, 95 hours, 56 hours, 21 hours, and 6 hours in the last 90 days, 60 days, 30 days, 7 days, and 24 hours, respectively. FedEx records indicated that the first officer had successfully completed the company's tailstrike awareness training program on May 6 and 10, 1997. A search of FAA and company records showed no enforcement actions, accidents or incidents, or company disciplinary actions, and a search of records at the National Driver Register found no history of driver's license revocation or suspension.

The first officer lived in Minnesota and was based at ANC. He was off duty in Anchorage for 2 days before the accident and reported routine activities. He reported sleeping more than 8 hours before the flight and waking about 1200 local time after being awake briefly from 0630 to 0830. The first officer reported eating meals en route. He told investigators that he did not feel fatigued during the accident flight and that he did not

³⁰ V_1 is takeoff decision speed or the decision point at which the takeoff is continued or rejected after an engine failure or other system failure. Simulator training includes V_1 cut scenarios in which engines or other systems are intentionally failed during this critical takeoff phase.

believe fatigue was an issue in the accident. The first officer was in good health, reported a stable personal life, and did not take medications or consume alcohol in the 24 hours before the accident.

1.6 Airplane Information

The accident airplane, serial number (SN) 48604, was initially registered on September 29, 1993. It had a certificated maximum gross weight of 625,500 pounds and was equipped with three General Electric CF6-80C2 engines. At the time of the accident, the airplane had accumulated about 13,034 hours total time in service and 2,950 cycles.³¹ Engine No. 1, installed on June 12, 1992, had a total of 14,652 hours (3,384 cycles), with 1,666 hours (379 cycles) since its last shop visit/inspection. Engine No. 2, installed on August 23, 1992, had a total of 14,930 hours (2,681 cycles), with 4,779 hours (918 cycles) since its last shop visit/inspection. Engine No. 3, installed on September 7, 1990, had a total of 16,950 hours (3,888 cycles), with 1,259 hours (284 cycles) since its last shop visit/inspection.

1.6.1 Airplane Maintenance and Incident History

The accident airplane, as part of a fleet of MD-11 airplanes operated by FedEx, was maintained under an FAA-approved maintenance program. According to FedEx maintenance records, the airplane had received a C check³² at 11,025 flight hours on January 14, 1997; its next C check was due at 15,825 flight hours. FedEx records indicated that an A check was conducted on the airplane on July 18, 1997, at 13,014 flight hours. The Safety Board reviewed the accident airplane's maintenance logs for the 30 days before the accident. Excluding the disabled thrust reverser, nothing remarkable was noted.

FedEx maintenance documents indicated that on January 4, 1994, the airplane sustained damage during a bounced landing at Memphis, Tennessee, when a 2.85 positive g load and a minus .45 lateral g load were applied to the airframe during the second touchdown. FedEx personnel conducted the manufacturer-recommended and FAA-approved hard landing inspection³³ and found "mild to moderate buckling of the external skin...from longeron³⁴ 36 to longeron 48 [near the nose gear wheel well]." Inspection notes added that "deformations [were] smooth with no creases. Suspect areas were verified to be crack-free via eddy current surface probe."³⁵ Because no serious damage to

³¹ A cycle on an airplane is one complete sequence of engine startup, taxi, takeoff, climb, cruise, descent, landing, thrust-reverse, taxi, and shutdown. A cycle on an engine is one startup and subsequent shutdown.

³² Under an FAA-approved maintenance program, maintenance tasks are divided into categories based on the level of maintenance required, beginning with A checks through E checks.

³³ The MD-11 hard landing inspection examines all landing gear, tires, fuselage, wings, empennage, engine nacelles and pylons, wheel wells, and control surfaces for signs of damage.

³⁴ Longerons are the principal longitudinal structural members in the fuselage.

³⁵ Eddy current inspections use alternating current to locate surface and near-surface cracks.

any structure was found, the airplane was released to be operated “with buckles ‘as is’” and with the requirement that the area be inspected periodically before permanent repairs were made at the airplane’s next scheduled C check.

FDR data for the Memphis, Tennessee, incident indicated that nose-up elevator inputs consistent with flare began at about 35 feet radio altitude and were maintained until 1 second after the first touchdown. The first touchdown occurred with pitch attitude increasing through 7°, roll increasing through 2° left wing down, and throttles in the flight idle position. The ground spoilers did not deploy, the airplane bounced, and nose-down elevator was initiated. Pitch attitude and vertical acceleration began decreasing, and the airplane touched down the second time with pitch attitude decreasing through 1° nose-up, roll angle decreasing through 4° right wing down, and elevator position at about 17° nose down. The ground spoilers deployed fully during the second touchdown; the airplane remained on the ground, and the landing rollout was completed (see FDR plots in appendix D).

The airplane also sustained damage from a tailstrike during a bounced landing at Anchorage, Alaska, on November 4, 1994, when a 2.59 positive g load was applied to the airframe during the second touchdown. FedEx maintenance documents indicated that the tailstrike had damaged the airplane’s aft fuselage skin, a rear bulkhead, and several floor supports.³⁶ According to the FedEx records, temporary repairs were made in Anchorage. A FedEx engineering authorization form, dated November 6, 1994, stated that “all other remaining damage [was] acceptable for a one-time non-revenue unpressurized ferry flight from Anchorage to LAX [Los Angeles International Airport] for permanent repair” and that the airplane was ferried to Los Angeles. According to FedEx maintenance records, the damage to the aft fuselage skin and bulkhead was repaired during November 1994.

FDR data for the Anchorage, Alaska, incident indicated that nose-up elevator inputs consistent with flare began at about 18 feet radio altitude and were maintained until 1 second after the first touchdown. The first touchdown occurred with pitch attitude increasing through 8°, with roll about 0°, and with throttles having just reached the flight idle position. The ground spoilers did not deploy, the airplane bounced, and nose-down elevator was initiated. Pitch attitude and vertical acceleration began decreasing, and the airplane began descending back toward the runway. Approximately 6° of nose-down elevator was maintained until about 0.5 seconds before the second touchdown when a 15° to 20° nose-up elevator input was made. The airplane touched down the second time with pitch attitude increasing through 3° and roll angle decreasing through 1°. Ground spoilers deployed to 30° after the second touchdown, and pitch attitude increased rapidly as nose-up elevator peaked at about 23°. Nose-down elevator input was initiated as pitch attitude increased through 10°, and the tail struck the ground as pitch attitude increased through 12°. Nose-down elevator input increased to about 20° as pitch attitude started to decrease, then nose-up elevator was used to slow the nose-down pitch rate. The nose gear contacted the runway, ground spoilers fully deployed, and the landing rollout was completed (see FDR plots in appendix D).

³⁶ Because this damage was substantial, the Safety Board classified the November 4, 1994, event as an aviation accident. For more information, see accident investigation file number ANC95FA008.

According to FedEx maintenance documents, permanent forward fuselage skin repairs resulting from the Memphis incident were completed in August 1995. FedEx maintenance records also indicated that the accident airplane's landing gear struts were examined during a B check on June 27, 1997, and that no anomalies were found.³⁷

1.6.2 Weight and Balance

Weight and balance information for FedEx airplanes is calculated by an automated weight and balance (AWAB) report computer program. According to FedEx procedures, station agents prepare the AWAB, which is included in the flight plan and release documentation provided to flight crews before departure; final AWAB figures are provided to flight crews just before departure. Weight and balance information for the accident airplane included the following:

Basic Operating Weight:	252,762 pounds
Three passengers:	600 pounds
Cargo:	167,384 pounds
Zero Fuel Weight:	420,762 pounds
Fuel:	138,000 pounds
Ramp Weight:	558,762 pounds
Taxi Burn:	minus 2,000 pounds
Estimated Gross Takeoff Weight:	556,762 pounds

According to McDonnell Douglas airplane documentation, the maximum gross takeoff weight for the accident airplane was 625,500 pounds, and the maximum zero fuel weight was 451,300 pounds. The airplane's maximum gross landing weight was 471,500 pounds. The airplane's actual gross landing weight was 452,300 pounds.

1.7 Meteorological Information

The METAR³⁸ valid for EWR at the time of the accident reported winds of 240° at 10 knots, visibility 10 statute miles (sm), scattered clouds at 8,000 feet, temperature 20° C, dew point 12, and altimeter 30.23 inches of mercury. The automated weather advisory system and automated weather observation system at 0130, about 2 minutes before the accident, reported winds of 270° at 10 knots, visibility 10 sm and clear. According to the CVR, the EWR tower controller informed the flight crew at 0129:45 that winds were 250° at 5 knots.

³⁷ The MD-11 was equipped with dual chamber, MLG shock struts. According to McDonnell Douglas personnel, improperly serviced struts can cause additional rebound during landing.

³⁸ METAR is the International Civil Aviation Organization (ICAO) code for routine weather reports.

1.8 Aids to Navigation

No problems with navigation aids were reported.

1.9 Communications

No external communication difficulties were reported.

1.10 Airport Information

EWR, located 3 miles south of Newark at 40°41.57' N latitude and 74°10.10' W longitude, is a publicly owned airport operated by the Port Authority of New York and New Jersey and handles about 421,000 commercial, military, and general aviation operations per year. It has an FAA-approved emergency plan and is certified as an Aircraft Rescue and Firefighting (ARFF) Index E³⁹ airport under 14 CFR Part 139. EWR has an elevation of 18 feet above msl.

The airport has three asphalt runways with precision instrument markings: 4L/22R, 4R/22L, and 11/29. Runway 22R is 8,200 feet long and 150 feet wide. Its grooved, asphalt surface was reported by EWR tower controllers to be in good condition at the time of the accident. The runway was equipped with high-intensity runway edge lights, centerline lights, and runway end identifier lights. Runway 22R was not equipped, nor was it required to be equipped, with runway approach lights or touchdown zone lights. The three-bar visual approach slope indicator (VASI) was located on the left side of the runway. The runway was also equipped with a Category I instrument landing system (ILS), which included an outer marker beacon but no middle or inner markers. The glideslope was set at a standard 3° angle. There were no FAA Notices to Airmen (NOTAM) on file indicating that any landing aid components were inoperative.⁴⁰

1.11 Flight Recorders

1.11.1 Flight Data Recorder

The airplane was equipped with a Sundstrand Data Control (model UFDR) FDR, SN 2222, which was equipped to record more than 250 parameters. The nonprotected portion of the FDR was destroyed in the postimpact fire. No evidence of thermal or impact

³⁹ Index E refers to ARFF requirements for airports used by air carrier aircraft of at least 200 feet in length. Title 14 CFR Part 139 requires that Index E airports have a minimum of three ARFF vehicles carrying water and fire-suppressing chemical foam and that the total quantity of water for foam production be at least 6,000 gallons.

⁴⁰ NOTAMs are disseminated to give information about conditions or changes in any aeronautical facility, service, procedure, or hazard.

damage was found on the inside of the crash-protected portion of the FDR, and all data were recovered successfully.

1.11.2 Cockpit Voice Recorder

The airplane was equipped with a Fairchild model A-100A CVR, SN 25685. The recording, which contained good quality audio information,⁴¹ consisted of four channels including the captain's microphone, the first officer's microphone, and the cockpit area microphone. The fourth channel included the interphone and public address systems. The external surface of the recovered CVR was found scorched and coated with soot but with little impact damage. The interior of the crash case was also found scorched and discolored but with no impact damage. Fluctuations in the tape's audio amplitude, consistent with heat damage, were present in the first 5 minutes of the recording playback. A transcript was prepared of the entire 30-minute, 25-second recording (see appendix B).

1.12 Wreckage and Impact Information

The airplane's wreckage was distributed along a 2,900-foot-long debris path that gradually arced to the right across runway 22R (see figure 7). Pieces of the right inboard trailing edge flap were found at the beginning of the wreckage path, about 2,226 feet from the runway's displaced threshold. The main wreckage, located about 5,126 feet from the runway threshold and 580 feet to the right of the runway centerline, comprised the fuselage, left wing, nose gear, left MLG, center MLG, and horizontal stabilizer. The fuselage came to rest inverted with the nose on a 95° heading. Other airplane components and structure separated from the airplane during the crash sequence and were located along the debris path.

Rubber marks consistent with the touchdown of the airplane's right MLG tires were found about 1,126 feet from the runway displaced threshold. Rubber marks consistent with the touchdown of the left MLG tires and center MLG tires were found at 1,151 feet and 1,160 feet from the runway displaced threshold, respectively. The location of the tire marks was consistent with a touchdown near the center of the runway. Rubber marks consistent with a second touchdown of the right MLG tires were found about 1,924 feet from the runway displaced threshold (798 feet after the tire marks consistent with the first touchdown). Rubber marks consistent with the center MLG tires were found again about 1,983 feet from the runway displaced threshold. The locations of the second touchdown tire marks were consistent with a touchdown near the center of the runway. The right MLG tire rubber marks veer to the right about 1,995 feet from the runway displaced threshold.

⁴¹ The Safety Board ranks the quality of CVR records by five categories: excellent, good, fair, poor, and unusable. In a recording of "good quality," most of the crew conversations can be accurately and easily understood, and the transcript developed from it may indicate several words or phrases that are not intelligible. Any loss in the transcript can be attributed to minor technical deficiencies or momentary dropouts in the recording system or to several simultaneous cockpit/radio transmissions that obscure each other.




Figure 7. Wreckage distribution diagram.

Ground scarring consistent with the No. 3 (right) engine nacelle contacting the runway were found about 2,164 feet from the runway displaced threshold and continued to about 3,476 feet from the runway threshold. Runway scarring consistent with impact of the right inboard trailing edge flap was found about 2,299 feet from the runway threshold, ending about 2,376 feet from the threshold (where the right inboard trailing edge flap was found). Soot marks consistent with burning fuel were found about 2,506 feet from the threshold and continued to the end of the wreckage path. Runway scrape marks and purple paint⁴² consistent with the airplane's tail striking the runway were found about 2,644 feet from the runway threshold and ended about 3,060 feet from the threshold. About 2,826 feet from the threshold, runway scrapes, soot marks, and runway surface gouging began turning toward the right of the runway.

The right wing, the vertical stabilizer, and all three engines separated from the airplane and were found in a grassy area to the right of the runway, about 4,577 feet from the runway threshold, and had sustained fire damage consistent with a postaccident fuel fire. The right MLG strut assembly and two MLG wheels and tires were found on the right edge of the runway, about 4,805 feet from the runway threshold. The other two right MLG wheels and tires were found about 235 feet to the right of the runway centerline and about 4,957 feet from the threshold.

The right wing separated from the fuselage just inboard of the wing MLG and fuel closure bulkhead at wing station (WS) 264. The outboard upper surface was intact and sooted. Buckling was noted in the upper surface skin approximately 12 feet inboard from the tip. The lower wingtip winglet had separated from the wingtip at its attach surface. The upper winglet remained attached to the wingtip. The No. 3 engine and pylon had separated from the wing completely, and the engine remained attached at the aft and forward pylon mounts. Stringers at the inboard end of the right wing upper surface, as well as the upper surface chordwise fracture surface, were bent in an upward direction. The rear spar fracture near WS 264 was bent aft.

All leading edge control surfaces outboard of WS 264 remained attached to the wing. The inboard flap structure had separated from the wing (the full 20-foot section of right inboard flap was found on taxiway H), portions of the separated flap hinge bracket structure were found close to the wing trailing edge, and the spoiler actuator and attach points were found intact.

The right MLG was separated from its attach points on the right wing (see figure 8).⁴³ The attach points were broken from the wing, except for the forward lug, which remained attached to the wing with no evidence of failure. The right MLG truck assembly⁴⁴ was found separated into four parts: one part was attached to the aft axle, where the wheels and tires were found intact; a second part was found on the runway; a

⁴² The accident airplane's tail cone, No. 2 engine, and vertical stabilizer were painted purple.

⁴³ On the MD-11, the right and left MLG comprise four wheels, tires, and brakes and are mounted to the wing structure outboard of the fuselage. The center MLG assembly comprises two wheels, tires, and brakes and is mounted to the center fuselage. Landing gear extension and retraction are hydraulically actuated.

⁴⁴ The landing gear wheel axles attach to the truck beam.




Figure 8. Right MLG components.

third part was found attached to the forward axle, where the No. 3 and No. 4 wheels were found intact; and a fourth part was found attached to the strut assembly. The pivot pin was found intact between the truck beam and the oleo piston assembly. The oleo piston and cylinder were found intact, and the piston was fully extended. The torque links were intact and had no structural damage. Parts of a wing-to-gear fitting were found on the aft trunnion⁴⁵ bolt. The forward trunnion bolt, or fuse pin,⁴⁶ failed and had broken into two pieces along the shear plane.⁴⁷ The aft portion of the forward trunnion bolt was found on the runway, and the forward portion was found in the right wing-to-gear-fitting forward trunnion lug.

Scraping damage was found on the forward trunnion lug's forward face. The fixed side brace (to) folding side brace fitting joint was found intact with the side brace, the fixed brace, the side brace fitting (commonly referred to as the "pillow block"), and the pillow block hinge joint pin assembly (see figure 8). The inboard attach bolt was found intact with the pillow block and a part of the trapezoidal panel assembly. The remaining bolt was found detached and in two pieces. One piece was found in the remaining part of

⁴⁵ A trunnion is a pin or pivot on which an attachment can be rotated or tilted.

⁴⁶ A fuse pin is an attachment fitting designed to fail at predetermined loads to prevent more severe damage to surrounding structures. MD-11 landing gear fuse pins were designed and positioned to allow the landing gear to fail under loads in the aft direction.

⁴⁷ A fuse pin shear plane is the point at which the pin is designed to fail.

the trapezoidal panel that had broken off from the fuselage and the pillow block assembly. The other bolt piece was found on the runway. The fixed side brace was found fractured about 6 inches from the wing fitting lug and was bent in the aft direction where it failed.

A metallurgical examination of the recovered right MLG components determined that all fracture surface evidence was consistent with overload failure. No evidence of fatigue cracking or corrosion was found. In addition, the examination found no indications of preimpact failures or anomalies. An examination of the right MLG tires found no evidence of pretouchdown failures or malfunctions.

The airplane's nose landing gear was found intact on the inverted fuselage. There was evidence of heat damage to the assembly and tires but no indication of structural damage to the assembly's support or wheel well structure. The strut was fully extended.

The center MLG assembly was found attached to the airplane in an upright position (on the inverted fuselage) but pushed into the fuselage. The strut was fully extended. The oleo piston was separated above the axle, and the remaining part of the oleo piston was pushed inside the cylinder.

The left MLG was found intact. There was evidence of fire damage but no indications of structural damage, except for a broken lower valve assembly (used to inflate the strut assembly lower chamber).⁴⁸ The tires were intact and pressurized. Examination determined that the torque of the two bolts that connected the side braces to the left trapezoidal panel pillow block fitting were normal.

The left wing came to rest inverted but remained attached to the fuselage, and all of the control surfaces were attached to the wing. The wing sustained severe damage in the postcrash fire, and sections were melted and sooted by the heat and flames. The left inboard flap was partially extended (10° to 15°) and connected to its attachment points. The left outboard flap was retracted and connected to its attachment points.

All three engines were separated from their wing or vertical stabilizer attachments. The No. 1 (left) engine fan cowl was separated from the engine, broken into pieces, and damaged by impact and postcrash fire. Fan blade damage (gradual bending) was consistent with damage occurring during low-speed rotation. The thrust reverser actuators were found in their stowed positions. No evidence of an in-flight engine fire was found. The No. 2 (tail-mounted) engine was separated from the vertical stabilizer at the pylon attachment points. The engine nacelle was found intact with minor impact damage and with postcrash fire damage. All fan blades were intact, and the thrust reverser actuators were found in their stowed positions. No evidence of an in-flight engine fire was found. The No. 3 (right) engine separated from the wing at the pylon-to-wing attachment, and witness marks on the wreckage indicated that the engine's turbine rear frame contacted the ground at the 6 o'clock position. The fan cowl separated from the engine, broke into pieces, and was damaged by impact and postcrash fire. Fan blade damage was consistent

⁴⁸ The valve was damaged during postaccident recovery efforts.

with damage occurring during low-speed rotation. The thrust reverser actuators were found in their stowed positions. No evidence of an in-flight engine fire was found.

1.13 Medical and Pathological Information

The flight crew provided postaccident toxicological samples, which were tested and found to be negative for drugs of abuse.⁴⁹

1.14 Fire

A fuel-fed fire erupted on impact.

1.15 Survival Aspects

1.15.1 Flight Crew and Passenger Egress

The captain told Safety Board investigators that the airplane began a “gradual roll” on the runway at the beginning of the accident sequence and that it remained on its side for a time as it slid down the runway. He stated that he remembered an explosion and saw orange flames. The captain stated that after the airplane pivoted and came to rest inverted, he released his seat belt and shoulder harness and fell on his head and hand. He stated that he crawled to his cockpit window and saw that there was no fire on that side. He stated that when he pushed the window release handle down, it jammed but opened when he applied more force. The captain stated that the window jammed again as he tried to crank it open and that he had to kick an obstruction out of the way to continue. He stated that he exited through the window and shouted “this window is open.”

The first officer described the roll as a slow, “controlled soft turnover” and stated that he was not slammed into his seat belt or shoulder harness by impact or rolling forces. He stated that he saw orange flames and sparks and the runway pavement coming up toward him as the airplane rolled over. The first officer stated that he unbuckled his seat belt and shoulder harness and rolled to the other side of his seat because he thought the fuselage and window structure were going to fail. He stated that as the airplane rolled about 135°, he “bear hugged” his seat back and stood on the (inverted) overhead instrument panel between his seat and the center console.

The first officer stated that as the airplane’s slide began to slow, he heard the captain say “we’ve got to get out of here” and that he saw the captain and jumpseat passenger hanging upside down, restrained by their seat belts and harnesses. The first officer stated that after the airplane came to a stop, he went to the forward cabin area to

⁴⁹ The five drugs of abuse tested in postaccident analysis are marijuana, cocaine, opiates, phencyclidine, and amphetamines.

check on the two cabin passengers. He stated that he found one passenger strapped upside down in a seat. The second passenger had unbuckled the seat belt and was standing on the ceiling. The first officer stated that the passengers were talking and appeared to be uninjured and that he attempted to open the right forward cabin door but was unsuccessful. He stated that he saw smoke coming from the cargo cabin and pushed the two passengers in the direction of the cockpit. He stated that he then attempted to open the left forward cabin door, but the handle was blocked by debris. The first officer stated that he yelled into the cockpit that the doors could not be opened and to open the cockpit windows. He stated that the captain exited through the cockpit window, followed by the jumpseat passenger and the two cabin passengers. The first officer stated that he exited through the window behind the cabin passengers. He stated that firefighting vehicles were approaching the airplane when they exited and that they moved to a runway marker located about 100 feet away from the airplane's nose as firefighters arrived.

The jumpseat passenger stated that he released his seat belt and harness after the airplane came to a stop and "did a half twist and roll" to get down on the ceiling. He stated that he remembered hearing the first officer yell that the doors would not open and that the captain opened a cockpit window and told him to come forward. He stated that it was difficult to maneuver in the cockpit because of the inverted seats and debris.

1.15.2 Emergency Response

Air traffic controllers in the EWR control tower witnessed the accident and immediately notified Port Authority fire (ARFF) and police units, transmitting a Condition One alarm.⁵⁰ While en route to the crash site, the ARFF fire crew chief reported that flames were visible along runway 22R and that flames were venting from the aft section of the fuselage. The ARFF fire crew chief stated that it took about 35 seconds to drive from the fire station to the accident site and that five ARFF vehicles were engaged in fire suppression within 3 minutes of the alarm. The Port Authority incident commander told Safety Board investigators that he contacted the Port Authority police dispatcher while en route to the crash site and requested activation of the mutual aid contingency (emergency response) plan with the Newark Fire Department (NFD). He stated that he assumed that the accident airplane carried hazardous cargo because it was a late-night cargo flight and that firefighters and equipment were deployed accordingly (that is, upwind and wearing protective breathing gear). Newark authorities were contacted about 0138 and dispatched firefighting vehicles and personnel, who arrived on scene about 0146.

About 0200, the NFD dispatcher notified the Newark Hazardous Materials Response Unit (HMRU) and the New Jersey Department of Environmental Protection (DEP). Newark HMRU personnel arrived at the accident scene shortly after 0200. DEP personnel arrived about 0300 and began downwind wind direction and air quality

⁵⁰ EWR's airport certification manual defines a Condition One alarm as "an actual or impending crash. Major aircraft accident or fire. Aircraft dire emergency. Full response as indicated in the aircraft emergency plan will go into effect."

monitoring operations. About 0315, DEP personnel advised the incident commander that the monitoring had not detected elevated levels of toxic chemicals in the air.

About 0320, the NFD deputy chief reported hearing “popping” sounds as the fire in the fuselage advanced toward the forward cabin bulkhead.⁵¹ According to ARFF and NFD logs, the entire wreckage site was covered with fire-suppressing foam about 0430. The fire was extinguished (except for sporadic hot spots) about 0700, according to ARFF and NFD logs. About this time, the NFD deputy chief discovered a package marked “Biomedical Research”⁵² and immediately halted all firefighting operations until a complete cargo manifest was obtained (see section 1.18.1 for details about dissemination of hazardous materials information and efforts to obtain information about the airplane’s cargo). Port Authority ARFF vehicles were withdrawn about 0700, and NFD assumed control of the accident site.

1.16 Tests and Research

1.16.1 Landing Gear Energy and Load Limit Certification

Landing gear certification requirements for transport category airplanes that were applicable to the certification of the MD-11 are primarily contained in 14 CFR 25.721 through 25.737.

Subsection 25.721(a) states:⁵³

The [MLG] system must be designed so that if it fails due to overloads during takeoff and landing (assuming the overloads to act in the upward and aft directions), the failure mode is not likely to cause—

- (1) For airplanes that have passenger seating configuration, excluding pilots seats, of nine seats or less, the spillage of enough fuel from any fuel system in the fuselage to constitute a fire hazard; and
- (2) For airplanes that have a passenger seating configuration, excluding pilots seats, of 10 seats or more, the spillage of enough fuel from any part of the fuel system to constitute a fire hazard.

Subsection 25.721(b) states further that “each airplane that has a passenger seating configuration...of 10 seats or more must be designed so that with the airplane under

⁵¹ According to FedEx shipping documents, declared items of hazardous materials were loaded in the forward 1L and 2L cargo container positions. Thirteen packages of hazardous materials were in container 1L, including 10 packages of (flammable gas) aerosols and 3 packages of a flammable solid. The 2L container carried 1 package of perfumery, classified as a flammable liquid, a package of gallium (a corrosive), and methyl methacrylate, another flammable liquid.

⁵² Subsequent examination of the package determined that it contained sterilized blood and that it was not a dangerous goods shipment.

control it can be landed on a paved runway with any one or more landing gear not extended without sustaining a structural component failure that is likely to cause the spillage of enough fuel to constitute a fire hazard.”⁵⁴

Section 25.473, “Ground Load Conditions and Assumptions,” describes the descent velocities that must be assumed for certain landing conditions (for example, level landing, tail-down landing, one-wheel landing, and side load conditions).

Section 25.723, “Shock Absorption Tests”; Section 25.725, “Limit Drop Tests”; and Section 25.727, “Reserve Energy Absorption Drop Tests,” describe landing gear energy and load limits. Subsection 25.723(a) states that “it must be shown that the limit load factors selected for design in accordance with [Section 25.473] for takeoff and landing weights, respectively, will not be exceeded.” Sections 25.725 and 25.727 describe the values and parameters to be used in conducting the landing gear limit and reserve energy absorption drop tests described in Subsections 25.723(a) and (b). Subsection 25.723(b) also states that the “landing gear may not fail in a test, demonstrating its reserve energy absorption capacity, simulating a descent velocity of 12 fps at design landing weight, assuming airplane lift not greater than the airplane weight acting during the landing impact.”

Subsection 25.473 (1) states:

The selected limit vertical inertia load factors at the center of gravity [c.g.] of the airplane may not be less than the values that would be obtained—

- (i) In the attitude and subject to the drag loads associated with the particular landing condition;
- (ii) With a limit descent velocity of 10 fps at the design landing weight (the maximum weight for landing conditions at the maximum descent velocity); and
- (iii) With a limit descent velocity of 6 fps at the design takeoff weight (the maximum weight for landing conditions at a reduced descent velocity).

⁵³ This requirement was added as a result of a notice of proposed rulemaking (NPRM) issued by the FAA on August 12, 1969. In this NPRM, the FAA stated that the existing Section 25.721 “was designed to [e]nsure that if the landing gear fails, no part of the fuel system in the fuselage of the airplane will be punctured. It is proposed to extend this protection to the entire fuel system of the airplane. However, since not all punctures of the fuel system would result in a fire hazard, the proposal would protect against those punctures only that would result in the spillage of enough fuel to cause a fire.” The NPRM proposed amending 25.721 to require that “[t]he [MLG] system...be designed so that if it fails due to overloads during takeoff and landing (assuming the overloads are in the vertical plane parallel to the longitudinal axis of the airplane), the failure mode is not likely to cause the spillage of enough fuel from any part of the fuel system to constitute a fire hazard.”

In its final rule, which adopted the language that currently appears in Subsection 25.721(a), the FAA stated on February 24, 1972, that this paragraph had been “substantially amended” since the NPRM and that “in response to a comment, the parenthetical expression in the proposed amendment has been changed to make it clear that the regulation is based on the assumption that the overloads act in the upward and aft directions.”

⁵⁴ The cargo version of the MD-11 was designed to passenger aircraft certification standards.

Subsection 25.473 (2) states that “airplane lift, not exceeding the airplane weight, may be assumed to exist throughout the landing impact and to act through the [c.g.] of the airplane.”

According to Boeing, the MD-11 was designed to allow “sacrificial shedding” (by use of fuse pins) of the MLG assemblies under aft (drag) overload conditions to prevent catastrophic loads being transmitted to the wing box.⁵⁵ Boeing indicated that the MD-11 landing gear certification was based on drop tests conducted on DC-10 landing gear, which are nearly identical to MD-11 landing gear.

Boeing, in a submission⁵⁶ to the Safety Board, stated that a review of “historical data indicated that [MLG] failure due to overload was most likely to occur as a result of striking an obstruction.” The Boeing submission, which described Douglas’ landing gear design philosophy for the DC-10 and MD-11, added the following:

The [Boeing Long Beach Division] believed that the most probable condition would be a 1.0 g vertical load at maximum ramp weight (i.e., the weight of the aircraft would be distributed between the two [right and left] [MLG], the center [MLG] and the nose landing gear with no aerodynamic lift), static gear extension, with a drag load applied to the axles until the failure of the gear. For this condition it was shown by analysis that the [MLG] would separate from the wing without any failures to the fuel tanks. This was validated by tests done on full scale DC-10 landing gear and wing test structure. By analysis this was shown to be true for vertical loads up to 2.0 g’s (i.e., twice the weight of the aircraft is distributed between the two [right and left] [MLG], the center [MLG] and the nose landing gear with no aerodynamic lift) at the aircraft ramp weight.

Because a fuse [pin] in the vertical plane may not prevent substantial loads from entering the wing structure once the fuse has released, and because the review of historical data indicated that failure due to overload was most likely to occur as a result of high drag loads, a different approach was taken to assure fuel tank integrity for the high vertical load (above 2.0 g’s) condition. For vertical loads above 2.0 g’s, the [MLG] is not designed to separate from the wing. Instead, the landing gear and its back-up structure are designed to be very robust, i.e., they are designed to withstand significantly greater descent rates than the 12 fps (ultimate) required per Part 25.723 (b). Analysis has indicated that for a maximum landing weight, typical-landing-configuration landing, the MD-11 [MLG] can withstand up to a 16.9 fps descent rate without bottoming the shock struts or failing its backup structure including the wing rear spar. Similarly, for a rolled landing (8 degrees one-wing-low attitude, with lift equal to aircraft weight), the landing gear can withstand up to 15 fps descent rate without bottoming the shock strut or failing its back-up structure including the wing rear spar.⁵⁷

⁵⁵ The wing box, often the heaviest single piece of an airplane’s airframe, is the strong, primary structure of a modern, stressed-skin wing. Loads are taken by cantilever beams comprising upper and lower skins joined to front and rear spars.

⁵⁶ Boeing’s Long Beach Douglas Products Division. Undated. Submission of Proposed Findings for *FedEx Flight 14, MD-11-F, N611FE, Newark, New Jersey, 31 July 1997*.

The Boeing submission added that "creating a reliable vertical fuse can only be accomplished by adding weight and complexity" to the airplane, and increasing landing gear energy absorption capability "could have a cascading effect in that the total aircraft structure would have to be strengthened to absorb the additional energy." For "extreme roll angles," the Boeing submission noted that "the landing gear design criteria and philosophy do not come into play. Striking the wingtip may fail the wing directly or may cause the aircraft to 'cartwheel.'" The Boeing submission stated that "for lesser roll angles the single gear on the 'wing low' side may fail (or fuse if so designed) if the combination of sink rate and roll rate (and amount of wing lift) impart loads that exceed the design thresholds." Boeing's submission added the following:

For 'fused' aircraft the (remaining) energy of vertical descent would then be absorbed by flexing the low-side wing, or by some combination of exercising the high-side landing gear, and flexing the low-side wing. For some combinations of sink and roll rates the low-side gear may fuse (followed by the wing engine/nacelle) and the aircraft may 'settle in' on the remaining gear and the low-side wing without compromising fuel tank integrity. For higher sink and roll rates (or lower amounts of wing lift) the low-side wing may fail nonetheless, as a result of exceeding its flexure (bending) limits.

The Boeing submission further noted that because "kinetic energy is a form of energy associated with the motion of an object, the kinetic energy dissipated into the landing gear during landing touchdown is derived from both the rate of descent and the aircraft's rolling rate at touchdown...During a normal landing, the kinetic energy from descent and roll rates is absorbed by shock strut stroking at touchdown, which can be called 'Phase 1' energy absorption." Boeing's submission added that during "Phase 2" energy absorption, which also occurs via shock strut stroking, "potential energy related to aircraft weight⁵⁸ eventually gets absorbed by the main and nose landing gears as wing lift is reduced due to the reduction of both angle of attack and forward velocity and deployment of ground spoilers. This energy is normally absorbed some time after the total kinetic energy related to the descent rate is completely absorbed at initial touchdown." The Boeing submission added the following:

In a stabilized approach, assuming calm atmospheric conditions and ignoring ground effect, once the aircraft's rate of descent is stabilized, vertical acceleration is equal to 1.0 g and lift is equal to the aircraft weight. ... If the aircraft's vertical acceleration at touchdown is a value less than 1.0 g, then the energy that results from the positive acceleration towards the ground due to the reduced lift becomes additive to the kinetic energy from the rate of descent. The effect is that the landing gear has to absorb not only the Phase 1 energy at touchdown, but a portion of the Phase 2 energy at the same time. The end result is a higher load into the landing gear and attaching structure during touchdown.

⁵⁷ Boeing further stated in its submission that it had "begun an evaluation into the net safety benefit of installing a fuse for vertical overload in the DC-10 and the MD-11 [MLG]...that could take a year or more to complete." Boeing also stated that it would include the Newark accident scenario in its study of the potential safety benefits of vertical fusing.

⁵⁸ Potential energy is a function of gravitational acceleration and vertical distance above a reference level, or the relative position of an object.

The accident aircraft's recorded vertical acceleration at the start of the second touchdown impact was approximately 0.5 g, that is, wing lift was equal to approximately half the aircraft weight, which imparted huge additional potential energy into the landing gear and attaching structure above and beyond those associated with the 11 fps [c.g.] descent rate and the 7 [degree per second] roll rate [which combined resulted in the 13.5 fps sink rate]. In addition, these energies were imparted primarily into the [right] MLG only, due to the right wing down roll angle...at touchdown. At the accident aircraft's landing weight of 452,000 [pounds]...potential energy of 678,000 ft-lbs was added to the approximately 896,000 ft-lbs. [Right] MLG kinetic energy from the combined aircraft descent and roll rates, for a total energy into the [right] MLG of nearly 1,574,000 ft-lbs. Comparing the loads into the [right] MLG from the accident landing at Newark to the [right] MLG energy absorption requirements for certification shows that the energy developed during the accident landing was over 3 times the reserve energy (ultimate) certification requirements for a single [MLG].

Figure 9 shows Boeing's calculations of the energy imparted to the right MLG in the Newark accident.




Figure 9. Boeing calculations of right MLG energy in the Newark accident.

The Boeing submission concluded that a “sink rate of approximately 13.5 fps (11 fps at the [c.g.] plus the [right-wing-down] roll rate) at touchdown impact is, by itself, outside the design envelope; a 13.5 fps sink rate landing on a single [MLG] is even further outside the design envelope; [and] a 13.5 fps sink rate landing on a single [MLG] with a net 0.5 g downward acceleration is yet further outside the design envelope.”⁵⁹

In addition, the Boeing submission noted that it was revising the MD-11 maintenance manual to expand hard landing definition and inspection criteria. Boeing

stated that the criteria should include "information on the effects of reduced lift and adverse aircraft attitude on loads into the landing gear." The Boeing submission added the following:

Data developed during this investigation show that the absolute recorded vertical acceleration value during landing should not be the only criteria for determining if a hard landing has taken place. The recorded vertical acceleration at the beginning of the touchdown can also be very important. Specifically, if the recorded vertical acceleration at the beginning of the landing is less than 1.0 g, then aircraft weight that is normally accommodated by the 1.0 g wing lift is instead transmitted into the landing gear on top of the loads required to decelerate the airplane vertically from the aircraft's sink rate. The effects of non-routine aircraft pitch and roll attitudes on energy introduced into singular landing gear should also be part of the hard landing evaluation.⁶⁰

1.16.2 Dynamic Failure Simulation of MD-11 Right Wing Structure and Right Main Landing Gear Assembly

Initial simulation conducted by Boeing did not show loads great enough to cause the failure of the right-wing rear spar, MLG, or associated structure. Subsequently, Boeing contracted with Mechanical Dynamics, Inc., (MDI), a Michigan-based company specializing in dynamic simulation, for assistance. Boeing and MDI developed a computer model of the airplane structure to simulate its flightpath based on the FDR data and determine the resulting dynamic loading imparted to the aircraft structure during the accident.⁶¹

MDI and Boeing personnel developed a computer model of an MD-11's structural elements and validated its static and dynamic characteristics via comparison with certification test data. Two structural failure sequence theories were then explored. The first scenario (beginning at the second touchdown impact) proposed the following failure sequence:

- the right MLG strut and tires bottomed but did not fail immediately, the right inboard flap separated, and the outboard bolt of the side brace fitting failed because of inboard load on the lower right MLG;
- the subsequent gear failure transferred the load to the No. 3 engine and pylon and outboard wing and flap; and

⁵⁹ Certification for landing on one wheel is governed by 14 CFR 25.483, "One-wheel Landing Operations." Based on conditions and assumptions contained in Section 25.473, Section 25.483 requires that an airplane be certified to withstand a 10 fps vertical landing at its maximum landing weight (471,500 pounds) with zero roll angle.

⁶⁰ Boeing incorporated these findings into a revised maintenance manual that was released in November 1999.

⁶¹ The simulation is based on a mechanical system simulation software package, known as ADAMS software, developed by MDI. According to MDI, ADAMS software is also widely used in the automotive, marine, and construction vehicle industries. The Board's Airplane Performance Group reviewed this simulation effort and verified the methodology.

- the wing failed inboard of the landing gear fitting.

According to the Boeing submission, simulations of Scenario 1 did not generate loads great enough to fail the side brace fitting. Scenario 1 also failed to match runway evidence.

The simulations for Scenario 2 indicated the following failure sequence:

- right MLG strut and outboard tires bottomed and vertical strut “spiked”;
- right rear spar web and spar caps fractured inboard of the gear fitting;
- inboard upper wing (skin and stringer) panel began to collapse from back to front;
- outboard right wing twisted leading-edge down, right MLG wing fitting moved up, and right MLG tires moved aft and outboard;
- right inboard flap track came off rollers at the side of the fuselage;
- right inboard flap twisted off its outboard hinge support fitting and separated from the aircraft;
- excessive movement of the right MLG and its wing attach fitting imparted large prying loads on the side-brace-fitting-to-trapezoidal-panel joint, inboard half of the inboard trap panel fractured, and outboard bolt fractured;
- right [engine] nacelle contacted runway;
- fuel spilled from the right wing and ignited;
- aircraft began to roll clockwise, “dragging” the right wing underneath; and
- other failures were consequent.

The Boeing submission concluded that its dynamic simulation model of the Scenario 2 accident sequence correlated “substantially with evidence from the crash site” and FDR data.⁶² Elaborating on this point, Boeing concluded that

it is most probable that, as a result of loads applied to the right [MLG] that were substantially beyond design limits, the right wing structure failed. The failure most probably initiated at the rear spar/bulkhead (trunnion) rib interface and progressed through the primary wing box structure. As a result of this failure, the right main gear trunnion moved substantially upward and aft with respect to the trap [trapezoidal] panel fitting. This motion was sufficient to cause the fixed side brace to bind against the pillow block footing, tearing the pillow block loose from the trap panel.⁶³

⁶² The Boeing submission stated that the “failure of the rear spar web and the wing torque box [was] modeled as perfectly elastic/perfectly brittle. In the real structure, the failure would be elastic/plastic. Consequently, the results from the point of failure of the rear spar on become less quantitative than prior to this point in the event. Nevertheless, the model behavior subsequent to the structural failure appears to be in reasonably good qualitative agreement with the evidence from the crash site.”

1.16.3 Tests of Airplane Systems

Electronic airplane systems that contained nonvolatile memory were removed for examination and testing. Testing determined that the airplane's three air data computers, the hydraulic systems control module, two flight control computers (FCC), the miscellaneous system controller, and two advanced flight management computers were operating normally before the accident and that their failures were consistent with loss of electrical power after the second touchdown and structural failure of the airplane.

The Safety Board reviewed the longitudinal stability augmentation system (LSAS) and found that its inputs to and outputs from the FCC were continuously monitored, even when the LSAS was not actively commanding the elevators (for example, below 100 feet agl). When these monitors detect a failure, a fault is stored in FCC maintenance memory. A review of FCC maintenance memory for the accident flight revealed that the FCCs did not record any LSAS fault messages immediately before or during the first touchdown. Additionally, the system design provides that failures detected with respect to LSAS inputs/outputs will also result in the affected LSAS channel(s) being shut down, which is recorded on the airplane's FDR.⁶⁴ The FDR data for the accident flight did not indicate any LSAS failures during the accident landing. The FCCs did record LSAS failure fault messages at speeds below the first and second recorded touchdown speeds (149 knots and 152.5 knots, respectively).⁶⁵

The airplane's left and right fuselage-mounted landing light filaments were examined for impact-related failures. The right landing light filament was found intact with its support structure intact. The left landing light filament was broken into pieces and had slight melting on several ends consistent with having broken while operating. No stretching was found on either filament.

1.17 Organizational and Management Information

FedEx began U.S. domestic operations with a fleet of 14 Falcon jets on April 17, 1973, and expanded its domestic operations between 1973 and 1980. Following a series of

⁶³ The Boeing submission also noted that, according to simulations, "subsequent to the failure [of the spar web structure], the right wing twists substantially nose-down under the imposed loads. This twisting causes the right wing to 'dump' most of its lift and results in a sudden and substantial outboard motion of the right main gear bogie, caused by the fixed and folding landing gear side braces pivoting about their (common) attachment at the trap panel fitting attachment point."

⁶⁴ The shutdown is accomplished by deenergizing the elevator's electrical shutoff valves that, when energized, permit LSAS commands to move the elevator. The shutdown would be annunciated to the flight crew via the LSAS FAIL lights on the overhead panel as well as electronic instrument system alerts (providing there are no display system inhibits in effect); an LSAS "FAIL" would also be logged in the FDR if the fault was sufficiently sustained to be recorded by the FDR (each LSAS channel is sampled twice per second).

⁶⁵ The airspeeds logged with these faults are generated by the digital air data computer and are routed to the centralized fault display system via the FMCs, resulting in a latency of less than 0.5 seconds from generation to storage.

international mergers in the 1980s, FedEx began operations in Europe and Asia. FedEx operates the largest all-cargo fleet, with a combined transport capacity of about 26.5 million pounds daily. The airline serves 365 airports worldwide in 210 countries with a fleet of 650 airplanes, including 29 MD-11s and 90 DC-10s. More than 150,000 employees handle 3.3 million packages daily (of which 20,000 daily are dangerous goods).⁶⁶ The company employs about 3,700 flight crewmembers.

1.18 Additional Information

1.18.1 Dissemination of Hazardous Materials Information

FedEx uses several forms to document the shipment of hazardous materials on board its cargo airplanes. The form “Notification of Dangerous Goods Loading (Part A)” is completed for all flights, including those without hazardous materials on board. Part A is an envelope with another multicopy form on the front that identifies cargo containers by their positions on the airplane and the classes of hazardous materials, such as flammable liquids and corrosives, in each container. The Part A envelope contains copies of all shipping documentation about hazardous materials on an airplane and is signed by a hazardous materials specialist and the captain.

A “Dangerous Goods Separation Pouch” for each cargo container loaded with a declared hazardous materials package is inserted into the Part A envelope. The separation pouch is also an envelope with a multicopy form on the front that identifies the various classes of hazardous materials in a specific cargo container. A copy of the form on the separation pouch is also affixed to both ends of each hazardous materials cargo container. The Part A form and the separation pouch do not indicate the specific hazardous materials and the quantities on board the airplane.

Specific information about hazardous materials in a given package, such as the proper shipping name, United Nations (UN) identification number, hazard class, packing group, quantity, and 24-hour emergency telephone number, is listed on a “Notification of Loading of Dangerous Goods (Part B)” form. The Part B form is affixed to a package containing hazardous materials along with a FedEx tracking number and remains on the package throughout shipment. A copy of the Part B form is placed in the separation pouch for the appropriate cargo container.

The assembled Part A form, separation pouches, and copies of Part B forms are carried on board the airplane so that they can be available to the flight crew.⁶⁷ Copies of the Part A form, separation pouches, and Part B forms are also retained at the originating station where the shipment was accepted and at the departing hub of the flight.

⁶⁶ FedEx fact sheet, June 2000.

The flight crew also carries a "Load and Weight Plan" form, which lists the position and weight of each cargo container on board the airplane. Remarks on the form identify classifications for hazardous materials carried in cargo containers but do not identify the specific shipping name or quantity of the hazardous material in each package.

The Port Authority incident commander stated that he requested the accident airplane's shipping documents about 5 minutes after arriving at the accident site to determine whether hazardous goods were on board.⁶⁸ Airport police relayed this request to the FedEx office at EWR. After waiting about 20 minutes, the incident commander stated that he dispatched a police officer to the FedEx office to locate the documents. After witnessing the accident, the FedEx manager for international flights at EWR contacted the FedEx Global Operations Command Center (GOCC) in Memphis, Tennessee, to coordinate collection of the accident flight's cargo documents. The FedEx duty manager also contacted the FedEx office at ANC, the departure station for flight 14, to obtain the hazardous materials shipping documents. Because the hazardous goods shipment originated in Narita, Japan, the Anchorage office did not have copies of the shipping documents. On the basis of preliminary information provided by the FedEx office in Narita and relayed through the Anchorage office, FedEx personnel in Newark forwarded a brief note to firefighters listing several of the hazardous materials on board flight 14, including the amount and the UN classification numbers.⁶⁹ The incident commander received the list between 0300 and 0320. The incident commander then requested that the Port Authority police contact the Chemical Transportation Emergency Center (CHEMTREC)⁷⁰ for a description of the materials based on their UN numbers. CHEMTREC responded that some of the material posed a contamination threat to the air and that one of the products might react violently with water. Firefighters were advised to remain upwind of the fire and to wear protective breathing gear.

Between 0500 and 0600, the Anchorage FedEx office began faxing hazardous goods information (Parts A and B) obtained from Narita to the FedEx office in Newark. According to the FedEx manager, the faxes were given to the incident commander about 0600.⁷¹

⁶⁷ In addition to requiring that the proper shipping name, UN identification number, hazard class, packaging group, total quantity of the material, and 24-hour emergency telephone number appear on shipping papers for hazardous materials, 49 CFR 175.33 also requires operators to provide this information in writing to the pilot-in-command and copies of the shipping papers to accompany the shipment on the airplane. In addition, Section 175.33 requires that emergency response information required under Subsection 172.600(g) "must be maintained in the same manner as the written notification to pilot-of-command during transport of the hazardous material aboard the aircraft."

⁶⁸ The Part A and Part B hazardous materials notification forms carried on board the accident airplane were not retrieved by the flight crew before they evacuated the airplane.

⁶⁹ The partial, handwritten list contained the UN/North American hazard identification numbers for five of seven hazardous materials on board, including a notation about "36 pounds of unknown hazardous materials."

⁷⁰ CHEMTREC is operated by the Chemical Manufacturers Association and was established to provide immediate emergency response information for handling hazardous materials and other chemicals.

1.18.1.1 Other FedEx Accidents Involving Dissemination of Hazardous Materials Information

On September 5, 1996, a FedEx DC-10-10CF was destroyed by fire after making an emergency landing at Stewart International Airport, Newburgh, New York.⁷² The emergency landing was executed after the flight crew determined that smoke was in the cabin cargo compartment. The Safety Board's investigation determined that emergency response agencies repeatedly requested specific information about the hazardous materials on board the airplane and that faxes of shipping documents sent by FedEx personnel in Memphis did not reach the incident commander. The Board also determined that many of the faxes were illegible.

The Safety Board's investigation of the Newburgh accident revealed that FedEx "did not have the capability to generate, in a timely manner, a single list indicating the shipping name, identification number, hazard class, quantity, number of packages, and the location of each declared shipment of hazardous materials on the airplane." In addition, the Board determined that FedEx was "unable to provide complete information to emergency responders in a timely manner [Part B shipping documents were not available to emergency responders]." (See sections 1.18.1.2, 1.18.2, and 2.6 for details of Board recommendations from this accident.) Two subsequent FedEx accidents also involved hazardous materials dissemination issues.⁷³

1.18.1.2 Previous Safety Board Recommendations on Hazardous Materials Information Dissemination

As a result of its investigation of the September 5, 1996, FedEx Douglas DC-10 accident at Newburgh, New York, the Safety Board issued Safety Recommendations A-98-75 and -80 on August 12, 1998. The Board noted in its analysis of the Newburgh accident that "compared to other modes of transportation, it is less likely that shipping papers on board an accident aircraft will survive or be accessible because of the greater likelihood of fire and destruction of the airplane. Because of the danger of fire, a flight crew is also less likely to have time to retrieve the shipping papers after a crash." The Safety Board concluded that "DOT hazardous materials regulations do not adequately address the need for hazardous materials information on file at a carrier to be quickly retrievable in a format useful to emergency responders."

⁷¹ According to 49 CFR 172.600(g), "Emergency Response Information," emergency response information, including an emergency response telephone number, is required to be "immediately available to any person who, as a representative of a Federal, State or local government agency, responds to an incident involving a hazardous material, or is conducting an investigation which involves hazardous material."

⁷² National Transportation Safety Board. 1998. *In-flight Fire/Emergency Landing, Federal Express Flight 1406, Douglas DC-10-10, N68055, Newburgh, New York, September 5, 1996*. Aircraft Accident Report NTSB/AAR-98/03. Washington, D.C.

⁷³ On April 7, 1998, a Cessna 208 operated by FedEx crashed near Bismarck, North Dakota. On March 5, 1998, a Cessna 208 owned by FedEx and operated by Baron Aviation Services, Inc., crashed near Clarksville, Tennessee.

Safety Recommendations A-98-75 and -80 were issued to the FAA and the Research and Special Programs Administration (RSPA), respectively, and asked them to:

Require, within 2 years, that air carriers transporting hazardous materials have the means, 24 hours per day, to quickly retrieve and provide consolidated, specific information about the identity (including proper shipping name), hazard class, quantity, number of packages, and location of all hazardous materials on an airplane in a timely manner to emergency responders.

In an October 27, 1998, response to the Safety Board, the FAA noted that RSPA was “the lead agency on this issue” and was drafting an advance notice of proposed rulemaking (ANPRM) to “require air carriers to develop and implement a system capable of providing this information during instances of emergencies.” Because Safety Recommendation A-98-80 was identical to Safety Recommendation A-98-75 issued to the FAA, the FAA response asked the Board to close Safety Recommendation A-98-75. In a November 9, 1998, response to RSPA, the Board acknowledged that RSPA and the FAA “were jointly developing” an ANPRM “to seek public comment on these recommendations.” Pending completion and review of the final rule, the Board classified Safety Recommendation A-98-80, to RSPA, “Open—Acceptable Response,” which is its current status. Noting RSPA’s assumption of lead agency responsibility in an April 22, 1999, letter to the FAA, the Board classified Safety Recommendation A-98-75 “Closed—No Longer Applicable.”

In a June 28, 2000, letter, the Safety Board requested an update from the RSPA regarding its progress on Safety Recommendation A-98-80. In a July 20, 2000, letter, RSPA stated that it is in the final stages of developing the ANPRM with the FAA and anticipates publishing it in the Federal Register by September 1, 2000. (See section 2.6 for further discussion of RSPA’s response.)

1.18.2 Cargo Operator Review and FedEx Postaccident Actions

As part of its investigation of the accident involving the FedEx DC-10 in Newburgh, Safety Board investigators reviewed seven other operators that carry cargo⁷⁴ to determine if they had the ability to quickly retrieve and produce complete information about hazardous materials carried on board a particular flight. Board investigators found that only one carrier (Swissair) had a computerized capability to provide information about the declared hazardous materials on board its airplanes. Swissair reported that all of its notification to captain (NOTOC) forms were accessible by computer and that it had developed a “simplified” NOTOC that contained the UN number, classification, name, quantity, drill code (emergency response guide), and destination of hazardous goods on board.⁷⁵ According to the Board survey, the remaining carriers, like FedEx, tracked this

⁷⁴ The September 1997 survey was administered to Airborne Express, United Parcel Service, Northwest Airlines, Swissair, United Airlines, British Airways, and Delta Air Lines.

information only by retaining, at the departing station, paper copies of the hazardous materials shipping documentation carried on board the airplane.

In a May 5, 1998, letter to the Safety Board, FedEx's president and CEO stated that FedEx was developing "systems and procedures which will reduce substantially the length of time required to provide firefighters and other emergency responders with detailed information concerning [hazardous materials] shipments aboard FedEx aircraft." The letter stated that FedEx planned to first create an "intermediate solution" consisting of an "electronic notification system upon which basic [hazardous materials] information of interest to firefighters will be entered by a DG [dangerous goods] specialist at airport ramps at departure of FedEx aircraft," including information on hazard class, quantity, and location of all hazardous materials on the airplane.

FedEx's May 5 letter outlined a "permanent solution" that would allow "the tracking, by container and aircraft, of [hazardous materials] shipments throughout the shipping cycle. Complete [hazardous materials] information, including inbound and outbound...manifests, will be available on an immediate basis at the FedEx GOCC, which is manned 24 hours-a-day, 7 days a week, and all FedEx facilities."⁷⁶ The letter indicated that this system would require "extensive system development efforts, along with scanning technologies which are currently under development" and that such development would take about 18 months before testing.

In a May 20, 1998, letter, the Safety Board replied that FedEx's plan appeared "reasonable and responsive" and asked the company to keep the Board informed of its progress and the effectiveness of the new systems.

FedEx informed the Safety Board of its progress in implementing the changes in a March 4, 1999, letter. FedEx stated that the interim system, the "manual entry of hazard class, total quantity and location of each Dangerous Good on each departing aircraft's Flight Dispatch Report," had been implemented in July 1998. The letter added that this eliminated "the necessity of faxing the basic and most needed" hazardous materials information after an accident and that the proposed fully automated tracking and tracing

⁷⁵ The simplified form, designed for use in emergencies, contains less information than required by 49 CFR 175.33 and ICAO's "Technical Instructions" for hazardous cargo transport. U.S. carriers must use the more detailed form required under Section 175.33.

⁷⁶ FedEx refers to the automated dangerous goods tracking system by the acronym BADGES (Beneficial Automation of Dangerous Goods Entry System).

system remained under development but would be ready for testing in late 1999. The letter added the following:

This system will be able to generate, on an immediate basis, a [DG] manifest which contains all of the required regulatory information for all DG shipments on every FedEx aircraft and truck...This is possible because of advanced scanning technology, sophisticated computer program development, and a dedicated and exclusive DG server. In addition to simply maintaining and displaying information, we believe the system will also alert aircraft loaders of potential problems with incompatible DG shipments, and alert truck drivers of the need for specific placards. These capabilities will reduce manifest entry mistakes and cargo loading errors, thus rendering our carriage of DG safer. It will certainly assist our efforts to get specific DG information to emergency providers.

In an April 5, 1999, letter, the Safety Board acknowledged FedEx for “the actions the company ha[d] initiated” and requested updates on the test and implementation of the system. In his April 19, 1999, letter to the Board, FedEx’s president and CEO stated that FedEx planned to trial test the software in October 1999 with a “full rollout to occur soon thereafter.”

In its March 9, 2000, letter and subsequent briefings, FedEx announced that following completion of the October 1999 software test in New Orleans, Louisiana, software changes would be finalized and more testing would be conducted in September 2000 at its St. Louis, Missouri, facility. In a March 24, 2000, letter, the Safety Board replied that it “was gratified that FedEx remained fully committed to the development and implementation of this important safety system.”

The Safety Board notes that recent software developments now offer cargo carriers several options for online retrieval of dangerous goods information, such as identifying specific information about hazardous materials on board an airplane and providing information to emergency response personnel. Several air carriers are reported to be incorporating this software into their tracking systems.

1.18.3 FedEx MD-11 Tailstrike Awareness and Training Initiatives

FedEx developed and implemented an MD-11 tailstrike awareness training program in June 1996. The program was designed to increase flight crew awareness of pilot-controlled factors that contribute to MD-11 tailstrikes, including control inputs that affect pitching tendency after touchdown. The program also focused on maintaining proper sink rates, bounce recovery, and low-level go-around techniques. FedEx incorporated the tailstrike awareness training into its MD-11 initial, transition, and recurrent training syllabi. The company also compiled and distributed a four-page “Tail Strike Awareness Information” bulletin (see appendix E) for flight crews to study before simulator training.⁷⁷ A 25-minute awareness video was added to FedEx’s recurrent ground school syllabus in August 1997.

The 1996 information bulletin stated that landing tailstrikes had occurred under the following conditions: “Flaps 35 and flaps 50, forward and aft [c.g.], light and heavy gross weight, and over-serviced and correctly serviced struts.”⁷⁸ The bulletin also stated that “one consistent factor in every landing tail strike to date [has] been an excessive descent rate with an increasing pitch attitude prior to initial touchdown.” It added that high sink rates can be caused by an unstable approach, late or abrupt align (de-crab)⁷⁹ maneuver, or early flare.

The instructor’s guide (see appendix F) for the 1996 Tail Strike Awareness Training program noted that “25 percent of MD-11 tail strikes to date have occurred on takeoff and 75 percent on landing.” The instructor’s guide recommended a 7.5° pitch attitude and thrust to recover from high sink rate and bounce. It added the following:

If a bounce occurs, a go-around should be initiated. Low level go-arounds, i.e., less than 20 feet [radio altitude], are dramatically different than higher altitude go-arounds. High altitude go-arounds are initiated with pitch, while low level go-arounds must be initiated with thrust. During low level go-arounds main wheel touchdown may be unavoidable. The PF [pilot flying] must not exceed 10 degrees of pitch or retract the landing gear until passing 20 feet [radio altitude] with a positive rate of climb.

Some tail strikes have occurred as a result of the pilot attempting to arrest a high sink rate or bounce by quickly adding up elevator. This technique immediately increases both the effective weight of the aircraft and the aircraft’s vertical velocity. The resulting increased attitude rate will aggravate the pitching tendency after touchdown and drive the main wheels into the ground, thus compressing the main wheel struts. The aft fuselage will contact the runway at approximately 10 degrees pitch attitude with the struts compressed.

The 1996 instructor’s guide included simulator scenarios designed to demonstrate tailstrike avoidance techniques. The approach and landing simulations included an early flare scenario and a high sink rate and bounce recovery demonstration.

FedEx’s 1996 MD-11 flight manual (section 7-46) noted that autothrottles should be used for landings “and will begin to retard after passing 50 feet agl.”⁸⁰ The manual

⁷⁷ The material in this June 1996 bulletin has since been updated and incorporated in FedEx flight and training manuals. In addition, following this accident, FedEx developed a tailstrike briefing guide for the tailstrike awareness program that incorporated MD-11 landing gear certification data, vertical acceleration information (the effects of acceleration on the weight bearing capability of the MLG), and described the effects of roll and pitch rates on total sink rate. For example, the FedEx bulletin describes the following landing situation: “If the pilot pushes the nose over and unloads the aircraft to .5 g prior to touchdown, the weight bearing capability of the landing gear will be reduced to 6 fps (from the original 10 fps certification).” It added: “One could easily imagine a case where a pilot inadvertently unloads the aircraft to .5 g reducing the weight bearing capability of the [MLG] to 6 fps, and also lowers the upwind wing just prior to touchdown at 6° per second generating another 2 fps of total sink rate at the [MLG], leaving only 4 fps (240 fpm) of capability.”

⁷⁸ FedEx’s current version of the MD-11 tailstrike awareness training program adds that tailstrikes have also occurred “with full, mid and no spoiler deployment.”

⁷⁹ The de-crab maneuver is the act of aligning the airplane’s longitudinal axis with the runway before touchdown during a crosswind landing.

stated that pilots should avoid holding the "aircraft off in an attempt to achieve a smooth landing. Holding [the] aircraft off to achieve a smooth landing may result in a long touchdown, unusually heavy braking, a higher pitch attitude and reduced tail clearance." The manual also noted:

Below 10 feet with the aircraft fully flared (sink rate approximately 2-4 [fps]), the basic technique is to maintain attitude by applying the required control wheel pressures. A more advanced technique is to relax the back pressure to lower the nose (approximately 1°) prior to main gear touchdown.⁸¹

The 1996 MD-11 flight manual also noted that "another contributor to tail strikes during landing is the nose-up pitching force generated by automatic ground spoiler deployment at main gear spin up." The manual (section 7-118) added:

This is quickly noted and pilots are taught to compensate for it during initial and transition training. It then becomes part of the MD-11 pilot's reflexes. Spoiler pitch-up is still present during every landing, and must be counteracted. If touchdown does occur with higher than normal pitch attitude, the nose should be lowered promptly to prevent spoiler deployment from further increasing the pitch attitude.

FedEx's revised MD-11 flight manual (section 7-1-6-1, dated June 30, 1998) noted that if the airplane "flares early and the autothrottles are allowed to retard, the airspeed will decay, elevator effectiveness will be reduced, and a higher pitch attitude will be required making pitch-up tendency after touchdown more pronounced and more difficult to counteract." The manual stated that after countering any pitch-up tendency after main wheel touchdown, the pilot should "fly the nose wheel smoothly to the runway⁸² [and] avoid full elevator down input." The revised manual also called for a 7.5° pitch attitude in bounce recovery and increased thrust "until the sink rate has been arrested and/or a normal landing is accomplished."

In "Know Your MD-11," a 1993 operator letter, McDonnell Douglas recommended the following procedure for flaring the airplane under normal conditions:

Autothrottles will begin to retard after passing 50 feet, and a slight flare should be initiated between 30 and 40 feet (approximately 2 degrees). The aircraft should touch down in the touchdown zone...Do not hold the aircraft off.

⁸⁰ As of Revision 28, June 30, 1998, the use of autothrottles is no longer mandatory for FedEx flight crews.

⁸¹ This paragraph was deleted in later revisions of FedEx's MD-11 flight manual as a result of the accident analysis provided by Boeing.

⁸² The June 1995 version of the MD-11 FCOM also stated that pilots should be prepared to counter "any pitch-up tendency as spoilers extend." The section, "Landing Characteristics and Techniques," added that after spoiler extension, pilots should "fly [the] nosewheel to [the] runway."

In addition, section 7-1-6-1 of the revised (1998) FedEx MD-11 flight manual described the following procedures for a normal landing:

Aim to touch down 1,500 [feet] from the runway threshold. The runway threshold should disappear under the nose at about the same time CAWS announces '100 [feet].' Maintain a stabilized flight path through the 50 and 40 foot CAWS callouts (unless sink rate is high). At 30 [feet] a smooth 2.5-degree flare should be initiated so as to arrive below 10 [feet] in the landing attitude. Do not trim in the flare. Elevator back pressure should be relaxed, and a constant pitch attitude should be maintained from 10 [feet] radio altitude to touchdown.

Section 7-1-6-2 of the FedEx flight manual stated that

crosswind landings are accomplished by flying the final approach in a wings level attitude with a crab into the wind. At approximately 200 [feet] agl, align the fuselage with the runway by smoothly applying rudder and maintain runway centerline by lowering the upwind wing. In high crosswinds, consideration should be given to commencing the align maneuver (de-crab) prior to 200 [feet] agl. The align maneuver shall be established by 100 [feet] agl."⁸³ The manual cautions that "excessive sink rates and subsequent tailstrikes have occurred as the result of a late or abrupt align (de-crab) maneuver.

The 1993 "Know Your MD-11" operator letter also recommended the following guidelines on go-around decisions while on approach to landing:

Experience has shown that approaches which result in large pitch deviations, and which never achieve true speed and glide path stability are much more likely to produce unpredictable landings; hold-offs, floats, hard touchdowns, strong rebounds and tailstrikes. Such approaches make it nearly impossible to establish a proper crosswind correction, and are especially risky on contaminated or slippery surfaces. A destabilized approach is a compelling reason to initiate an early go-around.

The MD-11 flight crew operating manual (FCOM), "Procedures and Techniques" (30-01, Volume Two, June 1995), states that if an airplane "is not stabilized by 500 feet agl, a missed approach should be executed."⁸⁴

⁸³ FedEx's tailstrike awareness program stated that the align maneuver was "commonly referred to as a forward slip." The term "forward slip" has since been replaced by "slip," which more accurately describes this maneuver.

⁸⁴ Boeing, in its submission to the Safety Board, stated that "operators should stress to their flight crews the importance of executing a go-around any time below approximately 500 agl that a stable approach becomes destabilized. As a general 'rule of thumb,' if large power and/or control deflections are required to maintain desired flight path and/or alignment with the runway, then a go-around is warranted."

1.18.4 MD-11 Hard Landing Accident at Hong Kong International Airport

On August 22, 1999, a China Airlines MD-11 crashed during a landing approach to Hong Kong International Airport. Of the 315 passengers and crew aboard, two were fatally injured, one passenger died later at a hospital, and 199 received various injuries. The aircraft was destroyed by impact and subsequent fire. The weather at the time of the accident included high winds and rain.

According to the Hong Kong Civil Aviation Department, after obtaining visual contact with the runway, the captain disconnected the autopilot but left the autothrottle system engaged. The airplane then continued to track the extended centerline but descended and stabilized slightly low on the glideslope. At around 50 feet above the runway, coincident with the reduction of power to flight idle by the autothrottle system and an increase in pitch attitude, the indicated airspeed reduced from 170 knots to 152 knots immediately before touchdown. Although an attempt was made to flare the airplane in a slightly right-wing-down attitude (less than 4°), the sink rate was maintained and a hard landing occurred. The right main wheels contacted the runway first, followed by the right engine cowlings; the right landing gear and wing separated as the aircraft rolled inverted.

The right wing front spar fractured at station (STA) 268 (4 inches outboard from the STA 264 bulkhead that separates the #2 and #3 fuel tanks). This was a vertical fracture that intersected the lower and upper cap. The rear spar fractured at STA 222 at the lower cap. The rear spar fracture progressed diagonally upwards and inward to the upper cap at STA 185.

Preliminary calculations conducted by the Safety Board indicate that the airplane's rate of descent at impact was 18 to 20 fps. This accident is still under investigation by the Hong Kong Civil Aviation Department.

1.18.5 DC-10 Hard Landing Accident in Faro, Portugal

On December 21, 1992, a DC-10-30CF operated as Martinair flight 495 crashed while landing on runway 11 at Faro (Portugal) Airport. There were 340 passengers and crewmembers on board at the time of the crash. Two cabin crewmembers and 54 passengers were killed, and 104 passengers were seriously injured. The Portuguese accident investigation report, prepared by the Director-General of Civil Aviation (DGAC),⁸⁵ stated that the right MLG hit the runway in a right-wing down attitude on the left side of the runway. The right MLG collapsed inboard and the "right engine and right wing tip contacted the runway," the report stated. "The right wing suffered total rupture

⁸⁵ Director-General of Civil Aviation. 1992. *McDonnell Douglas Corporation DC-10-30F, Martinair Holland NV, Final Report on the Accident Occurring at Faro Airport—Portugal, on 21 December 1992*, Report no. 22/Accid/GD1/92. The report was translated from Portuguese into English by the Netherlands Aviation Safety Board.

between the fuselage and the right engine. The aircraft slid along the runway for about 30 meters [98 feet] and gradually moved to the right, supported by the center landing gear.”

The DGAC report added the following:

After the rupture of the right wing, fire developed and enveloped the fuselage from the right to the left. The right wing followed a trajectory next to the aircraft up to the area [where] it came to rest. The aircraft [departed] the runway at the right-hand side, with a track of about 120 degrees, in an inverted position. When leaving the runway and entering the runway edge...the aircraft rolled left and the left wing bottom side dug into the ground and disintegrated partially, and the fuselage broke into...sections. It came to rest with the rear section in a normal position and the front section on the left side with the windows and doors [contacting] the ground. The fuel flowing from the tanks caused explosions followed by fire, causing the destruction of the rear fuselage up to the rear pressure bulkhead.

The airplane came to rest about 3,609 feet from the runway threshold and about 328 feet to the right of the runway centerline. The DGAC report stated that numerous thunderstorms were reported in the vicinity of the airport and concluded that the airplane had encountered turbulence “associated with microburst and downburst phenomena”⁸⁶ on final approach at an altitude of about 750 feet radio altitude. The report stated that the approach then became unstable with a descent rate that varied from 100 fpm to 1,300 fpm. The report stated that as the airplane crossed the runway threshold, it “encountered a crosswind component of 40 knots, and a tailwind component of 10 knots.”⁸⁷ The airplane landed with a 7° crab angle to the right, a 8.79° nose-up pitch angle, a 5.62° left-wing-up roll and 1.95 g vertical acceleration, the report stated.

A postaccident metallurgical examination of the right MLG determined that “the gear parts and the associated mechanisms were, at the time of the accident, without fatigue defects or defects of any other type and had no previous fatigue damage.” The report concluded that the “rupture happened exclusively due to the impact on landing which produced the overload which induced in the components and critical zones instantaneous levels of tension which exceeded the material static limit resistance.”

The DGAC determined that the probable causes of the accident were “the high rate of descent in the final phase of the approach and the landing made on the right landing gear, which exceeded the structural limitations of the aircraft, [and] the crosswind, which exceeded the aircraft limits and which occurred in the final phase of the approach and during landing.”

In connection with its work on the Newark accident, Boeing calculated that the airplane involved in the Faro accident landed on its right MLG at a vertical speed of

⁸⁶ A downburst is a strong, concentrated downdraft that creates an outward burst of damaging winds at the surface and is usually associated with convective showers and thunderstorms. A microburst is a downburst that has a maximum horizontal extent of 2.5 miles.

⁸⁷ Winds at the time were reported from 220°, gusting to 35 knots.

17 fps, or 263 percent greater than its energy certification limit. The Boeing submission stated that "because of the difference in potential energies into the respective [right] MLG, the Newark landing, at 13.5 fps, was a more severe test of the landing gear than the Faro accident at 17 fps." The Boeing submission also stated the following regarding the accident at Faro:

[A]t a landing weight of 353,000 [pounds], lift at start of touchdown of approximately 1.1 times the aircraft weight, and descent rate at the aircraft [c.g.] of approximately 15 fps and roll rate of 6 [degrees per second], the kinetic energy, 1,259,300 ft-lbs, was decreased by potential energy (from increased lift) by approximately 106,000 ft-lbs, for a total energy of approximately 1,153,000 ft-lbs on the [right] MLG. Comparing the Faro accident energy with the DC-10-30's [right] MLG energy required for certification shows that the energy developed during the Faro accident landing was over 2 and a half times the reserve energy (ultimate) certification requirements for a single [MLG].

Figure 10 shows Boeing's calculations of the energy imparted to the right MLG in the Faro accident.

RMLG Energy - Faro DC-10-30 Accident	
• RMLG Energy During Accident:	
– Potential Energy Due to Increased Lift =	-106,000 ft.-lb.
– Kinetic Energy	= <u>1,259,300 ft. lb.</u>
– Total Energy	= <u>1,153,300 ft.-lb.</u>
• 353,000 lb. Landing Weight	
• 15 fps Sink Rate @ c.g. and 6°/sec roll rate	
• Lift = 1.1 X Weight	
• MLG Strut Stroke = 23 in.	
• MLG Tire Deflection = 13 in.	
• RMLG Energy for Certification = <u>438,700 ft.-lb.</u>	
– 436,000 lb. Landing Weight, symmetrical landing	
– 12 fps Sink Rate (FAR 25.723 Reserve Energy Condition)	
– Lift = Weight (FAR 25.473)	
• RMLG Energy During Accident Relative to Energy for Certification: $(1,153,400/438,700) \times 100 \% =$	
<u>263 %</u>	

Figure 10. Boeing calculations of right MLG energy in the Faro accident.

1.18.6 Lockheed L-1011 Hard Landing Accident in New York

On July 30, 1992, a Trans World Airlines (TWA) L-1011 experienced an aborted takeoff shortly after liftoff from John F. Kennedy International Airport, Jamaica, New York, and a subsequent hard landing.⁸⁸ The airplane came to rest, upright and on fire,

about 290 feet left of the departure end of runway 13R. There were no fatalities, but 10 of the 280 passengers on board were injured during the emergency evacuation that followed.

The Safety Board's investigation determined that immediately after the airplane lifted off the ground, the stall warning stick shaker⁸⁹ activated and the airplane began to descend back to the runway. The captain retarded the throttles and executed a landing on the remaining runway. Although the Board determined that the airplane was "performing properly, had accelerated well above V_2 ⁹⁰ and could have climbed out successfully, the airplane reached about 16 feet of altitude before descending to the runway."

The Safety Board added the following:

The airplane landed hard, and the right wing sustained a fracture of the rear inboard spar because the airplane touched down with a sink rate of about 14 [fps]. The airplane's gross weight was about 71,000 pounds over the approved maximum landing weight, and the sink rate was well over the certified design limit of 6 [fps] for the structure. The Safety Board concludes that the failure of the right wing inboard rear spar was caused by the severe overload stresses imposed at touchdown.

The FDR data revealed that the airplane was banked right wing low about 1.1° at touchdown, which occurred with the centerline of the airplane just to the left of the center crown of the runway. Therefore, the right [MLG] probably touched down before the left [MLG], and the right wing took the initial violent forces, overloading the structure. The fractures noted in the right wing were consistent with such forces. Further, the forces imposed on the right wing rear spar during rotation for takeoff were calculated to be significantly less than those occurring at touchdown. Therefore, the Safety Board concludes that the fracture of the right wing rear spar occurred upon landing.

In connection with its work on the Newark accident, Boeing calculated that the L-1011's sink rate of about 14 fps and pretouchdown vertical acceleration of 0.75 g resulted in vertical loads 216 percent greater than certification limits. Boeing's submission also noted that "the 0.25 g nose-down 'push-over' (1.0 g minus 0.75 g at start of accident touchdown) during [this] accident was only half of the 0.50 g nose-down 'push-over'...during the Newark accident."

Figure 11 shows Boeing's calculations of the energy imparted to the right MLG in the L-1011 accident.

⁸⁸ National Transportation Safety Board. 1993. *Aborted Takeoff Shortly After Liftoff, Trans World Airlines Flight 843, Lockheed L-1011, N11002, John F. Kennedy International Airport, Jamaica, New York, July 30, 1992*. Aircraft Accident Report NTSB/AAR-93/04. Washington, D.C.

⁸⁹ The stick shaker, or control column shaker, is part of the airplane's stall warning system. An aerodynamic stall occurs when airflow over the airplane's wings and tail is sufficiently disrupted to result in loss of lift and control.

⁹⁰ V_2 is takeoff safety speed.




Figure 11. Boeing calculations of right MLG energy in the TWA L-1011 accident.

1.18.7 Other Landing Accidents

The Safety Board has investigated or participated in the investigation of several accidents in which pilots mishandled the airplanes during the landing phase. For example, in 1993, an American Airlines McDonnell Douglas DC-10 was destroyed during landing at Dallas-Fort Worth International Airport, Dallas, Texas.⁹¹ The Board's investigation found that although the touchdown was uneventful, the airplane veered off the side of the runway shortly thereafter because the captain held insufficient downward pressure on the control yoke after touchdown and attempted to steer the airplane with the tiller rather than through rudder application.

The Safety Board also assisted with the international investigations of three similar landing accidents involving Boeing 767s: an Asiana Airlines 767-300 in Cheju Island, South Korea, on January 16, 1992; American Airlines flight 957 in São Paulo, Brazil, on October 27, 1992; and LOT flight 002 in Warsaw, Poland, on December 31, 1993. Each accident occurred when the pilots applied large nose-down control column deflections after MLG touchdown, which resulted in large nose-down pitch rates and high vertical velocities at the nose gear. The combination of vertical velocity and pitch rate at nose-gear contact resulted in compression loads that exceeded the design loads of the forward fuselage crown structure.

Although Boeing had published landing techniques⁹² in its flight training manual, which were furnished to Boeing 767 operators before these accidents occurred, the

⁹¹ National Transportation Safety Board. 1994. *Runway Departure Following Landing American Airlines Flight 102 McDonnell Douglas DC-10, N139AA Dallas/Fort Worth International Airport, Texas April 14, 1993*. Aircraft Accident Report NTSB/AAR-94-01. Washington, D.C.

techniques had not been implemented consistently or completely by all operators. The Safety Board also learned from discussions with Boeing representatives that the DC-10 and MD-11 had experienced similar instances of damage after being mishandled during the post-touchdown derotation maneuver. Consequently, on June 16, 1994, the Board issued Safety Recommendations A-94-118 and -119. Safety Recommendation A-94-118 asked the FAA to:

Require that all FAA-approved Boeing 757/767 Operating Manuals, and other airplane model Operating Manuals as deemed appropriate, clearly communicate derotation techniques and the potential for excessive pitch rates after touchdown if pilots use large nose-down control column deflections. Such information should be inserted in the sections of the manual that refer to normal and crosswind approach and landing, as a cautionary note. Instructions calling for positive forward control pressure after nose wheel touchdown should be replaced with a warning to smoothly fly the nose wheel to the runway by relaxing aft control column pressure and not to use full down elevator.

In an August 29, 1994, letter, the FAA stated that it had reviewed the FAA-approved Boeing 757/767 Airplane Flight Crew Training Manual and Boeing's "guidance concerning the potential for excessive pitch rates after touchdown if pilots use large nose-down control column deflections." The FAA noted that the derotation procedures specified in the Boeing 757/767 Airplane Flight Crew Training Manual were consistent with those outlined in Safety Recommendation A-94-118 and were "similar to the guidance contained in McDonnell Douglas pilot operating manuals." The FAA also stated that it reviewed other actions by Boeing to "inform Boeing 757/767 pilots of proper derotation procedures," which included specification of proper landing techniques in the 767 Flight Crew Training Manual, issuance of a technical bulletin on proper flare and landing techniques, onsite reviews of proper derotation techniques with all Boeing customers, and review of the issues at a 1993 flight operations symposium. The FAA stated that it had determined that these actions were "effective and...[were] more extensive in addressing this issue than a cautionary note in the FAA-approved Boeing 757/767 Airplane Flight Manual." The Safety Board agreed and classified Safety Recommendation A-94-118 "Closed—Acceptable Alternate Action" on August 1, 1995.

Safety Recommendation A-94-119 asked the FAA to:

Modify initial and recurrent Boeing 757/767 pilot training programs, and other airplane model pilot training programs as deemed appropriate, to include discussion of derotation accidents.

In response to Safety Recommendation A-94-119, the FAA issued Flight Standards Information Bulletin for Air Transport (FSAT) 95-06, "Derotation Accidents During Landings of B-757/767, DC-10, and MD-11 Aircraft," to all FAA Flight Standards personnel. The FSAT, which was effective February 12, 1995, and expired February 29,

⁹² Step five in the published Boeing guidance states that after MLG touchdown, speedbrake deployment, and reverse thrust initiation, the pilot should "smoothly fly the nose wheel onto the runway by relaxing aft control column pressure [and should] not use full down elevator."

1996, reiterated the main points of the safety recommendation, including the Boeing-recommended derotation technique. Consequently, the Board classified Safety Recommendation A-94-119 "Closed—Acceptable Action."

1.18.8 Safety Board Recommendations Relating to DC-10 and MD-11 Spoiler Pitch-up Incidents

On August 2, 1992, a McDonnell Douglas MD-11, operated by Delta Air Lines, pitched nose-up after landing at Los Angeles International Airport and contacted the runway, damaging the airplane's aft fuselage. The airplane was later ferried to Atlanta for repairs, where it again pitched nose up after landing. In that incident, the pitching moment was corrected before the tail contacted the runway. As a result of its investigation of this incident, the Safety Board issued Safety Recommendation A-93-57, on June 3, 1993, which asked the FAA to:

Require McDonnell Douglas and U.S. operators of the DC-10 and MD-11 airplanes to revise their DC-10 and MD-11 [FCOM]s (or equivalent documents) to include an accurate and complete description of the ground spoiler-induced nose pitch-up tendencies of the airplanes and the specific pilot control techniques that may be required to counter those tendencies during landing.

The FAA agreed with the recommendation, and the manufacturer issued temporary revisions to its MD-11 and DC-10 FCOMs on June 25, 1993, and July 1, 1993, respectively, that described the airplanes' ground spoiler-induced nose pitch-up tendencies and specific pilot control techniques required to counter those tendencies.⁹³ The revisions were transmitted to all MD-11 and DC-10 domestic operators and foreign airworthiness authorities. The FAA also issued Flight Standards Information Bulletin 93-36, which directed FAA principal operation inspectors (POI) to ensure that the revised material was incorporated into their assigned operators' FCOMs. In November 1994, as a result of the FAA's and manufacturer's actions, the Safety Board classified Safety Recommendation A-93-57 "Closed—Acceptable Action."

As a result of the same Delta Airlines incident, the Safety Board also issued Safety Recommendation A-93-59, which asked the FAA to:

Require McDonnell Douglas to study possible revisions to the DC-10 and MD-11 ground spoiler deployment logic to reduce the possibility of landing tailstrikes. The revisions should include, but not be limited to, the following general concepts: if the aircraft touches down at a pitch angle close to the tailstrike pitch angle, initial partial ground spoiler deployment should not occur until the pitch angle falls below a specified angle; and nose gear strut compression status should be maintained long enough to ensure that the nose wheel is firmly on the ground, and has not just momentarily touched the ground, before full deployment of the ground spoilers occurs.

⁹³ The temporary revisions were incorporated into the standard revision cycle for the FCOMs of both aircraft. The applicable standard revisions for the MD-11 and DC-10 FCOMs were dated December 1, 1993, and October 15, 1993, respectively.

In a May 15, 1995, letter, the FAA responded that the “majority of DC-10 tailstrikes occurred early in the service life [of the DC-10 model] when ground spoilers were commanded to the full-up position by main gear spin-up” and that “some of the strikes were the result of poor pilot techniques and may have occurred regardless of the ground spoiler-induced pitch-up tendency.” The FAA added that “McDonnell Douglas in 1975 began offering a kit change notice that changed the logic to have the spoilers deploy only partially to the in-flight spoiler position on main gear wheel spin-up; and then to the full ground spoiler position following nose strut compression. This two-stage logic was incorporated into the basic design of the MD-11 as standard equipment.” The FAA concluded that “as a result of these changes and increased flight crew awareness, the potential for tailstrikes ha[d] been considerably reduced” and that no further action was warranted.

On July 17, 1995, the Safety Board disagreed with the FAA's May 15 response, classifying the recommendation “Open—Unacceptable Response.” In its reply to the FAA, the Board noted that tailstrikes had continued to occur after the 1975 modification to the DC-10 and its implementation on the MD-11. The Board also noted that its review of the manufacturer's incident records showed that there had been five landing tailstrike incidents involving DC-10 and MD-11 airplanes since the August 2, 1992, incident that may have been the result of ground spoiler deployment logic. The Board asked the FAA to explain how its review concluded that ground spoiler deployment logic was not a contributing factor in those incidents. The Board reiterated its belief that “initial spoiler deployment should be inhibited until the nose of the airplane is lowered sufficiently that a tailstrike is unlikely.”

In an October 10, 1995, response to the Safety Board, the FAA stated that its review indicated that the referenced tailstrike incidents “were not related solely to early spoiler deployments.” The FAA stated that it received reports from manufacturers daily and that it meets with manufacturers to investigate problems if a significant event or trend is identified, such as those referenced by the Board. The FAA stated that it had concluded that “the incidents were not caused solely by ground spoiler deployment.” The FAA reiterated its conclusion that a revision to the ground spoiler deployment logic was not warranted, adding that such a revision “would adversely affect safety by increasing the airplane's landing roll distance.”

In a December 20, 1995, response to the FAA, the Safety Board noted that in three of the five incidents reviewed by the FAA, the spoiler-induced pitching moment likely contributed to the tail drag occurrences. The Board stated that the “spoiler deployment logic change could be implemented without increasing landing distances” because “high pitch attitudes after touchdown are associated with low landing speeds, which may result in shorter landing distances.” The Board added that “timely lowering of the pitch attitude, which is retarded by spoiler deployment, is probably more important for safe stopping than spoiler deployment at high pitch attitudes.” The Board further added that it had been informed by Boeing that “landing distance penalties did not occur when it changed the spoiler logic on the Boeing 757” after the company had several early Boeing 757 ground spoiler logic-related tail drag incidents. The Board noted that Boeing determined that

“delaying deployment of outboard spoilers” reduced the nose-up pitching moment. Based on the FAA’s decision not to take further action, Safety Recommendation A-93-59 was classified “Closed—Unacceptable Action.”

1.18.9 MD-11 Flight Control Computer Software Changes

In December 1995, the MD-11 FCC-907 software certification introduced a pitch rate damper (PRD) control law to the previously certified LSAS. The -907 PRD utilized inertial reference unit (IRU) pitch rate feedback in the LSAS elevator control laws to counter pitch rate tendencies, thereby increasing the apparent static stability of the aircraft. According to Boeing, this change was implemented as a product improvement to help minimize MD-11 high-altitude upsets.⁹⁴ Because it was decided during FCC-907 development not to affect the MD-11’s low-altitude, low-speed handling qualities, the PRD was designed to phase-in and phase-out on a pressure altitude schedule (15,000 to 20,000 feet).

Boeing has developed an MD-11 FCC software upgrade—FCC-908—that was FAA-certified on May 23, 2000. The upgrade primarily comprises modifications to three subfunctions—PRD, pitch attitude protection (PAP), and positive nose lowering (PNL)—of the LSAS. Boeing refers to these LSAS subfunctions as a low altitude stability enhancement (LASE) package.

Boeing indicates that the LASE package implementation has two design goals. The first is to employ the existing LSAS to provide deterrence against tailstrikes; Boeing indicates this goal was established in response to the Safety Board’s Safety Recommendation A-93-59. The second goal is to augment the natural aircraft longitudinal handling qualities, via LSAS, in a manner approximating the handling qualities of the existing DC-10. Both objectives are intended to facilitate a common type rating between the MD-11 and the MD-10.⁹⁵

The MD-11 FCC-908 software upgrade will activate the PRD control loop below 15,000-foot pressure altitudes at a reduced gain. Whereas the -907 PRD feature was inactive at low altitudes, the -908 PRD will remain active at 30 percent strength from approximately 17,500 feet down to takeoff/landing field elevation. Because the PRD increases the apparent static stability, longitudinal handling qualities of the MD-11 will be more like those of the DC-10.

⁹⁴ The Safety Board investigated some of these upsets, including the April 6, 1993, China Eastern MD-11 accident at Shemya, Alaska, and the December 7, 1992, China Air accident at Anchorage, Alaska.

⁹⁵ According to information provided by Boeing, the MD-10 is a modification of the DC-10 model that was customized for FedEx. Like the MD-11, the MD-10 design incorporates a two-person flight crew complement with associated changes to flight deck displays and system controls. The basic fuselage, wing, control surface, flight control, and engine designs were not changed from those of the DC-10. On May 9, 2000, the FAA granted Boeing an amended type certificate for the MD-10 freighter. The FAA also approved a common pilot type rating and landing proficiency credit for the MD-10 and -11, provided that the MD-11 incorporates FCC-908 to render its handling similar to that of the DC-10/MD-10.

The PAP subfunction is being added to LSAS to mimic the tailstrike protection that the MD-11 autopilot already provides for coupled landing and go-around operations. The PAP subfunction is armed whenever an aircraft's radio altimeter registers below 100 feet agl. The PAP uses radio altitude in conjunction with IRU pitch angle and pitch attitude rate to provide nose-down elevator commands as a pilot begins to approach or exceed the prescribed PAP pitch limit (30° pitch at 41 feet agl and 9.5° pitch at 0 feet agl). This enhancement will slightly increase the control column force required to pitch the aircraft beyond the prescribed limits, but the pilot otherwise retains full pitch-control authority. As with all LSAS functions, the elevator command authority is mechanically limited to 5° of deflection within the elevator electro-hydraulic actuator.

Boeing indicates that the PNL subfunction is intended to address both design goals for the LASE package. The PNL subfunction provides a two-stage, nose-down elevator command as the main wheels spinup for landing, which counters the nose-up tendency typically experienced when landing ground spoilers are deployed. The PNL subfunction is armed when aircraft radio altitude registers below 100 feet agl. The FCC signals, which are used to command the auto ground spoilers to deploy, will cause the PNL subfunction to command the first stage of the nose-down elevator of 3° . When the ground spoilers are detected to be in excess of 10° of displacement, the second stage of the PNL increases the nose-down command to 4° . Because the closed-loop PRD acts in conjunction with the PNL, the nose derotation characteristics are essentially independent of the aircraft c.g. The PNL commands are removed from the LSAS outputs at the same time that the flight mode annunciator returns to the TAKEOFF mode (that is, after the nose wheel has been on the ground for at least 20 seconds).

2. Analysis

2.1 General

The two flight crewmembers were properly certificated and qualified in accordance with applicable Federal regulations and company requirements. Crew duty time, flight time, rest time, and off-duty activity patterns did not indicate that medical, behavioral, or physiological factors affected the flight crew's performance on the day of the accident.

The airplane was properly certificated, equipped, and maintained in accordance with Federal regulations and approved procedures, and the airplane's departure from ANC with the No. 1 engine thrust reverser inoperative was in accordance with approved minimum equipment list procedures (the failure of the left landing light is discussed in section 2.2.2.8). Cargo was loaded in accordance with FedEx's FAA-approved weight and balance requirements.

Although the airplane had experienced damage to its forward and rear fuselage sections during two prior hard landings in 1994, the damage was assessed and repaired in accordance with approved regulations and procedures. Detailed inspections performed after each of the two prior hard landings and during subsequent periodic maintenance did not reveal any evidence of damage to the MLG, gear attach points, or wing structure. Safety Board metallurgical staff also examined the fracture surfaces of the right MLG and right wing structure at the scene of the accident before its removal and found no evidence of preexisting structural damage or fatigue cracking. Further, the energy transmitted into the right MLG during the Newark accident landing was more than Boeing estimated to have been required to break the wing of a new, undamaged MD-11 (see section 2.5.1). Thus, the Safety Board concludes that there was no preexisting damage or degradation to the airplane structure, systems, or components that contributed to this accident.

The response and actions by ARFF and area firefighting personnel were timely and adequate, despite a lack of timely information about the nature and quantity of hazardous materials on board.

Clear night visual meteorological conditions with light winds prevailed at the time of the accident; weather was not a factor in the accident.

This analysis examines airplane and flight crew performance and design and certification requirements for the performance of transport-category airplanes during the landing phase. The analysis concludes with an examination of problems encountered during the emergency response relating to the timely dissemination of hazardous materials cargo information.

2.2 Accident Scenario

2.2.1 Airplane Performance During the Approach and Landing

During the approach, the airplane was configured for landing, with flaps set at 50°. The captain disconnected the autopilot as the airplane descended through 1,200 feet, and the autothrottles remained engaged. According to flight crew statements and FDR data, the airplane maintained the approach speed of about 158 knots (consistent with the target approach speed specified by FedEx, $V_{ref}+5$ knots or 157 knots), at a stable 800 fpm descent rate, and on the ILS localizer and glideslope for runway 22R until the landing flare. The average pitch attitude of 3° ANU was consistent with MD-11 flight manual data for descending on the ILS glideslope's 3° flightpath angle, given the airplane's weight, c.g., and flaps-50 configuration. The captain and the first officer also stated that the approach was routine until just before touchdown. Thus, on the basis of flight crew statements and airplane performance data, the Safety Board concludes that the airplane's approach before the landing flare was stabilized.

FDR data indicated that control inputs consistent with the start of flare occurred at about 37 feet radio altitude. Engine thrust was also decreasing about this time.⁹⁶ About 1.5 seconds after the start of the flare and 2 seconds before the first of two touchdowns, pitch attitude peaked at 5° nose up. The radio altitude was 17 feet. This portion of the flare maneuver was consistent with FedEx MD-11 flight manual guidance, which called for a "smooth 2.5 degree flare" to be initiated between 30 and 40 feet radio altitude. Thus, the Safety Board concludes that the captain's execution of the beginning of the flare maneuver was normal and not a factor in the accident.

As pitch attitude peaked about 2 seconds before the first touchdown, the elevator started deflecting from about 12° nose up to near 0°, and the airplane's pitch attitude began decreasing slightly in response to the nose-down elevator input. Further, about 1 second before ground contact, elevator deflection reversed to a nose-up elevator deflection of 26° (from about neutral elevator to about 70 percent of maximum nose-up elevator), and TRAs increased from about 40° to 70° (from near flight idle to near takeoff thrust). A small right-wing-down aileron input (4° to 5°) followed. The nose-up, throttle-up, and right-wing-down control inputs were initiated as the airplane was descending through 7 feet radio altitude. Pitch attitude and vertical acceleration had just begun to respond when the airplane contacted the ground in the first of two touchdowns. Vertical speed at the first touchdown was about 7.6 fps,⁹⁷ and vertical acceleration peaked at 1.67 g. The nose-up elevator and throttle inputs also peaked about the time of the first touchdown.

⁹⁶ With the MD-11 autothrottle system engaged and flaps extended to greater than 31.5°, the throttles are automatically driven to the idle stop when the radio altitude decreases through 50 feet.

⁹⁷ This value is the vertical speed at the right MLG and includes 6.6 fps vertical speed at the c.g. plus 1.0 fps vertical speed at the right MLG because of nose-up pitch rate and right-wing-down roll rate.

Within 1/2 second after the first touchdown, the captain initiated a rapid nose-down elevator input. The total elevator travel was about 40° (changing from about 70 percent of maximum nose-up elevator to about 67 percent of maximum nose-down elevator in less than 1 second). Despite the initiation of the large and rapid nose-down elevator input, the airplane began to lift off the runway as a result of landing gear strut and tire compression loads and the still-increasing pitch attitude, thrust, and airspeed. In addition, wing lift was not degraded upon touchdown because the spoilers did not deploy.

After the initial touchdown, the airplane was airborne for about 2 seconds.⁹⁸ During the first second, while airborne, the elevator remained about 67 percent nose down. In the next second, a large and rapid nose-up elevator input occurred (from 67 percent nose-down to 60 percent nose up), accompanied by nose left rudder and right-wing-down aileron inputs.⁹⁹

About 3/4 second before the second touchdown, as the airplane was peaking at a height of 5 feet agl, lift had decreased to about 0.6 g. The pitch attitude was about 2° nose-up and decreasing rapidly. The elevator was about 15° nose-down, although it was moving rapidly toward a nose-up position. Given the nose-down elevator position at that point in the bounce, there were probably no additional crew actions that could have been taken to prevent a hard impact with the runway.

The airplane touched down for the second time as vertical acceleration was decreasing through 0.5 g. The second touchdown occurred at a roll angle of 9.5° right wing down, a roll rate of approximately 7° per second right wing down, and a pitch attitude of minus 0.7°. Peak vertical speed at the right MLG was approximately 13.5 fps. The right wing failed at impact (see section 2.5.1 for a discussion of this failure).

The captain's actions during the 5 seconds preceding the second touchdown established the conditions that led to the right wing failure. When the captain rapidly moved the elevators to near neutral instead of maintaining nose-up elevator and continuing the flare (2 seconds before first touchdown), he destabilized the flare and established a greater sink rate. The large nose-up elevator and thrust inputs that the captain made with only 1 second remaining before touchdown were his reaction to the sink rate and an attempt to prevent a hard landing. From that moment on, evidence indicates that all of the captain's control inputs were too late and too large to achieve the desired effect. He made a large nose-down elevator input, consistent with an effort to keep the airplane on the runway and ensure an early touchdown of the nose gear with maximum available stopping distance. Although he began these nose-down inputs at about the time of the first touchdown, the airplane had bounced back into the air by the time he had pushed almost all the way forward on the control column. This large nose-down input, in turn, established a very high sink rate and low g load at the time of the second touchdown. The

⁹⁸ The time interval between the first touchdown and the second was about 3 seconds. During those 3 seconds, the airplane was on the ground with the struts stroking and tires compressing for about 1 second and was airborne for about 2 seconds.

⁹⁹ The Safety Board could not determine why the captain commanded right-wing-down aileron and left rudder deflection before the second touchdown.

captain's final, large nose-up inputs were made too late to soften the impact. The airplane touched down with enough energy and at a sufficiently high roll angle to bottom the right MLG strut and break the right wing.

All available data indicate that the airplane's aerodynamic performance and flight control functionality were normal until after the second touchdown. Thus, the Safety Board concludes that the accident airplane performed normally in response to the captain's flight control inputs until after the second touchdown.

The captain's large and rapid elevator control reversals, which resulted in an increasing divergence above and below the target pitch attitude, were consistent with a "classic" pilot-induced oscillation (PIO). Essentially, the captain made each increasingly larger elevator input in an attempt to compensate for the input he had made in the opposite direction about 1 second earlier. PIO in the pitch axis can occur when pilots make large, rapid control inputs in an attempt to quickly achieve desired pitch attitude changes. The airplane reacts to each large pitch control input, but by the time the pilot recognizes this and removes the input, it is too late to avoid an overshoot of the pilot's pitch target. This, in turn, signals the pilot to reverse and enlarge the control input, and a PIO with increasing divergence may result.

Additional key elements in the onset of PIO are derived from the interaction between the pilot and the flight environment. Researchers have described the following:

"...many of the reported [PIO] events have taken place during air-to-air refueling operations or approaches and landings, especially if the pilot is concerned about low fuel, adverse weather, emergencies, or other circumstances. Under these conditions, the pilot's involvement in closed-loop control is intense, and rapid response and precise performance...are necessary. Even so, these operations usually occur routinely without [PIO] problems. [PIO] events do not occur unless there is a transient triggering event that interrupts the already highly demanding...operations or requires an even higher level of precision. Typical triggers include shifts in the dynamics of the effective aircraft (the combination of the aircraft and the [flight control system]) caused by increases in the amplitude of pilot commands, [flight control system] changes, minor mechanical malfunctions, or severe atmospheric disturbances. Other triggers can stem from mismatches between pilot's expectations and reality.¹⁰⁰

The environmental cues and concerns that may have served as triggering events in this accident, motivating or influencing the captain's control inputs and decisions, are further analyzed in the following section.

¹⁰⁰ National Research Council. 1997. *Aviation Safety and Pilot Control: Understanding and Preventing Unfavorable Pilot-Vehicle Interactions*, p. 3.

2.2.2 Flight Crew Factors During the Approach and Landing

During the approach briefing, the first officer and the captain discussed the stopping distance available on runway 22R for the airplane's weight and landing configuration. During that discussion, they expressed concerns about the approximate landing distance and the length of the runway, which they had derived from the APLC (see section 2.2.2.7 for a discussion of the flight crew's misinterpretation of the data presented in the APLC). Additionally, during the approach, the flight crew indicated that they were aware of the inoperative No. 1 engine thrust reverser, which would have resulted in a slight reduction in deceleration capability after landing.¹⁰¹ The flight crew was also aware of three recent events recorded in the airplane's maintenance log in which the airplane's autobrakes had failed to arm at takeoff or failed to work at landing. Although maintenance personnel had checked the system after each reported failure and determined it was functioning properly, the captain told Safety Board investigators that he discussed the reliability of the autobrake system with the first officer before takeoff from ANC. The captain told investigators that the autobrakes remained armed during the departure from ANC. However, he kept the autobrake problem in mind when planning for the landing at EWR, adding that he planned to land the airplane at the start of the runway and wanted to ensure that the airplane would not float during the landing flare.

Thus, on the basis of the flight crew's comments during the approach about the relatively short runway length, the inoperative thrust reverser, the questionable reliability of the autobrake system, and the perceived need to land at the beginning of the runway, the Safety Board concludes that the captain was concerned about the airplane's touchdown location on runway 22R and intended to take measures during the landing to achieve an early touchdown and minimize the length of the rollout on the runway after touchdown.

2.2.2.1 Nose-Down Elevator Input at 0132:16 (2 seconds before first touchdown)

The Safety Board examined the captain's 12° nose-down elevator input at 17 feet radio altitude to determine if it was consistent with FedEx guidance for landing the MD-11. The Board's review of FedEx's MD-11 landing guidance found only one technique that promotes the use of nose-down elevator between the initiation of flare and touchdown. Specifically, the FedEx MD-11 "advanced technique" for landing recommends that "elevator back pressure...be relaxed" about 10 feet before touchdown (to achieve a 1° decrease in pitch attitude). However, the captain's nose-down elevator input, which moved the elevator from 12° nose-up to about the neutral position, was very rapid and much greater than is required for the maneuver. Further, the captain began his nose-down input about 1 second before the airplane reached 10 feet radio altitude, the aural annunciation of which should have served as the cue for such a pitch reduction if it

¹⁰¹ Although the flight crew may have been concerned about the reduction in deceleration capability, the inoperative thrust reverser did not increase the runway length requirement for the accident landing above that shown in the APLC because the deceleration effects of the thrust reversers are not used in calculating the distances required for landing.

had been related to the FedEx “advanced” landing technique. Thus, the Safety Board concludes that the captain’s nose-down elevator input beginning at 17 feet radio altitude was not consistent with FedEx guidance for landing the MD-11. Further, the Safety Board concludes that the captain’s nose-down elevator input at 17 feet radio altitude (2 seconds before the first touchdown) was consistent with an attempt to control the point of touchdown given his concerns about the runway length.

2.2.2.2 Nose-up Elevator Input at 0132:17 (1 second before first touchdown)

The captain and the first officer told Safety Board investigators that they felt the airplane’s sink rate increase shortly before the airplane touched down. They stated that these were “seat of the pants” feelings and were not based on observed indications on cockpit instruments. FDR data indicated that after the captain made the nose-down elevator input at 17 feet radio altitude, a small increase in sink rate and decrease in vertical acceleration occurred. The decreased vertical acceleration and increased nose-down pitch rate could have led to sensations of sink consistent with the pilots’ descriptions.

With just more than 1 second remaining before touchdown, the captain had the following options: accept the sink rate and subsequent hard landing, attempt to salvage the landing with last-second thrust and pitch adjustments, or execute a go-around. FDR data and postaccident interviews show that the captain chose to try to salvage the landing with last-second thrust and pitch adjustments. Thus, the Safety Board concludes that the captain made a nearly full nose-up elevator input and a large throttle increase to compensate for the increased sink rate caused by his previous nose-down input.

The FedEx MD-11 flight manual recommends that a “constant pitch attitude be maintained from 10 feet radio altitude until touchdown.” However, this guidance presupposes a stabilized approach and flare leading up to 10 feet radio altitude. In contrast, because the captain had destabilized the flare 1 second earlier, he perceived a need to arrest the resulting sink rate with additional thrust and nose-up pitch.

FedEx’s high sink rate and bounce recovery training recommends establishing a 7.5° pitch attitude and “arresting the sink rate with thrust” as a prelude to either landing with a high sink rate, re-landing the airplane after a bounce, or executing a low-level go-around. However, FedEx’s MD-11 tailstrike awareness training also cautioned that “quickly adding up elevator” near the ground should be avoided because it can result in increased nose-up pitch rate at touchdown, increased downward vertical speed at the MLG, a hard landing, and tailstrike. To gain a better understanding of this training and its relevance to the captain’s actions, Safety Board investigators participated in FedEx classroom and simulator training for high sink rate and bounce recovery, as well as for tailstrike avoidance. This experience demonstrated to investigators that the timing and large magnitude of the captain’s nose-up elevator input just before the first touchdown were inconsistent with FedEx’s MD-11 high sink rate recovery and tailstrike awareness training.

2.2.2.3 Nose-Down Elevator Input Shortly After the First Touchdown

The captain's large, nose-down elevator input began within 1/2 second of the first touchdown. Based on the sequence and timing of the events, this nose-down elevator input was the captain's response to the airplane's rapid nose-up pitching motion, which began in the second before touchdown as a result of the captain's immediately preceding large nose-up elevator input, and/or his attempt to rapidly land the nosewheel and begin braking immediately after touchdown. After the airplane touched down hard and bounced, the captain continued his nose-down input while the airplane continued to pitch up.

A large nose-up pitch rate and high pitch attitude at touchdown would have introduced several factors that may have contributed to the captain's subsequent large nose-down elevator input. First, MD-11 pilots are taught in training that nose-up pitch rate and high pitch attitude at touchdown are factors that lead to tailstrike. This consideration may have caused the captain to believe he should apply additional nose-down elevator to the amount that he normally applies after touchdown to counter the MD-11's characteristic nose-up pitching moment following ground spoiler deployment.¹⁰² Second, as demonstrated by his statements on the CVR and during postaccident interviews, the captain would have continued to be concerned about the available runway length; the rapidly increasing pitch attitude just before and during the first touchdown would have increased the probability of a floating flare, which, in turn, would have decreased the amount of runway available to bring the airplane to a stop. Therefore, the Safety Board concludes that the captain's full nose-down elevator control input at the time of the first touchdown was consistent with his continued concerns to avoid a long landing and his desire to avoid a tailstrike.

2.2.2.4 Summary of the Captain's Elevator Control Inputs

Considering the captain's three significant elevator control inputs in sequence, it is apparent that after the first destabilization of the landing flare (from the captain's nose-down input at 17 feet agl), each of the succeeding nose-up/nose-down elevator inputs resulted from the captain's attempt to correct for the immediately preceding control input. His perception of a short runway and the need to constrain the pitch attitude within a very limited range (to avoid a tailstrike) would have motivated the captain to rapidly return the airplane to a stable attitude. He attempted to accomplish this goal with the quick application of large elevator inputs; however, this succession of elevator inputs and pitch oscillations rendered the landing attempt increasingly unstable.

Throughout the sequence of increasingly extreme nose-down and nose-up elevator inputs, which were consistent with a "classic" PIO (as described in section 2.2.1), the captain continued to attempt to salvage the landing; however, a go-around executed by the captain at any time through the touchdown and bounce would have prevented the accident.

¹⁰² MD-11 pilots are taught and the MD-11 FCOM advises that ground spoiler deployment at touchdown creates a nose-up pitching moment that must be counteracted with pilot-induced nose-down elevator inputs. This technique is referred to in the MD-11 FCOM and operator training as "flying the nose to the runway."

Therefore, the Safety Board concludes that the captain's overcontrol of the elevator during the landing and his failure to execute a go-around from a destabilized flare were causal to the accident.

Further, the Safety Board's examination of the training that FedEx provided its pilots in landing the MD-11 showed that its training was consistent with and, in some respects, exceeded that provided by many other major airlines. On the basis of comparing the captain's control inputs with FedEx's procedures and training for landing the MD-11, the Safety Board concludes that the captain's control inputs during the flare and bounce were not consistent with landing procedures and techniques outlined in the FedEx MD-11 pilot training procedures, McDonnell Douglas FCOM, or with FedEx's MD-11 tailstrike awareness and high sink rate and bounce recovery training.

2.2.2.5 The Captain's Training History

The Safety Board attempted to determine if a factor in the captain's training history could explain his actions in attempting to control the airplane during the landing and thereafter. The Board notes that the captain received an unsatisfactory evaluation on an upgrade proficiency checkride on October 29, 1996. However, the Board obtained no other evidence that could reflect negatively on the captain's skills. Other than the October 1996 checkride, there was no history of unsatisfactory performance or of disciplinary action in his career at FedEx. There was also no record of accident, incident, or enforcement action in his FAA records. In addition, in the 10 months after the failed checkride, the captain satisfactorily completed a proficiency check and two line checks (the last line check was 20 days before the accident). Thus, the Safety Board concludes that the captain had no previously documented skill deficiencies that contributed to this accident.

2.2.2.6 Enhanced Pilot Training

The captain's failure to properly respond to a destabilized flare and his excessive overcontrol of the airplane, as well as the accumulated evidence from previous air transport landing accidents (see sections 1.18.4 through 1.18.7), indicate that action may be warranted to improve the quality of air carrier training and guidance to pilots in performing safe landings. The circumstances of this and other accidents suggest that, although accidents before or shortly after touchdown are rare, the risk of a future catastrophic accident could be reduced if air carrier pilot training programs devote additional attention to safety issues related to landings. It is particularly important to instill in pilots the orientation to perform a go-around in the event of an unstabilized approach or destabilized landing flare.

Shortly after the Safety Board conducted a special investigation¹⁰³ of rejected takeoff accidents in 1990, a joint government-industry task force was formed to study the issue and develop a flight crew training aid. This training aid has led to a reduction in the

¹⁰³ National Transportation Safety Board. 1990. *Runway Overruns Following High Speed Rejected Takeoffs*. Special Investigation Report NTSB/SIR-90-02. Washington, D.C.

incidence of rejected takeoff accidents and incidents.¹⁰⁴ The Board notes that other government-industry efforts have produced valuable training tools to avoid and recover from inadvertent encounters with wake vortices, windshear, controlled flight into terrain events, and aircraft upsets.

The Safety Board's review of accidents involving pilots' control handling in the landing phase of flight, including this accident, indicates that a similar training tool development effort should be made for landings. This tool should devote specific attention to proper high sink rate recovery techniques during the landing flare, risks associated with PIOs during the landing, and the hazards associated with overcontrol and premature derotation during a bounced landing.

In 1995, responding to a safety recommendation issued by the Safety Board as a result of its investigation of three Boeing 767 landing accidents as well as incidents involving DC-10s and MD-11s, the FAA issued FSAT 95-06. This document required FAA POIs to ensure that pilot training programs for the Boeing 757/767, DC-10, and MD-11 include a discussion about derotation accidents. Unfortunately, FSAT 95-06 expired in 1996.

Further, in its submission to the Safety Board on the Newark accident, Boeing advocated expanding traditional approach go-around guidance to instruct that missed approaches be made if the airplane is not stabilized by 500 feet or if approaches involve "large pitch deviations." The Board concurs with this suggestion and notes that air carrier pilots' adoption and use of a proactive go-around philosophy would be a desirable goal for a training tool development effort on this issue.

Following this accident, FedEx added instructional material and guidance on landing gear and wing structural certification to its tailstrike awareness training program. This guidance detailed the effects of vertical acceleration on the MLG and wings and explained the effects of roll and pitch rate on total sink rate. The FedEx training information describes in detail the aerodynamic effects of large nose-down elevator inputs that result in reduced-g touchdowns, which increase the loads that must be absorbed by the MLG.

The Safety Board notes that one of the new FedEx training modules closely describes the acceleration, pitch, and roll factors found in the Newark accident scenario. However, based on discussions with pilots who have flown with several air carriers, the Board is concerned that this information may be lacking in other operators' training programs and that this lack of landing guidance could contribute to similar landing accidents. Thus, based on its review of air carrier landing accidents, the Safety Board concludes that air carrier pilots' performance would be improved by additional guidance and training in landing techniques.

¹⁰⁴ A review of the Safety Board's database of U.S. accidents revealed no fatal overrun events since 1990.

Therefore, the Safety Board believes that the FAA should convene a joint government-industry task force composed, at a minimum, of representatives of manufacturers, operators, pilot labor organizations, and the FAA to develop, within 1 year, a pilot training tool to do the following:

- a. Include information about factors that can contribute to structural failures involving the landing gear, wings, and fuselage, such as design sink rate limits; roll angle limits; control inputs' roll rate; pitch rate; single-gear landings; the effect of decreased lift; and structural loading consequences of bottoming landing gear struts and tires;
- b. Provide a syllabus for simulator training on the execution of stabilized approaches to the landing flare, the identification of unstabilized landing flares, and recovery from these situations, including proper high sink rate recovery techniques during flare to landing, techniques for avoiding and recovering from overcontrol in pitch before touchdown, and techniques for avoiding overcontrol and premature derotation during a bounced landing; and
- c. Promote an orientation toward a proactive go-around.

2.2.2.7 Landing Distance Calculation Errors

During its investigation, the Safety Board determined that the flight crew misinterpreted the APLC stopping distance data for MED autobrakes by incorrectly comparing APLC runway data with the landing distance provided on the approach plate for runway 22R. Although there was sufficient stopping distance for a MED autobrake setting, the misinterpretation of the APLC data,¹⁰⁵ among other factors, led the captain to believe that stopping distance would be an issue in the landing. Thus, the Safety Board concludes that the flight crew's calculation error in determining the runway length required for landing influenced the captain's subsequent actions during final approach and landing by creating a sense of urgency to touch down early and initiate MAX braking immediately.

The Safety Board is concerned that two pilots with significant APLC experience at FedEx failed to properly interpret the calculated landing distances and that other experienced flight crews may also be deficient in their operational knowledge of how APLC systems function. The Board notes that following the accident, FedEx expanded the APLC pilot training presentation for all initial and upgrade training and also added it to recurrent flight crew training programs. The Board has learned that several operators have either adopted systems similar to FedEx's APLC system or are considering doing so and that other electronic performance calculators are in use at other operators. Thus, the Safety Board concludes that some flight crewmembers may lack proficiency in the operation of APLCs, or similar airplane performance computing devices, and that confusion about calculated landing distances may result in potentially hazardous miscalculations of available runway distances after touchdown. Therefore, the Safety Board believes that the

¹⁰⁵ Instead of the miscalculated 780-foot margin result that influenced his decision to set MAX autobrakes, there was actually a 1,680-foot margin.

FAA should require POIs assigned to Part 121 carriers that use auxiliary performance computers to review and ensure the adequacy of training and procedures regarding the use of this equipment and the interpretation of the data generated, including landing distance data.

2.2.2.8 Left Landing Light

The Safety Board considered whether the absence of the left landing light affected the captain's ability to land the airplane. The ability to land an airplane from the initiation of flare to touchdown requires that the pilot rapidly detect and assess the airplane's attitude, altitude, sink rate, velocity, and alignment with the runway. Cues used to accomplish this task include the relative size of objects, relative movement between objects, and variations in angles of convergence around the runway environment. Texture cues in the environment help pilots estimate altitude and velocity. Because of the absence of texture cues at night, estimating height may be difficult. Landing lights can increase the texture or detail available in the runway environment by illuminating the runway surface and tire marks on the runway and casting shadows in the periphery.

Runway 22R's edge lighting would have provided cues for altitude and sink rate from which the captain could extract the angular information needed to support the landing. In addition, the edge lighting system would have provided a fixed ground reference from which the captain could have gauged his drift and alignment with the runway. Runway 22R's three-bar VASI system would have helped the captain maintain a stabilized approach as he transitioned from the electronic glideslope to the visual glidepath. The weather during the landing was clear, and there were no obstructions to visibility that would have degraded the appearance of these lighting systems.

Although the left landing light was inoperative, the airplane had other external lights available during the landing, including the right landing light, turnoff lights,¹⁰⁶ and taxi and landing lights on the nose gear. Therefore, the area normally covered by the left landing light would have been darker than normal but not without illumination because of the overlapping areas of illumination from the other lights. Moreover, the captain was aware well before landing that the landing light was inoperative and told Safety Board investigators that the inoperative left landing light did not significantly affect his ability to detect sink rate and land the airplane. The captain also told investigators that the view out the windscreen was normal and that he had landed before with a landing light inoperative. Thus, the Safety Board concludes that the inoperative left landing light did not impede the captain's ability to land the airplane.

¹⁰⁶ Turnoff lights are located at the wing root and are turned on below 18,000 feet according to FedEx procedures.

2.3 MD-11 Handling Characteristics and Flight Control System Design

2.3.1 MD-11 Nose-Up Pitching Moment Because of Ground Spoiler Deployment

The MD-11's known tendency to pitch up after ground spoiler deployment and the captain's reference to it during interviews prompted the Safety Board to evaluate the role of the pitch-up tendency in the accident sequence. The captain told Board investigators that he was expecting the nose-up pitching moment associated with initial spoiler deployment at MLG spin-up. He stated that he remembered compensating with forward control column input and that he thought the spoilers had deployed at touchdown. Although a portion of the captain's nose-down elevator input at the time of the first touchdown may have been in response to the pitch-up tendency, the input greatly exceeded that required to control this tendency. Therefore, the Safety Board concludes that the MD-11's tendency to pitch up at ground spoiler deployment did not contribute to the accident. Nevertheless, a reduction or elimination of the pitch-up tendency would simplify MD-11 landing techniques and may help prevent future MD-11 landing incidents and accidents.

2.3.2 MD-11 Pitch Handling Characteristics and the FCC-908 Software Upgrade

The FCC-908 software package developed by Boeing will alter the handling of the airplane during landings by decreasing the pitch sensitivity through action of the PRD. The decrease in pitch sensitivity combined with additional handling improvements included in the FCC-908 upgrade should render the airplane less susceptible to overcontrol in pitch similar to that involved in this accident. Boeing's stated goal in implementing FCC-908 is to match the handling characteristics of the MD-11 to those of the existing DC-10 and the DC-10's newly developed two-pilot adaptation, the MD-10, thereby facilitating FAA approval of a common type rating for the MD-10 and MD-11. The DC-10 and MD-10 do not have the pitch sensitivity that, until implementation of the FCC-908 software upgrade, has been characteristic of the MD-11.

Further, the MD-11 FCC-908 software upgrade may help prevent tailstrikes by providing PAP and eliminating the MD-11's nose-up pitching tendency at touchdown through the positive nose-lowering feature of FCC-908. The Safety Board notes that changing the FCC software to eliminate the nose-up pitching tendency may be an acceptable alternate approach to changing MD-11 spoiler logic as recommended in Safety Recommendation A-93-59.

The Safety Board concludes that the handling changes incorporated in the MD-11 FCC-908 software upgrade will provide valuable improvements in safety during MD-11 landings. Therefore, the Safety Board believes that the FAA should require the

installation, within 1 year, of the MD-11 FCC-908 software upgrade on all MD-11 airplanes.

2.3.3 Digital Flight Data Recorder Update Required by FCC-908

The Safety Board notes that for an MD-11 equipped with the FCC-908 software package, the LSAS will apply elevator control inputs simultaneous with those of the pilots. The Safety Board concludes that with the information that is currently available from the FDR, it may be impossible to distinguish the control inputs of the MD-11 FCC-908 LSAS from the pilots' control inputs. As a result of discussions with Board staff on this subject, Boeing advised the Board that it plans to issue a service bulletin and digital flight data acquisition unit upgrade kit to add some LSAS-associated parameters to the digital flight data recorder (DFDR) data stream.

The Safety Board notes that a requirement for additional FDR parameters is supported by 14 CFR 25.1459(e), which states, "Any novel or unique design or operational characteristic of the aircraft shall be evaluated to determine if any dedicated parameters must be recorded on flight recorders in addition to or in place of existing requirements." Therefore, the Safety Board believes that the FAA should require, on all MD-11s equipped with the FCC-908 software, the retrofit of DFDR systems with all additional parameters required to precisely identify and differentiate between pilot and LSAS elevator control activity, including control column force, IRU pitch rate, LSAS command signals, elevator positions, and automatic ground spoiler (AGS) command signals.

2.3.4 MD-11 Ground Spoiler Knockdown Feature

The Safety Board also evaluated the role of the MD-11 ground spoiler knockdown feature in the accident sequence. MD-11 and DC-10 ground spoilers will not deploy if the No. 2 TRA is greater than 44° to 49°, or just above flight idle. This logic is intended to prevent spoiler deployment or retract spoilers during go-arounds. Go-arounds are characterized by large thrust increases near or above takeoff thrust. The Board is concerned that the MD-11's TRA threshold may be too low to allow for power applications to accommodate moderate sink rate and airspeed control techniques near the ground without disarming the AGS system.

Examination of the accident data shows that TRAs rapidly increased from near idle to about 75° (near takeoff thrust) just before touchdown, which prevented ground spoiler deployment at touchdown and contributed to the bounce. The Safety Board does not consider this large and rapid TRA increase to be consistent with a moderate attempt to control sink rate or airspeed and believes that even a modified DC-10 or MD-11 knockdown feature would likely have prevented spoiler deployment given such a large TRA increase. Further, DC-10 and MD-11 training and procedures require pilots to manually deploy ground spoilers if they do not automatically deploy. Therefore, the Safety

Board concludes that the MD-11's TRA-driven spoiler knockdown feature did not contribute to this accident.

Nevertheless, the Safety Board notes that it is possible to modify the existing DC-10 and MD-11 spoiler deployment system to allow greater throttle movement before the spoiler knockdown feature is activated. Delaying the knockdown feature would allow pilots to make larger thrust increases just before landing without preventing ground spoiler deployment at touchdown, which may help prevent or minimize some bounces. In the event of a go-around, the higher knockdown angle would slightly delay the retraction of ground spoilers; therefore, a study to determine an optimum angle for activation of the knockdown feature would be necessary. Therefore, the Safety Board believes that the FAA should review and, if appropriate, revise the DC-10 and MD-11 TRA-driven ground spoiler knockdown feature to ensure that it does not prevent ground spoiler deployment at moderate TRAs that could be associated with sink rate and airspeed corrections during the landing phase. Further, the Safety Board believes that the FAA should require DC-10 and MD-11 operators to provide their pilots with information and training regarding the ground spoiler knockdown feature and its effects on landing characteristics and performance.

2.4 Transport-Category Airplane Stability and Control During the Landing Phase

The records of previous MD-11 accidents and incidents (reviewed in sections 1.18.4 through 1.18.7), including the accident airplane's two hard landing events that preceded the Newark accident, have drawn attention specifically to the landing characteristics of the MD-11. However, other transport airplane types, including the Boeing DC-10 and 757/767 (as cited by the Safety Board in its June 16, 1994, safety recommendation letter), also have been involved in landing accidents that were or could have been catastrophic. Although improved pilot training in landing techniques and installation of the FCC-908 software upgrade can help prevent MD-11 landing incidents and accidents (see sections 2.2.2.6 and 2.3.2), the accident history involving the MD-11 and other transport airplane types prompted the Board to consider and review existing certification criteria for airplane handling qualities during landing operations.

The review indicated that, besides basic stability criteria, few objective standards exist for the assessment and acceptance of these handling qualities, including the interactions of airplane and pilot responses and the effects of adverse environmental conditions. Based on the accident and incident record, the Safety Board is concerned that certain complex system interactions, pilot input characteristics, and other factors, such as c.g. position and atmospheric conditions, may occasionally combine during the landing phase in undesirable ways that were not identified during the original certification of transport airplanes. Thus, the Safety Board concludes that additional basic research to identify undesirable landing phase combinations and to compare the overall qualitative and quantitative stability and control characteristics of widely used, large transport-

category airplanes is needed to improve certification criteria and reduce the incidence of potentially catastrophic landing accidents.

Therefore, the Safety Board believes that the FAA should sponsor a National Aeronautics and Space Administration (NASA) study of the stability and control characteristics of widely used, large transport-category airplanes to

- a. Identify undesirable characteristics that may develop during the landing phase in the presence of adverse combinations of pilot control inputs, airplane c.g. position, atmospheric conditions, and other factors; and
- b. Compare overall qualitative and quantitative stability and control characteristics on an objective basis. The study should include analyses of DC-10 and MD-11 landing accidents and any other landing incidents and accidents deemed pertinent by NASA.

Further, the Safety Board believes that, based on the results of the study, the FAA should implement improved certification criteria for transport-category airplane designs that will reduce the incidence of landing accidents.

2.5 Structures

2.5.1 Right-Wing Structural Design and Failure

Title 14 CFR Part 25 requires that an airplane's landing gear and associated structure be able to withstand a 12 fps vertical speed when landing at maximum landing weight on one gear at zero roll angle and 1.0 g lift. This equates to a maximum energy capacity for a single MD-11 MLG, as required for certification, of 494,500 ft-lbs. Boeing estimates that the MD-11 landing gear strut will bottom and cause the wing rear spar to fail if approximately more than 1,500,000 ft-lbs of energy is transmitted into a single MLG. At 13.5 fps vertical speed, 0.5 g vertical acceleration, and 8° roll angle, the accident airplane's right MLG experienced an energy input of 1,574,000 ft-lbs during the second touchdown, which was 3.2 times the maximum certification energy and slightly greater than the MD-11's estimated ultimate capability.

The MDI/Boeing structural simulations of the accident sequence indicate that the right MLG strut and outboard tires bottomed at the second touchdown. Energy not absorbed by the landing gear was then transmitted to the right wing rear spar through the right MLG attach points. A corresponding down load was introduced from the left wing and fuselage, which produced additional torsional loads on the right wing. These torsional loads then produced a shear overload condition in the right wing rear spar according to MDI/Boeing simulations. Boeing stated that the MDI simulations indicate that the failure most probably "initiated at the rear spar/bulkhead (trunnion) rib interface and progressed through the primary wing box structure. As a result of this failure, the right MLG trunnion moved substantially upward and aft with respect to the trap [trapezoidal] panel fitting." Thus, the Safety Board concludes that the energy transmitted into the right MLG during

the second touchdown was 3.2 times greater than the MD-11's maximum certificated landing energy and was sufficient to fully compress (bottom) the right MLG strut and cause structural failure of the right wing rear spar.

Runway sooting consistent with a fuel fire near the right MLG was also found at the area of the second touchdown. Thus, on the basis of runway evidence, analysis of performance data, and the MDI/Boeing structural simulations, the Safety Board concludes that the structural failure of the right wing rear spar resulted in the rupture of the right wing fuel tanks and fire.

Although the Hong Kong Civil Aviation Department's investigation of the August 22, 1999, China Airlines MD-11 accident at Hong Kong International Airport is ongoing, examination of the pertinent fracture surfaces suggests that the wing spar failure mode in this accident was very similar to that of FedEx flight 14. The Safety Board's preliminary calculations of the China Airlines MD-11's descent rate at impact, 18 to 20 fps, imply that like the FedEx accident at Newark, the wing spar failed in overload well in excess of certification requirements.

2.5.2 Landing Gear Certification

The MD-11 MLG was designed to break from the wing (fuse) in a drag overload condition but not in a vertical overload condition. Boeing has stated that this design was implemented because data indicated that the most likely landing gear overload condition would occur as a result of striking an obstruction. This "sacrificial shedding" of MLG assemblies in the aft direction was intended to prevent catastrophic loads being transmitted to the wing box and causing rupture.

During its investigation of the FedEx Newark accident, the Safety Board reviewed the circumstances of several accidents involving other wide-bodied airplane types that greatly exceeded aircraft structural limits. A Martinair DC-10 touched down at Faro, Portugal, with a sink rate of 17 fps, at vertical energy loads 2.6 times greater than energy certification requirements for a single MLG. A TWA L-1011 landed in New York at 14 fps, exhibiting vertical energy loads more than twice its certification requirements.

Current landing phase structural design requirements only require consideration of 1.0 g vertical acceleration, small roll angles, and sink rates up to 12 fps. Manufacturers are also required to consider landing gear overloads in the up and aft directions but have the option of either fusing or overdesigning the gear for such loads. Several major landing accidents have now occurred as a result of pilots allowing their airplanes to land with more adverse combinations of lift, roll angle, and sink rate than those specified in the regulations. In each accident, a wing broke and a fuel fire erupted. Each of these accidents involved aircraft whose landing gear were not fused for upward (vertical) acting loads, which concerns the Safety Board. The Safety Board concludes that the failure modes and effects for vertically fused and overdesigned landing gear designs may have been inadequately researched to identify whether, under overload conditions, one design might provide a safer break-up sequence for the airplane than the other design. Therefore, the

Safety Board believes that the FAA should conduct a study to determine if landing gear vertical overload fusing offers a higher level of safety than when the gear is overdesigned. If fusing offers a higher level of safety, the FAA should revise 14 CFR Part 25 to require vertical overload fusing of landing gear.

Further, peak vertical acceleration values recorded by the FDR at landing may not be sufficient for maintenance personnel to determine whether structural damage may have occurred during the landing. Data from the Newark accident indicate that initial vertical acceleration, pitch and roll rates, and attitudes should also be considered during FDR readout and evaluation of a potential hard landing event. The Safety Board notes that Boeing has revised its MD-11 maintenance manual to incorporate this guidance and that the company plans to revise the maintenance manuals of its other products based on the revised MD-11 maintenance manual example. However, the Board is concerned that this guidance will not be available to operators of non-Boeing products and that it is not binding.

Thus, the Safety Board concludes that current manufacturer guidance for hard landing identification and operator maintenance readouts and analysis of FDR data following suspected hard landings may not be adequate to identify landings in which structural damage may have occurred. Therefore, the Safety Board believes that the FAA should require manufacturers of 14 CFR Part 23 and Part 25 airplanes and Part 121 operators to revise their hard landing inspection and reporting criteria to account for all factors that can contribute to structural damage. The FAA should also instruct principal maintenance and operations inspectors assigned to Part 121 operators to ensure that these changes have been made to operator maintenance manuals and Flight Operations Quality Assurance exceedance monitoring programs.

2.6 Hazardous Materials Information Dissemination

After the accident airplane came to a stop inverted, the flight crew evacuated the burning airplane without retrieving shipping documents and hazardous materials information that were in the cabin beside the cockpit door. This is entirely understandable given the circumstances of the accident. According to 49 CFR 172.600, hazardous materials emergency response information (including the basic description, technical name, hazard, risks, precautions, and methods for dealing with releases) is required to be "immediately available" to appropriate personnel following an accident. The North American Emergency Response Guidebook also emphasizes the importance of identifying, within 30 minutes, hazardous materials involved in a transportation accident fire or potential spill runoff so that effective downwind evacuation measures can be implemented to minimize the public's exposure to airborne dispersion clouds and runoff effluents.

However, the incident commander's repeated requests for cargo manifest information went unanswered because FedEx personnel based in Newark did not have immediate access to this cargo information. FedEx personnel in Memphis spent hours

tracing flight 14's cargo documentation because information requests had to be directed first to FedEx offices in Memphis, then to Anchorage, and then to the FedEx office in Narita, Japan, where the hazardous material shipments originated. Firefighting operations had been under way for nearly 2 hours before a partial, handwritten list containing the UN/North American hazard identification numbers for five of seven hazardous materials on board, including a notation about "36 pounds of unknown hazardous materials," was provided to the incident commander.

Although he did not receive a complete list of the specific hazardous materials on board until the fire was nearly extinguished—more than 4 1/2 hours after making his initial request—the incident commander assumed, on the basis of Newark's high volume of cargo shipments, that hazardous materials were on board the accident airplane and took precautionary firefighting measures. Thus, the Safety Board concludes that risks to firefighters and the surrounding community were minimized substantially because the incident commander assumed that hazardous materials were on board and acted accordingly. The Board notes that the incident commander's decision to deploy firefighting units based on the assumption that hazardous materials were likely on board the airplane was prudent and in keeping with the North American Emergency Response Guidebook.

The accident at Newark was the second within a 12-month period involving a FedEx cargo airplane, and both accidents involved similar problems in the dissemination of important hazardous materials information to emergency responders. The Safety Board's investigation of the first of these accidents—the September 5, 1996, accident at Newburgh—determined that emergency response agencies in Newburgh also had to repeatedly request specific information about the hazardous materials on board the airplane and that this information was delayed because FedEx was unable to provide complete information in a timely manner. In addition, faxes of shipping documents sent by FedEx personnel in Memphis did not reach the incident commander. The Board's investigation of the Newburgh accident concluded that FedEx did not have the capability to generate, in a timely manner, a "single list indicating the shipping name, identification number, hazard class, quantity, number of packages, and the location of each declared shipment of hazardous materials on the airplane." The Safety Board concludes that the Newark accident demonstrates that air carriers transporting hazardous materials continue to need a means to quickly retrieve and provide consolidated, specific information to emergency responders about the identity of all hazardous materials on an airplane.

Safety Recommendations A-98-75 and -80, issued on August 12, 1998, recommended to the FAA and RSPA, respectively, that, within 2 years, such a measure be required of all air carriers transporting hazardous materials (see section 1.18.1.2 for a detailed description of these recommendations). RSPA's July 20, 2000, response indicates that, nearly at the end of the requested 2-year period, proposed action to address this safety issue is just in the beginning stages. It is apparent that the requested action is still many years from completion. Therefore, based on this delay, the Safety Board reclassifies Safety Recommendation A-98-80 "Open—Unacceptable Response" and urges RSPA to expedite the rulemaking process.

3. Conclusions

3.1 Findings

1. There was no preexisting damage or degradation to the airplane structure, systems, or components that contributed to this accident.
2. The airplane's approach before the landing flare was stabilized.
3. The captain's execution of the beginning of the flare maneuver was normal and not a factor in the accident.
4. The accident airplane performed normally in response to the captain's flight control inputs until after the second touchdown.
5. The captain was concerned about the airplane's touchdown location on runway 22R and intended to take measures during the landing to achieve an early touchdown and minimize the length of the rollout on the runway after touchdown.
6. The captain's nose-down elevator input beginning at 17 feet radio altitude was not consistent with Federal Express guidance for landing the MD-11.
7. The captain's nose-down elevator input at 17 feet radio altitude (2 seconds before the first touchdown) was consistent with an attempt to control the point of touchdown given his concerns about the runway length.
8. The captain made a nearly full nose-up elevator input and a large throttle increase to compensate for the increased sink rate caused by his previous nose-down input.
9. The captain's full nose-down elevator control input at the time of the first touchdown was consistent with his continued concerns to avoid a long landing and his desire to avoid a tailstrike.
10. The captain's overcontrol of the elevator during the landing and his failure to execute a go-around from a destabilized flare were causal to the accident.
11. The captain's control inputs during the flare and bounce were not consistent with landing procedures and techniques outlined in the Federal Express MD-11 pilot training procedures, McDonnell Douglas flight crew operating manual, or with Federal Express' MD-11 tailstrike awareness and high sink rate and bounce recovery training.
12. The captain had no previously documented skill deficiencies that contributed to this accident.

13. Air carrier pilots' performance would be improved by additional guidance and training in landing techniques.
14. The flight crew's calculation error in determining the runway length required for landing influenced the captain's subsequent actions during final approach and landing by creating a sense of urgency to touch down early and initiate maximum braking immediately.
15. Some flight crewmembers may lack proficiency in the operation of airport performance laptop computers, or similar airplane performance computing devices, and confusion about calculated landing distances may result in potentially hazardous miscalculations of available runway distances after touchdown.
16. The inoperative left landing light did not impede the captain's ability to land the airplane.
17. The MD-11's tendency to pitch up at ground spoiler deployment did not contribute to the accident.
18. The handling changes incorporated in the MD-11 flight control computer-908 software upgrade will provide valuable improvements in safety during MD-11 landings.
19. With the information that is currently available from the flight data recorder, it may be impossible to distinguish the control inputs of the MD-11 flight control computer-908 longitudinal stability augmentation system from the pilots' control inputs.
20. The MD-11's throttle resolver angle-driven spoiler knockdown feature did not contribute to this accident.
21. Additional basic research to identify undesirable landing phase combinations and to compare the overall qualitative and quantitative stability and control characteristics of widely used, large transport-category airplanes is needed to improve certification criteria and reduce the incidence of potentially catastrophic landing accidents.
22. The energy transmitted into the right main landing gear during the second touchdown was 3.2 times greater than the MD-11's maximum certificated landing energy and was sufficient to fully compress (bottom) the right main landing gear strut and cause structural failure of the right wing rear spar.
23. The structural failure of the right wing rear spar resulted in the rupture of the right wing fuel tanks and fire.
24. The failure modes and effects for vertically fused and overdesigned landing gear designs may have been inadequately researched to identify whether, under overload conditions, one design might provide a safer break-up sequence for the airplane than the other design.

25. Current manufacturer guidance for hard landing identification and operator maintenance readouts and analysis of flight data recorder data following suspected hard landings may not be adequate to identify landings in which structural damage may have occurred.
26. Risks to firefighters and the surrounding community were minimized substantially because the incident commander assumed that hazardous materials were on board and acted accordingly.
27. The Newark accident demonstrates that air carriers transporting hazardous materials continue to need a means to quickly retrieve and provide consolidated, specific information to emergency responders about the identity of all hazardous materials on an airplane.

3.2 Probable Cause

The National Transportation Safety Board determines that the probable cause of this accident was the captain's overcontrol of the airplane during the landing and his failure to execute a go-around from a destabilized flare. Contributing to the accident was the captain's concern with touching down early to ensure adequate stopping distance.

4. Recommendations

4.1 New Recommendations

As a result of the investigation of this accident, the National Transportation Safety Board makes the following recommendations:

To the Federal Aviation Administration:

Convene a joint government-industry task force composed, at a minimum, of representatives of manufacturers, operators, pilot labor organizations, and the Federal Aviation Administration to develop, within 1 year, a pilot training tool to do the following:

Include information about factors that can contribute to structural failures involving the landing gear, wings, and fuselage, such as design sink rate limits; roll angle limits; control inputs' roll rate; pitch rate; single-gear landings; the effect of decreased lift; and structural loading consequences of bottoming landing gear struts and tires; (A-00-92)

Provide a syllabus for simulator training on the execution of stabilized approaches to the landing flare, the identification of unstabilized landing flares, and recovery from these situations, including proper high sink rate recovery techniques during flare to landing, techniques for avoiding and recovering from overcontrol in pitch before touchdown, and techniques for avoiding overcontrol and premature derotation during a bounced landing; (A-00-93) and

Promote an orientation toward a proactive go-around. (A-00-94)

Require principal operations inspectors assigned to Part 121 carriers that use auxiliary performance computers to review and ensure the adequacy of training and procedures regarding the use of this equipment and the interpretation of the data generated, including landing distance data. (A-00-95)

Require the installation, within 1 year, of the MD-11 flight control computer-908 software upgrade on all MD-11 airplanes. (A-00-96)

Require, on all MD-11s equipped with the flight control computer-908 software, the retrofit of digital flight data recorder systems with all additional parameters required to precisely identify and differentiate between pilot and longitudinal stability augmentation system (LSAS) elevator control activity, including control column force, inertial reference unit pitch rate, LSAS command signals, elevator positions, and automatic ground spoiler command signals. (A-00-97)

Review and, if appropriate, revise the DC-10 and MD-11 throttle resolver angle (TRA)-driven ground spoiler knockdown feature to ensure that it does not prevent ground spoiler deployment at moderate TRAs that could be associated with sink rate and airspeed corrections during the landing phase. (A-00-98)

Require DC-10 and MD-11 operators to provide their pilots with information and training regarding the ground spoiler knockdown feature and its effects on landing characteristics and performance. (A-00-99)

Sponsor a National Aeronautics and Space Administration (NASA) study of the stability and control characteristics of widely used, large transport-category airplanes to

- Identify undesirable characteristics that may develop during the landing phase in the presence of adverse combinations of pilot control inputs, airplane center of gravity position, atmospheric conditions, and other factors; and

- Compare overall qualitative and quantitative stability and control characteristics on an objective basis.

The study should include analyses of DC-10 and MD-11 landing accidents and any other landing incidents and accidents deemed pertinent by NASA. (A-00-100)

Based on the results of the study recommended in Safety Recommendation A-00-100, implement improved certification criteria for transport-category airplane designs that will reduce the incidence of landing accidents. (A-00-101)

Conduct a study to determine if landing gear vertical overload fusing offers a higher level of safety than when the gear is overdesigned. If fusing offers a higher level of safety, revise 14 Code of Federal Regulations Part 25 to require vertical overload fusing of landing gear. (A-00-102)

Require manufacturers of 14 Code of Federal Regulations Part 23 and Part 25 airplanes and Part 121 operators to revise their hard landing inspection and reporting criteria to account for all factors that can contribute to structural damage; instruct principal maintenance and operations inspectors assigned to Part 121 operators to ensure that these changes have been made to operator maintenance manuals and Flight Operations Quality Assurance exceedance monitoring programs. (A-00-103)

4.2 Previously Issued Recommendations Classified in This Report

Safety Recommendation A-98-80, previously classified “Open—Acceptable Response,” is classified “Open—Unacceptable Response” in section 2.6 of this report.

BY THE NATIONAL TRANSPORTATION SAFETY BOARD

JAMES E. HALL
Chairman

JOHN A. HAMMERSCHMIDT
Member

JOHN J. GOGLIA
Member

GEORGE W. BLACK, JR.
Member

CAROL J. CARMODY
Member

Adopted: July 25, 2000

5. Appendixes

Appendix A Investigation and Hearing

5.1 Investigation

The National Transportation Safety Board was initially notified of this accident about 0200 eastern standard time, on July 31, 1997. An investigative team was dispatched to the accident site shortly thereafter. Investigative groups were formed in the following specialties: operations/human performance, aircraft performance, hazardous materials, structures, systems/powerplants, airports, flight data recorder, and cockpit voice recorder. Member John Goglia accompanied the team to Newark.

Parties to the investigation were:

1. Boeing Commercial Aircraft
2. Federal Express, Inc.
3. Port Authority of New York and New Jersey
4. Federal Aviation Administration
5. Federal Express Pilots Association
6. General Electric Aircraft Engines

5.2 Public Hearing

A public hearing was not held.

Appendix B

Cockpit Voice Recorder Transcript

Transcript of a Fairchild cockpit voice recorder (Model A100A, S/N 25685) installed on a MD-11, N611FE, which was involved in an accident at the Newark International Airport, NJ on July 31, 1997.

LEGEND

CAM	Cockpit area microphone
INT	Aircraft intercom system
HOT	Crewmember "hot" microphone
RDO	Radio transmission from accident aircraft
-1	Voice (or position) identified as Captain
-2	Voice (or position) identified as First Officer
-3	Voice (or position) identified as Jump Seat Rider
-?	Unidentifiable voice
ZBW	Boston Air Route Traffic Control Center (ARTCC)
RAMP	FedEx Newark Operations
MAINT	FedEx Newark Maintenance
NYAPP	New York Terminal Radar Approach Control (TRACON)
ATIS	Newark Automatic Terminal Information Service (ATIS)
EWR	Newark Air Traffic Control Tower, Local Control

Note: Unless otherwise noted, only those radio transmissions to and from the accident aircraft were transcribed.

LEGEND (continued)

*	Unintelligible word
#	Expletive deleted
...	Pause
()	Questionable text
[]	Editorial insertion
-	Break in continuity

Page 1 of 35

INTRA-COCKPIT COMMUNICATIONAIR-GROUND COMMUNICATION

<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0102:03 Beginning of Recording			
0102:03 Beginning of Transcript		0102:03 RDO-2	that's affirm SHAFF three after Hancock FedEx fourteen heavy.
		0102:06 ZBW	roger.
		0102:11 ZBW	okay FedEx fourteen, descend and maintain flight level one eight zero.
0102:15 CAM-1	that's affirm.	0102:17 RDO-2	down to flight level one eight zero, FedEx fourteen heavy.
0102:22 CAM-1	ah remind me to - we still want two and three for reverse.		
0102:27 CAM-2	yeah, okay.		
0102:29 CAM-1	*** ... you might ask him if wants that at our discretion ***.		
0102:34 CAM-?	***.		

Page 2 of 35

INTRA-COCKPIT COMMUNICATIONAIR-GROUND COMMUNICATION

<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0103:00 CAM-2	(isn't) this the APLC when it plugs out those distances?	0102:35 RDO-2	and Boston center FedEx fourteen heavy, you want us out of ah three three zero at this time?
0103:03 CAM-1	yup.	0102:47 ZBW	ah ... yeah .. you can start a gradual descent.
0103:04 CAM-2	that includes the ah ... runway you have before touchdown, right?	0102:52 RDO-2	and fourteen heavy roger.
0103:10 CAM-1	(gimme) that again.		
0103:11 CAM-2	I said that includes the ah .. that includes the runway that's used up prior to touchdown, right?		
0103:21 CAM-1	for which? beyond (beyond) the glide slope?		
0103:23 CAM-2	yeah.		

Page 3 of 35

<u>INTRA-COCKPIT COMMUNICATION</u>		<u>AIR-GROUND COMMUNICATION</u>	
<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0103:23 CAM-1	yeah, that's showing you how much you got remaining. if you fly the glide slope and you're right on it you've got sixty-eight. twenty-two ah right okay which is the one we're looking at, right?		
0103:33 CAM-2	yeah, twenty-two right's got (so beyond is sixty-eight sixty).		
0103:35 CAM-1	sixty-eight sixty.		
0103:37 CAM-2	so if we go medium brakes we're gonna have eight hundred. so does that mean if we go medium brakes landing on this runway we'll have eight hundred and .. eight hundred feet (in front of us) when we come to a stop?		
0103:47 CAM-1	yeah, *.		
0103:48 CAM-2	you don't want to go maximum? you wanna go max?		
0103:50 CAM-1	well we can .. we'll see how it goes .. I don't know. we we can probably as a matter of fact, we can we can start max if it makes you feel better and then we'll ah come off * * come on off regardless.		
0103:57 CAM-2	yeah, *.		
0103:59 CAM-1	* , we got .. we got a lot of stuff going against us here so we'll .. we'll start with max * * * * .		

Page 4 of 35

AIR-GROUND COMMUNICATION

<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0104:03 CAM-2	I mean .. I mean if we don't have the reverser so -		
0104:04 CAM-1	yeah that -		
0104:05 CAM-2	* * * *		
0104:06 CAM-1	that sounds good to me .. I'd rather play it that way. that was my original plan then I started thinking well we gotta a little plan here. most likely we're gonna go .. after we land we'll most likely probably plan to go to the end anyway to turn off at Victor .. that's what I'd like to do .. cause we come down here and make a left turn and then ah .. I think they park us over here so we'll come in this Pappa Charlie and your deal on that is to ah -		
0104:32 CAM-2	(not) Pappa Charlie.		
0104:34 CAM-1	(you see) Pappa - sometimes sometimes you might go in Pappa Bravo .. depends where they park us.		
0104:37 CAM-2	yeah.		
0104:38 CAM-1	but ah I been .. last few number of times I've come in we park over in this section right here .. but you're supposed to stay on ah ground until you get up to Pappa -		
0104:48 CAM-2	until you turn in basically.		

Page 5 of 35

AIR-GROUND COMMUNICATIONINTRA-COCKPIT COMMUNICATION

<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0104:49 CAM-1	yeah Pappa Charlie but when you get over here you're supposed to contact them some point in time to make sure the gate's still the same.		
0104:54 CAM-2	yeah.		
0104:56 CAM-1	anyways, if you're ready, we'll go dark.		
0104:58 CAM-2	yup, I'm all set.		
0105:07 CAM-?	* * .		
0105:13 CAM-2	why would this be saying IRS ONLY navigation * * ?		
0105:17 CAM-1	it's just not picking up ah whatever .. I don't know .. don't ask me why .. it should be picking up plenty of VORs out here.		
0105:28 CAM-2	* * * * .		
0105:33 CAM	[sound of several loud clicks]		
0105:44 CAM-1	I believe we should be getting an in-range deal from these guys telling us what our gate assignment is but ah in the event we don't get one say-		

Page 6 of 35

INTRA-COCKPIT COMMUNICATION

<u>TIME and SOURCE</u>	<u>CONTENT</u>
0105:52 CAM-2	why don't I call them right now.
0105:53 CAM-1	okay, you can give them a call.
0106:06 CAM-2	okay, I'm going up on two.
0106:08 HOT-1	okay, I've got one.

AIR-GROUND COMMUNICATION

<u>TIME and SOURCE</u>	<u>CONTENT</u>
0106:20 RDO-2	Newark ramp FedEx fourteen heavy.
0106:25 RAMP	fourteen heavy parking gate thirty-one, negative ground power.
0106:32 RDO-2	roger that thirty-one I'll start the APU. we'll probably be in around forty-five.
0106:35 ZBW	FedEx .. FedEx fourteen Boston center one three four point three.
0106:37 RAMP	copy that.
0106:39 RDO-1	thirty-four point three, roger.
0106:41 RDO-2	and it might be a little sooner ... we might be in around thirty-five to forty-five for FedEx fourteen heavy.

Page 7 of 35

INTRA-COCKPIT COMMUNICATIONAIR-GROUND COMMUNICATIONTIME and
SOURCECONTENTTIME and
SOURCECONTENT0106:58
HOT-2

gate thirty-one.

0107:06
HOT-1

three one?

0107:06
HOT-2

yeah.

0107:10
HOT-1

it's over in that -

0107:11
HOT-2

yeah, right where you said we'd be.

0107:16
HOT-2

we're way down at the end there ... there right where you said.

0107:17
HOT-1

got it .. so we'll be going in that ah Pappa Charlie and ah somewhere along the line when we get down there you can advise the ground .. the ground control that that's where we want to go in.

0106:45
RAMP

fourteen heavy roger.

0106:50
RDO-1

ah good morning Boston .. FedEx fourteen is with you out of twenty-one five for one eight zero.

0106:56
ZBW

fourteen roger.

Page 8 of 35

INTRA-COCKPIT COMMUNICATIONAIR-GROUND COMMUNICATION

<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0107:29 HOT-2	okay.		
0107:29 HOT-1	cause a lot of times they'll be expecting us to come in that other direction there.		
0107:42 HOT-1	[sound of human whistling]	0107:45 ZBW	FedEx fourteen verify you're going to Newark tonight.
0107:48 CAM	[sound of tone and verbalized "altitude" from the CAWS]		
0107:49 HOT-1	that's affirmative.		
		0107:50 RDO-2	FedEx fourteen that's affirmative we're going to Newark.
0107:56 HOT-2	there's coming up on eighteen thousand.		
0107:56 HOT-1	boy that cuts it close, don't it.		
0108:06 HOT-2	I started to reach for the hand mic.		
0108:34 HOT-1	[sound of human whistling]		

Page 9 of 35

<u>INTRA-COCKPIT COMMUNICATION</u>		<u>AIR-GROUND COMMUNICATION</u>	
<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0108:39 HOT-1	you might ask him if he's gonna expect us to ah cross the ah SPARTA twenty-five degree at eight thousand feet ... or twenty-five miles at eight thousand feet.		
0108:53 HOT-2	is this .. who is this Boston still?		
0108:55 HOT-1	it's Boston, yeah.		
		0108:59 RDO-2	ah Boston FedEx fourteen heavy are you expecting us to cross the SPARTA at twenty-five at ah eight thousand?
		0109:05 ZBW	(probably) at seven yeah .. can't do anything for another ten miles .. we do it every day .. don't worry .. I'll take care of you.
		0109:09 RDO-2	roger.
0109:12 HOT-1	I think I'm gonna cut this radar off .. I don't think we need it.		
0109:16 HOT-1	get all the glitter out of there ... anyways ah we're at eighteen .. we can do an in-range.	0109:15 RDO-2	yeah.
0109:24 HOT-2	roger that.		

Page 10 of 35

INTRA-COCKPIT COMMUNICATIONAIR-GROUND COMMUNICATION

<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0109:47 HOT-2	(I say) for altimeter there?		
0109:49 HOT-1	three zero two four huh. yeah I'm just gonna hold on the altimeter until we go below eighteen.		
0109:54 HOT-2	thirty twenty-four, okay.		
0110:14 HOT-1	thirty miles.	0110:15 ZBW	FedEx fourteen cross twenty-five north of SPARTA at seven thousand .. altimeter three zero two seven.
		0110:21 RDO-2	roger twenty-five north of SPARTA at seven thousand three zero two seven FedEx fourteen heavy.
0110:29 HOT-1	okay seven is the number .. I'm gonna put ten in here for just a second so I can get it to slow .. without shooting through there ... and three zero two seven.		
0110:50 HOT-2	so won't it slow down automatically?		
0110:53 HOT-1	well I'm .. I level changed it just to get it to go down quicker.		
0110:56 HOT-2	oh, okay.		

Page 11 of 35

<u>INTRA-COCKPIT COMMUNICATION</u>		<u>AIR-GROUND COMMUNICATION</u>	
<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0110:57 HOT-1	and we're behind as it is anyways.		
0111:01 HOT-2	so do you have to keep that ten in until we get to ten basically before you put seven in?		
0111:04 HOT-1	well, it's the safe way to do it.		
0111:05 HOT-2	yeah, okay.		
0111:06 HOT-1	it's just not a .. it's a technique more than anything else but ah -		
0111:11 HOT-2	yeah, I'm just starting to learn. okay yeah it's ah three zero two seven on the altimeters and in-range check is complete.		
0111:12 CAM	[sound of chime similar to that of ACARS message]		
0111:18 HOT-2	gate thirty-one north is what they're saying. negative ground power.		
0111:36 HOT-1	so like we've got thirty-one miles to make that and we've got ah what ah four, three, seven, twenty-one we're looking good.		
0111:43 HOT-2	seven'll be twenty-one, yeah we're fine.		

Page 12 of 35

AIR-GROUND COMMUNICATIONINTRA-COCKPIT COMMUNICATION

<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0111:50 HOT-1	now what I could do .. when this comes back .. go back to PROF .. then I put seven in here and now it will do it automatically.		
0111:59 HOT-2	and you probably pop the -		
0112:00 HOT-1	it's just when you come out of ah -		
0112:02 HOT-2	then you pop the drag out then too huh?		
0112:05 HOT-1	when you come out of that deal there it's ah .. out of PROF you're on your own. if you put something lower than ten thousand -		
0112:12 HOT-2	yeah.		
0112:13 HOT-1	in there and you just level change it, it'll shoot right on by.		
0112:15 HOT-2	oh it will? okay		
0112:16 HOT-1	yeah.		
0112:27 HOT-2	well this should be at seven thousand not eight thousand here.		

<u>INTRA-COCKPIT COMMUNICATION</u>		<u>AIR-GROUND COMMUNICATION</u>	
<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0112:30 HOT-1	well below seven or ah -		
0112:32 HOT-2	well I mean that's what he wanted us at seven right so I can come over here and go like this.		
0112:34 HOT-1	okay yeah you can put it ah you can put it at seven if you'd like.		
0112:41 HOT-1	you need a slash in there though, you got it?		
0112:42 HOT-2	yeah I was gonna go -		
0112:47 HOT-1	I'm just gonna help this out a little bit. let's see .. we got ah seven three -		
0112:57 HOT-2	it's saying not allowed.		
0113:00 HOT-1	well .. oh you're on the DIRECT TO page.		
0113:02 HOT-2	oh okay.		
0113:02 HOT-1	you need to go back to FLIGHT PLAN.		
0113:08 HOT-2	first time I did that.		

<u>INTRA-COCKPIT COMMUNICATION</u>		<u>AIR-GROUND COMMUNICATION</u>	
<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0113:13 HOT-1	just ignore the speed limit exceeded .. it's not a problem.		
0113:49 HOT-1	gotta clear that BUTTON PUSH IGNORED outta there ... there you go.		
0113:57 HOT-1	that's okay .. when we're around the bend here I'll just level change it and it'll .. it'll do its thing there.		
0114:00 HOT-2	there it goes.		
0114:01 HOT-1	it'll make it quicker.		
0114:22 HOT-1	you might wanna tell those girls in the back that ah we're gonna have a pretty abrupt stop because of those brakes and the thrust reversers and all that stuff so.		
0114:28 HOT-2	okay.		
0114:32 HOT-1	which if you actually you can use your microphone and push forward on your push-to-talk switch and that'll just use the interphone back there.		
0114:36 HOT-2	okay.		

Page 15 of 35

INTRA-COCKPIT COMMUNICATIONAIR-GROUND COMMUNICATION

<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0114:56 HOT-1	did you pull back or push forward?	0114:43 RDO-2	yeah we should be on the ground here in about .. about another fifteen twenty minutes .. we're gonna have a pretty quick stop here because we're landing on a short runway just to give you guys a heads up in the back there.
0114:59 HOT-2	I pushed it forward.	0114:54 ZBW	I appreciate it.
0115:01 HOT-1	ah well it should be. test. it should just go to the back if you push forward on it.		
0115:08 CAM	[sound of tone and verbalized "altitude" from the CAWS]		
0115:08 HOT-1	two one.		
0115:11 HOT-2	just went like that.		
0115:13 HOT-1	there you go .. that'll work.		
0115:17 HOT-2	try [sound of laughter]		
0115:20 HOT-1	oh well.		

<u>INTRA-COCKPIT COMMUNICATION</u>		<u>AIR-GROUND COMMUNICATION</u>	
<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0115:20 INT	to give you guys a heads up we're gonna be landing pretty ah pretty quick here .. we've got about another fifteen minutes to go to get on the ground .. we got a short runway so .. so let you know that the aircraft is going to be stopping pretty quick.		
0115:36 HOT-2	[sound of laughter]		
0115:39 HOT-1	I'm sure you're the only guy in this airline that's ever done that before.		
0115:43 CAM-3	I've never done that.		
0115:44 HOT-1	nah, me neither.		
0115:44 CAM-3	[sound of laughter]		
0115:46 HOT-2	I don't know what in the world happened .. I mean I was pushing on that thing forward.		
0115:49 HOT-1	you can turn on those lights if you would.		
0115:51 HOT-2	yeah sure.		
0115:52 HOT-1	ah landing lights.		

Page 17 of 35

AIR-GROUND COMMUNICATIONCONTENTTIME and
SOURCEINTRA-COCKPIT COMMUNICATIONCONTENTTIME and
SOURCE

0115:53 CAM	[sound of several clicks]
0115:56 HOT-1	and in-range is complete, correct?
0115:57 HOT-2	yes.
0115:59 HOT-1	yeah, we made that with plenty of room to spare.
0116:16 HOT-1	looks like we got one burned out.
0116:28 HOT-1	just having all kinds of fun here.
0116:29 HOT-2	left side's out, huh?
0116:31 HOT-1	well let's see.
0116:32 HOT-2	is the left side out?
0116:33 HOT-1	think so.
0116:35 HOT-1	yeah, just the right's working.
0116:39 HOT-1	well I guess we got another thing we'll write up.

Page 18 of 35

INTRA-COCKPIT COMMUNICATIONAIR-GROUND COMMUNICATION

<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0116:45 HOT-2	should I punch that over to maintenance real quick?		
0116:48 HOT-1	say again.		
0116:49 HOT-2	want to ACARS 'em real quick or just let them know?		
0116:52 HOT-2	I'll call Newark real quick.		
0116:53 HOT-1	no, I don't think it's a big issue. they'll defer it if they have to but -	0117:07 RDO-2	Newark maintenance FedEx fourteen.
		0117:15 MAINT	fourteen maintenance.
		0117:17 RDO-2	yeah maintenance fourteen .. just giving you a heads-up .. our left landing light is inoperative.
		0117:25 MAINT	okay fourteen we'll see you at the gate.
		0117:27 RDO-2	bye.

Page 19 of 35

<u>INTRA-COCKPIT COMMUNICATION</u>		<u>AIR-GROUND COMMUNICATION</u>	
<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0117:29 HOT-1	like these guys care. [sound of laughter] Newark .. these guys you'll find are some of the worst mechanics we've got in the system. man these guys don't do anything they got a note in the little orange pages down here -		
0117:44 HOT-2	ah huh.		
0117:45 HOT-1	that when you .. for the parking spot we're going to .. that if there's any containers on the right-hand side there by the blast fence .. you'll see this blast fence when we get up there -		
0117:53 HOT-2	yeah.		
0117:54 HOT-1	that ah uhm that you're supposed to shut down and get towed in. ah so in theory, they're supposed to always clear those out .. and you .. there'll be a hundred of them over there .. if there's any .. if there's .. I mean it'll they'll just be all over the place .. it just depends on how ah .. how tight we are here but at least we'll have the blast fence.		
0118:15 HOT-1	yeah, we're going to thirty-one you said?		
0118:16 HOT-2	yes.		
0118:17 HOT-1	yeah.		

Page 20 of 35

AIR-GROUND COMMUNICATION

<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0118:18 HOT-2	it's right down at the end there.		
0118:19 HOT-1	they can't go too far but .. I've actually just stopped it right there and told them to tow us in before.		
0119:02 HOT-2	luckily the controller probably thinks that I was a ah some passenger airline flight engineer calling up the flight attendants or something.		
0119:08 HOT-1	what's that?		
0119:09 HOT-2	I said hopefully the center will probably thinks that I was a ah some passenger airline calling the flight att -		
0119:13 HOT-1	yeah, he wouldn't figure that it's us ah -		
0119:15 HOT-2	not FedEx.		
0119:16 HOT-1	freight dogs.		
0119:21 HOT-2	[sound of laughter]		
0119:24 HOT-1	ah it barely matters.		
0119:37 HOT-1	[sound of human whistling]		

Page 21 of 35

<u>INTRA-COCKPIT COMMUNICATION</u>		<u>AIR-GROUND COMMUNICATION</u>	
<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0119:40 HOT-2	I heard a captain once give a whole .. briefing on weather .. their route of flight and everything to the passengers over the radio one time. it was pretty funny.		
0119:49 HOT-1	[sound of laughter]		
0119:50 HOT-2	I was flying with Delta.		
0119:51 HOT-1	probably talking for twenty minutes man.		
0119:52 HOT-2	yeah ... I bet every air .. every airline in the system was calling him up and saying yeah that sounded real good yeah you know.		
0120:00 HOT-1	[sound of laughter]		
0120:00 HOT-2	really giving him .. really giving him #.		
0120:02 HOT-1	ah.		
0120:03 HOT-2	and all these other airlines, United .. and all that stuff.		
0120:22 HOT-1	any time boys.		
		0120:30 RDO-1	folks don't seem to be overly busy this evening.

Page 22 of 35

INTRA-COCKPIT COMMUNICATIONTIME and
SOURCECONTENT

0120:36
HOT-1 yeah and they won't talk to us .. ah see .. we probably
 should be talking to New York or something.

AIR-GROUND COMMUNICATIONTIME and
SOURCECONTENT

0120:46 who's that calling?
ZBW

0120:48 that was FedEx fourteen .. I was just saying that ah it
RDO-1 seems awfully quiet out here, we weren't sure we still had
 you anymore.

0120:52 you still do .. let's go over to New York now one two zero
ZBW correction ah .. (let's get) the right frequency .. one two five
 point five .. have a nice night.

0120:59 twenty-five five switching.
RDO-2

0121:40 New York FedEx fourteen heavy with you at seven
RDO-2 thousand.

0121:44 FedEx fourteen heavy New York approach roger .. proceed
NYAPP direct to Teterboro for the ILS two two right .. Newark
 altimeter three zero two three.

0121:53 direct Teterboro .. three zero two three FedEx fourteen
RDO-2 heavy.

0121:58
HOT-1

I don't have that in there anywhere but if you can just -

Page 23 of 35

INTRA-COCKPIT COMMUNICATIONAIR-GROUND COMMUNICATION

<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0122:02 HOT-2	I'll put it in there .. TEB .. got it.		
0122:08 HOT-1	that's at just about Agnss .. I'll just .. I'll just head direct to that pretty much for right now.		
0122:14 HOT-2	there's the ah -		
0122:15 HOT-1	and when you get it in there we'll .. you don't have to do that. this .. Agnss and Teterboro are just about the same spot. direct there will work.		
0122:22 HOT-2	there it is.		
0122:24 HOT-2	nav's available.		
0122:25 HOT-1	okay, you can make it direct Agnss .. be alright .. I'm sorry. that's close enough .. it's .. they're right on top of each other.		
0122:45 HOT-2	oh, okay yeah.	0122:49 NYAPP	FedEx fourteen heavy descend and maintain three thousand.
		0122:52 RDO-2	three thousand now FedEx fourteen heavy.

Page 24 of 35

AIR-GROUND COMMUNICATIONINTRA-COCKPIT COMMUNICATION

<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0122:56 CAM	[sound of several clicks]		
0122:57 HOT-1	three thousand .. ah .. Agnss will be alright .. direct Agnss.		
0122:58 HOT-2	three thousand ... and kill Teterboro?		
0123:02 HOT-1	yeah, you don't need that. it's pretty much the same spot. okay, now (I'm in NAV).		
0124:16 HOT-2	what's that ATIS Kilo ... there's one ten seventy-five .. one ten seventy-five.		
0124:28 HOT-1	[sound of human whistling]		
0125:04 CAM	[sound of tone and verbalized "altitude" from the CAWS repeats twice]		
0125:08 HOT-2	and four for three.		
0125:09 HOT-1	alright.		
0125:10 HOT-2	why .. why does it have that amber altitude up there?		
0125:12 HOT-1	say again.		

<u>INTRA-COCKPIT COMMUNICATION</u>		<u>AIR-GROUND COMMUNICATION</u>	
<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0125:14 HOT-2	see that .. see that amber altitude right below the ... on your side there.		
0125:16 HOT-1	ah your .. yeah I've got .. we've got a difference .. I got twenty .. thirty twenty-three .. you got thirty twenty-seven, he gave twenty-three a minute ago to somebody. we'll just verify it when we get down there.		
0125:23 HOT-2	oh okay .. I'm sorry.		
0125:26 HOT-1	that's what that's all about.		
0125:26 HOT-2	yeah sure.		
0125:34 HOT-2	(and) coming up on three thousand.		
0125:34 HOT-1	I could be wrong. maybe he gave that to somebody else going someplace else .. but I heard a three zero two three in there awhile ago.		
0125:38 HOT-2	yeah oh, I think you're right .. I think I forgot .. failed to set it.		
0126:17 HOT-1	I'll take slats extend.		
0126:20 HOT-2	slats extend.		

Page 26 of 35

<u>INTRA-COCKPIT COMMUNICATION</u>		<u>AIR-GROUND COMMUNICATION</u>	
<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0126:21 CAM	[sound of several clicks, similar to that of the flap/slat handle movement]		
0126:21 HOT-1	and well looks like we do an approach check.		
0126:25 HOT-2	(two are tuned there.)		
0126:32 HOT-2	want the approach check?		
0126:33 HOT-1	approach check, yes. I don't know if you heard me or not.		
0126:35 HOT-2	okay, briefing?		
0126:36 HOT-1	ah .. it's complete for twenty-two right.		
0126:39 HOT-2	altimeters?		
0126:41 HOT-1	I've got three zero two three set on this side.		
0126:43 HOT-2	three zero two three set on this side .. we'll .. we'll check again (with) the next controller there. okay minimums?		
0126:49 HOT-1	ah two eleven.		

Page 27 of 35

INTRA-COCKPIT COMMUNICATIONAIR-GROUND COMMUNICATION

<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0126:50 HOT-2	two eleven .. radios?	0127:24 NYAPP	FedEx fourteen heavy turn right heading one eight zero.
0126:54 HOT-1	look tuned and identified.	0127:26 RDO-2	one eight zero FedEx fourteen heavy.
0126:55 HOT-2	tuned and identified .. approach checklist complete.	0127:38 ATIS	Newark airport information Lima time zero four five one Zulu .. automated weather .. wind two five zero at five .. visibility one zero .. eight thousand scattered .. temperature two zero .. dew point one two .. altimeter three zero two four.
0127:34 HOT-1	one eighty.	0127:59 NYAPP	[continuation of transmission to another aircraft] ... Newark altimeter three zero two three.
0127:59 HOT-2	the ATIS is calling three zero two four.		
0128:02 HOT-1	okay.		

Page 28 of 35

INTRA-COCKPIT COMMUNICATIONAIR-GROUND COMMUNICATION

<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0128:02 HOT-2	a there .. he just called three zero two three though.	0128:04 NYAPP	FedEx fourteen heavy .. descend and maintain two thousand .. advise field in sight.
0128:13 HOT-1	flaps fifteen.	0128:08 RDO-2	two thousand .. will advise ... FedEx fourteen heavy.
0128:14 HOT-2	flaps fifteen.		
0128:15 CAM	[sound of several clicks, similar to that of the flap/slat handle movement]		
0128:50 HOT-2	there's a beacon out there.		
0128:51 HOT-1	I sure don't see it.		
0128:58 HOT-2	there's a beacon right out ... it's all white .. it's gonna go green again in a little bit.	0129:01 NYAPP	FedEx fourteen heavy .. the field's ah one o'clock and ah eight.
0129:05 CAM-?	it should be over here.		

Page 29 of 35

INTRA-COCKPIT COMMUNICATIONAIR-GROUND COMMUNICATION

<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0129:07 HOT-1	I still don't have it.	0129:05 RDO-2	fourteen heavy roger.
0129:08 HOT-2	the white strobes .. see the white strobes .. I don't know if that would .. if that's the end of the runway.		
0129:10 HOT-1	okay yeah .. got it .. got it .. it was sitting right here in the -	0129:12 RDO-2	and fourteen heavy's got the field in sight.
		0129:14 NYAPP	FedEx fourteen heavy .. cleared visual approach runway two two right .. contact Newark tower one one eight point three .. good day.
		0129:20 RDO-2	eighteen three FedEx fourteen heavy switching.
0129:25 HOT-2	cleared the approach .. eighteen three.		
0129:32 HOT-2	there it is .. got it?		
0129:33 HOT-1	I got it.		
		0129:34 RDO-2	tower FedEx fourteen heavy is rolling final runway two two right.

Page 30 of 35

INTRA-COCKPIT COMMUNICATIONAIR-GROUND COMMUNICATION

<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0129:42 HOT-1	flaps twenty-eight.		
0129:44 HOT-2	flaps twenty-eight.		
0129:45 CAM	[sound of several clicks, similar to that of the flap/slat handle movement]	0129:45 EWR	FedEx fourteen heavy .. ah winds two five zero at five .. two two right cleared to land.
		0129:51 RDO-2	cleared to land two two right FedEx fourteen heavy.
0129:55 HOT-2	flaps are at twenty-eight.		
0129:55 HOT-1	got a glide slope capture .. gear down .. before landing check.		
0129:58 CAM	[sound similar to that of landing gear being lowered]		
0130:01 CAM	[sound of click, similar to that of spoilers being armed]		
0130:02 HOT-2	max brakes.		
0130:03 HOT-1	max brakes will be fine.		

Page 31 of 35

AIR-GROUND COMMUNICATIONCONTENTTIME and
SOURCEINTRA-COCKPIT COMMUNICATIONCONTENTTIME and
SOURCE

0130:05 HOT-2	if they work.
0130:17 HOT-1	flaps thirty-five.
0130:19 CAM	[sound of several clicks, similar to that of the flap/slat handle movement]
0130:25 HOT-2	okay, spoilers are armed .. autobrakes?
0130:30 HOT-1	okay, maximum .. looks like it's set.
0130:32 HOT-2	land .. landing gear down in four green.
0130:34 HOT-1	down in four green .. flaps fifty.
0130:36 HOT-2	flaps fifty.
0130:36 CAM	[sound of several clicks, similar to that of the flap/slat handle movement]
0130:41 HOT-2	flaps are fifty.
0130:43 HOT-1	okay.

Page 32 of 35

AIR-GROUND COMMUNICATION

<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0130:44 HOT-2	coming up on and -		
0130:45 HOT-1	coming off the autopilot.		
0130:48 HOT-2	flaps are fifty.		
0130:48 CAM	[sound of warble tone and verbalized "autopilot" from the CAWS]		
0130:49 HOT-2	before landing checklist is complete.		
0130:59 HOT-1	two and three on the reverse .. just in case I forget.		
0131:01 HOT-2	roger that .. two and three.		
0131:03 CAM	[sound of unknown click and chime]		
0131:03 CAM	[verbalized "one thousand" from the CAWS]		
0131:07 HOT-1	category one.		
0131:09 HOT-2	(got that.)		
0131:38 CAM	[verbalized "five hundred" from the CAWS]		

Page 33 of 35

AIR-GROUND COMMUNICATIONCONTENTTIME and
SOURCEINTRA-COCKPIT COMMUNICATIONCONTENTTIME and
SOURCE

0131:40
HOT-2 alright .. cleared to land two two right.

0132:03.00
HOT-2 there's (coming up) minimums.

0132:05.85
HOT-2 okay, gear's down .. flaps are fifty.

0132:09.58
HOT-2 brakes on max.

0132:09.65
CAM [verbalized "one hundred" from the CAWS]

0132:13.84
CAM [verbalized "fifty" from the CAWS]

0132:14.71
CAM [verbalized "forty" from the CAWS]

0132:15.72
CAM [verbalized "thirty" from the CAWS]

0132:16.55
CAM [verbalized "twenty" from the CAWS]

0132:17.67
CAM [verbalized "ten" from the CAWS]

0132:18.75
CAM [sound of initial touchdown]

0132:19.21
HOT-1 #.

<u>INTRA-COCKPIT COMMUNICATION</u>		<u>AIR-GROUND COMMUNICATION</u>	
<u>TIME and SOURCE</u>	<u>CONTENT</u>	<u>TIME and SOURCE</u>	<u>CONTENT</u>
0132:20.26 CAM	[sound of increase in high frequency tone, similar to that of engine spool-up]		
0132:21.06 CAM	[sound of decrease in high frequency tone, similar to that of engine spool-down]		
0132:20.98 HOT-1	# damn it.		
0132:21.56 HOT-2	jesus.		
0132:21.62 CAM	[sound of loud thump, similar to aircraft touchdown]		
0132:22.42 HOT-1	# damn it.		
0132:23.14 CAM	[0.31 second loss in CVR audio]		
0132:23.84 HOT-1	#.		
0132:24.43 HOT-1	oh #.		
0132:26.05 CAM	[verbalized "tire failure" repeats twice]		
0132:26.43 HOT-2	# damn it (damn it.)		

INTRA-COCKPIT COMMUNICATION

<u>TIME and SOURCE</u>	<u>CONTENT</u>
0132:27.42 CAM	[sound of metallic break-up]
0132:28.83 CAM	[end of recording]

AIR-GROUND COMMUNICATION

<u>TIME and SOURCE</u>	<u>CONTENT</u>
----------------------------	----------------


Appendix C

Excerpts from the Flight Data Recorder

Federal Express MD-11, 2 Landings Prior To Accident

DCA97MA055

flaps 35




National Transportation Safety Board/ VPD

Federal Express MD-11, Landing Prior To Accident

flaps 35 landing

DCA97MA055




National Transportation Safety Board/ VPD

Federal Express Accident Landing


MD-11. 7/31/97 @ EWR

DCA97MA055




National Transportation Safety Board

DCA97MA055



Federal Express Accident Landing




National Transportation Safety Board

Federal Express MD-11 Accident Landing

7/31/97 @ EWR

DCA97MA055




National Transportation Safety Board/ VPD

Appendix D

Prior Incident Flight Data Recorder Data for the Accident Airplane


Federal Express

MD-11, Jan 1994 Memphis Tr.



National Transportation Safety Board/ VPD

Federal Express



National Transportation Safety Board/ VPD

Appendix E

FedEx Tail Strike Awareness Information Bulletin

MD-11 TAIL STRIKE AWARENESS INFORMATION

INTRODUCTION

FedEx flight standards and flight training have developed an MD-11 tail strike awareness training program. The primary objective of this program is to improve awareness of the pilot controlled factors that affect pitching tendency after touchdown and to reinforce proper sink rate and bounce recovery technique. The program consists of a 30 minute briefing followed by 1 hour of simulator training. Tail strike awareness training has been incorporated into recurrent, initial, and transition training. All FedEx pilots currently qualified on the MD-11 will receive the training during their next recurrent event, i.e. warm up, pt, or loft.

The purpose of this document is to provide FedEx MD-11 pilots immediate access to the information gathered during the development of the tail strike awareness training program.

The airline industry has logged approximately 350,000 MD-11 landings to date. MD-11 tail strike incidents/accidents have occurred at a fairly constant rate (tail strikes/total landings). Approximately 25% of the industries MD-11 tail strikes occurred on takeoff and 75% on landing.

TAKEOFF

The recommended rotation technique is a 3 degree per second rotation to an initial pitch attitude of approximately 15 degrees. The pilot flying (PF) should then transition to the flight director pitch bar for guidance. The flight director pitch bar is not usable until approximately five seconds after nose gear strut extension. A two step rotation is not appropriate. Two step or segmented rotations will significantly impact takeoff performance, i.e. required runway, second segment climb gradients, and obstacle clearance. It is, however, the PF's responsibility to ensure that the aircraft is accelerating properly and has become airborne passing 10 degrees of pitch attitude. If the aircraft has not become airborne, possibly due to an inaccurate flap setting, stab setting, gross weight entry, or contaminated wing, the rotation should be stopped.

Some tail strikes on takeoff have occurred as a result of early or quick rotations. One tail strike occurred as a result of the pilot initiating a rotation at V1 vs. VR. Another tail strike occurred as a result of an inaccurate gross weight entry into the FMS which resulted in inaccurate V speeds.

LANDING

- Some of the factors that affect pitching tendency after touchdown are:

Flap setting	Strut servicing	Sink rate
Center of gravity	Ground spoilers	Pitch Attitude
Gross weight	Autobrakes	Pitch Attitude rate
		Airspeed

- Landing tail strikes have occurred with the following:

Flaps 35 and flaps 50
Forward and aft center of gravity
Light and heavy gross weight
Over serviced and correctly serviced struts

One consistent factor in every landing tail strike to date has been an excessive descent rate with an increasing pitch attitude rate prior to the initial touchdown.
Sink rates, pitch attitude, pitch attitude rate, and airspeed are pilot controlled factors that affect pitching tendency after touchdown and are the focus of the tail strike awareness training program.

- The following pilot actions may result in high sink rates prior to touchdown:

Unstable approach
Late or abrupt align maneuver
Early flare

- Stabilized approach

The aircraft should be fully configured, on speed (including appropriate wind and gust corrections applied to Vref) and on flight path by 1000 feet AGL. If the aircraft is not stabilized by 500 feet or if a sink rate of more than 1000 FPM develops, a missed approach should be executed.

Several tail strikes have occurred on visual approaches without the use of an electronic glideslope. Increased crew awareness and crew coordination during these types of approaches is critical.

- **Align maneuver**

The recommended method for a crosswind landing is to fly the final approach in a wing's level attitude with a crab into the wind. At approximately 200 feet AGL, align the fuselage with the runway by smoothly applying rudder pressure and lower the upwind wing to prevent drifting off runway centerline. In high crosswinds, consideration should be given to commencing the align maneuver prior to 200 feet, and in all cases, the align maneuver should be fully established by 100 feet AGL.

Some tail strikes have occurred as a result of the pilot initiating a late or abrupt align maneuver. The align maneuver, commonly referred to as a forward slip, will reduce lift and if unchecked with power, will result in an increased sink rate.

- **Flare**

The recommended flare technique is to maintain a stabilized flight path through the 50 and 40 foot CAWS callout (unless sink rate is high). At 30 feet a smooth 2.5 degree flare should be initiated so as to arrive below 10 feet in the landing attitude. Elevator back pressure should be relaxed, and a constant pitch attitude should be maintained from 10 feet radio altitude to touchdown.

Some tail strikes have occurred as a result of the pilot initiating an early flare and "feeling for the runway." It is critical that pilots understand the dynamics involved in this situation. The autothrottles switch to the retard mode at 50 feet radio altitude. In the retard mode, the throttles are retarded to idle at a pre-programmed rate without airspeed, vertical speed, or radio altitude bias. The pilot flying or the autopilot, if selected, must maintain the appropriate glide path to touchdown. If the aircraft is flared early and the autothrottles allowed to retard, the airspeed will decay, elevator effectiveness will be reduced, and a higher pitch attitude will be required making the pitch up tendency after touchdown more pronounced and more difficult to counteract.


Pilots must fully understand autothrottle retard logic. If the aircraft deviates from the appropriate glide path below 50 feet radio altitude, the PF must override the autothrottles.

HIGH SINK RATE AND BOUNCE RECOVERY TECHNIQUE


The recommended high sink rate and bounce recovery technique is to establish a 7 1/2 degree pitch attitude and arrest the sink rate with thrust. If a high bounce occurs, a go-around should be initiated. Low level go-arounds, i.e. less than 20 feet RA, are dramatically different than higher altitude go-arounds. High altitude go-arounds are initiated with pitch, while low level go-arounds must be initiated with thrust. During low level go-arounds main wheel touchdown may be unavoidable. The PF must not exceed 10 degrees of pitch or retract the landing gear until passing 20 feet RA with a positive rate of climb.

Some tail strikes have occurred as a result of the pilot attempting to arrest a high sink rate or bounce by quickly adding up elevator. This technique immediately increases both the effective weight of the aircraft and the aircraft's vertical velocity. The resulting increased attitude rate will aggravate the pitching tendency after touchdown and drive the main wheels into the ground, thus compressing the main wheel struts. The aft fuselage will contact the runway at approximately 10 degrees pitch attitude with the struts compressed.

It is imperative that pilots fully understand the correlation between an increasing attitude rate at touchdown and an increased pitch up tendency after touchdown. One degree per second of increasing attitude rate at touchdown generates as much pitch up tendency as full spoiler deployment. Elevator back pressure should be relaxed, and a constant pitch attitude should be maintained from 10 feet radio altitude to touchdown.



Captain Jim Ward
Manager MD-11 Flight Standards



Captain Warren Travis
Manager MD-11 Flight Training

Appendix F

FedEx Tail Strike Awareness Training Instructor's Guide

*MD-11 FLIGHT INSTRUCTOR GUIDE***TAIL STRIKE AWARENESS TRAINING**
CONTENTS

Instructor Notes	page 3
Briefing	page 5
Introduction.....	page 5
Takeoff.....	page 5
Landing	page 6
High Sink Rate and Bounce Recovery	page 8
Quick Setup Values	page 10
Training Device	page 11

TAIL STRIKE AWARENESS TRAINING

INSTRUCTOR NOTES

BRIEFING 30 MINUTES
TRAINING DEVICE 1 HOUR
DEBRIEF 30 MINUTES

OBJECTIVE

The primary objective of tail strike awareness training is to improve awareness of the pilot controlled factors that affect pitching tendency after touchdown and to reinforce proper sink rate and bounce recovery technique.

This training may be accomplished as part of recurrent, initial, or transition training.

REQUIRED SIGN OFF

Note completion by a remark "Tail Strike Awareness Training Accomplished" in the remarks section of the 007 or 007A.

*MD-11 FLIGHT INSTRUCTOR GUIDE***TAIL STRIKE AWARENESS**
BRIEFINGINTRODUCTION

- MD-11 tail strike incidents/accidents have occurred at a fairly constant rate (tail strikes/total landings).
- 25% of MD-11 tail strikes to date have occurred on takeoff and 75% on landing.

TAKEOFF

The recommended rotation technique is a 3 degree per second rotation to an initial pitch attitude of approximately 15 degrees. The PF should then transition to the flight director pitch bar for guidance. The flight director pitch bar is not usable until approximately five seconds after nose gear strut extension. A two step rotation **is not** appropriate. Two step or segmented rotations will significantly impact takeoff performance i.e. required runway, second segment climb gradients, and obstacle clearance. It is, however, the PF's responsibility to ensure that the aircraft is accelerating properly and has become airborne passing 10 degrees of pitch attitude. If the aircraft has not become airborne, possibly due to an inaccurate flap setting, stab setting, gross weight entry, or contaminated wing, the rotation should be stopped.

Some tail strikes on takeoff have occurred as a result of early or quick rotations. One tail strike occurred as a result of the pilot initiating a rotation at V1 vs. VR. Another tail strike occurred as a result of an inaccurate gross weight entry into the FMS which resulted in inaccurate V speeds.

MD-11 FLIGHT INSTRUCTOR GUIDE

LANDING

- Some of the factors that affect pitching tendency after touchdown are:

Flap setting	Strut servicing	Sink rate
Center of gravity	Ground spoilers	Attitude
Gross weight	Autobrakes	Attitude rate

- Tail strikes have occurred with the following:

Flaps 35 and flaps 50
Forward and aft center of gravity
Light and heavy gross weight
Over serviced and correctly serviced struts

One consistent factor in every landing tail strike to date has been an excessive descent rate with an increasing attitude rate prior to the initial touchdown. Sink rates, aircraft attitude, and attitude rate are pilot controlled factors that affect pitching tendency after touchdown and will be the focus of this training program.

- The following pilot actions may result in high sink rates prior to touchdown:

Unstable approach
Late or abrupt forward slip maneuver
Early flare

- Unstable approach

The aircraft should be fully configured, on speed (including appropriate wind and gust corrections applied to Vref) and on flight path by 1000 feet AGL. If the aircraft is not stabilized by 500 feet or if a sink rate of more than 1000 FPM develops, a missed approach should be executed.

Several tail strikes have occurred on visual approaches without the use of an electronic glideslope. Increased crew awareness and crew coordination during these types of approaches is critical.

MD-11 FLIGHT INSTRUCTOR GUIDE

- **Late or abrupt forward slip maneuver**

The recommended method for a crosswind landing is to fly the final approach in a wing's level attitude with a crab into the wind. At approximately 200 feet AGL, align the fuselage with the runway by smoothly applying rudder pressure and lower the upwind wing to prevent drifting off runway centerline. In high crosswinds, consideration should be given to commencing the forward slip maneuver prior to 200 feet, and in all cases, the forward slip should be fully established by 100 feet AGL.

Some tail strikes have occurred as a result of the pilot initiating a late or abrupt align maneuver. The align maneuver, commonly referred to as a forward slip, will reduce lift and if unchecked, will result in an increased sink rate. This will be demonstrated in the simulator.

- **Early flare**

The recommended flare technique is to maintain a stabilized flight path through the 50 and 40 foot CAWS callout (unless sink rate is high). At 30 feet a smooth 2.5 degree flare should be initiated so as to arrive below 10 feet in the landing attitude. Back pressure should then be relaxed until touchdown.

Some tail strikes have occurred as a result of the pilot initiating an early flare and "feeling for the runway." It is critical that pilots understand the dynamics involved in this situation. The autothrottles switch to the retard mode at 50 feet radio altitude. In the retard mode, the throttles are retarded to idle at a pre-programmed rate without airspeed, vertical speed, or radio altitude bias. The pilot flying or the autopilot, if selected, must maintain the appropriate glide path to touchdown. If the aircraft is flared early, the airspeed will decay, elevator effectiveness will be reduced, and a higher pitch attitude will be required making the pitch up tendency after touchdown more pronounced and more difficult to counteract. This will be demonstrated in the simulator.

MD-11 FLIGHT INSTRUCTOR GUIDE

HIGH SINK RATE AND BOUNCE RECOVERY TECHNIQUE

The recommended high sink rate and bounce recovery technique is to establish a 7 1/2 degree pitch attitude and arrest the sink rate with thrust. If a high bounce occurs, a go-around should be initiated. Low level go-arounds, i.e. less than 20 feet RA, are dramatically different than higher altitude go-arounds. High altitude go-arounds are initiated with pitch, while low level go-arounds must be initiated with thrust. During low level go-arounds main wheel touchdown may be unavoidable. The PF must not exceed 10 degrees of pitch or retract the landing gear until passing 20 feet RA with a positive rate of climb.

Some tail strikes have occurred as a result of the pilot attempting to arrest a high sink rate or bounce by quickly adding up elevator. This technique immediately increases both the effective weight of the aircraft and the aircraft's vertical velocity. The resulting increased attitude rate will aggravate the pitching tendency after touchdown and drive the main wheels into the ground, thus compressing the main wheel struts. The aft fuselage will contact the runway at approximately 10 degrees pitch attitude with the struts compressed. This will be demonstrated in the simulator.

*MD-11 FLIGHT INSTRUCTOR GUIDE***TAIL STRIKE AWARENESS TRAINING****QUICK SETUP VALUES**

Location	KMEM Runway 27
Gross Weight	450,000
Fuel	150,000
ZFW	300,000
ZFWCG	28.6
Altimeter	29.80
Visual	Day
Ceiling	Clear
Visibility	48NM
Temperature	58 F
Wind	270/30

SIMULATOR SETUP**APU power on the aircraft****All quantities normal****All system controllers auto****ATIS**

This is Memphis international airport information MIKE, the ____ zulu observation, sky clear, visibility 48, temperature 58, dewpoint 40, wind 270 degrees at 30 knots, altimeter 29.80, departing runway 27, advise the controller on initial contact that you have received information Mike.

*MD-11 FLIGHT INSTRUCTOR GUIDE***TAIL STRIKE AWARENESS TRAINING**
TRAINING DEVICE

- **Instructor note.**

In order to make maximum utilization of simulator time, tail strike awareness simulator periods have no preflight/cockpit setup. The instructor will have the simulator fully configured for takeoff prior to the students arrival, i.e. on the active runway, all engines started, fms loaded (KMEM to KDFW) and the before takeoff checklist complete to the line.

Tail strike awareness simulator training is comprised of three individual scenarios. Each scenario is designed to demonstrate a specific pilot controlled factor that affects pitching tendency after touchdown.

BEFORE TAKEOFF

- **Review before takeoff checklist below the line.**
- **Save flight plan if able.**

TAKEOFF

- **Review normal takeoff procedures.**
- **Reinforce proper rotation technique.**

The recommended rotation technique is a 3 degree per second rotation to an initial pitch attitude of approximately 15 degrees. The PF should then transition to the flight director pitch bar for guidance. The flight director pitch bar is not usable until approximately five seconds after nose gear strut extension. A two step rotation is not appropriate. Two step or segmented rotations will significantly impact takeoff performance i.e. required runway, second segment climb gradients, and obstacle clearance. It is, however, the PF's responsibility to ensure that the aircraft is accelerating properly and has become airborne passing 10 degrees of pitch attitude. If the aircraft has not become airborne, possibly due to an inaccurate flap setting, stab setting, gross weight entry, or contaminated wing, the rotation should be stopped.

AFTER TAKEOFF

- **Review normal after takeoff procedures.**

APPROACH AND LANDING

- **Vector the aircraft for an ILS to 36L.**

Multiple resets to the 6 NM final to runway 36L will be used as a time management tool. To eliminate the need for time consuming FMS programming, the runway 36L ILS (IOHN/358) should be hard tuned, and both NDs should display raw data.

MD-11 FLIGHT INSTRUCTOR GUIDE

FORWARD SLIP SCENARIO

- **Instructor note.**

The primary objective of this scenario is to demonstrate that a forward slip will reduce lift, and if unchecked, will result in an increased sink rate. Ideally, this demonstration will impress upon your students the need to commence the forward slip prior to 200 feet in a high crosswind and, in all cases, to have the forward slip fully established by 100 feet AGL.

The setup for this demonstration is as follows:

Position	6 NM final
Init runway	36L
Visual	Day
Ceiling	Clear
Visibility	48NM
Wind	270/30
AP and ATS	Engaged
Instructor station	APPR PROG displayed

It is imperative that this scenario commence from a fully stabilized condition. The AP and ATS must be engaged and the FGS programed to fly the ILS. At 1000 feet AGL the AP and ATS should be disconnected. The PF should take their hands off the throttles and accomplish an aggressive forward slip. At 500 feet AGL, the demonstration is complete, and the simulator should be repositioned to the 6 NM point. The instructor should now direct the pilots attention to the APPR PROG display on the instructor station and point out the inevitable dip below glideslope that occurred when the forward slip maneuver was initiated. This is a classic example of how a high sink rate can develop prior to touchdown.

Repeat this demonstration with the other pilot flying.

MD-11 FLIGHT INSTRUCTOR GUIDE

EARLY FLARE SCENARIO

- **Instructor note.**

The primary objective of this scenario is to demonstrate the dynamics of an early flare. The autothrottles switch to the retard mode at 50 feet radio altitude. In the retard mode, the throttles are retarded to idle at a pre-programmed rate without airspeed, vertical speed, or radio altitude bias. The pilot flying or the autopilot, if selected, must maintain the appropriate glide path to touchdown. If the aircraft is flared early, the airspeed will decay, elevator effectiveness will be reduced, and a higher pitch attitude will be required making the pitch up tendency after touchdown more pronounced and more difficult to counteract. Ideally this demonstration will increase the pilots understanding of the correlation between a high pitch attitude at touchdown and an increased pitch up tendency after touchdown. Additionally, ATS retard logic will be stressed to encourage overriding the autothrottles when needed.

The setup for this demonstration is as follows:

Position	6 NM final
Init runway	36L
Visual	Day
Ceiling	Clear
Visibility	48NM
Wind	Calm
AP and ATS	Engaged

The AP and ATS should be engaged and the FGS programed to fly the ILS. At 1000 feet AGL the AP should be disconnected. The PF should take their hands off the throttles for the remainder of this demonstration. The PF should be directed to make a normal descent until 40 feet RA, where an early flare should be commenced. The PNF should be directed to call out RA and pitch attitude. The PF should make every effort to remain at or above 20 feet RA until the PNF calls 10 degrees of pitch attitude. The PF should then allow a sink rate to develop. At touchdown the instructor will move the spoiler handle to the GROUND SPOILER position. The pitch up tendency will be pronounced and difficult to counteract.

Reposition the simulator to the 6 NM point.

The second part of this demonstration is set up identical to the first except this time the PF should make a normal descent with only a slight flare prior to touchdown. The landing attitude should be less than 5 degrees resulting in little or no pitch up tendency after touchdown.

Repeat this demonstration with the other pilot flying.

MD-11 FLIGHT INSTRUCTOR GUIDE

HIGH SINK RATE AND BOUNCE RECOVERY DEMONSTRATION

- **Instructor note.**

The primary objective of this scenario is to demonstrate proper sink rate and bounce recovery technique. Ideally, this demonstration will increase the pilot's awareness of the correlation between an increasing pitch attitude rate at touchdown and an increased pitch up tendency after touchdown. Additionally, Captains will be trained to recognize and recover from a high sink rate or bounce when the First Officer is flying.

To ensure a consistent and standardized presentation, the instructor will sit in a flying seat and set up the high sink rate and bounce.

The setup for this demonstration is as follows:

Position	6 NM final
Init runway	36L
Visual	Day
Ceiling	Clear
Visibility	48NM
Wind	Calm
AP and ATS	Engaged

The instructor will first fly the sim from the left seat. The Captain will observe from the instructor station. The AP and ATS should be engaged and the FGS programed to fly the ILS. At 1000 feet AGL the instructor will disconnect the AP and set up the high sink rate and bounce as follows:

At 100 feet RA go high on glideslope
Pull the throttles back to idle
Push over to establish a high sink rate
Ideally, a GPWS warning will activate
Just prior to touchdown establish an increasing pitch attitude rate
Ideally, the aircraft will touch down and bounce less than 20 feet
Transfer control after the bounce by saying, "*You have the airplane.*"

The First Officer should establish a 7 1/2 degree pitch attitude and arrest the sink rate with thrust. Re-accomplish this demonstration until proficiency has been achieved.

The instructor will now fly the sim from the right seat. The First Officer will observe from the instructor station.

Repeat the demonstration until proficiency has been achieved.

MD-11 FLIGHT INSTRUCTOR GUIDE

- **Instructor note.**

The final phase of tail strike awareness training is designed to improve the Captain's ability to recognize and recover from a high sink rate or bounce when the First Officer is flying. Analyses of some tail strikes that have occurred while the First Officer was flying has shown that the Captain did not take control of the aircraft or did not make a positive transfer of control resulting in both pilots manipulating the flight controls.

Ideally, the Captain should now be able to recognize the pilot controlled factors that will cause an increased pitch up tendency after touchdown, specifically:

- High sink rate
- High aircraft attitude
- Increasing attitude rate

In the final phase of the high sink rate and bounce recovery demonstration, the instructor will set up the high sink rate, and the Captain should make a positive transfer of control by saying, "*I have the airplane,*" as soon as he recognizes the situation developing. The Captain should establish a 7 1/2 degree pitch attitude and arrest the sink rate with thrust. If a high bounce occurs, a go-around should be initiated. Low level go-arounds, i.e. less than 20 feet RA, are dramatically different than higher altitude go-arounds. High altitude go-arounds are initiated with pitch, while low level go-arounds must be initiated with thrust. During low level go-arounds main wheel touchdown may be unavoidable. The PF must not exceed 10 degrees of pitch or retract the landing gear until passing 20 feet RA with a positive rate of climb.

ERRATA

**THESE CORRECTIONS SHOULD BE MADE
TO THE PREVIOUSLY PUBLISHED REPORT
IDENTIFIED AS FOLLOWS:**

AIRCRAFT ACCIDENT REPORT

UNCONTROLLED DESCENT AND COLLISION WITH TERRAIN

USAIR FLIGHT 427

BOEING 737-300, N513AU

NEAR ALIQUIPPA, PENNSYLVANIA

SEPTEMBER 8, 1994


NTSB/AAR-99/01 (PB99-910401)

Pages 29 and 31, figures 9 and 10: The pictures for these figures were reversed, but figure numbers and captions were correct. The picture on page 31 should be located on page 29 and paired with the figure 9 caption, and the picture on page 29 should be located on page 31 and paired with the figure 10 caption. *(4 Nov 99)*

Page 45, third complete paragraph, line 5: The ending quotation mark for one of the first officer's comments (United flight 585) was misplaced. Revise the text to read: officer said "wow" about 0943:08 and "we're at a thousand feet" at 0943:28.2. *(4 Nov 99)*

Page 102, first paragraph, lines 1 and 2: The figure references for the United flight 585 simulations on roll and yaw rate are incorrect. Revise the text to read: "...are presented in figures 22h and 22i, respectively, for the 100-percent jam case." *(16 Feb 00)*

**CORRECTED PAGES ARE ATTACHED
AND ARE INCLUDED IN THE ONLINE VERSION
OF THE PUBLICATION**



Note: The maximum 737 rudder deflection that the yaw damper can command is only a small portion of the total rudder travel. Yaw damper limits of the 737-100 and -200 can be 2, 3, or 4°, depending upon the installation.

Figure 9. Boeing 737-300, -400 and -500 rudder, rudder trim, and yaw damper authority limits.

1.6.3.2.1 Main Rudder PCU and Servo Valve

The main rudder PCU is powered by hydraulic systems A and B, each of which provides about 3,000 pounds of output force to move the rudder, for a total output force of about 6,000 pounds. The main rudder PCU operates by converting either a mechanical input from the rudder pedals or an electrical signal from the yaw damper system into motion of the rudder by means of mechanical linkages (summing levers, input cranks, and shafts) and a servo valve that directs hydraulic fluid either to extend or retract the PCU actuator rod that moves the hinged rudder surface.

The body of the main rudder PCU is attached to the airplane vertical fin structure, and the actuating rod is attached to the rudder. The PCU moves the rudder right or left when actuated by rudder pedal or trim input or signals from the yaw damper. Rudder pedal and trim input are transmitted to the PCU's external input crank through an external summing lever and linkage. The external input crank is also moved by feedback from motion of the rudder, which comes from a mechanical system linkage (see figure 8). The input shaft rotates, actuating the internal summing levers and moving the primary and secondary slides of the servo valve.

The 737 main PCU servo valve was designed by Boeing and is manufactured to Boeing specifications by Parker Hannifin Corporation. It is a dual-concentric tandem valve composed of a primary slide that moves within a secondary slide that, in turn, moves within the servo valve housing. The primary and secondary concentric slides are moved by primary and secondary internal summing levers, which translate inputs from the yaw damper⁵⁸ and/or the external input crank (which moves when a pilot steps on the rudder pedals) into axial movement of the slides. Figure 10 shows an expanded view of the servo valve.

When rudder motion is commanded (by the yaw damper, rudder pedal input, and/or rudder trim), the internal input shaft moves the servo valve slides through the internal summing levers to connect hydraulic pressure and return circuits from hydraulic systems A and B so that hydraulic pressure is ported to the appropriate sides of the dual-tandem actuator piston to extend or retract⁵⁹ the main rudder PCU piston rod. At the same time, fluid is directed from the other side of the piston to the hydraulic return system. As the

⁵⁸ When the yaw damper solenoid control valve is energized, 3,000 psi of hydraulic pressure is applied to the transfer valve, which proportionally converts electrical signals from the yaw damper coupler into hydraulic flow and control pressure. The control pressure moves the yaw damper actuator assembly piston (mod piston), which moves the pivot point of the internal summing levers. The internal summing levers move the primary and secondary slides of the servo valve from neutral, which causes movement of the pistons in the actuator assembly. Movement of the yaw damper actuator piston generates a balancing signal by the LVDT, which assists in returning the transfer valve to the neutral position. Feedback, provided through the external summing lever and linkage, returns the slides of the servo valve to near neutral, which maintains hydraulic pressure to hold the actuator position against the air load while not commanding further motion.

⁵⁹ When the actuator moves in the extend direction, it commands left rudder; when it moves in the retract direction, it commands right rudder.




Figure 10. Boeing 737 main rudder PCU servo valve.

rudder reaches the commanded deflection, external linkages reposition the servo valve's internal summing levers to nullify the initial command signal and arrest further motion.

During normal operation, the primary summing lever applies force to move the primary slide, and the secondary summing lever applies force to move the secondary slide as needed. The primary slide is normally displaced first, and the secondary slide is displaced only when the primary slide does not provide enough hydraulic flow to keep up with the input commanded by the pilots or the yaw damper (that is, when the movement of only the primary slide is not sufficient to move the rudder at the commanded rate). The normal maximum axial movement from the neutral positions to the extreme travel positions in either the extend or retract directions is about 0.045 inch for both the primary and secondary slides, for a combined distance of about 0.090 inch. Both the primary and secondary slides are designed so that they can move about 0.018 inch axially beyond their normal operating range (overtravel capability).

The two slides are designed to provide approximately equal flow. Thus, the primary slide alone can provide a rudder rate of about 33° per second, and the primary and secondary slides together can provide a rudder rate of about 66° per second (under zero aerodynamic load conditions).

The outside diameter surfaces of the primary and secondary slides are composed of Nitralloy 135 that, in its prefinished form (slightly larger in diameter than its finished form), is nitrided⁶⁰ to a depth from 0.005 to 0.008 inch to a surface hardness of 55 to 58 on

⁶⁰ Nitriding is a process in which the surface of the part is impregnated with nitrogen to increase hardness.

the ground about 0943:42.⁸³ All 25 people aboard the airplane were killed, and the airplane was destroyed by impact forces and postcrash fire.

When the accident sequence began (CVR and FDR evidence indicated that the upset began about 0943:32), the airplane was operating at 160 knots with flaps extended to 30° and the landing gear extended. CVR and meteorological information indicated that the pilots of United flight 585 were conducting a visual approach to the runway in moderate-to-severe turbulence and gusty wind conditions; low-level windshear was reported.

The United flight 585 CVR indicated that, as the pilots prepared for the approach to the destination airport, they discussed the strong gusty winds and windshear conditions they expected to encounter during the approach, airspeed adjustments to compensate for those conditions, and missed approach procedures. The captain was performing the PF duties, and the first officer was performing PNF duties. About 0938:14, the first officer requested information from ATC regarding pilot reports concerning loss or gain of airspeed. About 0939:26, when the airplane was on a southerly heading and had just passed abeam (and to the east) of the end of runway 35, the CVR recorded the captain saying "...we're not gonna be in a rush...we want to stabilize it out here..." The first officer responded, "yeah, I feel the same way." About 0940:44, while the first officer was busy completing a checklist, the captain requested additional information from ATC regarding traffic. The pilots began a series of right turns toward the (northbound) final approach. They incrementally extended flaps, extended the landing gear, and accomplished the final descent checklist. Figure 11 shows a plot of United flight 585's ground track based on FDR and radar data.

As the pilots began to align the airplane with the final approach course, the airplane was experiencing airspeed changes (± 10 knots) and rapid heading changes.⁸⁴ About 0942:29, 0942:31, and 0943:01, the CVR recorded the flight crew stating information related to uncommanded airspeed changes. According to the CVR, the first officer said "wow" about 0943:08 and "we're at a thousand feet" at 0943:28.2. At 0943:32.6, the CVR recorded the first officer exclaiming "oh god;" less than 1 second later (at 0943:33.5), the captain stated "fifteen flaps," and the first officer responded "fifteen." The CVR sound spectrum study indicated that the sounds before impact were consistent with both engines accelerating.⁸⁵

FDR data indicated that United flight 585 began a sharp heading change to the right and a sudden descent about the time the captain called for "fifteen flaps." The CVR recorded the first officer stating "oh" at 0943:34.4 and the captain exclaiming "oh" loudly at 0943:34.7. One second later, the first officer and the captain each stated "[expletive]"

⁸³ All times in this subsection are mountain standard time, based on a 24-hour clock. The CVR time equals FDR time in seconds plus 0941:55 (local mountain standard time).

⁸⁴ The FDR installed on United flight 585, a Fairchild Digital Flight Recorder Model F800 (S/N 4016), directly recorded five parameters. Altitude, indicated airspeed, magnetic heading, and microphone keying versus time were recorded at once per second, and vertical acceleration was recorded eight times per second. The Safety Board conducted simulation studies to derive additional flight-related information from the FDR and radar data (see section 1.16.6).

performance, are presented in the figures 22h and 22i, respectively, for the 100-percent jam case. CVR data are presented on figures 22f, 22g, and 22i to correlate verbal responses of the pilots to simulated pitch angle, bank angle, and yaw rate, respectively. Wind direction and horizontal and vertical windspeeds used in the Safety Board's best-match scenario are presented in figures 22j through 22l, respectively.




Figure 22a. Pilot rudder pedal force positions for United flight 585.