



to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering the collection of information. Send comments regarding this burden estimate or any other aspect of this form, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Avenue, Washington, DC 20540.

1. AGENCY USE ONLY (Leave blank)	2. REPORT DATE 10/00/91	3. REPORT TYPE AND DATES COVERED	
4. TITLE AND SUBTITLE QUARTERLY WATER-LEVEL MONITORING REPORT, OTHER CONTAMINATION SOURCES, INTERIM RESPONSE ACTION, SOUTH TANK FARM PLUME			5. FUNDING NUMBERS 1
6. AUTHOR(S)			8. PERFORMING ORGANIZATION REPORT NUMBER 91275R01
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) MORRISON-KNUDSEN CORPORATION DENVER, CO		9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES) SHELL OIL COMPANY DENVER, CO	
11. SUPPLEMENTARY NOTES		10. SPONSORING/MONITORING AGENCY REPORT NUMBER	
12a. DISTRIBUTION/AVAILABILITY STATEMENT APPROVED FOR PUBLIC RELEASE; DISTRIBUTION IS UNLIMITED		12b. DISTRIBUTION CODE	
13. ABSTRACT (Maximum 200 words) SHELL 1991 QUARTERLY WATER-LEVELS WILL BE MEASURED IN AND BEYOND THE SOUTH TANK PLUME AREA. THE OBJECTIVE OF THE WATER-LEVEL MEASUREMENT PROGRAM IS TO COLLECT SUFFICIENT INFORMATION TO MONITOR ANY TEMPORAL HYDROGEOLOGIC CHANGES OCCURRING AND WHAT EFFECT THEY MAY HAVE ON THE STEP. THIS REPORT PROVIDES THE RESULTS OF THE MOST RECENT MONITORING EVENT, COMPLETED SEPT 13, 1991.			
14. SUBJECT TERMS LAKES, LAKE LADORA, LAKE DERBY			15. NUMBER OF PAGES
17. SECURITY CLASSIFICATION UNCLASSIFIED			16. PRICE CODE
18. SECURITY CLASSIFICATION OF THIS PAGE	19. SECURITY CLASSIFICATION OF ABSTRACT	20. LIMITATION OF ABSTRACT	

DTIC
SELECTED
NOV 14 1994
F

94-35039

173

DTIC QUALITY INSPECTED 1

94 11 10 00 9
60 01 11 46

INTRODUCTION

As described in the Final Implementation Document for the South Tank Farm Plume (STFP) Interim Response Action (IRA) (Shell 1991), quarterly water-levels will be measured in and beyond the STFP area. The objective of the water-level measurement program is to collect sufficient information to monitor what, if any, temporal hydrogeologic changes may be occurring and what effect they may have on the STFP. This report provides the results of the most recent monitoring event, completed September 13, 1991.

RESULTS

The results of the September 1991 water-level measurements are illustrated by the water table contour map shown by Figure 1. The general groundwater hydrology has changed since June 1991 (Figure 2), as shown on Figure 3 which gives the change in water-level for each well. However, the groundwater flowpaths have not changed, nor has the effect of Lake Ladora on the local groundwater.

Water-levels in the tank farm have risen over 2 feet since the last quarter. This increase in water table elevation is most likely due to a combination of the heavy precipitation which has occurred during the summer and a water line break which occurred near Building 316A in August and was not repaired until mid-September.

Water-levels in Lower Derby Lake and the wells adjacent to the lake have declined since last quarter. This is due to the lowering of the lake in order that repairs to sections of rip-rap may be made. The Army started lowering the lake in early September.

The most recent water-levels in Lake Ladora and the wells nearest the lake exhibit similar patterns to those observed during June and July 1991 (Figures 4 through 10). Water-levels in this area have increased slightly (less than 0.5 feet) since last quarter due to the heavy precipitation received during this summer. At the beginning of August, Sand Creek Lateral was full of flowing water along the entire length of Lake Ladora. In addition, Figure 11 shows that the Army has been maintaining the level of Lake Ladora at an elevation of approximately 5220 feet or above.

CONCLUSIONS


While water-levels vary from last quarter's measurements, the hydrogeologic conditions have not significantly changed within and around the STFP area. There are no hydrologic effects which indicate the STFP will impact Lake Ladora. Therefore, regular monitoring, as outlined in the Final Implementation Document, remains the appropriate course of action for this IRA.

REFERENCES

Shell Oil Company, August 1991, Final Implementation Document, Other Contamination Sources Interim Response Action, South Tank Farm Plume

Legend

- Existing Well Location
- ◇ Existing Cluster Well Location
- Water Level Location
- - - Drainage
- ==== Railroad
- - - Section Boundary
- ▨ Lakes
- Building/Structure
- Berm
- 5245.5 Water Level Elevation (Feet above MSL)
- - - Contour Interval Dashed where Inferred


north



0 250 500 1000
 FEET

**ROCKY MOUNTAIN ARSENAL
 South Tank Farm Area**

Figure 1

Water Table
 Contour Map
 September 13, 1991

 MORRISON KNUDSEN CORPORATION
 ENGINEERING, ARCHITECTURE, CONSTRUCTION



Legend


- Existing Well Location
- ◇ Existing Cluster Well Location
- Water Level Location
- Drainage
- Railroad
- - - Section Boundary
- ▨ Lakes
- Building/Structure
- Berm
- 5245.5 Water Level Elevation (Feet above MSL)
- - - Contour Interval Dashed where Inferred



**ROCKY MOUNTAIN ARSENAL
South Tank Farm Area**

Figure 2

Water Table
Contour Map
June 1991



Legend


- Existing Well Location
- ⊕ Existing Cluster Well Location
- Water Level Location
- - - Drainage
- ⊕⊕⊕ Railroad
- - - Section Boundary
- ▨ Lakes
- Building/Structure
- Berm
- 0.50 Change in Water Table Elevation in Feet (Negative for Decrease)
- - - Above this line Water Table Elevation Increased more than 2 Feet.
- - - Below this line, Water Table Elevations Decreased



**ROCKY MOUNTAIN ARSENAL
South Tank Farm Area**

Figure 3

Change in Water Table Elevations Between June 1991 and September 1991



**FIGURE 4
WATER LEVELS NEAR LAKE LADORA**





FIGURE 5
WATER LEVELS NEAR LAKE LADORA



**FIGURE 6
WATER LEVELS NEAR LAKE LADORA**





FIGURE 7
WATER LEVELS NEAR LAKE LADORA



**FIGURE 8
WATER LEVELS NEAR LAKE LADORA**






FIGURE 9
WATER LEVELS NEAR LAKE LADORA



—□— 09/13/91

FIGURE 10
WATER LEVELS NEAR LAKE LADORA



**FIGURE 11
LAKE LADORA SURFACE ELEVATIONS**

