REPORT DOCUMENTATION PAGE

Form Approved
OMB No. 0704-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing this collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to Department of Defense, Washington Headquarters Services, Directorate for Information Operations and Reports (0704-0188), 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number. **PLEASE DO NOT RETURN YOUR FORM TO THE ABOVE ADDRESS.**

1. REPORT DATE *(DD-MM-YYYY)*
09-05-2022

2. REPORT TYPE
Historical Release

3. DATES COVERED *(From - To)*
16 June 1965

4. TITLE AND SUBTITLE
Test Report XB-70A Flight 1-13

5a. CONTRACT NUMBER

5b. GRANT NUMBER

5c. PROGRAM ELEMENT NUMBER

5d. PROJECT NUMBER

5e. TASK NUMBER

5f. WORK UNIT NUMBER

6. AUTHOR(S)
Joseph Cotton
Guy Townsend
Ira Plummer

7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) AND ADDRESS(ES)
AFTC/HO
305 Popson Ave
Edwards AFB CA 93524

8. PERFORMING ORGANIZATION REPORT NUMBER
412TW-PA-22165

9. SPONSORING / MONITORING AGENCY NAME(S) AND ADDRESS(ES)
412th Test Wing
195 E Popson Ave
Edwards AFB CA 93524

10. SPONSOR/MONITOR'S ACRONYM(S)
N/A

11. SPONSOR/MONITOR'S REPORT NUMBER(S)

12. DISTRIBUTION / AVAILABILITY STATEMENT
Approved for public release Distribution Statement A: distribution is unlimited.

13. SUPPLEMENTARY NOTES
Source Code 012100 (This number comes from STINFO via EAFB Technical Library)
CA: 412th Test Wing, Edwards AFB, CA

14. ABSTRACT
The thirteenth flight (Flt. 1-13) of the XB-70, 62-001-was scheduled four times (for 21 May, 24 May, 27 May and 16 June) before satisfactory completion on 16 June. The aircraft was not ready for flight due to uncompleted Flt. 1-12 repairs on 21 May and the 24 May schedule was cancelled on 22 May due to inoperative No. 3 fuel tank boost pumps and high No. 3 engine vibrations. Air Force Quality Assurance grounded the aircraft on 27 May for excessive fuel leaks. The engines were running preparatory to flight at the time of grounding.

15. SUBJECT TERMS

16. SECURITY CLASSIFICATION OF:			**17. LIMITATION OF ABSTRACT**	**18. NUMBER OF PAGES**	**19a. NAME OF RESPONSIBLE PERSON**
Unclassified			None	35	412 TENG/EN (Tech Pubs)
a. REPORT	**b. ABSTRACT**	**c. THIS PAGE**			**19b. TELEPHONE NUMBER** *(include area code)*
Unclassified	Unclassified	Unclassified			661-277-8615

Standard Form 298 (Rev. 8-98)
Prescribed by ANSI Std. Z39.18