


NO-A152 540


MM2 LRSLA TESTING STAGE III PROPELLANT(U) OGDEN AIR
LOGISTICS CENTER HILL AFB UT PROPELLANT LAB SECTION
E M DALABA JAN 85 MANPA-501(85)

1/2

UNCLASSIFIED

F/G 21/8.2 NL





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963 A

HEADQUARTERS
OGDEN AIR LOGISTICS CENTER
UNITED STATES AIR FORCE
HILL AIR FORCE BASE, UTAH 84056


AD-A152 540

MM2 LRSLA TESTING
STAGE III PROPELLANT

PROPELLANT LAB SECTION

MANPA REPORT
NR 501(85)

January 1985




APPROVED FOR PUBLIC RELEASE, DISTRIBUTION UNLIMITED

85 03 28 182


DTIC FILE COPY

MM2 LRSLA TESTING
STAGE II PROPELLANT

Author


ELIZABETH M. DALABA, Chemist
Component & Combustion Test Unit

Engineering & Statistical Review By



JOHN K. SCAMBIA, Project Engineer
Engineering & Reliability Branch


EDWARD ERICKSON, Mathematician
Data Analysis Unit

Recommended Approval By


DAN TANAKA, Chief
Propellant Test Units

Approved By


ANTHONY J. INVERSO, Chief
Propellant Analysis Laboratory

January 1985

Directorate of Maintenance
Ogden Air Logistics Center
United States Air Force
Hill Air Force Base, Utah 84056

ABSTRACT

Data in this report is a continuation of LRSIA testing on Stage III Dissected Motors. Problems in testing C-7 bonds were not alleviated by changing specimen size as previously suggested.

The data variation that has been observed has prompted a closer analysis of testing for variance.

The plotted points used on the regression plots are a combined average of test results at a designated test period.

The data variance within test periods is now demonstrated with the addition of separating the test results into individual plotted points on the regressions for each test period.

Data variance between motors is demonstrated by the use of unique motor plot symbols in the multi-motor regressions. These unique symbols are data mean values and the number of samples per mean can be found with its minimum and maximum values in the sample size summary.

Statistically, these multi-motor regressions are inappropriate for analysis use and should be used for visual display only to show motor-to-motor relationship.

*Additional Requirements:
Solid preparation method;
regression analysis; stress relaxation;
endurance; fracture toughness;
tensile testing; Maintenance.*



By	
Distribution	
Availability	
Dist	
AV	

TABLE OF CONTENTS

<u>Section</u>		<u>Page</u>
	Abstract	ii
	List of Figures	iv
I	Introduction	1-1
	Statistical Analysis	1-2
II	Stress Relaxation	2-1
III	Hardness	3-1
IV	Tensile Testing	4-1
V	Fracture Toughness	5-1
VI	Short Beam Shear Aft-Boot-to-Flap	6-1
VII	Summary and Recommendation	7-1
	Distribution List	8-1
	DD 1473	8-2

LIST OF FIGURES

<u>Figure Nr</u>		<u>Page</u>
	Regression Plot, Stress Relaxation, 2% Strain	
2-1	Modulus at 10 sec	2-2
2-2	Modulus at 50 sec	2-4
2-3	Modulus at 100 sec	2-6
2-4	Modulus at 1000 sec	2-8
	Regression Plot, Hardness, Shore A	
3-1	Multi-motor	3-2
3-2	Motor 0031064	3-4
3-3	Motor 0031134	3-6
3-4	Motor 0032434	3-8
3-5	Motor 0032831	3-10
3-6	Motor 0033174	3-12
	Regression Plot, Hardness, Shore C	
3-7	Multi-motor	3-14
3-8	Motor 0031064	3-16
3-9	Motor 0031134	3-18
3-10	Motor 0032434	3-20
3-11	Motor 0032831	3-22
3-12	Motor 0033174	3-24
	Regression Plot, Tensile, 2.0 in/min, Multi-motor	
4-1	Maximum Stress	4-3
4-2	Strain at Max Stress	4-4
4-3	Strain at Rupture	4-5
4-4	Stress at Rupture	4-6
4-5	Modulus	4-7

LIST OF FIGURES (cont)

<u>Figure Nr</u>		<u>Page</u>
	Regression Plot, Tensile, 2.0 in/min, Motor 0031064	
4-6	Maximum Stress, Mean Point Data	4-8
4-7	Strain at Max Stress, Mean Point Data	4-10
4-8	Strain at Rupture, Mean Point Data	4-12
4-9	Stress at Rupture, Mean Point Data	4-14
4-10	Modulus, Mean Point Data	4-16
4-11	Maximum Stress, Individual Data Point	4-18
4-12	Strain at Max Stress, Individual Data Point	4-19
4-13	Strain at Rupture, Individual Data Point	4-20
4-14	Stress at Rupture, Individual Data Point	4-21
4-15	Modulus, Individual Data Point	4-22
	Regression Plot, Tensile, 2.0 in/min, Motor 0031134	
4-16	Maximum Stress, Mean Point Data	4-23
4-17	Strain at Max Stress, Mean Data Point	4-25
4-18	Strain at Rupture, Mean Point Data	4-27
4-19	Stress at Rupture, Mean Point Data	4-29
4-20	Modulus, Mean Point Data	4-31
4-21	Maximum Stress, Individual Data Point	4-33
4-22	Strain at Max Stress, Individual Data Point	4-34
4-23	Strain at Rupture, Individual Data Point	4-35
4-24	Stress at Rupture, Individual Data Point	4-36
4-25	Modulus, Individual Data Point	4-37
	Regression Plot, Tensile, 2.0 in/min, Motor 0032434	
4-26	Maximum Stress, Mean Point Data	4-38
4-27	Strain at Max Stress, Mean Point Data	4-40
4-28	Strain at Rupture, Mean Point Data	4-42

LIST OF FIGURES (cont)

<u>Figure Nr</u>		<u>Page</u>
4-29	Stress at Rupture, Mean Point Data	4-44
4-30	Modulus, Mean Point Data	4-46
4-31	Maximum Stress, Individual Data Point	4-48
4-32	Strain at Max Stress, Individual Data Point	4-49
4-33	Strain at Rupture, Individual Data Point	4-50
4-34	Stress at Rupture, Individual Data Point	4-51
4-35	Modulus, Individual, Individual Data Point	4-52
Regression Plot, Tensile, 2.0 in/min, Motor 0032831		
4-36	Maximum Stress, Mean Point Data	4-53
4-37	Strain at Max Stress, Mean Point Data	4-55
4-38	Strain at Rupture, Mean Point Data	4-57
4-39	Stress at Rupture, Mean Point Data	4-59
4-40	Modulus, Mean Point Data	4-61
4-41	Maximum Stress, Individual Data Point	4-63
4-42	Strain at Max Stress, Individual Data Point	4-64
4-43	Strain at Rupture, Individual Data Point	4-65
4-44	Stress at Rupture, Individual Data Point	4-66
4-45	Modulus, Individual Data Point	4-67
Regression Plot, Tensile, 2.0 in/min, Motor 0033174		
4-46	Maximum Stress, Mean Point Data	4-68
4-47	Strain at Max Stress, Mean Point Data	4-70
4-48	Strain at Rupture, Mean Point Data	4-72
4-49	Stress at Rupture, Mean Point Data	4-74
4-50	Modulus, Mean Point Data	4-76
4-51	Maximum Stress, Individual Data Point	4-78
4-52	Strain at Max Stress, Individual Data Point	4-79

LIST OF FIGURES (cont)

<u>Figure Nr</u>		<u>Page</u>
4-53	Strain at Rupture, Individual Data Point	4-80
4-54	Stress at Rupture, Individual Data Point	4-81
4-55	Modulus, Individual Data Point	4-82
	Regression Plot, Biaxial Tensile, 0.2 in/min, Six Motors	
4-56	Maximum Stress	4-83
4-57	Strain at Max Stress	4-85
4-58	Strain at Rupture	4-87
4-59	Stress at Rupture	4-89
4-60	Modulus	4-91
	Regression Plot, Biaxial Tensile, 200 in/min, Six Motors	
4-61	Maximum Stress	4-92
4-62	Strain at Max Stress	4-93
4-63	Strain at Rupture	4-94
4-64	Stress at Rupture	4-95
4-65	Modulus	4-96

SECTION I
INTRODUCTION

In 1968, OO-ALC began testing dissected motors. Changes to the Aging and Surveillance program reduced the number of test motors to five per year. In 1983, one additional motor was added to the program.

In 1976, humidity conditioning at 50 ± 5 percent relative humidity for 48 hours was introduced into the program. Longer conditioning times, depending upon the thickness of the test specimen, began in 1981. At that same time changes were also made in several test parameters (GTD-30, Rev 2, 1 April 1981).

The motor serial numbers, lot numbers, cast dates and symbols used in the computer plots are shown below.

<u>Motor S/N</u>	<u>Lot Number</u>	<u>Cast Date</u>	<u>Symbol</u>
0031064	SR-56-62	62294	□
0031134	SR-65-62	63328	○
0032434	RAD-1-1-63	64021	△
0032619	RAD-1-4-64	64258	★
0032831	RAD-1-1-65	65176	+
0033174	RAD-1-10-66	67020	x

STATISTICAL APPROACH

Regression analysis has been selected as the method for projecting aging trends and demonstrating data variation in the propellant. The linear model $Y = a + bX$ was found to have the best fit throughout the data for this report.

A unique plot symbol is used for each motor tested. Analysis of covariance results indicate that the combined motor regression plots are to be used for visual display only.

Most points on the regression plots represent a data mean value at its particular age at test. The remaining points are single valued as shown in figures 4-11 thru 4-15, 4-21 thru 4-25, 4-31 thru 4-35, 4-41 thru 4-45, and 4-51 thru 4-55. The single valued points have multi-points per its particular age at test. Sample sizes per the mean values can be found in the Sample Size Summary. All regressions are calculated on single data values.

The data variance about each regression line was used to compute a tolerance interval such that at 90% confidence 90% of the sample distribution will fall within this interval. This tolerance interval is extrapolated 24 months beyond the age of the last test date.

The F value and student 't' values with their significance are recorded at the top of each regression. The significance gives an indication of the regression statistical significance of the trend line slope as compared to a line of zero slope.

SECTION II


STRESS RELAXATION

Stress relaxation specimens (0.5" x 0.5" x 4") were tested in the OO-ALC program at 3% strain and 77°F. In 1978, under the LRSLA program, an evaluation program tested two types of specimens at 2% strain, at 77°F. At the same time, specimens were tested at -30°F under 300 psi. The severe conditions could not be reproduced and testing was dropped.

Visual display for six motors and two test periods is shown in figures 2-1 thru 2-4. These combined data show a significant decrease in strain at rupture. The trend is not obvious for the two oldest motors for stress at rupture, but shows clearly for the RAD motors.

Individual regressions should be available for inclusion in the next report.

$Y = ((+1.9404687E+03) + (-1.9472035E+00) * X)$
 $F = +4.5117037E+00$ SIGNIFICANCE OF F = SIGNIFICANT $G_1 = +1.4242336E+02$
 $R = -2.7768275E-01$ SIGNIFICANCE OF R = SIGNIFICANT $S_0 = +9.1672919E-01$
 $t = +2.1240771E+00$ SIGNIFICANCE OF t = SIGNIFICANT $S_1 = +1.3808332E+02$
 $N = 56$ DEGREES OF FREEDOM = 54
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = 77 DEG F, AMB RH



STRESS RELAXATION MODULUS AT 10 SEC AND 2% STRAIN, SIX MOTOR VISUAL DISPLAY

Figure 2-

*** LITHIUM REACTION ANALYSIS ***

*** ANALYSIS OF THE RESULTS ***

ACT (CHARGE)	REACTED FUEL GROUP	CHARGE	STANDARD DEVIATION	EXTRAPOLATED	MINIMUM	PERCENTAGE
100.0	1	+7.959990E+01	+0.000000E+07	+7.959990E+01	+7.959990E+01	+3.182353E+01
100.0	1	+8.000000E+01	+0.000000E+07	+8.000000E+01	+8.000000E+01	+3.157415E+01
100.0	5	+8.200000E+01	+7.071000E-01	+8.200000E+01	+8.100000E+01	+8.128042E+01
100.0	10	+8.300000E+01	+1.012700E+00	+8.300000E+01	+8.100000E+01	+8.109458E+01
110.0	5	+8.300000E+01	+1.000000E+00	+8.300000E+01	+8.200000E+01	+8.083575E+01
110.0	5	+7.330000E+01	+1.140175E+00	+7.330000E+01	+7.200000E+01	+7.001502E+01
110.0	5	+7.019990E+01	+1.391340E+00	+7.019990E+01	+6.900000E+01	+6.803604E+01
110.0	5	+7.319990E+01	+3.300000E-01	+7.319990E+01	+7.200000E+01	+7.010200E+01
120.0	5	+7.800000E+01	+5.103977E-01	+7.800000E+01	+7.700000E+01	+7.609674E+01
120.0	5	+8.039990E+01	+0.944271E-01	+8.039990E+01	+7.900000E+01	+7.835145E+01

<0031134>

REACTOR II, STAGE III, DISSECTED HTR

$Y = ((+8.3108782E+01) + (-1.9182732E-02) \cdot X)$
 $F = +9.3799746E+00$ SIGNIFICANCE OF F = SIGNIFICANT $\sigma_1 = +2.5508967E+00$
 $R = -4.1155175E-01$ SIGNIFICANCE OF R = SIGNIFICANT $S_0 = +6.2633927E-03$
 $t = +3.0626744E+00$ SIGNIFICANCE OF t = SIGNIFICANT $S_z = +2.3499868E+00$
 $N = 48$ DEGREES OF FREEDOM = 46
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH





Figure 3-3

$Y = ((+8.5048443E+01) + (-2.7347393E-02) \cdot X)$
 $F = +1.5727897E+01$ SIGNIFICANCE OF F = SIGNIFICANT
 $R = -5.0477122E-01$ SIGNIFICANCE OF R = SIGNIFICANT
 $t = +3.9658413E+00$ SIGNIFICANCE OF t = SIGNIFICANT
 $N = 48$ DEGREES OF FREEDOM = 46
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH



MINUTEMAN II, STAGE III, DISSECTED MTR 0031064, 10 sec HARDNESS, SHORE A


Figure 3-2

*** SAMPLES OF TOOTHBRUSH ***

AGE (MONTHS)	NO. SAMPLES	AGE (MONTHS)	NO. SAMPLES
30.0	1	130.0	5
51.0	1	133.0	5
55.0	1	140.0	5
58.0	10	152.0	5
60.0	5	155.0	5
67.0	1	163.0	5
68.0	1	201.0	5
69.0	5	202.0	5
70.0	1	219.0	5
76.0	10	230.0	5
80.0	1	234.0	5
82.0	5	237.0	5
83.0	1	243.0	5
84.0	5	252.0	5
87.0	5		
93.0	5		
100.0	20		
105.0	10		
116.0	5		
117.0	5		
120.0	5		
121.0	5		

STATION 11, STAGE III, DISSECTED 4185/00 4100, 0031124, 0032434, 0033174

$Y = ((+8.4953558E+01) + (-2.8989592E-02) \cdot X)$
 $F = +8.829834CE+01$ SIGNIFICANCE OF F = SIGNIFICANT
 $R = -5.4406508E-01$ SIGNIFICANCE OF R = SIGNIFICANT
 $t = +9.3967196E+00$ SIGNIFICANCE OF t = SIGNIFICANT
 $N = 212$ DEGREES OF FREEDOM = 210
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH



MINUTEMAN II, STAGE III, DISSECTED MTRS/0031064,0031134,0032434,0032831,00333174

Figure 3-1

SECTION III

HARDNESS

The Shore A and Shore C hardness testing were performed on dogbone ends.

Figure 3-1 is a visual display of the 5 motor data. Figures 3-2 thru 3-6 show Shore A hardness on individual motors. All regressions show a significant decrease in hardness.

Shore C hardness is shown in figure 3-7 as a visual display. Figures 3-8 thru 3-12 show a significant decrease in each of the motors.


*** LINEAR REGRESSION ANALYSIS ***

*** ANALYSIS OF TIME SERIES **

AGE (MONTHS)	SPECIMENS PER GROUP	MEAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
183.0	5	+8.9200000E+02	+1.4404360E+01	+9.0500000E+02	+8.7000000E+02	+9.1785058E+02
201.0	5	+7.5400000E+02	+1.5572411E+01	+7.7500000E+02	+7.4000000E+02	+8.8868017E+02
202.0	5	+9.8100000E+02	+4.3214580E+01	+1.0150000E+03	+9.1000000E+02	+8.8705957E+02
219.0	5	+1.0330000E+03	+4.7381430E+01	+1.0700000E+03	+9.5000000E+02	+8.5950976E+02
221.0	5	+8.4900000E+02	+3.7815340E+01	+8.9500000E+02	+8.1000000E+02	+8.5626855E+02
230.0	5	+7.7700000E+02	+2.4135036E+01	+8.0500000E+02	+7.4500000E+02	+8.4168334E+02
231.0	5	+8.4900000E+02	+7.4161984E+00	+8.6000000E+02	+8.4000000E+02	+8.4006298E+02
234.0	6	+8.8000000E+02	+2.6645825E+01	+9.3000000E+02	+8.6000000E+02	+8.3520117E+02
238.0	5	+7.4800000E+02	+2.5396850E+01	+7.8500000E+02	+7.2500000E+02	+8.2871875E+02
249.0	5	+7.6200000E+02	+3.8503246E+01	+8.3000000E+02	+7.4000000E+02	+8.1089233E+02
252.0	5	+8.3800000E+02	+2.3075961E+01	+8.7000000E+02	+8.0500000E+02	+8.0603076E+02

STRESS RELAXATION MODULUS AT 1000 SEC AND 2% STRAIN, SIX MOTOR VISUAL DISPLAY

$F = +7.7978565E+00$
 $R = -3.5522286E-01$
 $t = +2.7924642E+00$
 $N = 56$
 $Y = ((+1.2144166E+03) + (-1.6205786E+00) * X)$
 SIGNIFICANCE OF F = SIGNIFICANT
 SIGNIFICANCE OF R = SIGNIFICANT
 SIGNIFICANCE OF t = SIGNIFICANT
 DEGREES OF FREEDOM = 54
 STORAGE CONDITIONS = AMB TEMP/RH
 TEST CONDITIONS = 77 DEG F, AMB RH



STRESS RELAXATION MODULUS AT 1000 SEC AND 2% STRAIN. SIX MOTOR VISUAL DISPLAY

Figure 2-4


*** LINEAR REGRESSION ANALYSIS ***

*** ANALYSIS OF TIME SERIES ***

AGE (MONTHS)	SPECIMENS PL. GROUP	MEAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
183.0	5	+1.1180000E+03	+1.6431676E+01	+1.1400000E+03	+1.0950000E+03	+1.1527011E+03
201.0	5	+9.8700000E+02	+1.5247950E+01	+1.0050000E+03	+9.7000000E+02	+1.1247778E+03
202.0	5	+1.2360000E+03	+5.8672821E+01	+1.2800000E+03	+1.1400000E+03	+1.1232265E+03
219.0	5	+1.2920000E+03	+5.3455589E+01	+1.3400000E+03	+1.2000000E+03	+1.0968542E+03
221.0	5	+1.1050000E+03	+3.0822070E+01	+1.1500000E+03	+1.0750000E+03	+1.0937517E+03
230.0	5	+9.9600000E+02	+2.5099800E+01	+1.0250000E+03	+9.6500000E+02	+1.0797900E+03
231.0	5	+1.0460000E+03	+1.0246950E+01	+1.0550000E+03	+1.0300000E+03	+1.0782387E+03
234.0	6	+1.1300000E+03	+3.6193922E+01	+1.1950000E+03	+1.1000000E+03	+1.0735849E+03
238.0	5	+9.5600000E+02	+1.9811612E+01	+9.9000000E+02	+9.4000000E+02	+1.0673796E+03
249.0	5	+1.0020000E+03	+3.5812009E+01	+1.0650000E+03	+9.8000000E+02	+1.0503154E+03
252.0	5	+1.1070000E+03	+2.1679483E+01	+1.1400000E+03	+1.0800000E+03	+1.0456613E+03

STRESS RELAXATION MODULUS AT 100 SEC AND 2% STRAIN. SIX MOTOR VISUAL DISPLAY

$Y = ((+1.4365894E+03) + (-1.5513010E+00) * X)$
 F = +5.2976052E+00 SIGNIFICANCE OF F = SIGNIFICANT $\sigma = +1.0541287E+02$
 R = -2.9889676E-01 SIGNIFICANCE OF R = SIGNIFICANT $S_e = +6.7399439E-01$
 t = +2.3016527E+00 SIGNIFICANCE OF t = SIGNIFICANT $S_r = +1.0152112E+02$
 N = 56 DEGREES OF FREEDOM = 54
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = 77 DEG F. AMB RH



STRESS RELAXATION MODULUS AT 100 SEC AND 2% STRAIN. SIX MOTOR VISUAL DISPLAY

Figure 2-3

*** LINEAR REGRESSION ANALYSIS ***


*** ANALYSIS OF TIME SERIES ***

AGE (MONTHS)	SPECIMENS PLR GROUP	MEAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
183.0	5	+1.2100000E+03	+1.9999999E+01	+1.2350000E+03	+1.1800000E+03	+1.2480292E+03
201.0	5	+1.0750000E+03	+1.2247448E+01	+1.0900000E+03	+1.0600000E+03	+1.2201975E+03
202.0	5	+1.3400000E+03	+6.4710895E+01	+1.3900000E+03	+1.2350000E+03	+1.2186513E+03
219.0	5	+1.4050000E+03	+5.8630196E+01	+1.4600000E+03	+1.3050000E+03	+1.1923654E+03
221.0	5	+1.1970000E+03	+2.7064737E+01	+1.2350000E+03	+1.1700000E+03	+1.1892731E+03
230.0	5	+1.0870000E+03	+2.1965882E+01	+1.1150000E+03	+1.0600000E+03	+1.1753571E+03
231.0	5	+1.1360000E+03	+1.3416407E+01	+1.1500000E+03	+1.1150000E+03	+1.1738110E+03
234.0	6	+1.2275000E+03	+4.0712405E+01	+1.3000000E+03	+1.1900000E+03	+1.1691723E+03
238.0	5	+1.0450000E+03	+2.0310096E+01	+1.0800000E+03	+1.0300000E+03	+1.1629875E+03
249.0	5	+1.0910000E+03	+3.5951356E+01	+1.1550000E+03	+1.0700000E+03	+1.1459790E+03
252.0	5	+1.2120000E+03	+2.3611437E+01	+1.2450000E+03	+1.1800000E+03	+1.1413403E+03

2
1
5

STRESS RELAXATION MODULUS AT 50 SEC AND 2% STRAIN, SIX MOTOR VISUAL DISPLAY

$Y = ((+1.5309871E+03) + (-1.5462165E+00) * X)$
 $F = +4.5445439E+00$ SIGNIFICANCE OF F = SIGNIFICANT
 $R = -2.7861336E-01$ SIGNIFICANCE OF R = SIGNIFICANT
 $t = +2.1317935E+00$ SIGNIFICANCE OF t = SIGNIFICANT
 $N = 56$ DEGREES OF FREEDOM = 54
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = 77 DEG F, AMB RH



STRESS RELAXATION MODULUS AT 50 SEC AND 2% STRAIN, SIX MOTOR VISUAL DISPLAY

Figure 2-2


*** LINEAR REGRESSION ANALYSIS ***

*** ANALYSIS OF TIME SERIES **

AGE (MONTHS)	SPECIMENS PLR GROUP	MLAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
153.0	5	+1.5260000E+03	+2.5592967E+01	+1.5650000E+03	+1.4950000E+03	+1.5841303E+03
201.0	5	+1.3920000E+03	+1.4832396E+01	+1.4100000E+03	+1.3750000E+03	+1.5490808E+03
202.0	5	+1.6940000E+03	+8.6631403E+01	+1.7650000E+03	+1.5550000E+03	+1.5471335E+03
219.0	5	+1.7770000E+03	+7.8549347E+01	+1.8550000E+03	+1.6450000E+03	+1.5140310E+03
221.0	5	+1.5440000E+03	+2.7477263E+01	+1.5850000E+03	+1.5150000E+03	+1.5101367E+03
230.0	5	+1.3720000E+03	+3.8013155E+01	+1.4350000E+03	+1.3400000E+03	+1.4926118E+03
231.0	5	+1.4240000E+03	+1.9170289E+01	+1.4400000E+03	+1.3950000E+03	+1.4906645E+03
234.0	6	+1.5558332E+03	+5.5354915E+01	+1.6550000E+03	+1.5050000E+03	+1.4848229E+03
238.0	5	+1.3100000E+03	+1.7677669E+01	+1.3400000E+03	+1.2950000E+03	+1.4770341E+03
249.0	5	+1.3920000E+03	+3.0331501E+01	+1.4450000E+03	+1.3750000E+03	+1.4556149E+03
252.0	5	+1.5540000E+03	+2.2472205E+01	+1.5850000E+03	+1.5250000E+03	+1.4497734E+03

STRESS RELAXATION MODULUS AT 10 SEC AND 2% STRAIN. SIX MOTOR VISUAL DISPLAY

$F = +8.0236202E+01$ SIGNIFICANCE OF F = $(-6.6354797E-02) \cdot X$
 $R = -8.1689748E-01$ SIGNIFICANT $\sigma_r = +3.8025756E+00$
 $t = +8.9574662E+00$ SIGNIFICANT $S_e = +7.4077641E-03$
 $N = 42$ DEGREES OF FREEDOM = 40 $S_t = +2.2205071E+00$
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH



SHORE A

MINUTEMAN II, STAGE III, DISSECTED MTR 0032434, HARDNESS

Figure 3-4

*** LINEAR REGRESSION ANALYSIS ***

*** ANALYSIS OF TIME SERIES ***

TIME (HRS)	DATE	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	PERCENTAGE
00.0	1	+0.0000000E+07	+0.0799987E+01	+0.0799987E+01	+8.5989730E+01
05.0	1	+0.0000000E+07	+0.0799987E+01	+0.0799987E+01	+8.5127120E+01
10.0	5	+5.4772255E-01	+8.0000000E+01	+8.0000000E+01	+2.4065444E+01
15.0	5	+5.4772255E-01	+8.0000000E+01	+8.0000000E+01	+8.348246E+01
105.0	10	+1.3374935E+00	+8.0000000E+01	+8.0000000E+01	+8.267197E+01
115.0	5	+1.1401754E+00	+8.0000000E+01	+7.7000000E+01	+8.1809387E+01
131.0	5	+1.0954451E+00	+8.0000000E+01	+7.9000000E+01	+8.0946762E+01
149.0	5	+5.4772255E-01	+8.0000000E+01	+7.9000000E+01	+8.0349578E+01
257.0	5	+5.4772255E-01	+7.0000000E+01	+7.4000000E+01	+7.3913162E+01

GROUP 11, STAGE 111, DISSECTED AIR

<0032434>

$Y = ((+8.5330991E+01) + (-2.3716416E-02) \cdot X)$
 $F = +1.7602437E+01$ SIGNIFICANCE OF F = SIGNIFICANT
 $R = -5.7305213E-01$ SIGNIFICANCE OF R = SIGNIFICANT
 $t = +4.1955258E+00$ SIGNIFICANCE OF t = SIGNIFICANT
 $N = 38$ DEGREES OF FREEDOM = 36
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH




Figure 3-5

*** LINEAR REGRESSION ANALYSIS ***


*** ANALYSIS OF LINEAR SERIES ***

AGE (MONTHS)	SPECIMENS PER GROUP	MEAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
20.0	1	+8.139992E+01	+0.000000E+07	+8.139999E+01	+8.139999E+01	+8.442976E+01
21.0	1	+8.255999E+01	+0.000000E+07	+8.255999E+01	+8.255999E+01	+8.412144E+01
22.0	5	+3.379993E+01	+3.369000E-01	+8.300000E+01	+3.300000E+01	+8.376570E+01
23.0	10	+8.479997E+01	+7.669100E-01	+8.600000E+01	+3.400000E+01	+8.382853E+01
24.0	5	+3.459999E+01	+5.477225E-01	+8.500000E+01	+3.400000E+01	+8.326765E+01
25.0	5	+7.359999E+01	+2.073941E+00	+8.000000E+01	+7.500000E+01	+8.241386E+01
26.0	5	+7.960005E+01	+9.164903E-01	+8.100000E+01	+7.900000E+01	+8.094020E+01
27.0	5	+8.200000E+01	+0.000000E+07	+8.200000E+01	+8.200000E+01	+8.013708E+01

<0032831>

MINUTEMAN II, STAGE III, DISJECTED MTR

$Y = ((+8.3249295E+01) + (-2.2984999E-02) \cdot X)$
 $F = +1.0814481E+01$ SIGNIFICANCE OF F = SIGNIFICANT
 $R = -4.9123993E-01$ SIGNIFICANCE OF R = SIGNIFICANT
 $t = +3.2885378E+00$ SIGNIFICANCE OF t = SIGNIFICANT
 $N = 36$ DEGREES OF FREEDOM = 34
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH



SHORE A

MINUTEMAN II, STAGE III, DISSECTED MTR 0033174, HARDNESS

Figure 3-6

*** LINEAR REGRESSION ANALYSIS ***

*** ANALYSIS OF THE SERIES ***

AGE (MONTHS)	SPCIFIED PER GROUP	MEAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
00.0	10	+8.387993E+01	+1.1005049E+00	+8.0000000E+01	+3.2000000E+01	+8.1916152E+01
02.0	5	+6.259993E+01	+5.4772235E-01	+8.3000000E+01	+8.2000000E+01	+8.1663330E+01
04.0	5	+7.5799987E+01	+4.4721359E-01	+7.9000000E+01	+7.8000000E+01	+8.1364517E+01
06.0	5	+7.7199996E+01	+1.3033404E+00	+7.9000000E+01	+7.6000000E+01	+8.0858840E+01
08.0	5	+7.6833326E+01	+1.1690451E+00	+8.0000000E+01	+7.7000000E+01	+7.9043029E+01
10.0	5	+8.039993E+01	+3.9442719E-01	+8.1000000E+01	+7.9000000E+01	+7.8629302E+01

STUDY PLAN II, STAGE III, DISSECTED NTR


<0033174>

$Y = ((+5.4455382E+01) + (-2.0075474E-02) \times X)$
 SIGNIFICANCE OF F = SIGNIFICANT
 SIGNIFICANCE OF R = SIGNIFICANT
 SIGNIFICANCE OF t = SIGNIFICANT
 DEGREES OF FREEDOM = 170
 STORAGE CONDITIONS = AMB TEMP/RH
 TEST CONDITIONS = AMB TEMP/RH
 $\sigma_r = +3.7779887E+00$
 $S_s = +5.9985350E-03$
 $S_e = +3.6701084E+00$

F = +1.1200599E+01
 R = -2.4862271E-01
 t = +3.3467296E+00
 N = 172

PARAMETER = 10 SECOND HARDNESS

UNIT OF MEASURE = SHORE C



*** SAMPLE SIZE SUMMARY ***

AGE (MONTHS)	NR SAMPLES	AGE (MONTHS)	NR SAMPLES
34.0	1	130.0	5
51.0	1	133.0	5
55.0	1	140.0	5
58.0	10	152.0	5
66.0	5	155.0	5
67.0	1	183.0	6
68.0	1	201.0	5
69.0	5	202.0	6
70.0	1	219.0	5
76.0	10	230.0	6
80.0	1	234.0	6
82.0	5	237.0	5
83.0	1	248.0	5
84.0	5	252.0	5
87.0	5		
93.0	5		
95.0	5		
98.0	5		
104.0	5		
105.0	20		
108.0	10		
116.0	5		
118.0	5		
120.0	5		
125.0	5		

MINOTURMAN II, STAGE III, DISSECTED AIRS/0031004, 0031134, 0032434, 0032831, 0033174

$Y = ((+5.7709871E+01) + (-3.5401351E-02) \cdot X)$
 $F = +9.4099679E+00$ SIGNIFICANCE OF F = SIGNIFICANT
 $R = -4.3205184E-01$ SIGNIFICANCE OF R = SIGNIFICANT
 $t = +3.0675671E+00$ SIGNIFICANCE OF t = SIGNIFICANT
 $N = 43$ DEGREES OF FREEDOM = 41
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH




Figure 3-8

*** LITERATURE DISCUSSION AND ANALYSIS ***

*** ANALYSIS OF THE RESULTS ***

ANALYST	EXPERIMENTAL PER GROUP	MEAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	DISCUSSION Y
700.0	1	+5.100000E+01	+0.000000E+07	+5.100000E+01	+5.100000E+01	+5.5231765E+01
800.0	1	+4.000000E+01	+0.000000E+07	+4.000000E+01	+4.000000E+01	+5.4771545E+01
900.0	5	+4.3799087E+01	+5.3666032E-01	+5.000000E+01	+4.800000E+01	+5.4240524E+01
1000.0	10	+5.5899993E+01	+2.2027838E+00	+5.500000E+01	+5.200000E+01	+5.3886520E+01
1200.0	5	+5.3199990E+01	+8.3666032E-01	+6.000000E+01	+5.800000E+01	+5.3461700E+01
1400.0	5	+5.5599990E+01	+1.3416407E+00	+5.700000E+01	+5.400000E+01	+5.3001480E+01
1600.0	5	+4.6799987E+01	+1.4831426E+00	+4.900000E+01	+4.500000E+01	+5.2227656E+01
1800.0	5	+5.2500000E+01	+1.5165730E+00	+5.400000E+01	+5.000000E+01	+4.9425949E+01
2000.0	5	+4.5599990E+01	+1.1401754E+00	+4.700000E+01	+4.400000E+01	+4.8788726E+01

REMARKS: STAGE III, DISCUSSION

<0031064>

$Y = ((+5.4456603E+01) + (-2.2354976E-02)) \cdot X$
 $F = +8.4176287E+00$ SIGNIFICANCE OF F = SIGNIFICANT $\sigma_r = +3.1353448E+00$
 $R = -4.1271849E-01$ SIGNIFICANCE OF R = SIGNIFICANT $S_e = +7.7051186E-03$
 $t = +2.9013149E+00$ SIGNIFICANCE OF t = SIGNIFICANT $S_r = +2.8904736E+00$
 $N = 43$ DEGREES OF FREEDOM = 41
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH




Figure 3-9

*** LINEAR REGRESSION ANALYSIS ***

*** ANALYSIS OF TIME SERIES ***

TIME	SPECIFIED PER GROUP	MEAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
07.0	1	+5.1000000E+01	+0.0000000E+07	+5.1000000E+01	+5.1000000E+01	+5.295816L+01
08.0	1	+5.219996E+01	+0.0000000E+07	+5.219996E+01	+5.219996E+01	+5.2668197E+01
09.0	5	+5.1000000E+01	+7.0710678E-01	+5.2000000E+01	+5.0000000E+01	+5.2332870E+01
10.0	10	+5.3769937E+01	+1.393+117E+00	+5.6000000E+01	+5.2000000E+01	+5.2109329E+01
11.0	5	+5.3599920E+01	+1.5165750E+00	+5.5000000E+01	+5.2000000E+01	+5.1863418E+01
12.0	5	+5.5000000E+01	+1.4142135E+00	+5.5000000E+01	+5.2000000E+01	+5.1550445E+01
13.0	5	+4.4799871E+01	+2.77+3873E+00	+4.7000000E+01	+4.0000000E+01	+5.1058639E+01
20.0	6	+4.9000050E+01	+5.1639777E-01	+5.0000000E+01	+4.9000000E+01	+4.9314956E+01
24.0	5	+5.0000000E+01	+1.0000000E+00	+5.1000000E+01	+4.9000000E+01	+4.8912507E+01

AR:OUTP44L 11, STAGE 111, DISSECTED MTR

<0031134>

$Y = ((+6.4335378E+01) + (-1.0523031E-01) \cdot X)$
 $F = +1.1427270E+02$ SIGNIFICANCE OF F = SIGNIFICANT
 $R = -8.7494559E-01$ SIGNIFICANCE OF R = SIGNIFICANT
 $t = +1.0689841E+01$ SIGNIFICANCE OF t = SIGNIFICANT
 $N = 37$ DEGREES OF FREEDOM = 35
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH




Figure 3-10

*** LPH 48 PRODUCTION ANALYSIS ***


*** ANALYSIS OF THE DATA ***

ANALYSIS	GROUP	MEAN	STANDARD DEVIATION	STANDARD Y	MINIMUM Y	PERCENTAGE
100.0	1	+5.059999E+01	+0.000000E+00	+5.059999E+01	+5.059999E+01	+5.854709E+01
100.0	1	+4.779999E+01	+0.000000E+00	+4.779999E+01	+4.779999E+01	+5.717970E+01
100.0	5	+5.001000E+01	+1.453239E+00	+5.000000E+01	+5.000000E+01	+5.549801E+01
100.0	5	+5.001000E+01	+1.095451E+00	+5.000000E+01	+5.000000E+01	+5.454295E+01
100.0	10	+5.479998E+01	+1.617327E+00	+5.000000E+01	+5.000000E+01	+5.328619E+01
100.0	5	+5.519999E+01	+1.303340E+00	+5.000000E+01	+5.000000E+01	+5.191819E+01
100.0	5	+4.059999E+01	+1.140175E+00	+4.000000E+01	+4.000000E+01	+4.960313E+01
100.0	5	+5.019999E+01	+1.043167E+00	+4.000000E+01	+3.000000E+01	+5.049578E+01

<0032434>

STANDARD 11, STAGE 11, DISPERSED ATR

F = +6.2445213E-02
 R = -2.9643501E-02
 t = +2.4989040E-01
 N = 73
 STORAGE CONDITIONS = AMB TEMP/RH
 TEST CONDITIONS = 77 DEG F, AMB RH
 SIGNIFICANCE OF F = NOT SIGNIFICANT
 SIGNIFICANCE OF R = NOT SIGNIFICANT
 SIGNIFICANCE OF t = NOT SIGNIFICANT
 DEGREES OF FREEDOM = 71
 G_r = +5.1910318E-02
 S_r = +9.7014115E-05
 S_t = +5.2251633E-02



UNIAXIAL TENSILE, STRAIN AT MAX. 2.0 IN/MIN AT 77 DEG F, MOTOR=0031064.

Figure 4-7

*** LINEAR REGRESSION ANALYSIS ***

*** ANALYSIS OF TIME SERIES ***

AGE (MONTHS)	SPECIMENS PER GROUP	MEAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
70.0	10	+4.2519995E+02	+1.0726913E+01	+4.4500000E+02	+4.1200000E+02	+4.5247583E+02
93.0	10	+4.0100000E+02	+5.6754621E+00	+4.1000000E+02	+3.9000000E+02	+4.4789990E+02
95.0	10	+4.6500000E+02	+6.2360956E+00	+4.8000000E+02	+4.6000000E+02	+4.4367553E+02
107.0	10	+4.3079980E+02	+1.3554826E+01	+4.5300000E+02	+4.1300000E+02	+4.3945141E+02
120.0	5	+3.8395971E+02	+7.279715E+00	+3.9459985E+02	+3.7539990E+02	+4.3487524E+02
133.0	5	+5.1666650E+02	+1.9731531E+01	+5.3000000E+02	+4.9400000E+02	+4.3029931E+02
146.0	8	+5.5602978E+02	+2.6587161E+02	+1.2130998E+03	+4.4400000E+02	+4.2572314E+02
155.0	2	+4.1587475E+02	+3.1991114E+00	+4.1811987E+02	+4.1362988E+02	+4.2255493E+02
234.0	0	+4.0242651E+02	+6.8941651E+00	+4.1176977E+02	+3.9221997E+02	+3.9474609E+02
252.0	4	+2.8990234E+02	+2.8445475E+00	+2.9300976E+02	+2.8615991E+02	+3.8840991E+02
262.0	5	+3.7076171E+02	+8.3824962E+00	+3.8378979E+02	+3.6450976E+02	+3.8488964E+02


4

UNIAXIAL TENSILE, MAXIMUM STRESS, 2.0 IN/MIN AT 77 DEG F. MOTOR=0031064.

1

9


$Y = ((+4.7711687E+02) + (-3.5201169E-01) * X)$
 $F = +3.4217615E+00$ SIGNIFICANCE OF F = NOT SIGNIFICANT $G_1 = +1.0420315E+02$
 $R = -2.1442474E-01$ SIGNIFICANCE OF R = NOT SIGNIFICANT $S_0 = +1.9029712E-01$
 $t = +1.8498004E+00$ SIGNIFICANCE OF t = NOT SIGNIFICANT $S_1 = +1.0249369E+02$
 $N = 73$ DEGREES OF FREEDOM = 71
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = 77 DEG F, AMB RH




UNIAXIAL TENSILE, MAXIMUM STRESS, 2.0 IN/MIN AT 77 DEG F, MOTOR=0031064.

Figure 4-6

$Y = ((+1.7355000E+03) + (+7.0385281E-02) * X)$
 $F = +8.2685131E-02$ SIGNIFICANCE OF F = NOT SIGNIFICANT $G = +3.0120423E+02$
 $R = +1.5948387E-02$ SIGNIFICANCE OF R = NOT SIGNIFICANT $S_0 = +2.4477560E-01$
 $t = +2.8755022E-01$ SIGNIFICANCE OF t = NOT SIGNIFICANT $S_t = +3.0162890E+02$
 $N = 327$ DEGREES OF FREEDOM = 325
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = 77 DEG F, AMB RH



$Y = ((+4.0312417E+02) + (-2.5460750E-01) \cdot X)$
 $F = +2.0179775E+01$ SIGNIFICANCE OF F = SIGNIFICANT $\sigma_y = +7.1867365E+01$
 $R = -2.4178842E-01$ SIGNIFICANCE OF R = SIGNIFICANT $S_e = +5.6677806E-02$
 $t = +4.4921905E+00$ SIGNIFICANCE OF t = SIGNIFICANT $S_r = +6.9842190E+01$
 $N = 327$ DEGREES OF FREEDOM = 325
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = 77 DEG F, AMB RH



UNIAXIAL TENSILE, STRESS AT RUP. 2.0 IN/MIN AT 77 DEG F, SIX MOTOR DISPLAY

Figure 4-4

$Y = ((+4.7608374E-01) + (+1.3554419E-05) \cdot X)$
 $F = +3.3777246E-01$ SIGNIFICANCE OF F = NOT SIGNIFICANT $S_r = +4.1418663E-02$
 $R = +3.2221434E-02$ SIGNIFICANCE OF R = NOT SIGNIFICANT $S_e = +3.3645951E-05$
 $t = +5.8118195E-01$ SIGNIFICANCE OF t = NOT SIGNIFICANT $S_r = +4.1460795E-02$
 $N = 327$ DEGREES OF FREEDOM = 325
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = 77 DEG F, AMB RH




Figure 4-3

$Y = ((+4.0905708E-01) + (+2.9110279E-05) \cdot X)$
 $F = +7.4214385E-01$ SIGNIFICANCE OF F = NOT SIGNIFICANT $G_1 = +4.1623185E-02$
 $R = +4.7731718E-02$ SIGNIFICANCE OF R = NOT SIGNIFICANT $S_1 = +3.3791099E-05$
 $t = +8.614771E-01$ SIGNIFICANCE OF t = NOT SIGNIFICANT $S_2 = +4.1639656E-02$
 $N = 327$ DEGREES OF FREEDOM = 325
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = 77 DEG F, AMB RH





Figure 4-2

$Y = ((+4.2375278E+02) + (-2.1027210E-01) * X)$
 $F = +1.6491886E+01$ SIGNIFICANCE OF F = SIGNIFICANT
 $R = -2.1975814E-01$ SIGNIFICANCE OF R = SIGNIFICANT
 $t = +4.0610203E+00$ SIGNIFICANCE OF t = SIGNIFICANT
 $N = 327$ DEGREES OF FREEDOM = 325
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = 77 DEG F, AMB RH



UNIAXIAL TENSILE, MAXIMUM STRESS, 2.0 IN/MIN AT 77 DEG F, SIX MOTOR DISPLAY

Figure 4-1

from the test program's inception should be available for regressions.

C. A change in testing rails under pressure was made in GTD-30, REV 2, April 1981. This required rails to be tested at 200 in/min under 300 psi pressure. These data are shown as a visual display in figures 4-61 thru 4-65. Strains show a significant increase and there appears to be a significant decrease in modulus.

SECTION IV

TENSILE TESTING

A. Uniaxial JANNAF dogbones were tested at 77°F and 2.0 in/min. The data are shown in three sets of figures. Figures 4-1 thru 4-5 represent the visual display of data from six motors. The next set of figures represent averages of data on the individual motors and a third set represent individual data points for each test period.

Figures 4-1 and 4-5 show a significant decrease in maximum stress and stress at rupture. These figures depict a visual display of six motors.

Figures 4-6 thru 4-15 represent motor S/N 0031064. The average values show a non-significant trend in any parameter. The maximum stress shows a significant decrease when individual specimen values are used.

Figures 4-16 thru 4-25 represent motor S/N 0031134. The strain at maximum stress shows a significant increase (figures 4-17 and 4-22).

Figures 4-26 thru 4-35 represent motor S/N 0032434. The maximum stress and stress at rupture show a significant decrease. The modulus for individual points also shows a significant decrease (figure 4-35).

Figures 4-36 thru 4-45 represent motor S/N 0032831. Only strain at rupture (figure 4-38) shows a non-significant trend. With one less time point, the individual data plots show a significant decrease in strain at maximum stress, stress at rupture (figures 4-42 and 4-44) and a significant increase in modulus (figure 4-45).

Figures 4-46 thru 4-55 represent motor S/N 0033174. Only strain at rupture and modulus shows a non-significant trend (figures 4-48 and 4-50).

B. Biaxial rails at low rate, 0.2 in/min, are shown in figures 4-56 thru 4-60. Strains show a significant increase. This data represents the data from the last three test periods. In the next report, data acquired

*** LINEAR REGRESSION ANALYSIS ***


** ANALYSIS OF TIME SERIES **

AGE (MONTHS)	SPECTRUM FREQ GROUP	MEAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
00.0	10	+5.1599990L+01	+1.0749070E+00	+5.3000000E+01	+5.0000000E+01	+5.0732162E+01
05.0	5	+5.1799987E+01	+6.3000002E-01	+5.5000000E+01	+5.1000000E+01	+5.0518295E+01
07.0	5	+5.1799987E+01	+4.4721359E-01	+5.2000000E+01	+5.1000000E+01	+5.0265533E+01
10.0	5	+4.5199990E+01	+1.3038404E+00	+4.5000000E+01	+4.2000000E+01	+4.9837783E+01
15.0	5	+5.0533320E+01	+8.1049050E-01	+5.2000000E+01	+5.0000000E+01	+4.8001803E+01
20.0	5	+4.7599990E+01	+5.4772255E-01	+4.8000000E+01	+4.7000000E+01	+4.7051843E+01

ALPHABETIC II, STAGE III, DISSECTED MTR

<0033174>

$Y = ((+5.1859849E+01) + (-1.9442790E-02) \cdot X)$
 $F = +4.8616919E+00$ SIGNIFICANCE OF F = SIGNIFICANT $G_1 = +3.1223719E+00$
 $R = -3.5369821E-01$ SIGNIFICANCE OF R = SIGNIFICANT $S_1 = +8.8178942E-03$
 $t = +2.2049244E+00$ SIGNIFICANCE OF t = SIGNIFICANT $S_2 = +2.9631784E+00$
 $N = 36$ DEGREES OF FREEDOM = 34
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH



MINUTEMAN II, STAGE III, DISSECTED MTR 0033174, 10 sec
 HARDNESS, SHORE C

Figure 3-12

*** LINEAR REGRESSION ANALYSIS ***

*** ANALYSIS OF TIME SERIES ***

AGE (MONTHS)	SEX	GROUP	MEAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
30.0	1	1	+5.1000000E+01	+0.0000000E+07	+5.1000000E+01	+5.1000000E+01	+5.3905181E+01
31.0	1	1	+4.9199999E+01	+0.0000000E+07	+4.9199999E+01	+4.9199999E+01	+5.3677307E+01
32.0	5	5	+5.3509990E+01	+3.9442719E-01	+5.5000000E+01	+5.3000000E+01	+5.3414782E+01
37.0	10	10	+5.4099990E+01	+1.2500000E+00	+5.5000000E+01	+5.2000000E+01	+5.3239105E+01
47.0	5	5	+5.7000000E+01	+1.0000000E+00	+5.8000000E+01	+5.6000000E+01	+5.3042203E+01
123.0	5	5	+4.7000000E+01	+1.0000000E+00	+4.8000000E+01	+4.6000000E+01	+5.2415283E+01
207.0	5	5	+5.0000000E+01	+0.0000000E+07	+5.1000000E+01	+5.0000000E+01	+5.1030563E+01
219.0	5	5	+5.5000000E+01	+1.8703224E+00	+5.5000000E+01	+5.0000000E+01	+5.0732574E+01

STAGE III, DISSECTED MTR

<0032831>

$Y = ((+5.4571257E+01) + (-1.7528167E-02) * X)$
 $F = +4.6578642E+00$ SIGNIFICANCE OF F = SIGNIFICANT $\sigma_y = +3.1883366E+00$
 $R = -3.3847074E-01$ SIGNIFICANCE OF R = SIGNIFICANT $S_e = +8.1216283E-03$
 $t = +2.1582085E+00$ SIGNIFICANCE OF t = SIGNIFICANT $S_e = +3.0415345E+00$
 $N = 38$ DEGREES OF FREEDOM = 36
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = AMB TEMP/RH




Figure 3-11


*** LINEAR REGRESSION ANALYSIS ***

*** ANALYSIS OF TIME SERIES ***

AGE (MONTHS)	SPECIMENS PER GROUP	MLAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
70.0	10	+4.0909952E-01	+6.6136148E-03	+4.7999995E-01	+4.5799994E-01	+4.4910496E-01
83.0	10	+4.4739967E-01	+6.6640446E-03	+4.6199995E-01	+4.3999999E-01	+4.4878977E-01
95.0	10	+4.4729971E-01	+9.3880207E-03	+4.6199995E-01	+4.2999994E-01	+4.4849884E-01
107.0	10	+4.4879966E-01	+9.0731777E-03	+4.6399998E-01	+4.2999994E-01	+4.4820797E-01
120.0	5	+4.4839972E-01	+5.7021084E-03	+4.5399999E-01	+4.3999998E-01	+4.4789278E-01
133.0	3	+4.5799982E-01	+8.0091578E-03	+4.6599996E-01	+4.4999998E-01	+4.4757765E-01
146.0	8	+4.0242469E-01	+1.5406605E-01	+4.6899998E-01	+2.1999999E-02	+4.4726246E-01
155.0	2	+4.5369994E-01	+1.8371599E-03	+4.5499998E-01	+4.5239996E-01	+4.4704431E-01
234.0	6	+4.4319963E-01	+5.5927591E-03	+4.5079994E-01	+4.3829995E-01	+4.4512909E-01
252.0	4	+4.7712469E-01	+2.2210520E-03	+4.7869998E-01	+4.7399997E-01	+4.4469273E-01
262.0	5	+4.4713973E-01	+5.8580023E-03	+4.5469999E-01	+4.4019997E-01	+4.4445031E-01

UNIAXIAL TENSILE, STRAIN AT MAX, 2.0 IN/MIN AT 77 DEG F, MOTOR=0031064.

$Y = ((+5.0854254E-01) + (-3.1562812E-05) \cdot X)$
 F = +7.9124522E-02 SIGNIFICANCE OF F = NOT SIGNIFICANT $G_1 = +6.0046801E-02$
 R = -3.3364491E-02 SIGNIFICANCE OF R = NOT SIGNIFICANT $S_0 = +1.1220705E-04$
 t = +2.8129081E-01 SIGNIFICANCE OF t = NOT SIGNIFICANT $S_e = +6.0434522E-02$
 N = 73 DEGREES OF FREEDOM = 71
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = 77 DEG F, AMB RH



UNIAXIAL TENSILE, STRAIN AT RUP, 2.0 IN/MIN AT 77 DEG F, MOTOR=0031064.

Figure 4-8


*** LINEAR REGRESSION ANALYSIS ***

*** ANALYSIS OF TIME SERIES ***

AGE (MONTHS)	SPECIMENS PER GROUP	MEAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
70.0	10	+5.2699953E-01	+8.2680051E-03	+5.3899997E-01	+5.1699995E-01	+5.0633311E-01
83.0	10	+5.3039968E-01	+7.8170340E-03	+5.4199999E-01	+5.1599997E-01	+5.0592279E-01
95.0	10	+4.9649953E-01	+1.7798327E-02	+5.1999998E-01	+4.5999997E-01	+5.0554406E-01
107.0	10	+4.9349951E-01	+8.0655454E-03	+5.1099997E-01	+4.7999995E-01	+5.0516527E-01
120.0	5	+5.1899963E-01	+1.4716522E-02	+5.3999996E-01	+5.0099998E-01	+5.0475496E-01
133.0	3	+4.9166643E-01	+1.4648017E-02	+5.0499999E-01	+4.7599995E-01	+5.0434464E-01
146.0	8	+4.4144952E-01	+1.6671396E-01	+5.2499997E-01	+3.0999999E-02	+5.0393432E-01
155.0	2	+5.0489997E-01	+8.2045966E-03	+5.1069998E-01	+4.9909996E-01	+5.0365030E-01
234.0	6	+5.0159960E-01	+1.2672013E-02	+5.2109998E-01	+4.8769998E-01	+5.0115680E-01
252.0	4	+5.5374956E-01	+7.0328638E-03	+5.6199997E-01	+5.4519999E-01	+5.0058871E-01
262.0	5	+5.0117945E-01	+1.8494879E-02	+5.2499997E-01	+4.8459994E-01	+5.0027304E-01

UNIAXIAL TENSILE, STRAIN AT RUP, 2.0 IN/MIN AT 77 DEG F, MOTOR=0031064.

$F = +3.6011305E+00$
 $R = -2.1970843E-01$
 $t = +1.8976645E+00$
 $N = 73$
 $Y = ((+4.5973759E+02) + (-3.7641649E-01) * X)$
 SIGNIFICANCE OF F = NOT SIGNIFICANT
 SIGNIFICANCE OF R = NOT SIGNIFICANT
 SIGNIFICANCE OF t = NOT SIGNIFICANT
 DEGREES OF FREEDOM = 71
 STORAGE CONDITIONS = AMB TEMP/RH
 TEST CONDITIONS = 77 DEG F, AMB RH



UNIAXIAL TENSILE, STRESS AT RUP. 2.0 IN/MIN AT 77 DEG F. MOTOR=0031064.

Figure 4-9

*** LINEAR REGRESSION ANALYSIS ***

*** ANALYSIS OF TIME SERIES ***

AGE (MONTHS)	SPECIMENS PER GROUP	MEAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
70.0	10	+4.0419905L+02	+1.0443498E+01	+4.1700000F+02	+3.9200000F+02	+4.3138342F+02
80.0	10	+3.7639990L+02	+1.2313870L+01	+3.9200000L+02	+3.5000000L+02	+4.2849487L+02
90.0	10	+4.4600000L+02	+9.6609178E+00	+4.6000000L+02	+4.3000000L+02	+4.2397802F+02
107.0	10	+4.2559985L+02	+2.5325437E+01	+4.3000000L+02	+4.0300000E+02	+4.1946093F+02
110.0	5	+3.3905991L+02	+1.1855813E+01	+3.5000000L+02	+3.2000000L+02	+4.1456738E+02
113.0	3	+4.9250050L+02	+1.7925772E+01	+5.0400000E+02	+4.7200000F+02	+4.0967407E+02
116.0	3	+5.4293457L+02	+2.7117295E+02	+1.2130000E+03	+4.2862988F+02	+4.0478076L+02
125.0	2	+3.9172973L+02	+3.7117053L+00	+3.9575970E+02	+3.8769995E+02	+4.0139232F+02
134.0	1	+3.7807312E+02	+1.0121482E+01	+3.321997E+02	+3.6432933F+02	+3.7165600L+02
140.0	4	+2.0370483E+02	+4.3171507E+00	+2.6795994L+02	+2.5911987E+02	+3.6488001L+02
142.0	5	+3.4732565L+02	+1.401345E+01	+3.6450976L+02	+3.2989900E+02	+3.6111645F+02

UNIAXIAL TENSILE, STRESS AT ROP, 2.0 IN/MIN AT 77 DEG F, MULTIP=0031064.

$Y = ((+1.5790956E+03) + (-6.9748583E-02) * X)$
 $F = +3.0571794E-02$ SIGNIFICANCE OF F = NOT SIGNIFICANT $\sigma_r = +2.1340091E+02$
 $R = -2.0746164E-02$ SIGNIFICANCE OF R = NOT SIGNIFICANT $S_e = +3.9891000E-01$
 $t = +1.7484791E-01$ SIGNIFICANCE OF t = NOT SIGNIFICANT $S_e = +2.1485223E+02$
 $N = 73$ DEGREES OF FREEDOM = 71
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = 77 DEG F, AMB RH




Figure 4-10


*** LINEAR REGRESSION ANALYSIS ***

*** ANALYSIS OF TIME SERIES ***

AGE (MONTHS)	SPECIMENS PER GROUP	MEAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
70.0	10	+1.5165000E+03	+6.0491964E+01	+1.6050000E+03	+1.4140000E+03	+1.5742131E+03
83.0	10	+1.3110000E+03	+3.3476359E+01	+1.3900000E+03	+1.2700000E+03	+1.5733063E+03
95.0	10	+1.7880000E+03	+7.2541176E+01	+1.8800000E+03	+1.6800000E+03	+1.5724694E+03
107.0	10	+1.6205000E+03	+8.4929709E+01	+1.7300000E+03	+1.4500000E+03	+1.5716323E+03
120.0	5	+1.6143999E+03	+5.8624227E+01	+1.6720000E+03	+1.5200000E+03	+1.5707255E+03
135.0	3	+1.7933332E+03	+9.8657657E+01	+1.8600000E+03	+1.6800000E+03	+1.5698188E+03
148.0	8	+1.5312500E+03	+1.6699508E+02	+1.6840000E+03	+1.1760000E+03	+1.5689121E+03
155.0	2	+1.8875000E+03	+1.9445436E+02	+2.0250000E+03	+1.7500000E+03	+1.5682844E+03
234.0	6	+1.6463332E+03	+5.9948867E+01	+1.7510000E+03	+1.5740000E+03	+1.5627744E+03
252.0	4	+1.0552500E+03	+3.1573987E+01	+1.0900000E+03	+1.0280000E+03	+1.5615187E+03
262.0	5	+1.7315998E+03	+9.7022162E+01	+1.8890000E+03	+1.6560000E+03	+1.5608212E+03

UNIAXIAL TENSILE, MODULUS, 2.0 IN/MIN AT 77 DEG F, MOTOR=0031064.

Y = C 475.341430) + C -0.431264) * X
 SIGNIFICANCE OF T SIGNIFICANT
 SIGNIFICANCE OF R SIGNIFICANT
 SIGNIFICANCE OF L SIGNIFICANT
 DEGREES OF FREEDOM 68
 STORAGE COND - AMB TEMP/RH TEST COND : 77 DEG F
 MOTOR #0031064
 23.106483
 0.503608
 4.806919
 N = 70




STAGE III. MAX STRESS. LOW RATE TENSILE TEST. CHS-2.0

Figure 4-11

F = 0.575815
 R = 0.98558
 U = 0.822687
 N = 71

Y = (0.450438) + (0.000023) * X
 SIGNIFICANCE OF F = NOT SIGNIFICANT
 SIGNIFICANCE OF R = NOT SIGNIFICANT
 SIGNIFICANCE OF U = NOT SIGNIFICANT
 DEGREES OF FREEDOM = 69

STORAGE COND. AMB TEMP/RH TEST COND 77 DEG F
 MOTOR = 13104




STAGE III. STRAIN AT MAX STRESS. LOW RATE TENSILE TEST. CHS=2.0

Figure 4-12

Y = C 0.507471 2 + C 0.065062 3 * X
 SIGNIFICANCE OF F NOT SIGNIFICANT
 SIGNIFICANCE OF R NOT SIGNIFICANT
 SIGNIFICANCE OF U NOT SIGNIFICANT
 DEGREES OF FREEDOM = 69
 TEST COND = 77 DEG F
 STORAGE COND = AMB TEMP/RH
 MOTOR #0031064


0.327532
 0.068745
 0.572391
 N = 71



STAGE 100. STORAGE OF MOTOR #0031064 UNDER TEST. COND. 77

Figure 4-13

F = 21.089523
 R = -0.486542
 U = 4.592332
 N = 70
 STORAGE COND= AMB TEMP/RH
 TEST COND = 77 DEG F
 MOTOR #0031064
 Y = (458.653442) + (-0.456093) * X
 SIGNIFICANCE OF F = SIGNIFICANT
 SIGNIFICANCE OF R = SIGNIFICANT
 SIGNIFICANCE OF U = SIGNIFICANT
 DEGREES OF FREEDOM = 68
 QY = 54.473052
 SQ = 0.099316
 SF = 47.939437




STAGE III. STRESS AT RUPTURE. LOW RATE TENSILE TEST. CHS-2.0

Figure 4-14

$Y = (1662.997070) + (-0.741012) * X$
 F = 2.634711 SIGNIFICANCE OF F = NOT SIGNIFICANT QY = 222.931823
 K = -0.191781 SIGNIFICANCE OF R = NOT SIGNIFICANT S_D = 9.456519
 C = 1.623179 SIGNIFICANCE OF C = NOT SIGNIFICANT S_F = 220.373474
 N = 71 DEGREES OF FREEDOM = 69
 STORAGE COND = AMB TEMP/RH TEST COND = 77 DEG F MOTOR #: 0031064


PARAMETER = MODULUS
 UNIT OF MEASURE = PSI
 *10³



STAGE III, MODULUS. LOW RATE TENSILE TEST. CHS-2.0

Figure 4-15

$Y = ((+4.1611572E+02) + (-4.4680375E-02) \cdot X)$
 $F = +1.9428884E-01$ SIGNIFICANCE OF F = NOT SIGNIFICANT $G_1 = +5.5142470E+01$
 $R = -5.1521124E-02$ SIGNIFICANCE OF R = NOT SIGNIFICANT $S_0 = +1.0136613E-01$
 $t = +4.4078208E-01$ SIGNIFICANCE OF t = NOT SIGNIFICANT $S_1 = +5.5445139E+01$
 $N = 75$ DEGREES OF FREEDOM = 73
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = 77 DEG F, AMB RH



UNIAXIAL TENSILE, MAXIMUM STRESS, 2.0 IN/MIN AT 77 DEG F, MOTOR=0031134.

Figure 4-16


*** LINEAR REGRESSION ANALYSIS ***

*** ANALYSIS OF TIME SERIES ***

AGE (MONTHS)	SPECIMENS PER GROUP	MEAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
67.0	10	+3.0769925E+02	+1.5434809E+01	+3.3000000E+02	+2.8700000E+02	+4.1312207E+02
80.0	9	+4.3433325E+02	+1.8881207E+01	+4.6000000E+02	+4.1500000E+02	+4.1254125E+02
92.0	10	+4.6250000E+02	+5.8925565E+00	+4.7500000E+02	+4.5500000E+02	+4.1200488E+02
104.0	10	+4.4089990E+02	+2.802447E+01	+4.7300000E+02	+4.0000000E+02	+4.1146875E+02
116.0	5	+3.7087988E+02	+9.1243210E+00	+3.8319995E+02	+3.6000000E+02	+4.1093261E+02
130.0	5	+4.6559985E+02	+7.7974354E+00	+4.7200000E+02	+4.5200000E+02	+4.1030712E+02
143.0	7	+4.5821118E+02	+4.8467680E+01	+5.2289990E+02	+4.0447998E+02	+4.0972631E+02
152.0	3	+3.9598315E+02	+4.7279058E+00	+3.9975000E+02	+3.9068994E+02	+4.0932421E+02
230.0	6	+3.8656152E+02	+5.6911173E+00	+3.9211987E+02	+3.7658984E+02	+4.0583911E+02
249.0	5	+3.7834375E+02	+7.5887701E+00	+3.3920996E+02	+3.6993994E+02	+4.0499023E+02
253.0	5	+3.9101977E+02	+4.0537609E+00	+3.9761987E+02	+3.8692993E+02	+4.0458813E+02

UNIAxIAL TENSILE, MAXIMUM STRESS, 2.0 IN/MIN AT 77 DEG F, MOTOR=0031134.

$F = +3.0130109E+01$ SIGNIFICANCE OF $F =$ SIGNIFICANT
 $R = -5.7807683E-01$ SIGNIFICANCE OF $R =$ SIGNIFICANT
 $t = +6.0113367E+00$ SIGNIFICANCE OF $t =$ SIGNIFICANT
 $N = 74$ DEGREES OF FREEDOM = 72
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = 77 DEG F, AMB RH




UNIAXIAL TENSILE, MAXIMUM STRESS, 2.0 IN/MIN AT 77 DEG F, MOTOR=0032434.

Figure 4-26

01 17210
 02 00000
 03 00000
 04 00000
 05 00000
 06 00000
 07 00000
 08 00000
 09 00000
 10 00000
 11 00000
 12 00000
 13 00000
 14 00000
 15 00000
 16 00000
 17 00000
 18 00000
 19 00000
 20 00000
 21 00000
 22 00000
 23 00000
 24 00000
 25 00000
 26 00000
 27 00000
 28 00000
 29 00000
 30 00000
 31 00000
 32 00000
 33 00000
 34 00000
 35 00000
 36 00000
 37 00000
 38 00000
 39 00000
 40 00000
 41 00000
 42 00000
 43 00000
 44 00000
 45 00000
 46 00000
 47 00000
 48 00000
 49 00000
 50 00000
 51 00000
 52 00000
 53 00000
 54 00000
 55 00000
 56 00000
 57 00000
 58 00000
 59 00000
 60 00000
 61 00000
 62 00000
 63 00000
 64 00000
 65 00000
 66 00000
 67 00000
 68 00000
 69 00000
 70 00000
 71 00000
 72 00000
 73 00000
 74 00000
 75 00000
 76 00000
 77 00000
 78 00000
 79 00000
 80 00000
 81 00000
 82 00000
 83 00000
 84 00000
 85 00000
 86 00000
 87 00000
 88 00000
 89 00000
 90 00000
 91 00000
 92 00000
 93 00000
 94 00000
 95 00000
 96 00000
 97 00000
 98 00000
 99 00000
 100 00000


PARAMETER = MODULUS
 UNIT OF MEASURE = PSI
 *10⁶



STAGE III. MODULUS. LOW RATE TEST. 1000 PSI.

Figure 4-25

Y = (390.808349) + (-0.024805) * X
 SIGNIFICANCE OF F = NOT SIGNIFICANT
 SIGNIFICANCE OF R = NOT SIGNIFICANT
 SIGNIFICANCE OF U = NOT SIGNIFICANT
 DEGREES OF FREEDOM = 68
 STORAGE COND = AMB TEMP/RH TEST COND = 77 DEC F MOTOR #0031134



STAGE III. STRESS AT RUPTURE. LOW RATE TENSILE TEST. CHS-20

Figure 4-24

$Y = (0.497603) + (0.000061) * X$
 F = 2.033417
 R = 0.170396
 C = 1.425979
 N = 70
 STORAGE COND = AMB TEMP/RH
 TEST COND = 77 DEG F
 MOTOR #0031134
 SIGNIFICANCE OF F = NOT SIGNIFICANT
 SIGNIFICANCE OF R = NOT SIGNIFICANT
 SIGNIFICANCE OF C = NOT SIGNIFICANT
 DEGREES OF FREEDOM = 68
 QY = 0.019907
 S₀ = 0.000043
 S_F = 0.019760




Figure 4-23

F = 14.210792
 R = 0.415762
 C = 3.769721
 N = 70
 STORAGE COND = AMB TEMP/RH
 TEST COND = 77 DEG F
 MOTOR #0031134
 Y = (0.429968) + (0.000121) * X
 SIGNIFICANCE OF F = SIGNIFICANT
 SIGNIFICANCE OF R = SIGNIFICANT
 SIGNIFICANCE OF C = SIGNIFICANT
 DEGREES OF FREEDOM = 68
 GY = 0.016301
 SD = 0.000032
 SE = 0.014934





Figure 4-22

Y = C 411844300) * C -0 000530) * X
 SIGNIFICANT OF F - NOT SIGNIFICANT
 SIGNIFICANT OF R - NOT SIGNIFICANT
 SIGNIFICANT OF T - NOT SIGNIFICANT
 DEGREES OF FREEDOM = 68
 STORAGE COND = AMB TEMPRH TEST COND = 77 DEG F
 MOTOR #0031134

STRESS = MAX STRESS
 STRESS = PSI
 *10³



STAGE III. MAX STRESS FOR REF TUNNEL TO 1000 YRS

Figure 4-21


*** LINEAR REGRESSION ANALYSIS ***

*** ANALYSIS OF TIME SERIES ***

AGE (MONTHS)	SPECIMENS PER GROUP	MEAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
67.0	10	+1.2180000E+03	+5.1415518E+01	+1.2960000E+03	+1.1170000E+03	+1.6084995E+03
80.0	9	+1.6044443E+03	+7.8751366E+01	+1.7600000E+03	+1.4900000E+03	+1.6044455E+03
92.0	10	+1.8190000E+03	+8.3982802E+01	+1.9600000E+03	+1.6800000E+03	+1.6007033E+03
104.0	10	+1.8335000E+03	+1.7769683E+02	+2.1200000E+03	+1.5600000E+03	+1.5969611E+03
116.0	5	+1.6240000E+03	+1.2837445E+02	+1.8400000E+03	+1.5200000E+03	+1.5932189E+03
130.0	5	+1.4815998E+03	+4.8236915E+01	+1.5600000E+03	+1.4400000E+03	+1.5888530E+03
143.0	7	+1.6155712E+03	+1.5194665E+02	+1.8380000E+03	+1.4280000E+03	+1.5847990E+03
152.0	3	+1.7193332E+03	+1.5947811E+01	+1.7300000E+03	+1.7010000E+03	+1.5819924E+03
230.0	6	+1.5415000E+03	+5.8776696E+01	+1.5950000E+03	+1.4490000E+03	+1.5576682E+03
249.0	5	+1.5577998E+03	+1.2503079E+02	+1.6900000E+03	+1.3700000E+03	+1.5517431E+03
258.0	5	+1.3845998E+03	+3.1141612E+01	+1.4340000E+03	+1.3540000E+03	+1.5489365E+03

UNIAXIAL TENSILE, MODULUS, 2.0 IN/MIN AT 77 DEG F, MOTOR=0031134.

$Y = ((+1.6293935E+03) + (-3.1184851E-01) \cdot X)$
 $F = +5.9961404E-01$ SIGNIFICANCE OF F = NOT SIGNIFICANT $\sigma_t = +2.1968493E+02$
 $R = -9.0260582E-02$ SIGNIFICANCE OF R = NOT SIGNIFICANT $S_e = +4.0272425E-01$
 $t = +7.7434749E-01$ SIGNIFICANCE OF t = NOT SIGNIFICANT $S_e = +2.2028167E+02$
 $N = 75$ DEGREES OF FREEDOM = 73
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = 77 DEG F, AMB RH



UNIAXIAL TENSILE, MODULUS, 2.0 IN/MIN AT 77 DEG F, MOTOR=0031134.

Figure 4-20


*** LINEAR REGRESSION ANALYSIS ***

** ANALYSIS OF TIME SERIES **

AGE (MONTHS)	NO. OF GROUPS	MEAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
17.0	10	+2.3000000E+02	+1.7422345E+01	+3.1900000E+02	+2.6600000E+02	+3.9042700E+02
20.0	9	+4.1333325E+02	+1.8027750E+01	+4.4000000E+02	+3.9000000E+02	+3.8961279E+02
22.0	10	+4.4050000E+02	+1.0394977E+01	+4.3500000E+02	+4.2000000E+02	+3.8886132E+02
104.0	10	+4.3029930E+02	+2.7593497E+01	+4.6200000E+02	+3.8800000E+02	+3.8810986E+02
116.0	5	+3.2305981E+02	+1.5111311E+01	+3.4600000E+02	+3.0400000E+02	+3.8735815E+02
120.0	5	+4.2479980E+02	+1.3682105E+01	+4.4400000E+02	+4.0800000E+02	+3.8648144E+02
143.0	7	+4.3488549E+02	+4.7433711E+01	+5.0000000E+02	+3.8270980E+02	+3.8560723E+02
157.0	3	+3.7214040E+02	+1.0670349E+00	+3.7329930E+02	+3.7123999E+02	+3.8510375E+02
200.0	6	+2.6613047E+02	+7.8439047E+00	+3.7302978E+02	+3.5789990E+02	+3.8021875E+02
226.0	5	+3.5139379E+02	+3.5397609E+00	+3.6400000E+02	+3.4150976E+02	+3.7902880E+02
250.0	5	+3.6634790E+02	+2.9591179E+00	+3.7019995E+02	+3.6195996E+02	+3.7846533E+02

COAXIAL TENSILE, STRESS AT RUP, 2.0 IN/MIN AT 77 DEG F, GUTOP=0031134.

$Y = ((+3.9462305E+02) + (-6.2626546E-02) \cdot X)$
 $F = +3.5878084E-01$ SIGNIFICANCE OF F = NOT SIGNIFICANT $\sigma_r = +5.6940938E+01$
 $R = -6.9934032E-02$ SIGNIFICANCE OF R = NOT SIGNIFICANT $S_e = +1.0455476E-01$
 $t = +5.9898317E-01$ SIGNIFICANCE OF t = NOT SIGNIFICANT $S_r = +5.7189253E+01$
 $N = 75$ DEGREES OF FREEDOM = 73
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = 77 DEG F, AMB RH



UNIAXIAL TENSILE, STRESS AT RUP, 2.0 IN/MIN AT 77 DEG F, MOTOR=0031134.

Figure 4-19

**** LINEAR REGRESSION ANALYSIS ****

*** ANALYSIS OF TML SERIES ***

AGE (MONTHS)	SPECIMENS PER GROUP	MEAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
67.0	10	+5.0469958E-01	+1.8627096E-02	+5.2199995E-01	+4.5899999E-01	+5.0207930E-01
80.0	9	+5.0422191E-01	+1.3313103E-02	+5.2499997E-01	+4.7999995E-01	+5.0271344E-01
92.0	10	+4.9919962E-01	+9.6415934E-03	+5.1999998E-01	+4.8999994E-01	+5.0329881E-01
104.0	10	+4.7909963E-01	+1.4387741E-02	+5.0699996E-01	+4.5299994E-01	+5.0388425E-01
116.0	5	+5.2399957E-01	+7.6926053E-03	+5.3299999E-01	+5.1499998E-01	+5.0446963E-01
130.0	5	+5.3979969E-01	+9.3947854E-03	+5.4799997E-01	+5.2599996E-01	+5.0515258E-01
143.0	7	+5.0805664E-01	+1.6074084E-02	+5.2399998E-01	+4.8399996E-01	+5.0578677E-01
152.0	3	+5.1086016E-01	+6.8253874E-03	+5.1699995E-01	+5.0359994E-01	+5.0622582E-01
230.0	6	+4.9684953E-01	+1.4488414E-02	+5.1899999E-01	+4.8429995E-01	+5.1003080E-01
249.0	5	+5.2027946E-01	+6.8153711E-03	+5.2759999E-01	+5.1199996E-01	+5.1095771E-01
258.0	5	+5.0755977E-01	+1.2365844E-02	+5.2339994E-01	+4.8999994E-01	+5.1139676E-01

UNIAXIAL TENSILE, STRAIN AT RUP, 2.0 IN/MIN AT 77 DEG F, MOTOR=0031134.

$Y = ((+4.9881089E-01) + (+4.8782478E-05) \cdot X)$
 $F = +1.9058392E+00$ SIGNIFICANCE OF F = NOT SIGNIFICANT $S_y = +1.9446135E-02$
 $R = +1.5950903E-01$ SIGNIFICANCE OF R = NOT SIGNIFICANT $S_e = +3.5336271E-05$
 $t = +1.3805213E+00$ SIGNIFICANCE OF t = NOT SIGNIFICANT $S_e = +1.9328196E-02$
 $N = 75$ DEGREES OF FREEDOM = 73
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = 77 DEG F, AMB RH




Figure 4-18


*** LINEAR REGRESSION ANALYSIS ***

*** ANALYSIS OF TIME SERIES ***

AGE (MONTHS)	SPECIMENS PER GROUP	MEAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
67.0	10	+4.2069951E-01	+6.5335333E-03	+4.3499994E-01	+4.1199994E-01	+4.3861281E-01
80.0	9	+4.4159901E-01	+3.8898424E-03	+4.4499999E-01	+4.3499994E-01	+4.3999475E-01
92.0	10	+4.3879956E-01	+9.4774412E-03	+4.5199996E-01	+4.1999995E-01	+4.4127029E-01
104.0	10	+4.3569952E-01	+1.1444890E-02	+4.6099996E-01	+4.1999995E-01	+4.4254589E-01
116.0	5	+4.4339978E-01	+1.5780289E-03	+4.4499999E-01	+4.4199997E-01	+4.4382148E-01
130.0	5	+4.8359966E-01	+2.2278151E-03	+4.3599994E-01	+4.7999995E-01	+4.4530969E-01
143.0	7	+4.5838946E-01	+1.2331770E-02	+4.7029995E-01	+4.3599998E-01	+4.4669157E-01
152.0	3	+4.5673304E-01	+4.2207913E-03	+4.6149998E-01	+4.5369994E-01	+4.4764822E-01
200.0	6	+4.4186639E-01	+1.4435750E-03	+4.4299995E-01	+4.3989998E-01	+4.5593953E-01
249.0	5	+4.5883959E-01	+3.0737838E-03	+4.6309995E-01	+4.5529997E-01	+4.5795923E-01
258.0	5	+4.5407980E-01	+8.4506896E-03	+4.5969998E-01	+4.3939995E-01	+4.5891588E-01

UNIAXIAL TENSILE, STRAIN AT MAX, 2.0 IN/MIN AT 77 DEG F. MOTOR=0031134.

$Y = ((+4.3149085E-01) + (+1.0629880E-04) * X)$
 $F = +1.5793670E+01$ SIGNIFICANCE OF F = SIGNIFICANT $G_1 = +1.6026274E-02$
 $R = +4.2174557E-01$ SIGNIFICANCE OF R = SIGNIFICANT $S_0 = +2.6747724E-05$
 $t = +3.9741251E+00$ SIGNIFICANCE OF t = SIGNIFICANT $S_z = +1.4630441E-02$
 $N = 75$ DEGREES OF FREEDOM = 73
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = 77 DEG F, AMB RH



UNIAXIAL TENSILE, STRAIN AT MAX, 2.0 IN/MIN AT 77 DEG F, MOTOR=0031134.

Figure 4-17


*** LINEAR REGRESSION ANALYSIS ***

*** ANALYSIS OF TIME SERIES ***

AGE (MONTHS)	SPECIMENS PER GROUP	MEAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
55.0	10	+3.6519995E+02	+7.4206917E+00	+3.7800000E+02	+3.5300000E+02	+4.1057177E+02
68.0	9	+4.1766650E+02	+4.3588989E+00	+4.2500000E+02	+4.1200000E+02	+4.0600732E+02
80.0	10	+4.2600000E+02	+5.6764621E+00	+4.3500000E+02	+4.1500000E+02	+4.0179370E+02
92.0	9	+4.1011108E+02	+9.6234666E+00	+4.2600000E+02	+4.0000000E+02	+3.9758007E+02
105.0	5	+3.5493994E+02	+7.6270894E+00	+3.6769995E+02	+3.4859985E+02	+3.9301562E+02
118.0	5	+4.2479980E+02	+1.6828547E+01	+4.4400000E+02	+4.0000000E+02	+3.8845092E+02
132.0	7	+4.0461132E+02	+7.6758767E+00	+4.1407983E+02	+3.9369995E+02	+3.8353515E+02
140.0	3	+3.6965991E+02	+5.6246394E+00	+3.7547998E+02	+3.6425976E+02	+3.8072607E+02
219.0	0	+3.7386474E+02	+5.1658409E+00	+3.7870996E+02	+3.6489990E+02	+3.5298730E+02
237.0	5	+2.8734179E+02	+2.5263873E+01	+3.3164990E+02	+2.7060986E+02	+3.4666699E+02
246.0	5	+3.5542773E+02	+4.6699180E+00	+3.6206982E+02	+3.5150000E+02	+3.4350683E+02

UNIAXIAL TENSILE, MAXIMUM STRESS, 2.0 IN/MIN AT 77 DEG F, MOTOR=0032434.

$Y = N + 3.8666957E-01 + (-1.2937058E-05) \cdot X$
 F = +2.5147601E-01 SIGNIFICANCE OF F = NOT SIGNIFICANT $\sigma_1 = +1.4045747E-02$
 R = -5.8996320E-02 SIGNIFICANCE OF R = NOT SIGNIFICANT $S_e = +2.5798071E-05$
 t = +5.0147384E-01 SIGNIFICANCE OF t = NOT SIGNIFICANT $S_e = +1.4118316E-02$
 N = 74 DEGREES OF FREEDOM = 72
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = 77 DEG F, AMB RH



UNIAXIAL TENSILE, STRAIN AT MAX. 2.0 IN/MIN AT 77 DEG F, MOTOR=0032434.

Figure 4-27


*** LINLAR REGRESSION ANALYSIS ***

*** ANALYSIS OF TIME SERIES ***

AGE (MONTHS)	SPECIMENS PLR GROUP	MEAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
55.0	10	+3.9259964E-01	+9.2447333E-03	+4.1199994E-01	+3.8199996E-01	+3.8595801E-01
68.0	9	+3.7788856E-01	+6.3218515E-03	+3.8599997E-01	+3.6799997E-01	+3.8578981E-01
80.0	10	+3.8299947E-01	+5.9690495E-03	+3.9499998E-01	+3.7500000E-01	+3.8563460E-01
92.0	9	+3.8277751E-01	+1.0257653E-02	+3.9799994E-01	+3.6299997E-01	+3.8547933E-01
105.0	5	+3.6459976E-01	+3.5242881E-03	+3.6999994E-01	+3.6099994E-01	+3.8531118E-01
118.0	5	+3.9999979E-01	+1.2089275E-02	+4.1199994E-01	+3.7999999E-01	+3.8514298E-01
132.0	7	+4.0061390E-01	+9.1882850E-03	+4.0899997E-01	+3.8249999E-01	+3.8496184E-01
140.0	3	+3.9236640E-01	+9.0313813E-04	+3.9279997E-01	+3.9149999E-01	+3.8485836E-01
219.0	6	+3.6753284E-01	+3.0124252E-03	+3.7199997E-01	+3.6409997E-01	+3.8383632E-01
237.0	5	+4.0459972E-01	+7.8216063E-03	+4.0989995E-01	+3.9089995E-01	+3.8360345E-01
246.0	5	+3.7255972E-01	+1.7066662E-03	+3.7409996E-01	+3.7019997E-01	+3.8348704E-01

UNIAXIAL TENSILE, STRAIN AT MAX, 2.0 IN/MIN AT 77 DEG F, MOTOR=0032434.

$Y = ((+4.5263761E-01) + (+3.1734931E-05) * X)$
 F = +6.6628501E-01 SIGNIFICANCE OF F = NOT SIGNIFICANT $S_y = +2.1227960E-02$
 R = +9.5755459E-02 SIGNIFICANCE OF R = NOT SIGNIFICANT $S_e = +3.8878324E-05$
 t = +8.1626283E-01 SIGNIFICANCE OF t = NOT SIGNIFICANT $S_e = +2.1276648E-02$
 N = 74 DEGREES OF FREEDOM = 72
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = 77 DEG F, AMB RH



UNIAxIAL TENSILE, STRAIN AT RUP. 2.0 IN/MIN AT 77 DEG F, MOTOR=0032434.

Figure 4-28


*** LINEAR REGRESSION ANALYSIS ***

*** ANALYSIS OF TIME SERIES ***

AGE (MONTHS)	SPECIMENS PER GROUP	MEAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
55.0	10	+4.7279953E-01	+1.0355348E-02	+4.8299998E-01	+4.5099997E-01	+4.5438301E-01
68.0	9	+4.4233310E-01	+2.3943043E-02	+4.5499998E-01	+3.7999999E-01	+4.5479553E-01
80.0	10	+4.4979971E-01	+8.8202296E-03	+4.6499997E-01	+4.3499994E-01	+4.5517641E-01
92.0	9	+4.4355517E-01	+1.7345953E-02	+4.8199999E-01	+4.2299997E-01	+4.5555722E-01
105.0	5	+4.5199966E-01	+1.0942681E-02	+4.6599996E-01	+4.3599998E-01	+4.5596975E-01
118.0	5	+4.5959967E-01	+2.6514381E-02	+4.7999995E-01	+4.1399997E-01	+4.5638233E-01
132.0	7	+4.6807098E-01	+2.1198064E-02	+4.9199998E-01	+4.4549995E-01	+4.5682662E-01
140.0	3	+4.6969985E-01	+5.2236655E-03	+4.7439998E-01	+4.6409994E-01	+4.5708048E-01
219.0	6	+4.3948298E-01	+9.4050625E-03	+4.5309996E-01	+4.2699998E-01	+4.5958751E-01
237.0	5	+4.9031943E-01	+2.1911117E-02	+5.0709998E-01	+4.5309996E-01	+4.6015876E-01
246.0	5	+4.4979971E-01	+5.7274727E-03	+4.5969998E-01	+4.4489997E-01	+4.6044439E-01

UNIAXIAL TENSILE, STRAIN AT RUP, 2.0 IN/MIN AT 77 DEG F, MOTOR=0032434.

$Y = ((+4.1105007E+02) + (-4.3049291E-01) * X)$
 $F = +3.0713179E+01$ SIGNIFICANCE OF F = SIGNIFICANT $\sigma_r = +5.0425585E+01$
 $R = -5.4682618E-01$ SIGNIFICANCE OF R = SIGNIFICANT $S_o = +7.7678998E-02$
 $t = +5.5419472E+00$ SIGNIFICANCE OF t = SIGNIFICANT $S_r = +4.2510801E+01$
 $N = 74$ DEGREES OF FREEDOM = 72
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = 77 DEG F, AMB RH



UNIAXIAL TENSILE, STRESS AT RUP, 2.0 IN/MIN AT 77 DEG F, MOTOR=0032434.

Figure 4-29


*** LINEAR REGRESSION ANALYSIS ***

*** ANALYSIS OF TIME SERIES ***

AGE (MONTHS)	SPECIMENS PER GROUP	MEAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
55.0	10	+3.307980E+02	+1.2025897E+01	+3.6200000E+02	+3.1900000E+02	+3.8737280E+02
65.0	9	+3.9766050E+02	+7.8421935E+00	+4.1000000E+02	+3.3500000E+02	+3.8177636E+02
80.0	10	+4.050000E+02	+1.3550317E+01	+4.2000000E+02	+3.8000000E+02	+3.7661059E+02
95.0	9	+4.157758E+02	+4.1321234E+01	+4.3900000E+02	+3.7800000E+02	+3.7144458E+02
105.0	5	+3.0491992E+02	+1.6209525E+01	+3.2400000E+02	+2.8700000E+02	+3.6584814E+02
115.0	5	+3.3639990E+02	+1.3445169E+01	+4.0300000E+02	+3.7200000E+02	+3.6025170E+02
125.0	7	+3.6873413E+02	+2.3699068E+01	+3.9200000E+02	+3.3700000E+02	+3.5422485E+02
140.0	3	+3.2003320E+02	+1.4503175E+01	+3.3507563E+02	+3.0614990E+02	+3.5078100E+02
219.0	6	+3.3743310E+02	+1.0050703E+01	+3.4821997E+02	+3.2377978E+02	+3.1677197E+02
257.0	5	+2.5543193E+02	+3.0092872E+01	+3.0797998E+02	+2.3602999E+02	+3.0502319E+02
340.0	5	+3.1782788E+02	+5.1664740E+00	+3.2650000E+02	+3.1362988E+02	+3.0514868E+02

UNIAXIAL TENSILE, STRESS AT RUP, 2.0 IN/MIN AT 77 DEG F, MOUR=0032434.

$Y = ((+1.9918492E+03) + (-2.6491964E-02) \cdot X)$
 $F = +2.4691717E-03$ SIGNIFICANCE OF F = NOT SIGNIFICANT $\sigma_f = +2.8976535E+02$
 $R = -5.8560119E-03$ SIGNIFICANCE OF R = NOT SIGNIFICANT $S_e = +5.3313663E-01$
 $t = +4.9690760E-02$ SIGNIFICANCE OF t = NOT SIGNIFICANT $S_e = +2.9176567E+02$
 $N = 74$ DEGREES OF FREEDOM = 72
 STORAGE CONDITIONS = AMB TEMP/RH TEST CONDITIONS = 77 DEG F, AMB RH



UNIAXIAL TENSILE, MODULUS, 2.0 IN/MIN AT 77 DEG F, MOTOR=0032434.

Figure 4-30

*** LINEAR REGRESSION ANALYSIS ***


*** ANALYSIS OF TIME SERIFS ***

AGE (MONTHS)	SPECIMENS PER GROUP	MEAN Y	STANDARD DEVIATION	MAXIMUM Y	MINIMUM Y	REGRESSION Y
55.0	10	+1.7457998E+03	+1.0883606E+02	+1.9130000E+03	+1.6120000E+03	+1.9903920E+03
68.0	9	+2.0177775E+03	+9.5751994E+01	+2.2200000E+03	+1.9000000E+03	+1.9900476E+03
80.0	10	+2.1310000E+03	+5.8581377E+01	+2.2000000E+03	+2.0400000E+03	+1.9897297E+03
92.0	9	+2.2450000E+03	+7.5920188E+01	+2.3500000E+03	+2.1550000E+03	+1.9894118E+03
105.0	5	+1.9663999E+03	+3.4129166E+01	+2.0000000E+03	+1.9200000E+03	+1.9890673E+03
118.0	5	+1.9760000E+03	+8.7338422E+01	+2.1100000E+03	+1.9100000E+03	+1.9887231E+03
132.0	7	+1.8184284E+03	+9.6931861E+01	+1.9460000E+03	+1.7130000E+03	+1.9883522E+03
140.0	3	+2.0216665E+03	+2.6274195E+01	+2.0420000E+03	+1.9920000E+03	+1.9881401E+03
219.0	6	+2.0746665E+03	+7.6217233E+01	+2.2190000E+03	+1.9980000E+03	+1.9860473E+03
237.0	5	+1.2900000E+03	+1.8377567E+02	+1.5980000E+03	+1.1140000E+03	+1.9855705E+03
246.0	5	+2.5243999E+03	+1.5353110E+02	+2.7300000E+03	+2.3880000E+03	+1.9853320E+03

UNIAXIAL TENSILE, MODULUS, 2.0 IN/MIN AT 77 DEG F, MOTOR=0032434.

Y = (434.107299) (0.392357) * X
 SIGNIFICANCE OF T - SIGNIFICANT
 SIGNIFICANCE OF R - SIGNIFICANT
 SIGNIFICANCE OF C - SIGNIFICANT
 DEGREES OF FREEDOM - 69
 STORAGE COND = AMB TEMP/RH TEST COND = 77 DEG F MOTOR #0032434
 F = 31.802787
 R = 0.561690
 C = 5.639394
 N = 71
 QY = 39.023040
 SD = 0.069574
 SE = 32.518753

PARAMETER = MAX STRESS
 UNIT OF MEASURE = PSI
 * 10⁴
 0.00 5.00 10.00 15.00 20.00 25.00 30.00 35.00 40.00 45.00 50.00




STRESS IS MAX STRESS. LOW RATIO TENSILE TEST. CUS 2.0

Figure 4-31

Y = (0.383260) + (0.000023) * X
 SIGNIFICANCE OF F = NOT SIGNIFICANT
 SIGNIFICANCE OF R = NOT SIGNIFICANT
 SIGNIFICANCE OF U = NOT SIGNIFICANT
 DEGREES OF FREEDOM = 68
 STORAGE COND= AMB TEMP/RH TEST COND = 77 DEG F MOTOR #0032434

PARAMETER = STRAIN AT MAX STRESS
 UNIT OF MEASURE = INCH/INCH

0.48
 0.44
 0.40
 0.36
 0.32
 0.28
 0.24
 0.20
 0.16
 0.12
 0.08
 0.04
 0.00



0.00 3.00 6.00 9.00 12.00 15.00 18.00 21.00 24.00
 AGE AT TEST (YEARS)
 STRAIN AT MAX STRESS, LOW RH TEST, 77 DEG F

Figure 4-32

F = 1.995180
R = 0.168833
C = 1.412508
N = 70

SIGNIFICANCE OF F = NOT SIGNIFICANT
SIGNIFICANCE OF R = NOT SIGNIFICANT
SIGNIFICANCE OF C = NOT SIGNIFICANT
DEGREES OF FREEDOM = 68
TEST COND = 77 DEG F

QY = 0.021751
S_b = 0.000046
S_f = 0.021596

STORAGE COND = AMB TEMP/RH
MOTOR #0032434




Figure 4-33

F = 26.274162
R = -0.525142
L = 5.125831
N = 71

SIGNIFICANCE OF F = SIGNIFICANT
SIGNIFICANCE OF R = SIGNIFICANT
SIGNIFICANCE OF L = SIGNIFICANT
DEGREES OF FREEDOM = 69
TEST COND = 77 DEG F

STORAGE COND = AMB TEMP/RH

Q1 = 50.458129
S_a = 0.092238
S_f = 43.250640

MOTOR #0032434

PARAMETER = STRESS AT RUPTURE
UNIT OF MEASURE = PSI
* 10³




Figure 4-34

K = 0.371735
 U = 3.326478
 N = 71

SIGNIFICANCE OF K = SIGNIFICANT
 SIGNIFICANCE OF U = SIGNIFICANT
 DEGREES OF FREEDOM = 69

ST = 240.129455

STORAGE COND= AMB TEMP/RH

TEST COND = 77 DEG F

MOTOR #0032434




Figure 4-35