	1.0									28			2.5
						3.2			2.2
						3.6	
	1.1				4.5			2.0
							1.8
		1.25			1.4			1.6

MICROCOPY RESOLUTION TEST CHART

NATIONAL BUREAU OF STANDARDS

AVRADCOM
Report No. TR-82-F-1

AD

MANUFACTURING METHODS AND TECHNOLOGY (MANTECH) PROGRAM MANUFACTURING TECHNIQUES FOR A COMPOSITE TAIL SECTION FOR THE ADVANCED ATTACK HELICOPTER

J.V. ALEXANDER
R.E. HEAD

AD A121172

October 1981   FINAL REPORT

Contract No. DAAK50-78-G-0004
DO 0002

NOV 0 8 1982

E

UNITED STATES ARMY
AVIATION RESEARCH AND DEVELOPMENT COMMAND

J96

SECURITY CLASSIFICATION OF THIS PAGE *(When Data Entered)*

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER USAAVRADCOM TR-32-F-1	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE *(and Subtitle)* Manufacturing Techniques for a Composite Tail Section for the Advanced Attack Helicopter		5. TYPE OF REPORT & PERIOD COVERED Final Report Sept. 1979 - April 1981
		6. PERFORMING ORG. REPORT NUMBER HHI 81-367
7. AUTHOR(s) J. V. Alexander R. E. Head		8. CONTRACT OR GRANT NUMBER(s) DAAK50-78-G-0004 (DO-0002)
9. PERFORMING ORGANIZATION NAME AND ADDRESS Hughes Helicopters, Inc. Centinela and Teale Streets Culver City, CA 90230		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS Project No. 7333
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Aviation Research and Development Command, Attn: DRDAV-EGX, 4300 Goodfellow Blvd., St. Louis, MO 63120		12. REPORT DATE October 1931
		13. NUMBER OF PAGES
14. MONITORING AGENCY NAME & ADDRESS*(if different from Controlling Office)*		15. SECURITY CLASS. *(of this report)* Unclassified
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE

16. DISTRIBUTION STATEMENT *(of this Report)*

Approved for public release; distribution unlimited

17. DISTRIBUTION STATEMENT *(of the abstract entered in Block 20, if different from Report)*

18. SUPPLEMENTARY NOTES

19. KEY WORDS *(Continue on reverse side if necessary and identify by block number)*

Fuselage	Antenna Pattern	Fabrication	Kevlar
Empennage	Lightning Protection	Resin	Nomex
Composite Structure	Tooling	Graphite	Electrolysis
Ballistic Survivability			

20. ABSTRACT *(Continue on reverse side if necessary and identify by block number)*

This manufacturing methods and technology program involved the study of establishing manufacturing methods for a Composite Tail Section (CTS) for the AH-64A Advanced Attack Helicopter by the wet filament wound, cocure process. The CTS was meant to replace equivalent metal components on the AH-64A while providing potential weight and cost savings. Ballistic tolerance against 23mm HEI-T was demonstrated, and VHF antenna

DD FORM 1473 EDITION OF 1 NOV 65 IS OBSOLETE

20. performance was shown to be unaffected by the change to composite construction. The program was terminated for fiscal reasons just when the CTS design was completed and the tooling design was within one month of completion. This CTS concept offers significant benefits to the AH-64A helicopter program and should be reinstated at the earliest opportunity.

PREFACE

This report was prepared by Hughes Helicopters, Inc. (HHI) under U.S.
Army Basic Ordering Agreement DAAK50-78-G-0004, Delivery Order 0002.
The contract was sponsored by the U.S. Army Aviation Research and
Development Command (AVRADCOM) and administered under the technical
direction of Mr. James Tutka, AVRADCOM, with assistance from Mr.
Nicholas Calapodas, Applied Technology Laboratory, Ft. Eustis, VA.

The technical tesks were conducted under the direction of HHI's program
managers, Messrs. Nicholas Mocerino and Robert Head, and Mr. Sherwood
Twitchell, the project engineer at Fiber Science, Inc., the major sub-
contractor for tooling and fabrication.

Accession For	
NTIS GRA&I	X
DTIC TAB	
Unannounced	
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A	

TABLE OF CONTENTS

TABLE OF CONTENTS (CONT)

LIST OF ILLUSTRATIONS

LIST OF ILLUSTRATIONS (CONT)

LIST OF ILLUSTRATIONS (CONT)

LIST OF ILLUSTRATIONS (CONT)

LIST OF TABLES

LIST OF TABLES (CONT)

INTRODUCTION

In August, 1979, Hughes Helicopters, Inc. (HHI) was awarded a contract under a Manufacturing Methods and Technology (MM&T) program to develop and refine the manufacturing processes necessary to fabricate and test a set number of Composite Tail Sections (CTS) for the AH-64A Advanced Attack Helicopter (AAH). Anticipated benefits resulting from this MM&T program were reduced weight and cost, and improved survivability, reliability, and maintainability.

The CTS program as initially defined required that the aft portion of the tailboom, the vertical tail spar, and the horizontal tail be the primary composite structure. See Figure 1. Existing fairings from the prototype design such as those for the leading and trailing edges of the vertical tail, driveshaft cover, and aft tailboom fairing were to be transferred to the CTS. The CTS was to accommodate all existing mounts for the gearboxes, controls, tail wheel, etc.

STA 450

Figure 1. AH-64A - Initial CTS Configuration

13

The CTS technology was based on work HHI had done previously in concert with Fiber Science, Inc. (FSI) for a composite tail assembly for the AH-1G helicopter (Reference 1), a composite main rotor blade for the AH-1G (Reference 2), and a composite landing gear for the AH-64A (Reference 3). These components were fabricated by the wet filament winding, cocure process and this process was to be carried over into the CTS program. HHI had overall program responsibility, did the design refinement work, and was to conduct all laboratory and flight testing. FSI was responsible for optimizing the tooling and fabrication processes for the CTS components.

When the CTS program was proposed, the prototype metal tailboom for the AH-64A had a fold joint at Fuselage Station (Sta) 450 to aid in an air transportability in C-141 cargo planes. However, the Air Force lengthened the fuselages of all its C-141s making the AH-64A tail folding no longer needed. In the interest of structural efficiency, the fold joint was replaced by a tension bolt attachment. The prototype tail assembly was a T-tail configuration with the horizontal stabilizer rigidly attached to the top of the vertical tail.

This was to be the configuration for the composite tail assembly -- a geometric copy of the prototype metal tail section.

AH-64A flight tests that were made just before the CTS design work began showed that the helicopter's flying qualities could be markedly improved by changing from the T-tail configuration to one having a controllable stabilator mounted at the base of the vertical tail. When this change was made, the tail rotor was moved up the vertical tail to have clearance from the new position of the stabilator. The composite tail design matched this flight test configuration from the beginning (see Figure 2).

As the design work progressed, it became apparent that important benefits could be attained if the composite portion of the tailboom was extended further forward. A contract modification was negotiated to extend the composite structure 80 inches forward and make the metal-to-composite joint at Sta 370. This was the farthest forward point the composite structure could go without compromising the existing design of equipment bays, access doors, etc. It was determined that a shear bolt attachment at this point would be a production manufacturing break.

Other modifications were made to the CTS design to accommodate the findings of the prototype flight test program and the composite flexbeam tail rotor design program that were going along in parallel. These included softening the torsional stiffness of the tailboom to avoid a resonance with the main rotor 4-per-rev frequency, increasing the torsional strength of the tailboom and the sideward bending strength of the vertical tail to support

14

Figure 2. AH-64A Final CTS Configuration

the composite tail rotor that had 16 percent more thrust capability than the
flight test metal tail rotor, and changing the vertical tail incidence and
camber to unload the tail rotor in cruise flight to reduce its flapping motion
for better fatigue life.

So what started out to be essentially a one-for-one replacement of metal
by composites turned into a sophisticated CTS design that improved dynamics,
permitted the use of the larger tail rotor needed for high altitude control-
lability when the T700-GE-701 engine is installed, and made a spectacular
reduction in parts count while reducing the weight and cost. In this CTS
configuration, the gearbox, control system, and tail wheel mount points were
held inviolate, and the drive shaft covers and vertical tail leading edge fair-
ing were retained. A new trailing edge fairing for the vertical tail spar
was required by the modified incidence and camber.

A tradeoff study was made to determine the best design concepts for the
three CTS components: tailboom, vertical tail, and stabilator. For the
tailboom and vertical tail spar, a monocoque honeycomb sandwich shell with

15

frames located at high load points was determined to be optimum, consistent with good design practice and the wet filament winding manufacturing process. The skins of these components were selected to be hybrid graphite/Kevlar/epoxy. The best stabilator configuration proved to be a skin/spar/rib arrangement with graphite/epoxy used for the spars and central ribs, and Kevlar/epoxy for the skin and for the nose and tail portions of the ribs.

In parallel with this design refinement work, FSI established refined processes for fabricating the three CTS components, predominantly by the wet filament winding, cocure process that had been used successfully in a wide variety of previous programs. This work included analytical and experimental assessment of mandrel shapes to accommodate the specified winding angles, frame and hardpoint inserts, etc. Based on these activities, tooling suitable for building 50 shipsets of the components was designed.

At the time that the CTS program was terminated, the design was complete. The tooling design was in the final stages, and tool fabrication was ready to start. Material properties tests in support of design had been completed. Antenna pattern tests had been conducted to show that the composite structure had no appreciable influence on the radiation characteristics. Ballistic damage tests, conducted at the Army's Ballistic Research Laboratory, had shown that simulated composite tailboom components were survivable against 23mm HEI-T projectiles equipped with MG-25 fuzes. Lightning survivability tests had demonstrated the suitability of the design. Both the ballistic and lightning tests were sponsored by HHI.

The analysis of the CTS showed that in comparison with the metal* components it would replace, there would be:

- 71 pounds weight saving

- $41,000 design to unit production cost saving (1981 dollars)

- 269 parts count saving

- 9047 fastener count saving

- 55 feet per minute vertical rate of climb increase from weight reduction

- $1.1 million fuel saving over life of the fleet

---

*AH-64A weight and cost values for metal components are those quoted for the second quarter of 1981.

DESIGN REQUIREMENTS

The Composite Tail Section (CTS) consists of three major components:

- Tailboom

- Stabilator

- Vertical Tail

plus fairings, covers, steps, handholds, lights, and antennas.

The basic geometry of the CTS is shown in the lines drawing, Figure 3.

The strategy for optimizing the design of the CTS to match optimized techniques used in building it is to create a low cost, light-weight configuration while providing:

- External Geometric Similarity

- Accommodation of Existing Gearboxes, Controls and Tailwheel

- Maximum Incorporation of Filament-Reinforced Plastic Structure

- Aerodynamic Compatibility

- 4500-Hour Service Life

- Ballistic Survivability

- Lightning Survivability

- Reduced Parts and Fastener Count

- Interchangeability at Fuselage Station 370

- Accommodation of Existing Antennas, Lights, Mission Equipment Kits

In addition, the configuration must accept either the 112-inch diameter composite flexbeam tail rotor or the 110-inch diameter prototype metal tail rotor.

17

Figure 3. AH-64A Lines Drawing

18

The basic AH-64A description and all its design criteria remain the same as those described in Reference 4, the Design Criteria Report for AH-64A vehicle, with the exception of minor geometry changes to the stabilator and vertical tail (see Design Refinement section).

For reference, the flight envelope for weights at or below the Basic Structural Design Gross Weight (BSDGW) is presented in Figure 4. For weights above the BSDGW, the maximum vertical load factor is reduced by the ratio of the BSDGW divided by the gross weight for the particular condition up to the maximum alternate gross weight. In no case is the load factor less than 2.0. The sideslip envelopes for the AH-64A are presented in Figure 5 for the static limit, transient limit, and emergency limit.

The requirements for CTS stiffness to assure good dynamic properties are given in Figures 6, 7, and 8. These are chosen to place the stabilator roll and yaw assymetric natural frequencies at 30 Hz while avoiding the main rotor 4P, main rotor 8P, and tail rotor 1P excitation frequencies that occur at 19.3, 38.6, and 23.5 Hz, respectively.

The basic external loads for the composite tail section are used for static and failsafe analysis and, where specified, for weighted fatigue. Oscillatory load levels from the flight strain survey weighted fatigue level of ±10 percent of limit load for the fuselage and ±30 percent for the vertical stabilizer and stabilator are used. These loads are the same as those specified for the basic AH-64A and are calculated for the flight maneuver conditions specified in Reference 5, and in Army-approved deviations to Reference 5.

One of the driving forces behind the increased use of composites is the increase in reliability; i.e., the decrease in failure rate. Structural failures can be classified according to severity and cause.

Severity of failures can be classified as minor, major, and critical. Minor failures merely require maintenance, and can generally be termed discrepancies. Major failures represent a threat to personnel and equipment and may result in a degradation of performance. Critical failures may result in loss of control of the aircraft.

Figure 4. Flight Load Factors Versus Airspeed (Basic Structural Design Gross Weight Except Where Noted)

20

Figure 5. Sideslip Envelopes

21

Figure 6. Tailboom Stiffness

22

Figure 7. Vertical Tail Stiffness

23

Figure 8. Stabilator Stiffness

24

Classification by cause divides failure into inherent or induced modes.
Induced failures generally include any damage caused by external influences
such as foreign objects, by certain environmental factors, or by conditions
outside of the design envelope (such as overload conditions). Inherent
failures include anything that is not induced such as fretting, cracking, etc.,
that occur at load levels within the design envelope. Examples of induced
and inherent failures are given in Table 1.

TABLE 1. EXAMPLES OF STRUCTURAL FAILURES

<u>Inherent Failures</u>

Minor

- Fretting
- Delaminations
- Change in bolt preload

Major

- Formation of small crack
- Loss of primary fastener

Critical

- Loss of multiple primary fastener
- Growth of large crack

<u>Induced Failures</u>

Minor

- Scratch or gouge
- Delamination
- Lightning damage

Major

- Deep gouge
- Small ballistic perforation

Critical

- Large Ballistic perforations

DESIGN REFINEMENT

The AH-64A Composite Tail Section (CTS) is designed according to the existing metal tail section design criteria. Based on the success that HHI had experienced with wet filament winding in other aircraft primary structure programs for the Army, this process was selected for fabricating all the major components.

Design refinements include optimization of weight, mass distribution, inertial properties, stiffness distributions, natural frequencies, vibratory loads, fuselage vibrations, ballistic survivability/tolerance, anticipated service life, maintainability/reliability, acquisition cost, and life cycle cost. The design is in accordance with the AH-64A system specification AMC-SS-AAH-H10000A and meets the following restraints:

- The aluminum fuselage/CTS interface is a permanent joint at Fuselage Station (Sta 370).

- CTS stiffness distributions are dynamically compatible with the test aircraft.

- The CTS interfaces with existing operational hardware of the AH-64A (i.e., gearboxes, tail rotor drive shaft, control components, landing gear, etc.).

- The external geometry of the aluminum baseline configuration is maintained.

- The antennas are functionally integrated within the tailboom and vertical tail.

This section describes the design features of the CTS.

The CTS that consists of three major components -- tailboom, stabilator, and vertical tail -- mates with the AH-64A airframe in a manufacturing splice at Sta 370. Figure 9 is an isometric sketch that shows the configuration of the CTS and the associated fairings, covers, and external hardware that mate with it. Assembly and major subassembly drawings of these components may be found at the back of this report (Figures 95 through 99).

Before this configuration that is based primarily on sandwich wall monocoque construction was selected, a predesign study investigated other structural concepts. The primary contender was a skin, stringer, frame design of

27

VERTICAL STABILIZER

TRAILING EDGE**

HORIZONTAL STABILIZER

DUAL ACTUATORS

TIP FAIRING**

UPPER LEADING EDGE**

MIDDLE L.E.

LOWER L.E.

TAIL WHEEL ASSY*

DRIVE SHAFT FAIRINGS*

ANGLES

TAIL BOOM

* COMPONENTS FROM PROTOTYPE AIRCRAFT
** CONFIGURATION REVISED FROM BASELINE METAL AIRCRAFT

Figure 9. Composite Tail Section with Adjacent Fairings, Closeouts, and Internal Hardware

28

the tailboom and vertical tail spar. Structurally, this alternate design was equally acceptable, but the sandwich concept was selected as being more amenable to the wet filament winding manufacturing process.

TAILBOOM

The composite tailboom shown in Figure 10 retains most of the baseline metal fuselage configuration. It transitions from a flat-topped ovaloid at Sta 370 to a circular cone from Sta 450 to Sta 530. From Sta 530 aft, the composite tailboom maintains a constant diameter, differing from the continuing cone shape of the baseline configuration.

The composite tailboom is composed of the following major components (see Figures 95 and 96:

- Structural Shell

- Station 387 Frame

- Forward Fitting Assembly

- Intercostal, Upper

- Intercostal, Lower (2)

- Intercostal, Jack Fitting

- Rear Frame

Other details that are attached onto this assembly are:

- Access Steps, Upper and Lower

- Angle Fairing, Right and Left

- Jack Point Fitting

Hard points (local reinforcement and/or core filled honeycomb) are provided for the following details that are common to both CTS and metal baseline:

- Drive Shaft Fairing Hinges

- Drive Shaft Bearing Support Bracket

29

STA 547.15

STA 450.00

0°

90°

16.3

STA 370.00
WL 129.20

Figure 10. Tail Boom Configuration

- Drive Shaft Anti-Flail and Damper Support

- Flare Dispenser

The structural shell of the tailboom is a graphite-Kevlar/epoxy sandwich with balanced helically wound skins and 0.50 inch thick Nomex core. The inner and outer skins converge at the front end of the tailboom (Sta 370) and at the aft, constant diameter section to form solid laminates as Figure 11 shows.

The base sandwich skin thickness is 0.043 inch and the winding angle is 8° ±1° at Sta 370. Skin thickness and wrap angle increase from the forward to aft end of the tailboom. Hoop windings (90°) stabilize the spiral windings. The skin is wound from a 50-50 ratio of graphite/Kevlar rovings. This winding pattern is tailored to provide the required bending and torsional stiffness and strength.

The solid laminate attach flange at Sta 370 is interwound with ±45° graphite fabric and 90° E-glass to a total flange thickness of 0.172 inches. The interwound plies, in addition to providing the necessary bearing area, are structurally balanced in thickness and elastic modulus to evenly distribute load into the two skins. Figure 12 shows how this solid laminate region is attached to the forward airframe by splice plates and a double row of HiLok fasteners.

The solid laminate at the aft end of the tailboom (sta 530, aft) is also made up of interwound fabric plies tailored for bearing strength and balanced load distribution.

Local attach points and cut-outs employ additional interwound plies of fabric to provide load-carrying structure in these high stress areas. The honeycomb core in these areas is filled with syntactic foam to stabilize the core, anchor the fasteners, or provide compressive strength to support fastener loads.

The materials used to fabricate the tailboom are:

- Graphite Roving: T-300, 3000 Filament Count

- Kevlar Roving: Kevlar-49, 1420 Denier

- Graphite Fabric: T-300, 3000 Filament count, Eight Harness, Satin Weave

- E-glass Fabric: 1581 Glass Fabric

31

Figure 11. Tail Boom - Structure Details

32

Figure 12. Metal/Composite Manufacturing Splice, Sta 370

33

- Epoxy Resin: APCO 2434/2347

- Core Adhesive: FM 123-5 Film Adhesive

- Core: Nomex HRH - 10/0X - 3/16

There are three graphite/epoxy frames that are molded separately and then assembled into the tailboom. The forward one at Sta 387 is provided to stiffen the tail rotor shaft bearing support at this location. It is installed by a secondary bonding process. The two back-to-back frames centered at Sta 532.33 are made into a subassembly unit consisting of these two frames, a connecting strap bonded around them, and four graphite/epoxy intercostals that distribute tail wheel loads into the tailboom. This subassembly unit is wound into the tailboom shell structure to become an integral part of it. The tailboom in the region of this subassembly unit is shown in Figure 13.

A machined aluminum fitting is bolted between the two back-to-back composite frames after the tailboom is cured (see Figure 14). This is the fitting to which the forward bolts for the vertical tail attach.

The materials for the frames are:

- Fitting: 7075-T6 Aluminum Alloy

- Frames: Graphite Fabric: T-300, 3000 Filament Count, Eight Satin Weave

  Glass Fabric: 1581 Glass Cloth

  Resin: APCO 2434/2347

Four graphite/epoxy intercostals are located between the forward/frame assembly and the rear frame, (see Figure 13). Three of these intercostals transfer most of the tail wheel shock and strut loads into the skin. The balance of the load goes into the forward frame assembly through a row of shear bolts. The fourth intercostal transfers jacking and tie-down loads into the tailboom. The materials for the intercostals are :

- Graphite Fabric: T-300, 3000 Filament Count, Eight Harness, Satin Weave

- Epoxy Resin: APCO 2434/2347

ALUMINUM BULKHEAD

GRAPHITE/EPOXY INTERCOSTALS

ALUMINUM VERTICAL STABILIZER ATTACH FITTING

GRAPHITE/EPOXY FRAMES

Figure 13. Tail Boom

35

VERTICAL STABILIZER
ATTACH POINTS

TAIL WHEEL SHOCK
STRUT LUG

STABILATOR
ACTIVATOR LUG

REAR FRAME

HORIZONTAL
STABILATOR
PIVOT LUG

TAIL WHEEL
STRUT LUG

JACK PAD &
TIE DOWN
FITTING

Figure 14. Aft End of Tailboom

36

The rear frame, Figure 14, is a machined aluminum fitting that has multiple functions. It contains the tail wheel assembly attach points, stabilator pivot points, and the stabilator actuator attach points. It provides the two aft points for vertical tail attachment and anchors the aft jacking fitting. The frame, made from 7075-T6 aluminum alloy, is bolted into the tailboom with HiLok fasteners.

VERTICAL TAIL

The geometry of the composite vertical tail is:

Area (from boom $\mathcal{C}_L$) - ft^2	32.2
Span (from boom $\mathcal{C}_L$) - in.	113.0
Tip chord - in.	35.1
Chord of section at W.L. 196.0 - in.	43.5
Root chord (at boom $\mathcal{C}_L$) - in.	44.0
Geometric aspect ration (based on span from boom $\mathcal{C}_L$)	2.5
Airfoil	NACA 4415 modified
Leading edge sweep - deg	29.4
Rudder - (mean) percent chord	55.0
Rudder deflection - deg	4.0
Rudder tab - (mean) percent chord	25.0
Rudder tab deflection (from rudder chord line) - deg	18.0
Geometric incidence - deg	0.0
Aerodynamic incidence - deg	9.4

The major structural element in the vertical tail is the spar box shown in Figure 15. Leading and trailing edge fairings and tip cap as shown in Figure 9 complete the assembly. The vertical tail's planform is unchanged

STEP/HAND-HOLD

ALUMINUM FITTINGS/
GRAPHITE EPOXY RIBS

GRAPHITE/EPOXY LONGOS

NOMEX HONEYCOMB

GRAPHITE KEVLAR/EPOXY SKINS

GRAPHITE/EPOXY
GEARBOX FITTING

GRAPHITE/EPOXY LONGOS

GRAPHITE/EPOXY CLOSE OUT RIB

ALUMINUM ROOT
FITTINGS

Figure 15. Vertical Tail Spar Box Structure

from that of the prototype AH-64A, and the vertical incidence is increased four degrees to partially unload the tail rotor in high-speed flight and minimize its flapping motion for improved fatigue life. Figure 16 shows this incidence change. Note that the front face of the spar remains unchanged while the rear face is moved to the left. This keeps the gearbox attach points in the same location as the metal baseline, allowing all driveshaft and control hardware to be interchangeable. The leading edge, trailing edge, and tip closure fairings are the same as the baseline except where contours are impacted in a minor way by the four-degree vertical tail incidence change. Steps and hand-hold locations are the same as the metal baseline. See Figure 15.

The composite vertical tail is composed of the following components (see Figures 97 and 98):

- Spar box

- Root Fittings

- Upper Gearbox Support Assembly

- Lower Gearbox Support Frames

- Upper Closure Rib

- Steps and Handholds

Hardpoints for attaching hardware are provided for the following:

- Tip Fairing

- Leading Edge

- Trailing Edge

- Tail Rotor Brace (2)

The basic structure of the box is a graphite/Kevlar/epoxy filament wound honeycomb sandwich. The skins are ±38-degree helical windings over a 0.250 inch thick Nomex honeycomb core. Graphite/epoxy spar angles (0° ±45° plies) are incorporated in the four corners between the inner and outer skins. The helical windings provide the necessary torsional strength and stiffness, with the corner spar angles supplying bending strength and stiffness. See the lower portion of Figure 16.

39

FRONT SPAR
(UNCHANGED)

REAR SPAR
(MOVES LEFT)

METAL SPAR
BOX CONTOUR

COMPOSITE VERTICAL TAIL
SPAR BOX (TYPICAL
CROSS SECTION)

Δa 4°

FWD

EXISTING TRAILING
EDGE FAIRING

EXISTING LEADING
EDGE FAIRING

COMPOSITE SPAR
BOX CONTOUR

MODIFIED TRAILING
EDGE FAIRING

VERTICAL STABILIZER INCIDENCE ANGLE MODIFICATION

SPAR ANGLES
[0° ±45°] GR/EP

HONEYCOMB

ATTACHMENT TEE
[±45°] GR/EP

0.026 IN. THICK
INNER SKIN
[90/+ 38/90]
GR/EP

0 026 IN. THICK
OUTER SKIN
[90/±38] GR/EP

LEADING AND TRAILING EDGE FAIRING ATTACHMENT TEES

Figure 16. Vertical Tail Cross Sections

The honeycomb sandwich is a balanced structure with each skin 0.020 inch thick. The skins converge to form solid laminates at the root fitting attach region and at the tip end just below the tip cap. Local skin thickness is sized to accommodate the local load requirements. The skin thickness, including laminae and honeycomb core is illustrated in Figure 17. In the center of the spar the sandwich is 0.301 inch thick. The ends taper to 0.060 inch solid laminate.

Figure 17. Vertical Stabilizer Skin Thickness

The leading and trailing edge attachment tees are bonded to the box as indicated in Figure 16.

The materials used to fabricate the spar box are:

- Graphite Roving: T300, 3000 filament count

- Kevlar Roving: Kevlar-49, 1420 Denier

- Graphite Fabric: T300, 3000 filament count, eight harness, satin weave

- Epoxy resin: APCO 2434/2347

- Core Adhesive: FM 123-5 film adhesive

- Honeycomb Core: HRH-10 -1/4, 0.250 inch thick

41

The composite vertical tail attaches to the tailboom with the four-piece aluminum fitting shown in Figure 18. This split fitting attaches to the composite box with HiLok fasteners and carries the bosses for the four 5/8-inch diameter attach bolts. The forward portions of the root fitting also incorporates the intermediate gearbox attach bosses. The root fitting is made from 7049-T6 aluminum alloy.

MATERIAL -
7049-T6
ALUM ALLOY

Figure 18. Root Fitting

The upper gearbox mount shown in Figure 19 consists of three graphite/epoxy ribs that have aluminum reinforcing bars bonded in. Self-locking anchor nuts mount the gearbox. The three ribs are connected with a strap to form a prefabricated unit that is assembled with the winding mandrel and wound into the spar box structure. HiLok fasteners are also used to anchor these ribs to the spar box. The lower gearbox supporting rib (Figure 15) is a premolded/graphite/epoxy rib that is bolted in place with HiLok fasteners. An aluminum reinforcing bar supports the intermediate gearbox.

The materials used for the ribs are:

- Rib Assemblies: Graphite/epoxy: T300, 3000 filament, eight harness, satin weave, preimpregnated

  E-glass/Epoxy: 1581 glass cloth, preimpregnated

  Adhesive: FM 123-5

- Inserts: 2024-T6: Aluminum alloy

The upper closure is made from graphite/epoxy - T-300, 3000 filament count, eight harness, satin weave, preimpregnated.

The steps and handhold are graphite/epoxy tubes fixed on the vertical tail spar box as shown in Figure 15. That portion extending into the air stream is elliptically shaped for reduced drag (See Figure 20).

The materials for the steps are:

- Graphite/epoxy: T-300, 3000 Filament count, eight harness, satin weave, preimpregnated

- Graphite roving: T-300, 3000 filament count

- Epoxy resin: APCO 2434/2347

The leading and trailing edge fairings attach to flanges that are bonded to the corners of the spar box. These are T-section flanges as indicated in Figure 16. They are made from:

- Graphite/epoxy: T-300, 3000 Filament Count, eight harness, satin weave, preimpregnated

43

Figure 19. Upper Gearbox Assembly

MOLDED BOSS

VERTICAL TAIL SPAR BOX

LEADING EDGE FAIRING ATTACH ANGLE

ELLIPTICALLY SHAPED TUBE FOR REDUCED DRAG

GRAPHITE TUBE

Figure 20. Step/Hand Hold

45

STABILATOR

The composite stabilator's geometry is:

Area - ft^2	33.36
Span - in.	128.0
Tip chord - in.	31.85
Root chord - (at centerline) - in.	43.2
Airfoil	NACA 0018
Aspect ratio	3.41
Chordline for zero sweepback, percent	50

The composite stabilator is shown in Figure 21. It has the same outside contour as the AH-64A metal stabilator, but with added leading edge sweepback. The pivot point and actuator locations are changed to facilitate hinging the stabilator to the tailboom instead of to the vertical tail. This change permits decoupling of the vertical tail/stabilator dynamic responses and also allows the hinge spacing to be increased, thus reducing the hinge loads. An improved actuation system replaces the prototype helicopter's tandem electric actuator by a pair of side-by-side hydraulic actuators attached to the tailboom aft bulkhead. The hinge is also part of the aft bulkhead.

The stabilator is made up of the following structural members (see Figure 99):

- Skins (left, right, and center)

- Spars (forward and aft)

- Ribs (left and right, 3 each)

- Nose ribs (left and right, 3 each)

- Reinforcing ribs (left and right, 1 each)

- Tip closures (2)

POLYURETHANE EROSION
PROTECTION MATERIAL

GRAPHITE/EPOXY SPAR-RIB STRUCTURE

KEVLAR/EPOXY TRAILING EDGE RIBS

KEVLAR/EPOXY SKIN AND TIP CAPS

KEVLAR/EPOXY
NOSE RIBS

ALUMINUM
HINGE/ACTUATOR
BRACKETS

Figure 21. Stabilator Structure

47

Attach details are:

- Pivot/actuator fitting (left and right)

- Bathtub fitting (left and right)

In addition, the stabilator is protected from rocket debris by a polyurethane cover.

The skin is made of four pieces, (left, right, upper center, lower center). The skin provides the torsional stiffness and shear tie for the spars. The spars provide axial bending stiffness and resist air loads and diagonal tensions loads caused by thin skin shear buckling. The left and right-hand skins are premolded to the airfoil shape, fit over the spar/rib structure, and are bonded to it. The skin is reinforced in the center section for torsional requirements. The total skin thickness is 0.030 inch with an additional 0.030 inch thickness in the center box area between the root end ribs.

The skin material is:

- Kevlar roving: Kevlar-49 roving, 1420 Denier

- Epoxy Resin: APCO 2434/2347

The forward and aft spars consist of C-section beams. Spanwise bending stiffness is provided by unidirectional fiber in the caps oriented in the spanwise direction. The spars are made of:

- Graphite roving: T300, 3000 Filament Count

- Epoxy Resin: APCO 2434/2347

The ribs are molded as three element boxes with flanges all around their peripheries. The portions of the ribs that lie between the spare are graphite/epoxy, while the leading and trailing edge portions are Kevlar/epoxy. The materials used to make the ribs are:

- Graphite Roving: T300, 3000 filament count

- Kevlar Roving: Kevlar-49 Roving, 1420 Denier

- Epoxy Resin: APCO 2434/2347

The tip closures provide a shear rib at the outboard end of the airfoil and serve to shield the edges of the skin and the substructure from environmental effects. The material is the same Kevlar/epoxy used for the skins.

The pivot/actuator fittings are two aluminum alloy fittings attached to the stabilator assembly with stainless steel bolts. The pivot holes are bushed with TFE-lined stainless steel bushings. The materials for these fittings that are shown in Figure 21 are:

- Fitting: 7049-T411 aluminum alloy

- Bushing: CRES steel, TFE coated

Rocket debris protection is provided by a polyurethane cover 0.050 inch thick extending over the outboard 23.5 inches of the span on both sides. This material wraps around the leading edge and covers the forward five inches of the upper surface and all but the aft six inches of the lower surface.

ENVIRONMENTAL PROTECTION

Extensive investigation during the advanced composites programs has established that there will be no corrosion problem with the composite components. However, suppression of galvanic corrosion between aluminum fittings and adjacent graphite/epoxy laminates requires the use of a layer of E-glass/epoxy for electrical isolation at all interfaces.

All steel parts are cadmium plated and all aluminum parts are chromic acid anodized. All fasteners are corrosion-resistant steel. Final painting consists of a urethane top coat over a suitable primer for protection against ultraviolet radiation.

Figure 22 shows how lightning protection is provided by a grounding system that extends from a lightning collector in the tip cap of the vertical tail, down through the aluminum ground plane for the antennas in the trailing edge fairing of the vertical tail, and out through the tailboom's aluminum frame at Sta 547 and the tail landing gear strut. A grid of aluminum foil around the leading and trailing edges and tip to two discharge wicks on each stabilator tip and through a jumper into the aluminum rear frame in the tailboom provides lightning protection for the stabilator.

ALUMINUM LIGHTNING ROD

JUMPER TO ANTENNA GROUND PLANE

ANTENNA GROUND PLANE

FM ANTENNAS

JUMPER TO ALUMINUM BULKHEAD

TAIL WHEEL STRUT

STA 547 ALUMINUM BULKHEAD

BONDING STRAP ACROSS HINGE

STATIC DISCHARGE WICKS

ALUMINUM TAPE CONNECTS TO GRAPHITE SPARS

Figure 22. Lightning Protection

WEIGHT ANALYSIS

The weight analysis for the CTS is given in detail in Table 2 per MIL-STD-1374 Part III for the three components -- stabilator, vertical tail, and tail-boom. The calculations for these weights are based on released drawings (84 percent by weight), and on pre-release drawings for the remaining details and installation. The component weights are . ..imarized .n Table 3 and are compared with their counterparts in the basic metal helicopter. The weight saving is shown to be 72.4 pounds.

Two adjustments are needed. First, a calculation for a preliminary layout of the metal-to-composite splice joint at Sta 370 shows an incremental weight increase of 7.6 pounds relative to a structure without a manufacturing break at this point. Second, the CTS is designed to accept the Composite Flexbeam Tail Rotor (CFTR) that increases the load on the tailboom by six percent relative to the metal tail rotor. A weight analysis of a strengthened metal tailboom to accept this load indicates a weight increase of 6.0 pounds is needed. Hence, the total adjustment for the Sta 370 splice and the CFTR yields an overall weight reduction of 70.8 pounds for the CTS versus the metal tail section modified to accept the CFTR.

The longitudinal center of gravity for the AH-64A equipped with the CTS is given in Figure 23. For comparison, the normal envelope portion of the chart for the helicopter with the metal tail section is shown as a dotted line in Figure 23. Note that the lighter weight CTS results in a m< re forward center of gravity for the vehicle.

TABLE 2. CTS WEIGHT ANALYSIS

	Original Goal	Current Status	Basis For Current Data	
			% EST	% CALC
Stabilator - Basic	(58.0)	(52.0)	(18)	(82)
Upper - Cover	3.0	3.2	0	100
Lower - Cover	3.0	3.2	0	100
Spars	7.0	15.2	0	100
Interspar - Ribs	4.0	6.0	0	100
- Chordwise Stiff.	0.0	0.0	0	0
Leading Edge - Cover	7.0	3.6	0	100
- Ribs	2.0	1.4	0	100
- Fasteners	1.0	0.0	0	0
Trailing Edge - Cover	14.0	3.6	0	100
- Ribs	4.0	0.6	0	100
- Fasteners	2.0	0.0	0	0
Fitting - Hinge (pivot)	5.0	8.0	100	0
- Actuator	2.0	1.0	0	100
Attachments - Misc. & Fasteners	2.0	2.3	50	50
Tips	2.0	0.0	0	0
Debris Protection	0.0	3.8	0	100
Lightning Protection	0.0	0.1	0	100
Vertical Tail - Basic	(79.0)	(90.0)	(22)	(76)
Cover	26.0	0.0	0	0
Spar Webs	21.0	0.0	0	0
Spar Box Assembly	0.0	34.2	0	100
Interspar Ribs	10.0	9.5	26	74
Leading Edge - Cover	7.0	11.5	0	100
- Ribs	2.0	2.2	0	100
- Fasteners	1.0	2.5	0	100
Trailing Edge - Cover	3.0	4.3	0	100
- Ribs	1.0	0.6	0	100
- Fasteners	0.0	2.1	0	100
Attachments - Tail to Fuselage	2.0	12.0	100	0
- Miscellaneous	1.0	3.0	100	0
Tips	3.0	3.5	0	100
Steps & Grips	2.0	2.0	100	0
Tail Rotor Gear Box Fittings	0.0	2.6	0	100
Tailboom - Basic	(117.6)	(139.5)	(12)	(88)
Bulkheads + Frames	16.0	27.2	48	52
Joints, Splices + Fasteners	8.6	3.4	70	30
Monocoque Sandwich	89.0	100.4	0	100
Intercostals	0.0	4.4	0	100
Stabilator Actuator Fitting	2.0	0.0	0	0
Jack Fitting	2.0	1.2	100	0
Steps + Grips	0.0	1.4	0	100
Tail Rotor Fairing Angles	0.0	1.5	0	100

TABLE 3. CTS WEIGHT STATUS SUMMARY

Item	Metal Weight (lb.)	Composite Weight (lb.)	Weight Savings (lb.)
Stabilator	73.1	52.0	21.1
Vertical Tail	120.0	90.0	30.0
Tailboom	160.8	139.5	21.3
Totals	353.9	281.5	72.4

Estimated increase in weight at fuselage station 370 to install CTS (reduced weight savings)	- 7.6
Net Weight Savings	64.8
Estimated weight increase of metal tailboom to accommodate CFTR	+ 6.0
Adjusted Weight Savings	70.8

Figure 23. AH-64A Longitudinal Center-of-Gravity with CTS

54

RELIABILITY ASSESSMENT

Reliability assessment of the CTS is based on the results of a preliminary systemized Failure Modes, Effects, and Criticality Analysis (FMECA), a review of program requirements, and a review of reliability studies conducted for other composite programs at HHI. The analysis considers the degradation of reliability that may occur as a result of manufacturing defects, storage, environmental conditions, in-service conditions, and production techniques. Specific areas of concern include delamination and disbonding, porosity and voids, resin rich and resin starved areas, internal geometry and bond lines, resistance to impact, and defects in metal attach fittings. These studies show that the hazards imposed by air vehicle operation and maintenance are the primary reliability considerations. Detection through such nondestructive inspection techniques as X-ray or Bondoscope permits these problems to be detected and cured.

Cracking occurs primarily at fastener interfaces and is easily detectable. The CTS is designed to use a minimum of fasteners and the composite structure is adequately designed to accept fasteners. Degradation due to limited cracking is expected to be minor.

Resin-starved/resin-rich areas can contribute to structural degradation and loss of effective performance. Resin starvation can fail to support the filaments properly and result in delamination; this can result in geometric misplacement of the fibers to cause unanticipated load paths. Resin richness means either that not enough filaments are present to carry the loads or that the resin/filament matrix is oversized and, hence, out of its desired position in the structure -- in either case structural integrity is jeopardized. These conditions occur only during manufacturing not during in-service operation and are discovered during nondestructive evaluation. A resin-rich or resin-starved defect is not considered to be a failure mode in the FMECA because it is a failure mechanism (cause) of a delamination failure mode.

Ultraviolet light, rain erosion, moisture entrapment, extreme temperatures, snow, wind, and lightning contribute greatly to reliability degradation. The resin matrix material degrades considerably when exposed to ultraviolet light. Protection from ultraviolet light is provided by a suitable coating of the exposed skins. Although moisture entrapment cannot be avoided, the composite tail section is designed for the worst case condition as is true with the rest of the environmental extremes. Extremely rare incidents such as heavy hail or hurricane velocity winds are not considered since these environments should be avoided when operating the air vehicle.

The significant contributors to reliability degradation of the CTS are hazards induced during air vehicle operation and maintenance. These include thermal cycling, shock, vibration, aircraft fluids, rotor downwash (induced airborne particles and FOD), rocket debris, rough handling, impact with terrain objects, maintenance, and contact with work stands and ground vehicles. Design allowables may compensate for some of these hazards and the resultant degradation may be readily visible. However, the resultant degradation of those hazards, not readily visible, can only be determined by an effective and adequate nondestructive evaluation or nondestructive test technique. Based on results of previous testing and for equivalent material thickness, the order of damage tolerance is as follows. Fiberglass is the most damage tolerant, Kevlar is next best, and graphite has low damage tolerance. Sandwich construction has poorer impact resistance than mono-lithic construction and tends to suffer reductions in strength due to subsurface damage. Nomex sandwich construction is protected by Kevlar/graphite facing sheets on the composite tail section and Nomex has shown to have better damage tolerance than aluminum. Finally, simple field-type repair methods have been shown to be effective for many types of routine impact damage. At the time that the program was terminated, a Failure Modes, Effects, and Criticality Analysis (FMECA) had not been made for comparison with the metal empennage of the basic AH-64A helicopter.

STRUCTURE VERIFICATION TESTS

Tests were made to determine the properties of the particular laminates used in the tailboom, vertical stabilizer, and stabilator of the CTS. The testing included tension, compression, shear, and bearing of typical configurations found in the CTS to verify strength, elasticity, and strain allowables.

Two types of test specimens were investigated: helically wound tubular specimens used for tension, compression, and torsional shear tests and flat panel specimens laminated from wet-filament-wound broadgoods with fabric reinforcing plies. Test fixture end reinforcement was applied to the wet specimens at each end. Specimen identification, material description, and type of test as well as number of specimens are presented for tubular tension and compression specimens in Figure 24 and Table 4, for tubular torsion specimens in Figure 25 and Table 5, and for bolt bearing test specimens in Figures 26 and 27 and Tables 6 and 7. All of the specimens were wet-filament wound using Kevlar-49 and Thornel 300 graphite fibers with APCO 2434/2347 (7.5 PPHR) resin. The fiber volume ratio was 0.50 for all specimens.

All specimens were tested in a room temperature (70°- 75°F), dry condition. Each tension and compression tubular specimen was installed in a test machine as shown in Figures 28 and 29 in a manner to prevent any bending loads from being applied. (A stabilizing bar was installed in the compression specimens to prevent buckling.) A two-inch extensometer was mounted to each specimen to measure deflection. A load-deflection strip-chart recorder monitored the applied load and deflection. The load-deflection curve was used to calculate the modulus of elasticity of the specimen. The load was applied at an average rate of 0.05 inches per minute for the moving head of the test machine. All specimens were tested to failure.

Each tubular torsion test specimen was installed in a test fixture designed to apply shear loads to the test section of the specimen as shown in Figure 30 with a stabilizing bar installed to prevent buckling. Holes were drilled in the end pieces of the specimens to firmly attach them in the test fixture.

57

Figure 24. Tension/Compression Specimen

TABLE 4. TENSION/COMPRESSION SPECIMENS

Specimen No.	Component	Layup Composition	Total Thickness	Condition
I-1	Stabilator Skin	$[\pm45°/0°/\pm45°]$ Kevlar (KV)	.020/.020/.020 .060	Tension Compression
I-2	Vertical Tail Skin	$[\pm30°/90°/\pm30°]$ Graphite (GR)	.020/.020/.020 .060	T C
I-3	Stabilator & Vertical Tail Spar Caps	$\pm45°/0°_{12}/\pm45°$ GR	.014/.085/.014 .113	T C
I-4	Tailboom	$\pm45°/0°_{12}/\pm45°$ GR/KV 50-50	.014/.083/.014 .111	T C
I-5	Tailboom	$[90°,(\pm13.5°)_2,90°]$ GR/KV 50-50	.007/.038/.007 .052	T C
I-6	Tailboom	$[90°(\pm8°)_2 90°]$ GR/KV 50-50	.007/.032/.007 .046	T C

58

Figure 25. Torsion Test Specimen

TABLE 5. TORSION SPECIMEN

Specimen No.	Component	Layup Composition	Skin Thickness
II-1	Stabilator Skin	$[\pm 45°/0°/\pm 45°]$ KV	.020/.020/.020 .060
II-2	Vertical Tail Skin	$[\pm 30°/90°/\pm 30°]$ GR	.020/.020/.020 .060
II-3	Tailboom	$[90°, (13.5°)_2, 90°]$ GR/KV 50-50	.0066/.0382/.0066 .051
II-4	Tailboom	$[90°, (\pm 8°)_2, 90°]$ GR/KV 50-50	.0066/.0320/.0066 .0452
II-5	Tailboom	$[90°, (\pm 9°)_2, 90°]$ GR	.010/.032/.010 .052
II-6	Tailboom	$[90°, (\pm 15°)_2, 90°]$ GR	.010/.034/.010 .054

Figure 26. Bearing Test Specimen Type III-1

8 LAMINATE PER HP 15-42

7 APCO 2434-2347 EPOXY RESIN

6 EA 934 NA ADHESIVE ROOM TEMP
   CURE

5 FOR LAMINATE MATERIAL CALLOUT AND
   STACKING SEQUENCE SEE TABLES 6 AND 7

4 4340 OR 4130 STEEL PLATE (0.100 x 1.25 x 5.00,
   HEAT TREAT 150 KSI UTS

3 E-GLASS FABRIC MIL-C-9084 1581 CLOTH
   TYPE VIII, CL2, GR A(0.010/PLY)

2 SAND BLAST BONDING SURFACES PRIOR TO
   BONDING

1 INSTALL HI-LOK FASTENERS PER HP 3-2

NOTES:

60

Figure 27. Bearing Test Specimen Type III-2.

7 3 8 0.030 (3 PLIES) GLASS SHIM
THIS AREA ONLY-IN BETWEEN JOINT

10.06

5.44

2.50 (4 PLIES)

1.50 (4 PLIES)

0.94

0.47

6.00

3
0.270 (27 PLIES)

3
0.400 (40 PLIES)

5
0.271

5.00

0.38

0.400 (40 PLIES)
3

2 6

2 6

3 0.100 (10 PLIES)

0.100
4

0.56

1

HL 40-6-6 PIN
HL 70-6 COLLAR

1 (3/16'' DIA) 2620 LB. SHEAR ULT

8 LAMINATE PER HP 15-42

7 APCO 2434-2347 EPOXY RESIN

6 EA 934 ADHESIVE ROOM TEMP CURE

5 FOR LAMINATE MATERIAL CALLOUT AND
STACKING SEQUENCE SEE TABLE. 6 AND 7

4 4340 OR 4130 STEEL PLATE (0.100 x 0.94 x 5.00)
HEAT TREAT 150 KSI UTS

3 E-GLASS FABRIC MIL-C-9084 1581 CLOTH
TYPE VIII, CL 2, GR A (0.010/PLY)

2 SAND BLAST BONDING SURFACES PRIOR TO
BONDING

1 INSTALL HI-LOK FASTENERS PER HP 3-2

NOTES:

61

TABLE 6.   STACKING SEQUENCE FOR TYPE III SPECIMENS

Ply Number	Angle	Material*		Ply Thickness
P15	90°	⑥	⑧	.011
P14	±45°	④		.013
P13	±8°	⑤⑥		.022
P12	±45°	④		.013
P11	90°	⑦		.020
P10	±45°	④		.013
P9	90°	⑦		.020
P8	±45°	④		.026
P7	90°	⑥		.011
P6	±45°	④		.026
P5	90°	⑥		.011
P4	±45°	④		.026
P3	±8°	⑤ ⑥		.022
P2	±45°	④		.026
P1	90°	⑥	⑧	.011

*See Table 7.

TABLE 7. FABRICATION NOTES FOR
TYPE III SPECIMENS

⑧ APCO 2434-2347 Epoxy Resin
HMS 16-1115 Type I, CL 1

⑦ E-Glass, Roving
MIL-R-60346 Type I, CL 1

⑥ T300 3000 Fil Count, Roving
HMS 16-1163 Type I, CL 1

⑤ Kevlar 49, Roving 1420 Denier
HMS 16-1164 Type I, CL 3

④ T300 3000 Fil Count, Fabric
HMS 16-1163 Type II, CL 1, GRA

③ Filament wind per HP 15-67

② Layup per HP 15-42

① First Ply goes Against Tool Face

Figure 28. Tubular Static Tension Test Schematic

63

Figure 29. Tubular Static Compression Test Schematic.

Figure 30. Tubular Static Shear (Torsion) Test Schematic.

64

A gage indicator was mounted to the test section of the specimen to measure angular displacement during testing. A torque arm was mounted to one end of the specimen and attached to the moving head of the test machine while the other end of the test specimen was fastened to the fixed head of the machine. The torque arm was designed to preclude the application of bending loads to the specimen. The load was applied to the torque arm at the rate of 0.05 inches per minute as for the other tests with each specimen loaded to failure. Angular deflection was measured at periodic intervals during the test. The bolt bearing test specimens were tested in a manner similar to the tension specimens except the deflections were not monitored.

A total of 64 specimens were tested. Test results are given in Tables 8, 9 and 10 for tension/compression, torsion, and bearing tests respectively. The dimensions, ultimate load, ultimate stress, and modulus of elasticity for each specimen are given.

TABLE 8. TENSION/COMPRESSION TEST RESULTS

Specimen					Applied Load			
Type	No.	I.D. (in.)	O.D. (in.)	Area (in.²)	Type	Ult. (lb.)	Ult. Stress	
1-1	1	0.991	1.104	0.148	Tension			
	2	0.993	1.106	0.187	T	16400		
	3	0.993	1.116	0.204	T	16140		
	4	0.993	1.109	0.192	Comp			
	5	0.993	1.116	0.204	C			
	6	0.992	1.104	0.193	C			
1-2	7	0.990	1.115	0.197	T	7600		
	8	0.995	1.114	0.197	T	7400		
	9	0.990	1.111	0.190	T			
	10	0.990	1.113	0.194	C	1600		
	11	0.995	1.118	0.204	C			
	12	0.994	1.108	0.188	C			
1-3	15	1.017	1.236	0.896	C			
	16	1.016	1.237	0.891	C			
	17	1.017	1.235	0.880	C			
1-4	19	0.996	1.208	0.867	C	18240	41.20	
	20	0.996	1.201	0.853	C	17600		
	21	0.996	1.196	0.840	C			
	22	0.996	1.208	0.862	C	16480		
	23	0.994	1.205	0.851	C	14640	43.4	
	24	0.994	1.194	0.844	C			
1-5	25	1.018	1.073	0.0900	T	7700		1.
	26	1.019	1.070	0.0837	T			1.
	27	1.019	1.074	0.0404	T			11.
	28	1.018	1.078	0.0480	C			
	29	1.020	1.076	0.0422	C			
	30	1.020	1.077	0.0439	C			
1-6	31	1.018	1.107	0.149	T	11640		
	32	1.018	1.103	0.142	T	10840		
	33	1.019	1.103	0.140	T	11680		
	34	1.020	1.104	0.140	C	11800		
	35	1.019	1.102	0.147	C	10700		
	36	1.019	1.102	0.136	C	9140		

See Table 4.

66

TABLE 9. TORSION TEST RESULTS

Specimen		I.D. (in.)	O.D. (in.)	Area (in.^{2})	Ult. Load (in. - lb.)	G (10^6 psi)	Ult. Stress (psi)
Type[*]	No.						
II-1	37	1.011	1.125	0.191	1730	1.5	17,793
	38	1.013	1.125	0.188	1700	1.7	17,749
	39	1.011	1.125	0.191	1680	1.7	17,279
II-2	40	0.996	1.108	0.185	2650	2.6	28,589
	41	0.995	1.115	0.199	2200	2.6	22,094
	42	0.996	1.114	0.195	2400	2.5	24,491
II-3	43	0.994	1.050	0.090	630	0.91	14,079
	44	0.993	1.050	0.091	590	0.90	12,972
	45	0.995	1.050	0.088	740	0.92	16,813
II-4	46	1.018	1.100	0.136	980	0.65	14,073
	47	1.017	1.102	0.141	990	0.77	13,718
	48	1.018	1.100	0.136	1080	0.73	15,508
II-5	49	1.002	1.134	0.221	2580	0.77	18,371
	50	1.001	1.132	0.219	2280	0.69	16,418
	51	1.000	1.131	0.219	2090	0.73	16,440
	52	1.006	1.139	0.224	2100	0.70	15,973
	53	1.006	1.129	0.206	2120	0.63	14,545
II-6	54	1.000	1.074	0.121	1110	1.65	23,078
	55	1.000	1.076	0.124	1020	1.56	20,603
	56	1.002	1.084	0.134	1110	1.54	18,921
	57	1.001	1.084	0.136	1090	1.56	18,490
	58	1.002	1.091	0.146	1070	1.62	20,300

[*]See Table 5.

TABLE 10. BEARING TEST RESULTS

Specimen		Thickness (in.)		Pin Dia.	Ultimate Load (lbs)	Ult Bearing Stress (psi)
Type*	No.	Steel	Comp.			
	59	0.10	0.258	3/16	2,475	51,000
III-1	60	0.10	0.260	3/16	2,535	51,800
	61	0.10	0.258	3/16	2,500	51,500
	62	0.10	0.257	1/4	3,910	60,900
III-2	63	0.10	0.257	1/4	3,625	56,400
	64	0.10	0.257	1/4	3,825	59,500

*See Figures 26 and 27.

BALLISTIC VULNERABILITY EVALUATION (HHI-SPONSORED TEST)

A ballistic vulnerability test was undertaken to determine the vulnerability of the CTS to the 23mm HEI-T projectile threat. The tests on two simulated tailboom shells determined the suitability of design refinements to be incorporated in the CTS. The test articles consisted of two tapered cylindrical specimens designed to simulate the CTS structural shell from Sta 450 to 547. Both specimens were of sandwich construction with adapters used to interface with the metal tailboom ballistic test fixture. The specimens were honeycomb sandwich construction with composite face sheets and Nomex core. Figure 31 shows the details of construction. Specimen #1 had 0° graphite/±60° E-glass/90° Kevlar skins with 200 x 200 aluminum wire mesh on the outside surface for lightning protection. Specimen #2 had 90°/±12.5°/90° all graphite skins with no lightning protection. Instrumentation consisted of a set of photoelectric velocity screens and electronic time interval counters for determining the impact velocity of the projectiles, and a load cell to verify load conditions. Both high speed and still photographic records were made.

An equivalent hover load was applied to the loading fixture (approximately 1,500 lbs) during and after ballistic impact. Each test specimen was subjected to one Soviet 23mm HEI-T projectile with an MG-25 delay fuze at 1,500 ±50 ft per sec in an aligned attitude at Station 510. Figure 32 shows the test setup and impact location.

Specimen #1 shows less severe damage than Specimen #2 due to the excellent energy absorption capacity of the Kevlar and E-glass, although both specimens are considered successful in defeating the 23mm threat.

Ballistic damage to Specimen #1 consists of a clean entrance hole and three zones of exit damage. See Figure 33 through 36. Zone 1 consists of an area of approximately 8 inches in diameter on the back side of the specimen on the shot line. Damage in this area consists of approximately five holes ranging in size from one to two inches in diameter. One hole is accompanied by a torn face sheet approximately 2 by 6 inches. Zone 2 consists of an area approximately 24 inches in diameter on the back side of the specimen. Damage in this area consists of a large number of small perforations (less than one inch in diameter) spaced relatively widely. Zone 3 consists of two areas approximately 30 by 6 inches along the top and bottom of the specimen just forward of the center line. Damage in this area is most severe with a multitude of small (less than one inch) holes accompanied by some local tearing and delamination of the outer face sheet. Delaminations and tears range up to approximately 3 by 4 inches, maximum. No large holes or delaminations appear in the specimen and sufficient cross section remains intact to assure safe flight.

Figure 31. Ballistic Test Specimen Construction

Figure 32. Ballistic Test Setup and Impact Location

70

Figure 33. Ballistic Damage Zones.

71

Figure   Damaged

Figure   Drainage

Figure 36. Specimen #1 -- Rear View With Damage

Damage to Specimen #2 is more severe than to Specimen #1. However, residual strength of the specimen is not reduced sufficiently to prevent carrying the hover load. See Figures 37 through 40. Referring to the same zone designations as for Specimen #1, Zone 1 damage is quite similar with slightly more delaminations of the skin. Zone 2 damage is also very similar to that for Specimen #1, although the perforations through the all-graphite skin are much cleaner due to the brittleness of the graphite fibers compared to the Kevlar and fiberglass fibers. Several of the holes are accompanied by minor local delaminations of the skin. Zone 3 damage to Specimen #2 is much more severe than Specimen #1. Although the majority of the holes are smaller, several large holes are present with an area of approximately 6 by 18 inches torn away from the honeycomb core on the lower side.

Photo 80-10881-13

Figure 57. Ballistic Specimen #2 -- Undamaged


Photo 80-10881-22

Figure 58. Specimen #2 -- Front View With Damage

74

Photo 80-10881-25

Figure 39. Specimen #2 -- Close-up Front View With Damage

Photo 80-10881-23

Figure 40. Specimen #2 -- Rear View With Damage

LIGHTNING PROTECTION EVALUATION (HHI-SPONSORED TEST)

Preliminary lightning tests were conducted on two graphite/Kevlar 12- x 24-inch flat test panels that were representative of the tailboom laminated sandwich in the Sta 370 region (see stacking sequence in Table 2 of Figure 9) The tests consisted of high current tests in which 200 kiloamperes (or as much as the specimen would pass) was fired through the sample from end to end, and a 100 kiloampere discharge fired as a restrike into an inboard area of the specimens.

The test arrangement is shown in Figures 41 and 42. The test results are summarized as follows:

- A 150,000 ampere end-to-end discharge on these flat panels causes only very slight damage, but the current is limited by the resistance of the graphite. An additional discharge across half the panel (to lower the resistance) also causes only slight damage. See Figures and 44.

- A 100,000 ampere discharge inboard on the sections representing a swept stroke causes delamination of the outer skin of both test samples over an area approximately ten inches square. The damag appears to be severe at first, but it is determined not be flight critical. See Figures 45 and 46.

Figure 41. Test Arrangement for Stationary 200,000 Ampere Discharge)

Figure 42. Test Arrangement for Swept Stroke Tests

77

Photo No. 4740

Figure 45. Stationary Discharge Damage — Specimen 1

Photo 80-4742

Figure 44. Stationary Discharge Damage -- Specimen 2

Photo A-4741

Figure 45. Swept Stroke Discharge Damage -- Specimen 3

The tests may be summarized as having caused little damage in the case
of 150,000 amperes from end-to-end of the test section, but inboard 75,000
ampere discharges cause extensive delamination of the outer skin in direct
contact with the arc. The damage in the latter case is less severe than the
ballistic damage caused by a 23mm HEI-1 projectile, and this is considered
to be non-flight critical. In either case, the damage is considered repair-
able, even in the event of a swept lightning strike directly to the tailboom.

It is concluded that because the skin can withstand a swept lightning stroke
(which is noted as an unlikely event) that further protection need not be
provided.

A feasibility study was conducted for the #1 FM antenna that is integrated into the trailing edge of the vertical tail to determine if its operation is compatible with the composite tail section. The study included testing of the various composite materials proposed for use, and included comparative impedance, patterns, and gain measurements in the FM frequency band for both aluminum and graphite/epoxy composite tail section mockups. Antenna impedance, pattern, and gain were measured. The purpose of the study was to determine if the existing FM #1 Vertical Stabilizer Trailing Edge Antenna designed for installation on a metal tail section would provide acceptable performance when installed on a composite tail section, and to provide recommendations for antenna redesign if so indicated by the study.

The electrical properties of materials were studied to determine the construction of the composite mockup to simulate the electrical characteristics of the tail structure closely and with reasonable cost. Unidirectional graphite fabric was used in an epoxy resin wet layup to electrically simulate the semiconducting members of the mockup. Since structural strength was not needed for the mockup, part thicknesses were chosen to simulate the R.F. properties of the structure. Graphite parts were reduced to 0.06 inch thickness, thereby limiting the cost of the mockup and shortening fabrication time. This amounts to six plies of the unidirectional graphite fabric use. (90% unidirectional graphite fabric, T-300, 3000 filament count with 10% glass fill fibers. Woven Structures Style No. ES 1---.)

One composite material designated for study and test was the Thorstrand (aluminized fiberglass)/Kevlar/graphite/epoxy laminate. The electrical properties of this candidate are very difficult to analyze and test because the Kevlar dielectric layer separates the two semiconducting layers. Resistance measurements were made on the Thorstrand alone and on graphite epoxy alone. Manufacturer's resistivity data was also obtained. Composite materials providing improved strength-to-weight characteristics over aluminum fall in the category of electrically non-conducting (dielectric) or semi-conducting materials, whereas aluminum is highly conductive to direct electrical current (DC) and is known as a good conductor. Based on these materials, electrical tests, and the lightning tests, it was determined that the Thorstrand was not needed for the mockup, and only graphite and fiberglass were selected for its construction.

For antennas in the VHF frequency region and below, the airframe on which they are installed form a part of the antenna and contribute to its impedance, radiation pattern, and gain characteristics. The degree to which this is true depends upon the antenna configuration as well as the airframe configuration and the physical relation between antenna and airframe. If the airframe is highly conductive to the RF energy, these characteristics can vary widely when compared to a nonconducting or semi-conducting airframe.

To satisfy the requirements of this study, it was necessary to have two full scale AH-64A tail mockups. Since the trailing edge antenna is designed to operate on the metal version of the tail section, a metal mockup from the AH-64A program was provided for this purpose. All parts of the tail structure from Sta 450 aft that are necessary to electrically simulate the AH-64A metal tail section are included. The composite tail section mockup includes the tailboom skin, vertical spar box skin, and the ribs and spars within the stabilator. Stacking angles and the number of plies are maintained as closely as possible. The stabilator skin is fabricated of epoxy fiberglass. Additional parts of the tail section included in the mockup are tail rotor shaft and gearbox, vertical rotor driveshaft, and tail landing gear. The stabilator is movable in elevation within the +10° to -45° limits. Figure 47 shows the AH-64A graphite tail section mockup installed on the tower/positioner. Figure 48 is a schematic of the equipment.

The Vertical Tail Trailing Edge (VSTE) Antenna (P/N 7-211122630) is a folded dipole antenna integrated into the trailing edge fairing of the AH-64A helicopter vertical tail. An aluminum sheet metal spar at the forward side of the antenna and forms the "folded" portion of the antenna element.

Swept frequency impedance measurements were performed in the 30 to 70 MHz frequency range of the trailing edge antenna installed on both the aluminum and composite tail section mockups. These measurements enable a judgement to be made as to the comparative level of difficulty to be anticipated in impedance matching the antenna to the 50-ohm transmission line in the two different installation environments. A network analyzer was used to measure the antenna impedance.

Figures 49 and 50 show the impedance plots on impedance coordinates of the Smith Chart, with several Frequency points in the FM band marked. These impedance plots show that the antenna impedance variation between the two installations is small. As a result, major impedance matching network compensation is not required to provide antenna impedance performance compatibility on the metal and composite tail sections. At most, some circuit component value changes in the matching network may be required. Antenna impedance is not appreciably affected by changing stabilator position on the metal mockup.

Mockup

Figure 48. Radiation Pattern Test Setup.

Figure 49.   AH-64A Trailing Edge Antenna on Aluminum Mockup

Figure 50. AH-64A Trailing Edge Antenna on Graphite Mockup.

Azimuth radiation pattern and gain measurements were performed at six frequencies in the VHF-FM band on the trailing edge antenna installed on both the aluminum and graphite tail mockups. The test setup is shown in Figure 48. The radiation patterns are shown in Figures 49 and 50. Each contains a gain reference to allow the relative gain of the antenna on the graphite mockup to be compared to that of the antenna on the aluminum mockup. No attempt has been made to measure the absolute antenna gain for this program, since relative gain provides the necessary data for comparison. As shown by the patterns, the major difference is found in the 50 MHz pattern for the graphite mockup. This pattern contains a deep azimuth null and exhibits much lower gain than that for the metal mockup pattern. This condition is not characteristic of this antenna. The deep null can be caused by a parasitic element located on the mockup forward of the antenna. Since the only part of the mockup that has this characteristic is the tail rotor vertical driveshaft, it was removed and the patterns were rerun at one MHz intervals from 40 to 60 MHz. The null remained at frequencies of 49, 50, and 51 MHz, indicating that it is not caused by the driveshaft. This pattern and gain deficiency is believed to be caused by the test environment.

The test tower contains metal positioner, supporting structure, and connecting cables that can act as parasitic elements and are resonant at one or more frequencies. Resulting radiation patterns can contain both azimuth and elevation nulls. The azimuth null is evident in the azimuth pattern. An elevation null located on or near the horizon can also result in the lowered gain. But, as shown by the 50 MHz pattern for the aluminum mockup, a null is not present. The metal skin of the mockup is responsible for this change. The conducting skin has most likely upset the parasitic arraying effect of the test structure to eliminate the null entirely or shift it to a frequency not tested when the antenna is installed on the aluminum mockup. A less severe pattern deficiency occurs at 60 MHz on the metal model. The two deeper side nulls and lower relative gain are caused by the parasitic arraying effect of the antenna tower structure and the aluminum mockup.

Antenna pattern tests were run on the metal mockup with stabilator up 10 degrees and down 45 degrees for comparison with the 0 degree position. Negligible differences were noted at the six test frequencies. These tests were not repeated for the composite mockup because the less conductive stabilator (graphite spar/rib -- Kevlar skin) is anticipated to cause an even smaller effect.

Antenna impedance data for both mockup installations shows only minor antenna impedance variation between the two mockups. Impedance tests also show that antenna impedance is not appreciably affected by changing stabilator position. Hence, major impedance matching compensation is not required.

The comparative gain performance of the trailing edge antenna installed on the two mockups is quite favorable as Figures 51 through 56 show. For four out of the six test frequencies, the gain difference is 2 dB maximum. At the two remaining test frequencies, the gain varies 6 to 8 dB due to the effects of the test environment. It was concluded that this trailing edge antenna installed in the graphite/epoxy tail section meets the Contract requirements for the #1 VHF-FM antenna.

Figure 51. Antenna Pattern -- 30 MHz

Figure 52. Antenna Pattern -- 40 MHz

Figure 53.   Antenna Pattern -- 50 MHz

Figure 54.   Antenna Pattern -- 60 MHz

91

Figure 55.   Antenna Pattern -- 70 MHz

Figure 56.   Antenna Pattern -- 70 MHz

92

MANUFACTURING TECHNOLOGY REFINEMENT

WET FILAMENT WINDING METHODOLOGY

The previous work that HHI and FSI had accomplished in the field of advanced composites primary structures was primarily in the field of the wet filament winding (WFW) cocure process. The CTS MM&T program was structured to continue the use of this process to the greatest extent possible, and refine it for the special requirements of the three CTS components.

The WFW process is summarized in Figure 57. This figure shows how bands of rovings are laid onto a rotating mandrel along geodesic paths until the entire surface of the mandrel is covered with a layer of filaments oriented in a ± angle pattern. This process can lay filaments onto a mandrel at any angle between approximately ±5 degrees and 90 degrees relative to the axis about which the mandrel rotates. Because the roving band follows a geodesic path to avoid slipping, the angular orientation is constant ± angle from end to end on a cylindrical mandrel. But it is a variable from end to end if the mandrel is conical (small ± angle at the large end to large ± angle at the small end). Each end of the mandrel has a suitably shaped dome for securing the filaments and guiding them smoothly as they turn around to make the reverse pass along the mandrel. It has been demonstrated that the mandrel need not have a circular cross section — rectangular and triangular cross sections are readily wound.

The band of wet rovings is created by passing a number of dry filament rovings (approximately 16 in number) through a resin impregnator such as that shown in Figure 58. It meters resin into the filaments to achieve a fixed fiber volume ratio. All of the filaments may be alike, such as graphite, or they may alternate, for example graphite and Kevlar, to form a hybrid composite. A dispensing eye whose travel along the mandrel is geared to the rotation of the mandrel guides the band of wet filaments onto the mandrel at the desired angle.

The tailboom and the vertical tail spar of the CTS are approximately cylindrical in shape and so are prime candidates for filament winding. The stabilator skin is also appropriate for WFW since its stacking sequence is 90/±45/90 degrees (90 degrees being the chordwise direction) and can be wound on a cylindrical mandrel, cut off, and formed to shape over an airfoil-shaped mandrel. With the basic concept of WFW being well established, the primary manufacturing development work for the CTS was the refinement of the details of how to wind each component.

93

Figure 57. Tubular Element Filament Winding Process

Figure 98. Resin Impregnator

MICROCOPY RESOLUTION TEST CHART

NATIONAL BUREAU OF STANDARDS 1963 A

TAILBOOM

The tailboom is a sandwich wall, hollow cone with the honeycomb filler deleted at both ends of the structure to make the walls a solid laminate in these regions. The configuration of the mandrel on which the tailboom would be wound is indicated in Figure 59. From Sta 370 to 450 the diameter tapers and the cross section varies smoothly from an essentially rectangular shape at the front to a circle at Sta 450. It is a circular cone between Stations 450 and 529, and then is cylindrical to the end of the tailboom. The shape of the end dome on the large end of the mandrel is critical for guiding the filament turnaround and also to guard against the ±8 degree filaments bridging over the flat region on the top of the forward end of the tailboom. The mandrel's geometry was worked out on the full-scale toolproofing mandrel shown in Figure 60. (This was lightweight fiberglass mandrel adequate for the development work but not suitable for CTS fabrication.) Figure 61 shows the removable segment that aligned the four intercostals that lie in the aft end of the tailboom, and the end domes. The ring frames that are centered on Sta 532.33 are clamped between the right end of the mandrel shown in Figure 60 and the left end of the slotted mandrel shown in Figure 61. The three ring frames (Sta 387.00, 531.23, and 533.43) and the four intercostals are hand layups. They are made in metal female molds to provide accurate contours for matching the interior of the tailboom, using silicon blocks to supply the molding pressure. This technology was considered to be well enough understood that it was not necessary to undertake a special manufacturing development program.

Figure 59. Tailboom Mandrel Geometry

96

Figure 60. Tailboom Mandrel - Main Section (Toolproofing)

Figure 61. Tailboom Mandrel - Removable Sections
(Toolproofing)

VERTICAL TAIL SPAR

The structure of this spar is similar to that of the tailboom - solid laminate walls at the ends and sandwich wall in the center. The major difference is that its periphery is smaller, and its cross section is generally trapezoidal in shape. This spar, too, has frames for the tail rotor gearbox support wound into the spar.

A full-scale toolproofing mandrel was made of fiberglass and was used for determining the winding procedure (see Figure 60). The development work included determining the manner of holding the composite frames in place in the mandrel, developing the configuration of the end domes, and determining how to remove the mandrel from the cured spar box. Figure 62 shows the results of winding on an early, unsatisfactory end dome configuration. Note how the filaments are spread in an unacceptable manner.

The frames that go into the vertical tail spar were proposed to be made in female metal molds with silicone blocks for pressurization. This technology was considered to be well enough understood that toolproofing studies were not needed.

STABILATOR

An early stabilator configuration had two spars, four ribs, and a bead-stiffened skin. A tooling development study was made of the skin which is shown in Figure 63. HHI had previous experience with a beaded skin for a composite stabilator for the OH-58A in which a flat, wet skin was worked onto an airfoil-shaped mandrel that had ridges to form the beads. While this was successful for the small size of the OH-58A, it was determined to be inappropriate for the AH-64A stabilator because of the size, and because of the filament distortion that was caused by forcing the flat skin to form around the deep beads. A second step, which is shown in Figure 63, consisted of forming beads separately and cocuring them to the skin that was draped over a single curvature mold. Based on the toolproof skin, this too appeared impractical from an overall skin stability standpoint and the design concept was changed to the spar/rib/skin structure described in the Design Refinement section. The technology for forming the spars and ribs in female metal molds with silicone blocks for pressure was considered well enough known not to need special development.

Vertical Tail Spar Winding Pattern Study

Figure 63. Bead-Stiffening Study for Stabilator Skin

RESIN CURE CYCLE

HHI and FSI recommended that Applied Plastics Corpor... resins and hardeners be used as the epoxy matrix for the structure:

- 2434 — epoxy resin

- 2347 — 300°F cure hardener

- 2340 — room temperature cure hardener

The 300 °F cure hardener, 2347, would be used for all filament winding of major structural elements. The 2340 hardener would be used for small, noncritical parts. The 2347 hardener is formulated to have a 24-hour pot life at room temperature. This time can be extended to 72 hours if stored at temperatures below 40°F, and to two weeks if stored at 0°F.

The cure cycle for the APCO resins has been determined through evaluation tests to be as shown in Figure 64. The Phase I cure is analogous to "B-staging" in conventional prepregs. This cycle rigidizes a component by partially cross-linking the resin so that the component is rigid enough to be handled, mounted in winding mandrels so wet filaments may be wound over it, or positioned in assembly fixture for final assembly by cocuring.

The "final assembly by cocuring" cycle that goes to 300 °F raises the glass transition temperature above the range of normal operating temperatures for strength at elevated temperatures, and produces a structure that is free of micro-cracking.

Figure 64. Resin Cure Cycle

FABRICATION REFINEMENT

At the time that the program was terminated, no production tooling had been built. The concept and approximately 60 percent of the drawings for it had been completed. The three components of the CTS were to be built on aluminum tooling to fulfill the requirement that the tools be satisfactory for fabricating a minimum of 50 shipsets of the CTS. The jig for assembling and aligning the three CTS components as an assembly was to use the tailboom winding mandrel as the base, with jigs and fixtures added to support the various components for bonding or bolting them together.

TAILBOOM TOOLING

The proposed tailboom mandrel is shown schematically in Figure 65. It consists of five major parts, plus two clamps to lock it together. The main section is generally conical in shape and has a shaft extending out of each end. It is shaped to the inside contour of the tailboom from Sta 370 to 429 and is an aluminum monocoque structure stiffened with bulkheads and longerons. The shafts are supported by the two bulkheads nearest to each end. The shafts and the bulkheads are perforated so that hot air may be circulated inside the mandrel while the resin cures in the oven.

The large end turn-around dome slips over the shaft of the main mandrel and is pinned to it so they will turn together. A wedge-type clamp anchors the dome to the shaft. The dome is contoured to guide the filaments smoothly as they leave and reapproach the mandrel, and to prevent bridging of the filaments across the flat spot on the mandrel. The dome has a channel all around it where it touches the main mandrel to serve as a cutoff guide for trimming the cured tailboom. This channel is to be filled with plastic foam during the winding process to present a smooth winding surface.

The cylindrical segment adjacent to the small end of the main mandrel slips over the shaft, is pinned to the main mandrel, is held against the main mandrel by the small end dome, and is locked to the shaft by a wedge lock at the outboard end of the end dome. This cylindrical mandrel is spaced away from the end of the main mandrel far enough to enclose the two graphite/epoxy frames that are bonded together as an assembly with aluminum tooling blocks between, and are centered at Sta 532.33. The tooling for this assembly is indicated in Figure 66. The cylindrical section of the mandrel has four lengthwise channels formed into its surface to accept the four graphite/epoxy intercostals that lie in the aft end of the tail boom. The end dome has a channel around its periphery where it touches the cylindrical mandrel to serve as a cutoff guide. This channel is filled with foam to provide a fair surface for winding.

Figure 65. Tailboom Mandrel

MAIN MANDREL

547

533.43

531.23

450

STA 370

END DOME

WEDGE LOCK

WEDGE LOCK

END DOME

SLOTTED MANDREL

FILLER RING

103

Figure 66. Frame Assembly Fixture
Schematic

The filler ring indicated in Figure 65 is a removable, tapered aluminum ring that fits closely onto the main mandrel and is shaped to the tapered aft end of the honeycomb filler. This ring must be able to slip off of the aluminum mandrel so that the cured tailboom will not be mechanically locked to the mandrel.

The graphite/epoxy frames at Sta 387.66, 531.23, and 533.43 and the four graphite/epoxy intercostals are formed in matched metal dies using trapped silicone rubber to furnish the molding pressure during the cure cycle. Figure 67 is a schematic cross section of such a mold. The design shows the Sta 533.43 frame and the intercostals attached to each other by HyLoc fasteners. This subassembly is located in the mandrel as the mandrel is being assembled.

Figure 67. Frame Mold Section Schematic

Flat-pattern metal templates are provided for cutting out the honeycomb filler for the sandwich portion of the tailboom, and for the individual sheets of prepreg material that are laid up to form the ring frames, intercostals, and tailboom skin reinforcements. Metal jigs that key to the mandrel serve to locate the reinforcements.

A conventional router is set up to bevel the ends of the honeycomb panels.

A wet filament winding machine similar to the one shown in Figure 68 is used to wet filament wind the tailboom. This machine takes dry composite rovings, impregnates them with a metered amount of resin, and winds them onto the mandrel at the spiral angles required by the design.

Figure 68. Helical Winding Machine

Aluminum male molds (Figure 69) are used to lay up prepreg material to form the angles that attach the tail rotor driveshaft cover.

Figure 69. Angle Mold Schematic

The proposed sequence for fabricating the composite components of the tailboom is laid out in Figure 70. It begins with the fabrication of premolded frames, goes through filament winding, curing, and subassembly of miscellaneous parts. From this operation it goes on to final assembly that is described below.

VERTICAL TAIL TOOLING

The mandrel for the hollow box structure of the vertical tail spar is the same in concept as that for the tailboom, except that it has a trapezoidal cross section. See Figure 71. The main part of the mold is an aluminum monocoque box with a shaft extending from each end. This mandrel is formed to the inside contour of the spar box. An end dome that is shaped to

Figure 70. Tailboom Fabrication Sequence

108

WEDGE LOCK

END DOME

TIP MANDREL

MAIN MANDREL

END DOME

WEDGE LOCK

Figure 71. Vertical Tail Spar Mandrel

perform the filament turnaround function and guide the filaments off of and onto the four-sided mandrel slips over the extension shaft at the big end of the mandrel. It is pinned to it to force them to rotate together and is secured by a wedge-type clamp. The tip end portion of the mandrel slides over the main mandrel's extension shaft and is pinned to it. A suitable end dome is mounted beyond this portion of the mandrel and is attached by another clamp. The tip-end portion of the mandrel is spaced away from the upper end of the main mandrel to allow insertion of the upper frame subassembly so that it may be wet filament wound into the vertical tail spar. Provisions are made for keying this subassembly to the mandrel.

The five composite frames (three upper frames to support the tail rotor gearbox and two lower frames to support the intermediate gearbox) are formed in matched metal molds with trapped silicone rubber furnishing the molding pressure.

The three frames that support the tail rotor gearbox are formed into an assembly that goes into the spar box mandrel. A three part wash-out mold locates the three frames while a prepreg shell is wrapped around them and cured. See Figure 72.

CONNECTING SHELL   WASHOUT MANDRELS   STEEL HARDBACK

GEARBOX SUPPORT FRAMES

Figure 72. Frame Subassembly Tool Schematic

110

Flat pattern metal templates are used to cut out the honeycomb filler for the spar box, and for the laminates that make up the frames, doublers, and fairings.

A routing fixture is clamped to the spar box and the top and bottom ends of the box are cut to shape. A support fixture holds the spar box and provides jig points for positioning the two lower bulkheads, and the four aluminum lower attachment fittings. These are held in place while HyLoc fasteners secure the components. A conventional milling machine faces off the attachment lugs and precisely bores holes in them for the vertical tail attachment bolts.

A female metal mold is used to form the vertical tail's tip cap, and contains appropriate keys for locating the navigation lights, radar warning antennas, and lightning protection strip. It is shown schematically in Figure 73.

The trailing edge fairing is a purchased part that contains communications antennas and is furnished by the antenna subcontractor. The leading edge fairing is taken unchanged from the prototype vertical tail.

A closed cavity metal mold with silicone rubber pressurizing blocks is used for forming each of the T-bars that are placed at the corners of the spar box for attaching the leading and trailing edge fairings. Figure 74 is a schematic cross section of such a mold.

The T-bars are bonded to the four corners of the vertical tail spar in a bonding jig similar to that shown in Figure 75. Trapped silicone rubber is used to supply the bonding pressure.

Figure 76 shows the proposed sequence for fabricating the vertical tail spar by the wet filament winding process. This spar assembly goes into the CTS final assembly process as described below.

STABILATOR TOOLING

The stabilator skin is wet filament wound on a cylindrical aluminum mandrel (Figure 77), cut off, and cured on an aluminum male mold shaped to the airfoil contour as Figure 78 indicates.

The spars and ribs are laid up in matched metal molds with silicone rubber pressurization in a manner similar to that described for the tailboom frames in Figure 67.

111

VACUUM BAG

COMPOSITE MATERIAL

METAL MOLD

A-A

Figure 73. Tip Cap Mold Schematic

COMPOSITE COMPONENT

SILICONE

MATCHED METAL MOLD

Figure 74. T-Bar Mold Section Schematic

TRAPPED SILICONE RUBBER

SPAR BOX

TEE-FLANGE

Figure 75. T-Bar Bonding Jig Schematic

113

Figure 76. Vertical Tail Fabrication Sequence

VERTICAL TAIL FABRICATION

LAY-UP MATERIAL IN CLOSED CAVITY MOLDS AND CURE SHAPES REQ

TRIM COMPONENTS

BOND & CURE COMPONENTS TO O.D. IN ASSY. FIXTURE

ASSEMBLE WINDING MANDREL & SECURE FOR WINDING

WIND SKIN ON MANDREL ASSY

PLACE DOUBLERS, CORNER ANGLES, AND HONEYCOMB ON MANDREL

WIND OUTSIDE SKIN

MOLD CORNER ANGLES AND TEE-FLANGES

PLACE TEE-FLANGES AND CURE

TRIM & DRILL AND BOLT ROOT FITTINGS IN FINAL ASSY FIXTURE

114

Figure 77. Stabilator Skin Winding Mandrel Schematic

Figure 78. Stabilator Skin Mold Schematic

115

The tip caps are laid up on metal male mold as shown in **Figure 79.**

COMPOSITE TIP CAP

VACUUM BAG

METAL MOLD

Figure 79. Tip Cap Mold Schematic

The stabilator's interior structure is assembled in a fixture that locates the spars, ribs, and tip caps. It includes clamping devices to apply bonding pressure where the ribs and tip caps bear against the spar. The stabilator final assembly jig (Figure 80) is basically a grid structure that locates the skin segments over the internal structure of the stabilator and has an array of elastomeric pads that provide the bonding pressure. They press the skin against the spars and ribs, and the upper and lower skins together at the trailing edge. A single blind rivet at the nose of each rib aligns the skin and ribs positively. This jig also has provisions for aligning the stabilator hinge fittings with respect to the stabilator, so that they may be attached with mechanical fasteners.

The process shown in Figure 81 is the proposed fabrication sequence for the stabilator. Final assembly into the CTS is described below.

RIB SEGMENTS

SKIN

BONDING JIG
WITH
ELASTOMERIC
PADS

A-A

SPARS

Figure 80. Stabilator Skin Bonding Jig Schematic

117

Figure 81. Stabilator Fabrication Sequence

MOLD TIP CAPS

TRIM TIP CAPS

ASSEMBLE SPAR/RIB STRUCTURE

ASSEMBLE AND CURE

TRIM SPARS

TRIM RIB SEGMENTS

TRIM SKIN

MOLD SPARS

MOLD RIB SEGMENTS

MOLD SKIN

INSTALL HINGE/ACTUATOR BRACKETS & EROSION PROTECTION MATERIAL

FILAMENT WIND SKIN

TRIM & DRILL ASSEMBLY

118

FINAL ASSEMBLY

Final assembly of the CTS is accomplished in the fixture that is shown
schematically in Figure 82. Its first purpose is to locate the aluminum rear
bulkhead in the tailboom and hold it while it is bolted in place. Next it serves
as a jig for drilling the four bolt holes that attach the vertical tail, for mill-
ing off the top of the vertical tail attach bosses, and for locating the jacking/
tiedown fitting. It has drill jig plates for locating the tail rotor driveshaft
bearing and anti-flail supports and for mounting the steps and flare
dispenser. It holds the vertical tail in alignment while the gearboxes and
controls are installed. It positions the stabilator while its actuators are
adjusted.

When the CTS assembly is taken out of this fixture, it is ready to be
mounted on the AH-64A airframe. An alignment jig is needed for attaching the
CTS to the metal fuselage at Sta 370; a jig that is not a part of the MM&T pro-
gram tooling but is to be provided by the AH-64A project organization under
AVRADCOM Contract DAAJ01-77-C-0064, Modification P00108.

119

FWD FRAME PLATE & AFT CAGE ARE STATIONARY

LOCATING & BOND FIXTURE

ALL TRIM BOND FIXTURES INDEX TO ASSY FIXTURE (TYP HAND/STEP&FLARE)

AFT CENTERING DISC (TO MOLD I.D. OF CYL.)

AFT FRAME / FITTING SUPPORT BRIDGE

FITTING SUPPORT BRIDGE (DUMMY ROOT)

DRILL / FACE BRIDGE

HAND/STEP BOND FIX.

FORWARD LOCATING FIXTURE

FRAME LOCATING JIG

STATIONARY FIXTURE

CENTER PART IN FIXTURE

AFT LOCATING FIXTURE

AFT FRAME LOCATING JIG

FITTING SUPPORT

INSTALL AFT FRAME & ALL COMPONENTS BY FIXTURES INDEXED TO ASSY FIXTURE

DRIVE SHAFT ATTACHING JIG

ESTABLISH STATION BY INDEXING FITTING TO FIXTURE

AFT FRAME FIXTURE INDEXES TO ASSY FIX

Figure 82. Final Assembly Fixture Functions

120

NON-DESTRUCTIVE EVALUATION (NDE)

NDE is planned to ensure that all CTS components meet the design criteria, that they are free of internal defects, and that they have the proper internal geometry. Reports of all NDE activities are maintained by component serial number for permanent record.

Types of defects that could degrade the components' performance are:

- Delaminations

- Unbonded areas

- Porosity or voids

- Resin rich or resin starved areas

- Geometry of internal spars

- Thick bond lines

- Foreign objects

- Defects in metal attach fittings

The importance of these defects varies with their location and size in components. Tentative criteria for various areas and sections of the CTS components are given below.

Figure 83 indicates critical zones A, B, and C of the tailboom. Allowable limits for disbonds and delaminations that may occur in the ring stiffener, sandwich wall of the shell mainframe, frames, intercostals, and fairing hinge supports are detailed in Table 11. NDE techniques scheduled for use on tailboom hardware are listed in Table 12.

Figure 84 delineates critical zones A and B of the vertical tail. Table 13 lists the limits for disbonds and delaminations allowed in the preassembly structure and in the completed item. Table 14 is a matrix of NDE techniques scheduled for vertical tail components.

STA
547

ZONE
C

STA
450

ZONE
B

STA
387.7

STA
370

ZONE
A

Figure 83. Composite Tailboom Inspection Zones

122

TABLE 11. TAILBOOM CRITICAL DISBOND AND DELAMINATION LIMITS

Zone A

| 1. Solid Laminate:	No single delamination to be larger than 0.5 inch in diameter.
	No delaminated areas to be within 3.0 inches of each other.
	No more than 10 percent delamination allowed.
2. Sandwich Wall:	No single delamination or disbond to be larger than 1.0 inch in diameter.
	No delaminated or disbonded areas to be within 3.0 inches of each other.
	No more than 10 percent delamination or disbond allowed.

Zone B

1. Sandwich Wall:	No single delamination or disbond to be larger than 1.0 inch in diameter.
	No delaminations or disbonded areas to be within 3.0 inches of each other.
	No more than 10 percent delamination of disbond allowed.
2. Fairing Hinge Supports:	No more than 20 percent disbond allowed.
	No single disbond to be more than 1.0 square inch.
	No two disbonded areas to be within 2.0 inches of each other.

Zone C

1. Shell:	No single delamination to be larger than 1.0 inch in diameter.
	No delaminated areas to be within 3.0 inches of each other.
	No more than 1.0 percent delamination allowed.
2. Frame:	No single disbond to be more than 1.0 square inch.
	No two delaminated areas to be within 2.0 inches of each other.
	No more than 10 percent disbond allowed.
3. Intercostals:	No single disbond to be more than 1.0 square inch.
	No two delaminated areas to be within 2.0 inches of each other.
	No more than 10 percent disbond allowed.

TABLE 12. POTENTIAL NDE TECHNIQUES – TAILBOOM

| Section | X-ray | Acoustic Emission (1) | Ultrasonic | | | Impulse Response | Visual (2) | Stiffness Test |
			Harmonic Bond Tester	C-Scan	Bondascope			
Conical Section	X	X	X	X	X	X	X	X
Frames/ Intercostals			X		X	X	X	

(1) During static, dynamic and fatigue testing.

(2) Cut edges, exterior bond surfaces, etc.

124

TABLE 13. VERTICAL TAIL - CENTER BOX CRITICAL DISBOND AND DELAMINATION LIMITS

Zone A
1. Laminate: No delamination to be over 1.0 inch in diameter.   No skin delamination to be within 3.0 inches of another.   No more than 15 percent delamination allowed.

Zone B
1. Preassembly Sandwich Structure: No single void to be more than 0.5 inch in any direction, and not tangent to any edge.   No two void areas to be within 3.0 inches of each other.   No more than 10 percent delamination allowed.
2. Integrally Fabricated Attach Brackets: No disbond to be over 0.5 inch in diameter.   No two disbond areas to be within 3.0 inches of each other.   No more than 10 percent disbond allowed.

125

Figure 84. Composite Vertical Tail Inspection Zones

TABLE 14. POTENTIAL NDE TECHNIQUES – VERTICAL

Section	X-ray	Acoustic Emission (1)	Ultrasonic			Impulse Response	Visual (2)	Stiffness Test
			Harmonic Bond Tester	C-Scan	Bondascope			
Spar Box	X	X	X	X	X	X	X	X
Ribs			X		X		X	
T-Flanges			X		X		X	

(1) During static, dynamic, fatigue testing.

(2) Cut edges, exterior bond surfaces, etc.

127

The stabilators' critical zones A and B are defined in Figure 85. Tolerances for bond and laminate defects permitted in preassembly components, attachable details, and the completed structure are delineated in Table 15. Table 16 presents the NDE procedures to be used to evaluate the integrity of stabilator structural parts.

Figure 85. Composite Stabilator Inspection Zones

TABLE 15. STABILATOR CRITICAL DISBOND AND
DELAMINATION LIMITS

Preassembly and Attachable Details	
1. Skin:	No single delamination to be over 1.0 square inch. No delamination to be within 3.0 inches of another. No more than 10 percent delamination allowed.
2. Forward and Aft Spar Assemblies:	No delamination to be over 1.0 square inch. No single delaminations to be within 3.0 inches of each other. No more than 10 percent delamination allowed.
3. Ribs and Caps:	No skin delamination to be over 1.0 square inch. No single delamination to be within 3.0 inches of another. No more than 10 percent delamination allowed.

TABLE 15. STABILATOR CRITICAL DISBOND AND DELAMINATION LIMITS (CONT)

Final Assembly
Zone A
1. Forward and Aft Spar Assembly Bonds: No more than 10 percent disbond allowed.   No disbond to be larger than 1.0 square inch.   No disbonded area to be within 3.0 inches of another.
2. Ribs and Closeouts: No more than 10 percent for ribs and 20 percent for closeout disbonds allowed along attach flanges.   No area of disbond to extend across bonding flange.
Zone B
1. Forward and Aft Spar Assembly Bond: No more than 10 percent disbond allowed.   No single disbond to be more than 1.0 square inch.   No disbonded area to be within 3.0 inches of another.
2. Trailing Edge Bond Joint: No more than 10 percent disbond allowed.   No voids allowed 0.5 inch from trailing edge.
3. Ribs and Caps: No more than 10 percent disbond allowed.   No disbond to extend across bonding flange.

TABLE 16. POTENTIAL NDE TECHNIQUES – STABILATOR

| Section | X-ray | Ultrasonic | | | Impulse Response | Visual (1) | Stiffness Test |
		Harmonic Bond Tester	C-Scan	Bondascope			
Spars	X	X	X	X		X	
Ribs		X	X	X		X	
Assembly		X		X	X	X	X

(1) Cut edges, exterior bond surfaces, etc.

DESIGN TO UNIT PRODUCTION COST

The design to unit production cost (DTUPC) assessment (in Second Quarter 1981 dollars) is based on HHI's experience with procuring and fabricating composites and metal components, and assembling them. The estimate for fabricating composite components is divided into those that are labor-intensive and labor non-intensive. Different process improvement factors are used for each category. The procurement of the metal components is related to similar components in the prototype AH-64A helicopter. The initial estimates are made for the Serial Number (S/N) 010 unit. The costs are worked backward to the S/N-001 unit and then forward to the average for the 536 shipset production base.

The labor required to fabricate the three major composite components is estimated in Tables 17, 18, and 19 for each step in the process. The composite materials required for three CTS components are listed in Table 20.

The fabricated metal components that go into each of the three CTS components and connect them together are estimated in Table 21.

The production improvement factors used in this analysis are:

- Composite fabrication (labor intensive)   80 percent

- Composite fabrication (labor non-intensive)   85 percent

- Purchased metal components   95 percent

- Purchased composite materials   100 percent

The mathematical ratios for these factors relative to the first unit, tenth unit, and cumulative average for 536 units are:

Improvement Factor	S/N-001	S/N-010	Cumulative Average, 536
80 percent	1.0000	0.3286	0.1373
85 percent	1.0000	0.4636	0.2291
95 percent	1.0000	0.8193	0.6281
100 percent	1.0000	1.0000	1.0000

TABLE 17. LABOR FOR TAILBOOM (S/N-010)

		Manminutes	
		Labor Intensive	Labor Non-Intensive
Clean and prepare tailboom mandrel	2 men, 1 hour	120	-
Clean and prepare frame and intercostal molds	7 molds, 1 man per mold per 1/4 hour	105	-
Cut out fabric	2 men, 1/2 hour	60	-
Layup frames and intercostals	7 molds, 2 men per mold per 1/2 hour	420	-
Cure frames and intercostals	1 man, 6 hours	360	-
Trim and prepare honeycomb	2 men, 1 hour	120	-
Trim and assemble frames and intercostals	2 men, 2 hours	240	-
Assembly tailboom mandrel	2 men, 1/2 hour	60	-
Mount mandrel in winding machine	2 men, 1/4 hour	-	30
Wind inner skin	1 man, 50 lb, 8 lb/hour	-	375
Place film adhesive	2 men, 1/4 hour	-	30
Place honeycomb	2 men, 1/2 hour	-	60

TABLE 17. LABOR FOR TAILBOOM (S/N-019) (CONT)

		Manminutes	
		Labor Intensive	Labor Non-Intensive
Place film adhesive	2 men, 1/4 hour	-	30
Place doublers and fillers	2 men, 1/2 hour	60	-
Wind outer skin	1 man, 50 lb, 8 lb/ hour	-	375
Install peel ply	2 men, 1/4 hour	-	30
Overwind	1 man, 1 ft/min, 20 ft	-	20
Phase I cure	1 man, 6 hours	-	360
Remove tailboom from mandrel	2 men, 3/4 hour	-	90
Install frames, etc.	2 men, 1 hour	120	-
Post cure	1 man, 6 hours	-	360
Trim, drill, install metal fittings, finish machine	3 men, 8 hours	1440	-
Inspect	1 man, 2 hours	-	120
Paint	1 man, 2 hours	-	120
Weigh	2 men, 1/4 hour	-	30
Pack for shipment	2 men, 1/4 hour	-	30
TOUCH TIME		3105	2060

TABLE 18. LABOR FOR STABILATOR (S/N-010)

		Manminutes	
		Labor Intensive	Labor Non-Intensive
Clean and prepare skin and broadgoods mandrels	2 men, 1 hour	120	-
Clean and prepare rib, spar and skin molds	32 molds, 1 man, 1/4 hour	480	-
Wind broadgoods	1 man, 40 lb, 8 lb/hour	-	300
Cut out fabric and broadgoods	2 men, 2 hours	240	-
Lay up ribs and spars	16 molds, 1 man/mold, 1/2 hr	480	-
Wind skins	1 man, 30 lb, 8 lb/hour	-	225
Cut out skins	2 men, 1/2 hour	60	-
Lay up skins	2 men, 1 hour	120	-
Phase I cure ribs, spars and skins	Ⓐ	-	0
Trim ribs, spars and skins	2 men, 3 hours	-	960

Ⓐ Coincide with tailboom and vertical fin

TABLE 18. LABOR FOR STABILATOR (S/N-010) (CONT)

		Manminutes	
		Labor Intensive	Labor Non-Intensive
Assembly ribs and spars	2 men, 2 hours	-	240
Cure rib/spar assembly	(A)	-	0
Assemble skins	2 men, 1/2 hour	60	-
Cure stabilator	(A)	-	0
Trim, drill, install metal fittings	2 men, 3 hours	960	-
Inspect	1 man, 1 hour	-	60
Paint	1 man, 1 hour	-	60
Weigh	2 men, 1/8 hour	-	15
Pack for shipment	1 man, 1/4 hour	-	15
	TOUCH TIME	2520	1875

(A) Coincide with tailboom and vertical fin

TABLE 19. LABOR FOR VERTICAL TAIL (S/N-010)

		Manminutes	
		Labor Intensive	Labor Non-Intensive
Clean and prepare spar mandrel	1 man, 1 hour	60	-
Clean and prepare bulkhead and angle molds	8 molds, 1 man, 1/4 hour	120	-
Cut out fabric	1 man, 1 hour	60	-
Lay up bulkheads and angles	8 molds, 2 men/ mold, 1/2 hour	480	-
Cure bulkheads	Ⓑ	-	0
Trim bulkheads and prepare bulkheads and angles	2 men, 2 hours	240	-
Assemble fin spar mandrel	2 men, 1 hour	120	-
Wind inner skin	1 man, 10 lb, 8 lb/ hour	-	75
Place film adhesive	2 men, 1/8 hour	-	15
Place honeycomb	2 men, 1/4 hour	-	30
Place film adhesive	2 men, 1/8 hour	-	15

Ⓑ Coincide with tailboom and stabilator

TABLE 19. LABOR FOR VERTICAL TAIL (S/N-010) (CONT)

		Manminutes	
		Labor Intensive	Labor Non-Intensive
Wind outer skin	1 man, 10 lb, 8 lb/hour	-	75
Place peel ply	2 men, 1/8 hour	15	-
Place caul sheets	2 men, 1/4 hour	-	-
Overwind	1 man, 1 ft/min, 9 ft	-	10
Phase I Cure	Ⓑ	-	0
Remove spar from mandrel	2 men, 1/4 hour	30	-
Install bulkheads and angles	2 men, hour	240	-
Post cure	Ⓑ		
Trim, drill, install metal fittings, and finish machine	2 men, hours	480	-
Inspect	1 man, 1 hour	-	60
Paint	1 man, 1 hour	-	60

Ⓑ Coincide with tailboom and stabilator

139

TABLE 19. LABOR FOR VERTICAL TAIL (S/N-010) (CONT)

		Manminutes	
		Labor Intensive	Labor Non-Intensive
Install leading and trailing edge fairings	2 men, 1/2 hour each	120	-
Weigh	2 men, 1/8 hour	-	15
Pack for shipping	1 man, 1/4 hour	-	15
	TOUCH TIME	1995	370

TABLE 20. COMPOSITE MATERIAL FOR CTS
(SECOND QUARTER 1981 DOLLARS)

	Pounds	Square Feet	$ per Pound	$ per Square Foot	$
TAILBOOM					
Graphite	34.1		26.00		887
Kevlar	27.4		9.00		245
Resin	61.0		1.20		73
Honeycomb	13.0		150.00		1950
Film Adhesive		105		1.30	137
Miscellaneous Process Materials					150
25% Allowance for Scrap, Turnaround, etc.					861
				TOTAL	$4303
STABILATOR					
Graphite	11.3		26.00		294
Kevlar	7.0		9.00		63
Resin	18.0		1.20		22
Urethane	3.8		15.00		57
Film Adhesive		15.0		1.30	20
Miscellaneous Process Materials					100
25% Allowance for Scrap, Turnaround, etc.					139
				TOTAL	$ 695
VERTICAL TAIL					
Graphite	16.0		26.00		416
Resin	16.0		1.20		19
Honeycomb	3.0		150.00		450
Film Adhesive		40		1.30	52
Miscellaneous Process Materials					100
25% Allowance for Scrap, Turnaround, etc.					259
				TOTAL	$1296
				GRAND TOTAL	$6294

TABLE 21. COMPONENTS OTHER THAN STRUCTURAL COMPOSITES (SECOND QUARTER 1981 DOLLARS)

Tailboom

One Sta 547 Frame	Based on $3800 Phase II frame + 40 percent inflation + added complexity and HHI material + machining estimate)	$ 5,700
Two Sta 532 Fittings	Based on size and complexity relative to 547 frame	700
Four Intercostal Clips	Based on size and complexity relative to 547 frame	400
One Jack Fitting	Based on $700 Phase II titanium fitting redesigned into stainless steel	400
One Set of Tail Rotor Shaft Supports	Phase II quote + 40 percent inflation	1,400
One Set of Maintenance Steps	HHI estimate	600
Miscellaneous Hardware, Fasteners, etc.	HHI estimate	1,200
	TOTAL	$10,400

Stabilator

Two Stabilizer Hinge Fittings	Based on size and complexity relative to 547 frame	$ 1,000
Six Bathtub Fittings	Based on size and complexity relative to 547 frame	900
Two Actuator Fittings	Based on size and complexity relative to 547 frame	300
Miscellaneous Hardware, Fasteners, etc.		200
	TOTAL	$ 2,400

Vertical Tail

Four Fin Attach Fittings	Based on size and complexity relative to 547 frame	$ 3,200
Nine Gearbox Attach Fittings	Based on size and complexity relative to 547 frame	2,000
Leading Edge, Trailing Edge, and Tip Fairings	Phase II quote	5,000
Four Maintenance Steps	HHI estimate	300
Miscellaneous Hardware, Fasteners, etc.	HHI estimate	800
	TOTAL	$11,300
	GRAND TOTAL	$22,800

A burdened labor rate of $35 per hour is assumed for composites fabrication and final assembly.

The DTUPC for the CTS is calculated in Table 22 and is summarized in Table 23. At the time that the CTS program was terminated, the AH-64A DTUPC for the comparable metal components was quoted by Teledyne Ryan Aeronautical (the AH-64A airframe subcontractor) as shown in Table 23. (Both composite and metal DTUPC's are rounded to the nearest $500.)

TABLE 22.   DESIGN TO UNIT PRODUCTION COST
(SECOND QUARTER 1981 DOLLARS)

<u>Tailboom</u>

S/N-010   Labor Intensive + Support = 1-2/3* x 3105 = 5175 mm

Labor Non-Intensive + Support =

$$1-2/3* \times 2060 = 3433 \text{ mm}$$

Metal, etc. = $9100

Composites = $4303

S/N-001   Labor Intensive + Support =

$$\frac{5175}{60 \times 0.3286} = \quad 262 \text{ mh}$$

Labor Non-Intensive + Support =

$$\frac{3433}{60 \times 0.4636} = \frac{123}{385 \text{ mh}}$$

Metal, etc. $= \frac{\$10,400}{0.8193} = \$12,694$

Composite $= \frac{\$4303}{1.0000} = \$4,303$

*2/3 factor for nonproductive personnel time

144

TABLE 22. DESIGN TO UNIT PRODUCTION COST (CONT)
(SECOND QUARTER 1981 DOLLARS)

Tailboom (Cont)

Cumulative Avg for 536	Labor Intensive	=	262 x 0.1323 x \$35	=	\$ 1,213
	Labor Non-Intensive	=	123 x 0.2291 x \$35	=	986
	Metal	=	\$12,694 x 0.6281	=	7,973
	Composite	=	\$4,303 x 1.0000	=	4,303
				TOTAL	\$14,475

Stabilator

S/N-010   Labor Intensive + Support = 1-2/3* x 2520 = 4200 mm

Labor Non-Intensive + Support =

1-2/3* x 1875 = 3125 mm

Metal, etc. = \$2400

Composites = \$695

*2/3 factor for nonproductive personnel time

145

Stabilator (Cont)

S/N-001   Labor Intensive + Support =

$$\frac{4200}{60 \times 0.3286} = 213 \text{ mh}$$

Labor Non-Intensive + Support =

$$\frac{3125}{60 \times 0.4636} = \frac{112}{325 \text{ mh}}$$

$$\text{Metal, etc.} = \frac{\$2400}{0.8193} = \$2929$$

$$\text{Composite} = \frac{\$695}{1.0000} \approx \$695$$

Cumulative Avg for 536	Labor Intensive	= 213 x 0.1323 x \$35	=	\$ 986
	Labor Non-Intensive	= 112 x 0.2291 x \$35	=	898
	Metal	= \$2929 x 0.6281	=	1,840
	Composite	= \$695 x 1.0000	=	695
			TOTAL	\$ 4,419

TABLE 22. DESIGN TO UNIT PRODUCTION COST (CONT)
(SECOND QUARTER 1981 DOLLARS)

<u>Vertical Tail</u>

S/N-010   Labor Intensive + Support = 1-2/3* x 1995 = 3325 mm

Labor Non-Intensive + Support =

$$1\text{-}2/3* \times 370 = 617 \text{ mm}$$

Metal, etc. = \$11,300

Composites = \$1296

S/N-001   Labor Intensive + Support =

$$\frac{3575}{60 \times 0.3286} = 168 \text{ mh}$$

Labor Non-Intensive + Support =

$$\frac{617}{60 \times 0.4636} = \frac{22}{190 \text{ mh}}$$

Metal, etc. $= \dfrac{\$11,300}{0.8193} = \$13,792$

Composite $= \dfrac{\$1296}{1.0000} = \$1296$

---

*2/3 factor for nonproductive personnel time

147

Vertical Tail (Cont)

Cumulative Avg for 536	Labor Intensive	=	168 x 0.1323 x $35	=	$	778
	Labor Non-Intensive	=	22 x 0.2291 x $35	=		176
	Metal	=	$13,792 x 0.6281	=		8,663
	Composite	=	$1296 x 1.0000	=		1,296
				TOTAL		$10,913

TABLE 23. DTUPC SUMMARY
(SECOND QUARTER
1981 DOLLARS)

Component	Metal	Composite	Saving
Tailboom	28,000	14,500	13,500
Stabilator	13,500	4,500	9,000
Vertical Tail	32,000	11,000	21,000
Airframe Modification to Accommodate CTS	-	2,500	<2,500>
	73,500	32,500	41,000

LABORATORY AND FLIGHT TEST PLANS

The CTS program did not progress far enough to conduct any structural testing. The plan was to conduct static, dynamic, fatigue, ballistic, and local impact tests to a level that would demonstrate safety of flight for a 25-hour flight test to be conducted under the MM&T program. When this was demonstrated to be successful, full airworthiness qualification in the laboratory and in flight would have been conducted.

LABORATORY TESTS

The CTS laboratory test article consists of the main structural elements of the CTS assembly including the tailboom, vertical tail spar, and stabilator. Fairings, etc., that have no influence on strength and/or stiffness are deleted from the test article.

Criteria for the laboratory tests include:

Static
: The factor of safety is 1.5 for all conditions, with negligible permanent set at limit load, and no failure at ultimate load. The minimum margin of safety for all flight and ground loading conditions is zero for all structures, but in such cases where the analytical margin of safety is less than zero, a positive margin is to be demonstrated by static test.

Dynamic
: The natural frequency of the CTS when installed on the AH-64A fuselage is such that the modal separation from the excitation frequencies is better than or equal to that of the metal tailboom and empennage to reduce CTS loads and vibration.

Fatigue
: The CTS is designed to require no major overhaul in less than 4500 flight hours. Prior to determination of oscillatory load levels from flight strain surveys, weighted fatigue level of 10 percent of limit load for the tailboom and 30 percent for the stabilator and vertical tail is used for design purposes. The distribution of maneuver load cycles used in the fatigue analysis calculations is derived from the flight profile shown in Table 24.

| Ballistic | The CTS ballistic survivability test consists of impacting the structure with a 23mm HEI-T projectile while the CTS is under load, and then applying static loading to destruction. |
| Impact | After static test failure, a local impact test that simulates anticipated service abuse will be conducted on the tailboom and stabilator. Type, location, and extent of damage will be recorded. |

The test article shown in Figure 86 is mounted at Station 370 on a steel fixture. Straps, loading frames, or whiffletrees are attached to the CTS for introducing loads. Hydraulic loading jacks apply the test loads between the airframe attachments and the support framework. The tare weight of the attachments, linkages, and dummy fixtures is counterbalanced by hydraulic compensation in the loading system as well as by counterweights, pulleys, and cable.

Instrumentation includes strain and rosette gages mounted as shown in Figures 87 through 92. The same gages and locations are used in the laboratory test and in flight. Prior to test and at specified times during the tests, all gages are calibrated against standards.

Predicted loading conditions are established based on AH-64A flight tests, and *modes of failure are predicted for comparison with actual test results.*

FLIGHT TESTS

Limited flight tests are conducted on the load survey air vehicle for a total of 25 hours and to a level of 80 percent of the AH-64A flight envelope. Flight conditions are summarized in Table 24.

MOUNTING FRAME

TAILBOOM
(P/N 7-311114710)

VERTICAL TAIL
(P/N 7-311122700)

STABILATOR
(P/N 7-311123700)

Figure 86. Schematic Static/Fatigue Test Setup

151

Figure 87. Strain Gage Installation FS 375

$$\begin{pmatrix} \varepsilon_1 \approx 0046 \\ \varepsilon_2 \approx 0047 \\ \varepsilon_3 \approx 0048 \end{pmatrix}$$

$$\begin{pmatrix} \varepsilon_1 \approx 0049 \\ \varepsilon_2 \approx 0050 \\ \varepsilon_3 \approx 0051 \end{pmatrix}$$

3148   3149   3150

0046
BBR   3159

3161   3160

20°

3153

3152

BBR
0049   15°

3154   VIEW FS 456.0
LOOKING FORWARD

3163   3162

FS 456.0

3149
3150 RH
3151 LH
3152 RH
3153 LH   WL 129.20

3154

FS 450

3159
ε_2
ε_3 BBR 0046
3160 RH
3161 LH

FS 539.0

FS
547.15

Figure 88.   Strain Gage Installation - Tail Boom FS 539

153

BRR0052

$\epsilon_1 = 0.0052$

$\epsilon_2 = 0.0053$

$\epsilon_3 = 0.0054$

WL 129.2

Figure 89. Strain Gage Installation - Vertical Stabilizer
Fitting FS 530. 09

154

NOTE:
$\varepsilon_1 \approx 0055$
$\varepsilon_2 \approx 0056$
$\varepsilon_3 \approx 0057$
LOCATET LOCATED AT
WL 138.0 BL 2.0 LH

FRAME, REAR
P/N 7-311114714

LOOKING FORWARD

VIEW B-B

VIEW C-C

Figure 90. Strain Gage Installation - Rear Frame FS 547

155

Figure 91. Strain Gage Installation - Vertical Stabilizer Spar

FS 559
FS 553.07
FS 546
FS 573

₵ AIRCRAFT

BBR $\frac{0022}{(0025)}$

3300 LOWER
(3301) UPPER

$\frac{3302}{(3303)}$

(BBR (0028)

ϵ_3 ϵ_3 ϵ_3

Y_S 20

ϵ_1 ϵ_2 ϵ_1 ϵ_2 ϵ_1 ϵ_2

BBR 0034

BBR (0031)

Y_S 50

ϵ_3

ϵ_1 ϵ_2

LOOKING DOWN ON LEFT
HAND SIDE

INSTALL STRAIN GAGES ON
LEFT HAND SIDE ONLY

LBL 64.0

FIGURE 107. STRAIN GAGE INSTALLATION — STABILATOR SPAR 4 AXIAL STRAIN GAGE, SKIN 5 BBRs

BBR: TOP SKIN NO. 0022 AT Y_S 20

$\epsilon_1 \approx 0022$
$\epsilon_2 \approx 0023$
$\epsilon_3 \approx 0024$

BBR: TOP SKIN NO. 0034 AT Y_S 20

$\epsilon_1 \approx 0034$
$\epsilon_2 \approx 0035$
$\epsilon_3 \approx 0036$

3302, 6, 10

3300, 4, 8

3303, 7, 11

3301, 5, 9

BBR: BOTTOM SKIN
NO. 0028 AT Y_S 20

$\epsilon_1 \approx 0028$
$\epsilon_2 \approx 0029$
$\epsilon_3 \approx 0030$

BBR: BOTTOM SKIN NO. 0025 AT
Y_S 20 AND NO. 0031 AT Y_S 50

$\epsilon_1 \approx 0025$ $\epsilon_1 \approx 0031$
$\epsilon_2 \approx 0026$ $\epsilon_2 \approx 0032$
$\epsilon_3 \approx 0027$ $\epsilon_3 \approx 0033$

Figure 92. Strain Gage Installation - Stabilator Spar

157

TABLE 24. FLIGHT PROFILE

Speed Spectrum		Maneuver Spectrum		
Speed	Speed Envelope % Life	Peak Nz at cg	Time at g (sec)	Cumulative Exceedances per 4500 hours
Hover	23.0	3.00	0.8	200
(HOGE)		2.75	1.2	500
0.5 V_H	3.0	2.50	1.7	1,000
0.6 V_H	6.0	2.25	2.8	2,000
0.7 V_H	15.0	2.00	4.0	5,000
0.8 V_H	15.0	1.75	6.0	10,000
0.9 V_H	15.0	1.50	10.0	20,000
1.0 V_H	10.0	1.25	12.0	150,000
1.2 V_H	3.0			
Sideward Flight	7.0	0.75	4.2	60,000
Rearward Flight		0.50	2.8	8,000
Vertical Flight		0.25	2.5	1,000
Ground	3.0	0	2.0	200
Total	100.0			

NOTES:

1. 60 percent of maneuvers shall be unsymmetrical maneuvers.
   40 percent of maneuvers shall be symmetrical maneuvers.

2. Climb and descent time shall be distributed as follows:
   5 percent of level flight/moderate maneuvering time in ascending mode.
   8 percent of level flight/moderate maneuvering time in descending mode.

3. Gross weight shall be distributed as follows:
   40 percent of life at basic structural design gross weight.
   40 percent of life at basic structural design gross weight minus payload and 50 percent fuel.
   20 percent of life at maximum alternate gross weight.

4. The average time per maneuver considering all types of maneuvers shall be in accordance with the time at g column.

5. Life shall be divided approximately as follows:
   70 percent level flight with moderate maneuvering (0.75-1.25 g).
   20 percent pull up and turn maneuvers.
   10 percent other maneuvers (control reversals, auto rotation, accelerations/decelerations).

6. Firing loads shall be additive to the above profile. Assume 810 firing anti-armor missions with 55 percent of mission ordnance (MO) expended during HOGE. Assume 875 firing escort or covering missions with 20 percent of MO expended during HOGE. Distribution of remaining MO should be in accordance with the forward flight spectrum.

7. The altitude spectrum shall be:
   80 percent at sea level-STD (representing low altitude flight).
   20 percent at 4000 ft 95°F (representing high altitude flight).

8. GAG cycles: Three engine start/stop cycles per flight hour.

IMPLICATIONS FOR PRODUCTION

The CTS is designed to be a lightweight, low cost, integrated replacement
for the AH-64A's metal tail section. As designed, it is attached to the
forward fuselage structure at Sta 370 by a double row of HiLok fasteners and
requires a modification of the metal airframe at this point. The joint thus
formed imposes a small penalty that is well worth accepting in light of the
overall benefits of the CTS that are a 71 pound weight saving (including a
7.6 pound weight penalty for the joint) and a $41,000 production cost saving
(including a $2,500 cost penalty for the joint).

This is the most efficient CTS that can be used, but just before the design
work was terminated, a plan was proposed to change to a "mix-and-match"
configuration. In this arrangement, any or all of the three composite
components could be used interchangeably with the AH-64A metal compo-
nents. This work was not pursued beyond a preliminary estimate of the
design work required and the potential impacts of such a configuration. The
unique, integrated design of the CTS that came out of the program is the
most effective configuration from a cost and weight standpoint, while the
"mix-and-match" design would be easier to introduce into the AAH produc-
tion line. Table 25 describes the CTS changes needed to accomplish
"mix-and-match." Figures 93 and 94 compare the CTS as designed with the
two most probable "mix-and-match" arrangements:

- Metal tailboom with composite stabilator and vertical tail

- Composite tailboom, stabilator, and vertical tail

with the basic metal configuration in terms of weight and cost. In
addition to weighing more and costing more, the "mix-and-match" design
would have the following consequences:

- Reduced vertical tail incidence increases CFTR flapping and
  potentially reduces its fatigue life

- Reduced stabilator hinge space increases hinge loads and
  reduces hinge life

159

TABLE 25. CTS DESIGN CHANGES TO ACHIEVE "MIX-AND-MATCH"

Vertical Tail

- Reduce incidence to match metal vertical tail

- Locate stabilator hinge fittings on vertical tail spar instead of on tailboom aft bulkhead

- Change root fittings and bolt pattern for attachment to tailboom

Stabilator

- Modify hinge fittings to match fittings on vertical tail spar

- Modify spar/rib structure to accommodate new hinge fitting location

Tailboom

- Change tailboom aft structure and bolt pattern for attaching vertical tail

Figure 93. Tail Section Weight Comparison

161

Figure 94. Unit Production Cost Comparison 536 Shipsets -
Second Quarter 1981 Dollars

CONCLUSIONS

This MM&T program demonstrated how advanced composites technology can be applied to the tail section of the AH-64A helicopter to realize important performance, weight, and cost benefits. Methods that HHI has established are directly applicable to the CTS with the manufacturing refinement segment of the program having shown the way to build this particular configuration.

The CTS structural design is complete, and the tooling design is nearly so. It is recommended that the fabrication and test activities be reinstated in a timely manner so that the CTS can be qualified for installation on the production AH-64A. For maximum savings, the complete CTS offers:

- 71 pounds weight saving
- $41,000 DTUPC saving (1981 dollars)
- 269 parts count saving
- 9047 fastener count saving
- $1.1 million fuel saving over the life of the fleet
- $22 million overall production and life cycle cost saving for the fleet
- 55 fpm vertical rate of climb increase
- Improved reliability and maintainability

As an alternative to funding the entire CTS, a program limited to only the composite stabilator can offer:

- 19 pounds weight saving
- $9000 DTUPC saving (1981 dollars)
- 11 parts count saving
- 41 fastener count saving
- $300,000 fuel saving over the life of the fleet
- $5.9 million overall production and life cycle cost saving for the fleet
- 15 fpm vertical rate of climb increase
- Improved reliability and maintainability

163

REFERENCES

1. Needham, J.F., USAAMRDL TR-76-24: Design, Fabrication, and Testing of an Advanced Composite AH-1G Tail Section (Tailboom/Vertical Fin), February 1976.

2. Head, R.E., USAAMRDL TR-77-19: Flight Test of a Composite Multi-Tubular Spar Main Rotor Blade on the AH-1G Helicopter, August 1977.

3. Goodall, R.E., USAAMRDL TR-77-27: Advanced Technology Helicopter Landing Gear, October 1977.

4. Anon, Design Criteria Report for the YAH-64 Advanced Attack Helicopter, Phase 2 Hughes Helicopters, Inc. Report HH 78-174, revised 15 February 1980.

5. MIL-S8698 (ASG) Military Specification Structural Design Requirements, Helicopters, 28 February 1958.

CTS ASSEMBLY AND SUBASSEMBLY DRAWINGS

Figure	Title	Drawing Number
95	Tailboom Assembly	7-311114700, Sheet 1
	Tailboom Assembly	Sheet 2
	Tailboom Assembly	Sheet 3
96	Tailboom Subassembly	7-311114710, Sheet 1
	Tailboom Subassembly	Sheet 2
	Tailboom Subassembly	Sheet 3
	Tailboom Subassembly	Sheet 4
97	Vertical Tail Assembly	7-311122700, Sheet 1
98	Vertical Tail Subassembly	7-311122710, Sheet 1
	Vertical Tail Subassembly	Sheet 2
99	Stabilator Assembly	7-311123710, Sheet 1
	Stabilator Assembly	Sheet 2

VIEW M-M
FULL SIZE

FASTENER 'Y'

INTERSECTION OF
FAIRING LOFT LINE
& FUS LOFT LINE

.50 TYP FOR STA 450.00
THRU STA 491.70
.87 FOR STA 502.02

FASTENER 'X'

INTERSECTION OF
FAIRING LOFT LINE
& FUS LOFT LINE

.1900-.1940 (±.0005) DIA HOLE 56 PL
HL48-6-5 PIN 56 REQD
HL 75G-6AGW COLLAR 56 REQD

FOR FASTENER
CALLOUT & LOCATION
SEE ABOVE

FASTENER 'X'

FASTENER 'Y'

M

M

W L HL 95.6 & HINGE

7-3111471 REF

7-31114710 REF

7-311114714 REF

44 EQ SP

SECTION A-A
LOOKING AFT

7-311114716-9 ANGLE

HS4430-1 REF

7-311114716-13 ANGLE

HS4430-1 REF

7-311114710 REF

BL 0.000

ON OF
LINE
LINE

TYP FOR STA 450.00
THRU STA 491.70
FOR STA 502.02

.32

STA REF

HS4430-1 RECEPTACLE

BARRIER
SEE DETAIL
1 PLY 0°/90° FABRIC
Ø.50 DIA THRU CENTER
BEFORE APPLYING RECEPTACLE

.60

BL 0.000

1.04 TYP FOR STA 508.204
.79 TYP FOR STA 512.13 &
-BOTH SIDES

7-311114710 REF

INTERSECTION OF
FAIRING LOFT LINE
FUS LOFT LINE

FAIRING LOFT LINE

HINGE -2 REQD

7-311114716-7 ANGLE

VIEW E-E
SCALE 1/1
10 PL ALONG 7-311114716-9 & -13
4 PL ALONG 7-311114716-11
7 PL ALONG 7-311114716-3

E   E

SECTION B-B

HEEL LINE

7-311114716-11 ANGLE

SECTION C-C

STA 472.39

STA 460.000

STA 461.60

STA 475.000

STA 473.60

7-311114720 REF

C

7-311114720 REF

7-311114716-7 REF

STA 480.10

STA 490.000

STA 494.70

STA 495.60

STA 505.000

STA 501.480

STA 505.000

STA 500.15

.14 TYP

.70

.12

-13 REF

WL 140.25
& HINGE

C

8.50

8.50

8.50

8.50

5.00

5.00

5.00

4.00

VIEW LOOKING INBD
LH SIDE BSC ASSY

7-3

1.20

.65

DETAIL -15
SCALE 1/1

-311114716-13 ANGLE

REF

7-311114710 REF

BL 0.000

TYP FOR STA 508.20+.14 & STA 529.00+.14
TYP FOR STA 512.13 & STA 520.98
BOTH SIDES

-311114716-11 ANGLE

STA 536.00

2.500 (+.0050) DIA HOLE 6 PL
2.590 (+.0005)
HL48-8-8 PIN 6 REQD
HL75G BAGW COLLAR 6 REQD

7-311114726 REF

7-311114714 REF

BL 0.000

.75

.75

.75

.3200 (+.0050) DIA HOLE 2 PL
.2640 (+.0005)
HL48-8-6 PIN 2 REQD
HL75G BAGW COLLAR
.2 REQD

.375 3 EQ SP

FOR LOCATION & FASTENER CALLOUT SEE VIEW M-M

NAS1303-14 PIN 4 REQD
MS21042-3 NUT 4 REQD
AN 960C10 WASHER 4 REQD

NAS1303-8 PIN 4 REQD
MS21042-3 NUT 4 REQD
AN 960C10 WASHER 4 REQD

STA 520.000

B

7-311114716-11 REF

G
.204 DIA THRU
.196
C'SK .386 DIA X
100°, THIS SIDE
ONLY

STA 529.000

STA 532.13

STA 536.000

WL 180.23
HINGE

A

H

7-311114726 REF

7-311114720
UPPER STEP

7-311114718 REF

FASTENERS OMITTED FOR
CLARITY FOR LOCATION &
FASTENER CALLOUT SEE
SECTION A-A

LB 6.080

B

8.90

.62

2.70

2.55

.375 3 EQ SP
2 PL

.75 2 PL

H

7-311114727 REF

7-311114718 REF

7-311114721
LOWER STEP

.19

7-311114710 SUB ASSY

A

NAS1303-5 PIN 4 REQD
MS21042-3 NUT 4 REQD
AN 960C10 WASHER

NAS1303-8 PIN 4 REQD
MS21042-3 NUT 4 REQD
AN 960C10 WASHER 4 REQD

HS444-06-16
HS439-624
MS21206-6
7-311114723 FITTING

HL48-8-7 PIN 4 REQD
HL75G BAGW COLLAR 4 REQD
.2500 (+.0050) DIA HOLE 4 PL
.2590 (+.0005)

.75

.75

.75

.150

.75

.85R
2 PL

1.10

FULL

DETAIL -9
SCALE 1/1

Figure 95. Tailboom Assembly (Sheet 1 of 3)

Left side notes:

HS4441-06-10 BOLT
HS4139-604 NUT
MS21206-6 WASHER

PBL
3.480
REF

WL
129.200

.75

.2540 +.0050 DIA. HOLE 4 PL
.3800 +.0005
HL48-8-7 PIN 4 REQD
HL75G-8AGW COLLAR 4 REQD

.75

HS4441-06-10 BOLT
HS4139-604 NUT
MS21206-6 WASHER

.2540 +.0050 DIA. HOLE 4 PL
.2500 +.0005
HL48-8-7 PIN 4 REQD
HL75G-8AGW COLLAR 4 REQD

7-311114714 FRAME

PER EPB 4-230.
PASTE ADHESIVE CL 1.
MARK MIL-C-9084, TYPE VIII.
MS 2.(.010/PLY)
ADHESIVE BOND PER HP16-30
6-... FILM ADHESIVE CL 6
...NG & TOLERANCING PER ANSI Y14.5
...THREADED FASTENERS PER HP6-3
...LOK FASTENERS PER HP 3-2
...HERWISE SPECIFIED

QTY REQD		PART NO	NAME	SIZE	DESCRIPTION	SPECIFICATION	ZONE
21		HS4430-1	RECEPTACLE				6F
6		MS4447-1032	NUT				2B
6		MS21206-6	WASHER				
16		MS21042-3	NUT				
2		MS21044N3	NUT				5B
6		HS4139-624	NUT				3F
6		HS4441-06-10	BOLT				3F
39		AN960C10	WASHER				25B
2		NAS1635-3-4	SCREW				
4		NAS1303-14	BOLT				
8		NAS1303-8	BOLT				
4		NAS1303-5	BOLT				
16		NAS1503P3E7	SCREW				
6		HL48-8-6	PIN				
12		HL48-8-7	PIN				
2		HL48-8-6	PIN				
36		HL48-8-5	PIN				
3		HL48-6-7	PIN				
56		HL48-6-5	PIN				
56		HL75G-8AGW	COLLAR				
59		HL75G-6AGW	COLLAR				
1		7-311114740	FITTING				3E
1		7-311114739	FITTING				1H
1		7-311114735	INTERCOSTAL				3D
1		7-311114734	BRACKET ASSY				2D
1		7-311114733	BRACKET				2D
1		7-311114731	BRACKET				2D
2		7-311114729	BRACKET				7B
1		7-311114723	FITTING				3B
1		7-311114721	LOWER STEP				4C
1		7-311114720	UPPER STEP				4E
1		7-311114716-13	FAIRING ANGLE				4H
1		7-311114716-11	FAIRING ANGLE				6F
1		7-311114716-9	FAIRING ANGLE				8H
1		7-311114716-7	FAIRING ANGLE				8C
1		7-311114716-5	FAIRING ANGLE				6F
1		7-311114716-3	FAIRING ANGLE				3F
1		7-311114714	REAR FRAME				3B
1		7-311114710-1	SUB ASSY				5B
2		-2	BARRIER	6			7E
1		-9	BARRIER	6			2D
1		-7	BARRIER	6			1E
2		-5	BARRIER	5			6F
2		-3	HINGE		MS20257-3-4300		6F
1		-11	HINGE		MS20257-3-4000		7F
2		-9	RAD 5 BLOCK	20.75x.20	2024-T3 ALANSI 20-A-250/4		3F
11		-7	BARRIER	5			6A
44		-3	BARRIER	5			6G

7-311114716-5 ANGLE [4]

FAIRING LOFT LINE-REF
7-311114729 REF
-13 REF

7-311114716-3 ANGLE [4]

.67 TYP FOR STA 370.00+1.50
THRU STA 450.00-1.720
.87 FOR STA 450.00-1.73

WL 147.20 & HINGE

H54430-1
RECEPTACLE
-REF

4.25
11 PL

7-311114729 REF
(ELECTRICAL)

HEEL LINE

7-311114729 REF (ELECTRICAL)

7-311114729 BRACKET ASSY [4] (HYDRAULIC)
66 REQD

7-311114710 REF

7-311114729 REF (ELECTRICAL)

7-311114729 REF (ELECTRICAL)

SECTION D-D [X]

STA 570.000

11.50

.14

-11 HINGE -2 REQD

HINGE

DX

D

-3 BARRIER 4A REQD
SEE DETAIL 28
1 PLY 0/90° FABRIC 6

STA 585.000   STA 587.662

STA 600.000

STA 615.000

68.40

56.40

44.40

32.40
38.80 REF

REF (ELECTRICAL)

8.30

8.30

8.30

10.00

9.00

7.00

8.50

11.50

2.64

BY 4 (HYDRAULICS)

D

7-31114722 REF

-7 BARRIER 11 REQD
SEE DETAIL 8
1 PLY 0/90° FABRIC 6

3.30

.90

DETAIL -3

STA 430.000

STA 445.000

STA 452.000

7-311114729 RMF

1.37

22.40
38.80 FWD-H

17.28

WL 142.93 C HINGE

.11 REF

.60

HB4430-1 RECEPTACLE(7REQD)ON-15BARR.ER(7 REQD)
-SEE VIEW E-E (7 PL ALONG 7-3111471G-3)

FSLG & FAIRING INTERSECTION

1.18

1.73

8.90

8.90

5.00

5.00

7.80

CONTINUED
ON SHT 1

5.40

.90

DETAIL -7

3.50

DETAIL -3

142.93 C HINGE

HB4630-I RECEPTACLE (7 REQD) ON IS BARRIER (7 REQD)
SEE VIEW E-E (7 PL ALONG 7-31T11471G-3)
& FAIRING INTERSECTION

TINUED
SHT I

Figure 95. Tailboom Assembly (Sheet 2 of 3)

SECTION J-J
LOOKING FWD

BL
0.000

-C-

BBL
6.520
BF

LBL
6.080
BF

.5625 DIA HOLE 2 PL

-B-

⊕ ⌀ .0028 Ⓜ A C Ⓢ D Ⓢ
.005 Ⓜ

6.520

6.080

.13 APPROX
AFTER ASSY
-4 PL

WL
140.280

.13 APPROX
AFTER ASSY
-4 PL

7-311114739
FITTING

7-311114740
FITTING

5.00

5.50

2540 +.0050 DIA HOLE 36 PL
2500 +.0005
HL48-B-5 PIN -36 REQD
HL75 G-BAGW COLLAR -36 REQD

WL
129.200

7-311114738 FRAME ASSY (REF)

7-311114710-1 SUB-ASSY (REF)

STA 532.SP

STA 547.150

WL. 125.200

1.100 REF

A

2.200 REF

D

.81

7-311114714
FRAME

.70

HL48-6-7 PIN - 3 REQD
HL75G-6AGW COLLAR - 3 REQD

7-311114735-7 SHIM

7-311114736
CLIP

7-311114736
INTERCOSTAL

7-311114738 FRAME (REF)

7-311114723 FITTING ASSY

NAS1190P3E7 SCREW-16 REQD
AN960C10L WASHER-16 REQD
MS4447-1032 NUT-16 REQD
TORQUE 40 LB IN

SECTION L-L

UP

.19 H .96 DIA 2 PL THRU PLOT HOLES
NAS1635-3-4 SCREW 2 REQD
MS21044N3 NUT 2 REQD
AN960C10 WASHER 2 REQD

7-311114733 BRACKET

-3

7-31114731
BRACKET

-21 BARRIER   2 PL
SEE DETAIL
1 PLY 0°/90° FABRIC

(FWD)

STA
27.00

1.25

7-31114731
BRACKET

-21 BARRIER

LBL
4.18

-21 BARRIER

SL
0.00

7-31114710 REF

SECTION G-G
SCALE 1/1
LOOKING AFT

BL
0.00

WL
129.200

HOLES
REQD
REQD

114733 BRACKET

7-31114714 FRAME

2.38

SECTION H-H
LOOKING AFT

1.64

1.00

DETAIL -21
SCALE 1/1

D

3111473!
BRACKET

21 BARRIER 2 PL
SEE DETAIL
1 PLY 0/90° FABRIC

STA
42.00

7-311114731
BRACKET
-21 BARRIER

LBL
4.187

BL
0.00

7-311114710 REF

SECTION G-G
SCALE 1/1
LOOKING AFT

VIEW K-K

7-3111478
INTERCOSTAL

7-311114725-2
CLIP

BARRIER
SEE DETAIL 1 PLY 0/90 FABRIC

7-311114734
BRACKET ASSY

7-311114734
BRACKET ASSY

STA
57.28

STA
52.78

BARRIER
SEE DETAIL
1 PLY 0/90 FABRIC

3.67

7-311114714
FRAME

WL
129.200

K

K

7-311114725-2
CLIP

7-311114719
INTERCOSTAL

7-311114727-2
CLIP

SECTION F-F

B.50

113 FOR -17
1.26 FOR -19

DETAIL -17 & -19
SCALE 1/1

-3

02731 J

Figure 95. Tailboom Assem

171

L 1

VIEW K-K

SECTION F-F

Figure 95. Tailboom Assembly (Sheet 3 of 3)

171

LINE DIAGRAM II
FOR -29 & -33 DOUBLER
AT STA 496.28, 501.70 & 521.00
SCALE: NONE

-29P1
-29P2
-29P3
-3 REF
-3 REF
2 EQ SP
5.00 DIA
4.00 DIA
-5 REF
-7 REF
-5 REF
-7 REF
-33P1
-33P2
-33P3

-SP5
-3P4
-3P3
-SP2

1.80
3 EQ SP

STA 529.000

-3P1

LINE DIAGRAM I
-3 OUTER SKIN JOINT
@ STA 529.000
NO SCALE

STA 525.000
STA 529.000
STA 490.00

1.00
3 EQ SP
1.00
.50
.25

-SP8
-SP7
-SP6
-SP5

-SP4
-SP3
-SP2
-SP1

LINE DIAGRAM III
-5 INNER SKIN JOINT
@ STA 529.000
NO SCALE

-59 REF

CONTINUED
ON SHT 2

PLY NO	ORIENT	MATL		PLY THK
P3	±45°	6	8	.017
P2	0/90°	6	8	.017
P1	0/90°	6	8	.017

STACKING SEQUENCE
FOR -29 DOUBLER
AT STA 496.28, 501.70 & 521.00
TABLE 4

PLY NO	ORIENT	MATL		PLY THK
P3	0/90°	6	8	.017
P2	0/90°	6	8	.017
P1	±45°	6	8	.017

STACKING SEQUENCE
FOR -33 DOUBLER
AT STA 496.28, 501.70 & 521.00
TABLE 3

PLY NO	ORIENT	MATL		PLY THK
P5	90°	6	8	.010
P4	±45°	6	7	.017
P3	±5°	8		.020
P2	±45°	6	7	.017
P1	±45°	6	8	.017

STACKING SEQUENCE
FOR -3 OUTER SKIN
AT STA 375.00
TABLE 1

PLY NO	ORIENT	MATL		PLY THK
P10	90°	8	6	.010
P9	±45°	6	7	.017
P8	0/90°	6		.017
P7	0/90°	6		.017
P6	±45°	6		.017
P5	±45°	6		.017
P4	0/90°	6		.017
P3	±8°	8		.020
P2	±45°	6		.017
P1	90°	8	6	.010

STACKING SEQUENCE
FOR -5 INNER SKIN
AT STA 570.00
TABLE 2

.198-.204 DIA THRU 8 PL
TO MATCH 7-211380014

-33 BARRIER

STA
472.388

VIEW AA-AA
(FULL SIZE)

BL
0.000

-47 REF

BL
0.000

1.80

5.10

4.00

STA
472.388

STA
471.00

-35 REF

-47 BARRIER

P

1.80

-56 REF

STA
476.280

STA
70.70

R

K

J

-7 REF

-3 REF

DOUBLER
FOR PLY
4 DROP OFF
DIAGRAM

482

-33 REF

.052
CONST

2.002 REF

2.738

-29 REF

BL
0.08

-3 REF

-7 REF

-5 REF

SECTION U-U

RIBBON

CONTINUED
ON SHT 2

P

K

J

R

VIEW LOOKING INBD
BSC ASSY

A

SECTION U-U

KING INBD

3

DETAIL B
SCALE: 1/1

NOTES UNLESS OTHERWISE SPECIFIED

SEAL FASTENERS PER HP 8-10 TYPE IV

HYGRID · 55 LB. DENSITY ALUMINUM MATERIAL.
AMERICAN CYANAMID CO., BLOOMINGDALE PLANT,
HAVRE DE GRACE, MD. 21078

50% VOLUME GRAPHITE ROVING &
50% VOLUME KEVLAR ROVING (.020 TOTAL PLY THK)

50% VOLUME GRAPHITE ROVING &
50% VOLUME KEVLAR ROVING (.010/PLY)

HMS 16-1068 PASTE ADHESIVE CL 3. APPLY PER HP 165

HMS 16-1111 FILM ADHESIVE, CL 3.

MILLED GLASS FIBERS/EPOXY 1/32 LENGTH
THALCO, LA

FINISH EXTERIOR ONLY
CODE E PER EPB 4-290

K. IDENTIFY PER HP8-5 TYPE I, CL 3 LOC OPT

13. DIMENSIONING & TOLERANCING
PER ANSI Y14.5

FOAM ADHESIVE PER
HMS 16-1111, CL 4

E-GLASS FABRIC
MIL-C-9084 TYPE VIII, A CL 2 (.010/PLY)

12. LAYUP PER HP 15-42

CORE (NOMEX)
HMS 16-1114 TYPE V, CL 1

10 INSTALL HI-LOK FASTENERS PER HP 3-2

9 FOR LOFT LINES SEE DWG 7-1L11131017OSTA520.00

EPOXY RESIN SYSTEM
HMS 16-1115
TYPE I, CL 1

E-GLASS, ROVING
MIL-R-60946
TYPE I. CL 1 (.010/PLY)

GRAPHITE FABRIC
HMS 16-1163 TYPE II, CL 1 GR A (.007/PLY)

GRAPHITE ROVING
HMS 16-1163 TYPE I, CL 1

KEVLAR ROVING
HMS 16-1164 TYPE I, CL 3

FILM ADHESIVE BOND PER HP 16-30

2. FILAMENT WIND PER HP 15-67

FIRST PLY GOES AGAINST TOOL FACE

				PART NO	NAME	QTY	
			1	-63	DOUBLER	AR	
			1	-61	DOUBLER	AR	
			1	-59	DOUBLER	AR	
			1	-57	DOUBLER	AR	
			18	HLT56-8AGN	COLLAR		
			18	HLT56-6AGN	COLLAR		
			18	HL48-8-7	PIN		
			18	HL48-6-5	PIN		
			AR	HMS 16-1111, CL 3	FILM ADHESIVE		
			4	SL601-3-3CM	INSERT		
			AR	HMS 1068, CL 3	PASTE ADHESIVE		
			2	7-311114737	INSERT		
			1	7-31114727-2	LOWER FITTING		
			1	7-311114727-1	LOWER FITTING		
			1	7-311114726	UPPER FITTING		
			1	7-311114725-2	LOWER CLIP		
			1	7-311114725-1	LOWER CLIP		
			1	7-311114242	UPPER CLIP		
			1	7-311114722	FRAME		
			1	7-311114721-2	LOWER INTERCOSTAL		
			1	7-311114719-1	LOWER INTERCOSTAL		
			1	7-311114718	UPPER INTERCOSTAL		
			2	7-311114736	SHEAR CLIP		
			1	7-311114735	INTERCOSTAL		
			1	7-311114738	FRAME ASSY		
			1	-55	INSERT		
			1	-53	DOUBLER		
			2	-51	DOUBLER		
			2	-49	DOUBLER		
			1	-47	BARRIER		
			1	-45	BARRIER		
			1	-43	BARRIER		
			1	-41	DOUBLER		
			1	-39	BARRIER		
			1	-37	BARRIER		
			1	-35	BARRIER		
			3	-33	DOUBLER		
			1	-31	DOUBLER		
			3	-29	DOUBLER		
2	-	-		-27	BARRIER	3/4 φ	
1	-	-		-25	PAD	3/4 φ	
			1	-23	BARRIER		
			21	-21	INSERT ASSY		
2	-			-19	BARRIER	1" φ	
1	-			-17	PAD	1" φ	
			8	-15	INSERT ASSY		
			4	-11	BARRIER		
			4	-9	BARRIER		
			1	-7	CORE	AR	
			1	-5	INNER SKIN	AR	
			1	-3	OUTER SKIN	AR	

LIST OF MATERIAL

7-311114700

02731   J

Figure 96.   Tailboom Subassembly (Sheet

FILL -7 CORE WITH [▨]
FOAM ADHESIVE
THIS AREA BEFORE
WINDING -3 OUTER SKIN

-15 CONST

-10 CONST

DETAIL B [▨]
SCALE: 1/1

MILLED GLASS
FIBERS/EPOXY [▨]

[▨] SEAL FASTENERS PER HP 8-10 TYPE IV
[▨] HYGRID · 5# LB. DENSITY ALUMINUM MATERIAL -
   AMERICAN GRAFHIL CO., BLOOMINGDALE PLANT,
   HAVRE DE GRACE, MD. 21078
[▨] 50% VOLUME GRAPHITE [▨] ROVING &
   50% VOLUME KEVLAR [▨] ROVING (.020 TOTAL PLY THK)
[▨] 50% VOLUME GRAPHITE [▨] ROVING &
   50% VOLUME KEVLAR [▨] ROVING (.010/PLY)
[▨] HMS 16-1068 PASTE ADHESIVE CL 3. APPLY PER HP16S
[▨] HMS 16-1111 FILM ADHESIVE, CL 3.
[▨] MILLED GLASS FIBERS/EPOXY 1/32 LENGTH
   THALCO, LA
[▨] FINISH EXTERIOR ONLY
   CODE E PER EPB 4-230
16. IDENTIFY PER HP8-5 TYPE I, CL 3 LOC OPT
15. DIMENSIONING & TOLERANCING
   PER ANSI Y14.5
[▨] FOAM ADHESIVE PER
   HMS 16-1111, CL 4
[▨] E-GLASS FABRIC
   MIL-C-9084 TYPE VIII, A CL 2 (.010/PLY)
R. LAYUP PER HP 15-42
[▨] CORE (NOMEX)
   HMS 16-1114 TYPE V, CL 1
10 INSTALL HI-LOK FASTENERS PER HP 3-2
9 FOR LOFT LINES SEE DWG 7-1L11131011OSTA52100
[▨] EPOXY RESIN SYSTEM
   HMS 16-1115
   TYPE I, CL 1
[▨] E-GLASS ROVING
   MIL-R-60946
   TYPE I, CL 1 (.010/PLY)
[▨] GRAPHITE FABRIC
   HMS 16-1165 TYPE II, CL 1 GR A (.007/PLY)
[▨] GRAPHITE ROVING
   HMS 16-1163 TYPE I, CL 1
[▨] KEVLAR ROVING
   HMS 16-1164 TYPE I, CL 3
[▨] FILM ADHESIVE BOND PER HP 16-30
2. FILAMENT WIND PER HP 15-6?
[▨] FIRST PLY GOES AGAINST TOOL FACE

ES UNLESS OTHERWISE SPECIFIED

QTY	PSC	PART NO.	DESCRIPTION				ZONE
1		-63	DOUBLER	AR			33F
1		-61	DOUBLER	AR			33C
1		-59	DOUBLER	AR			39E
1		-57	DOUBLER	AR			39E
18 722B		HL756-8AGN	COLLAR				4G
1B 722B		HL756-6AGN	COLLAR				4C
18 7221S		HLAB-8-7	PIN				4G
1B 72218		HLAB-6-5	PIN				4C
AR		HMS 16-1111, CL 3	FILM ADHESIVE				
4		SL601-3-3CM	INSERT				39A
AR		HMS 1068, CL 3	PASTE ADHESIVE				
2		7-311114737	INSERT				
1		7-31114727-2	LOWER FITTING				2BC
1		7-311114727-1	LOWER FITTING				4C
1		7-311114726	UPPER FITTING				4D
1		7-311114725-2	LOWER CLIP				2K
1		7-311114725-1	LOWER CLIP				2K
1		7-311114724-2	UPPER CLIP				4H
1		7-311114722	FRAME				4F
1		7-311114721P-2	LOWER INTERCOSTAL				2BC
1		7-311114719-1	LOWER INTERCOSTAL				4D
1		7-311114718	UPPER INTERCOSTAL				4D
2		7-311114736	SHEAR CLIP				2BC
1		7-311114735	INTERCOSTAL				2AC
1		7-311114738	FRAME ASSY				4A
1		-55	INSERT	2.2 GTS			39E
1		-53	DOUBLER				16E
2		-51	DOUBLER				13B
2		-49	DOUBLER				13E
1		-47	BARRIER				7F
1		-45	BARRIER				14F
1		-43	BARRIER				15F
1		-41	DOUBLER				14E
1		-39	BARRIER				16F
1		-37	BARRIER				14E
1		-35	BARRIER				7E
3		-33	DOUBLER				6F
1		-31	DOUBLER				14E
3		-29	DOUBLER				6F
2		-27	BARRIER	3/4 φ			24D
1		-25	PAD	3/4 φ			24D
1		-23	INSERT ASSY				35B
21		-21	INSERT ASSY				37F
2		-19	BARRIER	1 φ			28E
1		-17	PAD	1 φ			24C
8		-15	INSERT ASSY				22E
4		-13	BARRIER				24D
4		-9	BARRIER				24B
1		-7	CORE	AR			36
1		-5	INNER SKIN	AR			5F
1		-3	OUTER SKIN	AR			5E

LIST OF MATERIAL

7-311114700

02731 J

Hughes Helicopters

Figure 96. Tailboom Subassembly (Sheet 1 of 4)

173

STA 372.000
STA 370.00
STA 372.06
STA 375.86

.81
.56
.31

LINE DIAGRAM IV
-3 OUTER SKIN JOINT
@ STA 370.00
NO SCALE

-3P3
-3P2
-3P5
-3P4
-3P1

STA 372.000

-5P0
-5P9
-5P8
-5P7
-5P6

5.90
6.05
5.90
5.95
6.05
4.80
2.05
2.80
2.55
1.00
.30

-5P5
-5P4
-5P3
-5P2
-5P1

LINE DIAGRAM III
-5 INNER SKIN JOINT
@ STA 370.00
NO SCALE

-3 REF (FOR
NUMBERS
SEE LINE
& TABLE

STA 370.000
STA 372.06

5 PLIES
DB
REF
6.0
2.06 REF

11 PLIES
.172 REF
6 PLIES
.041
REF
2.71
5.86
MILLED

-5 REF (FOR
DASH NUMBER
DROP OFFS S
LINE DIAGRAM
& TABLE 2

-29 REF
-9 REF
-7 REF
-9 REF

7-311114787
REF

2.75R FOR
-29 & -33

2.00 R
REF -291 -33

1.74
1.44
.87

.082
.052

38 DOUBLER
FOR PLY NUMBERS
& DROP OFFS SEE LINE
DIAGRAM & TABLE

-5 REF
-7 REF

29 DOUBLER
FOR PLY DASH NUMBERS
& DROP OFFS SEE LINE
DIAGRAM & TABLE 4

VIEW N
SCALE 1/1

WL
129.200

BL
0.000

-9 REF
-7 REF
-9 REF

L

U

WL
129.200

WL
129.200

SECTION J-J

STA 496.280

.41

-3 REF

7-311114787 INSERT
POT INSERT IN CORE
2.25 DIA THRU WITH
FOAM ADHESIVE

-29 REF
-33 REF

WL 129.200 TRUE

VIEW L-L
SCALE 1/1

-3 REF (FOR PLY DASH
NUMBERS & DROP OFFS
SEE LINE DIAGRAM IV
& TABLE 1)

FILL -7 CORE WITH
FOAM ADHESIVE
THIS AREA BEFORE
WINDING -3 OUTER SKIN

.500 CONST

.45 CONST

STA
372.06

6.88

STA
375.86

-3 REF

2.06 REF

.10 CONST

2.71

5.86 REF

-7 REF

-5 REF

MILLED GLASS FIBERS/EPOXY

-5 REF (FOR PLY
DASH NUMBERS &
DROP OFFS SEE
LINE DIAGRAM III
& TABLE 2)

DETAIL A
SCALE: 1/1

BL
0.000

1.10

5.00

1.40

STA
970.000

T

STA
987.662

-3 REF

A

7-311114722 FRAME

STA
977.000

53 DOUBLER 1 PLY OF
0/90° FABRIC

WL
129.200

-45°

-8°
0°
+8°

WL
129.200

+45°

90°

T

EDP -31, -37, -41

BARRIER -57

7 REQD - INSERT (21)
SEE DETAIL

.198-.204 DIA THRU 7 PL
TO MARK 7-2H350012

5.200

EDP -31, -37,
-41

-45 REF

6.40
TYP

BL
0.000

3.680

1.10

5.50

1.574

2.00

1.450

1.000

2.000

.015

EDP -31, -37, -41

VIEW V-V
(FULL SIZE)

4.90

1.10

-43 REF

5.00

1.40

STA
371.00

BARRIER

M1114722 FRAME

BARRIER (18)

.120

3.90

BL
0.000

-37
REF

-3 REF

-7 REF

.9 REF

SECTION Q-Q

STA
480.145

37 BARRIER

STA
450.000

BARRIER (45)

STA
490.000

X

Q

Y

2.60

.60

Y

Q

41 DOUBLER 1 PLY OF
0°/90° FABRIC

DOUBLER 1 PLY OF
0° FABRIC

39 DOUBLER 1 PLY OF
0°/90° FABRIC

Q

X

3

SECTION X-X

DETAIL -49 & -51 (FULL SCALE)

Figure 96. Tailboom Subassembly (Sheet

-51 DOUBLERS

AM ADHESIVE

FILL-7 CORE WITH
FOAM ADHESIVE
THIS AREA BEFORE
WINDING -3 OUTER SKIN

DOUBLER: 1 PLY OF CARO FABRIC
SEE DETAIL
DOUBLER
1 PLY OF CARO FABRIC
SEE DETAIL

SPAR
CL

(7-51

22°30'

SECTION X-X

10.70 FOR -51
10.76 FOR -49

4.00

DETAIL -49 & -51 (FULL SCALE)

SEE SHEET 1

02731 J

Figure 96. Tailboom Subassembly (Sheet 3 of 4)

175

BL
0.000

-9 REF

-7 REF

-5 REF

-23 REF
ALSO SEE ZONE

7-31114737 BRACKET

L

2.89

.87

M

WL
129.000

7-3111478 B REF

7-311147 24 REF

-23 REF

3 REF
5 REF

BL
0.200

RBL
16.520

WL
129.200

7-3111478 FRAME ASSY

SECTION H-H

7-31114736 SHEAR CLIP 2 REQD
7-31114725-1 SHEAR CLIP
7-31114719-1 INTERCOSTAL
SECTION G-G

-9 REF
-5 REF
-7 REF

2.00 R
-29
REF

052

052

⊕ DOUBLER
FOR P/ DASH NUMBERS
& DROP OFFS SEE LINE
DIAGRAM Ⅶ & TABLE 3

⊕ DOUBLER
FOR P/ DASH NUMBERS
& DROP OFFS SEE LINE
DIAGRAM Ⅶ & TABLE 4

CLF
-5 REF

-7 31114738 FRAME ASSY

7-31114729-2 SHEAR CLIP

7-31114719-2 INTERCOSTAL

2 REQD

BL
0.000

7-314718 REF

9 REF

-5 REF

WL
29.800

2.22

-9 REF

8.08

-9 REF

RBL
7.000

LBL
7.000

-7-31114719-2 REF

7-31114735 REF

7-31114719-1 REF

SECTION E-E
SECTION F-F

70 TYP

SYMM
CL

A TYP

B TYP

DETAIL -29
SCALE 1/1

DIMENSION		
POINT	A	B
1	3.80	6
2	3.50	46
3	3.00	2.70
4	2.00	3.08
5	.00	3.44
6	Θ	3.66
7	1.00	3.44
8	2.00	3.08
9	3.00	2.32
10	3.50	.64
11	3.80	6

4.70

3.20

DETAIL -13   SHT 1
SCALE 1/1

MICROCOPY RESOLUTION TEST CHART

NATIONAL BUREAU OF STANDARDS 1963-A

.70 TYP

	DIMENSION	
	A	B
1	3.80	0
2	3.50	1.40
3	3.00	2.20
4	2.00	3.08
5	1.00	3.44
6	0	3.44
7	1.00	3.44
8	2.00	3.08
9	3.00	2.32
10	3.50	1.64
11	3.80	0

2.45

LOCATION -9 REF

-7 REF

2.00 TRUE

-5 REF NOT AS NOTED IN SECTION C-C, D-D TYP

SECTION V-V
TYP 2 PL
SIZE

-3 REF

REF

V ←   → V

-6 REF   .10

SECTION N-N

- 17 PAD
CELL LENGTH
DIRECTION

-19 BARRIER 2 PL [20]

-17 PAD

.500

-19 REF

1.00 DIA

DETAIL -15 INSERT
FULL SIZE

-27 BARRIER 2 PL

-25 PAD

25 PAD
CELL LENGTH
DIRECTION

.500

-27

.75 DIA

DETAIL -21 INSERT
FULL SIZE

3.65

3.20

DETAIL -9
SCALE: 1/1

3

SECTION C-C
SECTION D-D

Figure 96. Tailboom Subas

177

4

-13. INSERT
8 REQD
SEE DETAIL
POT IN -7 CORE
BEFORE WINDING
-3 SKIN WITH
FOAM ADHESIVE
-9 REF

15.06

-5
REF

-10 TYP

-15 REF

-9 REF
-15 REF

WL
129.200

-9 REF

-7 REF

-9 REF

SEE SHEET 1

02731 J

Figure 96.   Tailboom Subassembly (Sheet 3 of 4)

177

STA
472.389

4.10

1.50

-7 REF

-55 REF

-59 P1
-57 P2
-57 P3

-3 REF

-59 P1
-59 P2
-59 P3

-5 REF

LINE DIAGRAM -55 INSERT
& -57,-59 DOUBLERS
NO SCALE

4.10

P3	I45	6	U	
P2	90	6	U	
P1	0/90	7	U	
RV NO	ORIENT	MATL		

STACKING SEQUE
FOR -55 INSERT
-57,-59 DOUBLE

CELL LENGTH
DIRECTION

.500

RADIUS
SEE DETAIL C

DETAIL -55 INSERT

FILL -7 CORE WITH
FOAM ADHESIVE
THIS AREA
- BOTH SIDES

-35 REF

INSET -55

BL
0.000

4.50

2.25

AA

AA

-57 DOUBLER
SEE LINE DIAGRAM

-3 REF

FOAM ADHESIVE
REF

EOP P1

-5 REF

-59 DOUBLER
SEE LINE DIAGRAM

10°

10°

-7 REF

SECTION P-P
(STA. 472.389)

STACKING SEQUENCE
FOR -55 INSERT 6
-57,-59 DOUBLERS

NO	ORIENT	MATL	PLY THK
	±45	6 U	.017
2	90°	6 U	.030
3	0/90°	7 B	.010

5.250 TRUE

1.000
.470

.198-.204 DIA THRU 6 PL
TO MATCH 7-211113345
BRACKET ASSY

1.750
STA
387.240

2.50
1.30
3.00
1.30
1.006

VIEW S-S
(FULL SIZE)

-21 INSERT 6 REQD
SEE DETAIL

FOAM ADHESIVE -REF
-7 REF

BL
0.000

-39 REF

S

6.65
TRUE

1.25

S

FILL -7 CORE WITH
FOAM ADHESIVE
THIS AREA 4 PLT
-21 INSERTS 6 PL
BEFORE WINDING
-3 OUTER SKIN

STA
496.80

WL
27.800

-3 REF
-7 REF
-5 REF

7-311114122 REF

SECTION T-T
(LOOKING AFT)

-4

2

BL
0.000

3.50 3.00 2.90 2.00 .98
RBL
K 520
220
720 620 520 4.20

DOUBLER ◁
SEE LINE
DIAGRAM ▣

BL
0.000

WL
159.800

SEE SECT K-K ▣ REF

STA
796.80

-3 REF

WL
82.380

-23 REF

2.52
1.06
LBL
6.080

-3 REF
-7 REF
-5 REF

DOUBLER -61
SEE LINE
DIAGRAM ▣

.50 R TYP

SECTION R-R ▣

BARRIER ▣
SEE DETAIL ▣

BL601-3-3 CM INSERT-4 REQD
LOCATE AS SHN PER 10 HOLE
ATTACH PATTERN OF 7-267510503
ASSY - POT WITH FOAM ADHESIVE ▣
IN .70 DIA X 40 DEEP THRU-3 INTO-7.

-61,-63P3
-61,-63P1
-61,-63P2
-61,-63P4

STA
532.380

-3P10
-3P9
-3P8
-3P7
-3P6

-3P7
-3P4
-3P3
-3P2
-3P1

LINE DIAGRAM FOR
-61 & -63 DOUBLERS
NO SCALE

3

Figure 96. Tailboom Subassembly (She

Figure 96.   Tailboom Subassembly (Sheet 4 of 4)

179

3

Figure 97.   Vertical Tail Assembly

181

VIEW LOOKING INBD
LEFT HAND SIDE
BSC ASSEMBLY

QTY		NO.	DESCRIPTION		
AR			MILLED GLASS FIBERS		[11]
AR	HMS 16-1111, CL 3		FILM ADHESIVE		
AR	HMS 17-1002		SYNTACTIC FOAM		
74	LAG669-3L9		BLIND FASTENER		
80	HLT5G-6A8N		COLLAR		
4	HL48-6-5		PIN		
24	HL98-6-4		PIN		
52	HL48-6-3		PIN		
32	MS20FROAD4		RIVET		
4	HS413-0548C		RETAINER		
R	HS413-0948C		RETAINER		
4	HS4210-6N		NUT		
12	HS4210-584		NUT		
1	7-311122731		FITTING		
1	7-311122728		RIB		
1	7-311122727		FITTING		
1	7-311122726		FITTING		
1	7-311122725		ANGLE		
1	7-311122714		FITTING		
1	7-311122713		FITTING		
1	7-311122713		STRUT FITTING		
1	7-311122712		RIB		
1	7-311122711		RIB		
1		-21	LONGERON		[6][5]
1		-19	LONGERON		[6][5]
1		-17	LONGERON		[6][5]
1		-15	LONGERON		[6][5]
1		-13	CORE		[7]
1		-11	CORE		[7]
1		-9	CORE		[7]
1		-7	CORE		[7]
1		-5	OUTER SKIN	AR	[6][5]
1		-3	INNER SKIN	AR	[6][5]

7-311122700

02731 J

Figure 98. Vertical Tail Subassembly (Shee

QTY	PART NO.	DESCRIPTION			
AR		FILLED GLASS FIBERS		⑩	
AR	HMS 16-1111, CL 3	FILM ADHESIVE			
AR	HMS 17-1002	SYNTACTIC FOAM			
74	LMG1669-3L9	BLIND FASTENER			9C
80	HL75G-6ARN	COLLAR			MC
4	HL48-6-5	PIN			MC
24	HL98-6-4	PIN			MW
52	HL48-6-3	PIN			BC
32	MS20FROAD4	RIVET			SM
4	HS4119-064BC	RETAINER			SM
R	HS4713-094BC	RETAINER			GF
4	HS4270-6R4	NUT			GM
12	HS4270-5B4	NUT			GG
1	7-311122731	FITTING			GF
1	7-311122728	RIB			GC
1	7-311122727	FITTING			GM
1	7-311122726	FITTING			GC
1	7-311122725	ANGLE			SC
1	7-311122704	FITTING			SM
1	7-311122723	FITTING			SC
1	7-311122715	STRUT FITTING			RM
1	7-311122712	RIB			GG
1	7-311122711	RIB			3D
1	-21	LONGERON		⑧⑨	BA
1	-19	LONGERON		⑧⑨	BC
1	-17	LONGERON		⑧⑨	BF
1	-15	LONGERON		⑧⑨	BM
1	-13	CORE		⑰	7B
1	-11	CORE		⑰	6C
1	-9	CORE		⑰	6C
1	-7	CORE		⑰	7F
1	-5	OUTER SKIN	AR	⑩⑫	7F
1	-3	INNER SKIN	AR	⑩⑫	7F

7-311122700

02731   J

Figure 98.   Vertical Tail Subassembly (Sheet 1 of 2)

183

7-31112713 REF

.1940 [+.0020] DIA HOLE 8 PLACES
.1900 [-.0015]
HL48-6-3 PIN 16 REQD
HL75G-6 ASW COLLAR 16 REQD

7-311122731 REF

FRONT SPAR
MOLD LINE

7-311122723 REF

REAR SPAR
MOLD LINE

SECTION G-G
SCALE: 1/1

SECTION F-F
SCALE: 1/1

REAR SPAR
MOLD LINE

FRONT SPAR
MOLD LINE

FRONT SPAR
MOLD LINE

-7

-5

-5

-11

-21

REAR SPAR
MOLD LINE

-7

-9

-9

-19

-13

Y₀
0.00

-7

-9

-5

-3

-11

-21

REAR SPAR
MOLD LINE

SECTION E-E
SCALE: 1/1

FILL -9 CORE WITH
FOAM ADHESIVE
THIS AREA BEFORE
WINDING -5 OUTER SKIN

-9

Y₀
0.00

-7

-13

-7-3111227186 REF

-17

.190 [+.0050] DIA HOLE
.1900 [+.005] DIA HOLE
HL48-6-3 PIN & BEND
HL75G-GAGN COLLAR & BEND

2.99

.895

1.70

2.66

-7-3111227186

.190 [+.0050] DIA HOLE
.1900 [+.005] DIA HOLE
HL48-6-4 PIN G
HL75G-GAGN COLLAR

.190 [+.0050]
.1900 DIA
HL48-6
HL75G

7-3111227

REAR SPAR
MOLD LINE

SECTION D-D
SCALE: 1/1

CONTINUOUS RIBS

2

This is a detailed engineering drawing. The text is largely illegible due to image quality. Transcribing readable labels below.

LINE DIAGRAM II
(NO SCALE)

END OF PLIES
P1, P2, P3, P4, P5
P6, P7, P8, P10, P11
P12, P14, P26, P27, P28
P29, P30, P31, P32
P33, P34, P35, P36
P31,

.940 [.0090] DIA HOLE 6 PLACES
.1900 [.0008]
HL48-6-4 PIN 6 REQD
HL75G-6A6N COLLAR 6 REQD

FRONT SPAR
MOLD LINE

FILL -11 CORE WITH
FOAM ADHESIVE
THIS AREA BEFORE
WINDING -5
OUTER SKIN

SECTION C-C
SCALE: 1/1

LINE DIAGRAM III
(NO SCALE)

MILLED GLASS FIBERS/EPOXY

LINE DIAGRAM I
(NO SCALE)

CONTINUOUS PLIES

MILLED GLASS FIBERS/EPOXY

3

Figure 98. Vertical Tail Subassembly (S

Figure 98. Vertical Tail Subassembly (Sheet 2 of 2)

185

7-3111237I7 PIVOT FITTING REF

.3165 [+.0080] HOLE 6 PLACES
.3125 [-.0005]
HL 48-10-15 PIN
HL 756-10 AGN COLLAR [7]
8 REQD

7-311123729-3 PIVOT INSERT
2 REQD

.3165 +.005 HOLE 6 PL
.3125 -.0005
HL 48-10-15 PIN
HL 756-10AGN COLLAR [7]
6 REQD

7-311123729-5 PIVOT INSERT
2 REQD

7-311123729-7 PIVOT INSERT
2 REQD

.1960 [+.0080] HOLE 2 PL
.1900 [-.0005]
HL 48-6-5 PIN
HL 756-6 AGN COLLAR [7]
4 REQD

7-311123714 RIB REF

7-3111237I6
ACTUATOR FITTING
2 REQD

.1960 [+.0080] HOLE 2 PLACES
.1900 [-.0005]
HL 48-6-6 PIN
HL 756-6 AGN COLLAR [7]
4 REQD

SECTION C-C
SCALE 1/1

C

HL48-6-5 PIN
HL75G-6 EACH COLLAR
24 REQD

1960 [+.0080]
1900 [-.0008] HOLE DIA FL

[7]

HL48-6-6 PIN
HL75G-6 EACH COLLAR
REQD

1960 [+.0080]
1900 [-.0008] HOLE DIA FL

[7]

7-311123728 RIB REF

FWD

VIEW LOOKING DOWN
WITH 7-311123711-5 SKIN REMOVED

C

Figure 99. Stabilator Assembly (Sheet 1 of 2)

7-311123727 COVER DEBRIS
PROTECTION
2 REQD

7-311123725-7
LEADING EDGE RIB
2 REQD

B

5.67

4.50

8.80

15.90

22.30

31.86
TIP CHORD
REF

52.76

6.00 CONST

LOCATE FROM
HS4731-2

B

VIEW B-B

7-311123720
TIP CLOSURE
2 REQD

HS4731-2 STATIC WICK
2 REQD

7-311123722 RIB ASSY
2 REQD

7- 3111237∠5 - 5
LEADING EDGE RIB
2 REQD

7- 3111237∠5 - 3
LEADING EDGE RIB
2 REQD

7- 3111237∠7   PIVOT FITTING
2 REQD

2.00

6.65

7-3111237∠8 RIB
2 REQD

7- 3111237
⑥

②

RIB ASSY

7-3111237∠1 RIB ASSY
2 REQD

7-3111237∠4 RIB ASSY
2 REQD

7-3111237∠1-3 SKIN
2 REQD
⑥

STA
11.000

A

9.886

18.672

21.600

7-31123712
FWD SPAR

30.240

63.200
ROOT CHORD
REF

44.08

B.L.
8.000

7-31123713 AFT SPAR

7-31123711-5 SKIN

.975 REF

SECTION A-A

3

9 FINISH NO ED PER EPB 4-230

8 SEAL FASTENERS USING NMS 16-1097 PER HP 5-10 TYPE II

7 INSTALL NICRES PER HP3-2

6 INSTALL BLIND RIVETS PER HP3-5

5 INSTALL SOLID RIVETS PER HP3-0

4 BOND PER HP16-30

3 DIMENSIONS & TOLERANCES PER ANSI Y14.5

2 IDENTIFY PER HP8-5 TYPE I, CLASS 3 LOCATE APPROX AS SHOWN

1 CONTOUR PER 7-2L1123600 EXCEPT PLANFORM AS SHOWN

NOTES UNLESS OTHERWISE SPECIFIED

				AR			ADHESIVE		FILM
				2	CR 3215		RIVET		
				2	MS 20470 AD6		RIVET		
				52	HL 756-6 AGN		COLLAR		
				12	HL 756-10 AGN		COLLAR		
				4	HL 48-6-6		PIN		
				4	HL 48-6-5				
				26	HL 48-6-4				
				26	HL 48-6-3				
				8	HL 48-10-15				
				6	HL 48-10-14		PIN		
				2	HS4731-2		STATIC WICK		
				2	7-311123716		FITTING ACTUATOR		
				2	7-311123729		INSERT, FITTING		
				2	7-311123727		DEBRIS PROTECTION		
				2	7-311123728		RIB, BL 8.00		
				2	7-311123725		RIBS, LEADING EDGE		
				2	7-311123722		RIB ASSY BL 47.00		
				2	7-311123721		RIB ASSY, BL 24.00		
				2	7-311123720		TIP CLOSEOUT		
				2	7-311123717		PIVOT FITTING		
				2	7-311123714		RIB ASSY, BL 11.6		
				1	7-311123713		SPAR, AFT		
				1	7-311123712		SPAR, FWD		
				1	7-311123711		SKIN		

02731

Figure 99. Stabilator Assembly (Sh

189

QTY	PART NO.	NOMENCLATURE				ZONE
AR		ADHESIVE		FILM	NMS 16 1111 CLASS 2	
2	CR 3213	RIVET				
2	MS 20470 AD6	RIVET				
56	HL 756-6 AGN	COLLAR				
12	HL 756-10 AGN	COLLAR				
4	HL 48-6-6	PIN				
4	HL 48-6-5					
28	HL 48-6-4					
24	HL 48-6-3					
8	HL 48-10-15					
4	HL 48-10-14	PIN				
2	HS4731-2	STATIC WICK				9C
2	7-311123716	FITTING ACTUATOR				17C
2	7-311123729	INSERT, FITTING				4D 4E
2	7-311123727	DEBRIS PROTECTION				8C
2	7-311123728	RIB, BL 8.00				6D
2	7-311123725	RIBS, LEADING EDGE				
2	7-311123722	RIB ASSY BL 42.00				8B
2	7-311123721	RIB ASSY BL 24.00				7B
2	7-311123720	TIP CLOSEOUT				9C
2	7-311123717	PIVOT FITTING				6C
2	7-311123714	RIB ASSY BL 11.8				6B
1	7-311123713	SPAR, AFT				5D
1	7-311123712	SPAR, FWD				5F
1	7-311123711	SKIN				7B

097 PER NP 5-10 TYPE IV

PER ANSI Y14.5
CLASS 3 LOCATE APPROX AS SHOWN
EXCEPT PLANFORM AS SHOWN

02731 | J

Figure 99. Stabilator Assembly (Sheet 2 of 2)

189