

AD-A082 820

ILC DOVER FREDERICA DE PROTECTIVE EQUIPMENT DIV
VISOR OPTIMIZATION.(U)
MAR 80 C R SANDY

F/G 6/17

UNCLASSIFIED

DAAK11-79-C-0066

NL

1-1
AD
025 1800



END

DATE

FILED

5 80

DTIC

LEVEL ~~II~~

VISOR OPTIMIZATION

DAAK11-79-C-0066

ADA 082820

Charles R. Sandy
Project Engineer
Protective Equipment Division
ILC DOVER
P.O. Box 266
Frederica, Delaware
19946

②
DTIC
EXTRACTED
APR 7 1980
D
C

28 March 1980

Final Report for Period 12 June 1979 -- 29 March 1980

Prepared For:

CDR, ARRADCOM
CML/Ballistics Procurement
APG (Edgewood Area), Maryland
21010

DCASR Philadelphia
P.O. Box 7730
Philadelphia, Pennsylvania
19101

This document has been approved
for public release and sale; its
distribution is unlimited.

The view, opinions, and/or findings contained in this report are those of the author and should not be construed as an official Department of the Army position, policy or decision, unless so designated by other documentation.

DDC FILE COPY

30 4 411692 4 037 B

Unclassified

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER DAAK11-79-C-0066-05	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Visor Optimization	5. TYPE OF REPORT & PERIOD COVERED Final Report 12 June 79 - 29 March 80	6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(s) Charles R. Sandy, Project Engineer Protective Equipment, ILC DOVER	8. CONTRACT OR GRANT NUMBER(s) DAAK11-79-C-0066	
9. PERFORMING ORGANIZATION NAME AND ADDRESS ILC DOVER P.O. Box 266 Frederica, Delaware 19946	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS Task Order Number 5	
11. CONTROLLING OFFICE NAME AND ADDRESS CDR, ARRADCOM CML/Ballistics Procurement APG (Edgewood Area), Maryland 21010	12. REPORT DATE 28 March 1980	13. NUMBER OF PAGES Page 1 of 4
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) DCASR Philadelphia P.O. Box 7730 Philadelphia, Pennsylvania 19101	15. SECURITY CLASS. (of this report) Unclassified	15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release: Distribution Unlimited		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Outergarment DPE, Demilitarization Protective Ensemble		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This task was authorized to redesign the visor closure tools on the DPE Outergarment in order to eliminate cutting of the vinyl visor material. The tooling was designed, fabricated and tested. It succeeds in preventing cutting of the vinyl visor material while maintaining the peel strength of the seam required per specification.		

DD FORM 1473
1 JAN 73

EDITION OF 1 NOV 68 IS OBSOLETE

411 692

Unclassified

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

FOREWARD

The work reported herein was conducted by ILC DOVER, Frederica, Delaware, for ARRADCOM, CML/Ballistics Procurement, APG (Edgewood Area), Maryland in accordance with Contract DAAK11-79-C-0066, Task Order Number 5. Mr. Donald R. Cohee was the Program Manager for ILC DOVER. Mr. Wayne Davis was the Contract Monitor for the Chemical Systems Laboratory. This work was accomplished between 12 June 1979 and 29 March 1980.

This technical report has been reviewed and is approved.

Mr. David M. English, Chief
Combat Vehicle Section
Physical Protection Division
Chemical Systems Laboratory

Accession For	
NIMS C&AI	
DDG TAB	
Unannounced	
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or special

INTRODUCTION

This task was authorized to redesign the visor tooling in order to eliminate cutting of the vinyl visor material while allowing heat seal machine time and power settings that will force a large extrusion.

COMPLETED ACTIVITY

The following work was performed during the completion of this task order:

- (1) The tooling redesign was completed. The vinyl cutting problem is eliminated by predetermining the desired heat seal thickness and incorporating it in the heat seal tool. The straight heat seal bar is held upright by a wide phenolic stand-off. The phenolic bar is slightly thicker than the aluminum bar. When two layers of 40-mil vinyl lie under the aluminum bar, however, it is higher than the phenolic. Therefore, the top platen contacts the aluminum first.

As heat sealing begins, the aluminum sinks into the vinyl until the platen bottoms on the phenolic. At this point the platen can travel no further, and the heat seal thickness is determined by the difference in heights between the phenolic and aluminum bars. By limiting the depth of penetration of the aluminum into the vinyl, the cutting is eliminated.

A lucite bar bolted to the aluminum bar on one side prevents spreading of the vinyl material on that side during heat sealing. This leaves little space for a bead to form, forcing most of the extruded material to form a large bead on the opposite side. This is desirable because the tool can be positioned to form the pronounced bead on the inside of the seam, where it is needed due to pressure loading. Also, it is a readily visible indication of a good seal.

- (2) Two (2) heat seal tools were fabricated and drawings made of each; a short tool for the top visor heat seal, and a long tool for the longer side visor heat seals. Seam samples made by the new tools were tested and found adequate per specification. ECP Number 80-0058-002 includes these tool drawings and test results.
- (3) All changes to the specification, tool drawings, and test results have been submitted with ECP Number 80-0058-002, proposing the implementation of the redesigned helmet closure tooling.

CONCLUSION

The redesigned visor closure tools are available for use in production of DPE Outergarments.