Vol 2 of 2

7886

U.S. Army Environmental Center

FINAL REPORT

VOLUME II OF II
APPENDICES A - F

SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY

BUILDING NO. 500

U.S. ARMY GARRISON, FITZSIMONS AURORA, COLORADO

Contract No. DACA31-94-D-0068, D.O. 0006

Prepared for

The U.S. Army Environmental Center

Aberdeen Proving Ground, Maryland

Prepared by

Parsons Engineering Science, Inc.

Denver, Colorado

September 1996

Distribution Unlimited:
Approved for Public Release

AEC Form 45, 1 Feb 93 replaces THAMA Form 45 which is obsolete.

TABLE OF CONTENTS

VOLUME I

Page

EXECUTIVE SUMMARY ES-1

LIST OF ACRONYMS v

SECTION 1 - INTRODUCTION 1-1

1.1 Authority for the Site-Specific Environmental Baseline Survey 1-2
1.2 Objective 1-5
1.3 Organization of the Site-Specific Environmental Baseline Survey 1-5

SECTION 2 - SURVEY METHOD 2-1

2.1 Fitzsimons Environmental Documents 2-1
2.2 Regulatory and Fitzsimons Records 2-2
2.3 Interviews and Visual Inspections 2-2

SECTION 3 - DESCRIPTION OF BUILDING NO. 500 3-1

3.1 General Building Information 3-1
3.2 Building History 3-2
3.3 Permitting/License Status 3-44
3.3.1 Resource Conservation and Recovery Act Status 3-44
3.3.2 Comprehensive Environmental Response, Compensation, and Liability Act Status 3-45
3.3.3 National Pollution Discharge Elimination System Permits 3-45
3.3.4 Solid Waste Permits 3-45
3.3.5 Air Permits 3-45
3.3.6 Water Supply Permits 3-45
3.3.7 Underground and Aboveground Storage Tank Registrations 3-45
3.3.8 Nuclear Regulatory Commission 3-45

SECTION 4 - RESEARCH FINDINGS 4-1

4.1 Document Review, Interviews, and Visual Inspections 4-1
4.1.1 Hazardous Substance Storage Locations 4-1
4.1.2 Hazardous, Non-Hazardous, and Radioactive Waste Sites 4-2
4.1.2.1 Incineration 4-2
4.1.2.2 Discharges to the Sanitary and Storm Sewer System 4-2
4.1.2.3 Gaseous Emissions Sources 4-3

TABLE OF CONTENTS (CONTINUED)

Page

4.1.2.4 Waste Management Practices 4-4
4.1.3 Releases of Petroleum Product 4-4
4.1.4 Asbestos Sites 4-5
4.1.5 Lead-Based Paint Sites 4-5
4.1.6 Polychlorinated Biphenyls Storage Locations 4-5
4.1.7 Radon Sites 4-6
4.1.8 Radionuclide Sites 4-6
4.1.9 Areas With No Identified Contamination 4-8
4.2 Records Review 4-8
4.2.1 Fitzsimons Records 4-8
4.2.3 Fitzsimons Records and Personnel Interviews 4-8
4.2.3.1 Hazardous Material Inventory Database 4-9
4.2.3.2 Hazardous Waste Inventory Database 4-9
4.2.3.3 Spills Database 4-9
4.2.3.4 Storage Tank Database 4-11
4.2.3.5 Asbestos Records 4-11
4.2.3.6 Polychlorinated Biphenyl Records 4-11
4.2.3.7 Radon Records 4-11
4.2.3.8 Radiological Records 4-12
4.2.3.9 Real Estate Records 4-12
4.2.3.10 Renovations 4-12

SECTION 5 - ENVIRONMENTAL CONDITION AND CATEGORIZATION OF PROPERTY 5-1

5.1 Ninth Floor 5-33
5.2 Eighth Floor 5-34
5.3 Seventh Floor 5-34
5.4 Sixth Floor 5-35
5.5 Fifth Floor 5-37
5.6 Fourth Floor 5-38
5.7 Third Floor 5-40
5.8 Second Floor 5-43
5.9 First Floor 5-45
5.10 Ground Floor 5-48
5.11 Basement 5-48
5.12 Non-CERCLA Environmental, Hazardous, and Safety Issues 5-50
5.12.1 Asbestos 5-51
5.12.2 Lead-Based Paint 5-51
5.12.3 Polychlorinated Biphenyls 5-51
5.12.4 Radon 5-51
5.12.5 Radionuclides 5-51
5.13 Remediation Efforts 5-52

TABLE OF CONTENTS (CONTINUED)

VOLUME II

APPENDICES

Appendix A - Community Environmental Response Facilitation Act Letter Report
Appendix B - References
Appendix C - Worksheets, Hazardous Substance Inventory, Cleanup Sites, and Non-CERCLA Related Issues
Appendix D - Interview Summaries
Appendix E - Visual Inspection Summaries

LIST OF TABLES

No.	Title	Page
3.1	Historical Room Use	3-3
4.1	Estimated Quantities of Chemicals Historically Discharged by Department of Pathology Laboratories within Building No. 500	4-2
4.2	Radioisotope Material Listing and Usage within Building No. 500	4-6
4.3	Hazardous Waste Inventory Building No. 500	4-9
4.4	Spills Database Building No. 500	4-10
4.5	Suspected Spills Building No. 500	4-11
4.6	Renovations Building No. 500	4-12
5.1	Rooms Identified as Category 1	5-3
5.2	Category 2 Rooms Seventh Floor	5-34
5.3	Category 2 Rooms Sixth Floor	5-35
5.4	Category 2 Rooms Fifth Floor	5-38
5.5	Category 2 Rooms Fourth Floor	5-40
5.6	Category 2 Rooms Third Floor	5-43
5.7	Category 2 Rooms Second Floor	5-44
5.8	Category 2 Rooms First Floor	5-46
5.9	Category 2 Rooms Ground Floor	5-48

LIST OF FIGURES

No.	Title	Page
1.1	Vicinity Map of Fitzsimons	1-3
1.2	Site Map of Fitzsimons	1-4

TABLE OF CONTENTS (CONTINUED)

LIST OF FIGURES (CONTINUED)

No.	Title	Page
5.1	Location of Radioactive Materials and Waste - Six Floor and Seventh Floor	5-53
5.2	Location of Radioactive Materials and Waste - Third Floor and Fourth Floor	5-54
5.3	Location of Radioactive Materials and Waste - First Floor and Second Floor	5-54

APPENDIX A

COMMUNITY ENVIRONMENTAL RESPONSE FACILITATION ACT LETTER REPORT

EXECUTIVE SUMMARY

This letter report presents the results of the Community Environmental Response Facilitation Act (CERFA) investigation conducted by the Army Environmental Center for Building No. 500 at the U.S. Army Garrison, Fitzsimons (Fitzsimons), a U.S. government property selected for closure in 1995 by the Base Realignment and Closure (BRAC) Commission under Public Laws 100-526 and 101-510. Under CERFA (Public Laws 102-426), Federal agencies are required to expeditiously identify real property that can be immediately reused and redeveloped. Satisfying this objective requires the identification of real property where no hazardous substances, regulated by the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), and no petroleum products or their derivatives were stored for 1 year or more, known to have been released, or disposed.

Information in this letter report was obtained during the preparation of the Site-Specific Environmental Baseline Survey (SSEBS) for Building No. 500 at Fitzsimons and was current as of August 5, 1996. This information was used to divide Building No. 500 into seven categories of parcels. These categories, as defined by the Department of Defense BRAC Cleanup Plan (BCP) Guidebook, Fall 1993, are as follows:

1. Areas where no storage, release or disposal of hazardous substances or petroleum products has occurred (including no migration of these substances from adjacent areas) [white]

2. Areas where only storage of hazardous substances or petroleum products has occurred (but no release, disposal, or migration from adjacent areas has occurred) [blue]

3. Areas where storage, release, disposal, and/or migration of hazardous substances or petroleum products has occurred, but at concentrations that do not require a removal or remedial action [light green]

4. Areas where storage, release, disposal, and/or migration of hazardous substances or petroleum products has occurred, and all remedial actions necessary to protect human health and the environment have been taken [dark green]

5. Areas where storage, release, disposal, and/or migration of hazardous substances or petroleum products has occurred, removal and/or remedial actions are under way, but all required remedial actions have not yet been taken [yellow]

6. Areas where storage, release, disposal, and/or migration of hazardous substances or petroleum products has occurred, but required response actions have not yet been implemented [red]

7. Areas that are unevaluated or require additional evaluation [gray]

Areas of the facility which contained Non-CERCLA related environmental or safety issues, including asbestos, lead-based paint, PCB, radon, UXO, and radionuclides, have also been identified in separate parcels.

This letter report contains a map that summarizes the categorization of Building No. 500 at Fitzsimons on the basis of the above definitions. This report should be read only in conjunction with the complete SSEBS report for Building No. 500 at Fitzsimons. The SSEBS report provides the relevant environmental history to substantiate the parcel categorization. This report does not address other property transfer requirements that may be applicable under the National Environmental Policy Act, nor does it address natural resource considerations such as the threat to plant or animal life.

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
1	1(2)HS	B1	3265.73	2	9000	storage of chemicals for elevator repair	visual inspection	None
2	2(1)	C2	7483.41	1	8001	always been patient room	real estate	None
2	2(1)	C2	7483.41	1	8001A	always been latrine	visual inspection, real estate	None
2	2(1)	B2	7483.41	1	8002	always been administration	visual inspection, real estate	None
2	2(1)	C2	7483.41	1	8002A	always been latrine	visual inspection, real estate	None
2	2(1)	B2	7483.41	1	8004	always been office/space	visual inspection, real estate	None
2	2(1)	B2	7483.41	1	8004A	always been latrine	visual inspection, real estate	None
2	2(1)	B2	7483.41	1	8006	historically room and serving room	visual inspection, real estate	None
2	2(1)	B2	7483.41	1	8007	always been a theater	visual inspection, real estate	None
2	2(1)	B2	7483.41	1	8007A	always been stage	visual inspection, real estate	None
2	2(1)	B2	7483.41	1	8007B	always been dressing room	visual inspection, real estate	None
2	2(1)	B2	7483.41	1	8007C	always been dressing room	visual inspection, real estate	None
2	2(1)	B2	7483.41	1	8007D	always been dressing room	visual inspection, real estate	None
2	2(1)	B2	7483.41	1	8008	always been latrine	visual inspection, real estate	None
2	2(1)	B1	7483.41	1	8009	always been room	real estate	None
2	2(1)	B1	7483.41	1	8009A	always been latrine	visual inspection, real estate	None
2	2(1)	B1	7483.41	1	8010	always been room	real estate	None
2	2(1)	C1	7483.41	1	8010A	always been latrine	visual inspection, real estate	None
2	2(1)	C2	7483.41	1	8011	always been linen closet and file room	visual inspection, real estate	None
2	2(1)	C2	7483.41	1	8012	historically patient room and nursing room	real estate	None
2	2(1)	C2	7483.41	1	8013	always been office	real estate	None
3	3(2)HS	B2	34.23	2	8005	janitor closets historically store chemicals	real estate	None
4	4(2)HS	C2	245.15	2	8000	potential for chemical use	real estate	None
4	4(2)HS	C2	245.15	2	8003	potential chemical storage	visual inspection, real estate	None
4	4(2)HS	C2	245.15	2	8003A	potential chemical storage	visual inspection, real estate	None
5	5(1)	C4	26794.58	1	7000	historically used as linen and copier room	visual inspection, real estate	None
5	5(1)	C4	26794.58	1	7002	historically office and patient room	visual inspection, real estate	None
5	5(1)	C4	26794.58	1	7003	always been a latrine	visual inspection, real estate	None
5	5(1)	B4	26794.58	1	7005	always been reception area	visual inspection, real estate	None
5	5(1)	B4	26794.58	1	7007	always been a patient room	visual inspection, real estate	None
5	5(1)	C4	26794.58	1	7007A	historically porch and patient room	visual inspection, real estate	None
5	5(1)	C4	26794.58	1	7008	always been latrine	visual inspection, real estate	None
5	5(1)	B4	26794.58	1	7009	always been patient room	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
5	5(1)	B5	26794.58	1	7010	always been patient room	visual inspection, real estate	None
5	5(1)	C5	26794.58	1	7010A	historically porch and patient room	visual inspection, real estate	None
5	5(1)	B5	26794.58	1	7011	always been latrine	visual inspection, real estate	None
5	5(1)	B5	26794.58	1	7013	always been patient room	visual inspection, real estate	None
5	5(1)	C5	26794.58	1	7013A	historically porch and patient room	visual inspection, real estate	None
5	5(1)	C5	26794.58	1	7014	always been latrine	visual inspection, real estate	None
5	5(1)	B5	26794.58	1	7015	historically been linen storage and corridor	visual inspection, real estate	None
5	5(1)	B5	26794.58	1	7018	always been latrine	visual inspection, real estate	None
5	5(1)	C5	26794.58	1	7019	always been office	visual inspection, real estate	None
5	5(1)	B5	26794.58	1	7020	always been linen chute	visual inspection, real estate	None
5	5(1)	B5	26794.58	1	7023	always been patient room	visual inspection, real estate	None
5	5(1)	B5	26794.58	1	7024	always been latrine	visual inspection, real estate	None
5	5(1)	B5	26794.58	1	7025	always been patient room	visual inspection, real estate	None
5	5(1)	B4	26794.58	1	7026	always been patient room	visual inspection, real estate	None
5	5(1)	B4	26794.58	1	7027	always been latrine	visual inspection, real estate	None
5	5(1)	B4	26794.58	1	7028	always been patient room	visual inspection, real estate	None
5	5(1)	B4	26794.58	1	7029	always been patient room or office	visual inspection, real estate	None
5	5(1)	B4	26794.58	1	7030	always been latrine	visual inspection, real estate	None
5	5(1)	B4	26794.58	1	7032	always been patient room or office	visual inspection, real estate	None
5	5(1)	B4	26794.58	1	7033	always been latrine	visual inspection, real estate	None
5	5(1)	B4	26794.58	1	7035	always been latrine	visual inspection, real estate	None
5	5(1)	B4	26794.58	1	7047	always been latrine	visual inspection, real estate	None
5	5(1)	B4	26794.58	1	7048	always been patient room or office	visual inspection, real estate	None
5	5(1)	B3	26794.58	1	7049	always been latrine	visual inspection, real estate	None
5	5(1)	B3	26794.58	1	7051	always been patient room	visual inspection, real estate	None
5	5(1)	B3	26794.58	1	7052	always been patient room	visual inspection, real estate	None
5	5(1)	B3	26794.58	1	7053	always been latrine	visual inspection, real estate	None
5	5(1)	B3	26794.58	1	7054	always been patient room	visual inspection, real estate	None
5	5(1)	B3	26794.58	1	7055	always been patient room	visual inspection, real estate	None
5	5(1)	B3	26794.58	1	7056	always been latrine	visual inspection, real estate	None
5	5(1)	B3	26794.58	1	7057	always been patient room	visual inspection, real estate	None
5	5(1)	B3	26794.58	1	7060	always been linen chute	visual inspection, real estate	None
5	5(1)	C3	26794.58	1	7061	always been day room or office	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
5	5(1)	B3	26794.58	1	7063	always been latrine	visual inspection, real estate	None
5	5(1)	B3	26794.58	1	7064	always been linen storage or corridor	visual inspection, real estate	None
5	5(1)	B3	26794.58	1	7065	always been patient room closet	visual inspection, real estate	None
5	5(1)	C3	26794.58	1	7066	always been latrine	visual inspection, real estate	None
5	5(1)	C3	26794.58	1	7066A	always been patient room or porch	visual inspection, real estate	None
5	5(1)	B3	26794.58	1	7067	always been patient room	visual inspection, real estate	None
5	5(1)	C3	26794.58	1	7068A	always been patient room or porch	visual inspection, real estate	None
5	5(1)	C3	26794.58	1	7069	always been latrine	visual inspection, real estate	None
5	5(1)	B3	26794.58	1	7070	always been patient room	visual inspection, real estate	None
5	5(1)	C3	26794.58	1	7071A	always been patient room or porch	visual inspection, real estate	None
5	5(1)	C3	26794.58	1	7072	always been latrine	visual inspection, real estate	None
5	5(1)	B3	26794.58	1	7073	always been patient room	visual inspection, real estate	None
5	5(1)	C3	26794.58	1	7074	always been patient room	visual inspection, real estate	None
5	5(1)	C4	26794.58	1	7075	always been latrine	visual inspection, real estate	None
5	5(1)	C4	26794.58	1	7076	always been patient room or office	visual inspection, real estate	None
5	5(1)	C4	26794.58	1	7079	always been office	visual inspection, real estate	None
6	6(2)HS/PS	B5	349.30	2	7021	potential for chemical use	visual inspection, real estate	None
6	6(2)HS/PS	B5	349.30	2	7022	potential for chemical use	visual inspection, real estate	None
7	7(2)HS	B5	28.03	2	7017	potential for chemical use	visual inspection, real estate	None
8	8(2)HS	B5	127.22	2	7012	potential for chemical storage	visual inspection, real estate	None
9	9(2)HS	C4	214.04	2	7004	potential for chemical storage	visual inspection, real estate	None
10	10(2)HS	B4	15.06	2	7031	potential for chemical storage	visual inspection, real estate	None
11	11(2)HS	B4	68.16	2	7006	potential for chemical storage	visual inspection, real estate	None
12	12(2)HS	B4	27.93	2	7034	potential for chemical storage	visual inspection, real estate	None
13	13(2)HS	C4	181.32	2	7001	potential for chemical use	visual inspection, real estate	None
14	14(2)HS	B4	233.77	2	7078	potential for chemical storage	visual inspection, real estate	None
15	15(2)HS	B3	15.07	2	7050	potential for chemical storage	visual inspection, real estate	None
16	16(2)HS	B3	132.61	2	7071	potential for chemical storage	visual inspection, real estate	None
17	17(2)HS	B3	135.86	2	7068	potential for chemical use	visual inspection, real estate	None
18	18(2)HS	B3	353.86	2	7058	potential for chemical storage	visual inspection, real estate	None
18	18(2)HS	B3	353.86	2	7059	potential for oils and greases	visual inspection, real estate	None
19	19(2)HS	B3	27.63	2	7062	potential for chemical storage	visual inspection, real estate	None
20	20(7)HR	B4	2811.76	7	7036	potential chemical use	Errett, Neeper, Boatwright	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
20	20(7)HR	B4	2811.76	7	7036A	potential chemical use	Errett, Neeper, Boatwright	None
20	20(7)HR	B4	2811.76	7	7037	potential chemical use	Errett, Neeper, Boatwright	None
20	20(7)HR	B4	2811.76	7	7038	potential chemical use	Errett, Neeper, Boatwright	None
20	20(7)HR	B4	2811.76	7	7039	potential chemical use	Errett, Neeper, Boatwright	None
20	20(7)HR	B4	2811.76	7	7040	potential chemical use	Errett, Neeper, Boatwright	None
20	20(7)HR	B4	2811.76	7	7040A	potential chemical use	Errett, Neeper, Boatwright	None
20	20(7)HR	B4	2811.76	7	7041	potential chemical use	Errett, Neeper, Boatwright	None
20	20(7)HR	B4	2811.76	7	7042	potential chemical use	Errett, Neeper, Boatwright	None
20	20(7)HR	B4	2811.76	7	7043	potential chemical use	Errett, Neeper, Boatwright	None
20	20(7)HR	B4	2811.76	7	7045	potential chemical use	Errett, Neeper, Boatwright	None
20	20(7)HR	B4	2811.76	7	7046	installation of lead lined doors in 1967	real estate	None
21	21(1)	E3	23382.33	1	6007	always been latrine	visual inspection, real estate	None
21	21(1)	E4	23382.33	1	6010	always been latrine	visual inspection, real estate	None
21	21(1)	E4	23382.33	1	6012	always been patient room or office	visual inspection, real estate	None
21	21(1)	E4	23382.33	1	6012A	always been office or porch	visual inspection, real estate	None
21	21(1)	E4	23382.33	1	6014	always been latrine	visual inspection, real estate	None
21	21(1)	E4	23382.33	1	6017	always been soiled linen or telephone room	visual inspection, real estate	None
21	21(1)	E4	23382.33	1	6018	always been bedroom or office	visual inspection, real estate	None
21	21(1)	E4	23382.33	1	6019	always been latrine	visual inspection, real estate	None
21	21(1)	E4	23382.33	1	6020	always been latrine	visual inspection, real estate	None
21	21(1)	E4	23382.33	1	6023	always been latrine	visual inspection, real estate	None
21	21(1)	E4	23382.33	1	6024	always been patient room or office	visual inspection, real estate	None
21	21(1)	E4	23382.33	1	6024A	always been office or porch	visual inspection, real estate	None
21	21(1)	E4	23382.33	1	6025	always been latrine	visual inspection, real estate	None
21	21(1)	E4	23382.33	1	6026	always been telephone booth	visual inspection, real estate	None
21	21(1)	E4	23382.33	1	6026A	always been waiting room or porch	visual inspection, real estate	None
21	21(1)	D4	23382.33	1	6026B	always been break room or porch	visual inspection, real estate	None
21	21(1)	D4	23382.33	1	6028	always been nurse station	visual inspection, real estate	None
21	21(1)	D4	23382.33	1	6030	always been latrine	visual inspection, real estate	None
21	21(1)	D4	23382.33	1	6031	always been office or corridor	visual inspection, real estate	None
21	21(1)	D4	23382.33	1	6033	always been serving kitchen and conference	visual inspection, real estate	None
21	21(1)	D4	23382.33	1	6035	always been patient room or office	visual inspection, real estate	None
21	21(1)	D4	23382.33	1	6036	always been latrine	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
21	21(1)	D4	23382.33	1	6039	always been patient room or office	visual inspection, real estate	None
21	21(1)	D4	23382.33	1	6040	always been latrine	visual inspection, real estate	None
21	21(1)	D4	23382.33	1	6041	always been patient room or office	visual inspection, real estate	None
21	21(1)	D4	23382.33	1	6042	always been patient room or office	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6043	always been latrine	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6045	always been patient room or office	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6046	always been latrine	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6049	always been latrine	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6051	always been latrine	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6052	always been patient room	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6052A	always been patient room or porch	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6054	always been latrine	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6057	always been patient room	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6059	always been latrine	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6060	always been linen	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6070	always been a nurse station	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6071	always been a latrine	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6077A	always been patient room or laundry	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6081A	always been physician room or serving kitchen	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6081B	always been latrine or ante room	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6085	always been latrine	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6086	always been patient room or office	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6087	always been latrine	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6089	always been soiled linen	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6090	always been patient room	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6090A	always been porch or ultrasound room	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6094	always been bedroom or office	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6095	always been latrine	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6096	always been latrine	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6097	always been patient room	visual inspection, real estate	None
21	21(1)	D3	23382.33	1	6099	always been latrine	visual inspection, real estate	None
21	21(1)	D2	23382.33	1	6100	always been patient room or office	visual inspection, real estate	None
21	21(1)	D2	23382.33	1	6101	always been patient room	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
21	21(1)	D2	23382.33	1	6102	always been latrine	visual inspection, real estate	None
21	21(1)	D2	23382.33	1	6103	always been patient room	visual inspection, real estate	None
21	21(1)	D2	23382.33	1	6104	always been patient room	visual inspection, real estate	None
21	21(1)	D2	23382.33	1	6105	always been latrine	visual inspection, real estate	None
21	21(1)	D2	23382.33	1	6106	always been patient room	visual inspection, real estate	None
21	21(1)	D2	23382.33	1	6109	always been latrine	visual inspection, real estate	None
21	21(1)	D2	23382.33	1	6110	always been patient room	visual inspection, real estate	None
21	21(1)	D2	23382.33	1	6111A	always been kitchen	visual inspection, real estate	None
21	21(1)	D2	23382.33	1	6112A	always been either a room or kitchen	visual inspection, real estate	None
21	21(1)	D2	23382.33	1	6112B	always been either a room or kitchen	visual inspection, real estate	None
21	21(1)	D2	23382.33	1	6114	always been corridor or office	visual inspection, real estate	None
21	21(1)	D2	23382.33	1	6117	always been nurse station	visual inspection, real estate	None
21	21(1)	D2	23382.33	1	6118	always been room or linen storage	visual inspection, real estate	None
21	21(1)	D1	23382.33	1	6118A	always been patient room or porch	visual inspection, real estate	None
21	21(1)	E2	23382.33	1	6119	always been telephone booth	visual inspection, real estate	None
21	21(1)	E2	23382.33	1	6120	always been latrine	visual inspection, real estate	None
21	21(1)	E2	23382.33	1	6121	always been patient room	visual inspection, real estate	None
21	21(1)	E1	23382.33	1	6121A	always been patient room or porch	visual inspection, real estate	None
21	21(1)	E2	23382.33	1	6122	always been latrine	visual inspection, real estate	None
21	21(1)	E2	23382.33	1	6123	always been patient room	visual inspection, real estate	None
21	21(1)	E2	23382.33	1	6124	always been patient room	visual inspection, real estate	None
21	21(1)	E2	23382.33	1	6125	always been latrine	visual inspection, real estate	None
21	21(1)	E2	23382.33	1	6128	always been soiled linen	visual inspection, real estate	None
21	21(1)	E2	23382.33	1	6130A	always been patient room	visual inspection, real estate	None
21	21(1)	E2	23382.33	1	6130B	always been patient room	visual inspection, real estate	None
21	21(1)	E2	23382.33	1	6130C	always been patient room or office	visual inspection, real estate	None
21	21(1)	E2	23382.33	1	6131	always been patient room	visual inspection, real estate	None
21	21(1)	E2	23382.33	1	6132	always been latrine	visual inspection, real estate	None
21	21(1)	E2	23382.33	1	6133	always been bedroom or office	visual inspection, real estate	None
21	21(1)	E2	23382.33	1	6134	always been bedroom or office	visual inspection, real estate	None
21	21(1)	E2	23382.33	1	6135	always been bedroom or office	visual inspection, real estate	None
21	21(1)	E2	23382.33	1	6136	always been bedroom or office	visual inspection, real estate	None
22	22(2)HS	D4	121.54	2	6032	potential for chemical use	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
23	23(2)HS	D4	202.72	2	6027	potential for chemical storage	visual inspection, real estate	None
23	23(2)HS	D4	202.72	2	6029	potential for chemical storage	visual inspection, real estate	None
24	24(2)HS	E4	275.23	2	6022	potential for chemical use	visual inspection, real estate	None
25	25(2)HS	D4	27.46	2	6034	potential for chemical storage	visual inspection, real estate	None
26	26(2)HS	E4	78.50	2	6019A	potential for chemical storage	visual inspection, real estate	None
27	27(2)HS	E4	114.43	2	6013	potential for chemical storage	visual inspection, real estate	None
27	27(2)HS	E4	114.43	2	6016	potential for chemical storage	visual inspection, real estate	None
28	28(2)HS	D4	139.04	2	6037	potential for chemical storage	visual inspection, real estate	None
28	28(2)HS	D4	139.04	2	6038	potential for chemical storage	visual inspection, real estate	None
29	29(2)HS	E3	2749.80	2	6000	potential for chemical use	visual inspection, real estate	None
29	29(2)HS	E3	2749.80	2	6001	potential for chemical use	visual inspection, real estate	None
29	29(2)HS	E3	2749.80	2	6002	potential for chemical use	visual inspection, real estate	None
29	29(2)HS	E3	2749.80	2	6003	potential for chemical use	visual inspection, real estate	None
29	29(2)HS	E3	2749.80	2	6004	potential for chemical use	visual inspection, real estate	None
29	29(2)HS	E3	2749.80	2	6006	potential for chemical use	visual inspection, real estate	None
29	29(2)HS	E3	2749.80	2	6006A	potential for chemical use	visual inspection, real estate	None
29	29(2)HS	E4	2749.80	2	6008	potential for chemical use	visual inspection, real estate	None
29	29(2)HS	E4	2749.80	2	6009	potential for chemical	visual inspection, real estate	None
29	29(2)HS	E4	2749.80	2	6009A	potential for chemical use	visual inspection, real estate	None
29	29(2)HS	E4	2749.80	2	6011	potential for chemical use	visual inspection, real estate	None
29	29(2)HS	E2	2749.80	2	6140	potential for chemical use	visual inspection, real estate	None
29	29(2)HS	E3	2749.80	2	6141	potential for chemical storage	visual inspection, real estate	None
29	29(2)HS	E3	2749.80	2	6143	potential for chemical use	visual inspection, real estate	None
29	29(2)HS	E3	2749.80	2	6144	potential for chemical use	visual inspection, real estate	None
30	30(2)HS	D3	130.90	2	6044	potential for chemical storage	visual inspection, real estate	None
31	31(2)HS	D3	14.10	2	6047	potential for chemical storage	visual inspection, real estate	None
32	32(2)HS	E3	199.44	2	6005	potential for chemical use	visual inspection, real estate	None
33	33(2)HS	D3	1162.85	2	6061	potential for chemical use	visual inspection, real estate	None
33	33(2)HS	D3	1162.85	2	6065	storage of contaminated trash	visual inspection, real estate	None
33	33(2)HS	D3	1162.85	2	6066	potential for chemical storage	visual inspection, real estate	None
33	33(2)HS	D3	1162.85	2	6067	potential for chemical use	visual inspection, real estate	None
33	33(2)HS	D3	1162.85	2	6068	potential for chemical use	visual inspection, real estate	None
34	34(2)HS	D3	28.55	2	6050	potential for chemical storage	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
35	35(2)HS	D3	196.16	2	6053	potential for chemical storage	visual inspection, real estate	None
35	35(2)HS	D3	196.16	2	6055	potential for chemical storage	visual inspection, real estate	None
35	35(2)HS	D3	196.16	2	6056	potential for chemical use	visual inspection, real estate	None
36	36(2)HS	D3	128.60	2	6069	potential for chemical storage	visual inspection, real estate	None
37	37(2)HS	D3	426.04	2	6072	potential for chemical storage/use	visual inspection, real estate	None
37	37(2)HS	D3	426.04	2	6074	potential for chemical use	visual inspection, real estate	None
37	37(2)HS	D3	426.04	2	6075A	potential for chemical storage	visual inspection, real estate	None
37	37(2)HS	D3	426.04	2	6077B	potential for chemical storage	visual inspection, real estate	None
38	38(2)HS	D3	102.11	2	6091	potential for chemical storage	visual inspection, real estate	None
38	38(2)HS	D3	102.11	2	6092	potential for chemical storage	visual inspection, real estate	None
38	38(2)HS	D3	102.11	2	6093	potential for chemical storage	visual inspection, real estate	None
39	39(2)HS	E3	189.69	2	6142	potential for chemical use	visual inspection, real estate	None
40	40(2)HS	D3	163.22	2	6076	potential for chemical storage	visual inspection, real estate	None
40	40(2)HS	D3	163.22	2	6080	potential for chemical storage	visual inspection, real estate	None
41	41(2)HS	D3	15.04	2	6098	potential for chemical storage	visual inspection, real estate	None
42	42(2)HS	D3	479.09	2	6075B	potential chemical storage	visual inspection, real estate	None
42	42(2)HS	D3	479.09	2	6078	potential for chemical storage	visual inspection, real estate	None
42	42(2)HS	D3	479.09	2	6079	potential for chemical use	visual inspection, real estate	None
43	43(2)HS	D3	2017.05	2	6082	potential for chemical use	visual inspection, real estate	None
43	43(2)HS	D2	2017.05	2	6083	potential for chemical storage	visual inspection, real estate	None
43	43(2)HS	D2	2017.05	2	6083A	potential for chemical storage	visual inspection, real estate	None
43	43(2)HS	D3	2017.05	2	6084	potential for chemical storage	visual inspection, real estate	None
43	43(2)HS	D3	2017.05	2	6094A	potential chemical use	visual inspection, real estate	None
44	44(2)HS	D2	149.55	2	6107	potential for chemical storage	visual inspection, real estate	None
44	44(2)HS	D2	149.55	2	6108	potential for chemical storage	visual inspection, real estate	None
45	45(2)HS	E2	219.55	2	6126	potential for chemical storage	visual inspection, real estate	None
45	45(2)HS	E2	219.55	2	6127	potential for chemical storage	visual inspection, real estate	None
45	45(2)HS	E2	219.55	2	6129	potential for chemical storage	visual inspection, real estate	None
46	46(2)HS	D2	21.59	2	6111B	potential for chemical storage	visual inspection, real estate	None
47	47(2)HS	D2	418.36	2	6113	potential for chemical use	visual inspection, real estate	None
47	47(2)HS	D2	418.36	2	6115	potential for chemical storage	visual inspection, real estate	None
47	47(2)HS	D2	418.36	2	6116	potential for chemical storage	visual inspection, real estate	None
48	48(7)HR	E4	255.25	7	6021	Use of radioactive materials	Boatwright	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
49	49(2)HS	D3	23.19	2	6088	potential for chemical storage	visual inspection, real estate	None
50	50(2)HS	D3	13.12	2	6058	potential for chemical storage	visual inspection, real estate	None
51	51(2)HS	B4	109.92	2	5046	potential for chemical storage	visual inspection, real estate	None
51	51(2)HS	B4	109.92	2	5047	potential for chemical storage	visual inspection, real estate	None
52	52(2)HS	B4	359.74	2	5021	potential for chemical storage	visual inspection, real estate	None
52	52(2)HS	B4	359.74	2	5022	potential for chemical storage	visual inspection, real estate	None
52	52(2)HS	B4	359.74	2	5025	potential for chemical storage	visual inspection, real estate	None
53	53(2)HS	B4	918.11	2	5050	potential for chemical storage	visual inspection, real estate	None
53	53(2)HS	B4	918.11	2	5051	potential for chemical use	visual inspection, real estate	None
54	54(2)HS/PS	C4	1156.37	2	M5000	potential for chemical use	visual inspection, real estate	None
55	55(2)HS	B4	564.43	2	5013	potential for chemical storage in janitor closet	visual inspection, real estate	None
56	56(2)HS	B3	145.48	2	5008	always been library or porch	visual inspection, real estate	None
57	57(2)HS	B3	314.59	2	5063	potential for chemical use	visual inspection, real estate	None
58	58(2)HS	B3	231.37	2	5004	potential for chemical storage	visual inspection, real estate	None
59	59(2)HS	C3	1633.95	2	5000B	potential for chemical use	visual inspection, real estate	None
59	59(2)HS	C3	1633.95	2	5001	potential for chemical storage	visual inspection, real estate	None
59	59(2)HS	C3	1633.95	2	5002	potential for chemical storage	visual inspection, real estate	None
59	59(2)HS	C3	1633.95	2	5003	potential for chemical storage	visual inspection, real estate	None
59	59(2)HS	C3	1633.95	2	5005	potential for chemical use	visual inspection, real estate	None
59	59(2)HS	C3	1633.95	2	5006	potential for chemical use	visual inspection, real estate	None
59	59(2)HS	C3	1633.95	2	5007A	potential for chemical use	visual inspection, real estate	None
59	59(2)HS	B3	1633.95	2	5153	potential for chemical storage and use	visual inspection, real estate	None
59	59(2)HS	B3	1633.95	2	5154	potential for chemical storage and use	visual inspection, real estate	None
59	59(2)HS	B3	1633.95	2	5155	potential for chemical use	visual inspection, real estate	None
59	59(2)HS	B3	1633.95	2	5156	potential for chemical use	visual inspection, real estate	None
60	60(2)HS	B3	41.86	2	5065	potential for chemical storage	visual inspection, real estate	None
61	61(2)HS	A3	546.12	2	5071	potential for chemical use	visual inspection, real estate	None
61	61(2)HS	A3	546.12	2	5071B	potential for chemical use	visual inspection, real estate	None
62	62(2)HS	B3	571.99	2	5073	potential for chemical use	visual inspection, real estate	None
62	62(2)HS	B3	571.99	2	5073B	potential for chemical storage	visual inspection, real estate	None
63	63(2)HS	B3	508.38	2	5066A	potential for chemical use	visual inspection, real estate	None
63	63(2)HS	B3	508.38	2	5067A	potential for chemical use	visual inspection, real estate	None
63	63(2)HS	B3	508.38	2	5067C	potential for chemical use	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
64	64(2)HS	A3	405.35	2	5074	potential for chemical storage	visual inspection, real estate	None
64	64(2)HS	A3	405.35	2	5075	potential for chemical use	visual inspection, real estate	None
64	64(2)HS	A3	405.35	2	5076	potential for chemical use	visual inspection, real estate	None
65	65(2)HS	A3	499.41	2	5077	potential for chemical use	visual inspection, real estate	None
65	65(2)HS	A3	499.41	2	5077A	potential for chemical storage	visual inspection, real estate	None
65	65(2)HS	A3	499.41	2	5078	potential for chemical use	visual inspection, real estate	None
65	65(2)HS	A3	499.41	2	5079	potential for chemical use	visual inspection, real estate	None
66	66(2)HS	B3	101.33	2	5068	potential for chemical storage	visual inspection, real estate	None
66	66(2)HS	B3	101.33	2	5086	potential for chemical storage	visual inspection, real estate	None
67	67(2)HS	B3	463.63	2	5091B	potential for chemical use	visual inspection, real estate	None
68	68(2)HS	A3	69.39	2	5082	potential for chemical storage	visual inspection, real estate	None
69	69(2)HS/PS	A3	2495.10	2	5084	potential for chemical use	visual inspection, real estate	None
69	69(2)HS/PS	A3	2495.10	2	5085	potential for chemical use	visual inspection, real estate	None
69	69(2)HS/PS	B3	2495.10	2	5087	potential for chemical use	visual inspection, real estate	None
69	69(2)HS/PS	B3	2495.10	2	5088A	potential for chemical use	visual inspection, real estate	None
69	69(2)HS/PS	B3	2495.10	2	5089	potential for chemical storage	visual inspection, real estate	None
69	69(2)HS/PS	B3	2495.10	2	5090	potential for chemical use	visual inspection, real estate	None
70	70(2)HS	B3	193.18	2	5093	potential for chemical storage	visual inspection, real estate	None
71	71(2)HS	B3	20.11	2	5096	potential for chemical storage	visual inspection, real estate	None
72	72(2)HS	B2	22.37	2	5144A	potential for chemical storage	visual inspection, real estate	None
73	73(2)HS	B2	38.17	2	5139	potential for chemical storage	visual inspection, real estate	None
74	74(2)HS	B2	58.69	2	5107	potential for chemical storage	visual inspection, real estate	None
75	75(2)HS	B2	130.18	2	5128	potential for chemical storage	visual inspection, real estate	None
75	75(2)HS	B2	130.18	2	5129	potential for chemical storage	visual inspection, real estate	None
75	75(2)HS	B2	130.18	2	5130	potential for chemical storage	visual inspection, real estate	None
76	76(2)HS	B2	472.99	2	5109	potential for chemical use	visual inspection, real estate	None
76	76(2)HS	B2	472.99	2	5110	potential for chemical storage	visual inspection, real estate	None
76	76(2)HS	B2	472.99	2	5112	potential for chemical storage	visual inspection, real estate	None
76	76(2)HS	B2	472.99	2	5115	potential for chemical storage	visual inspection, real estate	None
77	77(2)HS	B1	515.34	2	5118	potential for chemical use	visual inspection, real estate	None
78	78(2)HS	B1	157.27	2	5121	potential for chemical storage	visual inspection, real estate	None
78	78(2)HS	B1	157.27	2	5122	potential for chemical storage	visual inspection, real estate	None
79	79(1)	B3	143.14	1	5088B	always been ward or office	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
80	80(1)	B3	33953.10	1	5000A	always been office and corridor	visual inspection, real estate	None
80	80(1)	C3	33953.10	1	5007B	always been patient room or library	visual inspection, real estate	None
80	80(1)	B4	33953.10	1	5009	always been office or bedroom	visual inspection, real estate	None
80	80(1)	B4	33953.10	1	5010	always been patient room	visual inspection, real estate	None
80	80(1)	B4	33953.10	1	5011	always been latrine	visual inspection, real estate	None
80	80(1)	B4	33953.10	1	5012	always been latrine	visual inspection, real estate	None
80	80(1)	B4	33953.10	1	5014	always been soiled linen	visual inspection, real estate	None
80	80(1)	B4	33953.10	1	5015	always been nourishment room or double room	visual inspection, real estate	None
80	80(1)	B4	33953.10	1	5016	always been patient lounge or porch	visual inspection, real estate	None
80	80(1)	C4	33953.10	1	5017	always been patient room	visual inspection, real estate	None
80	80(1)	C4	33953.10	1	5017A	always been latrine	visual inspection, real estate	None
80	80(1)	C4	33953.10	1	5018	always been patient room	visual inspection, real estate	None
80	80(1)	C4	33953.10	1	5018A	always been latrine	visual inspection, real estate	None
80	80(1)	B4	33953.10	1	5019	always been porch or room	visual inspection, real estate	None
80	80(1)	B4	33953.10	1	5020	always been oxygen storage or porch	visual inspection, real estate	None
80	80(1)	B4	33953.10	1	5023	always been breakroom or porch	visual inspection, real estate	None
80	80(1)	B4	33953.10	1	5024	always been latrine	visual inspection, real estate	None
80	80(1)	B5	33953.10	1	5026	always been patient room or porch	visual inspection, real estate	None
80	80(1)	B5	33953.10	1	5027	always been latrine or ward	visual inspection, real estate	None
80	80(1)	B5	33953.10	1	5028	always been patient room	visual inspection, real estate	None
80	80(1)	B5	33953.10	1	5029	always been latrine or ward	visual inspection, real estate	None
80	80(1)	B5	33953.10	1	5030	always been patient room	visual inspection, real estate	None
80	80(1)	B5	33953.10	1	5031	always been latrine or ward	visual inspection, real estate	None
80	80(1)	B5	33953.10	1	5032	always been dayroom or office	visual inspection, real estate	None
80	80(1)	B5	33953.10	1	5034	always been toilet or patient room	visual inspection, real estate	None
80	80(1)	B5	33953.10	1	5035	always been latrine	visual inspection, real estate	None
80	80(1)	B5	33953.10	1	5036	always been patient room	visual inspection, real estate	None
80	80(1)	B5	33953.10	1	5037	always been latrine or ward	visual inspection, real estate	None
80	80(1)	B5	33953.10	1	5038	always been patient room	visual inspection, real estate	None
80	80(1)	B5	33953.10	1	5039	always been patient room	visual inspection, real estate	None
80	80(1)	B5	33953.10	1	5040	always been latrine or ward	visual inspection, real estate	None
80	80(1)	B5	33953.10	1	5041	always been patient room	visual inspection, real estate	None
80	80(1)	B5	33953.10	1	5042	always been patient room	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
80	80(1)	B5	33953.10	1	5043	always been latrine or ward	visual inspection, real estate	None
80	80(1)	B5	33953.10	1	5044	always been patient room	visual inspection, real estate	None
80	80(1)	B4	33953.10	1	5045	always been patient room	visual inspection, real estate	None
80	80(1)	B4	33953.10	1	5048	always been linen or physician charting	visual inspection, real estate	None
80	80(1)	B4	33953.10	1	5049	always been nurses station	visual inspection, real estate	None
80	80(1)	B4	33953.10	1	5052	always been bedroom or tub room	visual inspection, real estate	None
80	80(1)	B4	33953.10	1	5053	always been bedroom or office	visual inspection, real estate	None
80	80(1)	B4	33953.10	1	5054	always been patient room	visual inspection, real estate	None
80	80(1)	B4	33953.10	1	5055	always been latrine	visual inspection, real estate	None
80	80(1)	B4	33953.10	1	5056	always been patient room	visual inspection, real estate	None
80	80(1)	B4	33953.10	1	5057	always been patient room	visual inspection, real estate	None
80	80(1)	B4	33953.10	1	5058	always been latrine	visual inspection, real estate	None
80	80(1)	B3	33953.10	1	5059	always been patient room	visual inspection, real estate	None
80	80(1)	B3	33953.10	1	5064	always been patient room	visual inspection, real estate	None
80	80(1)	B3	33953.10	1	5066	always been latrine	visual inspection, real estate	None
80	80(1)	B3	33953.10	1	5067B	always been porch/ward office or corridor	visual inspection, real estate	None
80	80(1)	B3	33953.10	1	5069	always been linen or electric room	visual inspection, real estate	None
80	80(1)	B3	33953.10	1	5070	potential for chemical use	visual inspection, real estate	None
80	80(1)	A3	33953.10	1	5071A	always been patient room	visual inspection, real estate	None
80	80(1)	B3	33953.10	1	5072	always been latrine or utility corridor/area	visual inspection, real estate	None
80	80(1)	B3	33953.10	1	5073A	always been patient room	visual inspection, real estate	None
80	80(1)	A3	33953.10	1	5080	always been locker room or room	visual inspection, real estate	None
80	80(1)	A3	33953.10	1	5081	always been patient room	visual inspection, real estate	None
80	80(1)	A3	33953.10	1	5081A	always been ward or latrine	visual inspection, real estate	None
80	80(1)	A3	33953.10	1	5083	always been ward or office	visual inspection, real estate	None
80	80(1)	B3	33953.10	1	5091A	always been porch or office	visual inspection, real estate	None
80	80(1)	B3	33953.10	1	5091C	always been porch or office	visual inspection, real estate	None
80	80(1)	B3	33953.10	1	5092	always been latrine	visual inspection, real estate	None
80	80(1)	B3	33953.10	1	5094	always been patient room or electric room	visual inspection, real estate	None
80	80(1)	B3	33953.10	1	5095	always been latrine	visual inspection, real estate	None
80	80(1)	B3	33953.10	1	5097	always been bedroom or office	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5098	always been bedroom or office	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5099	always been latrine	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
80	80(1)	B2	33953.10	1	5100	always been patient room	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5101	always been patient room	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5102	always been latrine	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5103	always been patient room	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5104	always been patient room	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5105	always been latrine	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5106	always been patient room	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5108A	always been serving kitchen or office	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5108B	always been kitchen	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5113	always been nurse station	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5114	always been clean linen	visual inspection, real estate	None
80	80(1)	B1	33953.10	1	5116	always been patient room	visual inspection, real estate	None
80	80(1)	B1	33953.10	1	5117	always been patient room	visual inspection, real estate	None
80	80(1)	B1	33953.10	1	5119	always been patient area	visual inspection, real estate	None
80	80(1)	B1	33953.10	1	5120	always been latrine	visual inspection, real estate	None
80	80(1)	B1	33953.10	1	5123	always been dayroom or office	visual inspection, real estate	None
80	80(1)	B1	33953.10	1	5124	always been patient room	visual inspection, real estate	None
80	80(1)	B1	33953.10	1	5124A	always been porch and patient area	visual inspection, real estate	None
80	80(1)	B1	33953.10	1	5125	always been patient room	visual inspection, real estate	None
80	80(1)	B1	33953.10	1	5125A	always been porch and patient area	visual inspection, real estate	None
80	80(1)	B1	33953.10	1	5126	always been patient room	visual inspection, real estate	None
80	80(1)	B1	33953.10	1	5126A	always been porch and patient area	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5131	always been latrine	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5132	always been patient room or office	visual inspection, real estate	None
80	80(1)	C2	33953.10	1	5133	always been latrine	visual inspection, real estate	None
80	80(1)	C2	33953.10	1	5134	always been patient room or office	visual inspection, real estate	None
80	80(1)	C2	33953.10	1	5134A	always been porch or room	visual inspection , real estate	None
80	80(1)	C2	33953.10	1	5134B	always been porch or room	visual inspection, real estate	None
80	80(1)	C2	33953.10	1	5135	always been patient room	visual inspection, real estate	None
80	80(1)	C2	33953.10	1	5136	always been latrine	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5137	always been patient room or lounge	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5138	always been soiled linen	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5140	always been latrine	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
80	80(1)	B2	33953.10	1	5141	always been latrine	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5142	always been corridor or patient room	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5144	always been patient room	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5144B	always been porch or patient room	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5145	always been patient room	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5145A	always been porch or patient room	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5146	always been latrine	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5147	always been patient room	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5147A	always been porch or patient room	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5148	always been patient room	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5148A	always been patient room	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5149	always been latrine	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5150	always been patient room	visual inspection, real estate	None
80	80(1)	B2	33953.10	1	5150A	always been patient room	visual inspection, real estate	None
80	80(1)	B3	33953.10	1	5151	always been office	visual inspection, real estate	None
80	80(1)	B3	33953.10	1	5152	always been lockers or report room	visual inspection, real estate	None
81	81(2)HS	B5	141.70	2	5033	potential for chemical storage	visual inspection, real estate	None
82	82(1)	B2	52.27	1	5111	always been latrine	visual inspection, real estate	None
83	83(1)	D4	35565.81	1	4004	always been patient room	visual inspection, real estate	None
83	83(1)	D4	35565.81	1	4006	always been porch or soiled linen	visual inspection, real estate	None
83	83(1)	D4	35565.81	1	4007	always been soiled linen	visual inspection, real estate	None
83	83(1)	E4	35565.81	1	4010	always been porch or oxygen storage	visual inspection, real estate	None
83	83(1)	E4	35565.81	1	4011	always been patient room	visual inspection, real estate	None
83	83(1)	E4	35565.81	1	4013	always been patient room	visual inspection, real estate	None
83	83(1)	E4	35565.81	1	4014	always been patient room	visual inspection, real estate	None
83	83(1)	E4	35565.81	1	4015	always been patient room	visual inspection, real estate	None
83	83(1)	E4	35565.81	1	4017	always been corridor	visual inspection, real estate	None
83	83(1)	E4	35565.81	1	4018	always been dayroom or office	visual inspection, real estate	None
83	83(1)	E4	35565.81	1	4019	always been dayroom or vestibule	visual inspection, real estate	None
83	83(1)	E4	35565.81	1	4020	always been dayroom/porch or soiled utility	visual inspection, real estate	None
83	83(1)	E4	35565.81	1	4021	always been porch or patient room	visual inspection, real estate	None
83	83(1)	E4	35565.81	1	4022	always been porch or patient room	visual inspection, real estate	None
83	83(1)	E4	35565.81	1	4023	always been double room or nurse's station	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
83	83(1)	E4	35565.81	1	4024	always been corridor or latrine	visual inspection, real estate	None
83	83(1)	E4	35565.81	1	4025	always been porch/double room or SRU	visual inspection, real estate	None
83	83(1)	E4	35565.81	1	4026	always been porch or nurse's station	visual inspection, real estate	None
83	83(1)	D4	35565.81	1	4027	always been patient room	visual inspection, real estate	None
83	83(1)	E4	35565.81	1	4028	always been porch or soiled utility room	visual inspection, real estate	None
83	83(1)	E4	35565.81	1	4029	always been porch or office	visual inspection, real estate	None
83	83(1)	E4	35565.81	1	4029	always been porch or office	visual inspection, real estate	None
83	83(1)	D5	35565.81	1	4030	always been ward or nurse station	visual inspection, real estate	None
83	83(1)	E5	35565.81	1	4031	always been porch or patient room	visual inspection, real estate	None
83	83(1)	E5	35565.81	1	4032	always been porch or patient room	visual inspection, real estate	None
83	83(1)	D5	35565.81	1	4034	always been ward or latrine	visual inspection, real estate	None
83	83(1)	D5	35565.81	1	4035	always been ward or nurses station	visual inspection, real estate	None
83	83(1)	E5	35565.81	1	4036	always been porch or patient room	visual inspection, real estate	None
83	83(1)	E5	35565.81	1	4037	always been dayroom or office	visual inspection, real estate	None
83	83(1)	D5	35565.81	1	4039	always been porch or oxygen storage	visual inspection, real estate	None
83	83(1)	D5	35565.81	1	4041	always been ward or conference room	visual inspection, real estate	None
83	83(1)	D5	35565.81	1	4042	always been ward of office	visual inspection, real estate	None
83	83(1)	D5	35565.81	1	4043	always been patient room	visual inspection, real estate	None
83	83(1)	D5	35565.81	1	4044	always been ward or latrine	visual inspection, real estate	None
83	83(1)	D5	35565.81	1	4045	always been patient room	visual inspection, real estate	None
83	83(1)	D5	35565.81	1	4046	always been patient room	visual inspection, real estate	None
83	83(1)	D4	35565.81	1	4047	always been patient room	visual inspection, real estate	None
83	83(1)	D4	35565.81	1	4048	always been ward or latrine	visual inspection, real estate	None
83	83(1)	D4	35565.81	1	4051	always been linen and nurses station	visual inspection, real estate	None
83	83(1)	D4	35565.81	1	4052	always been ward office or electric room	visual inspection, real estate	None
83	83(1)	D4	35565.81	1	4054	always been serving kitchen or locker	visual inspection, real estate	None
83	83(1)	D4	35565.81	1	4055	always been serving kitchen or locker	visual inspection, real estate	None
83	83(1)	D4	35565.81	1	4057	always been vent or oxygen storage	visual inspection, real estate	None
83	83(1)	D4	35565.81	1	4058	always been patient room	visual inspection, real estate	None
83	83(1)	D4	35565.81	1	4059	always been latrine	visual inspection, real estate	None
83	83(1)	D4	35565.81	1	4060	always been bedroom or office	visual inspection, real estate	None
83	83(1)	D4	35565.81	1	4061	always been bedroom or conference room	visual inspection, real estate	None
83	83(1)	D4	35565.81	1	4078	always been latrine	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
83	83(1)	D3	35565.81	1	4079	always been bedroom or office	visual inspection, real estate	None
83	83(1)	D3	35565.81	1	4081	always been bedroom or office	visual inspection, real estate	None
83	83(1)	D3	35565.81	1	4082	always been double room or lounge	visual inspection, real estate	None
83	83(1)	D3	35565.81	1	4083	always been locker room or dressing room	visual inspection, real estate	None
83	83(1)	D3	35565.81	1	4084	always been latrine	visual inspection, real estate	None
83	83(1)	D3	35565.81	1	4087	always been linen or office	visual inspection, real estate	None
83	83(1)	D3	35565.81	1	4122	always been latrine	visual inspection, real estate	None
83	83(1)	D3	35565.81	1	4122A	always been latrine	visual inspection, real estate	None
83	83(1)	D3	35565.81	1	4123	always been double room or latrine	visual inspection, real estate	None
83	83(1)	D3	35565.81	1	4124	always been double room or office	visual inspection, real estate	None
83	83(1)	D3	35565.81	1	4126	always been latrine	visual inspection, real estate	None
83	83(1)	D3	35565.81	1	4127	always been bedroom or office	visual inspection, real estate	None
83	83(1)	D2	35565.81	1	4128	always been bedroom or office	visual inspection, real estate	None
83	83(1)	D2	35565.81	1	4129	always been latrine	visual inspection, real estate	None
83	83(1)	D2	35565.81	1	4130	always been bedroom or office	visual inspection, real estate	None
83	83(1)	D2	35565.81	1	4131	always been bedroom or office	visual inspection, real estate	None
83	83(1)	D2	35565.81	1	4132	always been latrine	visual inspection, real estate	None
83	83(1)	D2	35565.81	1	4133	always been patient room	visual inspection, real estate	None
83	83(1)	D2	35565.81	1	4134	always been patient room	visual inspection, real estate	None
83	83(1)	D2	35565.81	1	4135	always been latrine	visual inspection, real estate	None
83	83(1)	D2	35565.81	1	4136	always been bedroom or office	visual inspection, real estate	None
83	83(1)	D2	35565.81	1	4137	always been kitchen	visual inspection, real estate	None
83	83(1)	D2	35565.81	1	4138A	always been kitchen or office	visual inspection, real estate	None
83	83(1)	D2	35565.81	1	4143	always been nurse station	visual inspection, real estate	None
83	83(1)	D2	35565.81	1	4144	always been linen	visual inspection, real estate	None
83	83(1)	D1	35565.81	1	4146B	always been ward or nurse room	visual inspection, real estate	None
83	83(1)	D1	35565.81	1	4147	always been patient room	visual inspection, real estate	None
83	83(1)	D1	35565.81	1	4148	always been patient room	visual inspection, real estate	None
83	83(1)	D1	35565.81	1	4149	always been patient room	visual inspection, real estate	None
83	83(1)	D1	35565.81	1	4150	always been latrine	visual inspection, real estate	None
83	83(1)	E1	35565.81	1	4153	always been dayroom or office	visual inspection, real estate	None
83	83(1)	D1	35565.81	1	4154	always been patient room	visual inspection, real estate	None
83	83(1)	D1	35565.81	1	4155	always been patient room	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
83	83(1)	D1	35565.81	1	4156	always been patient room	visual inspection, real estate	None
83	83(1)	D1	35565.81	1	4157	always been ward or nurse station	visual inspection, real estate	None
83	83(1)	D3	35565.81	1	4159	always been phone booth	visual inspection, real estate	None
83	83(1)	E2	35565.81	1	4161	always been patient room or office	visual inspection, real estate	None
83	83(1)	E2	35565.81	1	4162	always been latrine	visual inspection, real estate	None
83	83(1)	E1	35565.81	1	4163	always been office or porch	visual inspection, real estate	None
83	83(1)	E2	35565.81	1	4164	always been patient room	visual inspection, real estate	None
83	83(1)	E2	35565.81	1	4164A	always been porch or patient room	visual inspection, real estate	None
83	83(1)	E2	35565.81	1	4164B	always been latrine	visual inspection, real estate	None
83	83(1)	E2	35565.81	1	4165	always been patient room	visual inspection, real estate	None
83	83(1)	E2	35565.81	1	4165A	always been porch or patient room	visual inspection, real estate	None
83	83(1)	E2	35565.81	1	4166	always been latrine	visual inspection, real estate	None
83	83(1)	E2	35565.81	1	4167	always been patient room	visual inspection, real estate	None
83	83(1)	E2	35565.81	1	4167A	always been porch or patient room	visual inspection, real estate	None
83	83(1)	E2	35565.81	1	4168	always been dayroom or EEG lab	visual inspection, real estate	None
83	83(1)	E2	35565.81	1	4169	always been patient room or office	visual inspection, real estate	None
83	83(1)	E2	35565.81	1	4171	always been latrine	visual inspection, real estate	None
83	83(1)	E2	35565.81	1	4172	always been patient room or medical testing	visual inspection, real estate	None
83	83(1)	E2	35565.81	1	4173	always been latrine	visual inspection, real estate	None
83	83(1)	E2	35565.81	1	4174	always been patient room or waiting room	visual inspection, real estate	None
83	83(1)	E2	35565.81	1	4176A	always been latrine	visual inspection, real estate	None
83	83(1)	E2	35565.81	1	4177	always been porch or oxygen room	visual inspection, real estate	None
83	83(1)	D2	35565.81	1	4179	always been soiled linen	visual inspection, real estate	None
83	83(1)	E2	35565.81	1	4180	always been latrine	visual inspection, real estate	None
83	83(1)	E2	35565.81	1	4184	always been latrine	visual inspection, real estate	None
83	83(1)	D2	35565.81	1	4185	always been bedroom or office	visual inspection, real estate	None
83	83(1)	D2	35565.81	1	4187	always been latrine	visual inspection, real estate	None
83	83(1)	D2	35565.81	1	4188	always been bedroom or office	visual inspection, real estate	None
83	83(1)	D2	35565.81	1	4190	always been latrine	visual inspection, real estate	None
83	83(1)	D2	35565.81	1	4191	always been bedroom or office	visual inspection, real estate	None
83	83(1)	E3	35565.81	1	4192	always been office	visual inspection, real estate	None
83	83(1)	E3	35565.81	1	4193	always been latrine	visual inspection, real estate	None
83	83(1)	E3	35565.81	1	4194	always been office	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
83	83(1)	E3	35565.81	1	4195	always been office	visual inspection, real estate	None
83	87(2)HS	E3	3011.61	2	4196	potential for chemical use	visual inspection, real estate	None
83	83(1)	D3	35565.81	1	4197	always been waiting space or office	visual inspection, real estate	None
84	84(2)HS	E4	77.53	2	4016	potential for chemical storage	visual inspection, real estate	None
85	85(2)HS	D4	242.31	2	4053	potential for chemical use	visual inspection, real estate	None
86	86(2)HS	E4	206.76	2	4012	potential for chemical storage	visual inspection, real estate	None
87	87(2)HS	E3	3011.61	2	4000	potential for chemical use	visual inspection, real estate	None
87	87(2)HS	E3	3011.61	2	4001	potential for chemical use	visual inspection, real estate	None
87	87(2)HS	E3	3011.61	2	4002	potential for chemical storage	visual inspection, real estate	None
87	87(2)HS	E3	3011.61	2	4003	potential for chemical use	visual inspection, real estate	None
87	87(2)HS	D4	3011.61	2	4005	potential for chemical storage	visual inspection, real estate	None
87	87(2)HS	D4	3011.61	2	4008	potential for chemical storage	visual inspection, real estate	None
87	87(2)HS	E4	3011.61	2	4009	potential for chemical storage	visual inspection, real estate	None
88	88(2)HS	D4	115.45	2	4077	potential for chemical use	visual inspection, real estate	None
89	89(2)HS	D3	131.52	2	4080	potential for chemical storage	visual inspection, real estate	None
90	90(2)HS	E4	24.13	2	4023A	potential for chemical use	visual inspection, real estate	None
91	91(2)HS	D3	1479.17	2	4085	potential for chemical use	visual inspection, real estate	None
91	91(2)HS	D3	1479.17	2	4086	potential for chemical storage	visual inspection, real estate	None
91	91(2)HS	D3	1479.17	2	4088	potential for chemical storage	visual inspection, real estate	None
91	91(2)HS	D3	1479.17	2	4089	potential for chemical storage	visual inspection, real estate	None
91	91(2)HS	D3	1479.17	2	4090	potential for chemical use	visual inspection, real estate	None
91	91(2)HS	D3	1479.17	2	4091	potential for chemical storage	visual inspection, real estate	None
91	91(2)HS	D3	1479.17	2	4092	potential for chemical storage	visual inspection, real estate	None
91	91(2)HS	D3	1479.17	2	4093	potential for chemical use	visual inspection, real estate	None
92	92(2)HS	D3	4102.01	2	4094	potential for chemical use	visual inspection, real estate	None
92	92(2)HS	C3	4102.01	2	4095	potential for chemical use	visual inspection, real estate	None
92	92(2)HS	C3	4102.01	2	4096	potential for chemical use	visual inspection, real estate	None
92	92(2)HS	C3	4102.01	2	4097	potential for chemical storage	visual inspection, real estate	None
92	92(2)HS	C3	4102.01	2	4098	potential for chemical storage	visual inspection, real estate	None
92	92(2)HS	D3	4102.01	2	4099	potential for chemical storage	visual inspection, real estate	None
92	92(2)HS	D3	4102.01	2	4100	potential for chemical use	visual inspection, real estate	None
92	92(2)HS	D3	4102.01	2	4101	potential for chemical storage	visual inspection, real estate	None
92	92(2)HS	D3	4102.01	2	4102	potential for chemical storage	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
92	92(2)HS	C3	4102.01	2	4103	potential for chemical use	visual inspection, real estate	None
92	92(2)HS	C3	4102.01	2	4104	potential for chemical use	visual inspection, real estate	None
92	92(2)HS	C3	4102.01	2	4105	potential for chemical use	visual inspection, real estate	None
92	92(2)HS	D3	4102.01	2	4106	potential for chemical storage	visual inspection, real estate	None
92	92(2)HS	C3	4102.01	2	4107	potential for chemical storage	visual inspection, real estate	None
92	92(2)HS	C3	4102.01	2	4108	potential for chemical use	visual inspection, real estate	None
92	92(2)HS	C3	4102.01	2	4109	potential for chemical storage	visual inspection, real estate	None
92	92(2)HS	D3	4102.01	2	4110	potential for chemical use	visual inspection, real estate	None
92	92(2)HS	D3	4102.01	2	4111	potential for chemical storage	visual inspection, real estate	None
92	92(2)HS	C3	4102.01	2	4112	potential for chemical use	visual inspection, real estate	None
92	92(2)HS	D2	4102.01	2	4113	potential for chemical storage	visual inspection, real estate	None
94	94(2)HS/PS	D2	2949.90	2	4114A	potential for chemical use	visual inspection, real estate	None
94	94(2)HS/PS	D3	2949.90	2	4114B	potential for chemical storage	visual inspection, real estate	None
94	94(2)HS/PS	D3	2949.90	2	4115	potential for chemical storage	visual inspection, real estate	None
94	94(2)HS/PS	D3	2949.90	2	4116	potential for chemical storage	visual inspection, real estate	None
94	94(2)HS/PS	D3	2949.90	2	4117	potential for chemical storage	visual inspection, real estate	None
94	94(2)HS/PS	D3	2949.90	2	4118	potential for chemical storage	visual inspection, real estate	None
94	94(2)HS/PS	D3	2949.90	2	4118A	potential for chemical storage	visual inspection, real estate	None
94	94(2)HS/PS	D3	2949.90	2	4119	potential for chemical storage	visual inspection, real estate	None
94	94(2)HS/PS	D3	2949.90	2	4121	potential for chemical storage	visual inspection, real estate	None
95	95(2)HS	D3	24.75	2	4125	potential for chemical storage	visual inspection, real estate	None
96	96(2)HS	E2	1279.68	2	4178	potential for chemical use	visual inspection, real estate	None
96	96(2)HS	E2	1279.68	2	4185A	potential for chemical storage	visual inspection, real estate	None
96	96(2)HS	D2	1279.68	2	4186	potential for chemical storage	visual inspection, real estate	None
96	96(2)HS	D2	1279.68	2	4189	potential for chemical storage	visual inspection, real estate	None
96	96(2)HS	E2	1279.68	2	4189A	potential for chemical storage	visual inspection, real estate	None
97	97(2)HS	D2	14.42	2	4182	potential for chemical storage	visual inspection, real estate	None
97	97(2)HS	D2	14.42	2	4183	potential for chemical storage	visual inspection, real estate	None
98	98(2)HS	D2	19.61	2	4138	potential for chemical storage	visual inspection, real estate	None
99	99(2)HS	D2	28.12	2	4181	potential for chemical storage	visual inspection, real estate	None
100	100(2)HS	E2	102.90	2	4175	potential for chemical storage	visual inspection, real estate	None
101	101(7)HR	E2	222.89	7	4176	potential for chemical use	visual inspection, real estate	None
102	102(2)HS	E2	16.43	2	4170	potential for chemical storage	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
103	103(2)HS	D3	60.95	2	4160	potential for chemical storage	visual inspection, real estate	None
104	104(2)HS	D2	541.49	2	4139	potential for chemical use	visual inspection, real estate	None
104	104(2)HS	D2	541.49	2	4141	potential for chemical storage	visual inspection, real estate	None
104	104(2)HS	D2	541.49	2	4142	potential for chemical storage	visual inspection, real estate	None
104	104(2)HS	D2	541.49	2	4145	potential for chemical storage	visual inspection, real estate	None
104	104(2)HS	D2	541.49	2	4146A	potential for chemical storage	visual inspection, real estate	None
105	105(2)HS	D3	33.23	2	4158	potential for chemical storage	visual inspection, real estate	None
106	106(2)HS	D1	142.89	2	4151	potential for chemical storage	visual inspection, real estate	None
106	106(2)HS	D1	142.89	2	4152	potential for chemical storage	visual inspection, real estate	None
107	107(1)	D2	43.68	1	4140	always been latrine	visual inspection, real estate	None
108	108(2)HS	D5	452.75	2	4038	potential for chemical storage	visual inspection, real estate	None
108	108(2)HS	D5	452.75	2	4040	potential for chemical storage	visual inspection, real estate	None
109	109(2)HS	D5	87.24	2	4033	potential for chemical storage	visual inspection, real estate	None
110	110(2)HS	D4	189.35	2	4049	potential for chemical storage	visual inspection, real estate	None
112	112(2)HS	B4	616.90	2	3058	potential for chemical storage	visual inspection, real estate	None
112	112(2)HS	B4	616.90	2	3060	potential for chemical storage and use	visual inspection, real estate	None
113	113(2)HS	B5	507.74	2	3052	potential for chemical use	visual inspection, real estate	None
113	113(2)HS	B4	507.74	2	3053	potential for chemical use	visual inspection, real estate	None
113	113(2)HS	B4	507.74	2	3054	potential for chemical storage	visual inspection, real estate	None
113	113(2)HS	B4	507.74	2	3055	potential for chemical storage	visual inspection, real estate	None
114	114(2)HS	C4	84.60	2	3024	potential for chemical storage	visual inspection, real estate	None
115	115(2)HS	B4	606.31	2	3013	potential for chemical storage	visual inspection, real estate	None
115	115(2)HS	B4	606.31	2	3015	potential for chemical storage	visual inspection, real estate	None
116	116(2)HS	B4	106.70	2	3040	potential for chemical storage	visual inspection, real estate	None
117	117(2)HS	B3	22.21	2	3074	potential for chemical storage	visual inspection, real estate	None
118	118(2)HS	C3	1383.64	2	3000	potential for chemical storage	visual inspection, real estate	None
118	118(2)HS	C3	1383.64	2	3001	potential for chemical storage	visual inspection, real estate	None
118	118(2)HS	C3	1383.64	2	3002	potential for chemical use	visual inspection, real estate	None
118	118(2)HS	C3	1383.64	2	3003	potential for chemical use	visual inspection, real estate	None
118	118(2)HS	C3	1383.64	2	3004	potential for chemical use	visual inspection, real estate	None
118	118(2)HS	B3	1383.64	2	3207	former x-ray room - chemical use	visual inspection, real estate	None
118	118(2)HS	C3	1383.64	2	3208	potential for chemical use	visual inspection, real estate	None
118	118(2)HS	C3	1383.64	2	3209	potential for chemical use	real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
119	119(2)HS	B3	28.34	2	3077	potential for chemical storage	visual inspection, real estate	None
120	120(2)HS/PS	B3	1557.25	2	3141	potential for chemical use	visual inspection, real estate	None
121	121(2)HS	C2	41.20	2	3189	potential for chemical storage	visual inspection, real estate	None
122	122(2)HS	B3	394.21	2	3137	potential for chemical storage	visual inspection, real estate	None
123	123(2)HS	B2	728.66	2	3151	potential for chemical storage	visual inspection, real estate	None
124	124(2)HS	B2	389.67	2	3157	potential for chemical storage	visual inspection, real estate	None
124	124(2)HS	B2	389.67	2	3158	potential for chemical storage	visual inspection, real estate	None
124	124(2)HS	B2	389.67	2	3159	potential for chemical storage	visual inspection, real estate	None
125	125(2)HS	B2	165.69	2	3172	potential for chemical storage	visual inspection, real estate	None
126	126(2)HS	B2	105.10	2	3174	potential for medical storage	visual inspection, real estate	None
127	127(2)HS	B1	23.61	2	3161B	potential for chemical storage	visual inspection, real estate	None
128	128(2)HS	B1	35.38	2	3162B	potential for chemical storage	visual inspection, real estate	None
129	129(2)HS	B1	77.60	2	3165	potential for chemical storage	visual inspection, real estate	None
129	129(2)HS	B1	77.60	2	3166	potential for chemical storage	visual inspection, real estate	None
130	130(7)HR	B3	9520.24	7	3079	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B3	9520.24	7	3080	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B3	9520.24	7	3082	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B4	9520.24	7	3083	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B3	9520.24	7	3084A	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B3	9520.24	7	3084B	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B3	9520.24	7	3084C	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B3	9520.24	7	3085A	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B3	9520.24	7	3085B	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B4	9520.24	7	3086	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	A4	9520.24	7	3087	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	A3	9520.24	7	3089	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	A4	9520.24	7	3090	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	A3	9520.24	7	3092	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B3	9520.24	7	3092A	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	A3	9520.24	7	3095	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	A3	9520.24	7	3096	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	A3	9520.24	7	3100	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	A3	9520.24	7	3101	chemical use	Errett, Neeper, Boatwright	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
130	130(7)HR	A3	9520.24	7	3102	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	A3	9520.24	7	3104	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B3	9520.24	7	3107	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	A3	9520.24	7	3108	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	A3	9520.24	7	3109	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B3	9520.24	7	3110	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	A3	9520.24	7	3111	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	A3	9520.24	7	3113	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	A3	9520.24	7	3113A	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B3	9520.24	7	3113B	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	A3	9520.24	7	3114	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	A3	9520.24	7	3116	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B3	9520.24	7	3117	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	A2	9520.24	7	3118	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	A3	9520.24	7	3118A	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	A2	9520.24	7	3118B	radiological storage	Errett, Neeper, Boatwright	None
130	130(7)HR	B2	9520.24	7	3123	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B2	9520.24	7	3123A	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B3	9520.24	7	3127	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B3	9520.24	7	3128	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B3	9520.24	7	3129	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B3	9520.24	7	3130	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B3	9520.24	7	3130A	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B3	9520.24	7	3131A	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B3	9520.24	7	3131B	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B3	9520.24	7	3132	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B3	9520.24	7	3133	chemical use	Errett, Neeper, Boatwright	None
130	130(7)HR	B3	9520.24	7	3135	chemical use	Errett, Neeper, Boatwright	None
131	131(1)	C3	32656.85	1	3005	always been latrine	visual inspection, real estate	None
131	131(1)	B3	32656.85	1	3006	always been office	visual inspection, real estate	None
131	131(1)	B3	32656.85	1	3006A	always been porch or office	visual inspection, real estate	None
131	131(1)	B3	32656.85	1	3007	always been reception	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3008	always been bedroom or conference room	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
131	131(1)	B4	32656.85	1	3009	always been latrine	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3010	always been patient room or porch	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3011	always been porch or bedroom	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3012	always been latrine	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3014	always been latrine	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3019	always been soiled linen	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3020	always been patient room or charting room	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3021	always been patient room or playroom	visual inspection, real estate	None
131	131(1)	C4	32656.85	1	3022	always been latrine	visual inspection, real estate	None
131	131(1)	C4	32656.85	1	3023	always been patient room	visual inspection, real estate	None
131	131(1)	C4	32656.85	1	3025	always been patient room	visual inspection, real estate	None
131	131(1)	C4	32656.85	1	3026	always been latrine or office	visual inspection, real estate	None
131	131(1)	C4	32656.85	1	3027	always been double room or storage	visual inspection, real estate	None
131	131(1)	C4	32656.85	1	3028	always been patient room or office	visual inspection, real estate	None
131	131(1)	C4	32656.85	1	3029	always been latrine or office	visual inspection, real estate	None
131	131(1)	C4	32656.85	1	3030	always been patient room or office	visual inspection, real estate	None
131	131(1)	C4	32656.85	1	3030A	always been patient room	visual inspection, real estate	None
131	131(1)	C4	32656.85	1	3030B	always been porch or patient room	visual inspection, real estate	None
131	131(1)	C4	32656.85	1	3031	always been dayroom	visual inspection, real estate	None
131	131(1)	C4	32656.85	1	3032	always been patient room or office	visual inspection, real estate	None
131	131(1)	C4	32656.85	1	3032A	always been porch or patient room	visual inspection, real estate	None
131	131(1)	C4	32656.85	1	3032B	always been porch or patient room	visual inspection, real estate	None
131	131(1)	C4	32656.85	1	3033	always been latrine	visual inspection, real estate	None
131	131(1)	C4	32656.85	1	3034B	always been patient room or office	visual inspection, real estate	None
131	131(1)	C4	32656.85	1	3035	always been patient room	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3036	always been latrine	visual inspection, real estate	None
131	131(1)	C4	32656.85	1	3037	always been latrine	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3038	always been patient room	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3039	always been litter/bedscreens and nurse station	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3041	always been porch or patient room	visual inspection, real estate	None
131	131(1)	B5	32656.85	1	3041A	always been porch or patient room	visual inspection, real estate	None
131	131(1)	B5	32656.85	1	3042	always been porch or latrine	visual inspection, real estate	None
131	131(1)	B5	32656.85	1	3043	always been ward or station	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
131	131(1)	B5	32656.85	1	3044	always been patient room	visual inspection, real estate	None
131	131(1)	B5	32656.85	1	3045	always been patient room	visual inspection, real estate	None
131	131(1)	B5	32656.85	1	3045A	always been patient room	visual inspection, real estate	None
131	131(1)	B5	32656.85	1	3045B	always been patient room	visual inspection, real estate	None
131	131(1)	B5	32656.85	1	3046A	always been dayroom or vestibule	visual inspection, real estate	None
131	131(1)	B5	32656.85	1	3047	always been latrine or office	visual inspection, real estate	None
131	131(1)	B5	32656.85	1	3047A	always been latrine or patient room	visual inspection, real estate	None
131	131(1)	B5	32656.85	1	3048	always been patient room	visual inspection, real estate	None
131	131(1)	B5	32656.85	1	3048A	always been latrine	visual inspection, real estate	None
131	131(1)	B5	32656.85	1	3048B	always been latrine or oxygen room	visual inspection, real estate	None
131	131(1)	B5	32656.85	1	3049	always been patient room	visual inspection, real estate	None
131	131(1)	B5	32656.85	1	3050	always been patient room	visual inspection, real estate	None
131	131(1)	B5	32656.85	1	3050A	always been patient room	visual inspection, real estate	None
131	131(1)	B5	32656.85	1	3051	always been ward or office	visual inspection, real estate	None
131	131(1)	B5	32656.85	1	3051A	always been ward or linen room	visual inspection, real estate	None
131	131(1)	B5	32656.85	1	3051B	always been ward or office	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3056	always been nurse station or nourishment center	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3057	always been office	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3059	always been latrine	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3062	always been duct space or electric room	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3063	always been patient room	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3064	always been latrine	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3065	always been latrine or patient room	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3066	always been patient room	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3067	always been latrine	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3068	always been patient room	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3069	always been patient room	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3070	always been latrine	visual inspection, real estate	None
131	131(1)	B4	32656.85	1	3071	always been patient room	visual inspection, real estate	None
131	131(1)	B3	32656.85	1	3072	always been bedroom or office	visual inspection, real estate	None
131	131(1)	B3	32656.85	1	3073	always been latrine	visual inspection, real estate	None
131	131(1)	B3	32656.85	1	3075	always been patient room	visual inspection, real estate	None
131	131(1)	B3	32656.85	1	3078	always been latrine	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
131	131(1)	B3	32656.85	1	3136	always been latrine	visual inspection, real estate	None
131	131(1)	B2	32656.85	1	3140	always been patient or office	visual inspection, real estate	None
131	131(1)	B2	32656.85	1	3142	always been patient room	visual inspection, real estate	None
131	131(1)	B2	32656.85	1	3143	always been latrine	visual inspection, real estate	None
131	131(1)	B2	32656.85	1	3144	always been patient room	visual inspection, real estate	None
131	131(1)	B2	32656.85	1	3145	always been patient room	visual inspection, real estate	None
131	131(1)	B2	32656.85	1	3146	always been latrine	visual inspection, real estate	None
131	131(1)	B2	32656.85	1	3147	always been patient room	visual inspection, real estate	None
131	131(1)	B2	32656.85	1	3148	always been patient room or office	visual inspection, real estate	None
131	131(1)	B2	32656.85	1	3150	always been latrine or patient room	visual inspection, real estate	None
131	131(1)	B2	32656.85	1	3152	always been duct space	visual inspection, real estate	None
131	131(1)	B2	32656.85	1	3156	always been office	visual inspection, real estate	None
131	131(1)	B1	32656.85	1	3160	always been ward or nourishment center	visual inspection, real estate	None
131	131(1)	B1	32656.85	1	3161	always been patient room	visual inspection, real estate	None
131	131(1)	B1	32656.85	1	3161A	always been ward or latrine	visual inspection, real estate	None
131	131(1)	B1	32656.85	1	3162	always been patient room	visual inspection, real estate	None
131	131(1)	B1	32656.85	1	3162A	always been ward or latrine	visual inspection, real estate	None
131	131(1)	B1	32656.85	1	3163	always been patient room	visual inspection, real estate	None
131	131(1)	B1	32656.85	1	3163A	always been ward or latrine	visual inspection, real estate	None
131	131(1)	B1	32656.85	1	3163B	always been ward or ante room	visual inspection, real estate	None
131	131(1)	B1	32656.85	1	3164	always been latrine or patient room	visual inspection, real estate	None
131	131(1)	B1	32656.85	1	3167	always been dayroom or conference room	visual inspection, real estate	None
131	131(1)	B1	32656.85	1	3168	always been patient room	visual inspection, real estate	None
131	131(1)	B1	32656.85	1	3168A	always been ward or nurse station	visual inspection, real estate	None
131	131(1)	B1	32656.85	1	3169	alwyas been patient room	visual inspection, real estate	None
131	131(1)	B1	32656.85	1	3170	always been porch or patient room	visual inspection, real estate	None
131	131(1)	B1	32656.85	1	3170A	always been ward or latrine	visual inspection, real estate	None
131	131(1)	B1	32656.85	1	3171	always been ward or nurse station	visual inspection, real estate	None
131	131(1)	B2	32656.85	1	3173	always been litters and bedscreens and lounge	visual inspection, real estate	None
131	131(1)	B2	32656.85	1	3175	always been porch or latrine	visual inspection, real estate	None
131	131(1)	B2	32656.85	1	3176	always been patient room or nurse station	visual inspection, real estate	None
131	131(1)	C2	32656.85	1	3177	always been latrine	visual inspection, real estate	None
131	131(1)	C2	32656.85	1	3178	always been porch or office	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
131	131(1)	C2	32656.85	1	3179	always been patient room	visual inspection, real estate	None
131	131(1)	C2	32656.85	1	3180	always been patient room	visual inspection, real estate	None
131	131(1)	C2	32656.85	1	3180A	always been double room or nurse station	visual inspection, real estate	None
131	131(1)	C2	32656.85	1	3181	always been patient room	visual inspection, real estate	None
131	131(1)	C2	32656.85	1	3182	always been dayroom or office	visual inspection, real estate	None
131	131(1)	C2	32656.85	1	3184	always been patient room	visual inspection, real estate	None
131	131(1)	C2	32656.85	1	3185	always been latrine	visual inspection, real estate	None
131	131(1)	C2	32656.85	1	3186	always been patient room	visual inspection, real estate	None
131	131(1)	C2	32656.85	1	3186A	always been latrine	visual inspection, real estate	None
131	131(1)	C2	32656.85	1	3187	always been patient room or oxygen storage	visual inspection, real estate	None
131	131(1)	C2	32656.85	1	3188	always been patient room	visual inspection, real estate	None
131	131(1)	C2	32656.85	1	3188A	always been latrine	visual inspection, real estate	None
131	131(1)	C2	32656.85	1	3190	always been patient room or linen storage	visual inspection, real estate	None
131	131(1)	C2	32656.85	1	3191	always been latrine or soiled utility	visual inspection, real estate	None
131	131(1)	C2	32656.85	1	3192	always been porch/double room or office	visual inspection, real estate	None
131	131(1)	B2	32656.85	1	3193	always been patient room or locker room	visual inspection, real estate	None
131	131(1)	B2	32656.85	1	3194	always been soiled linen	visual inspection, real estate	None
131	131(1)	B2	32656.85	1	3200	always been patient room	visual inspection, real estate	None
131	131(1)	B2	32656.85	1	3201	always been patient room or nurse station	visual inspection, real estate	None
131	131(1)	B2	32656.85	1	3204	always been patient room/porch	visual inspection, real estate	None
131	131(1)	B2	32656.85	1	3205	always been porch or ante room	visual inspection, real estate	None
131	131(1)	B2	32656.85	1	3206	always been porch or isolation room	visual inspection, real estate	None
131	131(1)	B3	32656.85	1	3206A	always been waiting space or office	visual inspection, real estate	None
131	131(1)	B3	32656.85	1	3206B	always been waiting space or office	visual inspection, real estate	None
132	132(2)HS	B5	125.47	2	3046	potential for chemical storage	visual inspection, real estate	None
132	132(2)HS	B5	125.47	2	3047B	potential for chemical storage	visual inspection, real estate	None
133	133(2)HS	B5	278.44	2	3046B	potential for chemical storage	visual inspection, real estate	None
133	133(2)HS	B5	278.44	2	3046C	potential for chemical storage	visual inspection, real estate	None
134	134(2)HS	B2	76.31	2	3195	potential for chemical storage	visual inspection, real estate	None
135	135(2)HS	C4	422.66	2	3033A	potential for chemical storage	visual inspection, real estate	None
135	135(2)HS	C4	422.66	2	3034	potential for chemical storage	visual inspection, real estate	None
136	136(7)HR	C2	119.83	7	3183	always been corridor or benign storage	visual inspection, real estate	None
137	137(2)HS	E2	25.78	2	2176	potential for chemical storage	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
138	138(7)HS	E2	97.72	7	2173	potential for chemical storage	visual inspection, real estate	None
139	139(2)HS	D2	83.45	2	2228	potential for chemical storage	visual inspection, real estate	None
140	140(2)HS	D1	121.72	2	2223	potential for chemical use	visual inspection, real estate	None
141	141(7)HR	D2	340.96	7	2202W	radionuclide use	Boatwright	None
142	142(2)HS	D2	370.53	2	2200W	potential for chemical storage	visual inspection, real estate	None
142	142(2)HS	D1	370.53	2	2201W	potential for chemical use	visual inspection, real estate	None
143	143(2)HS	D1	110.96	2	2207	potential for chemical use	visual inspection, real estate	None
144	144(2)HS	D1	106.37	2	2209	potential for chemical use	visual inspection, real estate	None
145	145(2)HS	D1	89.25	2	2213	potential for chemical storage	visual inspection, real estate	None
146	146(7)HR	E3	18071.14	7	2005	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2006	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D3	18071.14	7	2006A	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2007	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2008A	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2008B	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2009	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2010	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2011	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2012	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2013	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2014	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2015	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2016	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2017	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2018	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2019	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2020	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2021	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2022	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2023	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2024	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2025	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2026	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
146	146(7)HR	E4	18071.14	7	2027	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2028	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2029	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2030	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2031	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2032	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2033	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2034	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2035	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2036	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2037	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2038	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2039	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2040	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2041	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2042	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2043	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2044	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2045	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2046	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E4	18071.14	7	2047	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E5	18071.14	7	2048	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D5	18071.14	7	2049	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E5	18071.14	7	2050	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D5	18071.14	7	2051	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E5	18071.14	7	2052	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D5	18071.14	7	2053	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D5	18071.14	7	2054	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E5	18071.14	7	2055	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	E5	18071.14	7	2056A	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D5	18071.14	7	2056B	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D5	18071.14	7	2057	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D5	18071.14	7	2058	radionuclide use	Errett, Neeper, Boatwright	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
146	146(7)HR	D5	18071.14	7	2059	radionuclide use	Errett, Neeper, Boatwright	None
146	146(7)HR	D5	18071.14	7	2060	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D5	18071.14	7	2061	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D5	18071.14	7	2062	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D5	18071.14	7	2063	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D5	18071.14	7	2064	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D5	18071.14	7	2065	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D5	18071.14	7	2066	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D5	18071.14	7	2067	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D5	18071.14	7	2068	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2069	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2070	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2071	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2072	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2073	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2074	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2075	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2076	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2077	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2078	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2079	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2080	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2081	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2082	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D4	18071.14	7	2083	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D3	18071.14	7	2084	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D3	18071.14	7	2085	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D3	18071.14	7	2086	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D3	18071.14	7	2087	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
146	146(7)HR	D3	18071.14	7	2090	numerous spills	Errett, Neeper, Boatwright	Spills cleaned up
147	147(7)HR	D3	13199.39	7	2094	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	D3	13199.39	7	2095	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	D3	13199.39	7	2096	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
147	147(7)HR	D3	13199.39	7	2097	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	D3	13199.39	7	2098	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	D3	13199.39	7	2099	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	D3	13199.39	7	2100	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	D3	13199.39	7	2101	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	C3	13199.39	7	2101A	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	C3	13199.39	7	2101B	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	D3	13199.39	7	2101C	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	C3	13199.39	7	2103	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	C3	13199.39	7	2104	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	C3	13199.39	7	2104A	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	C3	13199.39	7	2105	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	C3	13199.39	7	2105A	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	C3	13199.39	7	2105B	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	C3	13199.39	7	2106	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	C3	13199.39	7	2106A	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	C3	13199.39	7	2107	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	C3	13199.39	7	2109	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	D3	13199.39	7	2110	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	D3	13199.39	7	2111	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	D3	13199.39	7	2112	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	C3	13199.39	7	2113	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	D3	13199.39	7	2114	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	C2	13199.39	7	2115	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	D3	13199.39	7	2116	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	D2	13199.39	7	2117	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	D3	13199.39	7	2118	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	D3	13199.39	7	2119	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	D3	13199.39	7	2120	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	D3	13199.39	7	2121	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	D3	13199.39	7	2122	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	D3	13199.39	7	2124	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	D3	13199.39	7	2124A	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
147	147(7)HR	D3	13199.39	7	2125	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
147	147(7)HR	D3	13199.39	7	2126	Chemicals involved in laboratory process	Errett, Neeper, Boatwright	None
148	148(2)HS	D2	1071.23	2	2142	potential for chemical storage	visual inspection, real estate	None
148	148(2)HS	D2	1071.23	2	2143	potential for chemical use	visual inspection, real estate	None
148	148(2)HS	D2	1071.23	1	2145	always been transceiver room or latrine	visual inspection, real estate	None
148	148(2)HS	D2	1071.23	1	2146	always been latrine	visual inspection, real estate	None
148	148(2)HS	D2	1071.23	2	2147	potential for chemical storage	visual inspection, real estate	None
149	149(2)HS/PS	D3	1322.99	2	2125A	potential for chemical use	visual inspection, real estate	None
150	150(2)HS	D3	41.76	2	2092	potential for chemical storage	visual inspection, real estate	None
151	151(2)HS	E2	398.99	2	2183	potential for chemical storage	visual inspection, real estate	None
151	151(2)HS	E2	398.99	2	2184	potential for chemical use	visual inspection, real estate	None
151	151(2)HS	D2	398.99	2	2184A	potential for chemical storage	visual inspection, real estate	None
151	151(2)HS	E2	398.99	2	2185	potential for chemical storage	visual inspection, real estate	None
151	151(2)HS	D2	398.99	2	2187	potential for chemical storage	visual inspection, real estate	None
152	152(2)HS	E2	360.86	2	2194	potential for chemical storage	visual inspection, real estate	None
152	152(2)HS	E3	360.86	2	2197	potential for chemical storage	visual inspection, real estate	None
153	153(2)HS	E3	307.11	2	2200S	potential for chemical use	visual inspection, real estate	None
153	153(2)HS	E3	307.11	2	2201S	potential for chemical use	visual inspection, real estate	None
153	153(2)HS	E3	307.11	2	2202S	potential for chemical storage	visual inspection, real estate	None
154	154(2)HS	E3	165.11	2	2002	potential for chemical use	visual inspection, real estate	None
155	155(1)	E3	18565.98	1	2000	always been office	visual inspection, real estate	None
155	155(1)	E3	18565.98	1	2001	always been office	visual inspection, real estate	None
155	155(1)	D3	18565.98	1	2003	always been office	visual inspection, real estate	None
155	155(1)	D3	18565.98	1	2004	always been office	visual inspection, real estate	Spills cleaned up
155	155(1)	D3	18565.98	1	2093	always been latrine	visual inspection, real estate	None
155	155(1)	D3	18565.98	1	2127	always been latrine	visual inspection, real estate	None
155	155(1)	D3	18565.98	1	2128	always been patient room or office	visual inspection, real estate	None
155	155(1)	D3	18565.98	1	2131	always been latrine	visual inspection, real estate	None
155	155(1)	D3	18565.98	1	2132	always been patient room	visual inspection, real estate	None
155	155(1)	D2	18565.98	1	2133	always been patient room	visual inspection, real estate	None
155	155(1)	D2	18565.98	1	2134	always been latrine	visual inspection, real estate	None
155	155(1)	D2	18565.98	1	2135	always been patient room	visual inspection, real estate	None
155	155(1)	D2	18565.98	1	2136	always been patient room	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
155	155(1)	D2	18565.98	1	2137	always been latrine	visual inspection, real estate	None
155	155(1)	D2	18565.98	1	2138	always been patient room	visual inspection, real estate	None
155	155(1)	D2	18565.98	1	2139	always been patient room	visual inspection, real estate	None
155	155(1)	D2	18565.98	1	2140	always been latrine	visual inspection, real estate	None
155	155(1)	D2	18565.98	1	2141	always been patient room	visual inspection, real estate	None
155	155(1)	D2	18565.98	1	2148	always been nurse station	visual inspection, real estate	None
155	155(1)	D2	18565.98	1	2164	always been litter/bedscreens and clean linen	visual inspection, real estate	None
155	155(1)	D2	18565.98	1	2165	always been double room or kitchen	visual inspection, real estate	None
155	155(1)	E2	18565.98	1	2167	always been porch or patient room	visual inspection, real estate	None
155	155(1)	E2	18565.98	1	2167A	always been latrine	visual inspection, real estate	None
155	155(1)	E2	18565.98	1	2168	always been patient room	visual inspection, real estate	None
155	155(1)	E2	18565.98	1	2168A	always been latrine	visual inspection, real estate	None
155	155(1)	E2	18565.98	1	2171	always been porch/patient room	visual inspection, real estate	None
155	155(1)	E2	18565.98	1	2171A	always been double room or latrine	visual inspection, real estate	None
155	155(1)	E2	18565.98	1	2172	always been dayroom or patient room	visual inspection, real estate	None
155	155(1)	E2	18565.98	1	2174	always been patient room	visual inspection, real estate	None
155	155(1)	E2	18565.98	1	2174A	always been latrine	visual inspection, real estate	None
155	155(1)	E2	18565.98	1	2177	always been patient room	visual inspection, real estate	None
155	155(1)	E2	18565.98	1	2177A	always been latrine	visual inspection, real estate	None
155	155(1)	E2	18565.98	1	2179	always been patient room	visual inspection, real estate	None
155	155(1)	E2	18565.98	1	2182	always been latrine/patient room	visual inspection, real estate	None
155	155(1)	D2	18565.98	1	2186	always been dirty linen	visual inspection, real estate	None
155	155(1)	E2	18565.98	1	2188	always been porch or office	visual inspection, real estate	None
155	155(1)	D2	18565.98	1	2190	always been patient room	visual inspection, real estate	None
155	155(1)	D2	18565.98	1	2191	always been latrine	visual inspection, real estate	None
155	155(1)	D2	18565.98	1	2192	always been latrine	visual inspection, real estate	None
155	155(1)	E2	18565.98	1	2193	always been patient room	visual inspection, real estate	None
155	155(1)	E2	18565.98	1	2195	always been latrine	visual inspection, real estate	None
155	155(1)	D2	18565.98	1	2196	always been patient room	visual inspection, real estate	None
155	155(1)	E3	18565.98	1	2198	always been latrine	visual inspection, real estate	None
155	155(1)	E3	18565.98	1	2199	always been office	visual inspection, real estate	None
155	155(1)	E3	18565.98	1	2203S	always been office	visual inspection, real estate	None
155	155(1)	D1	18565.98	1	2203W	always been ward or office	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
155	155(1)	D1	18565.98	1	2204	always been ward	visual inspection, real estate	None
155	155(1)	D1	18565.98	1	2205	always been ward	visual inspection, real estate	None
155	155(1)	D1	18565.98	1	2206	always been ward	visual inspection, real estate	None
155	155(1)	D1	18565.98	1	2208	always been ward or office	visual inspection, real estate	None
155	155(1)	D1	18565.98	1	2210	always been latrine	visual inspection, real estate	None
155	155(1)	D1	18565.98	1	2211	always been latrine	visual inspection, real estate	None
155	155(1)	D1	18565.98	1	2212	always been porch or room	visual inspection, real estate	None
155	155(1)	E1	18565.98	1	2214	always been dayroom or office	visual inspection, real estate	None
155	155(1)	D1	18565.98	1	2215	always been ward or office	visual inspection, real estate	None
155	155(1)	D1	18565.98	1	2216	always been ward or office	visual inspection, real estate	None
155	155(1)	E1	18565.98	1	2217	always been porch or office	visual inspection, real estate	None
155	155(1)	E1	18565.98	1	2218	always been porch or office	visual inspection, real estate	None
155	155(1)	D1	18565.98	1	2219	always been ward or office	visual inspection, real estate	None
155	155(1)	D1	18565.98	1	2220	always been ward or office	visual inspection, real estate	None
155	155(1)	E1	18565.98	1	2221	always been porch or office	visual inspection, real estate	None
155	155(1)	E1	18565.98	1	2222	always been porch or office	visual inspection, real estate	None
155	155(1)	E1	18565.98	1	2224	always been porch or office	visual inspection, real estate	None
155	155(1)	E1	18565.98	1	2225	always been porch or office	visual inspection, real estate	None
155	155(1)	E2	18565.98	1	2226	always been porch or office	visual inspection, real estate	None
155	155(1)	D2	18565.98	1	2227	always been latrine	visual inspection, real estate	None
155	155(1)	D1	18565.98	1	2229	always been ward	visual inspection, real estate	None
156	156(2)HS	E2	233.87	2	2180	potential for chemical storage	visual inspection, real estate	None
156	156(2)HS	E2	233.87	2	2181	potential for chemical storage	visual inspection, real estate	None
157	157(2)HS	C4	43.20	2	1022	potential for chemical storage	visual inspection, real estate	None
158	158(2)HS	C4	110.97	2	1020	potential for chemical storage	visual inspection, real estate	None
158	158(2)HS	C4	110.97	2	1021B	potential for chemical storage	visual inspection, real estate	None
159	159(2)HS	B4	169.93	2	1018	potential for chemical storage	visual inspection, real estate	None
159	159(2)HS	B4	169.93	2	1019C	potential for chemical storage	visual inspection, real estate	None
160	160(7)HR	B4	257.34	7	1034A	radionuclide use	Boatwright	None
160	160(7)HR	B4	257.34	7	1034B	radionuclide use	Boatwright	None
160	160(7)HR	B4	257.34	7	1034C	radionuclide use	Boatwright	None
161	161(2)HS	B2	57.86	2	1189B	potential for chemical storage	visual inspection, real estate	None
162	162(2)HS	B3	39.91	2	1087	potential for chemical storage	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
163	163(2)HS	B2	56.51	2	1187	potential for chemical use	visual inspection, real estate	None
164	164(2)HS	B2	325.69	2	1184B	potential for chemical use	visual inspection, real estate	None
164	164(2)HS	B2	325.69	2	1184C	potential for chemical use	visual inspection, real estate	None
164	164(2)HS	B2	325.69	2	1185A	potential for chemical use and storage	visual inspection, real estate	None
165	165(2)HS	B2	465.54	2	1114A	potential for chemical use	visual inspection, real estate	None
165	165(2)HS	B2	465.54	2	1114B	potential for chemical use	visual inspection, real estate	None
165	165(2)HS	B2	465.54	2	1115	potential for chemical use	visual inspection, real estate	None
166	166(2)HS	B2	275.62	2	1178	potential for chemical use	visual inspection, real estate	None
167	167(2)HS	C2	198.67	2	1172	potential for chemical storage	visual inspection, real estate	None
167	167(2)HS	C2	198.67	2	1173	potential for chemical storage	visual inspection, real estate	None
168	168(2)HS	C2	528.88	2	1166	potential for chemical use	visual inspection, real estate	None
168	168(2)HS	C2	528.88	2	1167	potential for chemical use	visual inspection, real estate	None
169	169(2)HS	B2	2083.93	2	1156	potential for chemical storage	visual inspection, real estate	None
169	169(2)HS	C2	2083.93	2	1157	potential for chemical use	visual inspection, real estate	None
169	169(2)HS	C2	2083.93	2	1160	potential for chemical use	visual inspection, real estate	None
169	169(2)HS	C2	2083.93	2	1161	potential for chemical use	visual inspection, real estate	None
169	169(2)HS	C2	2083.93	2	1162	potential for chemical use	visual inspection, real estate	None
169	169(2)HS	C2	2083.93	2	1164	potential for chemical use	visual inspection, real estate	None
169	169(2)HS	C2	2083.93	2	1165	potential for chemical use	visual inspection, real estate	None
170	170(2)HS	B2	447.22	2	1116	potential for chemical storage and use	visual inspection, real estate	None
170	170(2)HS	B2	447.22	2	1117	potential for chemical storage	visual inspection, real estate	None
170	170(2)HS	B2	447.22	2	1118	potential for chemical use	visual inspection, real estate	None
171	171(2)HS	B1	125.93	2	1123	potential for chemical use	visual inspection, real estate	None
172	172(2)HS	B1	361.07	2	1125	potential for chemical use	visual inspection, real estate	None
172	172(2)HS	B1	361.07	2	1126	potential for chemical use	visual inspection, real estate	None
172	172(2)HS	B1	361.07	2	1127	potential for chemical use	visual inspection, real estate	None
173	173(2)HS	B1	426.99	2	1129	potential for chemical use	visual inspection, real estate	None
173	173(2)HS	B1	426.99	2	1130	potential for chemical use	visual inspection, real estate	None
173	173(2)HS	B1	426.99	2	1131	potential for chemical use	visual inspection, real estate	None
174	174(2)HR	B1	1304.73	2	1137	potential for chemical storage	visual inspection, real estate	None
174	174(2)HR	B1	1304.73	2	1138	potential for chemical use	visual inspection, real estate	None
174	174(2)HR	B1	1304.73	2	1139	potential for chemical use	visual inspection, real estate	None
174	174(2)HR	B1	1304.73	2	1140A	potential for chemical use	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
174	174(2)HR	B1	1304.73	2	1140B	potential for chemical use	visual inspection, real estate	None
174	174(2)HR	B1	1304.73	2	1141	potential for chemical storage	visual inspection, real estate	None
174	174(2)HR	B1	1304.73	2	1143	potential for chemical storage	visual inspection, real estate	None
174	174(2)HR	B1	1304.73	2	1145	potential for chemical use	visual inspection, real estate	None
175	175(2)HS	B1	132.50	2	1135	potential for chemical use	visual inspection, real estate	None
176	176	B3	21824.71	10	1089	lease is not being considered	Errett, Neeper, Boatwright	None
176	176	B3	21824.71	10	1089A	lease is not being considered	Errett, Neeper, Boatwright	None
176	176	B3	21824.71	10	1089B	lease is not being considered	Errett, Neeper, Boatwright	None
176	176	B3	21824.71	10	1089C	lease is not being considered	Errett, Neeper, Boatwright	None
176	176	B3	21824.71	10	1090	lease is not being considered	Errett, Neeper, Boatwright	None
176	176	B3	21824.71	10	1091	lease is not being considered	Errett, Neeper, Boatwright	None
176	176	A3	21824.71	10	1092	lease is not being considered	Errett, Neeper, Boatwright	None
176	176	A3	21824.71	10	1093	lease is not being considered	Errett, Neeper, Boatwright	None
176	176	A3	21824.71	10	1094	lease is not being considered	Errett, Neeper, Boatwright	None
176	176	A3	21824.71	10	1095	lease is not being considered	Errett, Neeper, Boatwright	None
176	176	A3	21824.71	10	1096	lease not being considered	visual inspection, real estate	None
176	176	A3	21824.71	10	1097	lease not being considered	visual inspection, real estate	None
176	176	A3	21824.71	10	1098	lease not being considered	visual inspection, real estate	None
176	176	A3	21824.71	10	1099	lease is not being considered	Errett, Neeper, Boatwright	None
176	176	A2	21824.71	10	1100	lease is not being considered	Errett, Neeper, Boatwright	None
176	176	A2	21824.71	10	1101	lease is not being considered	Errett, Neeper, Boatwright	None
176	176	A2	21824.71	10	1102	lease is not being considered	Errett, Neeper, Boatwright	None
176	176	A2	21824.71	10	1103	lease is not being considered	Errett, Neeper, Boatwright	None
176	176	A2	21824.71	10	1104	lease is not being considered	Errett, Neeper, Boatwright	None
176	176	A3	21824.71	10	1105	lease is not being considered	Errett, Neeper, Boatwright	None
176	176	A2	21824.71	10	1106	lease is not being considered	Errett, Neeper, Boatwright	None
176	176	B3	21824.71	10	1106A	lease is not being considered	Errett, Neeper, Boatwright	None
176	176	B3	21824.71	10	1106B	lease is not being considered	Errett, Neeper, Boatwright	None
176	176	B3	21824.71	10	1106C	lease is not being considered	Errett, Neeper, Boatwright	None
176	176	B3	21824.71	10	1107A	lease is not being considered	Errett, Neeper, Boatwright	None
176	176	B3	21824.71	10	1107B	lease is not being considered	visual inspection, real estate	None
177	177(7)HR	B2	194.82	7	1120	chemical use	real estate	None
178	178(7)HR	B1	2113.87	7	1142	chemotherapy	Errett, Neeper, Boatwright	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
178	178(7)HR	B1	2113.87	7	1144	chemotherapy	Errett, Neeper, Boatwright	None
178	178(7)HR	B1	2113.87	7	1147	chemotherapy	Errett, Neeper, Boatwright	None
178	178(7)HR	B2	2113.87	7	1148A	chemotherapy	Errett, Neeper, Boatwright	None
178	178(7)HR	B2	2113.87	7	1148B	chemotherapy	Errett, Neeper, Boatwright	None
178	178(7)HR	B2	2113.87	7	1148C	chemotherapy	Errett, Neeper, Boatwright	None
178	178(7)HR	B2	2113.87	7	1148D	chemotherapy	Errett, Neeper, Boatwright	None
178	178(7)HR	B1	2113.87	7	1148E	chemotherapy	Errett, Neeper, Boatwright	None
178	178(7)HR	B1	2113.87	7	1148F	chemotherapy	Errett, Neeper, Boatwright	None
178	178(7)HR	B1	2113.87	7	1148G	chemotherapy	Errett, Neeper, Boatwright	None
178	178(7)HR	B1	2113.87	7	1148H	chemotherapy	Errett, Neeper, Boatwright	None
178	178(7)HR	B1	2113.87	7	1149	chemotherapy	visual inspection, real estate	None
178	178(7)HR	B2	2113.87	7	1152	chemotherapy	Errett, Neeper, Boatwright	None
178	178(7)HR	B2	2113.87	7	1153	chemotherapy	Errett, Neeper, Boatwright	None
178	178(7)HR	B2	2113.87	7	1154	chemotherapy	Errett, Neeper, Boatwright	None
179	179(2)HS/PS	B4	412.71	2	1075	potential for chemical storage	visual inspection, real estate	None
180	180(2)HS/PS	B4	466.95	2	1064A	potential for chemical storage and use	visual inspection, real estate	None
180	180(2)HS/PS	B4	466.95	2	1065	potential for chemical storage	visual inspection, real estate	None
180	180(2)HS/PS	B4	466.95	2	1071	potential for chemical storage	visual inspection, real estate	None
181	181(2)HS	B5	180.96	2	1055A	potential for chemical use	visual inspection, real estate	None
182	182(2)HS	B5	164.74	2	1051A	potential for chemical storage	visual inspection, real estate	None
183	183(2)HS	B4	112.53	2	1035	potential for chemical storage	visual inspection, real estate	None
183	183(2)HS	B4	112.53	2	1036	potential for chemical storage	visual inspection, real estate	None
184	184(2)HS	B4	144.00	2	1014	potential for chemical storage	visual inspection, real estate	None
184	184(2)HS	B4	144.00	2	1015	potential for chemical storage	visual inspection, real estate	None
184	184(2)HS	B4	144.00	2	1016	potential for chemical storage	visual inspection, real estate	None
185	185(1)	C3	35404.50	1	1001	always been office or room	visual inspection, real estate	None
185	185(1)	C3	35404.50	1	1002	always been office	visual inspection, real estate	None
185	185(1)	C3	35404.50	1	1003	always been closet or vestibule	visual inspection, real estate	None
185	185(1)	B3	35404.50	1	1004	always been latrine	visual inspection, real estate	None
185	185(1)	B3	35404.50	1	1005	always been closet	visual inspection, real estate	None
185	185(1)	B3	35404.50	1	1006	always been closet	visual inspection, real estate	None
185	185(1)	B3	35404.50	1	1007	always been waiting area	visual inspection, real estate	None
185	185(1)	B3	35404.50	1	1008	always been office	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
185	185(1)	B4	35404.50	1	1009	always been conference room	visual inspection, real estate	None
185	185(1)	B4	35404.50	1	1010	always been office	visual inspection, real estate	None
185	185(1)	B4	35404.50	1	1011	always been office	visual inspection, real estate	None
185	185(1)	B4	35404.50	1	1011A	always been porch or office	visual inspection, real estate	None
185	185(1)	B4	35404.50	1	1012	always been office or hallway	visual inspection, real estate	None
185	185(1)	B4	35404.50	1	1017	always been patient room or lounge	visual inspection, real estate	None
185	185(1)	B4	35404.50	1	1019A	always been latrine	visual inspection, real estate	None
185	185(1)	B4	35404.50	1	1019B	always been latrine	visual inspection, real estate	None
185	185(1)	C4	35404.50	1	1021A	always been patient room	visual inspection, real estate	None
185	185(1)	C4	35404.50	1	1023A	always been patient room	visual inspection, real estate	None
185	185(1)	C4	35404.50	1	1023B	always been latrine	visual inspection, real estate	None
185	185(1)	C4	35404.50	1	1026	always been corridor or lounge	visual inspection, real estate	None
185	185(1)	C4	35404.50	1	1027	always been dayroom or office	visual inspection, real estate	None
185	185(1)	C4	35404.50	1	1028	always been porch or patient room	visual inspection, real estate	None
185	185(1)	C4	35404.50	1	1028C	always been latrine	visual inspection, real estate	None
185	185(1)	C4	35404.50	1	1030	always been patient room	visual inspection, real estate	None
185	185(1)	C4	35404.50	1	1030C	always been latrine	visual inspection, real estate	None
185	185(1)	B4	35404.50	1	1031A	always bee porch or office	visual inspection, real estate	None
185	185(1)	B4	35404.50	1	1031B	always been porch or office	visual inspection, real estate	None
185	185(1)	B4	35404.50	1	1032	always been latrine	visual inspection, real estate	None
185	185(1)	B4	35404.50	1	1033	always been patient room	visual inspection, real estate	None
185	185(1)	B5	35404.50	1	1040A	always been patient room	visual inspection, real estate	None
185	185(1)	B5	35404.50	1	1040B	always been porch or patient room	visual inspection, real estate	None
185	185(1)	B5	35404.50	1	1040C	always been latrine	visual inspection, real estate	None
185	185(1)	B5	35404.50	1	1043A	always been patient room	visual inspection, real estate	None
185	185(1)	B5	35404.50	1	1043B	always been porch or patient room	visual inspection, real estate	None
185	185(1)	B5	35404.50	1	1043C	always been latrine	visual inspection, real estate	None
185	185(1)	B5	35404.50	1	1046A	always been patient room	visual inspection, real estate	None
185	185(1)	B5	35404.50	1	1046B	always been porch or patient room	visual inspection, real estate	None
185	185(1)	B5	35404.50	1	1046C	always been latrine	visual inspection, real estate	None
185	185(1)	B5	35404.50	1	1049A	always been patient room	visual inspection, real estate	None
185	185(1)	B5	35404.50	1	1049B	always been porch or patient room	visual inspection, real estate	None
185	185(1)	B5	35404.50	1	1049C	always been latrine	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
185	185(1)	B5	35404.50	1	1050A	always been dayroom or office	visual inspection, real estate	None
185	185(1)	B5	35404.50	1	1050B	always been dayroom or office	visual inspection, real estate	None
185	185(1)	B5	35404.50	1	1050C	always been dayroom or office	visual inspection, real estate	None
185	185(1)	B5	35404.50	1	1054A	always been patient room	visual inspection, real estate	None
185	185(1)	B5	35404.50	1	1054B	always been latrine	visual inspection, real estate	None
185	185(1)	B5	35404.50	1	1055B	always been latrine	visual inspection, real estate	None
185	185(1)	B5	35404.50	1	1057	always been patient room	visual inspection, real estate	None
185	185(1)	B5	35404.50	1	1058A	always been patient room	visual inspection, real estate	None
185	185(1)	B5	35404.50	1	1058B	always been latrine	visual inspection, real estate	None
185	185(1)	B5	35404.50	1	1060	always been patient room	visual inspection, real estate	None
185	185(1)	B5	35404.50	1	1061A	always been patient room	visual inspection, real estate	None
185	185(1)	B5	35404.50	1	1063	always been patient room	visual inspection, real estate	None
185	185(1)	B4	35404.50	1	1066	always been nurse station	visual inspection, real estate	None
185	185(1)	B4	35404.50	1	1076	always been office space or electric room	visual inspection, real estate	None
185	185(1)	B4	35404.50	1	1078	always been office	visual inspection, real estate	None
185	185(1)	B4	35404.50	1	1081	always been office	visual inspection, real estate	None
185	185(1)	B4	35404.50	1	1082	always been office or patient room	visual inspection, real estate	None
185	185(1)	B4	35404.50	1	1083	always been office or patient room	visual inspection, real estate	None
185	185(1)	B3	35404.50	1	1084	always been office	visual inspection, real estate	None
185	185(1)	B3	35404.50	1	1085	always been office	visual inspection, real estate	None
185	185(1)	B3	35404.50	1	1086	always been toilet or room	visual inspection, real estate	None
185	185(1)	B3	35404.50	1	1088	always been latrine	visual inspection, real estate	None
185	185(1)	B3	35404.50	1	1107C	always been latrine	visual inspection, real estate	None
185	185(1)	B3	35404.50	1	1108	always been toilet or room	visual inspection, real estate	None
185	185(1)	B3	35404.50	1	1109A	always been an office	visual inspection, real estate	None
185	185(1)	B3	35404.50	1	1109B	always been office	visual inspection, real estate	None
185	185(1)	B2	35404.50	1	1110	always been office	visual inspection, real estate	None
185	185(1)	B2	35404.50	1	1111A	always been cashier	visual inspection, real estate	None
185	185(1)	B3	35404.50	1	1111B	always been vault	visual inspection, real estate	None
185	185(1)	B2	35404.50	1	1112A	always been office	visual inspection, real estate	None
185	185(1)	B2	35404.50	1	1112B	always been office	visual inspection, real estate	None
185	185(1)	B2	35404.50	1	1112C	always been office	visual inspection, real estate	None
185	185(1)	B2	35404.50	1	1113	always been office	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
185	185(1)	B2	35404.50	1	1121	always been office	visual inspection, real estate	None
185	185(1)	B1	35404.50	1	1122	always been office	visual inspection, real estate	None
185	185(1)	B1	35404.50	1	1124	always been waiting room or office	visual inspection, real estate	None
185	185(1)	B1	35404.50	1	1128	always been office	visual inspection, real estate	None
185	185(1)	B1	35404.50	1	1132	always been men's locker or conference room	visual inspection, real estate	None
185	185(1)	C2	35404.50	1	1171	always been office	visual inspection, real estate	None
185	185(1)	C2	35404.50	1	1174	always been office	visual inspection, real estate	None
185	185(1)	B2	35404.50	1	1183	always been office	visual inspection, real estate	None
185	185(1)	B2	35404.50	1	1184A	always been office	visual inspection, real estate	None
185	185(1)	B2	35404.50	1	1184D	always been office or latrine	visual inspection, real estate	None
185	185(1)	B2	35404.50	1	1186	always been office or patient room	visual inspection, real estate	None
185	185(1)	B2	35404.50	1	1188	always been office or patient room	visual inspection, real estate	None
185	185(1)	B2	35404.50	1	1189A	always been office or room	visual inspection, real estate	None
185	185(1)	B2	35404.50	1	1190	always been office	visual inspection, real estate	None
185	185(1)	B3	35404.50	1	1190A	always been office	visual inspection, real estate	None
185	185(1)	B3	35404.50	1	1190B	always been lobby or office	visual inspection, real estate	None
185	185(1)	B3	35404.50	1	1191	always been waiting area	visual inspection, real estate	None
185	185(1)	B3	35404.50	1	1194	always been office	visual inspection, real estate	None
185	185(1)	C3	35404.50	1	1195	always been office	visual inspection, real estate	None
185	185(1)	C3	35404.50	1	1196	always been office	visual inspection, real estate	None
186	186(1)	B4	68.36	1	1064B	always been latrine	visual inspection, real estate	None
187	187(7)HR	B4	59.66	7	1013	installation of lead lined doors in 1967	real estate	None
188	188(7)HR	B4	178.31	7	1074	potential for chemical use	visual inspection, real estate	None
189	189(2)HS/HR	B2	2391.05	2	1105B	potential for chemical storage	Errett, Neeper, Boatwright	None
190	190(2)HS	B2	394.44	2	1185B	potential for chemical use	visual inspection, real estate	None
190	190(2)HS	B2	394.44	2	1185C	potential for chemical use	visual inspection, real estate	None
191	191(7)HS	C4	362.51	7	1024	radionuclide use	Boatwright	None
191	191(7)HS	C4	362.51	7	1024A	radionuclide use	Boatwright	None
191	191(7)HS	C4	362.51	7	1024B	radionuclide use	Boatwright	None
192	192(1)	E3	29424.15	1	1	always been vault or Post office	visual inspection, real estate	None
192	192(1)	E4	29424.15	1	10	always been waiting room	visual inspection, real estate	None
192	192(1)	E2	29424.15	1	105	always been office	Errett, Neeper, Boatwright	None
192	192(1)	E2	29424.15	1	106	always been corridor/reception	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
192	192(1)	E2	29424.15	1	107	always been reading room or lounge	visual inspection, real estate	None
192	192(1)	E4	29424.15	1	11	always been latrine	visual inspection, real estate	None
192	192(1)	E4	29424.15	1	12	always been linen or storage	visual inspection, real estate	None
192	192(1)	D3	29424.15	1	128	always been office or laundry	visual inspection, real estate	None
192	192(1)	E4	29424.15	1	14	always been physiotherapy or dressing room	visual inspection, real estate	None
192	192(1)	E4	29424.15	1	15	always been physiotherapy or dressing room	visual inspection, real estate	None
192	192(1)	E4	29424.15	1	16	always been physiotherapy or exercise room	visual inspection, real estate	None
192	192(1)	E3	29424.15	1	2	always been post office	visual inspection, real estate	None
192	192(1)	E5	29424.15	1	23	always been whirlpool	visual inspection, real estate	None
192	192(1)	E5	29424.15	1	28	always been bath or office	visual inspection, real estate	None
192	192(1)	E4	29424.15	1	3	always been post exchange	visual inspection, real estate	None
192	192(1)	D4	29424.15	1	41	always been latrine or office	visual inspection, real estate	None
192	192(1)	D3	29424.15	1	45	always been latrine	visual inspection, real estate	None
192	192(1)	E3	29424.15	1	46	always been waiting room	visual inspection, real estate	None
192	192(1)	D3	29424.15	1	48	always been soiled linen or room	visual inspection, real estate	None
192	192(1)	D3	29424.15	1	49	always been clean linen or prayer room	visual inspection, real estate	None
192	192(1)	E4	29424.15	1	4A	always been storage for post exchange	visual inspection, real estate	None
192	192(1)	E4	29424.15	1	4B	always been storage for post exchange	visual inspection, real estate	None
192	192(1)	E4	29424.15	1	4E	always been post exchange	visual inspection, real estate	None
192	192(1)	D3	29424.15	1	50	always been laundry or office	visual inspection, real estate	None
192	192(1)	D3	29424.15	1	51	always been office	visual inspection, real estate	None
192	192(1)	D3	29424.15	1	52	always been office	visual inspection, real estate	None
192	192(1)	D3	29424.15	1	53	always been office	visual inspection, real estate	None
192	192(1)	E3	29424.15	1	54	always been waiting area or office	visual inspection, real estate	None
192	192(1)	E3	29424.15	1	55	always been information center	visual inspection, real estate	None
192	192(1)	E3	29424.15	1	56	always been library/office	visual inspection, real estate	None
192	192(1)	E3	29424.15	1	56A	always been library/pre-admission	visual inspection, real estate	None
192	192(1)	D3	29424.15	1	57	always been latrine	visual inspection, real estate	None
192	192(1)	E4	29424.15	1	6	always been soiled linen	visual inspection, real estate	None
192	192(1)	D2	29424.15	1	63	always been and office	visual inspection, real estate	None
192	192(1)	D1	29424.15	1	66A	always been ambulance garage	visual inspection, real estate	None
192	192(1)	E4	29424.15	1	7	always been waiting room or office	visual inspection, real estate	None
192	192(1)	E2	29424.15	1	79A	always been latrine	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
192	192(1)	E4	29424.15	1	8	always been store room or office	visual inspection, real estate	None
192	192(1)	E2	29424.15	1	80	always been dressing room	visual inspection, real estate	None
192	192(1)	E2	29424.15	1	80A	always been latrine	visual inspection, real estate	None
192	192(1)	E2	29424.15	1	83	always been latrine	visual inspection, real estate	None
192	192(1)	E2	29424.15	1	85	always been lobby or linen room	visual inspection, real estate	None
192	192(1)	E2	29424.15	1	86	always been office	visual inspection, real estate	None
192	192(1)	E4	29424.15	1	9	always been waiting room	visual inspection, real estate	None
192	192(1)	E2	29424.15	1	91	always been office	visual inspection, real estate	None
192	192(1)	E2	29424.15	1	92	always been corridor or office	visual inspection, real estate	None
192	192(1)	E2	29424.15	1	92A	always been corridor or administration	visual inspection, real estate	None
192	192(1)	E2	29424.15	1	93	always been office	visual inspection, real estate	None
192	192(1)	E2	29424.15	1	94A	always been library or ante room	visual inspection, real estate	None
192	192(1)	E2	29424.15	1	98	always been library or telephone room	visual inspection, real estate	None
193	193(2)HS	D3	121.36	2	47	potential for chemical storage	visual inspection, real estate	None
194	194(2)HS	E4	31.27	2	5	potential for chemical storage	visual inspection, real estate	None
195	195(2)HS	E2	456.43	2	89	potential for chemical use	visual inspection, real estate	None
195	195(2)HS	E2	456.43	2	90	potential for chemical use	visual inspection, real estate	None
196	196(2)HS	E3	78.08	2	56B	potential for chemical storage	visual inspection, real estate	None
197	197(2)HS	E2	406.72	2	87	potential for chemical use	visual inspection, real estate	None
197	197(2)HS	E2	406.72	2	88	potential for chemical use	visual inspection, real estate	None
198	198(2)HS/PS	E2	1024.31	2	81	potential for chemical storage	visual inspection, real estate	None
198	198(2)HS/PS	E2	1024.31	2	82	potential for chemical use	visual inspection, real estate	None
198	198(2)HS/PS	E1	1024.31	2	82A	potential for chemical use	visual inspection, real estate	None
198	198(2)HS/PS	E2	1024.31	2	84	potential for chemical storage	visual inspection, real estate	None
199	199(7)HR	D5	3116.21	7	30	chemotherapy	Errett, Neeper, Boatwright	None
199	199(7)HR	D5	3116.21	7	31	chemotherapy	Errett, Neeper, Boatwright	None
199	199(7)HR	D5	3116.21	7	32	chemotherapy	Errett, Neeper, Boatwright	None
199	199(7)HR	D5	3116.21	7	33	chemotherapy	Errett, Neeper, Boatwright	None
199	199(7)HR	D5	3116.21	7	34	chemotherapy	Errett, Neeper, Boatwright	None
199	199(7)HR	D5	3116.21	7	35	chemotherapy	Errett, Neeper, Boatwright	None
199	199(7)HR	D5	3116.21	7	36	chemotherapy	Errett, Neeper, Boatwright	None
199	199(7)HR	D4	3116.21	7	37	chemotherapy	Errett, Neeper, Boatwright	None
199	199(7)HR	E4	3116.21	7	38	chemotherapy	Errett, Neeper, Boatwright	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
199	199(7)HR	D4	3116.21	7	39	chemotherapy	Errett, Neeper, Boatwright	None
200	200(7)HR	D4	20637.43	7	100N	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D4	20637.43	7	101A	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D4	20637.43	7	101N	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D4	20637.43	7	102N	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D4	20637.43	7	103A	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D4	20637.43	7	103N	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D4	20637.43	7	104N	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D4	20637.43	7	105N	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	106A	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	106B	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	106N	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D4	20637.43	7	107N	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D4	20637.43	7	108	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	109	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C4	20637.43	7	110	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	111	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	112	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	112A	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	113	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	114	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	115	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	116	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	117	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	118N	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	119	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	120	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	120A	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	121	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	121A	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	122	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	123	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	124	extensive historic chemical use	Errett, Neeper, Boatwright	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
200	200(7)HR	D3	20637.43	7	125	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	126	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	126A	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	126B	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	126C	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	126E	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	126F	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	127	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	127A	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	129	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	129A	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C4	20637.43	7	130	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	131	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C4	20637.43	7	132	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C4	20637.43	7	133	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	134	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	135	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	136	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	137	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	138	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	139	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	140	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	141	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	142	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	143	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	144	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	144A	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	144B	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C2	20637.43	7	145	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C2	20637.43	7	146	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C2	20637.43	7	147	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C2	20637.43	7	148	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C2	20637.43	7	149	extensive historic chemical use	Errett, Neeper, Boatwright	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
200	200(7)HR	C2	20637.43	7	150A	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C2	20637.43	7	150B	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C2	20637.43	7	150N1	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	150N2	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	151N1	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	151N2	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	C3	20637.43	7	152	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D2	20637.43	7	153N1	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	153N2	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	154	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	155	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	157	extensive historic chemical use	Errett, Neeper, Boatwright	None
200	200(7)HR	D3	20637.43	7	48A	extensive historic chemical use	Errett, Neeper, Boatwright	None
201	201(7)HR	D2	6122.49	7	67	extensive historic chemical use	Errett, Neeper, Boatwright	None
201	201(7)HR	D1	6122.49	7	68	extensive historic chemical use	Errett, Neeper, Boatwright	None
201	201(7)HR	D1	6122.49	7	69	extensive historic chemical use	Errett, Neeper, Boatwright	None
201	201(7)HR	D1	6122.49	7	69A	extensive historic chemical use	Errett, Neeper, Boatwright	None
201	201(7)HR	D1	6122.49	7	70	extensive historic chemical use	Errett, Neeper, Boatwright	None
201	201(7)HR	D1	6122.49	7	71	extensive historic chemical use	Errett, Neeper, Boatwright	None
201	201(7)HR	E1	6122.49	7	72	extensive historic chemical use	Errett, Neeper, Boatwright	None
201	201(7)HR	E1	6122.49	7	73	extensive historic chemical use	Errett, Neeper, Boatwright	None
201	201(7)HR	E1	6122.49	7	74	extensive historic chemical use	Errett, Neeper, Boatwright	None
201	201(7)HR	E1	6122.49	7	75	extensive historic chemical use	Errett, Neeper, Boatwright	None
201	201(7)HR	E1	6122.49	7	76	extensive historic chemical use	Errett, Neeper, Boatwright	None
201	201(7)HR	E1	6122.49	7	77	extensive historic chemical use	Errett, Neeper, Boatwright	None
201	201(7)HR	E2	6122.49	7	79	extensive historic chemical use	Errett, Neeper, Boatwright	None
202	202(2)HS	D4	1840.60	2	42	potential for chemical storage	visual inspection, real estate	None
202	202(2)HS	D4	1840.60	2	43	potential for chemical storage	visual inspection, real estate	None
202	202(2)HS	D4	1840.60	2	44	potential for chemical storage	visual inspection, real estate	None
203	203(2)HS	D4	396.22	2	40	potential for chemical storage	visual inspection, real estate	None
204	204(2)HS	E5	122.38	2	29	potential for chemical use	visual inspection, real estate	None
205	205(2)HS	E5	743.63	2	24	potential for chemical use	visual inspection, real estate	None
205	205(2)HS	E5	743.63	2	25	potential for chemical use	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
205	205(2)HS	E5	743.63	2	26	potential for chemical use	visual inspection, real estate	None
205	205(2)HS	E5	743.63	2	27	potential for chemical use	visual inspection, real estate	None
206	206(2)HS	E4	118.49	2	22	potential for chemical storage	visual inspection, real estate	None
206	206(2)HS	E4	118.49	2	23A	potential for chemical storage	visual inspection, real estate	None
207	207(2)HS	E4	95.20	2	21	potential for chemical use	visual inspection, real estate	None
208	208(2)HS	E4	147.22	2	13	potential for chemical storage	visual inspection, real estate	None
209	209(2)HS	E4	555.73	2	17	potential for chemical use	visual inspection, real estate	None
209	209(2)HS	E4	555.73	2	18	potential for chemical use	visual inspection, real estate	None
209	209(2)HS	E4	555.73	2	18A	potential for chemical storage	visual inspection, real estate	None
209	209(2)HS	E4	555.73	2	19	potential for chemical use	visual inspection, real estate	None
210	210(2)HS	E4	397.58	2	20	potential for chemical use	visual inspection, real estate	None
211	211(2)HS	E2	19.09	2	78	potential for chemical storage	visual inspection, real estate	None
212	212(2)HS/PS	D2	426.86	2	66	potential for chemica storage	visual inspection, real estate	None
213	213(2)HS/PS	D2	455.03	2	64	potential for chemical storage	visual inspection, real estate	None
213	213(2)HS/PS	D2	455.03	2	65	potential for chemical use	visual inspection, real estate	None
214	214(2)HS/PS	E2	2464.11	2	100	potential for chemical use	Errett, Neeper, Boatwright	None
214	214(2)HS/PS	E2	2464.11	2	101	potential for chemical use	Errett, Neeper, Boatwright	None
214	214(2)HS/PS	E2	2464.11	2	102	potential for chemical use	Errett, Neeper, Boatwright	None
214	214(2)HS/PS	E2	2464.11	2	103	potential for chemical use	Errett, Neeper, Boatwright	None
214	214(2)HS/PS	E2	2464.11	2	104	potential for chemical use	Errett, Neeper, Boatwright	None
214	214(2)HS/PS	E2	2464.11	2	94	potential for chemical use	visual inspection, real estate	None
214	214(2)HS/PS	E2	2464.11	2	95	potential for chemical storage	visual inspection, real estate	None
214	214(2)HS/PS	E2	2464.11	2	96	potential for chemical storage	visual inspection, real estate	None
214	214(2)HS/PS	E2	2464.11	2	97	potential for chemical use	visual inspection, real estate	None
214	214(2)HS/PS	E2	2464.11	2	99	potential for chemical use	visual inspection, real estate	None
215	215(2)HS/PS	D2	3545.31	2	4N	potential chemical use	visual inspection, real estate	None
215	215(2)HS/PS	D3	3545.31	2	58	potential for chemical storage	visual inspection, real estate	None
215	215(2)HS/PS	D2	3545.31	2	59	potential for chemical storage and use	visual inspection, real estate	None
215	215(2)HS/PS	D2	3545.31	2	60	potential for chemical storage	visual inspection, real estate	None
215	215(2)HS/PS	D2	3545.31	2	61	potential for chemical storage	visual inspection, real estate	None
215	215(2)HS/PS	D2	3545.31	2	62	potential for chemical storage	visual inspection, real estate	None
217	217(2)HS	D3	89.61	2	BC13	housekeeping chemicals stored	visual inspection, real estate	None
218	218(1)	D3	56.61	1	BC16	no indications of chemical storage/use	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
219	219(1)	D3	481.35	1	BC20	always been oxygen storage	visual inspection, real estate	None
221	221(2)HS	C2	1966.48	2	BC26	petroleum products may have been used	visual inspection, real estate	None
221	221(2)HS	C2	1966.48	2	BC27	petroleum products may have been used	visual inspection, real estate	None
222	222(7)HR	C3	62065.76	7	BC01	formerly stored transformers containing PCB	visual inspection, real estate, Errett	Transformer removed from basement
222	222(7)HR	C3	62065.76	7	BC02	historical use questionable	visual inspection, real estate	None
222	222(7)HR	C3	62065.76	7	BC03	historical use questionable	visual inspection, real estate	None
222	222(7)HR	C3	62065.76	7	BC04	formerly soil, pipe breaks and sewage/drainage	visual inspection, real estate	soil was excavated prior to laying
222	222(7)HR	C3	62065.76	7	BC05	always been mechanical room potential for	visual inspection, real estate	None
222	222(7)HR	C3	62065.76	7	BC06	potential for chemical use	visual inspection, real estate	None
222	222(7)HR	C3	62065.76	7	BC07	potential for historical chemical use	visual inspection, real estate	None
222	222(7)HR	D3	62065.76	7	BC11	potential for historical chemical use	visual inspection, real estate	None
222	222(7)HR	D3	62065.76	7	BC12	potential for historical chemical use	visual inspection, real estate	None
222	222(7)HR	D3	62065.76	7	BC14	potential for historical chemical use	visual inspection, real estate	None
222	222(7)HR	D3	62065.76	7	BC15	potential for historical chemical use	visual inspection, real estate	None
222	222(7)HR	D3	62065.76	7	BC17	potential for historical chemical use	visual inspection, real estate	None
222	222(7)HR	D3	62065.76	7	BC18	questionable historical use	visual inspection, real estate	None
222	222(7)HR	D3	62065.76	7	BC19	questionable historical use	visual inspection, real estate	None
222	222(7)HR	D3	62065.76	7	BC21	potential for historical chemical use	visual inspection, real estate	None
222	222(7)HR	D3	62065.76	7	BC22	potential for historical chemical use	visual inspection, real estate	None
222	222(7)HR	C3	62065.76	7	BC23	potential for historical chemical use	visual inspection, real estate	None
222	222(7)HR	C3	62065.76	7	BC24	potential for historical chemical use	visual inspection, real estate	None
222	222(7)HR	C3	62065.76	7	BC25	potential for historical chemical use	visual inspection, real estate	None
222	222(7)HR	C4	62065.76	7	BE01	formerly soil, pipe breaks and sewage/drainage	visual inspection, Ed Payne	soil was excavated prior to laying
222	222(7)HR	D3	62065.76	7	BE02	formerly soil, pipe breaks and sewage/drainage	visual inspection, Ed Payne	soil was excavated prior to laying
222	222(7)HR	C3	62065.76	7	BE03	formerly soil, pipe breaks and sewage/drainage	visual inspection, Ed Payne	soil was excavated prior to laying
222	222(7)HR	C4	62065.76	7	BE04	formerly soil, pipe breaks and sewage/drainage	visual inspection, Ed Payne	soil was excavated prior to laying
222	222(7)HR	B3	62065.76	7	BN01	formerly soil, pipe breaks and sewage/drainage	visual inspection, Ed Payne	soil was excavated prior to laying
222	222(7)HR	C3	62065.76	7	BN02A	potential chemical use	visual inspection, Captain Boatwright, Ed Payne	Room has been decommissioned,
222	222(7)HR	C3	62065.76	7	BN02B	potential chemical use	visual inspection	None
222	222(7)HR	C3	62065.76	7	BN03	formerly soil, pipe breaks and sewage/drainage	visual inspection, Ed Payne	soil was excavated prior to laying
222	222(7)HR	C3	62065.76	7	BN06	potential for oil, grease and chemicals	visual inspection, real estate	None
222	222(7)HR	C3	62065.76	7	BN12	questionable historical use	Real estate, visual inspection	None
222	222(7)HR	C3	62065.76	7	BN13	questionable historical use	visual inspection, real estate	None

CERFA MAP TABLE
SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY
BUILDING NO. 500
U.S. ARMY GARRISON, FITZSIMONS

Parcel ID	Parcel Label	Location	Size (ft^2)	Category	Room No.	Basis	Source of Evidence	Remediation or Mitigation
222	222(7)HR	C3	62065.76	7	BN14	formerly stored transformers containing PCB	Real estate, Errett	Transformer removed from basement
222	222(7)HR	C3	62065.76	7	BN15	formerly stored transformers containing PCB	Real estate, Errett	Transformer removed from basement
222	222(7)HR	C3	62065.76	7	BN16	adjacent to transformer room formerly	visual inspection, real estate	Transformer removed from basement
222	222(7)HR	C2	62065.76	7	BN17	formerly soil, pipe breaks and sewage/drainage	visual inspection, real estate	soil was excavated prior to laying
222	222(7)HR	B3	62065.76	7	BN18	formerly soil, pipe breaks and sewage/drainage	visual inspection, real estate	soil was excavated prior to laying
222	222(7)HR	C2	62065.76	7	BW01	formerly soil, pipe breaks and sewage/drainage	visual inspection, Ed Payne	soil was excavated prior to laying
222	222(7)HR	C2	62065.76	7	BW02	formerly pipe breaks and sewage/drainage	visual inspection, Ed Payne	soil was excavated prior to laying
222	222(7)HR	C3	62065.76	7	BW03	pipe breaks and sewage/drainage	visual inspection, Ed Payne	soil was excavated prior to laying
223	223(2)HS	C3	194.61	2	BN04	Used to store housekeeping chemicals	visual inspection, real estate	None
224	224(1)	C3	1927.62	1	BN05	No indication of chemical storage	visual inspection, real estate	None
226	226(1)	C3	667.75	1	BC08	always been hallway or administration	visual inspection, real estate	None
226	226(1)	C3	667.75	1	BC09	always been hallway	visual inspection, real estate	None
226	226(1)	C3	667.75	1	BC10	always been administration	visual inspection, real estate	None

APPENDIX B

REFERENCES

1938 Construction Drawings and Specifications. 1938. Fitzsimons Army Medical Center. Great Lakes Construction Company of Chicago. Chicago, Illinois.

Army Corps of Engineers (ACE). 1996a. Fitzsimmon's Army Medical Center Building 500 Asbestos Survey. Asbestos Sample Results. Omaha, Nebraska.

Army Corps of Engineers (ACE). 1996b. Fitzsimmon's Army Medical Center Building 500 Lead-Based Paint Survey. Omaha, Nebraska.

Army Environmental Center (AEC). 1995. BRAC 95 EBS/BCP Guidance. Base Closure Division. Aberdeen Proving Ground, Maryland.

Covington, E. No date. The Building of an Army Hospital. Aurora History Museum. Aurora, Colorado

Cross, Jerry. 1995. Personal Communication with Emily Millikin, Parsons Engineering Science, Inc. November 7.

Department of Defense (DOD). 1993. BRAC Cleanup Plan (BCP) Guidebook. U.S. Department of Defense, Washington, D.C.

Department of Defense (DOD). 1995. BRAC Cleanup Plan (BCP) Guidebook. U.S. Department of Defense, Washington, D.C.

Environmental Science and Engineering (ES&E). 1984. Installation Assessment of Fitzsimons Army Medical Center, Report No. 345. Gainesville, Florida.

Fitzsimons Army Medical Center (FAMC). 1985a. Analytical/Environmental Assessment Report for Future Development Plans for Fitzsimons Army Medical Center. Directorate of Facilities Engineering, Fitzsimons Army Medical Center. Denver, Colorado.

Fitzsimons Army Medical Center (FAMC). 1985b. Capability Analytical/Environmental Assessment Report, Fitzsimons Army Medical Center. Directorate of Engineering and Housing, Denver, Colorado.

Fitzsimons Facts. 1992. Aurora Historical Society. Aurora, Colorado

Higginbotham and Associates. 1977. Analysis of Existing Facilities/Environmental Assessment Report, Fitzsimons Army Medical Center, Denver, Colorado.

Parsons Engineering Science, Inc. (Parsons ES). 1996. Environmental Baseline Survey, Fitzsimons Army Medical Center. Denver, Colorado.

Parsons Engineering Science, Inc. (Parsons ES). 1994. Hazardous Material Inventory. Denver, Colorado.

Simmons, R.L. 1991. Cultural Resources Study, Fitzsimons Army Medical Center, Aurora, Colorado. Front Range Research Associates, Inc. Denver, Colorado.

Techlaw, Inc. 1994. Installation Environmental Baseline Conditions and Compliance Study. Lakewood, Colorado.

U.S. Army Environmental Hygiene Agency (USAEHA). 1993. Environmental Compliance Assessment System (ECAS) External Assessment No. 43-21-N18F-93, Draft Findings Report, Fitzsimons Army Medical Center, Aurora, Colorado. Aberdeen Proving Ground, Maryland. 11-15 January.

War Department, U.S. Army. 1923. The Medical Department of the United States Army in the World War, Vol. V, Military Hospitals in the United States. U.S. Army. Washington, D.C.

Worksheet A : Review of Storage of Hazardous and Non-Hazardous Substances and Petroleum Products

Substances Stored	Largest Quantity Stored	Length of Time of Storage	Is Notification of Storage Required Under CERCLA120(h)?	Category of Environmental Condition of Property *	Has a Release Occurred? (If Yes, See Worksheet B)
Building 500 - Third Floor N., X-Ray (Radiology)	**(Rooms 3079 through 3135)**				
+3% Hydrogen peroxide	1 pt	>1 year	Yes	2	
-Kodak developer (RP-X-Omat) + replenisher)	106.8 gal	>1 year	Yes	2	
1% Xylocaine	200 ml	>1 year	Yes	2	
99% Oxygen (25psi cylinder)	8 (160 cu/ft total)	>1 year	Yes	2	
Betadine solution (10% providine, iodine 1%)	3 gal .	>1 year	Yes	2	
CIDEX A-33 Disinfectant	1 gal	>1 year	Yes	2	
Isopropyl alcohol	9 pts	>1 year	Yes	2	
VIREX 128 Detergent	1 gal	>1 year	Yes	2	
		>1 year	Yes	2	
Building 500 - Second Floor N., Chemistry (Rooms 2084 through 2126)					
Acetic acid	2000 ml	>1 year	Yes	2	
Acetone	3 pts	>1 year	Yes	2	
Alconox Detergent	--	>1 year	Yes	2	
Alcotabs	--	>1 year	Yes	2	
Aqueous calibrators & controls	--	>1 year	Yes	2	
Beckman Antiform	50 ml	>1 year	Yes	2	
Beckman CO2 sulfuric acid reagent	6000 ml	>1 year	Yes	2	
Beckman CO2 alkaline buffer	1500 ml	>1 year	Yes	2	
Beckman electrolyte buffer	4000 ml	>1 year	Yes	2	
Beckman electrolute reference reagent	4000 ml	>1 year	Yes	2	
Beckman probe rinse concentration	5750 ml	>1 year	Yes	2	
Beckman trace-klean	2 qts	>1 year	Yes	2	
Denkman wash concentration	1500 ml	>1 year	Yes	2	
Boric acid	1000 gr	>1 year	Yes	2	
Bun reagent	--	>1 year	Yes	2	
Cholesterol reagent	--	>1 year	Yes	2	
Creatine reagent	--	>1 year	Yes	2	

* Note: Facilities may have been recategorized, as presented in Worksheet B.

Worksheet A : Review of Storage of Hazardous and Non-Hazardous Substances and Petroleum Products

Substances Stored	Largest Quantity Stored	Length of Time of Storage	Is Notification of Storage Required Under CERCLA120(h)?	Category of Environmental Condition of Property *	Has a Release Occurred? (If Yes, See Worksheet B)
Deoderant, general purpose	--	>1 year	Yes	2	
Formula 409	--	>1 year	Yes	2	
Glucose reagent	--	>1 year	Yes	2	
Glycerin	4000 ml	>1 year	Yes	2	
HDL cholesterol reagent	--	>1 year	Yes	2	
Hydrochloric acid	13 pts	>1 year	Yes	2	
Hydrochloric acid (6N)	1 pt	>1 year	Yes	2	
3% hydrogen peroxide	1 pt	>1 year	Yes	2	
Iron reagent	--	>1 year	Yes	2	
Isopropyl alcohol	2 pts	>1 year	Yes	2	
Isotonic saline solution	10 ltr	>1 year	Yes	2	
Kodak Ektachem cal 1 diluent	8 ml	>1 year	Yes	2	
Kodak Ektachem cal 2 diluent	8 ml	>1 year	Yes	2	
Kodak Ektachem cal 3 diluent	8 ml	>1 year	Yes	2	
Kodak Ektachem cal 4 diluent	8 ml	>1 year	Yes	2	
Kodak Ektachem cal 5 diluent	8 ml	>1 year	Yes	2	
Kodak Ektachem cal 6 diluent	8 ml	>1 year	Yes	2	
Kodak Ektachem cal 7 diluent	8 ml	>1 year	Yes	2	
Kodak Ektachem cal 15 diluent	4 ml	>1 year	Yes	2	
Kodak Ektachem cal 16 diluent	4 ml	>1 year	Yes	2	
Kodak Ektachem cal 17 diluent	4 ml	>1 year	Yes	2	
Kodak Ektachem con I & II	36 ml	>1 year	Yes	2	
Kodak Ektachem con I & II diluent	36 ml	>1 year	Yes	2	
Kodak Ektachem cal electrolute ref fluid	--	>1 year	Yes	2	
Kodak Ektachem cal electrolute diluent	--	>1 year	Yes	2	
Lypholysed calibrators & controls	--	>1 year	Yes	2	
Methanol	12 pts	>1 year	Yes	2	
Microprotein reagent	--	>1 year	Yes	2	

* Note: Facilities may have been recategorized, as presented in Worksheet B.

Worksheet A : Review of Storage of Hazardous and Non-Hazardous Substances and Petroleum Products

Substances Stored	Largest Quantity Stored	Length of Time of Storage	Is Notification of Storage Required Under CERCLA120(h)?	Category of Environmental Condition of Property *	Has a Release Occurred? (If Yes, See Worksheet B)
Nitric acid	3 gal	>1 year	Yes	2	
Phosphate-free concentration	8 gal	>1 year	Yes	2	
Scouring power	500 gr	>1 year	Yes	2	
Sodium carbonate	500 gr	>1 year	Yes	2	
Sodium hypochlorite	3 gal	>1 year	Yes	2	
TIBC reagent	--	>1 year	Yes	2	
Titration acid (Hydrochloric)	12 ml	>1 year	Yes	2	
Titration cartridge (Sodium hydroxide)	70 ml	>1 year	Yes	2	
Titration solution	8 ml	>1 year	Yes	2	
TP reagent	--	>1 year	Yes	2	
Triglyceride reagent	--	>1 year	Yes	2	
Wash solution (Hi-Chem)	--	>1 year	Yes	2	
White out	--	>1 year	Yes	2	
		>1 year	Yes	2	
Building 500 - Second Floor N., Hematology (Rooms 2084 through 2126)					
3% Hydrogen peroxide	3 pts	>1 year	Yes	2	
Acetone	4 pts	>1 year	Yes	2	
Benzidine Base	--	>1 year	Yes	2	
Bleach (Sodium hypochlorite)	5 gal	>1 year	Yes	2	
Buffered Formalin Acetone	--	>1 year	Yes	2	
Ethylene glycol	--	>1 year	Yes	2	
Formaldehyde	3 pts	>1 year	Yes	2	
Hydrochloric acid	1 pts	>1 year	Yes	2	
Mercurous chloride	--	>1 year	Yes	2	
Mercurous dichloride	--	>1 year	Yes	2	
Methanol	16 pts	>1 year	Yes	2	
Methanol still	10 gal	>1 year	Yes	2	
Nitric acid	1 pt	>1 year	Yes	2	

* Note: Facilities may have been recategorized, as presented in Worksheet B.

Worksheet A : Review of Storage of Hazardous and Non-Hazardous Substances and Petroleum Products

Substances Stored	Largest Quantity Stored	Length of Time of Storage	Is Notification of Storage Required Under CERCLA120(h)?	Category of Environmental Condition of Property *	Has a Release Occurred? (If Yes, See Worksheet B)
Perchloric acid	--	>1 year	Yes	2	
Phenol	500 gr	>1 year	Yes	2	
Sodium azide	500 gr	>1 year	Yes	2	
Sodium hydroxide	1000 gr	>1 year	Yes	2	
Sodium nitrite	1500 gr	>1 year	Yes	2	
Sodium nitroferrocyanide	200 ml	>1 year	Yes	2	
Waste methanol	11 gal	>1 year	Yes	2	
Waste methanol stain	2 gal	>1 year	Yes	2	
Xylene	1 pt	>1 year	Yes	2	
Building 500 - Ground Floor N., Morgue (Rooms 100 through 157)					
70% Isopropyl alcohol	1 pt	>1 year	Yes	2	
95% Ethyl alcohol	1 gal	>1 year	Yes	2	
Acetone	1 pt	>1 year	Yes	2	
Ammonium hydroxide	1 pt	>1 year	Yes	2	
Bleach	19 gal	>1 year	Yes	2	
Formaldehyde 10%	25 gal	>1 year	Yes	2	
Formaldehyde 37%	5 gal	>1 year	Yes	2	
Freon 113	900 ml	>1 year	Yes	2	
Methanol	4 gal	>1 year	Yes	2	
Sodium phosphate dibasic anhydrous	21 lbs	>1 year	Yes	2	
Sodium phosphate monobasic	86 lbs	>1 year	Yes	2	
Xylene	3 pts	>1 year	Yes	2	
Building 500 - EM Laboratory (Rooms 2084 through 2126)					
2,4,6-Tri(demethylaminomethyl)phenol	--	>1 year	Yes	2	
Acetic acid	1 pt	>1 year	Yes	2	
Acetone	1 pt	>1 year	Yes	2	

* Note: Facilities may have been recategorized, as presented in Worksheet B.

Worksheet A : Review of Storage of Hazardous and Non-Hazardous Substances and Petroleum Products

Substances Stored	Largest Quantity Stored	Length of Time of Storage	Is Notification of Storage Required Under CERCLA120(h)?	Category of Environmental Condition of Property *	Has a Release Occurred? (If Yes, See Worksheet B)
Ajax cleaner	--	>1 year	Yes	2	
Alcohol	1 pt	>1 year	Yes	2	
Alconox cleaner	--	>1 year	Yes	2	
Araldite 502 resin	--	>1 year	Yes	2	
Araldite 6005 resin	--	>1 year	Yes	2	
Buffer solution pH 4,7	--	>1 year	Yes	2	
Butyl glycidyl ether (BGE)	--	>1 year	Yes	2	
Calcium chloride	--	>1 year	Yes	2	
Cobalt napthenate, 6%	--	>1 year	Yes	2	
DDSA	2250 gr	>1 year	Yes	2	
Dichlorodifluoromethane	--	>1 year	Yes	2	
DMP-30	--	>1 year	Yes	2	
Dodecenyl succinic anhydride (DDSA)	--	>1 year	Yes	2	
Effapoxy resin	--	>1 year	Yes	2	
Ethanol	500 ml	>1 year	Yes	2	
Ethyene glycol base coolant fluid	--	>1 year	Yes	2	
Formaldehyde 16%	50 ml	>1 year	Yes	2	
Formvar resin (powder)	--	>1 year	Yes	2	
Freon	--	>1 year	Yes	2	
Freon 113	1 pt	>1 year	Yes	2	
Glutaraldehyde	225 ml	>1 year	Yes	2	
Glutaraldehyde 25%	10 ml	>1 year	Yes	2	
Grease - lubricant	--	>1 year	Yes	2	
Grease - vacuum lubricant	--	>1 year	Yes	2	
Hydrochloric acid	1 pt	>1 year	Yes	2	
Ink, stamp pad	--	>1 year	Yes	2	
Isopropyl alcohol	--	>1 year	Yes	2	
Kodak Dektol developer	3 gal	>1 year	Yes	2	

* Note: Facilities may have been recategorized, as presented in Worksheet B.

Worksheet A : Review of Storage of Hazardous and Non-Hazardous Substances and Petroleum Products

Substances Stored	Largest Quantity Stored	Length of Time of Storage	Is Notification of Storage Required Under CERCLA120(h)?	Category of Environmental Condition of Property *	Has a Release Occurred? (If Yes, See Worksheet B)
Kodak fixer	5 gal	>1 year	Yes	2	
Kodak indicator stop bath	--	>1 year	Yes	2	
Kodak photo-flo 200 solution	--	>1 year	Yes	2	
Kodak rapid fixer, Part A	10 gal	>1 year	Yes	2	
Kodak rapid fixer, Part B	--	>1 year	Yes	2	
Lead citrate, solution	--	>1 year	Yes	2	
Lead nitrate	1 lb	>1 year	Yes	2	
Maleic acid	500 gr	>1 year	Yes	2	
Molecular seive, indicating	--	>1 year	Yes	2	
Nadic methyl anhydride	--	>1 year	Yes	2	
Nitrogen (H-tanks)	2	>1 year	Yes	2	
Oil, immersion	--	>1 year	Yes	2	
Oil, vacuum pump	--	>1 year	Yes	2	
Osmium tetroxide 4%	20 ml	>1 year	Yes	2	
Osmium tetroxide waste)	1 pt	>1 year	Yes	2	
Phosphotungstic acid, solid	--	>1 year	Yes	2	
Potassium hydroxide, solid	--	>1 year	Yes	2	
Potassium phosphate, monobasic	--	>1 year	Yes	2	
Pronase	--	>1 year	Yes	2	
Propylene oxide	1 pt	>1 year	Yes	2	
Propylene oxide	6 pts	>1 year	Yes	2	
Quetol 651 resin	--	>1 year	Yes	2	
Ruthenium red stain, solid	--	>1 year	Yes	2	
Silica gel dehydrant, solid	--	>1 year	Yes	2	
Sodium borate, solid	--	>1 year	Yes	2	
Sodium cacodylate	1.0 ltr	>1 year	Yes	2	
Sodium cacodylate, solid & in .2M & .1 M solutions	--	>1 year	Yes	2	
Sodium chloride, solid	--	>1 year	Yes	2	

* Note: Facilities may have been recategorized, as presented in Worksheet B.

Worksheet A : Review of Storage of Hazardous and Non-Hazardous Substances and Petroleum Products

Substances Stored	Largest Quantity Stored	Length of Time of Storage	Is Notification of Storage Required Under CERCLA120(h)?	Category of Environmental Condition of Property *	Has a Release Occurred? (If Yes, See Worksheet B)
Sodium citrate, solid	--	>1 year	Yes	2	
Sodium hydroxide	1/4 lb	>1 year	Yes	2	

* Note: Facilities may have been recategorized, as presented in Worksheet B.

Worksheet B: Review of CERCLA, IRP, or Cleanup Sites

Site or Area Where Release or Disposal of CERCLA Hazardous Substances Occurred	Current Bldg No.	Category of Environmental Condition of Property					Comments
		3	4	5	6	7	
Main Hospital	500					√	Ground beneath may be contaminated.
UST	500					√	Bldg. 500, tanks not formally closed.
Incinerator 5	500					√	Disposal/incineration of waste.
Spill (Ground Floor North)	500					√	Spill of formaldehyde solution. Spill cleaned up.
Spill (Ground Floor North)	500					√	Spill of formaldehyde and biological specimen. Spill cleaned up.
Spill (Basement North)	500					√	Mercury spill. Waste taken to Building 261 for disposal.
Spill (Second Floor East)	500					√	Fluorouracil spill. Spill cleaned up.
Spill (Second Floor East)	500					√	Taxol spill. Spill cleaned up.

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 7/22/96
Name of Interviewee: Elise Sherva
Job Title: Base Environmental Engineer
Floor/Room No./Area of Room:

Drainage and Clean-out Locations/Descriptions:

Time worked in Area: Since Feb '89
How many people worked in this area:
Has this area ever had another use:
Description of job functions in area:

Can you recommend others that may know the historical processes in this area better than yourself:

What substances are or were historically stored in this area:

1 West - pharmacy - cytotoxic chemo waste
3 East/2 West had it also (chemo waste)
Pathology - mercury thermometers
Maintenance - spent pump oil - All shipped to 261 prior to offsite shipment
Laboratory packing staging area 7 East
7 North - Urology clinic - spent x-ray fixer, chemo drugs (sharps)
2 North - Pathology - methanol waste (hematology) (stain slides)
Morgue - formaldehyde waste
2 East - Chemo drugs occasionally

Largest quantity stored:
Length of time stored:
What hazardous or regulated materials or wastes are/were stored and used in this area:

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
2 East - cytotoxic spill, very minor, cleaned up.

What remedial actions have occurred to remedy any releases:

Do you know of other hazards located within this area (example asbestos, radon):

Do you know of any records that may assist us in determining past practices for this floor, and/or area:

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 7/18/96
Name of Interviewee: Sue Errett
Job Title: BRAC Environmental Coordinator
Floor/Room No./Area of Room:

Drainage and Clean-out Locations/Descriptions:

Time worked in Area: 5.5 years
How many people worked in this area:
Has this area ever had another use:
Description of job functions in area:

Can you recommend others that may know the historical processes in this area better than yourself:

What substances are or were historically stored in this area:

Pathology/radiology/CMS/Morgue/ground west all stored hazardous substances

Largest quantity stored: 50 gallon drum
Length of time stored: <90 days
What hazardous or regulated materials or wastes are/were stored and used in this area:
Radiology - silver recovery room. Plumbing leaking into 2 north
2 years ago, special plumbing installed to collect spent fixer from x-ray processing equipment (Peterson cells - buckets, cathodic exchange plug in, electric current 7 West, 3 North [quite a few] not changed often enough. DRMO silver recycling program).

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
1990 - Mercury spill in basement (contractor working in crawl space knocked pipes - mercury spilling in basement (before concrete basement).
Having boxes built before removal action - coffin size. Cleanup crew after hours cut pipes, mercury detector. Cleaned area. Preventive medicine declared clean, Shipped 3 coffins offsite (400 lbs each).
Sinks have mercury in traps. Metals all broken up. CMS area slop sink (8' long). 50 mercury thermometers were discovered behind sink.

What remedial actions have occurred to remedy any releases:
None other than mercury

Do you know of other hazards located within this area (example asbestos, radon):
Radon - basement

Do you know of any records that may assist us in determining past practices for this floor, and/or area:

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/25/96
Name of Interviewee: Elizabeth Baylinson
Job Title: Volunteer for Red Cross
Floor/Room No./Area of Room:
Dedicated in 1941. Renovated entire bldg. X-ray still where always been. Laboratory completely redone, but still in same location. In beginning TB hospital. Pediatrics, Obstetrics, operating room in same place. She handled recreation only. Formerly doctor didn't have offices. Linens formerly done on-post, now sent out. Emergency room has changed.

Drainage and Clean-out Locations/Descriptions:
NA

Time worked in Area: Since 1943
How many people worked in this area:
Has this area ever had another use:
Description of job functions in area:
WWII 4,000 patients. Entertainment - movies, games music (Denver). 200 volunteers (grey ladies), shopping for patients.

Can you recommend others that may know the historical processes in this area better than yourself: Dr. Lewis Barbado, Heritage House at Colorado and Evans.

What substances are or were historically stored in this area: NA

Largest quantity stored: NA
Length of time stored: NA
What hazardous or regulated materials or wastes are/were stored and used in this area:
No fires that she remembers

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
No

What remedial actions have occurred to remedy any releases:
NA

Do you know of other hazards located within this area (example asbestos, radon):
No

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
Dr. Lewis Barbados

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/26/96
Name of Interviewee: Paul Davis/Danny Sullivan/Byron O'Baily
Job Title: Maintenance
Floor/Room No./Area of Room:
Best record in 118. Logbook available. Cobalt room basement. Disposed of sand bags at Rocky Mountain Arsenal as hazardous waste.

Drainage and Clean-out Locations/Descriptions:
Basement lines to creek.

Time worked in Area: 1976 earliest
How many people worked in this area:
Has this area ever had another use: NA
Description of job functions in area:

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
9th floor cooling tower overflowed to 8th floor. Water softener. 1987. Cleaned up.

What remedial actions have occurred to remedy any releases:
Cleaned up.

Do you know of other hazards located within this area (example asbestos, radon):

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
1973 - present Nuclear Medicine in 511

Concrete Basement

- Dug out contaminated soil on north side (sewage). Lime for roach control (took out). Asbestos was found.
- Have not detected mercury at WWTP for 6 years. No heavy metals now.
- 1991 contractor increasing line size took down pipe, mercury spilled (north crawl space). Mercury possibly migrated in the trench to sump pump and pumped out.
- 6"-12" soil excavated in basement, for asbestos.

Old Existing Hospital

- Up to 1972 used mercury thermometers (then removed), mercury manometers still exist.

- In CMS - old cabinets, mercury on floor. Mercury still may exist in areas not renovated - 5 West.

2nd Floor

- Acids, pathology - renovated in 1993. (Silver recovery - under roof flood to storm sewer).
- Spills from x-ray to 2nd floor (fixer/developer)
- Fires from linen chutes, computer fire and trash can.
- Moving 7th floor (late 1970s) - (formaldehyde spilled w/specimens)

North Crawlspace

- Pathology line spilled blood frequently

1 East/2 West

- Terminal Patients

2 East

- (TB Type) Aids wards

1 East

- Hemoc., Dental

Morgue

- Blood from morgue to sanitary sewer. All formaldehyde from hospital stored in morgue.
- Basement drains - may find mercury. 5 West not renovated under cabinets may have mercury under cabinets.

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/18/96
Name of Interviewee: Sgt Costa
Job Title:
Floor/Room No./Area of Room:

8th Floor

Drainage and Clean-out Locations/Descriptions: NA

Time worked in Area: 2 years
How many people worked in this area: 11
Has this area ever had another use: Not that he knows of
Description of job functions in area:
Admin for last 7-8 years. May have been patients room in past because of bathrooms in many of offices

Can you recommend others that may know the historical processes in this area better than yourself: No

What substances are or were historically stored in this area: No chemicals

Largest quantity stored: NA
Length of time stored: NA
What hazardous or regulated materials or wastes are/were stored and used in this area:
Oxygen plug was observed, must have been patients room in past

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
No

What remedial actions have occurred to remedy any releases:
NA

Do you know of other hazards located within this area (example asbestos, radon):
Lead paint likely

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
DPW Records

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/18/96
Name of Interviewee: Karin Merthen
Job Title: Administrative Officer
Floor/Room No./Area of Room:

8th Floor

Drainage and Clean-out Locations/Descriptions:

NA

Time worked in Area: 1 year
How many people worked in this area: NA
Has this area ever had another use: NA
Description of job functions in area:
Administrative Office - Administration only

Can you recommend others that may know the historical processes in this area better than yourself: SGT Costa 2-3 years, Crimbill - Chief of Clinical Nursing

What substances are or were historically stored in this area: No chemicals

Largest quantity stored: NA
Length of time stored: NA
What hazardous or regulated materials or wastes are/were stored and used in this area:
None

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
Chemical spill last year - through vent - construction roofing material - had to evacuate floor

What remedial actions have occurred to remedy any releases:
Used different chemical

Do you know of other hazards located within this area (example asbestos, radon):
No

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
Colonel Fostel - QI

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/18/96
Name of Interviewee: Jenny Alcaraz
Job Title: Office Automation Clerk
Floor/Room No./Area of Room:

8th Floor

Drainage and Clean-out Locations/Descriptions:

NA

Time worked in Area: 6 years
How many people worked in this area: NA
Has this area ever had another use: not last 6 years
Description of job functions in area: Administration

Can you recommend others that may know the historical processes in this area better than yourself: Florence Williams

What substances are or were historically stored in this area: No chemicals

Largest quantity stored: NA
Length of time stored: NA
What hazardous or regulated materials or wastes are/were stored and used in this area:
Ventilation system - caulking from sheet rock and paint

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
No

What remedial actions have occurred to remedy any releases:
N/A

Do you know of other hazards located within this area (example asbestos, radon):
No

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
Velda Nance - Occupational Health

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date:
Name of Interviewee: Josephine Mangon
Job Title: Radiology Technician
Floor/Room No./Area of Room:

7th floor - Urology Clinic

Drainage and Clean-out Locations/Descriptions: NA

Time worked in Area: 7 years
How many people worked in this area: 6
Has this area ever had another use: NA
Description of job functions in area:
Assist doctors in clinics/surgical setup instruments/x-rays
kidney, cancer, fertility, surgery. Laboratory/Treatment Room (every room [4 rooms])
X-ray machines since early 1970s. Basic clinics for consultation.

Can you recommend others that may know the historical processes in this area better than yourself: Roberta Smith (since 1983), Sgt Deadzo

What substances are or were historically stored in this area: Bladder chemotherapy - disposed offsite. Chemicals for x-rays (taken out each week)

Largest quantity stored: 5 gallons per month
Length of time stored: Within one week
What hazardous or regulated materials or wastes are/were stored and used in this area: None

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
Immediate cleanup if happened.

What remedial actions have occurred to remedy any releases:
NA

Do you know of other hazards located within this area (example asbestos, radon):
Remodeled clinic approximately 3 years ago.

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
No

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/18/96
Name of Interviewee: Angela Klar
Job Title: Patient Services Division
Floor/Room No./Area of Room:

6th Floor

Drainage and Clean-out Locations/Descriptions:

NA

Time worked in Area: 2 years
How many people worked in this area: NA
Has this area ever had another use: Postpartum ward/nursery
Description of job functions in area: Administrative

Can you recommend others that may know the historical processes in this area better than yourself: Sgt Torres (1st Floor LHS - out of office)

What substances are or were historically stored in this area: Liquid soap

Largest quantity stored: NA
Length of time stored: NA
What hazardous or regulated materials or wastes are/were stored and used in this area:
None

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
No

What remedial actions have occurred to remedy any releases:
NA

Do you know of other hazards located within this area (example asbestos, radon):
No

Do you know of any records that may assist us in determining past practices for this floor, and/or area:

NA

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/18/96
Name of Interviewee: Barbara Lemarr (SGT Worlds)
Job Title: Medical Clerk
Floor/Room No./Area of Room:

6th Floor

Drainage and Clean-out Locations/Descriptions:

All piping replaced in 1993. Piping outside broken - big freeze (bottled water used)

Time worked in Area: 16.5 years (Oct 79)
How many people worked in this area: 150
Has this area ever had another use: Formerly Cancer Ward
Description of job functions in area:
OB/GYN

Can you recommend others that may know the historical processes in this area better than yourself: Red Cross Volunteer - Barbara Jackson, Ina Bouvier (3rd floor, plastic surgery)

What substances are or were historically stored in this area: DPW disposes

Largest quantity stored: NA
Length of time stored: NA
What hazardous or regulated materials or wastes are/were stored and used in this area: Renovation - 3 (late 1980s), 10 years ago - asbestos abatement

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
None

What remedial actions have occurred to remedy any releases:
NA

Do you know of other hazards located within this area (example asbestos, radon):
No

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
6 East formerly was cancer - believes basement for chemotherapy, 2 East formerly oncology

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/18/96
Name of Interviewee: Dr. James Ecklund
Job Title: Doctor
Floor/Room No./Area of Room:

6th floor, room 6021

Drainage and Clean-out Locations/Descriptions:

No hazards

Time worked in Area: 3 years
How many people worked in this area: 4
Has this area ever had another use: NA
Description of job functions in area:
Neurosurgery clinic only

Can you recommend others that may know the historical processes in this area better than yourself: Colonel Hill - Chief of Radiology

What substances are or were historically stored in this area: None
Largest quantity stored: NA
What hazardous or regulated materials or wastes are/were stored and used in this area:
None (Biomedical wastes only, minimum quantities)

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
None

What remedial actions have occurred to remedy any releases:
None

Do you know of other hazards located within this area (example asbestos, radon):
Unknown

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
NA

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/18/96
Name of Interviewee: Ben Burgess
Job Title: Orthopedic Technician
Floor/Room No./Area of Room:

5th Floor

Drainage and Clean-out Locations/Descriptions:

Plaster trap, Typical - blood, few chemicals

Time worked in Area: 10 years
How many people worked in this area:
Has this area ever had another use:
Description of job functions in area:
Cast room, inpatient and emergency

Can you recommend others that may know the historical processes in this area better than yourself: Susan (Nurse), Ortho ward staff

What substances are or were historically stored in this area: Phenol acid (ingrown toenails killer), fiberglass, general housekeeping cleaners

Largest quantity stored: NA
Length of time stored: NA
What hazardous or regulated materials or wastes are/were stored and used in this area:
Minor cleaning chemicals

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
Cleaner on floor, reacted with wax = odors - 1989

What remedial actions have occurred to remedy any releases:
Held a class for housekeeping staff

Do you know of other hazards located within this area (example asbestos, radon):
No - asbestos remediated in past

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
Bone bank - frozen, biomedical, bottled water - surgery w/bottled water

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/18/96
Name of Interviewee: Mike Berry
Job Title: Ward Master
Floor/Room No./Area of Room:

5th Floor

Drainage and Clean-out Locations/Descriptions:

NA

Time worked in Area: 2 years
How many people worked in this area: 36
Has this area ever had another use: Ortho
Description of job functions in area:
Bones, 33 beds, cardio, EMT, neurology - renovated in October, formerly 50 beds ortho in 1990

Can you recommend others that may know the historical processes in this area better than yourself: Civilians, Intensive care, Mary Hendricks

What substances are or were historically stored in this area: Peroxide, alcohol

Largest quantity stored: NA
Length of time stored: NA
What hazardous or regulated materials or wastes are/were stored and used in this area:
Peroxide, alcohol

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
No

What remedial actions have occurred to remedy any releases:
NA

Do you know of other hazards located within this area (example asbestos, radon):
None

Do you know of any records that may assist us in determining past practices for this floor, and/or area:

No

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/25/96
Name of Interviewee: LTC Peter McNally
Job Title: Chief of Gastroenterology
Floor/Room No./Area of Room:

Drainage and Clean-out Locations/Descriptions:

Time worked in Area: 9 years
How many people worked in this area:
Has this area ever had another use:
Description of job functions in area:
Gastrointerology

Can you recommend others that may know the historical processes in this area better than yourself:

What substances are or were historically stored in this area: Endoscopic procedures, miniature operating room, since 1976 - lab, gluteraldehyde, sporecedum, enzyme cleaner, formalin-preservation, bleach, klenzyme - clean surgical instruments

Largest quantity stored:
Length of time stored:
What hazardous or regulated materials or wastes are/were stored and used in this area:
Storage closet w/chemical, equipment

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
No

What remedial actions have occurred to remedy any releases:
N/A

Do you know of other hazards located within this area (example asbestos, radon):
No

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
No

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/20/96
Name of Interviewee: Alice Diadado
Job Title: Medical Records Technician
Floor/Room No./Area of Room:

4 - West Wing - formerly a blood bank

Drainage and Clean-out Locations/Descriptions:

Time worked in Area: 18 1/2 years
How many people worked in this area: 13
Has this area ever had another use:
Description of job functions in area:
Code and analyze medical records, statistics

Can you recommend others that may know the historical processes in this area better than yourself: Nursing staff

What substances are or were historically stored in this area: No chemicals

Largest quantity stored:
Length of time stored:
What hazardous or regulated materials or wastes are/were stored and used in this area:
None

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
No

What remedial actions have occurred to remedy any releases:
N/A

Do you know of other hazards located within this area (example asbestos, radon):
No

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
604 - Environmental Health

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/20/96
Name of Interviewee: Major Murphy
Job Title: Staff Nurse
Floor/Room No./Area of Room:

4th Floor

Drainage and Clean-out Locations/Descriptions:

Offices - housekeeping only (formerly patients' rooms)

Time worked in Area: 2 years
How many people worked in this area:
Has this area ever had another use:
Description of job functions in area:
Nurse on ward

Can you recommend others that may know the historical processes in this area better than yourself:

What substances are or were historically stored in this area: No chemicals

Largest quantity stored:
Length of time stored:
What hazardous or regulated materials or wastes are/were stored and used in this area:
No

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
No

What remedial actions have occurred to remedy any releases:
N/A

Do you know of other hazards located within this area (example asbestos, radon):
No

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
No

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/20/96
Name of Interviewee: Beverly Gehman
Job Title: Secretary
Floor/Room No./Area of Room:

4th Floor

Drainage and Clean-out Locations/Descriptions:

Time worked in Area: 5 years
How many people worked in this area: 6
Has this area ever had another use: Administrative area for surgery. May formerly have been patients' rooms
Description of job functions in area:
General Administration

Can you recommend others that may know the historical processes in this area better than yourself:

What substances are or were historically stored in this area: No chemicals

Largest quantity stored:
Length of time stored:
What hazardous or regulated materials or wastes are/were stored and used in this area:
None

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
No

What remedial actions have occurred to remedy any releases:
N/A

Do you know of other hazards located within this area (example asbestos, radon):
LBP in windows

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
No

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/20/96
Name of Interviewee: Larry Shoop/Nancy Thomason
Job Title: Diagnostic Radiologic Technologists
Floor/Room No./Area of Room:

3/Main CT Catscan

Drainage and Clean-out Locations/Descriptions:

Time worked in Area: Larry in military at Fitzsimons in 1972
How many people worked in this area: 2
Has this area ever had another use:
Description of job functions in area:
Operate the CT catscan equipment

Can you recommend others that may know the historical processes in this area better than yourself:

What substances are or were historically stored in this area:

- Processor - fixer and developer
- Radiation is within treatment room
- Iodine
- Sharps with medical waste
- Contaminated laundry

Largest quantity stored:
Length of time stored:
What hazardous or regulated materials or wastes are/were stored and used in this area:

- The treatment room has lead-lined doors and walls
- All waste from the processor is picked up by DPW

In 1972

- 3rd floor has always been radiology
- Chemical disposed down sanitary sewer
- Darkrooms have changed location, but the main darkroom has been in the same location
- 2nd floor north has always been the laboratory
- 4th floor north has always been the operating room

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
No

What remedial actions have occurred to remedy any releases:
N/A

Do you know of other hazards located within this area (example asbestos, radon):
No

Do you know of any records that may assist us in determining past practices for this floor, and/or area:

No

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/18/96
Name of Interviewee: Valerie Campbell
Job Title: Supervisor of files and reception
Floor/Room No./Area of Room:

3rd Floor Radiology

Drainage and Clean-out Locations/Descriptions:

Cleaning products, etc.

Time worked in Area: 10 years (68-78)
How many people worked in this area: 10-12 people
Has this area ever had another use:
Description of job functions in area:

Can you recommend others that may know the historical processes in this area better than yourself: Claudia Wells - X-ray Technician

What substances are or were historically stored in this area: No chemicals

Largest quantity stored: NA
Length of time stored: NA
What hazardous or regulated materials or wastes are/were stored and used in this area:
Processing room for x-rays (may have gone down drains), silver recovery

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
None

What remedial actions have occurred to remedy any releases:
NA

Do you know of other hazards located within this area (example asbestos, radon):
None

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
No

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/20/96
Name of Interviewee: Keith Daniels/Josette Wood
Job Title: Ward Master
Floor/Room No./Area of Room:

3rd Floor - ambulatory care center (scheduled) same day release

Drainage and Clean-out Locations/Descriptions:

Time worked in Area: 20 months / 1984
How many people worked in this area: 7
Has this area ever had another use: Formerly surgical intensive care unit (nursing, alcohol cleaning for sterilization)
Description of job functions in area:

Can you recommend others that may know the historical processes in this area better than yourself: Head Nurse

What substances are or were historically stored in this area: Alcohol, cleaning solution

Largest quantity stored: Small
Length of time stored: NA
What hazardous or regulated materials or wastes are/were stored and used in this area: Alcohol/cleaning supplies

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
No

What remedial actions have occurred to remedy any releases:
NA

Do you know of other hazards located within this area (example asbestos, radon):
Lead in area, but at low concentrations

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
No

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/20/96
Name of Interviewee: Diana Minor
Job Title: Medical Clerk/Office Automation
Floor/Room No./Area of Room:

3rd Floor, Room 3137 was formerly an x-ray room

Drainage and Clean-out Locations/Descriptions:

NA

Time worked in Area: 2 years
How many people worked in this area: 1
Has this area ever had another use: No
Description of job functions in area:
Administration only

Can you recommend others that may know the historical processes in this area better than yourself:

What substances are or were historically stored in this area: No chemicals

Largest quantity stored:
Length of time stored:
What hazardous or regulated materials or wastes are/were stored and used in this area:

None

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
No

What remedial actions have occurred to remedy any releases:
NA

Do you know of other hazards located within this area (example asbestos, radon):
None

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
Lead Technician

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/29/96
Name of Interviewee: Marilyn Evans X-4434
Job Title: Lead Technician
Floor/Room No./Area of Room:
3104 - processor chemicals
3109 - fixers & developers
Next to 3118 - formerly had processor
Drainage and Clean-out Locations/Descriptions:

Have been corrected. Formerly leaked to 2nd floor north

Time worked in Area: 9 years
How many people worked in this area: 25 people
Has this area ever had another use: No
Description of job functions in area:
X-ray technician

Can you recommend others that may know the historical processes in this area better than yourself: Catscan - Anne Salizar

What substances are or were historically stored in this area:

Largest quantity stored: 10 of each developer/fixer
Length of time stored: May need to fill 1 every other day
What hazardous or regulated materials or wastes are/were stored and used in this area:
Fixers, developers, cleaning solutions
Wastes into buckets to turn into DPW (Tuesdays) for silver recovery

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
Drain problems (to 2nd floor) overflowing (2 years ago)

What remedial actions have occurred to remedy any releases:
Fixed the drain

Do you know of other hazards located within this area (example asbestos, radon):
No

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
No

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/21/96
Name of Interviewee: Sgt Watkins
Job Title: In charge of laboratory
Floor/Room No./Area of Room:
2nd Floor North - laboratory - currently lab office, formerly all labs
Remodeled in 89/90/91

Drainage and Clean-out Locations/Descriptions:

Bleach, methanol used in cleaning

Time worked in Area: Since 1994
How many people worked in this area: 40
Has this area ever had another use: No
Description of job functions in area:
Patient testing, blood bank, microbiology processing room, blood drawn up front, chemistry/hematology labs

Can you recommend others that may know the historical processes in this area better than yourself: Dr. Sims (on leave July 15th)

What substances are or were historically stored in this area: formerly - hydrochloric and nitric acid (preservatives for 24 hour urine), methanol (microscope dyes), still to recycle methanol. Bleach, alcohol

Largest quantity stored:
Length of time stored:
What hazardous or regulated materials or wastes are/were stored and used in this area:
Kodak - regulated medical waste only, sharps, etc., since 1993 used Kodak (slide stain)

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
No

What remedial actions have occurred to remedy any releases:
NA

Do you know of other hazards located within this area (example asbestos, radon):
No

Do you know of any records that may assist us in determining past practices for this floor, and/or area: Helen Littlejohn - major change in technology recorded

CONTINUED

Building Name: Main Hospital
Building No: 500
Date: 6/21/96
Name of Interviewee: Sgt Watkins
Job Title: In charge of laboratory
Floor/Room No./Area of Room:
2nd Floor North - laboratory - currently lab office, formerly all labs
Remodeled in 89/90/91

Special Lab

- Antigen testing
- Hepatitis testing
- Formerly more chemicals to run analyses
  - Glucose
  - Triglycerides

Blood Bank

- Storage and testing
- Walk-in cooler - old

Main Lab

- Hematology section
- Corrosives cabinets
  - Bleach
  - Methanol
  - Alcohol
- Lots of equipment
- Drain
- Blue still to process used methanol waste currently broken - turning in waste
  All waste from process is turned in to Elise. - Volume - turned in 1 can every 2-3 weeks.

Acid Containers

- Hydrochloride
- Nitric acid
- Hood discharges (acid hood) carbon filter
  - Switched 4-6 months (carbon turned in to Elise)
- Methanol & alcohol

Hood

- Processing blood samples

Microbiology

- Set up only, inoculate plates w/sample

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/21/96
Name of Interviewee: Leona Moore
Job Title: Clinical Nurse
Floor/Room No./Area of Room:

2nd South - Preadmission

Drainage and Clean-out Locations/Descriptions:

No

Time worked in Area: 6 years
How many people worked in this area: 10
Has this area ever had another use: Formerly internal medicine Sept 94, Admin
Description of job functions in area:
Clinic

Can you recommend others that may know the historical processes in this area better than yourself:

What substances are or were historically stored in this area: No chemicals

Largest quantity stored:
Length of time stored:
What hazardous or regulated materials or wastes are/were stored and used in this area:
None

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
No

What remedial actions have occurred to remedy any releases:
NA

Do you know of other hazards located within this area (example asbestos, radon):
No

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
Department of Internal Medicine

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/21/96
Name of Interviewee: James Williams/Mr. Hot
Job Title: Hospital Treasurer
Floor/Room No./Area of Room:

1st floor

Drainage and Clean-out Locations/Descriptions:

NA

Time worked in Area: 1 year, since 1979
How many people worked in this area: 6
Has this area ever had another use: Medical Holding/Pharmacy/collect money
Description of job functions in area:
Hospital finances

Can you recommend others that may know the historical processes in this area better than yourself: Joyce Brooks - Buckley

What substances are or were historically stored in this area: Administration only, no chemicals

Largest quantity stored: NA
Length of time stored:
What hazardous or regulated materials or wastes are/were stored and used in this area:
None

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
No (4th floor mercury spill - 1991)

What remedial actions have occurred to remedy any releases:
NA

Do you know of other hazards located within this area (example asbestos, radon):
No

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
1 East - Female surgical ward, 1 East - Male medical ward, 1 West Pharmacy, mess hall funds (20 years)

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/21/96
Name of Interviewee: Christine Johnson
Job Title: Office Automation
Floor/Room No./Area of Room:

1st Floor West

Drainage and Clean-out Locations/Descriptions:
Yellow for chemo waste
Red for strictly medical waste
Pharmacy - hood to outside, cleaned out 1 week ago, sink, floor drain. Dialysis (tenant) formaldehyde.

Time worked in Area: 10 years
How many people worked in this area: 25
Has this area ever had another use: Clinics
Description of job functions in area:
Pulmonary function lab - lung capacity/ Gove chemotherapy (oncology/hematology clinics) neuphrology

Can you recommend others that may know the historical processes in this area better than yourself:

What substances are or were historically stored in this area: Chemo drugs

Largest quantity stored: Pharmacy retained records
Length of time stored:
What hazardous or regulated materials or wastes are/were stored and used in this area:
Chemo - poison (pharmacy w/hood to mix drugs) pharmacy technicians

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
No

What remedial actions have occurred to remedy any releases:
NA

Do you know of other hazards located within this area (example asbestos, radon):
No

Do you know of any records that may assist us in determining past practices for this floor, and/or area: Pharmacy records

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/18/96
Name of Interviewee: Florence Williams
Job Title: Administration
Floor/Room No./Area of Room:

1st Floor

Drainage and Clean-out Locations/Descriptions:

Time worked in Area: 6 years
How many people worked in this area: NA
Has this area ever had another use: NA
Description of job functions in area: Administration only

Can you recommend others that may know the historical processes in this area better than yourself: No

What substances are or were historically stored in this area: No chemicals

Largest quantity stored: NA
Length of time stored: NA
What hazardous or regulated materials or wastes are/were stored and used in this area: None

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
No

What remedial actions have occurred to remedy any releases:
NA

Do you know of other hazards located within this area (example asbestos, radon):
No

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
No

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/25/96
Name of Interviewee: CPT Betty Quitt (Dietitian)
Job Title: Director of Nutrition Care
Floor/Room No./Area of Room:

Ground
Francis Fluorentino
Drainage and Clean-out Locations/Descriptions:

Grease traps (in special container) need to talk to contractor

Time worked in Area: 2 years
How many people worked in this area: 8
Has this area ever had another use: 15 years ago - field equipment (gas masks, etc.)
Description of job functions in area:
COR for food service contract, budget, meetings, responsible to command, cafeteria

Can you recommend others that may know the historical processes in this area better than yourself: Francis Serentino

What substances are or were historically stored in this area: Cleaning supplies

Largest quantity stored:
Length of time stored:
What hazardous or regulated materials or wastes are/were stored and used in this area:
MSDS labels, Hazcom, cleaners (some stored on ground, some stored on 1)

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
No

What remedial actions have occurred to remedy any releases:
NA

Do you know of other hazards located within this area (example asbestos, radon):
Construction in dining hall - took asbestos out (last year)

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
No

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/25/96
Name of Interviewee: Francis Sorrentino
Job Title: Contractor
Floor/Room No./Area of Room:

Ground Floor

Drainage and Clean-out Locations/Descriptions:
Grease Traps existed

Time worked in Area: 1 year
How many people worked in this area:
Has this area ever had another use:
Description of job functions in area: Food service contractor

Can you recommend others that may know the historical processes in this area better than yourself: No

What substances are or were historically stored in this area: Just cleaning materials.

Largest quantity stored:
Length of time stored:
What hazardous or regulated materials or wastes are/were stored and used in this area: Cleaning supplies

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
No

What remedial actions have occurred to remedy any releases:
N/A

Do you know of other hazards located within this area (example asbestos, radon):
No

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
No

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/21/96
Name of Interviewee: Ken Conner/Ed Payne
Job Title: Maintenance (plumbing, electrical, carpentry)
Floor/Room No./Area of Room:
Basement

Drainage and Clean-out Locations/Descriptions:
Dropped a thermometer in wall hung sink (8th floor west) 4 years ago. Installed a new waterline to 824, never chlorinated the line and hooked buildings - raised bacteria levels.

Time worked in Area: 5 years/10 years
How many people worked in this area: 7
Has this area ever had another use:
Description of job functions in area:
Plumbing, electrical, carpentry - formerly generators, autoclave, incinerator, grinder

Can you recommend others that may know the historical processes in this area better than yourself:

What substances are or were historically stored in this area:

Oils, non-hazardous materials, film library (nuclear)

anaerobic live bacteria, potassium hydroxide, cast away drain cleaner, super chem-zyne, red streak, hand soap, lubrication oil.

Largest quantity stored:
Length of time stored:
What hazardous or regulated materials or wastes are/were stored and used in this area:
Piping out of the building (5 pipes out of building 12" to 24" pipes, elbows 90°)

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).

What remedial actions have occurred to remedy any releases:

Do you know of other hazards located within this area (example asbestos, radon):
Asbestos - most has been removed during renovations- 95% from remodeled floors

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
DPW

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 7/11/96
Name of Interviewee: Roger Walton
Job Title: Responsible for silver recovery
Floor/Room No./Area of Room:

Ground

Drainage and Clean-out Locations/Descriptions:

Time worked in Area: 11 years
How many people worked in this area: 1
Has this area ever had another use:
Description of job functions in area:
Fixer from the x-ray machines is drained into the silver recovery room on the ground floor of Building No. 500. Southwest Radiographics has been contracted to pick up and recycle the waste and FAMC receives credit for all they turn in.
The special piping system was installed 4-5 years ago and prior to that all of the x-ray fixer was collected and delivered. FAMC formerly performed their own silver recovery in Building No. 211.

Can you recommend others that may know the historical processes in this area better than yourself: No

What substances are or were historically stored in this area: Spent fixer

Largest quantity stored:
Length of time stored:
What hazardous or regulated materials or wastes are/were stored and used in this area:
Fixer

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
No

What remedial actions have occurred to remedy any releases:
N/A

Do you know of other hazards located within this area (example asbestos, radon):
No

Do you know of any records that may assist us in determining past practices for this floor, and/or area: No

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 6/18/96
Name of Interviewee: Barbara Nading
Job Title: SPC
Floor/Room No./Area of Room:

General Surgery Clinic

Drainage and Clean-out Locations/Descriptions:

rubbing alcohol/peroxide placed in drains

Time worked in Area: 1 year
How many people worked in this area: 58
Has this area ever had another use: Surgery - long time
Description of job functions in area:
General Surgery

Can you recommend others that may know the historical processes in this area better than yourself: SSG Dio Lazo

What substances are or were historically stored in this area: MSDS given

Largest quantity stored: three 1-gallon bottles
Length of time stored: Continuous
What hazardous or regulated materials or wastes are/were stored and used in this area: Formalin - Breast cell hold

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
Spills of alcohol/peroxide, minor

What remedial actions have occurred to remedy any releases:
NA

Do you know of other hazards located within this area (example asbestos, radon):
NA

Do you know of any records that may assist us in determining past practices for this floor, and/or area:
2 East - Chemo/Radiation (last patient in April), patients urine spilled

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 7/19/96
Name of Interviewee: Lou Aragon
Job Title: Construction Inspector
Floor/Room No./Area of Room:

Basement

Drainage and Clean-out Locations/Descriptions:

Time worked in Area: 30 years
How many people worked in this area:
Has this area ever had another use:
Description of job functions in area: Construction Inspector

Can you recommend others that may know the historical processes in this area better than yourself:

What substances are or were historically stored in this area: Unknown

Largest quantity stored:
Length of time stored:
What hazardous or regulated materials or wastes are/were stored and used in this area:
Unfamiliar with hazardous materials/waste issues

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe).
In 1991 until Jan 1992, a contractor was hired to remove asbestos from the crawl spaces of the basement. Approximately 6 inches of soil were removed from the areas. After 6 inches were removed, asbestos was still present in the soil. At that time, the crawl spaces of the basement were encapsulated with concrete. Prior to encapsulation, soil samples were collected and analyzed for asbestos. No hazardous materials analyses were conducted at that time. The demolition materials were sent to DADS and the asbestos was sent to Mead, Nebraska.

What remedial actions have occurred to remedy any releases:

Do you know of other hazards located within this area (example asbestos, radon):
No

Do you know of any records that may assist us in determining past practices for this floor, and/or area: The records for this project are present in the environmental records.

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 07/12/96
Name of Interviewee: Dr. Louis Barbado
Job Title: Retired Doctor
Floor/Room No./Area of Room:

Mostly not in Building No. 500. Only on occasion. He was primarily in the psychiatric wards not within Building No. 500.

Drainage and Clean-out Locations/Descriptions:

Not applicable

Time worked in Area: 1942-46
How many people worked in this area: 20
Has this area ever had another use: No
Description of job functions in area: General medicine

Can you recommend others that may know the historical processes in this area better than yourself:

Dr. David Hazard - Dental Officer (758-8729)

Dr. John Grow - Surgeon (722-5467)

What substances are or were historically stored in this area: NA

Largest quantity stored: NA
Length of time stored: NA
What hazardous or regulated materials or wastes are/were stored and used in this area: Just general cleaning and sterilizing materials.

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe). No

What remedial actions have occurred to remedy any releases: No

Do you know of other hazards located within this area (example asbestos, radon): No

Do you know of any records that may assist us in determining past practices for this floor, and/or area: No

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 07/12/96
Name of Interviewee: Dr. David Hazard
Job Title: Dental Officer
Floor/Room No./Area of Room:
Dental Clinic (1st West)

Drainage and Clean-out Locations/Descriptions: NA

Time worked in Area: 1941-1943
How many people worked in this area: NA
Has this area ever had another use: No
Description of job functions in area: Oral Surgery

Can you recommend others that may know the historical processes in this area better than yourself: No

What substances are or were historically stored in this area: Some Mercury (in amalgum), cleaning and sterilizing supplies.

Largest quantity stored: NA
Length of time stored: NA
What hazardous or regulated materials or wastes are/were stored and used in this area: NA

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe). Rugs used in the area were smeltered for metals collected within the rugs. Very small spills on floors of general compounds. Always cleaned up.

What remedial actions have occurred to remedy any releases: NA

Do you know of other hazards located within this area (example asbestos, radon): No

Do you know of any records that may assist us in determining past practices for this floor, and/or area: No

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 07/15/96
Name of Interviewee: Dr. John Grow
Job Title: Chief of Surgery
Floor/Room No./Area of Room:

Drainage and Clean-out Locations/Descriptions:

Time worked in Area: 1941-1947
How many people worked in this area: NA
Has this area ever had another use: NA
Description of job functions in area: NA

Can you recommend others that may know the historical processes in this area better than yourself: No

What substances are or were historically stored in this area: General cleaning supplies.

Largest quantity stored: NA
Length of time stored: NA
What hazardous or regulated materials or wastes are/were stored and used in this area: NA

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe). No

What remedial actions have occurred to remedy any releases: NA

Do you know of other hazards located within this area (example asbestos, radon): No

Do you know of any records that may assist us in determining past practices for this floor, and/or area: No

GENERAL INTERVIEW QUESTIONNAIRE
U.S. ARMY GARRISON, FITZSIMONS

Building Name: Main Hospital
Building No: 500
Date: 07/15/96
Name of Interviewee: CPT Annette Boatwright
Job Title: Radiation Protecton Office
Floor/Room No./Area of Room:
General Building No. 500 Coverage.

Drainage and Clean-out Locations/Descriptions: NA

Time worked in Area: 13 months
How many people worked in this area: NA
Has this area ever had another use: NA
Description of job functions in area: NA

Can you recommend others that may know the historical processes in this area better than yourself: No

What substances are or were historically stored in this area: Radiation sources were entered into Section 4 of the text as given by CPT Boatwright during the interview.

Largest quantity stored: NA
Length of time stored: NA
What hazardous or regulated materials or wastes are/were stored and used in this area: Radioactive

Do you know if any spills or incidents (past or present) that have caused release of regulated materials in this area (Please describe). Years ago an iodine-131 spill occurred in the basement. Spill was cleaned up. Iodine-131 has a short half-life and therefore, does not currently present a problem.

What remedial actions have occurred to remedy any releases: None

Do you know of other hazards located within this area (example asbestos, radon): No

Do you know of any records that may assist us in determining past practices for this floor, and/or area: She faxed over the listing that she provided over the phone.

VISUAL INSPECTION FORM

BUILDING NO: 500

FLOOR NO: 9

ROOM NO:

AREA DESCRIPTION: Elevator House

DATE OF INSPECTION: 6/18/96

OBSERVATIONS:

Outside - Air conditioner, rock floor w/drains

Elevator House

- Concrete ceiling
- Parts for elevators
- Electrical equipment
- Oily waste can - full of trash
- Communications equipment
- Christmas decorations
- Pigeon droppings
- Old motors/control for elevators
- Fire system
- Batteries - not leaking
- Brick walls
- Painted beams
- Some fluorescent lights

HVAC Room

- Fans
- Inlet/outlet piping

VISUAL INSPECTION FORM

BUILDING NO: 500

FLOOR NO: 8

ROOM NO:

AREA DESCRIPTION: Administration

DATE OF INSPECTION: 6/18/96

OBSERVATIONS:

Theater - Bushnell Auditorium

- Painted walls
- Fluorescent lights
- Linoleum floor

Bathroom

- Drop ceiling
- Tile/paint
- Fluorescent lights

Storage Closet

- Linoleum floor
- Painted walls
- Spray-on insulation beams - ceiling

Utility Room

- Concrete vault w/rock floor
- All torn up - under construction (elevator shaft)
- Crane
- Drop ceiling

VISUAL INSPECTION FORM

BUILDING NO: 500

FLOOR NO: 7

ROOM NO:

AREA DESCRIPTION: East Wing

DATE OF INSPECTION: 6/18/96

OBSERVATIONS:

7 East Wing

- Rooms used for collection of laboratory packs (haz waste) (7010/7012/7013)
- Patients rooms
  - Linoleum floor
  - Painted walls
  - Drop ceilings
  - Fabric walls - green paint under may be lead-based
- Bathrooms
  - Tile floor
  - Painted walls
  - Drop ceiling
  - Sinks with drains.

7022 - Dirty Utility Room

- Tile floor/walls
- Drop ceiling
- Storage space for linens, etc.
- Stainless steel shelves

Elevator Machine Room

- Concrete floor/walls
- Drop concrete ceiling
- Electrical relays for elevator

VISUAL INSPECTION FORM

BUILDING NO: 500

FLOOR NO: 7

ROOM NO:

AREA DESCRIPTION: West and South Wings

DATE OF INSPECTION: 6/18/96

OBSERVATIONS:

<u>7 West Wing</u> (Cardio-Thoracic Surgery)

- Linoleum floor
- Painted walls
- Drop ceiling

7050 - Oxygen tank storage

<u>Utility Room</u>

- Sink,
- Laundry shoot,
- "Cyclone" bedpan wash.

<u>7 South Wing</u> - Offices

- Linoleum floor
- Painted walls
- Drop ceiling

VISUAL INSPECTION FORM

BUILDING NO: 500

FLOOR NO: 7

ROOM NO:

AREA DESCRIPTION: North Wing

DATE OF INSPECTION: 6/18/96

OBSERVATIONS:

7 North Wing (Urology Clinic)

X-ray room 7045 and 7042

In hall 2 55-gallon drums of medial waste

7037 - Treatment Room

- Linoleum floor
- Tile walls
- Drop ceilings
- Fluorescent lights
- Medical waste (sharps, etc.)
- Floor drain - closed up

7039 - Laboratory

- Tile floor/walls
- Drop ceilings
- Fluorescent lights
- Fixer/developer (x-rays)
- Sterilizing/disinfection solution
- Hood for x-rays (vents outside)
- Stainless steel sink

7041 - Laboratory

- Microscope/spinette
- Sink
- Incubator
- Computer/printer

VISUAL INSPECTION FORM

BUILDING NO: 500

FLOOR NO: 6

ROOM NO:

AREA DESCRIPTION:

DATE OF INSPECTION: 6/18/96

OBSERVATIONS: East, West, and North Wings

6 East Wing

- Primarily patient rooms
- Linoleum floor
- Painted walls
- Drop ceiling

6038 - Utility Room

- Bedpan sanitizer
- Storage

GYN Equipment Room

- Stainless steel cabinets/sink
- Medical storage
-

6 West Wing

- Primarily patient rooms
- Linoleum floor
- Painted walls
- Drop ceiling

6018 - Supply Room

- Large drain
- Stainless steel cabinets - storage

6 North Wing - Labor and Delivery

6061 - Operating Room

- Stainless steel sinks
- Sterilizer
- C-Sections
- Acetone used (not currently stored), Glycerin (4th floor)
- Liquid chlorinating sanitizer (sodium hypochlorite)
- S-Klenz (phosphoric acid)

VISUAL INSPECTION FORM

BUILDING NO: 500

FLOOR NO: 5

ROOM NO:

AREA DESCRIPTION: East, North, and West Wings

DATE OF INSPECTION: 6/18/96

OBSERVATIONS:

5 East Wing - Orthopedics (recently remodeled)

- Linoleum floor
- Painted rooms
- 5063 - Cast Room and Storage (Sink with trap, general supplies)

5 North Wing - General Surgery (recently remodeled)

- Medical equipment
- Linoleum floor
- Painted walls
- Drop ceilings

Operating Room

- Sulfur hexane
- Sterilizer
- Stainless steel storage
- Linoleum floor
- Paint walls
- Drop ceilings

5 West Wing - Orthopedics

- Linoleum floors
- Painted walls
- Drop ceiling
- Fluorescent lights
- 5115 - Utility Room (same as previous utility rooms)

VISUAL INSPECTION FORM

BUILDING NO: 500

FLOOR NO: 4

ROOM NO:

AREA DESCRIPTION: West and South Wings

DATE OF INSPECTION: 6/20/96

OBSERVATIONS:

4 West Wing

- Linoleum floor
- Painted walls
- Drop ceilings
- Fluorescent lights
- EEG Laboratory

4 South Wing (office space)

- Linoleum floor
- Painted walls
- Drop ceilings

VISUAL INSPECTION FORM

BUILDING NO: 500

FLOOR NO: 4

ROOM NO:

AREA DESCRIPTION: East and North Wings

DATE OF INSPECTION: 6/18/96

OBSERVATIONS:

<u>4 East Wing</u> (Intensive care, post anesthesia, coronary care (Julie McKendrick))

- Pharmacy - (Room 4066)
- Linoleum floors
- Painted
- Drop ceiling
- Fluorescent lights
- Same as other, no laboratories
- Acetones
- Betadynes
- Alcohol
- Iodines
- Soaps/Cleaners

<u>Intensive Care</u> - Remodeled two years ago

- Mercury spill on 6th floor in 1991, in sinks also, replaced pipes
- Recent pipe breaks - water line (improper material)

<u>4 North Wing (Operating Room)</u> - (Sgt Brayman)

- Mineral oil
- Nitrogen/oxygen equipment
- Alcohol
- Betadyne
- Gluteraldehyde - cold sterilization
- Ethylene oxide gas - cold sterilization
- Housekeeping Supplies
- Ethylene oxide spills have occurred in past
- Floor drains - for laser machine coolant water

VISUAL INSPECTION FORM

BUILDING NO: 500

FLOOR NO: 3

ROOM NO:

AREA DESCRIPTION: West, North, and East Wings

DATE OF INSPECTION: 6/20/96

OBSERVATIONS:

3 West Wing (same-day surgery and office space)

- Linoleum floor
- Painted walls
- Drop ceilings

3 North Wing (Radiology)

- Dark rooms
- Fixer/developer for film processing
- Linoleum floor
- Painted walls
- Drop ceilings

3 East (Pediatrics)

- Linoleum floor
- Painted walls
- Drop ceilings
  - Cleaning supplies
    Bleach
    Hydrogen Peroxide
    Alcohol
    Cold sterilant equipment
- Children's clinic (formerly pediatric ward)
- New-born intensive care

VISUAL INSPECTION FORM

BUILDING NO: 500

FLOOR NO: 2

ROOM NO:

AREA DESCRIPTION: East, South, and West Wings

DATE OF INSPECTION: 6/21/96

OBSERVATIONS:

2 East Wing (to be new Fitzsimons Health Clinic)

- Linoleum floor
- Painted walls
- Drop ceilings

2038

- Formerly TB treatment - will be cleaned
- Storage (Sgt James Johnson)
  - Drain (appears clean)
  - Sodium chloride
- Mostly offices and clinics.

2076

- Formerly whirlpool
  - Floor drain

2 South Wing (Patient Services)

- Linoleum floor
- Painted walls
- Drop ceilings

2 West Wing (Cardiology Clinic)

- Linoleum floor
- Painted walls
- Drop ceilings

VISUAL INSPECTION FORM

BUILDING NO: 500

FLOOR NO: 1

ROOM NO:

AREA DESCRIPTION: West and North Wings

DATE OF INSPECTION: 6/21/96

OBSERVATIONS:

1 West Wing

- Hospital Treasurer/Central Clearance
- Patient Trust Fund
- Nephrology/Hematology/Perinatal
- Pulmonary Function/Sleep Laboratory
- Oral & Maxilofacial Surgery
- Hematology/Oncology Clinic
- All renovated within last few years
- 1135 - laboratory with sinks and scopes

1 North Wing

- Cafeteria - Tray cleaning area. Sinks, typical storage.
- Ongoing asbestos abatement visible.
- Cafeteria line and dining area
  - Carpet floor
  - Painted walls
  - Drop ceiling
- Stainless steel wash room
  - Ceramic tile floor (drain)
  - Sheetrock walls
  - Concrete ceiling
  - Danger signs up for asbestos

VISUAL INSPECTION FORM

BUILDING NO: 500

FLOOR NO: 1

ROOM NO:

AREA DESCRIPTION:

DATE OF INSPECTION:

OBSERVATIONS:

1 South Wing

- Office space - Reception area
  - Marble floors and pillars
- Bruns Room - Meeting room
  - Carpet floor
  - Painted walls and ceilings

1 East Wing - Office space for Department of Medicine Chief (City of Aurora Transition)

  - Linoleum floors
  - Wallpaper walls
  - Drop ceiling
  - Utility room
  - Kitchen
- GI Lab - 1054
  - Chemicals
- Mechanical Room
  - Ceramic Tile
  - Sheetrock walls
  - Concrete ceilings

VISUAL INSPECTION FORM

BUILDING NO: 500

FLOOR NO: Ground Level

ROOM NO:

AREA DESCRIPTION:

DATE OF INSPECTION: 6/25/96

OBSERVATIONS:

<u>Ground - East Wing</u>

- Pharmacy (5051) - newer pharmacy
- Inpatient
  - Hoods for mixing drugs (making IV)
- Physical Therapy clinic
- Cardiac cath clinic
- Radiation therapy service
- Interventional radiology
- MRI/CT
- Old Lab with new hood
- Waste from chemotherapy patients

- Robert Yochem - 11 years
  - Pharmacist
  - Always been pharmacy
  - No spills or problems w/chemicals
  - Asbestos removed from one room (511)
  - Nuclear pharmacy and Chemo pharmacy (1 West) in other areas
- Cardiac
  - Remodeled 2 years ago
  - Formerly Lab
- Physical Therapy (Cpt Lewis Gabbard)
  - Been physical therapy for 2 years
  - Bleaches to clean mats
  - Whirlpool clean
  - Chemicals - wound debreadment (take dead tissue off)
  - Diathermy (deep tissue heating) cause radiation sign.
  - Broken sewer pipe 1 month ago
  - Chemicals to clean whirlpool

GROUNDLEVEL (CONTINUED)

- Biomedical - Ground East
  - Contaminated dock (formerly breezeway)
  - Pick up all the biomedical waste and then send to autoclave
  - Remove waste not supposed to be there
- Post Chapel
  - Carpet
  - Panel walls
  - Drop ceilings
  - Office space
- Morgue (Sgt Carlton)
  - Still for alcohol/xylene
  - 3 flammable cabinets
  - Hood to use formaldehyde and xylene
  - Laboratory with corroded sinks
  - Darkroom
  - Sodium hypochlorite
  - Electron microscope
  - Nitrogen gas
  - Biohazard

Ground North (Food Service)

- Refrigerants
- Dry food storage area
  - Concrete floor
  - Tile walls
  - Concrete ceiling
  - CO for soda machines
  - Cleaning items
  - Numerous containers of soaps, oven/fry cleaner, detergent, etc.
  - Compressors - new refrigerant approx 1 year ago
  - No knowledge of use of ammonia as refrigerant
  - Grease traps - dishpan area - currently out of service
  - Cafe remodeled in 92/93
  - Potato peeler
  - Food service office
  - 6 compressors (1 yr old)
  - Floor drain
- Admissions - 5/6 years
  - Office space
  - Patient checkin
  - No regulated/hazardous materials
  - 7 people
  - Smell gas from outside

GROUND LEVEL (CONTINUED)

- Doesn't know prior use

- Old Walkins
  - 1 floor drain each
  - Some used for storage only

Ground South

- Post Office

- PX

- Emergency Room
  - Call housekeeping to clean up blood, bodily fluids as needed
  - Bleach used to decontaminate
  - Fitzsimons Control (central for emergency room)
  - Chemical sterilizer in operating room

- Radiation Therapy Service
  - Formerly offices
  - Now, x-ray storage
  - Chemotherapy dropped 4 yrs ago and had to go RPO

- Central Materials Services (Sterilizing)
  - Renovated within last 3 years
  - Moved sterilizers to another room for renovations
  - 19 people
  - Ethylene oxide - used to sterilize equipment that cannot be brought to high temperatures
  - Acetone
  - Pry - to clean steam
  - Dish soap
  - Uni-solve - take tape off of equipment
  - Klenzyme - east germs
  - A33 - clean blood, decontaminating
  - 50 gallons of steamer/sterilizer
  - Two minor incidents
  - Door not sealed - all shut off (5 ppm)

VISUAL INSPECTION FORM

BUILDING NO: 500

FLOOR NO: Basement

ROOM NO:

AREA DESCRIPTION: Tool rooms, mechanical, piping

DATE OF INSPECTION: 6/21/96

OBSERVATIONS:

- Drains to storm sewer in tool room. All basement drains go to storm sewer
- Autoclave was removed.
- Exhaust or intake air duct remains.
- Large buildup of dust and grit remain.
- Grinder is in basement sump area.
- Incinerator appears to have been in similar location.
- Grinder lines still intact.
- Old oil tanks in this area have been removed.

<u>North Crawlspace</u>

- New wall - installed 1 year ago
- Radiation Therapy - lead and sand bags - 4 feet deep/6 feet tall

<u>East Crawlspace</u>

- Spills of kitchen waste
  - Lime put down for dehydration
- Steam Tunnel - to boiler plant
- Housekeeping supplies and storage
  - Drums of degreaser and floor cleaner

<u>South Crawlspace</u>

- Old drain for old chillers
- Nitrous oxide storage
- Oxygen room storage